

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3527
SCHOOL NAME: Southside Occupational Academy
ADDRESS OF SCHOOL: 7342 S. Hoyne
CITY: Chicago, IL, 60636

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **10/3/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/6/2022 ENROLLMENT 345
IDPH INSPECTOR LICENSE NUMBER: 100-18281
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos
IDPH MP LICENSE NUMBER: 100-09870
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer

11/2/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Southside Occupational Academy

7342 S. Hoynes
Chicago, IL, 60636

Unit: 49031
Building ID: 1700

IDPH ID Number: 14-016-2990-3527

REPORT DATE:

Wednesday, November 02, 2022

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

11/02/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 49031 Region: 05 IDPH ID: 14-016-2990-3527

School: Southside Occupational Academy Building ID: 1700

Address: 7342 S. Hoyne

Chicago, IL, 60636

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 10/6/2022

Review Date: 11/02/2022

Inspector: Christopher Antonopoulos

Inspector IDPH License: 100-18281

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Todd Huffer
100-09870

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 02, 2022

RE: Southside Occupational Academy, Unit 49031
7342 S. Hoyne
Chicago, IL, 60636

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Southside Occupational Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Southside Occupational Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Southside Occupational Academy Unit: 49031 Region: 05
Address: 7342 S. Hoyne Chicago, IL, 60636
IDPH ID: 14-016-2990-3527 Building ID: 1700
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 345

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Christopher Antonopoulos



Signature:
Date: 10/6/2022

Inspector IDPH license # 100-18281
Reinspection Date: 10/6/2022

6. Management Planner

Management Planner Name: Todd Huffer



Signature:
Date: 11/02/2022

Management Planner IDPH license # 100-09870

7. Review Date: 11/02/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 11/2/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Southside Occupational Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1700:

21	12"x12" Tan, Orange & Green Mix Floor Tile
22	12"x12" Tan, Orange & Green Mix Floor Tile
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 1700:

21	12"x12" Tan, Orange & Green Mix Floor Tile
22	12"x12" Tan, Orange & Green Mix Floor Tile
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01A	12"x12" Tan Floor Tile
01B	12"x12" Green Floor Tile
01C	12"x12" Gray Floor Tile
02	Vinyl Inlay Tile
06	Fire Door Insulation
08A	12"x12" Tan Floor Tile Black Mastic
08B	12"x12" Green Floor Tile Black Mastic
08C	12"x12' Gray Floor Tile Black Mastic
09	Vinyl Inlay Tile Black Mastic
10A	Dark Blue Carpet/Light Brown Mastic
10B	Gray Carpet/Light Brown Mastic- NOT OBSERVED*
10C	Dark Green Carpet/Light Brown Mastic NOT OBSERVED
10D	Bluish Gray Carpet/Light Brown Mastic NOT OBSERVED
11A	Brown Vinyl Baseboard/Brown Mastic
11B	Gray Vinyl Baseboard/Tan Mastic
11C	Green Vinyl Baseboard/Brown Mastic
13A	Brown Vinyl Baseboard
13B	Gray Vinyl Baseboard
13C	Green Vinyl Baseboard
14	Stair Tread Mastic
15	12"x12" Blue w/Streaks Vinyl Floor Tile
15A	12"x12" Blue w/Streaks Vinyl Floor Tile Mastic
16	12"x12" Turquoise w/Streaks Vinyl Floor Tile NOT OBSERVED
16A	12"x12" Turquoise w/ Streaks Vinyl Floor Tile Mastic NOT OBSERVED
17	Tan Carpet Mastic
18	Black Vinyl Baseboard
18A	Black Baseboard Mastic
19	12"x12" Beige w/Brown Specks Floor Tile
20	12"x12" Beige w/Brown Specks Floor Tile Mastic
21	12"x12" Tan, Orange & Green Mix Floor Tile
22	12"x12" Tan, Orange & Green Mix Floor Tile
L	Duct Insulation NOT OBSERVED
M	Boiler Gasket
N	Tectum Panels
NEW	Newly Installed Suspect ACM
O	Boiler Breeching
P	Hot Water Tank Insulation

The following areas were deemed to be inaccessible:

06	Fire Door Insulation
08A	12"x12" Tan Floor Tile Black Mastic
08B	12"x12" Green Floor Tile Black Mastic
09	Vinyl Inlay Tile Black Mastic
10A	Dark Blue Carpet/Light Brown Mastic
11A	Brown Vinyl Baseboard/Brown Mastic
11B	Gray Vinyl Baseboard/Tan Mastic
11C	Green Vinyl Baseboard/Brown Mastic
14	Stair Tread Mastic
17	Tan Carpet Mastic
18A	Black Baseboard Mastic
20	12"x12" Beige w/Brown Specks Floor Tile Mastic
M	Boiler Gasket
N	Tectum Panels
O	Boiler Breeching

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Southside Occupational Academy Building 1700 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Southside Occupational Academy Unit 49031 Building ID 1700

Address 7342 S. Hoyne Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Ceiling Deck										
L	Duct Insulation NOT OBSERVED			Kitchen, Boiler Room	ASSUMED	TSI								
M	Boiler Gasket	40	LF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
N	Tectum Panels	660	SF	Gymnasium Upper Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNOWN			Yes	ACBM with the potential for damage		
O	Boiler Breeching	110	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
P	Hot Water Tank Insulation	400	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Southside Occupational Academy Unit 49031 Building ID 1700

Address 7342 S. Hoyne Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 10/6/2022
Inspector Name Christopher Antonopoulos
100-18281 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01A	Not Observed in Library
01B	
01C	
02	Not Observed 2022
06	
08A	Not Observed in Library
08B	
08C	
09	Not Observed 2022
10A	
10B	*Material Observed in Room 206- 2022
10C	Not Observed 2019 & 2022
10D	Not Observed 2019 & 2022
11A	
11B	
11C	
13A	
13B	
13C	
14	
15	Not Observed Previous Inspections, Observed in 2022
15A	Not Observed Previous Inspections, Observed in 2022
16	Not Observed 2019 & 2022
16A	Not Observed 2019 & 2022

Chicago Public Schools

School Southside Occupational Academy Unit 49031 Building ID 1700

Address 7342 S. Hoyne Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
17	
18	
18A	
19	
20	
21	
22	
HA3	
HAD	
L	Not Observed 2019 & 2022
M	
N	
NEW	
O	
P	

Table II

Management Planner's Review

Chicago Public Schools

School Southside Occupational Academy

Unit 49031

Building ID 1700

Address 7342 S. Hoyne

Chicago, IL, 60636

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	12"x12" Tan Floor Tile	4,200	SF	Throughout Building, 1st & 2nd Floor Corridors, Library, Main Office, Rooms 105, 106, 107, 108, 204 & 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01B	12"x12" Green Floor Tile	3,100	SF	2nd Floor Corridor, Rooms 202, 203, Gym Office & Student Dining	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
01C	12"x12" Gray Floor Tile	10,300	SF	1st & 2nd Floor Corridors, Stair Landings, Throughout Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	Vinyl Inlay Tile	80	SF	Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Fire Door Insulation	120	SF	Mechanical Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12"x12" Tan Floor Tile Black Mastic	4,200	SF	Throughout Building, 1st & 2nd Floor Corridors, Library, Main Office, Rooms 105, 106, 107, 108, 204 & 205	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08B	12"x12" Green Floor Tile Black Mastic	3,100	SF	2nd Floor Corridor, Room 202, 203, Gym Office, Student Dining	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08C	12"x12" Gray Floor Tile Black Mastic	10,300	SF	1st & 2nd Floor Corridors, Stair Landing, Throughout All Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Vinyl Inlay Tile Black Mastic	80	SF	Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10A	Dark Blue Carpet/Light Brown Mastic	200	SF	Kiva Room (Room 116)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10B	Gray Carpet/Light Brown Mastic- NOT OBSERVED*	600	SF	Throughout Classrooms and Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10C	Dark Green Carpet/Light Brown Mastic NOT OBSERVED			Nurse's Office, Room 105	Assumed	MISC					
10D	Bluish Gray Carpet/Light Brown Mastic NOT OBSERVED			Room 204	Assumed	MISC					
11A	Brown Vinyl Baseboard/Brown Mastic	1,800	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11B	Gray Vinyl Baseboard/Tan Mastic	2,500	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
11C	Green Vinyl Baseboard/Brown Mastic	700	LF	2nd Floor Corridor, Rooms 202 & 203, Gym Office, Engineer's Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13A	Brown Vinyl Baseboard	1,800	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13B	Gray Vinyl Baseboard	2,500	LF	Throughout Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
13C	Green Vinyl Baseboard	700	LF	2nd Floor Corridors, Rooms 202 & 203, Engineer's Office, Gym Office	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
14	Stair Tread Mastic	256	SF	North & South Staircase	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12"x12" Blue w/Streaks Vinyl Floor Tile	600	SF	Room 004	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12"x12" Blue w/Streaks Vinyl Floor Tile Mastic	600	SF	Room 004	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Southside Occupational Academy

Unit 49031

Building ID 1700

Address 7342 S. Hoyne

Chicago, IL, 60636

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
16	12"x12" Turquoise w/Streaks Vinyl Floor Tile NOT OBSERVED			Room 003	Assumed	MISC					
16A	12"x12" Turquoise w/ Streaks Vinyl Floor Tile Mastic NOT OBSERVED			Room 003	Assumed	MISC					
17	Tan Carpet Mastic	700	SF	Rooms 003 & 206, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Black Vinyl Baseboard	1,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	Black Baseboard Mastic	1,000	SF	Throughout Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Beige w/Brown Specks Floor Tile	320	SF	Rooms 101-104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Beige w/Brown Specks Floor Tile Mastic	320	SF	Rooms 101-104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Tan, Orange & Green Mix Floor Tile	500	SF	Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Tan, Orange & Green Mix Floor Tile	500	SF	Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA3	2'x4' White Ceiling Tile- No ACBM			Throughout	No ACBM	MISC					
HAD	Spray-On Fireproofing - No ACBM			Beams on the Ceiling Deck	No ACBM	SURFACE					
L	Duct Insulation NOT OBSERVED			Kitchen, Boiler Room	Assumed	TSI					
M	Boiler Gasket	40	LF	Boiler Room	Assumed	TSI	No	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Tectum Panels	660	SF	Gymnasium Upper Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
O	Boiler Breeching	110	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Hot Water Tank Insulation	400	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Southside Occupational Academy

Unit 49031

Building ID 1700

Address 7342 S. Hoyne

Chicago, IL, 60636

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	11/2/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	Not Observed in Library
01B	
01C	
02	Not Observed 2022
06	
08A	Not Observed in Library
08B	
08C	
09	Not Observed 2022
10A	
10B	*Material Observed in Room 206- 2022
10C	Not Observed 2019 & 2022
10D	Not Observed 2019 & 2022

Chicago Public Schools

School Southside Occupational Academy

Unit 49031

Building ID 1700

Address 7342 S. Hoyne

Chicago, IL, 60636

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
11A	
11B	
11C	
13A	
13B	
13C	
14	
15	
15A	
16	Not Observed 2019 & 2022
16A	Not Observed 2019 & 2022
17	
18	
18A	
19	
20	
21	
22	
HA3	
HAD	
L	Not Observed 2019 & 2022
M	
N	
NEW	
O	
P	

Chicago Public Schools

School Southside Occupational
Academy

Unit 49031

Building ID 1700

Address 7342 S. Hoyne

Chicago, IL, 60636

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building, 1st & 2nd Floor Corridors, Library, Main Office, Rooms 105, 106, 107, 108, 204 & 205**

MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Library**

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**
MATERIAL LOCATION: **Throughout Building, 1st & 2nd Floor Corridors, Library, Main Office, Rooms 105, 106, 107, 108, 204 & 205**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed in Library

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor, Rooms 202, 203, Gym Office & Student Dining**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01B**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile**
MATERIAL LOCATION: **2nd Floor Corridor, Rooms 202, 203, Gym Office & Student Dining**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/02/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Stair Landings, Throughout Classrooms**
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **01C**
MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Stair Landings, Throughout Classrooms**
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Vinyl Inlay Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not Observed 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **Vinyl Inlay Tile**
MATERIAL LOCATION: **Gymnasium**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUIDLING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 06
MATERIAL DESCRIPTION: Fire Door Insulation
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Mechanical Rooms
MATERIAL QUANTITY: 120 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Fire Door Insulation**
MATERIAL LOCATION: **Mechanical Rooms**
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/02/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Black Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building, 1st & 2nd Floor Corridors, Library, Main Office, Rooms 105, 106, 107, 108, 204 & 205**

MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Library**

Inspector's Signature: *Christopher Antonopoulos*

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **08A**
MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Black Mastic**
MATERIAL LOCATION: **Throughout Building, 1st & 2nd Floor Corridors, Library, Main Office, Rooms 105, 106, 107, 108, 204 & 205**
MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed in Library

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUILDING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08B
MATERIAL DESCRIPTION: 12"x12" Green Floor Tile Black Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: 2nd Floor Corridor, Room 202, 203, Gym Office, Student Dining
MATERIAL QUANTITY: 3100 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **08B**
MATERIAL DESCRIPTION: **12"x12" Green Floor Tile Black Mastic**
MATERIAL LOCATION: **2nd Floor Corridor, Room 202, 203, Gym Office, Student Dining**
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08C**
MATERIAL DESCRIPTION: **12"x12' Gray Floor Tile Black Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Stair Landing, Throughout All Classrooms**
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **08C**
MATERIAL DESCRIPTION: **12"x12' Gray Floor Tile Black Mastic**
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Stair Landing, Throughout All Classrooms**
MATERIAL QUANTITY: **10300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUIDLING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 09
MATERIAL DESCRIPTION: Vinyl Inlay Tile Black Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Gymnasium
MATERIAL QUANTITY: 80 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF
COMMENTS: Not Observed 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Vinyl Inlay Tile Black Mastic**
MATERIAL LOCATION: **Gymnasium**
MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Not Observed 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUIDLING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10A
MATERIAL DESCRIPTION: Dark Blue Carpet/Light Brown Mastic
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Kiva Room (Room 116)
MATERIAL QUANTITY: 200 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **10A**
MATERIAL DESCRIPTION: **Dark Blue Carpet/Light Brown Mastic**
MATERIAL LOCATION: **Kiva Room (Room 116)**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUIDLING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10B
MATERIAL DESCRIPTION: Gray Carpet/Light Brown Mastic- NOT OBSERVED*
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Throughout Classrooms and Offices

MATERIAL QUANTITY: 600

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS: *Material Observed in Room 206- 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **10B**
MATERIAL DESCRIPTION: **Gray Carpet/Light Brown Mastic- NOT OBSERVED***
MATERIAL LOCATION: **Throughout Classrooms and Offices**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

*Material Observed in Room 206- 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUILDING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10C
MATERIAL DESCRIPTION: Dark Green Carpet/Light Brown Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Nurse's Office, Room 105

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **10C**
MATERIAL DESCRIPTION: **Dark Green Carpet/Light Brown Mastic NOT OBSERVED**
MATERIAL LOCATION: **Nurse's Office, Room 105**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUILDING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 10D
MATERIAL DESCRIPTION: Bluish Gray Carpet/Light Brown Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 204

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **10D**
MATERIAL DESCRIPTION: **Bluish Gray Carpet/Light Brown Mastic NOT OBSERVED**
MATERIAL LOCATION: **Room 204**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard/Brown Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **11A**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard/Brown Mastic**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard/Tan Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **11B**
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard/Tan Mastic**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **Green Vinyl Baseboard/Brown Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridor, Rooms 202 & 203, Gym Office, Engineer's Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **11C**
MATERIAL DESCRIPTION: **Green Vinyl Baseboard/Brown Mastic**
MATERIAL LOCATION: **2nd Floor Corridor, Rooms 202 & 203, Gym Office, Engineer's Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/02/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **13A**
MATERIAL DESCRIPTION: **Brown Vinyl Baseboard**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13B**
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **13B**
MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13C**
MATERIAL DESCRIPTION: **Green Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd Floor Corridors, Rooms 202 & 203, Engineer's Office, Gym Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **13C**
MATERIAL DESCRIPTION: **Green Vinyl Baseboard**
MATERIAL LOCATION: **2nd Floor Corridors, Rooms 202 & 203, Engineer's Office, Gym Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/02/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUILDING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14
MATERIAL DESCRIPTION: Stair Tread Mastic
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: North & South Staircase
MATERIAL QUANTITY: 256 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Stair Tread Mastic**
MATERIAL LOCATION: **North & South Staircase**
MATERIAL QUANTITY: **256** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUILDING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15
MATERIAL DESCRIPTION: 12"x12" Blue w/Streaks Vinyl Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW
MATERIAL LOCATION: Room 004
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Not Observed Previous Inspections, Observed in 2022

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **12"x12" Blue w/Streaks Vinyl Floor Tile**
MATERIAL LOCATION: **Room 004**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12"x12" Blue w/Streaks Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 004**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed Previous Inspections, Observed in 2022**

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **15A**
MATERIAL DESCRIPTION: **12"x12" Blue w/Streaks Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 004**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Turquoise w/Streaks Vinyl Floor Tile NOT OBSERVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 003**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed 2019 & 2022**

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **12"x12" Turquoise w/Streaks Vinyl Floor Tile NOT OBSERVED**
MATERIAL LOCATION: **Room 003**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUILDING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 16A
MATERIAL DESCRIPTION: 12"x12" Turquoise w/ Streaks Vinyl Floor Tile Mastic NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 003

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **16A**
MATERIAL DESCRIPTION: **12"x12" Turquoise w/ Streaks Vinyl Floor Tile Mastic NOT OBSERVED**
MATERIAL LOCATION: **Room 003**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Tan Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 003 & 206, Principal's Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **Tan Carpet Mastic**
MATERIAL LOCATION: **Rooms 003 & 206, Principal's Office**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/02/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **18A**
MATERIAL DESCRIPTION: **Black Baseboard Mastic**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101-104**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Specks Floor Tile**
MATERIAL LOCATION: **Rooms 101-104**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 101-104**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **12"x12" Beige w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 101-104**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA3**
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile- No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **HA3**
MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile- No ACBM**
MATERIAL LOCATION: **Throughout**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HAD**
MATERIAL DESCRIPTION: **Spray-On Fireproofing - No ACBM**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Beams on the Ceiling Deck**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **HAD**
MATERIAL DESCRIPTION: **Spray-On Fireproofing - No ACBM**
MATERIAL LOCATION: **Beams on the Ceiling Deck**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 49031 BUIDLING ID: 1700
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos
SCHOOL NAME: Southside Occupational Academy INSPECTION DATE: 10/6/2022
ADDRESS: 7342 S. Hoyne IDPH LICENSE NO: 100-18281

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L
MATERIAL DESCRIPTION: Duct Insulation NOT OBSERVED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen, Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **L**
MATERIAL DESCRIPTION: **Duct Insulation NOT OBSERVED**
MATERIAL LOCATION: **Kitchen, Boiler Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Not Observed 2019 & 2022

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Boiler Gasket**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **M**
MATERIAL DESCRIPTION: **Boiler Gasket**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Tectum Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gymnasium Upper Walls**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Christopher Antonopoulos

Date: **10/06/2022**

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **N**
MATERIAL DESCRIPTION: **Tectum Panels**
MATERIAL LOCATION: **Gymnasium Upper Walls**
MATERIAL QUANTITY: **660** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/02/2022

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Boiler Breeching**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **110** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **0**
MATERIAL DESCRIPTION: **Boiler Breeching**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **110** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/02/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Hot Water Tank Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUIDLING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **P**
MATERIAL DESCRIPTION: **Hot Water Tank Insulation**
MATERIAL LOCATION: **Boiler Room**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/02/2022**

Chicago Public Schools

TEM Environmental, Inc.
2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
MATERIAL CATEGORY: **MISC** FRIABLE:
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE REASON:
DAMAGE UNITS:
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: **11/02/2022** _____

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" Tan, Orange & Green Mix Floor Tile**
MATERIAL LOCATION: **Room 207**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **12"x12" Tan, Orange & Green Mix Floor Tile**
MATERIAL LOCATION: **Room 207**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  _____ Date: **11/02/2022** _____

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**
SCHOOL NAME: **Southside Occupational Academy** INSPECTION DATE: **10/6/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12"x12" Tan, Orange & Green Mix Floor Tile**
MATERIAL LOCATION: **Room 207**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION:
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____

Christopher Antonopoulos

Date: 10/06/2022

Chicago Public Schools

TEM Environmental, Inc. 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **49031** BUILDING ID: **1700**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**
SCHOOL NAME: **Southside Occupational Academy** REVIEW DATE: **11/2/2022**
ADDRESS: **7342 S. Hoyne** IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12"x12" Tan, Orange & Green Mix Floor Tile**

MATERIAL LOCATION: **Room 207**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **11/02/2022**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS
has completed the **ASBESTOS INSPECTOR'S REFRESHER** course and successfully passed the
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N. Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff". The signature is written in a cursive style and is positioned above the printed name of the Director of Training.


Director of Training

Nicholas J. Peneff

Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER	ISSUED	EXPIRES
100 - 18281	2/10/2022	05/15/2023

CHRISTOPHER J ANTONOPO
1736 W 102nd ST
CHICAGO, IL 60643

Environmental Health



ENDORSEMENT	TC EXPIRES
INSPECTOR	6/1/2022

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

TODD T HUFFER
315 HATLEN COURT
MT. PROSPECT, IL 60056

2/18/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

			ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS		TC EXPIRES
ID NUMBER 100 - 09870	ISSUED 2/18/2022	EXPIRES 05/15/2023	INSPECTOR				11/1/2022
TODD T HUFFER 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health					MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL		11/19/2022 10/20/2022
					Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.		

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255


Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Todd Huffer

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265


Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed