

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-0526  
SCHOOL NAME: Chicago Vocational High School  
ADDRESS OF SCHOOL: 2100 E. 87th St.  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/15/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 9/29/2022 ENROLLMENT 638  
IDPH INSPECTOR LICENSE NUMBER: 100-18281  
IDPH LICENSED INSPECTOR NAME (Please Print): Christopher Antonopoulos  
IDPH MP LICENSE NUMBER: 100-09870  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Todd Huffer

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



10/18/2022

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: N

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Chicago Vocational High School**

2100 E. 87th St.  
Chicago, IL, 60617

Unit: 53011  
Building ID: 1010

IDPH ID Number: 14-016-2990-0526

**REPORT DATE:**

Tuesday, October 18, 2022

**Prepared for:**

**Chicago Public Schools  
42 W. Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

10/18/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 53011            Region: 06            IDPH ID: 14-016-2990-0526

School: Chicago Vocational High School            Building ID: 1010

Address: 2100 E. 87th St.

Chicago, IL, 60617

Building Contact: Allen, Darren

Contact Phone: 7737101931

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/29/2022

Review Date: 10/18/2022

Inspector: Christopher Antonopoulos

Inspector IDPH License: 100-18281

Management Planner: Todd Huffer

Management Planner IDPH License: 100-09870

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Todd Huffer  
100-09870

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 18, 2022

RE: Chicago Vocational High School, Unit 53011  
2100 E. 87th St.  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Chicago Vocational High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Chicago Vocational High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Chicago Vocational High School  
Address: 2100 E. 87th St.  
IDPH ID: 14-016-2990-0526  
Contact: Allen, Darren

Unit: 53011  
Chicago, IL, 60617  
Building ID: 1010  
Phone: 7737101931

Region: 06

### 2. Description of Facility

Original Construction: 1941  
Total Square Footage: 521300  
Current Occupancy: 638

Additional Construction: 1943,1943  
No of Floors: 3

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Christopher Antonopoulos



Signature:  
Date: 9/29/2022

Inspector IDPH license # 100-18281  
Reinspection Date: 9/29/2022

### 6. Management Planner

Management Planner Name: Todd Huffer



Signature:  
Date: 10/18/2022

Management Planner IDPH license # 100-09870

### 7. Review Date: 10/18/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 10/18/2022

Name: Richard J.Schleyer



## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Chicago Vocational High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1010:

15I	12x12 Black w/White Speckles Floor Tile
15L	12x12 White w/Brown Speckles Floor Tile
15R	12x12 Purple w/White Checkerboard Floor Tile
28D	9x9 Light Gray Floor Tile ABATED
32R	12x12 Purple/White Checkerboard Floor Tile Mastic
32X	Gold and Multicolor Dark Blue Checkerboard Floor Tile Mastic-NOT OBSERVED
51	Black Chalkboards
52	Hard Plaster
53	12"x12" Blue & White w/Green Specks Floor Tile



54	Mastic associated with 12"x12" Blue & White w/Green Specks Floor Tile
55	12"x12" White, Blue & Beige Mix Floor Tile
56	Mastic associated with 12"x12" White, Blue & Beige Mix Floor Tile
57	12x12 Light Grey & Grey Mix Floor Tile
58	12x12 Light Grey & Grey Mix Floor Tile Mastic
HA-1000	Transite Counter and Tabletops
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 1010:

51	Black Chalkboards
52	Hard Plaster
53	12"x12" Blue & White w/Green Specks Floor Tile
54	Mastic associated with 12"x12" Blue & White w/Green Specks Floor Tile
55	12"x12" White, Blue & Beige Mix Floor Tile
56	Mastic associated with 12"x12" White, Blue & Beige Mix Floor Tile
57	12x12 Light Grey & Grey Mix Floor Tile
58	12x12 Light Grey & Grey Mix Floor Tile Mastic
NEW	Newly Installed Suspect ACM

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

13F	9x9 Black w/Cream & Green Streaks Floor Tile
150A	12x12 White w/Multicolored Specks Vinyl Floor Tile
150AM	12x12 White w/Multi-colored specks Vinyl Floor Tile Mastic
151	Gray Linoleum
152	12x12 Purple w/Dark Purple Specks Vinyl Floor Tile
152M	12x12 Purple w/Dark Purple Specks Vinyl Floor Tile Mastic
153	12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile
153M	12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile Mastic
155	12x12 White w/Specks Vinyl Floor Tile
155M	12x12 White w/Specks Vinyl Floor Tile Mastic
156	12x12 Beige w/Specks Vinyl Floor Tile
156M	12x12 Beige w/Specks Vinyl Floor Tile Mastic
157	12x12 Pink w/Specks Vinyl Floor Tile
157M	12x12 Pink w/Specks Vinyl Floor Tile Mastic
158	12x12 Tan Vinyl Floor Tile
158M	12x12 Tan Vinyl Floor Tile Mastic
159	12x12 Algae Green w/Streaks Vinyl Floor Tile
159M	12x12 Algae Green w/Streaks Vinyl Floor Tile Mastic
15A	12x12 Beige & Purple Checker Board Patterned Floor Tile
15B	12x12 Cream & Tan Checker Board Patterned Floor Tile Mastic
15L	12x12 White w/Brown Speckles Floor Tile
15O	12x12 Turquoise W/Light Gray Checkerboard Floor Tile
15R	12x12 Purple w/White Checkerboard Floor Tile
15V	12x12 Dark & Light Blue Checkerboard Floor Tile NOT OBSERVED
15W	12x12 Gray/Light Blue Speckled Floor Tile
160	12x12 White w/Streaks Vinyl Floor Tile
160M	12x12 White w/Streaks Vinyl Floor Tile Mastic
161	Linoleum Gray w/Black & White Stripes
162	12x12 Red Vinyl Floor Tile
162M	12x12 Red Vinyl Floor Tile Mastic
163	12x12 Black Vinyl Floor Tile

163M	12x12 Black Vinyl Floor Tile Mastic
164	Black Spray-On Fireproofing
165	12x12 Dark Blue w/Streaks Vinyl Floor Tile
165M	12x12 Dark Blue w/Streaks Vinyl Floor Tile Mastic
166	12x12 Light Blue w/Streaks Vinyl Floor Tile
166M	12x12 Light Blue w/Streaks Vinyl Floor Tile Mastic
167	12x12 Brown w/Streaks Vinyl Floor Tile
167M	12x12 Brown w/Streaks Vinyl Floor Tile Mastic
168	12x12 Blue Vinyl Floor Tile
168M	12x12 Blue Vinyl Floor Tile Mastic
169	MJP E/F/V on Aircell Pipe Insulation
170	12x12 Brown w/Black & White Specks Vinyl Floor Tile
170M	12x12 Brown w/Black & White Specks Vinyl Floor Tile Mastic
18A	Mauve Carpet Mastic
18B	Blue-Speckled Carpet Mastic
18C	Blue Carpet Mastic
18D	Beige Carpet Mastic
200	Linoleum with Specks
200A	Linoleum with Specks Mastic
201	Multicolor Carpet Mastic
29A	12x12 Cream w/Multicolor Beige Checkerboard Floor Tile
29H	12x12 Multicolor Beige Floor Tile
30F	9x9 Black with Cream and Green Streaks Floor Tile Mastic
31F	12x12 Beige w/Brown & White Streaks Floor Tile Mastic
32	12x12 Beige Floor Tile
32A	12x12 Beige and Purple Checkerboard Floor Tile Mastic
32D	12x12 Reddish Orange Floor Tile Mastic-NOT OBSERVED
32J	12x12 Red Floor Tile Mastic
32L	White and Brown Speckles Floor Tile Mastic-NOT OBSERVED
32O	12x12 Turquoise & Light Gray Checkerboard Floor Tile Mastic
32P	Black & Maroon Checkerboard Floor Tile Mastic
32Q	12x12 Reddish Brown w/White Streak Floor Tile Mastic-NOT OBSERVED
32R	12x12 Purple/White Checkerboard Floor Tile Mastic
32U	Peach & Cream Speckles Floor Tile Mastic-NOT OBSERVED
32V	Dark and Light Blue Checkerboard Floor Tile Mastic
32X	Gold and Multicolor Dark Blue Checkerboard Floor

	Tile Mastic-NOT OBSERVED
32Z	12x12 Multicolor Light Blue Floor Tile Mastic
33	12x12 Red w/White and Black Blotches Floor Tile Mastic
33A	12x12 Creme w/Multicolor Beige Checkerboard Patterned Floor Tile Mastic
33G	12x12 White Floor Tile Mastic
33K	12x12 Turquoise w/Gray Floor Tile Mastic
36	9x9 Gray Tiles
37	9x9 Brown Floor Tile
38	12x12 Beige Floor Tile
38M	12x12 Beige Floor Tile Mastic
39	12x12 White w/Beige Specks Floor Tile
39M	12x12 White w/Beige Specks Floor Tile Mastic
41	12x12 Beige Speckled Floor Tile
41M	12x12 Beige Speckled Floor Tile Mastic
42M	12x12 Red and White Checkered Floor Tile Mastic
43	12x12 Brown, Beige and Red Floor Tile
43M	12x12 Brown, Beige and Red Floor Tile Mastic
45	Gray Terrazo
46	Beige Terrazzo
47	1'x1' Ceiling Tile
47M	1'x1' Ceiling Tile Adhesive
48	2'x4' Lay-In Ceiling Panels
49	2'x4' Lay-In Smooth Ceiling Panels
50	2'x2' Lay-In Ceiling Panels
51	Black Chalkboards
52	Hard Plaster
53	12"x12" Blue & White w/Green Specks Floor Tile
54	Mastic associated with 12"x12" Blue & White w/Green Specks Floor Tile
55	12"x12" White, Blue & Beige Mix Floor Tile
56	Mastic associated with 12"x12" White, Blue & Beige Mix Floor Tile
57	12x12 Light Grey & Grey Mix Floor Tile
58	12x12 Light Grey & Grey Mix Floor Tile Mastic
AP-1	Acoustical Plaster
B	Joint Insulation on Fiberglass Insulated Piping
BB-4A	Black Baseboard
BB-5	Brown Baseboard
BB-5A	Green Baseboard
BB-6	Brown Baseboard
BB-7	Blue Baseboard
BBM-4A	Black Baseboard Mastic
BBM-5	Mastic Beneath Brown Baseboard
BBM-5A	Green Baseboard Mastic
BBM-7	Blue Baseboard Mastic
DE-1	12x12 Yellow Floor Tile

DW-1	Drywall
DW-2	Drywall Compound
FT-1	12x12 Beige, Gray w/Tan Pattern Floor Tile
FT-10	12x12 Green w/White & Dark Green Specks Floor Tile
FT-11	12x12 Cream w/White & Dark Green Floor Tile
FT-2	12x12 Cream w/Multi-Colored Specks Floor Tile
FT-3	12x12 Yellow Floor Tile
FT-5	12x12 Light Blue Floor Tile
FT-9	Dark Blue w/Gray & Light Blue Linoleum
FTM-1	12x12 Beige Gray w/Tan Pattern Floor Tile Mastic
FTM-10	12x12 Green w/White & Dark Green Specks VFT Mastic
FTM-2	12x12 Cream w/Multi-Colored Specks Floor Tile Mastic
FTM-3	12x12 Yellow Floor Tile Mastic
FTM-4	12x12 Brown Floor Tile Mastic
FTM-5	12x12 Light Blue Floor Tile Mastic
FTM-8	12x12 Tan w/ Brown & White Streaks Floor Tile Mastic
FTM-9	Dark Blue w/Gray & Light Blue Linoleum Mastic
HA-1000	Transite Counter and Tabletops
NEW	Newly Installed Suspect ACM
S	Fireproofing
Y	12x12 White, Black, Red & Gray Floor Tile
Z	12x12 White, Black, Red & Gray Floor Tile Mastic

The following areas were deemed to be inaccessible:

150AM	12x12 White w/Multi-colored specks Vinyl Floor Tile Mastic
152M	12x12 Purple w/Dark Purple Specks Vinyl Floor Tile Mastic
155M	12x12 White w/Specks Vinyl Floor Tile Mastic
156M	12x12 Beige w/Specks Vinyl Floor Tile Mastic
157M	12x12 Pink w/Specks Vinyl Floor Tile Mastic
158M	12x12 Tan Vinyl Floor Tile Mastic
159M	12x12 Algae Green w/Streaks Vinyl Floor Tile Mastic
15B	12x12 Cream & Tan Checker Board Patterned Floor Tile Mastic
160M	12x12 White w/Streaks Vinyl Floor Tile Mastic
162M	12x12 Red Vinyl Floor Tile Mastic
163M	12x12 Black Vinyl Floor Tile Mastic
165M	12x12 Dark Blue w/Streaks Vinyl Floor Tile Mastic
166M	12x12 Light Blue w/Streaks Vinyl Floor Tile Mastic

167M	12x12 Brown w/Streaks Vinyl Floor Tile Mastic
168M	12x12 Blue Vinyl Floor Tile Mastic
170M	12x12 Brown w/Black & White Specks Vinyl Floor Tile Mastic
18A	Mauve Carpet Mastic
18B	Blue-Speckled Carpet Mastic
18C	Blue Carpet Mastic
200A	Linoleum with Specks Mastic
201	Multicolor Carpet Mastic
30	9x9 Grey Floor Tile Mastic
30B	9x9 Dark Beige w/Brown Streaks Floor Tile Mastic
30D	9x9 White w/Gray Streaks Floor Tile Mastic
30E	Beige w/Green Checkerboard Floor Tile Mastic
30F	9x9 Black with Cream and Green Streaks Floor Tile Mastic
30G	White & Black Streaks Floor Tile Mastic
31C	9x9 Pink Floor Tile Mastic
31E	9x9 Gray Floor Tile Mastic
31F	12x12 Beige w/Brown & White Streaks Floor Tile Mastic
31G	9x9 Maroon w/Beige Checkerboard Patterned Floor Tile Mastic (Not Observed)
31J	9x9 Red w/Speckles Floor Tile Mastic
31K	9x9 Gray with Dark Gray Streaks Floor Tile Mastic
31L	9x9 Dark Gray w/Black Streaks Floor Tile Mastic
31N	White w/Black Streaks Floor Tile Mastic
32A	12x12 Beige and Purple Checkerboard Floor Tile Mastic
32AA	12x12 Tan w/Multicolor Floor Tile Mastic
32B	12x12 Cream & Tan Checkerboard Floor Tile Mastic
32E	12x12 Cream Floor Tile Mastic
32F	12x12 Brown (Multicolored Beige) Floor Tile Mastic
32J	12x12 Red Floor Tile Mastic
32K	12x12 Cream w/Red Streaks Floor Tile Mastic
32M	12x12 Black Floor Tile Mastic (As Edging)
32O	12x12 Turquoise & Light Gray Checkerboard Floor Tile Mastic
32P	Black & Maroon Checkboard Floor Tile Mastic
32V	Dark and Light Blue Checkerboard Floor Tile Mastic
32W	12x12 Gray/Light Blue Speckled Floor Tile Mastic
33	12x12 Red w/White and Black Blotches Floor Tile Mastic
33A	12x12 Creme w/Multicolor Beige Checkerboard Patterned Floor Tile Mastic
33E	12x12 Cream with Tan Floor Tile Mastic

33G	12x12 White Floor Tile Mastic
33K	12x12 Turquoise w/Gray Floor Tile Mastic
38M	12x12 Beige Floor Tile Mastic
39M	12x12 White w/Beige Specks Floor Tile Mastic
42M	12x12 Red and White Checkered Floor Tile Mastic
43M	12x12 Brown, Beige and Red Floor Tile Mastic
47M	1'x1' Ceiling Tile Adhesive
BBM-4A	Black Baseboard Mastic
BBM-5	Mastic Beneath Brown Baseboard
BBM-5A	Green Baseboard Mastic
BBM-7	Blue Baseboard Mastic
DE-2	12x12 Yellow Floor Tile Mastic
FTM-1	12x12 Beige Gray w/Tan Pattern Floor Tile Mastic
FTM-10	12x12 Green w/White & Dark Green Specks VFT Mastic
FTM-2	12x12 Cream w/Multi-Colored Specks Floor Tile Mastic
FTM-3	12x12 Yellow Floor Tile Mastic
FTM-5	12x12 Light Blue Floor Tile Mastic
FTM-9	Dark Blue w/Gray & Light Blue Linoleum Mastic
S	Fireproofing
Z	12x12 White, Black, Red & Gray Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Christopher Antonopoulos, IDPH License # 100-18281. The Management Plan was updated by Todd Huffer, IDPH License # 100-09870. Inspector and Management Planner Licenses are included in Appendix B.



### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	7/13/2021
	7/13/2021
	7/13/2021
	7/13/2021
	7/13/2021
	7/13/2021

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Chicago Vocational High School Building 1010 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
13A	9x9 Tan Floor Tile ABATED			1939- Rooms 206, 218	ABATED	MISC								
13B	9x9 Dark Beige w/Brown Streaks Floor Tile ABATED			Rooms 250 and 280	ABATED	MISC								
13D	9x9 White w/Gray Streaks Floor Tile ABATED			Rooms 255 and 273	ABATED	MISC								
13E	9x9 Beige w/Streaks & Green Checkerboard Patterned Floor Tile	200	SF	Main Office (Vault)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13F	9x9 Black w/Cream & Green Streaks Floor Tile	2,900	SF	1st Floor Auditorium Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13G	9x9 Cream w/Black Streaks Floor Tile ABATED			Rooms 021, 013, 012	ABATED	MISC								
13H	9x9 Beige w/Multi-Colored Streaks Floor Tile	260	SF	1st Floor Women's Restroom and Corridor (West End)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14B	Black Linoleum			Room 130	NO_ACBM	MISC								
150A	12x12 White w/Multicolored Specks Vinyl Floor Tile	700	SF	Rooms 073, 156, 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
150AM	12x12 White w/Multi-colored specks Vinyl Floor Tile Mastic	700	SF	Room 023, 156, 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
151	Gray Linoleum	1,000	SF	Rooms 150, 012, 009	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
152	12x12 Purple w/Dark Purple Specks Vinyl Floor Tile	300	SF	Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
152M	12x12 Purple w/Dark Purple Specks Vinyl Floor Tile Mastic	300	SF	Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
153	12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile	2,900	SF	Room 267 (Anthony Wing)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
153M	12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile Mastic	2,900	SF	Room 267 (Anthony Wing)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
155	12x12 White w/Specks Vinyl Floor Tile	300	SF	Room 159	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
155M	12x12 White w/Specks Vinyl Floor Tile Mastic	300	SF	Room 159	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
156	12x12 Beige w/Specks Vinyl Floor Tile	300	SF	Room 159	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
156M	12x12 Beige w/Specks Vinyl Floor Tile Mastic	300	SF	Room 159	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
157	12x12 Pink w/Specks Vinyl Floor Tile	500	SF	Room 179	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
157M	12x12 Pink w/Specks Vinyl Floor Tile Mastic	500	SF	Room 179	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
158	12x12 Tan Vinyl Floor Tile	1,000	SF	Mobile Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE



# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Checkerboard Floor Tile (Not Observed)													
15Z	12x12 Multicolor Light Blue Floor Tile			Room 014	NO_ACBM	MISC								
160	12x12 White w/Streaks Vinyl Floor Tile	300	SF	Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
160M	12x12 White w/Streaks Vinyl Floor Tile Mastic	300	SF	Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
161	Linoleum Gray w/Black & White Stripes	4,000	SF	Room 009, 012, 145, 161, 208 & 208A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
162	12x12 Red Vinyl Floor Tile	456	SF	Rooms 117 & 217	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
162M	12x12 Red Vinyl Floor Tile Mastic	456	SF	Rooms 117 & 217	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
163	12x12 Black Vinyl Floor Tile	456	SF	Rooms 117 & 217 (Auditorium)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
163M	12x12 Black Vinyl Floor Tile Mastic	456	SF	Rooms 117 & 217 (Auditorium)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
164	Black Spray-On Fireproofing	250	SF	Hangar	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
165	12x12 Dark Blue w/Streaks Vinyl Floor Tile	288	SF	Men's & Women's Toilets in Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
165M	12x12 Dark Blue w/Streaks Vinyl Floor Tile Mastic	288	SF	Men's & Women's Toilets - Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
166	12x12 Light Blue w/Streaks Vinyl Floor Tile	144	SF	Women's Toilets - Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
166M	12x12 Light Blue w/Streaks Vinyl Floor Tile Mastic	144	SF	Women's Toilets - Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
167	12x12 Brown w/Streaks Vinyl Floor Tile	144	SF	Men's Toilet - Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
167M	12x12 Brown w/Streaks Vinyl Floor Tile Mastic	144	SF	Men's Toilets - Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
168	12x12 Blue Vinyl Floor Tile	70	SF	Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
168M	12x12 Blue Vinyl Floor Tile Mastic	70	SF	Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
169	MJP E/F/V on Aircell Pipe Insulation	3	SF	Hangar- Storage Room 7	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
170	12x12 Brown w/Black & White Specks Vinyl Floor Tile	148	SF	Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
170M	12x12 Brown w/Black & White Specks Vinyl Floor Tile Mastic	148	SF	Hangar	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18A	Mauve Carpet Mastic	5,600	SF	Rooms 125, 126, 125, 134A, 135,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				166, 231 & 252A										
18B	Blue-Speckled Carpet Mastic	500	SF	Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18C	Blue Carpet Mastic	1,600	SF	Rooms 143, 143A & 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18D	Beige Carpet Mastic	3,000	SF	Rooms 125, 126, 134A, 135, 166, 231, 237 & 252A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18E	Burgundy Carpet Mastic			Room 126	NO_ACBM	MISC								
18F	Orange Carpet Mastic			Room 231	NO_ACBM	MISC								
200	Linoleum with Specks	750	SF	Room 009	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
200A	Linoleum with Specks Mastic	750	SF	Room 009	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
201	Multicolor Carpet Mastic	700	SF	109	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Transite	3,830	SF	Showers Area, Old Garage Siding, Kitchen Receiving, Room 167 & Interior of Old Garage	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21A	Corrugated Transite Panels ABATED			Greenhouse	ABATED	MISC								
28	9x9 Brown Floor Tile	2,800	SF	1943 Building-Room 262 & Hallway	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28C	9x9 Pink Floor Tile	2,800	SF	1943 Building-Room 282	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28D	9x9 Light Gray Floor Tile ABATED			1943 Building-Room 021	ABATED	MISC					Yes			
28E	9x9 Gray Floor Tile	2,800	SF	1943 Building-Room 286	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28F	9x9 Beige w/Brown & White Streaks	1,000	SF	1943 Building-Rooms 280, 282 (Back Room), and 250	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28G	9x9 Maroon w/Beige Checkerboard Floor Tile	2,375	SF	1943 Building-Room 273, 279, 281, 265, 267	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28H	9x9 Tan Speckled Floor Tile	1,600	SF	1943 Building-Rooms 281 and 299	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28J	9x9 Red with Speckles Floor Tile	800	SF	1943 Building-Rooms 256 and 279	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28K	9x9 Gray w/Dark Gray Streaks Flor Tile	2,100	SF	1943- Room 286	CHR	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
30B	9x9 Dark Beige w/Brown Streaks Floor Tile Mastic	1,000	SF	Rooms 250 and 280	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30D	9x9 White w/Gray Streaks Floor Tile Mastic	600	SF	Rooms 255 and 273	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30E	Beige w/Green Checkerboard Floor Tile Mastic	200	SF	Main Office (Vault)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30F	9x9 Black with Cream and Green Streaks Floor Tile Mastic	85	SF	Auditorium 1st Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30G	White & Black Streaks Floor Tile Mastic	280	SF	Room 021, 013, 012	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30H	9x9 Beige w/Multicolor Streaks Floor Tile Mastic	260	SF	1st Floor Women's Restroom and Corridor (West End)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	9x9 Brown Floor Tile Mastic ABATED			1943 Building-Room 262 and Hallway	ABATED	MISC								
31C	9x9 Pink Floor Tile Mastic	2,800	SF	1943 Building-Room 282	CHR	MISC	N		0		No	ACBM with the potential for damage		LOW
31D	9x9 Light Gray Floor Tile Mastic ABATED			1943 Building-Rooms 021 and 288	ABATED	MISC								
31E	9x9 Gray Floor Tile Mastic	2,800	SF	1943 Building-Room 286	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31F	12x12 Beige w/Brown & White Streaks Floor Tile Mastic	500	SF	1943 Building-Rooms 250 and 280	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31G	9x9 Maroon w/Beige Checkerboard Patterned Floor Tile Mastic (Not Observed)	2,375	SF	1943 Building-Rooms 273, 279, 281, 265, 267	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31H	9x9 Tan Speckled Floor Tile Mastic ABATED			1943 Building-Rooms 279 & 281	ABATED	MISC								
31J	9x9 Red w/Speckles Floor Tile Mastic	800	SF	1943 Building-Rooms 256 and 279	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31K	9x9 Gray with Dark Gray Streaks Floor Tile Mastic	900	SF	1943 Building-Room 286 (Front) (Back), 285, 287	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31L	9x9 Dark Gray w/Black Streaks Floor Tile Mastic	900	SF	Room 288	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31N	White w/Black Streaks Floor Tile Mastic	600	SF	1943 Building-Rooms 255, 273, & 288	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12x12 Beige Floor Tile	370	SF	Rooms 175, 216 & Hanger	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32A	12x12 Beige and Purple Checkerboard Floor Tile Mastic	500	SF	Room 002	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32AA	12x12 Tan w/Multicolor Floor Tile Mastic	2,690	SF	1st, 2nd Floor	CHR	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Engineer Office, 008, Teachers' Lounge, 136, Auditorium, East Dressing Room, Football Storage								potential for damage		
32B	12x12 Cream & Tan Checkerboard Floor Tile Mastic	500	SF	Room 145	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32D	12x12 Reddish Orange Floor Tile Mastic-NOT OBSERVED			Room 206	ASSUMED	MISC								
32E	12x12 Cream Floor Tile Mastic	800	SF	Room 214	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32F	12x12 Brown (Multicolored Beige) Floor Tile Mastic	11,265	SF	Room 010	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32G	12x12 Gray Floor Tile Mastic ABATED			Rooms 260, 261, 265, 268, 269, and 270A	ABATED	MISC								
32H	12x12 Burnt Orange Floor Tile Mastic			Room 2nd Floor Teacher's Room		MISC								
32I	12x12 Black w/White Speckles Floor Tile Mastic			Room 206 & 208	NO_ACBM	MISC								
32J	12x12 Red Floor Tile Mastic	2,000	SF	Rooms 104, 241B, 256, and 258	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32K	12x12 Cream w/Red Streaks Floor Tile Mastic		SF	Room 208	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32L	White and Brown Speckles Floor Tile Mastic-NOT OBSERVED			Room 208, Main Office	ASSUMED	MISC								
32M	12x12 Black Floor Tile Mastic (As Edging)	115	SF	Room 212	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32O	12x12 Turquoise & Light Gray Checkerboard Floor Tile Mastic	2,000	SF	Rooms 009, 023, 105, 156	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32P	Black & Maroon Checkerboard Floor Tile Mastic	400	SF	Auditorium Pit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32Q	12x12 Reddish Brown w/White Streak Floor Tile Mastic-NOT OBSERVED			Room 256	ASSUMED	MISC								
32R	12x12 Purple/White Checkerboard Floor Tile Mastic	1,200	SF	Room 020 & 023	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
32U	Peach & Cream Speckles Floor Tile Mastic-NOT OBSERVED			Room 108	ASSUMED	MISC								
32V	Dark and Light Blue Checkerboard Floor Tile Mastic	500	SF	Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32W	12x12 Gray/Light Blue Speckled Floor Tile Mastic	2,000	SF	Rooms 109, 112, 113 & 114	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32X	Gold and Multicolor Dark Blue	600	SF	Rooms 115, 118	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Checkerboard Floor Tile Mastic-NOT OBSERVED											potential for damage		
32Z	12x12 Multicolor Light Blue Floor Tile Mastic			Room 014	ASSUMED	MISC								
33	12x12 Red w/White and Black Blotches Floor Tile Mastic	3,500	SF	1943 Building-Rooms 217, 117, 022, 020, and 019	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33A	12x12 Creme w/Multicolor Beige Checkerboard Patterned Floor Tile Mastic	8,000	SF	1943 Building-Room 008, 024, 135, 136, 259, 266, 338	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33B	12x12 Light and Dark Gray Floor Tile Mastic-NOT OBSERVED			1943 Building-Room 260		MISC								
33C	12x12 Dark Gray w/Black and Orange Streaks Floor Tile Mastic-NOT OBSERVED			1943 Building-Rooms 260, 268, 269 & 271		MISC								
33D	12x12 Maroon Floor Tile Mastic	2,800	SF	1943 Building-Room 262	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33E	12x12 Cream with Tan Floor Tile Mastic	2,335	SF	1943 Building-Women's Restroom 2nd Floor (2043), 270	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33G	12x12 White Floor Tile Mastic	1,200	SF	1943 Building-Room 271	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
33I	12x12 Beige Floor Tile Mastic			1943 Building-Corridor	NO_ACBM	MISC								
33J	Dark, Light Beige/Gray Checkerboard Pattern Floor Tile Mastic ABATED			1943 Building-Room 282 (Back Room)	ABATED	MISC								
33K	12x12 Turquoise w/Gray Floor Tile Mastic	2,400	SF	1943 Building - Rooms 009, 023	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Mastic Beneath Linoleum	5,600	SF	Gym (Room 251) 253	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34A	Red, Black, Brown, and Tan Linoleum Pattern Mastic NOT OBSERVED			Auditorium 1st and 2nd Floor Foyer		MISC								
34B	Black Linoleum Mastic NOT OBSERVED			Room 130		MISC								
35	Grey Linoleum			Room 208	NO_ACBM	MISC								
36	9x9 Gray Tiles		SF	Room 288	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	9x9 Brown Floor Tile	720	SF	286A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12x12 Beige Floor Tile	5,600	SF	3rd Floor Hallway, Rooms 28, 100, 120, 127, and Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
38M	12x12 Beige Floor Tile Mastic	5,600	SF	3rd Floor Hallway, Rooms 28, 100, 120, 127 and Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12x12 White w/Beige Specks Floor Tile	123,000	SF	1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39M	12x12 White w/Beige Specks Floor Tile Mastic	123,000	SF	1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12x12 Yellow with White Floor Tile			Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway	NO_ACBM	MISC								
40M	12x12 Yellow w/White Floor Tile Mastic			Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway	NO_ACBM	MISC								
41	12x12 Beige Speckled Floor Tile	1,100	SF	Rooms 322 & 326	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41M	12x12 Beige Speckled Floor Tile Mastic	1,100	SF	Rooms 322 & 326	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12x12 Red & White Checkered Floor Tile ABATED			Room 179	ABATED	MISC								
42M	12x12 Red and White Checkered Floor Tile Mastic	500	SF	Room 179	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12x12 Brown, Beige and Red Floor Tile	2,000	SF	Cafeteria Court	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43M	12x12 Brown, Beige and Red Floor Tile Mastic	2,000	SF	Cafeteria Court	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Beige Linoleum			Room 013	NO_ACBM	MISC								
44M	Beige Linoleum Adhesive			Room 013	NO_ACBM	MISC								
45	Gray Terrazo	10,000	SF	Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
BB-2	Turquoise Baseboard ABATED			1943 Building-Room 277	ABATED	MISC								
BB-3	4" Baseboard ABATED			1943- Room 281, 280, 282 Front and Back, 286 Front and Back, 285 Back Office	ABATED	MISC								
BB-4	Black Baseboard ABATED			1939 Building-Room 166	ABATED	MISC								
BB-4A	Black Baseboard	100	LF	Rooms 271, 113, 282	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB-5	Brown Baseboard	300	LF	1939 Building-Room 128, 115, Women's Restroom and Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB-5A	Green Baseboard	100	LF	Room 153	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB-6	Brown Baseboard	70	LF	Rooms 115, 209 & 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BB-7	Blue Baseboard	100	LF	Connecting Room between 113 and 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBM-1	Tan Baseboard Mastic ABATED			1943 Building-Room 278 and 278 Office	ABATED	MISC								
BBM-2	Turquoise Baseboard Mastic ABATED			1943 Building-Room 277	ABATED	MISC								
BBM-3	4" Black Baseboard Mastic ABATED			1943 Building-Room 281, 280, 280 Front and Back, 286 Front and Back, 285 Back Office	ABATED	MISC								
BBM-4	Black Baseboard Mastic ABATED			1939- Room 166	ABATED	MISC								
BBM-4A	Black Baseboard Mastic	150	LF	Rooms 113, 28	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBM-5	Mastic Beneath Brown Baseboard	300	LF	1939- Room 128, 115, Women's Restroom and Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBM-5A	Green Baseboard Mastic	100	LF	Room 153	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBM-6	Brown Baseboard Mastic			Rooms 209, 218, 282, 115	NO_ACBM	MISC								
BBM-7	Blue Baseboard Mastic	100	LF	Connecting Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				between 113 and 115								potential for damage		
C	Pipe Joint Insulation on Preformed Insulated Pipe	216	LF	Pipe Space, East and West Dressing Room, Room 117, 1939 Fan Room, Room 114	AMO	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Fitting Insulation on Preformed Insulated Piping	2,180	LF	1939 Building- Pipe Space, East and West Dressing Room in 117	AMO	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
DE-1	12x12 Yellow Floor Tile	1,400	SF	Driver's Education Building (Separate Building)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DE-2	12x12 Yellow Floor Tile Mastic	1,400	SF	Driver's Education Classroom (Separate Building)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DW-1	Drywall	1,200	SF	1943 Building- Rooms 266, 274, 274D, 274A, 278, 285	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DW-2	Drywall Compound	1,200	SF	1943 Building- Rooms 266, 274, 274D, 274A 278, 285	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
E	Aircell Pipe Insulation	6,450	LF	1939 Building- Above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
FD-1	Insulation in Fire Rated Doors	412	EA	Throughout Facility	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-1	12x12 Beige, Gray w/Tan Pattern Floor Tile	250	SF	Hangar Class Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-10	12x12 Green w/White & Dark Green Specks Floor Tile	2,200	SF	Room 110, 110A & 110B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-11	12x12 Cream w/White & Dark Green Floor Tile	2,800	SF	Rooms 282, 283, 286, 287	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FT-2	12x12 Cream w/Multi-Colored Specks Floor Tile	500	SF	Room 153	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FT-3	12x12 Yellow Floor Tile	700	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FT-4	12x12 Maroon Floor Tile NOT			Room 115	NO_ACBM	MISC						potential for damage		

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	OBSERVED													
FT-5	12x12 Light Blue Floor Tile	2,800	SF	Rooms 109, 114, 113, 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FT-8	12x12 Tan w/Brown & White Streaks Floor Tile			Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326	NO_ACBM	MISC								
FT-9	Dark Blue w/Gray & Light Blue Linoleum	700	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FTM-1	12x12 Beige Gray w/Tan Pattern Floor Tile Mastic	2,580	SF	Hangar Class Area	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-10	12x12 Green w/White & Dark Green Specks VFT Mastic	2,200	SF	Rooms 110, 110A & 110B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-11	12x12 Cream w/Reddish Brown Floor Tile Mastic ABATED			Rooms 282, 283, 286, 287	ABATED	MISC								
FTM-2	12x12 Cream w/Multi-Colored Specks Floor Tile Mastic	500	SF	Room 153	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
FTM-3	12x12 Yellow Floor Tile Mastic	700	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-4	12x12 Brown Floor Tile Mastic	700	SF	Room 115	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-5	12x12 Light Blue Floor Tile Mastic	2,800	SF	Rooms 109, 114, 113, 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-8	12x12 Tan w/ Brown & White Streaks Floor Tile Mastic	3,000	SF	Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FTM-9	Dark Blue w/Gray & Light Blue Linoleum Mastic	700	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
H	Duct Covering On Breeching	1,590	SF	Boiler Room, Throughout Fan Rooms	CHR	TSI	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
HA-1000	Transite Counter and Tabletops	350	SF	Rooms 009, 012, 019, 021, 022, 023, 024, 145A, 161, 213A & 213B	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
I	Tank #1 Jacket ABATED			Boiler Room	ABATED	TSI								
J	Tank #1 Mag Block Insulation ABATED			Boiler Room	ABATED	TSI								
K	Tank #2 Jacket ABATED			Boiler Room	ABATED	TSI								
L	Tank #2 Mag Block Insulation ABATED			Boiler Room	ABATED	TSI								
M	Tank #3 Jacket ABATED			Boiler Room	ABATED	TSI								
N	Tank #3 Mag Block Insulation ABATED			Boiler Room	ABATED	TSI								
NEW	Newly Installed Suspect ACM			Installed After Implementation of	ASSUMED	MISC		UNKNOWN			Yes	ACBM with the potential for damage		

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Management Plan and After Renovations										
O	Tank Jacket ABATED			Kitchen Prep.	ABATED	TSI								
P	Tank Insulation ABATED			Kitchen Prep.	ABATED	TSI								
Q	Tank Insulation ABATED			Hangar	ABATED	TSI								
R	Tank Jacket ABATED			Hangar	ABATED	TSI								
S	Fireproofing		SF	Hangar	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
T	Duct Covering			Hangar	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
U	Preform Pipe Insulation	100	LF	1943 Building- Side of Tunnels	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
U-1	Preform Fittings	10	LF	1943 Building- Side of Tunnels	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
V	Aircell Pipe Insulation	200	LF	1943 Building- Side of Tunnels	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
W	MJP E/F/V on Aircell Pipe Insulation	25	LF	1943 Building- Sides of Tunnels	AMO	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
X	Aircell Joints	840	LF	1939 Building- Attic above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage	AMO	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Y	12x12 White, Black, Red & Gray Floor Tile	5,000	SF	Throughout Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Z	12x12 White, Black, Red & Gray Floor Tile Mastic	5,000	SF	Throughout Classrooms and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/29/2022</b>
Inspector Name <b>Christopher Antonopoulos</b>
<b>100-18281</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
13A	
13B	
13D	
13E	
13F	
13G	
13H	Not Observed 2022
14B	
150A	Not Observed in Room 106. No Access to Room 156 to Confirm
150AM	Not Observed in Room 106. No Access to Room 156 to Confirm
151	Not Observed in Room 009
152	Not Observed in 106B & 106C
152M	Not Observed in Rooms 106B & 106C
153	No Access to Confirm
153M	No Access to Confirm
155	No Access to Confirm
155M	No Access to Confirm
156	No Access to Confirm
156M	No Access to Confirm
157	No Access to Confirm
157M	No Access to Confirm
158	
158M	
159	

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
159M	
15A	
15B	
15D	
15E	
15F	
15G	
15H	Material Removed. Not Observed Multiple Years
15I	Material Removed from 206. Observed in 208
15J	Not Observed in Room 204
15K	Not Observed 2022
15L	Observed in Main Office 2022
15M	Not Observed 2022
15O	Not Observed in 105A
15P	
15Q	Not Observed 2022
15R	Not Observed in Room 002. Observed in 020 & 023
15U	
15V	Not Observed Multiple Years
15W	
15X	Not Observed in Room 115
15Z	Not Observed 2019
160	
160M	
161	
162	
162M	
163	
163M	

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
164	
165	
165M	
166	
166M	
167	
167M	
168	
168M	
169	
170	
170M	
18A	No Access to Room 166 to Confirm
18B	
18C	
18D	
18E	
18F	
200	Not Observed 2022
200A	Not Observed 2022
201	
21	
21A	
28	No Access to Confirm
28C	No Access to Confirm
28D	
28E	Material Removed. No Access to Confirm 2022
28F	No Access to Confirm
28G	Material Removed. No Access to Confirm 2022

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
28H	No Access to Confirm
28J	No Access to Room 279 to Confirm
28K	Material Removed. No Access to Confirm 2022
28L	Material Removed. No Access to Confirm 2022
28N	Observed in Room 250. No Access to Rooms 273 & 288 to Confirm
29	Not Observed in Room 019
29A	Not Observed in Rooms 008, 024, 106, 135 & 136- 2022
29B	
29C	No Access to Confirm
29D	Material Removed. No Access to Confirm- 2022
29E	Material Removed. No Access to Confirm- 2022
29G	No Access to Confirm
29H	No Access to Confirm
29I	No Access to Confirm
29K	No Access to Room 277 to Confirm. Material Observed in Room 250
30	Not Observed 2022
30A	
30B	No Access to Room 280 to Confirm. Observed in 250
30D	No Access to Room 273 to Confirm. Not Present in 255
30E	
30F	
30G	Material Removed
30H	Not Observed 2022
31	No Access to Confirm
31C	Material Removed. No Access to Confirm
31D	No Access to Room 288 to Confirm
31E	Material Removed. No access to Confirm- 2022
31F	Not Observed in Room 250. No Access to Room 280 to Confirm
31G	No Access to Confirm 2022

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
31H	No Access to Confirm
31J	No Access to Room 279 to Confirm. Not Observed in Room 256
31K	Material Removed. No Access to Confirm- 2022
31L	Material Removed. No Access to Confirm- 2022
31N	No Access to Rooms 273 & 288 to Confirm
32	No access to Room 175 to Confirm
32A	
32AA	No Tile associated with this HA
32B	Not Observed 2022
32D	Not Observed Multiple Years
32E	
32F	Not Observed
32G	No Access to Confirm
32H	Not Observed 2019 & 2022
32I	Not Observed in Room 208
32J	No Access to Room 258 to Confirm. Not Observed in 256
32K	Not Observed 2022
32L	Not Observed Multiple Years, including 2022
32M	
32O	No Access to Room 156 to Confirm
32P	
32Q	Not Observed Multiple Years, including 2022
32R	Room 023 Added 2022
32U	Not Observed Multiple Years, including 2022
32V	
32W	
32X	Material is Present in room 115
32Z	Not Observed
33	Not Observed in Room 014

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
33A	Not Observed in Room 259 to Confirm
33B	Not Observed Multiple Years. No Access to Confirm- 2022
33C	Not Observed Multiple Years. No Access to Confirm- 2022
33D	No Access to Confirm
33E	No Access to Confirm
33G	No Access to Confirm
33I	
33J	No Access to Confirm
33K	
34	
34A	Not Observed Multiple Years, including 2022
34B	Not Observed Multiple Years, including 2022
35	2019 Inspection stated Linoleum's color is Grey
36	No Access to Confirm 2022
37	No Access to Confirm 2022
38	
38M	Observed in Rooms 100 & 241A
39	Some Areas Have Been Decommissioned and Are No Longer Accessible. Tile Sampled in Room 222
39M	Some Areas Have Been Decommissioned and Are No Longer Accessible. Tile in Room 222 Sampled
40	
40M	
41	Rooms 322 & 326 added in 2022
41M	Rooms 322 & 326 added in 2022
42	No Access to Room 179 to Confirm
42M	No Access to Room 179 to Confirm
43	
43M	

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
44	
44M	
45	
46	
47	
47M	
48	Cannot Confirm in Decommissioned Areas
49	
50	
51	
52	Damaged Plaster in Rooms 222, 330, 342 & 344. (Sampled in Room 344)
53	
54	
55	
56	
57	
58	
AP-1	
B	
BB-1	
BB-2	
BB-3	
BB-4	
BB-4A	
BB-5	
BB-5A	
BB-6	
BB-7	
BBM-1	No Access to Confirm

# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
BBM-2	No Access to Confirm
BBM-3	No Access to Confirm
BBM-4	
BBM-4A	
BBM-5	
BBM-5A	
BBM-6	No Access to Room 282 to Confirm
BBM-7	Not Observed 2019
C	
D	
DE-1	
DE-2	
DW-1	
DW-2	No Access to Confirm
E	
FD-1	
FT-1	
FT-10	
FT-11	Not Observed. No Access to Confirm
FT-2	
FT-3	Not Observed 2019
FT-4	Not Observed Multiple Years
FT-5	
FT-8	
FT-9	
FTM-1	
FTM-10	
FTM-11	
FTM-2	



# Chicago Public Schools

School Chicago Vocational High School Unit 53011 Building ID 1010

Address 2100 E. 87th St. Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
FTM-3	
FTM-4	
FTM-5	
FTM-8	
FTM-9	
H	
HA-1000	
I	
J	
K	
L	
M	
N	
NEW	
O	
P	
Q	
R	
S	Not Observed 2022
T	Material Removed
U	No Access to Confirm
U-1	No Access to Confirm
V	No Access to Confirm
W	No Access to Confirm
X	
Y	Not Observed 2022
Z	Not Observed 2022

# Chicago Public Schools

**School** Chicago Vocational High School **Unit** 53011 **Building ID** 1010

**Address** 2100 E. 87th St. **Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
13A	9x9 Tan Floor Tile ABATED			1939- Rooms 206, 218	Abated	MISC					
13B	9x9 Dark Beige w/Brown Streaks Floor Tile ABATED			Rooms 250 and 280	Abated	MISC					
13D	9x9 White w/Gray Streaks Floor Tile ABATED			Rooms 255 and 273	Abated	MISC					
13E	9x9 Beige w/Streaks & Green Checkerboard Patterned Floor Tile	200	SF	Main Office (Vault)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13F	9x9 Black w/Cream & Green Streaks Floor Tile	2,900	SF	1st Floor Auditorium Foyer	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13G	9x9 Cream w/Black Streaks Floor Tile ABATED			Rooms 021, 013, 012	Abated	MISC					
13H	9x9 Beige w/Multi-Colored Streaks Floor Tile	260	SF	1st Floor Women's Restroom and Corridor (West End)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14B	Black Linoleum			Room 130	No ACBM	MISC					
150A	12x12 White w/Multicolored Specks Vinyl Floor Tile	700	SF	Rooms 073, 156, 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
150AM	12x12 White w/Multi-colored specks Vinyl Floor Tile Mastic	700	SF	Room 023, 156, 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
151	Gray Linoleum	1,000	SF	Rooms 150, 012, 009	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152	12x12 Purple w/Dark Purple Specks Vinyl Floor Tile	300	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
152M	12x12 Purple w/Dark Purple Specks Vinyl Floor Tile Mastic	300	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153	12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile	2,900	SF	Room 267 (Anthony Wing)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
153M	12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile Mastic	2,900	SF	Room 267 (Anthony Wing)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155	12x12 White w/Specks Vinyl Floor Tile	300	SF	Room 159	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
155M	12x12 White w/Specks Vinyl Floor Tile Mastic	300	SF	Room 159	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156	12x12 Beige w/Specks Vinyl Floor Tile	300	SF	Room 159	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
156M	12x12 Beige w/Specks Vinyl Floor Tile Mastic	300	SF	Room 159	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157	12x12 Pink w/Specks Vinyl Floor Tile	500	SF	Room 179	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
157M	12x12 Pink w/Specks Vinyl Floor Tile Mastic	500	SF	Room 179	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158	12x12 Tan Vinyl Floor Tile	1,000	SF	Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
158M	12x12 Tan Vinyl Floor Tile Mastic	1,000	SF	Mobile Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159	12x12 Algae Green w/Streaks Vinyl Floor Tile	300	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
159M	12x12 Algae Green w/Streaks Vinyl Floor Tile Mastic	300	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12x12 Beige & Purple Checker Board Patterned	1,000	SF	Room 002 & 024	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Chicago Vocational High School

Unit 53011

Building ID 1010

Address 2100 E. 87th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Floor Tile										
15B	12x12 Cream & Tan Checker Board Patterned Floor Tile Mastic	1,000	SF	Room 002 & 024	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15D	12x12 Reddish Orange with Speckles Floor Tile ABATED			Room 206	Abated	MISC					
15E	12x12 Cream Floor Tile ABATED			Room 214	Abated	MISC					
15F	12x12 Brown Multi-Color Beige Floor Tile ABATED			Room 013, 206	Abated	MISC					
15G	12x12 Gray Floor Tile ABATED			Rooms 260, 261, 265, 268, 269, 270A and 271	Abated	MISC					
15H	12x12 Burnt Orange Floor Tile-NOT OBSERVED			Room 206, 2nd Floor Teachers' Room	Chrysotile	MISC					
15I	12x12 Black w/White Speckles Floor Tile	500	SF	Rooms 206 & 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15J	12x12 Red Floor Tile	1,600	SF	Rooms 214B, 104	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15K	12x12 Cream w/Red Streaks Floor Tile			Room 208	No ACBM	MISC					
15L	12x12 White w/Brown Speckles Floor Tile	600	SF	Main Office, Room 010	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15M	12x12 Black Floor Tile As Edging	115	SF	Room 212	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15O	12x12 Turquoise W/Light Gray Checkerboard Floor Tile	1,500	SF	Rooms 023, 023, 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15P	12x12 Black & Maroon Checkerboard Floor Tile	400	SF	Auditorium Pit	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15Q	12x12 Reddish Brown w/White Streaks			Room 256	No ACBM	MISC					
15R	12x12 Purple w/White Checkerboard Floor Tile	1,200	SF	Room 002, 020 & 023	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15U	12x12 Peach w/Cream Speckles Checkerboard Floor Tile			Room 104	No ACBM	MISC					
15V	12x12 Dark & Light Blue Checkerboard Floor Tile NOT OBSERVED			Room 105	Assumed	MISC					
15W	12x12 Gray/Light Blue Speckled Floor Tile	2,000	SF	Rooms 112-114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15X	12x12 Gold & Multi-Color Dark Blue Checkerboard Floor Tile (Not Observed)			Rooms 115 and 118		MISC					
15Z	12x12 Multicolor Light Blue Floor Tile			Room 014	No ACBM	MISC					
160	12x12 White w/Streaks Vinyl Floor Tile	300	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
160M	12x12 White w/Streaks Vinyl Floor Tile Mastic	300	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
161	Linoleum Gray w/Black & White Stripes	4,000	SF	Room 009, 012, 145, 161, 208 & 208A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162	12x12 Red Vinyl Floor Tile	456	SF	Rooms 117 & 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
162M	12x12 Red Vinyl Floor Tile Mastic	456	SF	Rooms 117 & 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
163	12x12 Black Vinyl Floor Tile	456	SF	Rooms 117 & 217 (Auditorium)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
163M	12x12 Black Vinyl Floor Tile Mastic	456	SF	Rooms 117 & 217 (Auditorium)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
164	Black Spray-On Fireproofing	250	SF	Hangar	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
165	12x12 Dark Blue w/Streaks Vinyl Floor Tile	288	SF	Men's & Women's Toilets in Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
165M	12x12 Dark Blue w/Streaks Vinyl Floor Tile Mastic	288	SF	Men's & Women's Toilets - Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166	12x12 Light Blue w/Streaks Vinyl Floor Tile	144	SF	Women's Toilets - Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
166M	12x12 Light Blue w/Streaks Vinyl Floor Tile Mastic	144	SF	Women's Toilets - Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167	12x12 Brown w/Streaks Vinyl Floor Tile	144	SF	Men's Toilet - Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
167M	12x12 Brown w/Streaks Vinyl Floor Tile Mastic	144	SF	Men's Toilets - Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
168	12x12 Blue Vinyl Floor Tile	70	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
168M	12x12 Blue Vinyl Floor Tile Mastic	70	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
169	MJP E/F/V on Aircell Pipe Insulation	3	SF	Hangar- Storage Room 7	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
170	12x12 Brown w/Black & White Specks Vinyl Floor Tile	148	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
170M	12x12 Brown w/Black & White Specks Vinyl Floor Tile Mastic	148	SF	Hangar	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	Mauve Carpet Mastic	5,600	SF	Rooms 125, 126, 125, 134A, 135, 166, 231 & 252A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18B	Blue-Speckled Carpet Mastic	500	SF	Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18C	Blue Carpet Mastic	1,600	SF	Rooms 143, 143A & 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18D	Beige Carpet Mastic	3,000	SF	Rooms 125, 126, 134A, 135, 166, 231, 237 & 252A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18E	Burgundy Carpet Mastic			Room 126	No ACBM	MISC					
18F	Orange Carpet Mastic			Room 231	No ACBM	MISC					
200	Linoleum with Specks	750	SF	Room 009	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
200A	Linoleum with Specks Mastic	750	SF	Room 009	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
201	Multicolor Carpet Mastic	700	SF	109	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Transite	3,830	SF	Shower Area, Old Garage Siding, Kitchen Receiving, Room 167 & Interior of Old Garage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21A	Corrugated Transite Panels ABATED			Greenhouse	Abated	MISC					
28	9x9 Brown Floor Tile	2,800	SF	1943 Building- Room 262 & Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28C	9x9 Pink Floor Tile	2,800	SF	1943 Building- Room 282	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28D	9x9 Light Gray Floor Tile ABATED			1943 Building- Room 021	Abated	MISC					
28E	9x9 Gray Floor Tile	2,800	SF	1943 Building- Room 286	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28F	9x9 Beige w/Brown & White Streaks	1,000	SF	1943 Building- Rooms 280, 282 (Back Room), and 250	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28G	9x9 Maroon w/Beige Checkerboard Floor Tile	2,375	SF	1943 Building- Room 273, 279, 281, 265, 267	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28H	9x9 Tan Speckled Floor Tile	1,600	SF	1943 Building- Rooms 281 and 299	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28J	9x9 Red with Speckles Floor Tile	800	SF	1943 Building- Rooms 256 and 279	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28K	9x9 Gray w/Dark Gray Streaks Flor Tile	2,100	SF	1943- Room 286 (Front)(Back), 285, 287 MATERIAL REMOVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28L	9x9 Dark Gray w/Black & White Streaks Floor Tile	1,175	SF	1943 Building- Room 288	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28N	9x9 White w/Black Streaks Floor Tile	1,000	SF	1943 Building- Rooms 255, 273, and 288	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12x12 Red w/Black & White Blotches Floor Tile	3,500	SF	1943 Building- Rooms 019, 022, 020, 117	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29A	12x12 Cream w/Multicolor Beige Cherckerboard Floor Tile	2,600	SF	1943 Building- Room 008, 024, 106, 135, 136, 326, 338	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29B	12x12 Light & Dark Gray Multicolor Floor Tile ABATED			1943 Building- Room 260	Abated	MISC					
29C	12x12 Dark Gray w/Black and Orange Streaks Floor Tile (MATERIAL REMOVED)	2,855	SF	1943 Building- Room 260, 268, 271, 269, 270A MATERIAL REMOVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29D	12x12 Maroon Floor Tile	2,800	SF	1943 Building- Room 262	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29E	12x12 Cream w/Tan Floor Tile	1,500	SF	1943 Building- Women's Restroom 2nd Floor (2043), 270	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29G	12x12 White Floor Tile ABATED			1943 Building- Room 271	Abated	MISC					
29H	12x12 Multicolor Beige Floor Tile		SF	1943 Building- Room 2047 Men's Restroom (Abated in 288)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29I	12x12 Beige Floor Tile ABATED			1943 Building- Room 272, 276, 285, 286, and Corridor	Abated	MISC					
29K	12x12 Tourquise w/Gray Speck Checkerboard Pattern Floor Tile (Not Observed)			1943 Building- Rooms 009, 023, 156, and 277	No ACBM	MISC					
30	9x9 Grey Floor Tile Mastic	2,900	SF	1939 Building- Room 010, 222, 103, 013, 011, 012, 021	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30A	9x9 Tan Floor Tile Mastic ABATED			1939 Building- Room 218 and 206	Abated	MISC					
30B	9x9 Dark Beige w/Brown Streaks Floor Tile Mastic	1,000	SF	Rooms 250 and 280	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
30D	9x9 White w/Gray Streaks Floor Tile Mastic	600	SF	Rooms 255 and 273	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30E	Beige w/Green Checkerboard Floor Tile Mastic	200	SF	Main Office (Vault)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30F	9x9 Black with Cream and Green Streaks Floor Tile Mastic	85	SF	Auditorium 1st Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30G	White & Black Streaks Floor Tile Mastic	280	SF	Room 021, 013, 012	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30H	9x9 Beige w/Multicolor Streaks Floor Tile Mastic	260	SF	1st Floor Women's Restroom and Corridor (West End)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	9x9 Brown Floor Tile Mastic ABATED			1943 Building- Room 262 and Hallway	Abated	MISC					
31C	9x9 Pink Floor Tile Mastic	2,800	SF	1943 Building- Room 282	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31D	9x9 Light Gray Floor Tile Mastic ABATED			1943 Building- Rooms 021 and 288	Abated	MISC					
31E	9x9 Gray Floor Tile Mastic	2,800	SF	1943 Building- Room 286	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31F	12x12 Beige w/Brown & White Streaks Floor Tile Mastic	500	SF	1943 Building- Rooms 250 and 280	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31G	9x9 Maroon w/Beige Checkerboard Patterned Floor Tile Mastic (Not Observed)	2,375	SF	1943 Building- Rooms 273, 279, 281, 265, 267	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31H	9x9 Tan Speckled Floor Tile Mastic ABATED			1943 Building- Rooms 279 & 281	Abated	MISC					
31J	9x9 Red w/Speckles Floor Tile Mastic	800	SF	1943 Building- Rooms 256 and 279	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31K	9x9 Gray with Dark Gray Streaks Floor Tile Mastic	900	SF	1943 Building- Room 286 (Front) (Back), 285, 287	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31L	9x9 Dark Gray w/Black Streaks Floor Tile Mastic	900	SF	Room 288	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31N	White w/Black Streaks Floor Tile Mastic	600	SF	1943 Building- Rooms 255, 273, & 288	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12x12 Beige Floor Tile	370	SF	Rooms 175, 216 & Hanger	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32A	12x12 Beige and Purple Checkerboard Floor Tile Mastic	500	SF	Room 002	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32AA	12x12 Tan w/Multicolor Floor Tile Mastic	2,690	SF	1st, 2nd Floor Engineer Office, 008, Teachers' Lounge, 136, Auditorium, East Dressing Room, Football Storage	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32B	12x12 Cream & Tan Checkerboard Floor Tile Mastic	500	SF	Room 145	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32D	12x12 Reddish Orange Floor Tile Mastic-NOT OBSERVED			Room 206	Assumed	MISC					
32E	12x12 Cream Floor Tile Mastic	800	SF	Room 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32F	12x12 Brown (Multicolored Beige) Floor Tile Mastic	11,265	SF	Room 010	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32G	12x12 Gray Floor Tile Mastic ABATED			Rooms 260, 261, 265, 268, 269, and	Abated	MISC					



# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				270A							
32H	12x12 Burnt Orange Floor Tile Mastic			Room 2nd Floor Teacher's Room		MISC					
32I	12x12 Black w/White Speckles Floor Tile Mastic			Room 206 & 208	No ACBM	MISC					
32J	12x12 Red Floor Tile Mastic	2,000	SF	Rooms 104, 241B, 256, and 258	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32K	12x12 Cream w/Red Streaks Floor Tile Mastic		SF	Room 208	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32L	White and Brown Speckles Floor Tile Mastic-NOT OBSERVED			Room 208, Main Office	Assumed	MISC					
32M	12x12 Black Floor Tile Mastic (As Edging)	115	SF	Room 212	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32O	12x12 Turquoise & Light Gray Checkerboard Floor Tile Mastic	2,000	SF	Rooms 009, 023, 105, 156	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32P	Black & Maroon Checkboard Floor Tile Mastic	400	SF	Auditorium Pit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32Q	12x12 Reddish Brown w/White Streak Floor Tile Mastic-NOT OBSERVED			Room 256	Assumed	MISC					
32R	12x12 Purple/White Checkerboard Floor Tile Mastic	1,200	SF	Room 020 & 023	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32U	Peach & Cream Speckles Floor Tile Mastic-NOT OBSERVED			Room 108	Assumed	MISC					
32V	Dark and Light Blue Checkerboard Floor Tile Mastic	500	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32W	12x12 Gray/Light Blue Speckled Floor Tile Mastic	2,000	SF	Rooms 109, 112, 113 & 114	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32X	Gold and Multicolor Dark Blue Checkerboard Floor Tile Mastic-NOT OBSERVED	600	SF	Rooms 115, 118	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32Z	12x12 Multicolor Light Blue Floor Tile Mastic			Room 014	Assumed	MISC					
33	12x12 Red w/White and Black Blotches Floor Tile Mastic	3,500	SF	1943 Building- Rooms 217, 117, 022, 020, and 019	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33A	12x12 Creme w/Multicolor Beige Checkerboard Patterned Floor Tile Mastic	8,000	SF	1943 Building- Room 008, 024, 135, 136, 259, 266, 338	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33B	12x12 Light and Dark Gray Floor Tile Mastic-NOT OBSERVED			1943 Building- Room 260		MISC					
33C	12x12 Dark Gray w/Black and Orange Streaks Floor Tile Mastic-NOT OBSERVED			1943 Building- Rooms 260, 268, 269 & 271		MISC					
33D	12x12 Maroon Floor Tile Mastic	2,800	SF	1943 Building- Room 262	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33E	12x12 Cream with Tan Floor Tile Mastic	2,335	SF	1943 Building- Women's Restroom 2nd Floor (2043), 270	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33G	12x12 White Floor Tile Mastic	1,200	SF	1943 Building- Room 271	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
33I	12x12 Beige Floor Tile Mastic			1943 Building- Corridor	No ACBM	MISC					
33J	Dark, Light Beige/Gray Checkerboard Pattern Floor Tile Mastic ABATED			1943 Building- Room 282 (Back Room)	Abated	MISC					
33K	12x12 Turquoise w/Gray Floor Tile Mastic	2,400	SF	1943 Building - Rooms 009, 023	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Mastic Beneath Linoleum	5,600	SF	Gym (Room 251) 253	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34A	Red, Black, Brown, and Tan Linoleum Pattern Mastic NOT OBSERVED			Auditorium 1st and 2nd Floor Foyer		MISC					
34B	Black Linoleum Mastic NOT OBSERVED			Room 130		MISC					
35	Grey Linoleum			Room 208	No ACBM	MISC					
36	9x9 Gray Tiles		SF	Room 288	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9x9 Brown Floor Tile	720	SF	286A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12x12 Beige Floor Tile	5,600	SF	3rd Floor Hallway, Rooms 28, 100, 120, 127, and Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38M	12x12 Beige Floor Tile Mastic	5,600	SF	3rd Floor Hallway, Rooms 28, 100, 120, 127 and Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12x12 White w/Beige Specks Floor Tile	123,000	SF	1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39M	12x12 White w/Beige Specks Floor Tile Mastic	123,000	SF	1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12x12 Yellow with White Floor Tile			Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway	No ACBM	MISC					
40M	12x12 Yellow w/White Floor Tile Mastic			Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway	No ACBM	MISC					
41	12x12 Beige Speckled Floor Tile	1,100	SF	Rooms 322 & 326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41M	12x12 Beige Speckled Floor Tile Mastic	1,100	SF	Rooms 322 & 326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12x12 Red & White Checkered Floor Tile ABATED			Room 179	Abated	MISC					
42M	12x12 Red and White Checkered Floor Tile Mastic	500	SF	Room 179	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12x12 Brown, Beige and Red Floor Tile	2,000	SF	Cafeteria Court	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43M	12x12 Brown, Beige and Red Floor Tile Mastic	2,000	SF	Cafeteria Court	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Chicago Vocational High School

Unit 53011

Building ID 1010

Address 2100 E. 87th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
44	Beige Linoleum			Room 013	No ACBM	MISC					
44M	Beige Linoleum Adhesive			Room 013	No ACBM	MISC					
45	Gray Terrazo	10,000	SF	Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Beige Terrazzo	2,000	SF	Main Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	1'x1' Ceiling Tile	4,000	SF	Lunchroom	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
47M	1'x1' Ceiling Tile Adhesive	4,000	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	2'x4' Lay-In Ceiling Panels	50,000	SF	1st, 2nd and 3rd Floor Hallways	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
49	2'x4' Lay-In Smooth Ceiling Panels	900	SF	Band Room and 014	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
50	2'x2' Lay-In Ceiling Panels	6,000	SF	Rooms 204, 205, and 213	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
51	Black Chalkboards	1,000	SF	3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Hard Plaster	100,000	SF	Throughout Building	Assumed	SURFACE	No	50	SF	6 ACBM with the potential for damage	Repair
53	12"x12" Blue & White w/Green Specks Floor Tile	1,000	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Mastic associated with 12"x12" Blue & White w/Green Specks Floor Tile	1,000	SF	Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12"x12" White, Blue & Beige Mix Floor Tile	600	SF	Rooms 019, 021 & 023	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Mastic associated with 12"x12" White, Blue & Beige Mix Floor Tile	600	SF	Rooms 019, 021 & 023	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12x12 Light Grey & Grey Mix Floor Tile	2,000	SF	Rooms 256A & 257	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12x12 Light Grey & Grey Mix Floor Tile Mastic	2,000	SF	Room 256A & 257	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
AP-1	Acoustical Plaster	8,000	SF	Hangar	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Joint Insulation on Fiberglass Insulated Piping	75	LF	Basement, Janitor's Closet, Northeast Corner Stairs, 3rd Floor Fan Room, Fan Room #12, Potting Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
BB-1	Tan Baseboard ABATED			1943 Building- 278 and 278 Office	Abated	MISC					
BB-2	Turquoise Baseboard ABATED			1943 Building- Room 277	Abated	MISC					
BB-3	4" Baseboard ABATED			1943- Room 281, 280, 282 Front and Back, 286 Front and Back, 285 Back Office	Abated	MISC					
BB-4	Black Baseboard ABATED			1939 Building- Room 166	Abated	MISC					

# Chicago Public Schools

School Chicago Vocational High School

Unit 53011

Building ID 1010

Address 2100 E. 87th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
BB-4A	Black Baseboard	100	LF	Rooms 271, 113, 282	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BB-5	Brown Baseboard	300	LF	1939 Building- Room 128, 115, Women's Restroom and Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BB-5A	Green Baseboard	100	LF	Room 153	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BB-6	Brown Baseboard	70	LF	Rooms 115, 209 & 218	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BB-7	Blue Baseboard	100	LF	Connecting Room between 113 and 115	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-1	Tan Baseboard Mastic ABATED			1943 Building- Room 278 and 278 Office	Abated	MISC					
BBM-2	Turquoise Baseboard Mastic ABATED			1943 Building- Room 277	Abated	MISC					
BBM-3	4" Black Baseboard Mastic ABATED			1943 Building- Room 281, 280, 280 Front and Back, 286 Front and Back, 285 Back Office	Abated	MISC					
BBM-4	Black Baseboard Mastic ABATED			1939- Room 166	Abated	MISC					
BBM-4A	Black Baseboard Mastic	150	LF	Rooms 113, 28	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-5	Mastic Beneath Brown Baseboard	300	LF	1939- Room 128, 115, Women's Restroom and Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-5A	Green Baseboard Mastic	100	LF	Room 153	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBM-6	Brown Baseboard Mastic			Rooms 209, 218, 282, 115	No ACBM	MISC					
BBM-7	Blue Baseboard Mastic	100	LF	Connecting Room between 113 and 115	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
C	Pipe Joint Insulation on Preformed Insulated Pipe	216	LF	Pipe Space, East and West Dressing Room, Room 117, 1939 Fan Room, Room 114	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Fitting Insulation on Preformed Insulated Piping	2,180	LF	1939 Building- Pipe Space, East and West Dressing Room in 117	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
DE-1	12x12 Yellow Floor Tile	1,400	SF	Driver's Education Building (Separate Building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DE-2	12x12 Yellow Floor Tile Mastic	1,400	SF	Driver's Education Classroom (Separate Building)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DW-1	Drywall	1,200	SF	1943 Building- Rooms 266, 274, 274D, 274A, 278, 285	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DW-2	Drywall Compound	1,200	SF	1943 Building- Rooms 266, 274, 274D,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Chicago Vocational High School

Unit 53011

Building ID 1010

Address 2100 E. 87th St.

Chicago, IL, 60617

Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				274A 278, 285							
E	Aircell Pipe Insulation	6,450	LF	1939 Building- Above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
FD-1	Insulation in Fire Rated Doors	412	EA	Throughout Facility	Chrysotile	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
FT-1	12x12 Beige, Gray w/Tan Pattern Floor Tile	250	SF	Hangar Class Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-10	12x12 Green w/White & Dark Green Specks Floor Tile	2,200	SF	Room 110, 110A & 110B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-11	12x12 Cream w/White & Dark Green Floor Tile	2,800	SF	Rooms 282, 283, 286, 287	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-2	12x12 Cream w/Multi-Colored Specks Floor Tile	500	SF	Room 153	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-3	12x12 Yellow Floor Tile	700	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-4	12x12 Maroon Floor Tile NOT OBSERVED			Room 115	No ACBM	MISC					
FT-5	12x12 Light Blue Floor Tile	2,800	SF	Rooms 109, 114, 113, 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-8	12x12 Tan w/Brown & White Streaks Floor Tile			Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326	No ACBM	MISC					
FT-9	Dark Blue w/Gray & Light Blue Linoleum	700	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-1	12x12 Beige Gray w/Tan Pattern Floor Tile Mastic	2,580	SF	Hangar Class Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-10	12x12 Green w/White & Dark Green Specks VFT Mastic	2,200	SF	Rooms 110, 110A & 110B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-11	12x12 Cream w/Reddish Brown Floor Tile Mastic ABATED			Rooms 282, 283, 286, 287	Abated	MISC					
FTM-2	12x12 Cream w/Multi-Colored Specks Floor Tile Mastic	500	SF	Room 153	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-3	12x12 Yellow Floor Tile Mastic	700	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-4	12x12 Brown Floor Tile Mastic	700	SF	Room 115	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-5	12x12 Light Blue Floor Tile Mastic	2,800	SF	Rooms 109, 114, 113, 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-8	12x12 Tan w/ Brown & White Streaks Floor Tile Mastic	3,000	SF	Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-9	Dark Blue w/Gray & Light Blue Linoleum Mastic	700	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Duct Covering On Breeching	1,590	SF	Boiler Room, Throughout Fan Rooms	Chrysotile	TSI	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
HA-1000	Transite Counter and Tabletops	350	SF	Rooms 009, 012, 019, 021, 022, 023, 024, 145A, 161, 213A & 213B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	Tank #1 Jacket ABATED			Boiler Room	Abated	TSI					

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	Tank #1 Mag Block Insulation ABATED			Boiler Room	Abated	TSI					
K	Tank #2 Jacket ABATED			Boiler Room	Abated	TSI					
L	Tank #2 Mag Block Insulation ABATED			Boiler Room	Abated	TSI					
M	Tank #3 Jacket ABATED			Boiler Room	Abated	TSI					
N	Tank #3 Mag Block Insulation ABATED			Boiler Room	Abated	TSI					
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
O	Tank Jacket ABATED			Kitchen Prep.	Abated	TSI					
P	Tank Insulation ABATED			Kitchen Prep.	Abated	TSI					
Q	Tank Insulation ABATED			Hangar	Abated	TSI					
R	Tank Jacket ABATED			Hangar	Abated	TSI					
S	Fireproofing		SF	Hangar	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
T	Duct Covering			Hangar	Chrysotile	TSI	No	0		6 ACBM with the potential for damage	Follow O&M Plan
U	Preform Pipe Insulation	100	LF	1943 Building- Side of Tunnels	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U-1	Preform Fittings	10	LF	1943 Building- Side of Tunnels	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
V	Aircell Pipe Insulation	200	LF	1943 Building- Side of Tunnels	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
W	MJP E/F/V on Aircell Pipe Insulation	25	LF	1943 Building- Sides of Tunnels	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
X	Aircell Joints	840	LF	1939 Building- Attic above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Y	12x12 White, Black, Red & Gray Floor Tile	5,000	SF	Throughout Classrooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Z	12x12 White, Black, Red & Gray Floor Tile Mastic	5,000	SF	Throughout Classrooms and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/18/2022
Manager Planner Name	Todd Huffer
100-09870	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
13A	
13B	
13D	
13E	
13F	
13G	
13H	
14B	
150A	
150AM	
151	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
152	
152M	
153	
153M	
155	
155M	
156	
156M	
157	
157M	
158	
158M	
159	
159M	
15A	
15B	
15D	
15E	
15F	
15G	
15H	
15I	
15J	
15K	
15L	
15M	



# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
15O	
15P	
15Q	
15R	
15U	
15V	
15W	
15X	
15Z	
160	
160M	
161	
162	
162M	
163	
163M	
164	
165	
165M	
166	
166M	
167	
167M	
168	
168M	
169	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
170	
170M	
18A	
18B	
18C	
18D	
18E	
18F	
200	
200A	
201	
21	
21A	
28	
28C	
28D	
28E	
28F	
28G	
28H	
28J	
28K	
28L	
28N	
29	
29A	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
29B	
29C	
29D	
29E	
29G	
29H	
29I	
29K	
30	
30A	
30B	
30D	
30E	
30F	
30G	
30H	
31	
31C	
31D	
31E	
31F	
31G	
31H	
31J	
31K	
31L	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
31N	
32	
32A	
32AA	
32B	
32D	
32E	
32F	
32G	
32H	
32I	
32J	
32K	
32L	
32M	
32O	
32P	
32Q	
32R	
32U	
32V	
32W	
32X	
32Z	
33	
33A	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
33B	
33C	
33D	
33E	
33G	
33I	
33J	
33K	
34	
34A	
34B	
35	
36	
37	
38	
38M	
39	
39M	
40	
40M	
41	
41M	
42	
42M	
43	
43M	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
44	
44M	
45	
46	
47	
47M	
48	
49	
50	
51	
52	patch and repair
53	
54	
55	
56	
57	
58	
AP-1	
B	
BB-1	
BB-2	
BB-3	
BB-4	
BB-4A	
BB-5	
BB-5A	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
BB-6	
BB-7	
BBM-1	
BBM-2	
BBM-3	
BBM-4	
BBM-4A	
BBM-5	
BBM-5A	
BBM-6	
BBM-7	
C	
D	
DE-1	
DE-2	
DW-1	
DW-2	
E	
FD-1	
FT-1	
FT-10	
FT-11	
FT-2	
FT-3	
FT-4	
FT-5	

# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
FT-8	
FT-9	
FTM-1	
FTM-10	
FTM-11	
FTM-2	
FTM-3	
FTM-4	
FTM-5	
FTM-8	
FTM-9	
H	
HA-1000	
I	
J	
K	
L	
M	
N	
NEW	
O	
P	
Q	
R	
S	
T	



# Chicago Public Schools

**School** Chicago Vocational High School

**Unit** 53011

**Building ID** 1010

**Address** 2100 E. 87th St.

Chicago, IL, 60617

**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
U	
U-1	
V	
W	
X	
Y	
Z	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2022 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1939- Rooms 206, 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile ABATED**  
MATERIAL LOCATION: **1939- Rooms 206, 218**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13B  
MATERIAL DESCRIPTION: 9x9 Dark Beige w/Brown Streaks Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 250 and 280

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13B**  
MATERIAL DESCRIPTION: **9x9 Dark Beige w/Brown Streaks Floor Tile ABATED**  
MATERIAL LOCATION: **Rooms 250 and 280**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13D  
MATERIAL DESCRIPTION: 9x9 White w/Gray Streaks Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 255 and 273

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

---



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13D**  
MATERIAL DESCRIPTION: **9x9 White w/Gray Streaks Floor Tile ABATED**  
MATERIAL LOCATION: **Rooms 255 and 273**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13E  
MATERIAL DESCRIPTION: 9x9 Beige w/Streaks & Green Checkerboard Patterned Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Office (Vault)  
MATERIAL QUANTITY: 200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13E**  
MATERIAL DESCRIPTION: **9x9 Beige w/Streaks & Green Checkerboard Patterned Floor Tile**  
MATERIAL LOCATION: **Main Office (Vault)**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13F  
MATERIAL DESCRIPTION: 9x9 Black w/Cream & Green Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1st Floor Auditorium Foyer  
MATERIAL QUANTITY: 2900    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13F**  
MATERIAL DESCRIPTION: **9x9 Black w/Cream & Green Streaks Floor Tile**  
MATERIAL LOCATION: **1st Floor Auditorium Foyer**  
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13G  
MATERIAL DESCRIPTION: 9x9 Cream w/Black Streaks Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 021, 013, 012

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13G**  
MATERIAL DESCRIPTION: **9x9 Cream w/Black Streaks Floor Tile ABATED**  
MATERIAL LOCATION: **Rooms 021, 013, 012**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13H  
MATERIAL DESCRIPTION: 9x9 Beige w/Multi-Colored Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1st Floor Women's Restroom and Corridor (West End)  
MATERIAL QUANTITY: 260    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **13H**  
MATERIAL DESCRIPTION: **9x9 Beige w/Multi-Colored Streaks Floor Tile**  
MATERIAL LOCATION: **1st Floor Women's Restroom and Corridor (West End)**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14B  
MATERIAL DESCRIPTION: Black Linoleum  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 130

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **14B**  
MATERIAL DESCRIPTION: **Black Linoleum**  
MATERIAL LOCATION: **Room 130**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 150A  
MATERIAL DESCRIPTION: 12x12 White w/Multicolored Specks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Rooms 073, 156, 106  
MATERIAL QUANTITY: 700    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 106. No Access to Room 156 to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **150A**  
MATERIAL DESCRIPTION: **12x12 White w/Multicolored Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 073, 156, 106**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 150AM  
MATERIAL DESCRIPTION: 12x12 White w/Multi-colored specks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 023, 156, 106  
MATERIAL QUANTITY: 700 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Not Observed in Room 106. No Access to Room 156 to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **150AM**  
MATERIAL DESCRIPTION: **12x12 White w/Multi-colored specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 023, 156, 106**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **Gray Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 150, 012, 009**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Room 009**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **151**  
MATERIAL DESCRIPTION: **Gray Linoleum**  
MATERIAL LOCATION: **Rooms 150, 012, 009**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 152  
MATERIAL DESCRIPTION: 12x12 Purple w/Dark Purple Specks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 106  
MATERIAL QUANTITY: 300    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in 106B & 106C

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **152**  
MATERIAL DESCRIPTION: **12x12 Purple w/Dark Purple Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **152M**  
MATERIAL DESCRIPTION: **12x12 Purple w/Dark Purple Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed in Rooms 106B & 106C**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **152M**  
MATERIAL DESCRIPTION: **12x12 Purple w/Dark Purple Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 153  
MATERIAL DESCRIPTION: 12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 267 (Anthony Wing)  
MATERIAL QUANTITY: 2900    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **153**  
MATERIAL DESCRIPTION: **12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 267 (Anthony Wing)**  
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 153M  
MATERIAL DESCRIPTION: 12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 267 (Anthony Wing)  
MATERIAL QUANTITY: 2900    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **153M**  
MATERIAL DESCRIPTION: **12x12 Gray w/Black & Dark Gray Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 267 (Anthony Wing)**  
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 155  
MATERIAL DESCRIPTION: 12x12 White w/Specks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 159  
MATERIAL QUANTITY: 300 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **155**  
MATERIAL DESCRIPTION: **12x12 White w/Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 159**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 155M  
MATERIAL DESCRIPTION: 12x12 White w/Specks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 159  
MATERIAL QUANTITY: 300    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **155M**  
MATERIAL DESCRIPTION: **12x12 White w/Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 159**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 156  
MATERIAL DESCRIPTION: 12x12 Beige w/Specks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 159  
MATERIAL QUANTITY: 300    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **156**  
MATERIAL DESCRIPTION: **12x12 Beige w/Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 159**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 156M  
MATERIAL DESCRIPTION: 12x12 Beige w/Specks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 159  
MATERIAL QUANTITY: 300    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **156M**  
MATERIAL DESCRIPTION: **12x12 Beige w/Specks Vinytl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 159**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **12x12 Pink w/Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Room 179**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **No Access to Confirm**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **157**  
MATERIAL DESCRIPTION: **12x12 Pink w/Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Room 179**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 157M  
MATERIAL DESCRIPTION: 12x12 Pink w/Specks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 179  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **157M**  
MATERIAL DESCRIPTION: **12x12 Pink w/Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Room 179**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 158  
MATERIAL DESCRIPTION: 12x12 Tan Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Mobile Unit  
MATERIAL QUANTITY: 1000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **158**  
MATERIAL DESCRIPTION: **12x12 Tan Vinyl Floor Tile**  
MATERIAL LOCATION: **Mobile Unit**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **158M**  
MATERIAL DESCRIPTION: **12x12 Tan Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mobile Unit**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **158M**  
MATERIAL DESCRIPTION: **12x12 Tan Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Mobile Unit**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 159  
MATERIAL DESCRIPTION: 12x12 Algae Green w/Streaks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 300 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **159**  
MATERIAL DESCRIPTION: **12x12 Algae Green w/Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 159M  
MATERIAL DESCRIPTION: 12x12 Algae Green w/Streaks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 300    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **159M**  
MATERIAL DESCRIPTION: **12x12 Algae Green w/Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15A  
MATERIAL DESCRIPTION: 12x12 Beige & Purple Checker Board Patterned Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 002 & 024  
MATERIAL QUANTITY: 1000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12x12 Beige & Purple Checker Board Patterned Floor Tile**  
MATERIAL LOCATION: **Room 002 & 024**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15B  
MATERIAL DESCRIPTION: 12x12 Cream & Tan Checker Board Patterned Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 002 & 024  
MATERIAL QUANTITY: 1000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **12x12 Cream & Tan Checker Board Patterned Floor Tile Mastic**  
MATERIAL LOCATION: **Room 002 & 024**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15D  
MATERIAL DESCRIPTION: 12x12 Reddish Orange with Speckles Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 206

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15D**  
MATERIAL DESCRIPTION: **12x12 Reddish Orange with Speckles Floor Tile ABATED**  
MATERIAL LOCATION: **Room 206**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15E  
MATERIAL DESCRIPTION: 12x12 Cream Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 214

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15E**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile ABATED**  
MATERIAL LOCATION: **Room 214**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15F  
MATERIAL DESCRIPTION: 12x12 Brown Multi-Color Beige Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 013, 206

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15F**  
MATERIAL DESCRIPTION: **12x12 Brown Multi-Color Beige Floor Tile ABATED**  
MATERIAL LOCATION: **Room 013, 206**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15G  
MATERIAL DESCRIPTION: 12x12 Gray Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 260, 261, 265, 268, 269, 270A and 271

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15G**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile ABATED**  
MATERIAL LOCATION: **Rooms 260, 261, 265, 268, 269, 270A and 271**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15H  
MATERIAL DESCRIPTION: 12x12 Burnt Orange Floor Tile-NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 206, 2nd Floor Teachers' Room

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: Material Removed. Not Observed Multiple Years

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15H**  
MATERIAL DESCRIPTION: **12x12 Burnt Orange Floor Tile-NOT OBSERVED**  
MATERIAL LOCATION: **Room 206, 2nd Floor Teachers' Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15I  
MATERIAL DESCRIPTION: 12x12 Black w/White Speckles Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 206 & 208  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Material Removed from 206. Observed in 208

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15I**  
MATERIAL DESCRIPTION: **12x12 Black w/White Speckles Floor Tile**  
MATERIAL LOCATION: **Rooms 206 & 208**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15J  
MATERIAL DESCRIPTION: 12x12 Red Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 214B, 104  
MATERIAL QUANTITY: 1600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 204

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15J**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile**  
MATERIAL LOCATION: **Rooms 214B, 104**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15K  
MATERIAL DESCRIPTION: 12x12 Cream w/Red Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 208

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15K**  
MATERIAL DESCRIPTION: **12x12 Cream w/Red Streaks Floor Tile**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15L  
MATERIAL DESCRIPTION: 12x12 White w/Brown Speckles Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Office, Room 010  
MATERIAL QUANTITY: 600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Observed in Main Office 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15L**  
MATERIAL DESCRIPTION: **12x12 White w/Brown Speckles Floor Tile**  
MATERIAL LOCATION: **Main Office, Room 010**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15M  
MATERIAL DESCRIPTION: 12x12 Black Floor Tile As Edging  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 212  
MATERIAL QUANTITY: 115 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15M**  
MATERIAL DESCRIPTION: **12x12 Black Floor Tile As Edging**  
MATERIAL LOCATION: **Room 212**  
MATERIAL QUANTITY: **115** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 150  
MATERIAL DESCRIPTION: 12x12 Turquoise W/Light Gray Checkerboard Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 023, 023, 105  
MATERIAL QUANTITY: 1500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in 105A

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **150**  
MATERIAL DESCRIPTION: **12x12 Turquoise W/Light Gray Checkerboard Floor Tile**  
MATERIAL LOCATION: **Rooms 023, 023, 105**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15P**  
MATERIAL DESCRIPTION: **12x12 Black & Maroon Checkerboard Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Pit**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15P**  
MATERIAL DESCRIPTION: **12x12 Black & Maroon Checkerboard Floor Tile**  
MATERIAL LOCATION: **Auditorium Pit**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15Q  
MATERIAL DESCRIPTION: 12x12 Reddish Brown w/White Streaks  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 256

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15Q**  
MATERIAL DESCRIPTION: **12x12 Reddish Brown w/White Streaks**  
MATERIAL LOCATION: **Room 256**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15R  
MATERIAL DESCRIPTION: 12x12 Purple w/White Checkerboard Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 002, 020 & 023  
MATERIAL QUANTITY: 1200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 002. Observed in 020 & 023

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15R**  
MATERIAL DESCRIPTION: **12x12 Purple w/White Checkerboard Floor Tile**  
MATERIAL LOCATION: **Room 002, 020 & 023**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15U  
MATERIAL DESCRIPTION: 12x12 Peach w/Cream Speckles Checkerboard Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 104

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15U**  
MATERIAL DESCRIPTION: **12x12 Peach w/Cream Speckles Checkerboard Floor Tile**  
MATERIAL LOCATION: **Room 104**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15V  
MATERIAL DESCRIPTION: 12x12 Dark & Light Blue Checkerboard Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 105

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15V**  
MATERIAL DESCRIPTION: **12x12 Dark & Light Blue Checkerboard Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **Room 105**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15W**  
MATERIAL DESCRIPTION: **12x12 Gray/Light Blue Speckled Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 112-114**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15W**  
MATERIAL DESCRIPTION: **12x12 Gray/Light Blue Speckled Floor Tile**  
MATERIAL LOCATION: **Rooms 112-114**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15X  
MATERIAL DESCRIPTION: 12x12 Gold & Multi-Color Dark Blue Checkerboard Floor Tile (Not Observed)  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 115 and 118

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed in Room 115

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15X**  
MATERIAL DESCRIPTION: **12x12 Gold & Multi-Color Dark Blue Checkerboard Floor Tile (Not Observed)**  
MATERIAL LOCATION: **Rooms 115 and 118**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15Z  
MATERIAL DESCRIPTION: 12x12 Multicolor Light Blue Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 014

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **15Z**  
MATERIAL DESCRIPTION: **12x12 Multicolor Light Blue Floor Tile**  
MATERIAL LOCATION: **Room 014**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 160  
MATERIAL DESCRIPTION: 12x12 White w/Streaks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 300 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **160**  
MATERIAL DESCRIPTION: **12x12 White w/Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 160M  
MATERIAL DESCRIPTION: 12x12 White w/Streaks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 300    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **160M**  
MATERIAL DESCRIPTION: **12x12 White w/Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 161  
MATERIAL DESCRIPTION: Linoleum Gray w/Black & White Stripes  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 009, 012, 145, 161, 208 & 208A  
MATERIAL QUANTITY: 4000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **161**  
MATERIAL DESCRIPTION: **Linoleum Gray w/Black & White Stripes**  
MATERIAL LOCATION: **Room 009, 012, 145, 161, 208 & 208A**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12x12 Red Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 117 & 217**  
MATERIAL QUANTITY: **456** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **162**  
MATERIAL DESCRIPTION: **12x12 Red Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 117 & 217**  
MATERIAL QUANTITY: **456** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 162M  
MATERIAL DESCRIPTION: 12x12 Red Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 117 & 217  
MATERIAL QUANTITY: 456 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **162M**  
MATERIAL DESCRIPTION: **12x12 Red Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 117 & 217**  
MATERIAL QUANTITY: **456** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **12x12 Black Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Rooms 117 & 217 (Auditorium)**  
MATERIAL QUANTITY: **456** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **163**  
MATERIAL DESCRIPTION: **12x12 Black Vinyl Floor Tile**  
MATERIAL LOCATION: **Rooms 117 & 217 (Auditorium)**  
MATERIAL QUANTITY: **456** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 163M  
MATERIAL DESCRIPTION: 12x12 Black Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 117 & 217 (Auditorium)  
MATERIAL QUANTITY: 456    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **163M**  
MATERIAL DESCRIPTION: **12x12 Black Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 117 & 217 (Auditorium)**  
MATERIAL QUANTITY: **456** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **Black Spray-On Fireproofing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **164**  
MATERIAL DESCRIPTION: **Black Spray-On Fireproofing**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 165  
MATERIAL DESCRIPTION: 12x12 Dark Blue w/Streaks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Men's & Women's Toilets in Hangar  
MATERIAL QUANTITY: 288    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **165**  
MATERIAL DESCRIPTION: **12x12 Dark Blue w/Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **Men's & Women's Toilets in Hangar**  
MATERIAL QUANTITY: **288** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **165M**  
MATERIAL DESCRIPTION: **12x12 Dark Blue w/Streaks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Men's & Women's Toilets - Hangar**  
MATERIAL QUANTITY: **288** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **165M**  
MATERIAL DESCRIPTION: **12x12 Dark Blue w/Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Men's & Women's Toilets - Hangar**  
MATERIAL QUANTITY: **288** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/Streaks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Women's Toilets - Hangar**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **166**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **Women's Toilets - Hangar**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **166M**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/Streaks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Women's Toilets - Hangar**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **166M**  
MATERIAL DESCRIPTION: **12x12 Light Blue w/Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Women's Toilets - Hangar**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 167  
MATERIAL DESCRIPTION: 12x12 Brown w/Streaks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Men's Toilet - Hangar  
MATERIAL QUANTITY: 144    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **167**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **Men's Toilet - Hangar**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 167M  
MATERIAL DESCRIPTION: 12x12 Brown w/Streaks Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Men's Toilets - Hangar  
MATERIAL QUANTITY: 144 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **167M**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Men's Toilets - Hangar**  
MATERIAL QUANTITY: **144** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 168  
MATERIAL DESCRIPTION: 12x12 Blue Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 70    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **168**  
MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 168M  
MATERIAL DESCRIPTION: 12x12 Blue Vinyl Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 70    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **168M**  
MATERIAL DESCRIPTION: **12x12 Blue Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hangar- Storage Room 7**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **169**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Hangar- Storage Room 7**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 170  
MATERIAL DESCRIPTION: 12x12 Brown w/Black & White Specks Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 148    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **170**  
MATERIAL DESCRIPTION: **12x12 Brown w/Black & White Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **148** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **170M**  
MATERIAL DESCRIPTION: **12x12 Brown w/Black & White Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **148** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **170M**  
MATERIAL DESCRIPTION: **12x12 Brown w/Black & White Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **148** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18A  
MATERIAL DESCRIPTION: Mauve Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 125, 126, 125, 134A, 135, 166, 231 & 252A  
MATERIAL QUANTITY: 5600 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No Access to Room 166 to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **Mauve Carpet Mastic**  
MATERIAL LOCATION: **Rooms 125, 126, 125, 134A, 135, 166, 231 & 252A**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18B  
MATERIAL DESCRIPTION: Blue-Speckled Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 200  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18B**  
MATERIAL DESCRIPTION: **Blue-Speckled Carpet Mastic**  
MATERIAL LOCATION: **Room 200**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18C**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 143, 143A & 200**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18C**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **Rooms 143, 143A & 200**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18D  
MATERIAL DESCRIPTION: Beige Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 125, 126, 134A, 135, 166, 231, 237 & 252A  
MATERIAL QUANTITY: 3000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18D**  
MATERIAL DESCRIPTION: **Beige Carpet Mastic**  
MATERIAL LOCATION: **Rooms 125, 126, 134A, 135, 166, 231, 237 & 252A**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18E  
MATERIAL DESCRIPTION: Burgundy Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Room 126  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18E**  
MATERIAL DESCRIPTION: **Burgundy Carpet Mastic**  
MATERIAL LOCATION: **Room 126**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18F  
MATERIAL DESCRIPTION: Orange Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Room 231  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **18F**  
MATERIAL DESCRIPTION: **Orange Carpet Mastic**  
MATERIAL LOCATION: **Room 231**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **200**  
MATERIAL DESCRIPTION: **Linoleum with Specks**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 009**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed 2022**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **200**  
MATERIAL DESCRIPTION: **Linoleum with Specks**  
MATERIAL LOCATION: **Room 009**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 200A  
MATERIAL DESCRIPTION: Linoleum with Specks Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 009  
MATERIAL QUANTITY: 750    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **200A**  
MATERIAL DESCRIPTION: **Linoleum with Specks Mastic**  
MATERIAL LOCATION: **Room 009**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 201  
MATERIAL DESCRIPTION: Multicolor Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 109  
MATERIAL QUANTITY: 700    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **201**  
MATERIAL DESCRIPTION: **Multicolor Carpet Mastic**  
MATERIAL LOCATION: **109**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Transite**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Shower Area, Old Garage Siding, Kitchen Receiving, Room 167 & Interior of Old Garage**

MATERIAL QUANTITY: **3830** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Transite**  
MATERIAL LOCATION: **Shower Area, Old Garage Siding, Kitchen Receiving, Room 167 & Interior of Old Garage**  
MATERIAL QUANTITY: **3830** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21A  
MATERIAL DESCRIPTION: Corrugated Transite Panels ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Greenhouse  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **21A**  
MATERIAL DESCRIPTION: **Corrugated Transite Panels ABATED**  
MATERIAL LOCATION: **Greenhouse**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1943 Building- Room 262 & Hallway**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **No Access to Confirm**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 262 & Hallway**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28C  
MATERIAL DESCRIPTION: 9x9 Pink Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 282  
MATERIAL QUANTITY: 2800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28C**  
MATERIAL DESCRIPTION: **9x9 Pink Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 282**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28D  
MATERIAL DESCRIPTION: 9x9 Light Gray Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Room 021

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28D**  
MATERIAL DESCRIPTION: **9x9 Light Gray Floor Tile ABATED**  
MATERIAL LOCATION: **1943 Building- Room 021**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28E  
MATERIAL DESCRIPTION: 9x9 Gray Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 286  
MATERIAL QUANTITY: 2800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28E**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 286**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28F  
MATERIAL DESCRIPTION: 9x9 Beige w/Brown & White Streaks  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 280, 282 (Back Room), and 250  
MATERIAL QUANTITY: 1000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28F**  
MATERIAL DESCRIPTION: **9x9 Beige w/Brown & White Streaks**  
MATERIAL LOCATION: **1943 Building- Rooms 280, 282 (Back Room), and 250**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28G  
MATERIAL DESCRIPTION: 9x9 Maroon w/Beige Checkerboard Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 273, 279, 281, 265, 267  
MATERIAL QUANTITY: 2375    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28G**  
MATERIAL DESCRIPTION: **9x9 Maroon w/Beige Checkerboard Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 273, 279, 281, 265, 267**  
MATERIAL QUANTITY: **2375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28H  
MATERIAL DESCRIPTION: 9x9 Tan Speckled Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 281 and 299  
MATERIAL QUANTITY: 1600 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28H**  
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile**  
MATERIAL LOCATION: **1943 Building- Rooms 281 and 299**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28J  
MATERIAL DESCRIPTION: 9x9 Red with Speckles Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 256 and 279  
MATERIAL QUANTITY: 800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Room 279 to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28J**  
MATERIAL DESCRIPTION: **9x9 Red with Speckles Floor Tile**  
MATERIAL LOCATION: **1943 Building- Rooms 256 and 279**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28K  
MATERIAL DESCRIPTION: 9x9 Gray w/Dark Gray Streaks Flor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943- Room 286 (Front)(Back), 285, 287 MATERIAL REMOVED  
MATERIAL QUANTITY: 2100    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28K**  
MATERIAL DESCRIPTION: **9x9 Gray w/Dark Gray Streaks Flor Tile**  
MATERIAL LOCATION: **1943- Room 286 (Front)(Back), 285, 287 MATERIAL REMOVED**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28L  
MATERIAL DESCRIPTION: 9x9 Dark Gray w/Black & White Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 288  
MATERIAL QUANTITY: 1175    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28L**  
MATERIAL DESCRIPTION: **9x9 Dark Gray w/Black & White Streaks Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 288**  
MATERIAL QUANTITY: **1175** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28N  
MATERIAL DESCRIPTION: 9x9 White w/Black Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 255, 273, and 288  
MATERIAL QUANTITY: 1000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Observed in Room 250. No Access to Rooms 273 & 288 to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **28N**  
MATERIAL DESCRIPTION: **9x9 White w/Black Streaks Floor Tile**  
MATERIAL LOCATION: **1943 Building- Rooms 255, 273, and 288**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29  
MATERIAL DESCRIPTION: 12x12 Red w/Black & White Blotches Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 019, 022, 020, 117  
MATERIAL QUANTITY: 3500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 019

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12x12 Red w/Black & White Blotches Floor Tile**  
MATERIAL LOCATION: **1943 Building- Rooms 019, 022, 020, 117**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29A  
MATERIAL DESCRIPTION: 12x12 Cream w/Multicolor Beige Checkerboard Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 008, 024, 106, 135, 136, 326, 338  
MATERIAL QUANTITY: 2600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed in Rooms 008, 024, 106, 135 & 136- 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29A**  
MATERIAL DESCRIPTION: **12x12 Cream w/Multicolor Beige Cherckerboard Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 008, 024, 106, 135, 136, 326, 338**  
MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29B  
MATERIAL DESCRIPTION: 12x12 Light & Dark Gray Multicolor Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Room 260

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29B**  
MATERIAL DESCRIPTION: **12x12 Light & Dark Gray Multicolor Floor Tile ABATED**  
MATERIAL LOCATION: **1943 Building- Room 260**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29C**  
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Black and Orange Streaks Floor Tile (MATERIAL REMOVED)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1943 Building- Room 260, 268, 271, 269, 270A MATERIAL REMOVED**  
MATERIAL QUANTITY: **2855** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **No Access to Confirm**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29C**  
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Black and Orange Streaks Floor Tile (MATERIAL REMOVED)**  
MATERIAL LOCATION: **1943 Building- Room 260, 268, 271, 269, 270A MATERIAL REMOVED**  
MATERIAL QUANTITY: **2855** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29D  
MATERIAL DESCRIPTION: 12x12 Maroon Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 262  
MATERIAL QUANTITY: 2800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm- 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29D**  
MATERIAL DESCRIPTION: **12x12 Maroon Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 262**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29E  
MATERIAL DESCRIPTION: 12x12 Cream w/Tan Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Women's Restroom 2nd Floor (2043), 270  
MATERIAL QUANTITY: 1500 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm- 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29E**  
MATERIAL DESCRIPTION: **12x12 Cream w/Tan Floor Tile**  
MATERIAL LOCATION: **1943 Building- Women's Restroom 2nd Floor (2043), 270**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29G  
MATERIAL DESCRIPTION: 12x12 White Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Room 271

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29G**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile ABATED**  
MATERIAL LOCATION: **1943 Building- Room 271**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29H  
MATERIAL DESCRIPTION: 12x12 Multicolor Beige Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1943 Building- Room 2047 Men's Restroom (Abated in 288)**

MATERIAL QUANTITY:    MATERIAL UNITS: **SF**

DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS: **No Access to Confirm**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29H**  
MATERIAL DESCRIPTION: **12x12 Multicolor Beige Floor Tile**  
MATERIAL LOCATION: **1943 Building- Room 2047 Men's Restroom (Abated in 288)**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29I  
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Room 272, 276, 285, 286, and Corridor

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29I**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile ABATED**  
MATERIAL LOCATION: **1943 Building- Room 272, 276, 285, 286, and Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29K**  
MATERIAL DESCRIPTION: **12x12 Tourquise w/Gray Speck Checkerboard Pattern Floor Tile (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1943 Building- Rooms 009, 023, 156, and 277**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **No Access to Room 277 to Confirm. Material Observed in Room 250**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **29K**  
MATERIAL DESCRIPTION: **12x12 Tourquise w/Gray Speck Checkerboard Pattern Floor Tile (Not Observed)**  
MATERIAL LOCATION: **1943 Building- Rooms 009, 023, 156, and 277**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30  
MATERIAL DESCRIPTION: 9x9 Grey Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1939 Building- Room 010, 222, 103, 013, 011, 012, 021  
MATERIAL QUANTITY: 2900 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **9x9 Grey Floor Tile Mastic**  
MATERIAL LOCATION: **1939 Building- Room 010, 222, 103, 013, 011, 012, 021**  
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30A  
MATERIAL DESCRIPTION: 9x9 Tan Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1939 Building- Room 218 and 206

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30A**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1939 Building- Room 218 and 206**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30B  
MATERIAL DESCRIPTION: 9x9 Dark Beige w/Brown Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 250 and 280  
MATERIAL QUANTITY: 1000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Room 280 to Confirm. Observed in 250

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30B**  
MATERIAL DESCRIPTION: **9x9 Dark Beige w/Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 250 and 280**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30D  
MATERIAL DESCRIPTION: 9x9 White w/Gray Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 255 and 273  
MATERIAL QUANTITY: 600 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No Access to Room 273 to Confirm. Not Present in 255

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30D**  
MATERIAL DESCRIPTION: **9x9 White w/Gray Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 255 and 273**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30E  
MATERIAL DESCRIPTION: Beige w/Green Checkerboard Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Office (Vault)  
MATERIAL QUANTITY: 200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30E**  
MATERIAL DESCRIPTION: **Beige w/Green Checkerboard Floor Tile Mastic**  
MATERIAL LOCATION: **Main Office (Vault)**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30F  
MATERIAL DESCRIPTION: 9x9 Black with Cream and Green Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Auditorium 1st Floor  
MATERIAL QUANTITY: 85    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30F**  
MATERIAL DESCRIPTION: **9x9 Black with Cream and Green Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Auditorium 1st Floor**  
MATERIAL QUANTITY: **85** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30G  
MATERIAL DESCRIPTION: White & Black Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 021, 013, 012  
MATERIAL QUANTITY: 280 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Material Removed

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30G**  
MATERIAL DESCRIPTION: **White & Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 021, 013, 012**  
MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30H**  
MATERIAL DESCRIPTION: **9x9 Beige w/Multicolor Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st Floor Women's Restroom and Corridor (West End)**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed 2022**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **30H**  
MATERIAL DESCRIPTION: **9x9 Beige w/Multicolor Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1st Floor Women's Restroom and Corridor (West End)**  
MATERIAL QUANTITY: **260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31  
MATERIAL DESCRIPTION: 9x9 Brown Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Room 262 and Hallway

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1943 Building- Room 262 and Hallway**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31C  
MATERIAL DESCRIPTION: 9x9 Pink Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 282  
MATERIAL QUANTITY: 2800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31C**  
MATERIAL DESCRIPTION: **9x9 Pink Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Room 282**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31D  
MATERIAL DESCRIPTION: 9x9 Light Gray Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Rooms 021 and 288

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: No Access to Room 288 to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31D**  
MATERIAL DESCRIPTION: **9x9 Light Gray Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1943 Building- Rooms 021 and 288**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31E  
MATERIAL DESCRIPTION: 9x9 Gray Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 286  
MATERIAL QUANTITY: 2800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Material Removed. No access to Confirm- 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31E**  
MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Room 286**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31F  
MATERIAL DESCRIPTION: 12x12 Beige w/Brown & White Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 250 and 280  
MATERIAL QUANTITY: 500 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Not Observed in Room 250. No Access to Room 280 to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31F**  
MATERIAL DESCRIPTION: **12x12 Beige w/Brown & White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Rooms 250 and 280**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31G**  
MATERIAL DESCRIPTION: **9x9 Maroon w/Beige Checkerboard Patterned Floor Tile Mastic (Not Observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1943 Building- Rooms 273, 279, 281, 265, 267**  
MATERIAL QUANTITY: **2375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **No Access to Confirm 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31G**  
MATERIAL DESCRIPTION: **9x9 Maroon w/Beige Checkerboard Patterned Floor Tile Mastic (Not Observed)**  
MATERIAL LOCATION: **1943 Building- Rooms 273, 279, 281, 265, 267**  
MATERIAL QUANTITY: **2375** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31H  
MATERIAL DESCRIPTION: 9x9 Tan Speckled Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Rooms 279 & 281

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31H**  
MATERIAL DESCRIPTION: **9x9 Tan Speckled Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1943 Building- Rooms 279 & 281**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31J  
MATERIAL DESCRIPTION: 9x9 Red w/Speckles Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 256 and 279  
MATERIAL QUANTITY: 800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No Access to Room 279 to Confirm. Not Observed in Room 256

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31J**  
MATERIAL DESCRIPTION: **9x9 Red w/Speckles Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Rooms 256 and 279**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31K  
MATERIAL DESCRIPTION: 9x9 Gray with Dark Gray Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 286 (Front)(Back), 285, 287  
MATERIAL QUANTITY: 900 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Material Removed. No Access to Confirm- 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31K**  
MATERIAL DESCRIPTION: **9x9 Gray with Dark Gray Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Room 286 (Front)(Back), 285, 287**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31L**  
MATERIAL DESCRIPTION: **9x9 Dark Gray w/Black Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 288**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Material Removed. No Access to Confirm- 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31L**  
MATERIAL DESCRIPTION: **9x9 Dark Gray w/Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 288**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31N  
MATERIAL DESCRIPTION: White w/Black Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 255, 273, & 288  
MATERIAL QUANTITY: 600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Rooms 273 & 288 to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **31N**  
MATERIAL DESCRIPTION: **White w/Black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Rooms 255, 273, & 288**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32  
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 175, 216 & Hanger  
MATERIAL QUANTITY: 370 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No access to Room 175 to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **Rooms 175, 216 & Hanger**  
MATERIAL QUANTITY: **370** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32A  
MATERIAL DESCRIPTION: 12x12 Beige and Purple Checkerboard Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 002  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32A**  
MATERIAL DESCRIPTION: **12x12 Beige and Purple Checkerboard Floor Tile Mastic**  
MATERIAL LOCATION: **Room 002**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32AA  
MATERIAL DESCRIPTION: 12x12 Tan w/Multicolor Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1st, 2nd Floor Engineer Office, 008, Teachers' Lounge, 136, Auditorium, East Dressing Room, Football Storage

MATERIAL QUANTITY: 2690

MATERIAL UNITS: SF

DAMAGE QUANTITY:

DAMAGE UNITS: SF

COMMENTS: No Tile associated with this HA

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32AA**  
MATERIAL DESCRIPTION: **12x12 Tan w/Multicolor Floor Tile Mastic**  
MATERIAL LOCATION: **1st, 2nd Floor Engineer Office, 008, Teachers' Lounge, 136, Auditorium, East Dressing Room, Football Storage**  
MATERIAL QUANTITY: **2690** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32B  
MATERIAL DESCRIPTION: 12x12 Cream & Tan Checkerboard Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 145  
MATERIAL QUANTITY: 500 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32B**  
MATERIAL DESCRIPTION: **12x12 Cream & Tan Checkerboard Floor Tile Mastic**  
MATERIAL LOCATION: **Room 145**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32D  
MATERIAL DESCRIPTION: 12x12 Reddish Orange Floor Tile Mastic-NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 206

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32D**  
MATERIAL DESCRIPTION: **12x12 Reddish Orange Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **Room 206**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32E**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 214**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32E**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
MATERIAL LOCATION: **Room 214**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32F**  
MATERIAL DESCRIPTION: **12x12 Brown (Multicolored Beige) Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 010**  
MATERIAL QUANTITY: **11265** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32F**  
MATERIAL DESCRIPTION: **12x12 Brown (Multicolored Beige) Floor Tile Mastic**  
MATERIAL LOCATION: **Room 010**  
MATERIAL QUANTITY: **11265** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32G  
MATERIAL DESCRIPTION: 12x12 Gray Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 260, 261, 265, 268, 269, and 270A

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32G**  
MATERIAL DESCRIPTION: **12x12 Gray Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Rooms 260, 261, 265, 268, 269, and 270A**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32H  
MATERIAL DESCRIPTION: 12x12 Burnt Orange Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 2nd Floor Teacher's Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2019 & 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32H**  
MATERIAL DESCRIPTION: **12x12 Burnt Orange Floor Tile Mastic**  
MATERIAL LOCATION: **Room 2nd Floor Teacher's Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32I  
MATERIAL DESCRIPTION: 12x12 Black w/White Speckles Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 206 & 208

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed in Room 208

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32I**  
MATERIAL DESCRIPTION: **12x12 Black w/White Speckles Floor Tile Mastic**  
MATERIAL LOCATION: **Room 206 & 208**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32J  
MATERIAL DESCRIPTION: 12x12 Red Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 104, 241B, 256, and 258  
MATERIAL QUANTITY: 2000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No Access to Room 258 to Confirm. Not Observed in 256

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32J**  
MATERIAL DESCRIPTION: **12x12 Red Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 104, 241B, 256, and 258**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools      UNIT NUMBER: 53011      BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois      AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School      INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.      IDPH LICENSE NO: 100-18281

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32K  
MATERIAL DESCRIPTION: 12x12 Cream w/Red Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile      FRIABLE: No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2022**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32K**  
MATERIAL DESCRIPTION: **12x12 Cream w/Red Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32L  
MATERIAL DESCRIPTION: White and Brown Speckles Floor Tile Mastic-NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 208, Main Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32L**  
MATERIAL DESCRIPTION: **White and Brown Speckles Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **Room 208, Main Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32M  
MATERIAL DESCRIPTION: 12x12 Black Floor Tile Mastic (As Edging)  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 212  
MATERIAL QUANTITY: 115    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32M**  
MATERIAL DESCRIPTION: **12x12 Black Floor Tile Mastic (As Edging)**  
MATERIAL LOCATION: **Room 212**  
MATERIAL QUANTITY: **115** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 320  
MATERIAL DESCRIPTION: 12x12 Turquoise & Light Gray Checkerboard Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 009, 023, 105, 156  
MATERIAL QUANTITY: 2000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Room 156 to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **320**  
MATERIAL DESCRIPTION: **12x12 Turquoise & Light Gray Checkerboard Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 009, 023, 105, 156**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32P**  
MATERIAL DESCRIPTION: **Black & Maroon Checkeboard Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium Pit**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32P**  
MATERIAL DESCRIPTION: **Black & Maroon Checkeboard Floor Tile Mastic**  
MATERIAL LOCATION: **Auditorium Pit**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32Q  
MATERIAL DESCRIPTION: 12x12 Reddish Brown w/White Streak Floor Tile Mastic-NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 256

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32Q**  
MATERIAL DESCRIPTION: **12x12 Reddish Brown w/White Streak Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **Room 256**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32R  
MATERIAL DESCRIPTION: 12x12 Purple/White Checkerboard Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 020 & 023  
MATERIAL QUANTITY: 1200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Room 023 Added 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32R**  
MATERIAL DESCRIPTION: **12x12 Purple/White Checkerboard Floor Tile Mastic**  
MATERIAL LOCATION: **Room 020 & 023**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32U  
MATERIAL DESCRIPTION: Peach & Cream Speckles Floor Tile Mastic-NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 108

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32U**  
MATERIAL DESCRIPTION: **Peach & Cream Speckles Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **Room 108**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32V  
MATERIAL DESCRIPTION: Dark and Light Blue Checkerboard Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 105  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32V**  
MATERIAL DESCRIPTION: **Dark and Light Blue Checkerboard Floor Tile Mastic**  
MATERIAL LOCATION: **Room 105**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32W  
MATERIAL DESCRIPTION: 12x12 Gray/Light Blue Speckled Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 109, 112, 113 & 114  
MATERIAL QUANTITY: 2000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32W**  
MATERIAL DESCRIPTION: **12x12 Gray/Light Blue Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 109, 112, 113 & 114**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32X**  
MATERIAL DESCRIPTION: **Gold and Multicolor Dark Blue Checkerboard Floor Tile Mastic-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 115, 118**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Material is Present in room 115**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32X**  
MATERIAL DESCRIPTION: **Gold and Multicolor Dark Blue Checkerboard Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **Rooms 115, 118**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32Z  
MATERIAL DESCRIPTION: 12x12 Multicolor Light Blue Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 014

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **32Z**  
MATERIAL DESCRIPTION: **12x12 Multicolor Light Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Room 014**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33  
MATERIAL DESCRIPTION: 12x12 Red w/White and Black Blotches Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 217, 117, 022, 020, and 019  
MATERIAL QUANTITY: 3500 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed in Room 014

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **12x12 Red w/White and Black Blotches Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Rooms 217, 117, 022, 020, and 019**  
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12x12 Creme w/Multicolor Beige Checkerboard Patterned Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1943 Building- Room 008, 024, 135, 136, 259, 266, 338**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Room 259 to Confirm**

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33A**  
MATERIAL DESCRIPTION: **12x12 Creme w/Multicolor Beige Checkerboard Patterned Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Room 008, 024, 135, 136, 259, 266, 338**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33B  
MATERIAL DESCRIPTION: 12x12 Light and Dark Gray Floor Tile Mastic-NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE:    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Room 260

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years. No Access to Confirm- 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33B**  
MATERIAL DESCRIPTION: **12x12 Light and Dark Gray Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **1943 Building- Room 260**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33C**  
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Black and Orange Streaks Floor Tile Mastic-NOT OBSERVED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1943 Building- Rooms 260, 268, 269 & 271**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years. No Access to Confirm- 2022**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33C**  
MATERIAL DESCRIPTION: **12x12 Dark Gray w/Black and Orange Streaks Floor Tile Mastic-NOT OBSERVED**  
MATERIAL LOCATION: **1943 Building- Rooms 260, 268, 269 & 271**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33D  
MATERIAL DESCRIPTION: 12x12 Maroon Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 262  
MATERIAL QUANTITY: 2800 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33D**  
MATERIAL DESCRIPTION: **12x12 Maroon Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Room 262**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33E  
MATERIAL DESCRIPTION: 12x12 Cream with Tan Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Women's Restroom 2nd Floor (2043), 270  
MATERIAL QUANTITY: 2335    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33E**  
MATERIAL DESCRIPTION: **12x12 Cream with Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Women's Restroom 2nd Floor (2043), 270**  
MATERIAL QUANTITY: **2335** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33G  
MATERIAL DESCRIPTION: 12x12 White Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Room 271  
MATERIAL QUANTITY: 1200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33G**  
MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Room 271**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33I**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1943 Building- Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33I**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building- Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33J**  
MATERIAL DESCRIPTION: **Dark, Light Beige/Gray Checkerboard Pattern Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1943 Building- Room 282 (Back Room)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No Access to Confirm**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33J**  
MATERIAL DESCRIPTION: **Dark, Light Beige/Gray Checkerboard Pattern Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1943 Building- Room 282 (Back Room)**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33K  
MATERIAL DESCRIPTION: 12x12 Turquoise w/Gray Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building - Rooms 009, 023  
MATERIAL QUANTITY: 2400    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **33K**  
MATERIAL DESCRIPTION: **12x12 Turquoise w/Gray Floor Tile Mastic**  
MATERIAL LOCATION: **1943 Building - Rooms 009, 023**  
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34  
MATERIAL DESCRIPTION: Mastic Beneath Linoleum  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Gym (Room 251) 253  
MATERIAL QUANTITY: 5600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Mastic Beneath Linoleum**  
MATERIAL LOCATION: **Gym (Room 251) 253**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34A  
MATERIAL DESCRIPTION: Red, Black, Brown, and Tan Linoleum Pattern Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium 1st and 2nd Floor Foyer

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **34A**  
MATERIAL DESCRIPTION: **Red, Black, Brown, and Tan Linoleum Pattern Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Auditorium 1st and 2nd Floor Foyer**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34B  
MATERIAL DESCRIPTION: Black Linoleum Mastic NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 130

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years, including 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **34B**  
MATERIAL DESCRIPTION: **Black Linoleum Mastic NOT OBSERVED**  
MATERIAL LOCATION: **Room 130**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35  
MATERIAL DESCRIPTION: Grey Linoleum  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 208

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: 2019 Inspection stated Linoleum's color is Grey

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Grey Linoleum**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **9x9 Gray Tiles**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 288**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **No Access to Confirm 2022**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **9x9 Gray Tiles**  
MATERIAL LOCATION: **Room 288**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37  
MATERIAL DESCRIPTION: 9x9 Brown Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 286A  
MATERIAL QUANTITY: 720    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
MATERIAL LOCATION: **286A**  
MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 38  
MATERIAL DESCRIPTION: 12x12 Beige Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 3rd Floor Hallway, Rooms 28, 100, 120, 127, and Lunchroom  
MATERIAL QUANTITY: 5600    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **3rd Floor Hallway, Rooms 28, 100, 120, 127, and Lunchroom**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38M**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **3rd Floor Hallway, Rooms 28, 100, 120, 127 and Lunchroom**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Observed in Rooms 100 & 241A**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **38M**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **3rd Floor Hallway, Rooms 28, 100, 120, 127 and Lunchroom**  
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 White w/Beige Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318**

MATERIAL QUANTITY: **123000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Some Areas Have Been Decommissioned and Are No Longer Accessible. Tile Sampled in Room 222**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 White w/Beige Specks Floor Tile**  
MATERIAL LOCATION: **1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318**  
MATERIAL QUANTITY: **123000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39M**  
MATERIAL DESCRIPTION: **12x12 White w/Beige Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318**

MATERIAL QUANTITY: **123000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Some Areas Have Been Decommissioned and Are No Longer Accessible. Tile in Room 222 Sampled**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **39M**  
MATERIAL DESCRIPTION: **12x12 White w/Beige Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1st & 2nd Floors, Rooms 010, 011, 012, 113, 116, 145A, 134, 209C, 212, 214, 218, 221, 222, 228, 240, 241A, 248, 253A, and 318**  
MATERIAL QUANTITY: **123000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12x12 Yellow with White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12x12 Yellow with White Floor Tile**  
MATERIAL LOCATION: **Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40M  
MATERIAL DESCRIPTION: 12x12 Yellow w/White Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **40M**  
MATERIAL DESCRIPTION: **12x12 Yellow w/White Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 103A, 103B, 103C, 103D, 204, 205, 205A, 206, 213A, 213B, 213D, and Hallway**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41  
MATERIAL DESCRIPTION: 12x12 Beige Speckled Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 322 & 326  
MATERIAL QUANTITY: 1100    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Rooms 322 & 326 added in 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile**  
MATERIAL LOCATION: **Rooms 322 & 326**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 41M  
MATERIAL DESCRIPTION: 12x12 Beige Speckled Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 322 & 326  
MATERIAL QUANTITY: 1100    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Rooms 322 & 326 added in 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **41M**  
MATERIAL DESCRIPTION: **12x12 Beige Speckled Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 322 & 326**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Red & White Checkered Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 179**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No Access to Room 179 to Confirm**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Red & White Checkered Floor Tile ABATED**  
MATERIAL LOCATION: **Room 179**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42M  
MATERIAL DESCRIPTION: 12x12 Red and White Checkered Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 179  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Room 179 to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **42M**  
MATERIAL DESCRIPTION: **12x12 Red and White Checkered Floor Tile Mastic**  
MATERIAL LOCATION: **Room 179**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Brown, Beige and Red Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria Court**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Brown, Beige and Red Floor Tile**  
MATERIAL LOCATION: **Cafeteria Court**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43M**  
MATERIAL DESCRIPTION: **12x12 Brown, Beige and Red Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Cafeteria Court**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **43M**  
MATERIAL DESCRIPTION: **12x12 Brown, Beige and Red Floor Tile Mastic**  
MATERIAL LOCATION: **Cafeteria Court**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 44  
MATERIAL DESCRIPTION: Beige Linoleum  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 013

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Beige Linoleum**  
MATERIAL LOCATION: **Room 013**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 44M  
MATERIAL DESCRIPTION: Beige Linoleum Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 013

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **44M**  
MATERIAL DESCRIPTION: **Beige Linoleum Adhesive**  
MATERIAL LOCATION: **Room 013**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Gray Terrazo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwells**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **Gray Terrazo**  
MATERIAL LOCATION: **Stairwells**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46  
MATERIAL DESCRIPTION: Beige Terrazzo  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Main Hallway  
MATERIAL QUANTITY: 2000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Beige Terrazzo**  
MATERIAL LOCATION: **Main Hallway**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 47M  
MATERIAL DESCRIPTION: 1'x1' Ceiling Tile Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Lunchroom  
MATERIAL QUANTITY: 4000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **47M**  
MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Adhesive**  
MATERIAL LOCATION: **Lunchroom**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 48  
MATERIAL DESCRIPTION: 2'x4' Lay-In Ceiling Panels  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1st, 2nd and 3rd Floor Hallways  
MATERIAL QUANTITY: 50000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Cannot Confirm in Decommissioned Areas

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **2'x4' Lay-In Ceiling Panels**  
MATERIAL LOCATION: **1st, 2nd and 3rd Floor Hallways**  
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **2'x4' Lay-In Smooth Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Band Room and 014**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **2'x4' Lay-In Smooth Ceiling Panels**  
MATERIAL LOCATION: **Band Room and 014**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **2'x2' Lay-In Ceiling Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 204, 205, and 213**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **2'x2' Lay-In Ceiling Panels**  
MATERIAL LOCATION: **Rooms 204, 205, and 213**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: AP-1  
MATERIAL DESCRIPTION: Acoustical Plaster  
HISTORICAL AHERA DAMAGE CATEGORY 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY: 8000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **AP-1**  
MATERIAL DESCRIPTION: **Acoustical Plaster**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement, Janitor's Closet, Northeast Corner Stairs, 3rd Floor Fan Room, Fan Room #12, Potting Room**

MATERIAL QUANTITY: **75**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Joint Insulation on Fiberglass Insulated Piping**  
MATERIAL LOCATION: **Basement, Janitor's Closet, Northeast Corner Stairs, 3rd Floor Fan Room, Fan Room #12, Potting Room**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-1  
MATERIAL DESCRIPTION: Tan Baseboard ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: 1943 Building- 278 and 278 Office

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-1**  
MATERIAL DESCRIPTION: **Tan Baseboard ABATED**  
MATERIAL LOCATION: **1943 Building- 278 and 278 Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-2  
MATERIAL DESCRIPTION: Turquoise Baseboard ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943 Building- Room 277

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-2**  
MATERIAL DESCRIPTION: **Turquoise Baseboard ABATED**  
MATERIAL LOCATION: **1943 Building- Room 277**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-3  
MATERIAL DESCRIPTION: 4" Baseboard ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1943- Room 281, 280, 282 Front and Back, 286 Front and Back, 285 Back Office

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-3**  
MATERIAL DESCRIPTION: **4" Baseboard ABATED**  
MATERIAL LOCATION: **1943- Room 281, 280, 282 Front and Back, 286 Front and Back, 285 Back Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-4  
MATERIAL DESCRIPTION: Black Baseboard ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1939 Building- Room 166

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-4**  
MATERIAL DESCRIPTION: **Black Baseboard ABATED**  
MATERIAL LOCATION: **1939 Building- Room 166**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-4A  
MATERIAL DESCRIPTION: Black Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 271, 113, 282  
MATERIAL QUANTITY: 100 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-4A**  
MATERIAL DESCRIPTION: **Black Baseboard**  
MATERIAL LOCATION: **Rooms 271, 113, 282**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-5  
MATERIAL DESCRIPTION: Brown Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1939 Building- Room 128, 115, Women's Restroom and Corridor  
MATERIAL QUANTITY: 300 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-5**  
MATERIAL DESCRIPTION: **Brown Baseboard**  
MATERIAL LOCATION: **1939 Building- Room 128, 115, Women's Restroom and Corridor**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-5A  
MATERIAL DESCRIPTION: Green Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 153  
MATERIAL QUANTITY: 100    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-5A**  
MATERIAL DESCRIPTION: **Green Baseboard**  
MATERIAL LOCATION: **Room 153**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-6  
MATERIAL DESCRIPTION: Brown Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 115, 209 & 218  
MATERIAL QUANTITY: 70    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-6**  
MATERIAL DESCRIPTION: **Brown Baseboard**  
MATERIAL LOCATION: **Rooms 115, 209 & 218**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BB-7  
MATERIAL DESCRIPTION: Blue Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Connecting Room between 113 and 115  
MATERIAL QUANTITY: 100    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BB-7**  
MATERIAL DESCRIPTION: **Blue Baseboard**  
MATERIAL LOCATION: **Connecting Room between 113 and 115**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **Tan Baseboard Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1943 Building- Room 278 and 278 Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No Access to Confirm**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-1**  
MATERIAL DESCRIPTION: **Tan Baseboard Mastic ABATED**  
MATERIAL LOCATION: **1943 Building- Room 278 and 278 Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-2**  
MATERIAL DESCRIPTION: **Turquoise Baseboard Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1943 Building- Room 277**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No Access to Confirm**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-2**  
MATERIAL DESCRIPTION: **Turquoise Baseboard Mastic ABATED**  
MATERIAL LOCATION: **1943 Building- Room 277**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-3**  
MATERIAL DESCRIPTION: **4" Black Baseboard Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1943 Building- Room 281, 280, 280 Front and Back, 286 Front and Back, 285 Back Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No Access to Confirm**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-3**  
MATERIAL DESCRIPTION: **4" Black Baseboard Mastic ABATED**  
MATERIAL LOCATION: **1943 Building- Room 281, 280, 280 Front and Back, 286 Front and Back, 285 Back Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-4**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1939- Room 166**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-4**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic ABATED**  
MATERIAL LOCATION: **1939- Room 166**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-4A**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 113, 28**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-4A**  
MATERIAL DESCRIPTION: **Black Baseboard Mastic**  
MATERIAL LOCATION: **Rooms 113, 28**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BBM-5  
MATERIAL DESCRIPTION: Mastic Beneath Brown Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1939- Room 128, 115, Women's Restroom and Corridor  
MATERIAL QUANTITY: 300 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-5**  
MATERIAL DESCRIPTION: **Mastic Beneath Brown Baseboard**  
MATERIAL LOCATION: **1939- Room 128, 115, Women's Restroom and Corridor**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: BBM-5A  
MATERIAL DESCRIPTION: Green Baseboard Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 153  
MATERIAL QUANTITY: 100 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-5A**  
MATERIAL DESCRIPTION: **Green Baseboard Mastic**  
MATERIAL LOCATION: **Room 153**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-6**  
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 209, 218, 282, 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No Access to Room 282 to Confirm**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-6**  
MATERIAL DESCRIPTION: **Brown Baseboard Mastic**  
MATERIAL LOCATION: **Rooms 209, 218, 282, 115**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **BBM-7**  
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Connecting Room between 113 and 115**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **LF**  
COMMENTS: **Not Observed 2019**

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **BBM-7**  
MATERIAL DESCRIPTION: **Blue Baseboard Mastic**  
MATERIAL LOCATION: **Connecting Room between 113 and 115**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: C  
MATERIAL DESCRIPTION: Pipe Joint Insulation on Preformed Insulated Pipe  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Amosite    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Pipe Space, East and West Dressing Room, Room 117, 1939 Fan Room, Room 114  
MATERIAL QUANTITY: 216    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Pipe Joint Insulation on Preformed Insulated Pipe**  
MATERIAL LOCATION: **Pipe Space, East and West Dressing Room, Room 117, 1939 Fan Room, Room 114**  
MATERIAL QUANTITY: **216** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Fitting Insulation on Preformed Insulated Piping**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1939 Building- Pipe Space, East and West Dressing Room in 117**  
MATERIAL QUANTITY: **2180** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Fitting Insulation on Preformed Insulated Piping**  
MATERIAL LOCATION: **1939 Building- Pipe Space, East and West Dressing Room in 117**  
MATERIAL QUANTITY: **2180** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: DE-1  
MATERIAL DESCRIPTION: 12x12 Yellow Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Driver's Education Building (Separate Building)  
MATERIAL QUANTITY: 1400    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **DE-1**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**  
MATERIAL LOCATION: **Driver's Education Building (Separate Building)**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **DE-2**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Driver's Education Classroom (Separate Building)**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **DE-2**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**  
MATERIAL LOCATION: **Driver's Education Classroom (Separate Building)**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: DW-1  
MATERIAL DESCRIPTION: Drywall  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 266, 274, 274D, 274A, 278, 285  
MATERIAL QUANTITY: 1200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **DW-1**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **1943 Building- Rooms 266, 274, 274D, 274A, 278, 285**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: DW-2  
MATERIAL DESCRIPTION: Drywall Compound  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Rooms 266, 274, 274D, 274A 278, 285  
MATERIAL QUANTITY: 1200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **DW-2**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **1943 Building- Rooms 266, 274, 274D, 274A 278, 285**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1939 Building- Above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage**

MATERIAL QUANTITY: **6450**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1939 Building- Above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage**  
MATERIAL QUANTITY: **6450** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FD-1  
MATERIAL DESCRIPTION: Insulation in Fire Rated Doors  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Facility  
MATERIAL QUANTITY: 412 MATERIAL UNITS: EA  
DAMAGE QUANTITY: DAMAGE UNITS: EA

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FD-1**  
MATERIAL DESCRIPTION: **Insulation in Fire Rated Doors**  
MATERIAL LOCATION: **Throughout Facility**  
MATERIAL QUANTITY: **412** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-1  
MATERIAL DESCRIPTION: 12x12 Beige, Gray w/Tan Pattern Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar Class Area  
MATERIAL QUANTITY: 250    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-1**  
MATERIAL DESCRIPTION: **12x12 Beige, Gray w/Tan Pattern Floor Tile**  
MATERIAL LOCATION: **Hangar Class Area**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-10  
MATERIAL DESCRIPTION: 12x12 Green w/White & Dark Green Specks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 110, 110A & 110B  
MATERIAL QUANTITY: 2200 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-10**  
MATERIAL DESCRIPTION: **12x12 Green w/White & Dark Green Specks Floor Tile**  
MATERIAL LOCATION: **Room 110, 110A & 110B**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-11  
MATERIAL DESCRIPTION: 12x12 Cream w/White & Dark Green Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Rooms 282, 283, 286, 287  
MATERIAL QUANTITY: 2800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed. No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-11**  
MATERIAL DESCRIPTION: **12x12 Cream w/White & Dark Green Floor Tile**  
MATERIAL LOCATION: **Rooms 282, 283, 286, 287**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-2  
MATERIAL DESCRIPTION: 12x12 Cream w/Multi-Colored Specks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 153  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-2**  
MATERIAL DESCRIPTION: **12x12 Cream w/Multi-Colored Specks Floor Tile**  
MATERIAL LOCATION: **Room 153**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-3  
MATERIAL DESCRIPTION: 12x12 Yellow Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 115  
MATERIAL QUANTITY: 700    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed 2019

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-3**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-4  
MATERIAL DESCRIPTION: 12x12 Maroon Floor Tile NOT OBSERVED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 115

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed Multiple Years

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-4**  
MATERIAL DESCRIPTION: **12x12 Maroon Floor Tile NOT OBSERVED**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-5  
MATERIAL DESCRIPTION: 12x12 Light Blue Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Rooms 109, 114, 113, 112  
MATERIAL QUANTITY: 2800    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-5**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile**  
MATERIAL LOCATION: **Rooms 109, 114, 113, 112**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-8  
MATERIAL DESCRIPTION: 12x12 Tan w/Brown & White Streaks Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-8**  
MATERIAL DESCRIPTION: **12x12 Tan w/Brown & White Streaks Floor Tile**  
MATERIAL LOCATION: **Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FT-9  
MATERIAL DESCRIPTION: Dark Blue w/Gray & Light Blue Linoleum  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 208  
MATERIAL QUANTITY: 700    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FT-9**  
MATERIAL DESCRIPTION: **Dark Blue w/Gray & Light Blue Linoleum**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-1  
MATERIAL DESCRIPTION: 12x12 Beige Gray w/Tan Pattern Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Hangar Class Area  
MATERIAL QUANTITY: 2580    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-1**  
MATERIAL DESCRIPTION: **12x12 Beige Gray w/Tan Pattern Floor Tile Mastic**  
MATERIAL LOCATION: **Hangar Class Area**  
MATERIAL QUANTITY: **2580** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-10  
MATERIAL DESCRIPTION: 12x12 Green w/White & Dark Green Specks VFT Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 110, 110A & 110B  
MATERIAL QUANTITY: 2200    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-10**  
MATERIAL DESCRIPTION: **12x12 Green w/White & Dark Green Specks VFT Mastic**  
MATERIAL LOCATION: **Rooms 110, 110A & 110B**  
MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-11  
MATERIAL DESCRIPTION: 12x12 Cream w/Reddish Brown Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 282, 283, 286, 287

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

---

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-11**  
MATERIAL DESCRIPTION: **12x12 Cream w/Reddish Brown Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **Rooms 282, 283, 286, 287**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-2  
MATERIAL DESCRIPTION: 12x12 Cream w/Multi-Colored Specks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE  
MATERIAL LOCATION: Room 153  
MATERIAL QUANTITY: 500    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-2**  
MATERIAL DESCRIPTION: **12x12 Cream w/Multi-Colored Specks Floor Tile Mastic**  
MATERIAL LOCATION: **Room 153**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-3**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-3**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-4  
MATERIAL DESCRIPTION: 12x12 Brown Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 115  
MATERIAL QUANTITY: 700    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-4**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **Room 115**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 109, 114, 113, 112**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-5**  
MATERIAL DESCRIPTION: **12x12 Light Blue Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 109, 114, 113, 112**  
MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-8  
MATERIAL DESCRIPTION: 12x12 Tan w/ Brown & White Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326  
MATERIAL QUANTITY: 3000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-8**  
MATERIAL DESCRIPTION: **12x12 Tan w/ Brown & White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **Rooms 206, 204, 212, 214, 216A, 216B, 218, 208, 322 & 326**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: FTM-9  
MATERIAL DESCRIPTION: Dark Blue w/Gray & Light Blue Linoleum Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Room 208  
MATERIAL QUANTITY: 700    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: Christopher Antonopoulos

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **FTM-9**  
MATERIAL DESCRIPTION: **Dark Blue w/Gray & Light Blue Linoleum Mastic**  
MATERIAL LOCATION: **Room 208**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Duct Covering On Breaching**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room, Throughout Fan Rooms**  
MATERIAL QUANTITY: **1590** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Duct Covering On Breeching**  
MATERIAL LOCATION: **Boiler Room, Throughout Fan Rooms**  
MATERIAL QUANTITY: **1590** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: HA-1000  
MATERIAL DESCRIPTION: Transite Counter and Tabletops  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Rooms 009, 012, 019, 021, 022, 023, 024, 145A, 161, 213A & 213B  
MATERIAL QUANTITY: 350    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **HA-1000**  
MATERIAL DESCRIPTION: **Transite Counter and Tabletops**  
MATERIAL LOCATION: **Rooms 009, 012, 019, 021, 022, 023, 024, 145A, 161, 213A & 213B**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: I  
MATERIAL DESCRIPTION: Tank #1 Jacket ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Boiler Room  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Tank #1 Jacket ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: J  
MATERIAL DESCRIPTION: Tank #1 Mag Block Insulation ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Boiler Room  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Tank #1 Mag Block Insulation ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: K  
MATERIAL DESCRIPTION: Tank #2 Jacket ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Tank #2 Jacket ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L  
MATERIAL DESCRIPTION: Tank #2 Mag Block Insulation ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Boiler Room  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **L**  
MATERIAL DESCRIPTION: **Tank #2 Mag Block Insulation ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: M  
MATERIAL DESCRIPTION: Tank #3 Jacket ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **M**  
MATERIAL DESCRIPTION: **Tank #3 Jacket ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: N  
MATERIAL DESCRIPTION: Tank #3 Mag Block Insulation ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Boiler Room  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Tank #3 Mag Block Insulation ABATED**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:  O  
MATERIAL DESCRIPTION: Tank Jacket ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Kitchen Prep.  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Tank Jacket ABATED**

MATERIAL LOCATION: **Kitchen Prep.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: P  
MATERIAL DESCRIPTION: Tank Insulation ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen Prep.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Tank Insulation ABATED**  
MATERIAL LOCATION: **Kitchen Prep.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Q  
MATERIAL DESCRIPTION: Tank Insulation ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:  
DISTURBANCE POTENTIAL:  
MATERIAL LOCATION: Hangar  
MATERIAL QUANTITY:    MATERIAL UNITS:  
DAMAGE QUANTITY:    DAMAGE UNITS:  
COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Tank Insulation ABATED**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: R  
MATERIAL DESCRIPTION: Tank Jacket ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hangar

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Tank Jacket ABATED**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: S  
MATERIAL DESCRIPTION: Fireproofing  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW

MATERIAL LOCATION: Hangar

MATERIAL QUANTITY:    MATERIAL UNITS: SF

DAMAGE QUANTITY:    DAMAGE UNITS: SF

COMMENTS: Not Observed 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Fireproofing**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Duct Covering**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Hangar**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material Removed**

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Duct Covering**  
MATERIAL LOCATION: **Hangar**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: **0** DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1943 Building- Side of Tunnels**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS: **No Access to Confirm**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation**  
MATERIAL LOCATION: **1943 Building- Side of Tunnels**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: U-1  
MATERIAL DESCRIPTION: Preform Fittings  
HISTORICAL AHERA DAMAGE CATEGORY 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Side of Tunnels  
MATERIAL QUANTITY: 10 MATERIAL UNITS: LF  
DAMAGE QUANTITY: DAMAGE UNITS: LF  
COMMENTS: No Access to Confirm

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **U-1**  
MATERIAL DESCRIPTION: **Preform Fittings**  
MATERIAL LOCATION: **1943 Building- Side of Tunnels**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1943 Building- Side of Tunnels**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS: **No Access to Confirm**

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1943 Building- Side of Tunnels**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: W  
MATERIAL DESCRIPTION: MJP E/F/V on Aircell Pipe Insulation  
HISTORICAL AHERA DAMAGE CATEGORY: 7 Any remaining friable ACBM or friable suspect ACBM  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Amosite    FRIABLE: Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: 1943 Building- Sides of Tunnels  
MATERIAL QUANTITY: 25    MATERIAL UNITS: LF  
DAMAGE QUANTITY:    DAMAGE UNITS: LF  
COMMENTS: No Access to Confirm

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**  
MATERIAL LOCATION: **1943 Building- Sides of Tunnels**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School** INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Aircell Joints**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1939 Building- Attic above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage**

MATERIAL QUANTITY: **840** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Christopher Antonopoulos*

Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Aircell Joints**  
MATERIAL LOCATION: **1939 Building- Attic above Teacher's Lunchroom, Throughout Fan Rooms and Basement Storage**  
MATERIAL QUANTITY: **840** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53011 BUIDLING ID: 1010  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St. IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Y  
MATERIAL DESCRIPTION: 12x12 White, Black, Red & Gray Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Classrooms and Corridors  
MATERIAL QUANTITY: 5000 MATERIAL UNITS: SF  
DAMAGE QUANTITY: DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature:

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **12x12 White, Black, Red & Gray Floor Tile**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 53011    BUILDING ID: 1010  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Christopher Antonopoulos  
SCHOOL NAME: Chicago Vocational High School    INSPECTION DATE: 9/29/2022  
ADDRESS: 2100 E. 87th St.    IDPH LICENSE NO: 100-18281

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Z  
MATERIAL DESCRIPTION: 12x12 White, Black, Red & Gray Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY: 6 ACBM with the potential for damage  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: LOW  
MATERIAL LOCATION: Throughout Classrooms and Corridors  
MATERIAL QUANTITY: 5000    MATERIAL UNITS: SF  
DAMAGE QUANTITY:    DAMAGE UNITS: SF  
COMMENTS: Not Observed 2022

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53011** BUIDLING ID: **1010**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School** REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.** IDPH LICENSE NO: **100-18281**

---

HOMOGENEOUS AREA: **Z**  
MATERIAL DESCRIPTION: **12x12 White, Black, Red & Gray Floor Tile Mastic**  
MATERIAL LOCATION: **Throughout Classrooms and Corridors**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **53011**    BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**    INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" Blue & White w/Green Specks Floor Tile**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" Blue & White w/Green Specks Floor Tile**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **10/18/2022** \_\_\_\_\_

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **53011**    BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**    INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12x12 Light Grey & Grey Mix Floor Tile**  
MATERIAL LOCATION: **Rooms 256A & 257**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*    Date: **09/29/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **12x12 Light Grey & Grey Mix Floor Tile**  
MATERIAL LOCATION: **Rooms 256A & 257**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **53011**    BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**    INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**    IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12x12 Light Grey & Grey Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Room 256A & 257**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **12x12 Light Grey & Grey Mix Floor Tile Mastic**  
MATERIAL LOCATION: **Room 256A & 257**  
MATERIAL QUANTITY: **2000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**      INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Blue & White w/Green Specks Floor Tile**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: *Christopher Antonopoulos*      Date: **09/29/2022**



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Blue & White w/Green Specks Floor Tile**  
MATERIAL LOCATION: **Room 106**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: 10/18/2022

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**      INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Hard Plaster**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **100000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **SURFACE**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **MODERATE**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **50**      DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:  
Damaged Plaster in Rooms 222, 330, 342 & 344. (Sampled in Room 344)

Inspector's Signature: *Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Hard Plaster**  
MATERIAL LOCATION: **Throughout Building**  
MATERIAL QUANTITY: **100000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:  
patch and repair

Management Planner's Signature:  \_\_\_\_\_ Date: **10/18/2022** \_\_\_\_\_

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**      INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Black Chalkboards**  
MATERIAL LOCATION: **3rd Floor Classrooms**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Black Chalkboards**  
MATERIAL LOCATION: **3rd Floor Classrooms**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **10/18/2022** \_\_\_\_\_

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**      INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12"x12" White, Blue & Beige Mix Floor Tile**  
MATERIAL LOCATION: **Rooms 019, 021 & 023**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12"x12" White, Blue & Beige Mix Floor Tile**  
MATERIAL LOCATION: **Rooms 019, 021 & 023**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: **10/18/2022** \_\_\_\_\_

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**      INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" White, Blue & Beige Mix Floor Tile**  
MATERIAL LOCATION: **Rooms 019, 021 & 023**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022



# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Mastic associated with 12"x12" White, Blue & Beige Mix Floor Tile**  
MATERIAL LOCATION: **Rooms 019, 021 & 023**  
MATERIAL QUANTITY: **600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **10/18/2022**

# Chicago Public Schools

TEM Environmental, Inc.  
2022 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Christopher Antonopoulos**  
SCHOOL NAME: **Chicago Vocational High School**      INSPECTION DATE: **9/29/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
MATERIAL CATEGORY: **MISC**      FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL:      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY:      DAMAGE REASON:  
DAMAGE UNITS:  
COMMENTS:

Inspector's Signature: \_\_\_\_\_

*Christopher Antonopoulos*

Date: 09/29/2022

# Chicago Public Schools

## TEM Environmental, Inc. 2022 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **53011**      BUILDING ID: **1010**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Todd Huffer**  
SCHOOL NAME: **Chicago Vocational High School**      REVIEW DATE: **10/18/2022**  
ADDRESS: **2100 E. 87th St.**      IDPH LICENSE NO: **100-18281**

HOMOGENEOUS AREA: **NEW**  
MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**  
MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**  
MATERIAL QUANTITY:      MATERIAL UNITS:  
DAMAGE QUANTITY:      DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  \_\_\_\_\_ Date: 10/18/2022

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/01/2021 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II; Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

06/01/2021

Course Dates:

06/01/2022

Expires:

2106BIR11

Certificate Number:

A handwritten signature in black ink, appearing to read "N Penneff".

Director of Training

Nicholas J. Penneff

Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that CHRISTOPHER J. ANTONOPOULOS  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 06/03/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

06/03/2022

Course Dates:

06/03/2023

Expires:

2206BIR01

Certificate Number:




37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

A handwritten signature in black ink, appearing to read "N. Peneff", is written over a light gray rectangular background.

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

 **ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>
100 - 18281	2/10/2022	05/15/2023

**CHRISTOPHER J ANTONOPO**  
1736 W 102nd ST  
CHICAGO, IL 60643

Environmental Health



<b>ENDORSEMENT</b>	<b>TC EXPIRES</b>
INSPECTOR	6/1/2022

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012557

Kathy DeSalvo, Director





525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**TODD T HUFFER**  
315 HATLEN COURT  
MT. PROSPECT, IL 60056

2/18/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09870

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

			<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
<b>ID NUMBER</b> 100 - 09870	<b>ISSUED</b> 2/18/2022	<b>EXPIRES</b> 05/15/2023			INSPECTOR	11/1/2022
<b>TODD T HUFFER</b> 315 HATLEN COURT MT. PROSPECT, IL 60056 Environmental Health			MANAGEMENT PLANNER			11/19/2022
			PROJECT MANAGER			10/20/2022
			AIR SAMPLING PROFESSIONAL			
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192815

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: BIR2210113255

  
Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Todd Huffer**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/11/2022

Exam Date: 10/11/2022

Expiration Date: 10/11/2023

Certificate Number: MPR2210113265

  
Kathy DeSalvo, Director

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed