

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0011
SCHOOL NAME: Farragut Academy
ADDRESS OF SCHOOL: 2345 S. Christiana
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **7/31/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/12/2022 ENROLLMENT 456
IDPH INSPECTOR LICENSE NUMBER: 100-20411
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



7/14/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Farragut Academy

2345 S. Christiana
Chicago, IL, 60623

Unit: 53091
Building ID: 1300

IDPH ID Number: 14-016-2990-0011

REPORT DATE:

Thursday, July 14, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

07/14/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 53091 Region: 03 IDPH ID: 14-016-2990-0011

School: Farragut Academy Building ID: 1300

Address: 2345 S. Christiana

Chicago, IL, 60623

Building Contact: Barragan, Ricardo

Contact Phone: 7737106983

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/12/2022

Review Date: 07/14/2022

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: July 14, 2022

RE: Farragut Academy, Unit 53091
2345 S. Christiana
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Farragut Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Farragut Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Farragut Academy
Address: 2345 S. Christiana
IDPH ID: 14-016-2990-0011
Contact: Barragan, Ricardo

Unit: 53091
Chicago, IL, 60623
Building ID: 1300
Phone: 7737106983

Region: 03

2. Description of Facility

Original Construction: 1974
Total Square Footage: 222991
Current Occupancy: 456

Additional Construction: 1909
No of Floors: 3

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Benyamen Maradkel


Inspector IDPH license # 100-20411
Reinspection Date: 7/12/2022

Signature: 
Date: 7/12/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature: 
Date: 07/14/2022

7. Review Date: 07/14/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/14/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Farragut Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1300:

100	4" Gray baseboard
101	4" Gray baseboard adhesive
102	2 x 2 Pinhole ceiling tiles
103	Black multicolor terrazzo
104	12" x 12" White w/ Gray Specks Floor Tile
105	12" x 12" White w/ Gray Specks Floor Tile Mastic
106	Black chalkboards
107	12" x 12" Light Gray w/ Beige Specks Floor Tile
108	12" x 12" Light Gray w/ Beige Specks Floor Tile Mastic

109	12" x 12" Gray w/ Dark Gray Specks Floor Tile
110	12" x 12" Gray w/ Dark Gray Specks Floor Tile Mastic
30	Fire doors
40	Purple carpet mastic
41	12" x 12" White Floor Tile w/ Brown, black, gray Streaks
67	Caulk Around Bottom of Sink
71	Spray on Fire Proofing
73	Adhesive on Wall
84	12" x 12" White w/ tan Streaks Vinyl Floor Tile & glue
91	Cardboard pipe insulation
92	Hard Joint Compound on Aircell Pipe Insulation
93	4" Blue baseboard
94	4" Blue baseboard adhesive
95	Black desk tops
96	Gray linoleum
97	Dark Yellow linoleum
98	Dark Blue linoleum
99	Gray, Dark Yellow, and Dark Blue Linoleum Mastic

B. The following new homogenous areas have been identified for Building 1300:

100	4" Gray baseboard
101	4" Gray baseboard adhesive
102	2 x 2 Pinhole ceiling tiles
103	Black multicolor terrazzo
104	12" x 12" White w/ Gray Specks Floor Tile
105	12" x 12" White w/ Gray Specks Floor Tile Mastic
106	Black chalkboards
107	12" x 12" Light Gray w/ Beige Specks Floor Tile
108	12" x 12" Light Gray w/ Beige Specks Floor Tile Mastic
109	12" x 12" Gray w/ Dark Gray Specks Floor Tile
110	12" x 12" Gray w/ Dark Gray Specks Floor Tile Mastic
93	4" Blue baseboard
94	4" Blue baseboard adhesive
95	Black desk tops
96	Gray linoleum
97	Dark Yellow linoleum
98	Dark Blue linoleum
99	Gray, Dark Yellow, and Dark Blue Linoleum Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	12" x12" Light Tan Replacement Floor Tile
08	12" x 12" Olive Green Floor Tile
100	4" Gray baseboard
101	4" Gray baseboard adhesive
102	2 x 2 Pinhole ceiling tiles
103	Black multicolor terrazzo
104	12" x 12" White w/ Gray Specks Floor Tile
105	12" x 12" White w/ Gray Specks Floor Tile Mastic
106	Black chalkboards
107	12" x 12" Light Gray w/ Beige Specks Floor Tile
108	12" x 12" Light Gray w/ Beige Specks Floor Tile Mastic
109	12" x 12" Gray w/ Dark Gray Specks Floor Tile
110	12" x 12" Gray w/ Dark Gray Specks Floor Tile Mastic
12	12" x 12" White/Blue Streak Floor Tile
30	Fire doors
31	Exterior brick (Non-AHERA)
32	Exterior brick mortar (Non-AHERA)
33	Roof flashing (Non-AHERA)
34	Insulation inside vault doors
35	4" Maroon baseboard
36	4" Maroon baseboard adhesive
37	Drywall and Joint Compound
38	Drywall and Joint Compound
39	Purple carpet mastic
40	Purple carpet mastic
41	12" x 12" White Floor Tile w/ Brown, black, gray Streaks
43	Lab Counters and Sinks
44	12" x 12" Beige Floor Tile w/ Brown Streaks
46	Blue stage curtain
47	Red stage curtain
48	Floor sheeting
49	Lab tops, counters & sinks
50	Blue carpet mastic
51	Tectum panels
53	12" x 12" Gray w/Brown & White Floor Tile
54	12" x 12" Gray w/Brown & White Floor Tile Mastic
55	12" x 12" Light Gray w/ White Floor Tile
56	12" x 12" Light Gray w/ White Floor Tile Mastic
59	Caulk around sink

61	12" x 12" Brown Floor Tile
67	Caulk Around Bottom of Sink
68	Non-skid stair treads
69	4" Brown vinyl baseboard
70	4" Brown vinyl baseboard mastic
71	Spray on Fire Proofing
72	Gray carpet mastic
73	Adhesive on Wall
75	12" x 12" White w/Multi-Colored Specks Floor Tile
76	12" x 12" White w/Multi-Colored Specks Floor Tile Mastic
80	12" x 12" White Vinyl Floor Tile w/ Blue Streaks w/Mastic
81	12" x 12" Blue and Light Blue checked Vinyl Floor Tile and glue
82	12" x 12" Off-White and Brown checked Vinyl Floor Tile& and Mastic
83	12" x 12" Blue and gray checked Vinyl Floor Tile& Mastic
84	12" x 12" White w/ tan Streaks Vinyl Floor Tile & glue
85	18" x 18" Blue Gray Floor tile
85m	Mastic for HA 85
86	18" x 18"
86m	Mastic for HA 86
87	Light Blue mottle linoleum
87M	Mastic for HA 87
88	12" x 12" Tan Floor Tile w/ Brown Streaks
88M	Mastic for HA 88
89	12" x 12" Dark Blue W/lite Blue Floor Tile
89M	12" x 12" Dark Blue W/lite Blue Floor Tile Mastic
90	12" x 12" Dark Yellow W/White Floor Tile
90M	12" x 12" Dark Yellow W/White Floor Tile Mastic
91	Cardboard pipe insulation
92	Hard Joint Compound on Aircell Pipe Insulation
93	4" Blue baseboard
94	4" Blue baseboard adhesive
95	Black desk tops
96	Gray linoleum
97	Dark Yellow linoleum
98	Dark Blue linoleum
99	Gray, Dark Yellow, and Dark Blue Linoleum Mastic
HA-100	Aircell pipe insulation debris
HA-101	White woven copper Wire Insulation

The following areas were deemed to be inaccessible:

04M	12" x 12" Light Tan Replacement Floor Tile Mastic
102	2 x 2 Pinhole ceiling tiles
28M	12" x 12" Tan Floor Tile w/Streaks Mastic
30	Fire doors
36	4" Maroon baseboard adhesive
42	12" x 12" White Floor Tile w/ Brown, black, gray Streaks Mastic
45	12" x 12" Beige Floor Tile w/Brown Streaks Mastic
50	Blue carpet mastic
52	Adhesive beneath tectum panels
62	12" x 12" Brown Floor Tile Mastic
71	Spray on Fire Proofing
72	Gray carpet mastic
85m	Mastic for HA 85
86m	Mastic for HA 86
89M	12" x 12" Dark Blue W/lite Blue Floor Tile Mastic
90M	12" x 12" Dark Yellow W/White Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Farragut Academy Building 1300 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18	1' x 1' Acoustical Ceiling Tile Mastic			Electronic Shop	NO_ACBM	MISC								
19	TSI Cover on Pipe Fittings			Basement	NO_ACBM	MISC								
20	TSI Insulation on Pipe Fittings			Basement	NO_ACBM	TSI								
21	TSI on Large Pipe Elbows (>4" diameter) and Cover			Basement	NO_ACBM	TSI								
22	TSI on Large Pipe(>4" diameter) Plaster Insulation			Basement	NO_ACBM	TSI								
24	Tsi valves insulation cover			Basement	NO_ACBM	TSI								
25	.5" Pipe tsi elbow insulation & cover			Basement	NO_ACBM	TSI								
26	2' x 4' Ceiling Panels			Hanging in Basement Corridor	NO_ACBM	MISC								
27	Veneer plaster			On Metal in Men's Room in Basement	NO_ACBM	SURFACE								
28	12" x 12" Tan Floor Tile w/Streaks	20,525	SF	2nd & 3rd Floor Corridors, Band (102), Drama Office, 112, 113, 114, 317, 401, 437, 439, 440, 446, 450, 451, 400 closet, 337	CHR	MISC	N	LOC	4	SF	No	ACBM with potential for significant damage	5	LOW
28M	12" x 12" Tan Floor Tile w/Streaks Mastic	20,525	SF	2nd&3rd Flr Corridors,Band (102),Drama Of., 112,113,114,317,40 1,437,439,440,446,4 50, 400 closet, 337	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
29	Carpet mastic			3rd Floor Library	NO_ACBM	MISC								
30	Fire doors	500	SF	Basement Mechanical Rooms	ASSUMED	TSI	N	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
31	Exterior brick (Non-AHERA)				ASSUMED	MISC								
32	Exterior brick mortar (Non-AHERA)				ASSUMED	MISC								
33	Roof flashing (Non-AHERA)				ASSUMED	MISC								
34	Insulation inside vault doors		SF	Second, Third, & Fourth Floor Corridor	ASSUMED	MISC				SF				
35	4" Maroon baseboard	700	LF	North Building Corridors	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
36	4" Maroon baseboard adhesive	700	LF	North Building Corridors	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
37	Drywall and Joint Compound	1,500	SF	North Building	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
38	Drywall and Joint Compound	600	SF	South Building	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
39	Purple carpet mastic			402-405, 408-427, 429-436, 441-445, 448, 300-304, 307, 310, 312, 314, 316, 318-322, 324, 326	ASSUMED	MISC								
40	Purple carpet mastic	1,200	SF	270, Counselor, Office, Attendance	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
41	12" x 12" White Floor Tile w/ Brown, black, gray Streaks	6,000	SF	South & north Building Corridors, Room 443, 472, 474, 474A, 474B, 474D, 449	ASSUMED	MISC	N	DIST	1,010	SF	Yes	ACBM with potential for significant damage	3	LOW
42	12" x 12" White Floor Tile w/ Brown, black, gray Streaks Mastic	3,000	SF	South & north Building Corridors, Rooms, 449, 451	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
43	Lab Counters and Sinks	200	SF	South Building Science Rooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
44	12" x 12" Beige Floor Tile w/ Brown Streaks	2,000	SF	ROTC Basement Classroom, 265, counseling office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
45	12" x 12" Beige Floor Tile w/Brown Streaks Mastic	2,000	SF	ROTC Basement Classroom (In Building Suspension room), 265, counseling office	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
46	Blue stage curtain	6,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
47	Red stage curtain	10,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
48	Floor sheeting	1,000	SF	464	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	Lab tops, counters & sinks	200	SF	Room 464	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
50	Blue carpet mastic	700	SF	374, 270, 268	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
51	Tectum panels		SF	ROTC Rifle Range	ASSUMED	MISC				SF				
52	Adhesive beneath tectum panels	10,000	SF	Auditorium, 113, 114, 101, 102	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
53	12" x 12" Gray w/Brown & White Floor Tile			Room 103	ASSUMED	MISC								
54	12" x 12" Gray w/Brown & White Floor Tile Mastic			Room 103	ASSUMED	MISC								
55	12" x 12" Light Gray w/ White Floor Tile		SF	Room 101	ASSUMED	MISC				SF				
56	12" x 12" Light Gray w/ White Floor Tile		SF	Room 101	ASSUMED	MISC				SF				

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic													
57	2" Black baseboard			Room 101	NO_ACBM	MISC								
58	2" Black baseboard mastic			Room 101	NO_ACBM	MISC								
59	Caulk around sink	3	LF	Room 172	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
60	Exterior door caulk - Non-AHERA			Room 172	NO_ACBM	MISC								
61	12" x 12" Brown Floor Tile	607	SF	Basement Corridor	ASSUMED	MISC	N	DIST	4	SF	No	ACBM with potential for significant damage	3	LOW
62	12" x 12" Brown Floor Tile Mastic	1,000	SF	Basement Corridor, Break Room, 3 basement locker rooms, Auditorium dressing rooms, auditorium entran	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
63	2Nd floor roof field - (Non-AHERA)			Second Floor Roof off ROTC Office	NO_ACBM	MISC								
64	Roof flashing - (Non-AHERA)			2nd Floor Roof off ROTC Office	CHR	MISC								
65	Beige Caulk on Metal - (Non-AHERA)			2nd Floor Roof off ROTC Office	CHR	MISC								
66	Black metal sealant - (Non-AHERA)			2nd Floor Roof off ROTC Office	CHR	MISC								
67	Caulk Around Bottom of Sink	4	SF	Room 103	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
68	Non-skid stair treads			Room 113	ASSUMED	MISC								
69	4" Brown vinyl baseboard		LF	Room 113	ASSUMED	MISC				LF				
70	4" Brown vinyl baseboard mastic		LF	Room 113	ASSUMED	MISC				LF				
71	Spray on Fire Proofing	10,000	SF	Structural Beams and Components Throughout North Building	ASSUMED	MISC	Y	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
72	Gray carpet mastic	10,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
73	Adhesive on Wall	60	SF	Storage across from 172	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
74	Exterior door caulk - (Non-AHERA)			South Building	CHR	MISC								
75	12" x 12" White w/Multi-Colored Specks Floor Tile		SF	Room 463	ASSUMED	MISC				SF				
76	12" x 12" White w/Multi-Colored Specks Floor Tile Mastic		SF	Room 463	ASSUMED	MISC				SF				
80	12" x 12" White Vinyl Floor Tile w/ Blue Streaks w/Mastic	20,000	SF	Classrooms throughout on 3rd and 4th floor north building. Teachers	ASSUMED	MISC	N	DIST	6	SF	No	ACBM with potential for significant damage	5	LOW

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				lounge, Copy Room 175,200, 202, Faculty Center faculty dining room.										
81	12" x 12" Blue and Light Blue checked Vinyl Floor Tile and glue	1,000	SF	272, 161	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
82	12" x 12" Off-White and Brown checked Vinyl Floor Tile& and Mastic	500	SF	167	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
83	12" x 12" Blue and gray checked Vinyl Floor Tile& Mastic	2,000	SF	163 -165, 160	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
84	12" x 12" White w/ tan Streaks Vinyl Floor Tile & glue	5,000	SF	P.E. Office 130A, 130B,474C, 372, 365, 461, 463, 462 465	ASSUMED	MISC	N	DIST	55	SF	Yes	ACBM with potential for significant damage	3	LOW
85	18" x 18" Blue Gray Floor tile	2,850	SF	2nd floor lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
85m	Mastic for HA 85	2,850	SF	2nd floor lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
86	18" x 18"	2,850	SF	3rd Floor Lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
86m	Mastic for HA 86	2,850	SF	Third floor lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
87	Light Blue mottle lineloum		SF	Room 464	ASSUMED	MISC				SF				
87M	Mastic for HA 87		SF	Room 464	ASSUMED	MISC				SF				
88	12" x 12" Tan Floor Tile w/ Brown Streaks			Room 374	ASSUMED	MISC								
88M	Mastic for HA 88			Rom 374	ASSUMED	MISC								
89	12" x 12" Dark Blue W/lite Blue Floor Tile	105	SF	1st, 2nd, and 3rd floor in Hallway as a Pattern	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
89M	12" x 12" Dark Blue W/lite Blue Floor Tile Mastic	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
90	12" x 12" Dark Yellow W/White Floor Tile	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
90M	12" x 12" Dark Yellow W/White Floor Tile Mastic	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
91	Cardboard pipe insulation	100	LF	Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces	ASSUMED	TSI	Y	NONE	0	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
92	Hard Joint Compound on Aircell Pipe Insulation	60	SF	Basement Corridors, Work Rooms,	ASSUMED	TSI	Y	NONE	0	SF	Yes	Damaged or significantly damaged		MODERATE

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 7/12/2022
Inspector Name Benyamen Maradkel
100-20411 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
03	
03M	
04	
04M	
05	
05M	
06	Not observed 2022
06M	Not observed 2022
07	
08	Not observed 2022
08M	Not observed 2022
09	
09M	
10	
100	
101	
102	
103	
104	Damage in outside 3rd floor lunchroom hallway
105	Damage in outside 3rd floor lunchroom hallway
106	
107	

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
108	
109	Damage in main office
11	
110	Damage in main office
12	Not observed 2022
12M	Not observed 2022
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
24	
25	
26	
27	
28	Damaged in Room 439, removed from 308
28M	Removed from 308
29	
30	
31	
32	
33	
34	Not observed 2022
35	

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
36	
37	
38	
39	Not observed 2022
40	Not observed in main office - 2022
41	Damage in hallway near 3rd flr lunchroom
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	Not observed 2022
52	
53	Not observed 2022
54	Not observed 2022
55	Not observed 2022
56	Not observed 2022
57	
58	
59	
60	
61	Damage in basement hallway
62	
63	
64	

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
65	
66	
67	
68	Not observed 2022
69	Not observed 2022
70	Not observed 2022
71	
72	
73	
74	
75	Not observed 2022
76	Not observed 2022
80	Damage in room 407,336, abated from 344-346
81	
82	
83	Buckling
84	Damage is located in Room 130A, and 130B, 462, 465, and 4th & 2nd floor corridors, 365
85	
85m	
86	
86m	
87	Not observed 2022
87M	Not observed 2022
88	Not observed 2022
88M	Not observed 2022
89	
89M	
90	

Chicago Public Schools

School Farragut Academy Unit 53091 Building ID 1300

Address 2345 S. Christiana Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
90M	
91	
92	
93	
94	
95	
96	
97	
98	
99	
HA-100	Not observed 2022
HA-101	Not observed 2022

Table II

Management Planner's Review

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
 Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Carpet mastic			Rooms 470 & 472	No ACBM	MISC					
02	2' x 4' Fissured Ceiling Tile			Throughout Building	No ACBM	MISC					
03	12" x 12" Light Tan Floor Tile - ABATED			3rd & 4th Floor Corridors, Rooms 338,340,372,374,438,447,449,461,462,462A,465, Freight Elevator.	Abated	MISC					
03M	12" x 12" Light Tan Floor Tile Mastic - ABATED			3rd & 4th Floor Corridors, Rooms 338,340,372,438,447,449,461,462,462 A,465, Freight Elevator	Abated	MISC					
04	12" x 12" Light Tan Replacement Floor Tile	20	SF	3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04M	12" x 12" Light Tan Replacement Floor Tile Mastic	20	SF	3rd Floor Hallway	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Black baseboard			Throughout Building	No ACBM	MISC					
05M	Black baseboard mastic			Throughout Building	No ACBM	MISC					
06	12" x 12" Tan Floor Tile		SF	First Floor North Corridor of South Building	Chrysotile	MISC			SF		Follow O&M Plan
06M	12" x 12" Tan Floor Tile Mastic		SF	First Floor North Corridor of South Building	Chrysotile	MISC			SF		Follow O&M Plan
07	Plaster walls (veneer) & ceilings			All Floors & ceilings in South Building	No ACBM	SURFACE					
08	12" x 12" Olive Green Floor Tile		SF	First Floor Corridor as Replacement Tiles	Assumed	MISC			SF		Follow O&M Plan
08M	12" x 12" Olive Green Floor Tile Mastic		SF	First Floor Corridor as Replacement Tiles	Chrysotile	MISC			SF		Follow O&M Plan
09	12" x 12" Gray Floor Tile - REMOVED			In Corridors of South Building	Abated	MISC					
09M	12" x 12" Gray Floor Tile Mastic - ABATED			In Corridors of South Building	Abated	MISC					
10	Carpet			Main Office, 350 closet	No ACBM	MISC					
100	4" Gray baseboard	400	SF	Room 400, 402, 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	4" Gray baseboard adhesive	400	SF	Room 400, 402, 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	2 x 2 Pinhole ceiling tiles	500	SF	Room 400	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Black multicolor terrazzo	25,000	SF	border of corridors in South building, 2nd floor Rotc gym hallway, stairwells in South building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" White w/ Gray Specks Floor Tile	50,000	SF	Throughout South building corridors and classrooms	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Repair
105	12" x 12" White w/ Gray Specks Floor Tile Mastic	50,000	SF	Throughout South building corridors and classrooms	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Repair
106	Black chalkboards	30,000	SF	throughout north & South building classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
107	12" x 12" Light Gray w/ Beige Specks Floor Tile	550	SF	Room 464	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Light Gray w/ Beige Specks Floor Tile Mastic	550	SF	Room 464	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12" x 12" Gray w/ Dark Gray Specks Floor Tile	600	SF	Main office	Assumed	MISC	No	15	SF	5 ACBM with potential for significant damage	Repair
11	Carpet mastic			Office, 350 closet	No ACBM	MISC					
110	12" x 12" Gray w/ Dark Gray Specks Floor Tile Mastic	600	SF	Main office	Assumed	MISC	No	15	SF	5 ACBM with potential for significant damage	Repair
12	12" x 12" White/Blue Streak Floor Tile		SF	175	Assumed	MISC			SF		Follow O&M Plan
12M	12" x 12" White/Blue Streaks Floor Tile Mastic		SF	175	Chrysotile	MISC			SF		Follow O&M Plan
13	Interlocking wall tiles			Rooms 173, 175 & 176	No ACBM	SURFACE					
14	2' x 4' Woven Ceiling Tile			1st Floor Corridor in South Building	No ACBM	MISC					
15	Veneer plaster walls			South Building lower Level, US ARoomy/ROTC Office and Stairwell	No ACBM	SURFACE					
16	Veneer plaster			Corridors and Classrooms	No ACBM	SURFACE					
17	1' x 1' Acoustical Ceiling Tile			South Building, Electronic Shop	No ACBM	MISC					
18	1' x 1' Acoustical Ceiling Tile Mastic			Electronic Shop	No ACBM	MISC					
19	TSI Cover on Pipe Fittings			Basement	No ACBM	MISC					
20	TSI Insulation on Pipe Fittings			Basement	No ACBM	TSI					
21	TSI on Large Pipe Elbows (>4" diameter) and Cover			Basement	No ACBM	TSI					
22	TSI on Large Pipe(>4" diameter) Plaster Insulation			Basement	No ACBM	TSI					
24	Tsi valves insulation cover			Basement	No ACBM	TSI					
25	.5" Pipe tsi elbow insulation & cover			Basement	No ACBM	TSI					
26	2' x 4' Ceiling Panels			Hanging in Basement Corridor	No ACBM	MISC					
27	Veneer plaster			On Metal in Men's Room in Basement	No ACBM	SURFACE					
28	12" x 12" Tan Floor Tile w/Streaks	20,525	SF	2nd & 3rd Floor Corridors, Band (102), Drama Office, 112, 113, 114, 317, 401, 437, 439, 440, 446, 450, 451, 400 closet, 337	Chrysotile	MISC	No	4	SF	5 ACBM with potential for significant damage	Repair
28M	12" x 12" Tan Floor Tile w/Streaks Mastic	20,525	SF	2nd&3rd Fir Corridors,Band (102), Drama Of., 112,113,114,317,401,437,439,440,446, 450, 400 closet, 337	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Carpet mastic			3rd Floor Library	No ACBM	MISC					
30	Fire doors	500	SF	Basement Mechanical Rooms	Assumed	TSI	No	0	SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
 Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										suspect ACBM	
31	Exterior brick (Non-AHERA)				Assumed	MISC					Follow O&M Plan
32	Exterior brick mortar (Non-AHERA)				Assumed	MISC					Follow O&M Plan
33	Roof flashing (Non-AHERA)				Assumed	MISC					Follow O&M Plan
34	Insulation inside vault doors		SF	Second, Third, & Fourth Floor Corridor	Assumed	MISC			SF		Follow O&M Plan
35	4" Maroon baseboard	700	LF	North Building Corridors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
36	4" Maroon baseboard adhesive	700	LF	North Building Corridors	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
37	Drywall and Joint Compound	1,500	SF	North Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Drywall and Joint Compound	600	SF	South Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Purple carpet mastic			402-405, 408-427, 429-436, 441-445, 448, 300-304, 307, 310, 312, 314, 316, 318-322, 324, 326	Assumed	MISC					Follow O&M Plan
40	Purple carpet mastic	1,200	SF	270, Counselor, Office, Attendance	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" x 12" White Floor Tile w/ Brown, black, gray Streaks	6,000	SF	South & north Building Corridors, Room 443, 472, 474, 474A, 474B, 474D, 449	Assumed	MISC	No	1,010	SF	5 ACBM with potential for significant damage	Repair
42	12" x 12" White Floor Tile w/ Brown, black, gray Streaks Mastic	3,000	SF	South & north Building Corridors, Rooms, 449, 451	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Lab Counters and Sinks	200	SF	South Building Science Rooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" x 12" Beige Floor Tile w/ Brown Streaks	2,000	SF	ROTC Basement Classroom, 265, counseling office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12" x 12" Beige Floor Tile w/Brown Streaks Mastic	2,000	SF	ROTC Basement Classroom (In Building Suspension room), 265, counseling office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Blue stage curtain	6,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Red stage curtain	10,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Floor sheeting	1,000	SF	464	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Lab tops, counters & sinks	200	SF	Room 464	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Blue carpet mastic	700	SF	374, 270, 268	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Tectum panels		SF	ROTC Rifle Range	Assumed	MISC			SF		Follow O&M Plan
52	Adhesive beneath tectum panels	10,000	SF	Auditorium, 113, 114, 101, 102	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Gray w/Brown & White Floor Tile			Room 103	Assumed	MISC					Follow O&M Plan
54	12" x 12" Gray w/Brown & White Floor Tile Mastic			Room 103	Assumed	MISC					Follow O&M Plan
55	12" x 12" Light Gray w/ White Floor Tile		SF	Room 101	Assumed	MISC			SF		Follow O&M Plan
56	12" x 12" Light Gray w/ White Floor Tile Mastic		SF	Room 101	Assumed	MISC			SF		Follow O&M Plan
57	2" Black baseboard			Room 101	No ACBM	MISC					

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
 Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
58	2" Black baseboard mastic			Room 101	No ACBM	MISC					
59	Caulk around sink	3	LF	Room 172	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
60	Exterior door caulk - Non-AHERA			Room 172	No ACBM	MISC					
61	12" x 12" Brown Floor Tile	607	SF	Basement Corridor	Assumed	MISC	No	4	SF	5 ACBM with potential for significant damage	Repair
62	12" x 12" Brown Floor Tile Mastic	1,000	SF	Basement Corridor, Break Room, 3 basement locker rooms, Auditorium dressing rooms, auditorium entran	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	2Nd floor roof field - (Non-AHERA)			Second Floor Roof off ROTC Office	No ACBM	MISC					
64	Roof flashing - (Non-AHERA)			2nd Floor Roof off ROTC Office	Chrysotile	MISC					Follow O&M Plan
65	Beige Caulk on Metal - (Non-AHERA)			2nd Floor Roof off ROTC Office	Chrysotile	MISC					Follow O&M Plan
66	Black metal sealant - (Non-AHERA)			2nd Floor Roof off ROTC Office	Chrysotile	MISC					Follow O&M Plan
67	Caulk Around Bottom of Sink	4	SF	Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Non-skid stair treads			Room 113	Assumed	MISC					Follow O&M Plan
69	4" Brown vinyl baseboard		LF	Room 113	Assumed	MISC			LF		Follow O&M Plan
70	4" Brown vinyl baseboard mastic		LF	Room 113	Assumed	MISC			LF		Follow O&M Plan
71	Spray on Fire Proofing	10,000	SF	Structural Beams and Components Throughout North Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Gray carpet mastic	10,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Adhesive on Wall	60	SF	Storage across from 172	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Exterior door caulk - (Non-AHERA)			South Building	Chrysotile	MISC					Follow O&M Plan
75	12" x 12" White w/Multi-Colored Specks Floor Tile		SF	Room 463	Assumed	MISC			SF		Follow O&M Plan
76	12" x 12" White w/Multi-Colored Specks Floor Tile Mastic		SF	Room 463	Assumed	MISC			SF		Follow O&M Plan
80	12" x 12" White Vinyl Floor Tile w/ Blue Streaks w/Mastic	20,000	SF	Classrooms throughout on 3rd and 4th floor north building. Teachers lounge, Copy Room 175,200, 202, Faculty Center faculty dining room.	Assumed	MISC	No	6	SF	5 ACBM with potential for significant damage	Repair
81	12" x 12" Blue and Light Blue checked Vinyl Floor Tile and glue	1,000	SF	272, 161	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12" x 12" Off-White and Brown checked Vinyl Floor Tile& and Mastic	500	SF	167	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Blue and gray checked Vinyl Floor Tile& Mastic	2,000	SF	163 -165, 160	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" White w/ tan Streaks Vinyl Floor Tile & glue	5,000	SF	P.E. Office 130A, 130B,474C, 372, 365, 461, 463, 462 465	Assumed	MISC	No	55	SF	5 ACBM with potential for significant damage	Repair

Chicago Public Schools

School Farragut Academy

Unit 53091

Building ID 1300

Address 2345 S. Christiana

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
85	18" x 18" Blue Gray Floor tile	2,850	SF	2nd floor lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85m	Mastic for HA 85	2,850	SF	2nd floor lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	18" x 18"	2,850	SF	3rd Floor Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86m	Mastic for HA 86	2,850	SF	Third floor lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Light Blue mottle lineloum		SF	Room 464	Assumed	MISC			SF		Follow O&M Plan
87M	Mastic for HA 87		SF	Room 464	Assumed	MISC			SF		Follow O&M Plan
88	12" x 12" Tan Floor Tile w/ Brown Streaks			Room 374	Assumed	MISC					Follow O&M Plan
88M	Mastic for HA 88			Rom 374	Assumed	MISC					Follow O&M Plan
89	12" x 12" Dark Blue W/lite Blue Floor Tile	105	SF	1st, 2nd, and 3rd floor in Hallway as a Pattern	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89M	12" x 12" Dark Blue W/lite Blue Floor Tile Mastic	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Dark Yellow W/White Floor Tile	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90M	12" x 12" Dark Yellow W/White Floor Tile Mastic	105	SF	1st, 2nd, and 3rd floor in Hallway as a pattern	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	Cardboard pipe insulation	100	LF	Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces	Assumed	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
92	Hard Joint Compound on Aircell Pipe Insulation	60	SF	Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces	Assumed	TSI	Yes	0	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
93	4" Blue baseboard	500	SF	Classrooms throughout 4th floor, 3rd floor north building corridors	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
94	4" Blue baseboard adhesive	500	SF	Classrooms throughout 4th floor, 3rd floor north building corridors	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
95	Black desk tops	400	SF	451, 400, 402, 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	Gray linoleum	1,000	SF	Room 400, 402, 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Dark Yellow linoleum	50	SF	Room 400, 402, 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Dark Blue linoleum	25	SF	Room 400, 402, 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Gray, Dark Yellow, and Dark Blue Linoleum Mastic	1,075	SF	Room 400, 402, 408	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
HA-100	Aircell pipe insulation debris			Unexcavated spaces beneath the basement	Assumed	TSI					Follow O&M Plan
HA-101	White woven copper Wire Insulation			Old stage light fixtures in Auditorium	Assumed	TSI					Follow O&M Plan

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
 Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	7/14/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
03M	
04	
04M	
05	

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
05M	
06	
06M	
07	
08	
08M	
09	
09M	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	
12	
12M	
13	
14	
15	
16	

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
17	
18	
19	
20	
21	
22	
24	
25	
26	
27	
28	
28M	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
 Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
71	
72	
73	
74	
75	
76	
80	
81	
82	
83	
84	
85	
85m	
86	
86m	
87	
87M	
88	
88M	
89	
89M	
90	
90M	
91	
92	
93	
94	

Chicago Public Schools

School Farragut Academy
Address 2345 S. Christiana

Unit 53091
Chicago, IL, 60623

Building ID 1300
Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
95	
96	
97	
98	
99	
HA-100	
HA-101	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 470 & 472**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Carpet mastic**

MATERIAL LOCATION: **Rooms 470 & 472**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **02**
MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd & 4th Floor Corridors, Rooms 338,340,372,374,438,447,449,461,462,462A,465, Freight Elevator,**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile - ABATED**

MATERIAL LOCATION: **3rd & 4th Floor Corridors, Rooms 338,340,372,374,438,447,449,461,462,462A,465, Freight Elevator,**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03M**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd & 4th Floor Corridors, Rooms 338,340,372,438,447,449,461,462,462A,465,Freight Elevator**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: 

Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **03M**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile Mastic - ABATED**
MATERIAL LOCATION: **3rd & 4th Floor Corridors, Rooms 338,340,372,438,447,449,461,462,462A,465,Freight Elevator**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **12" x12" Light Tan Replacement Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Corridor**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **12" x12" Light Tan Replacement Floor Tile**

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04M**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Replacement Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Hallway**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **04M**
MATERIAL DESCRIPTION: **12" x 12" Light Tan Replacement Floor Tile Mastic**
MATERIAL LOCATION: **3rd Floor Hallway**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**
MATERIAL DESCRIPTION: **Black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Black baseboard**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05M**
MATERIAL DESCRIPTION: **Black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **05M**

MATERIAL DESCRIPTION: **Black baseboard mastic**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor North Corridor of South Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **First Floor North Corridor of South Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06M**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor North Corridor of South Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **06M**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**
MATERIAL LOCATION: **First Floor North Corridor of South Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **07**
MATERIAL DESCRIPTION: **Plaster walls (veneer) & ceilings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:
DISTURBANCE POTENTIAL:
MATERIAL LOCATION: **All Floors & ceilings in South Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:
COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Plaster walls (vener) & ceilings**

MATERIAL LOCATION: **All Floors & ceilings in South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**
MATERIAL DESCRIPTION: **12" x 12" Olive Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor Corridor as Replacement Tiles**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12" x 12" Olive Green Floor Tile**

MATERIAL LOCATION: **First Floor Corridor as Replacement Tiles**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08M**
MATERIAL DESCRIPTION: **12" x 12" Olive Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **First Floor Corridor as Replacement Tiles**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **08M**
MATERIAL DESCRIPTION: **12" x 12" Olive Green Floor Tile Mastic**
MATERIAL LOCATION: **First Floor Corridor as Replacement Tiles**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile - REMOVED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **In Corridors of South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile - REMOVED**

MATERIAL LOCATION: **In Corridors of South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09M**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic - ABATED**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **In Corridors of South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **09M**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **In Corridors of South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **Carpet**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, 350 closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Carpet**

MATERIAL LOCATION: **Main Office, 350 closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office, 350 closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Carpet mastic**

MATERIAL LOCATION: **Office, 350 closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **12" x 12" White/Blue Streak Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **175**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" White/Blue Streak Floor Tile**

MATERIAL LOCATION: **175**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12M**
MATERIAL DESCRIPTION: **12" x 12" White/Blue Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **175**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **12M**

MATERIAL DESCRIPTION: **12" x 12" White/Blue Streaks Floor Tile Mastic**

MATERIAL LOCATION: **175**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Interlocking wall tiles**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 173, 175 & 176**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Interlocking wall tiles**

MATERIAL LOCATION: **Rooms 173, 175 & 176**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **2' x 4' Woven Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor in South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **2' x 4' Woven Ceiling Tile**

MATERIAL LOCATION: **1st Floor Corridor in South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Veneer plaster walls**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Building lower Level, US ARoomy/ROTC Office and Stairwell**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Veneer plaster walls**
MATERIAL LOCATION: **South Building lower Level, US ARoomy/ROTC Office and Stairwell**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Veneer plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridors and Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Veneer plaster**

MATERIAL LOCATION: **Corridors and Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Building, Electronic Shop**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**

MATERIAL LOCATION: **South Building, Electronic Shop**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Electronic Shop**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile Mastic**

MATERIAL LOCATION: **Electronic Shop**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **TSI Cover on Pipe Fittings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **TSI Cover on Pipe Fittings**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **TSI Insulation on Pipe Fittings**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **TSI Insulation on Pipe Fittings**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **TSI on Large Pipe Elbows (>4" diameter) and Cover**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **TSI on Large Pipe Elbows (>4" diameter) and Cover**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**
MATERIAL DESCRIPTION: **TSI on Large Pipe(>4" diameter) Plaster Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **TSI on Large Pipe(>4" diameter) Plaster Insulation**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **Tsi valves insulation cover**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Tsi valves insulation cover**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **.5" Pipe tsi elbow insulation & cover**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **.5" Pipe tsi elbow insulation & cover**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hanging in Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **Hanging in Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Veneer plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **On Metal in Men's Room in Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Veneer plaster**

MATERIAL LOCATION: **On Metal in Men's Room in Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage
Deterioration**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors, Band (102), Drama Office, 112, 113, 114, 317, 401, 437, 439, 440, 446, 450, 451, 400 closet, 337**
MATERIAL QUANTITY: **20525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damaged in Room 439, removed from 308**

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **28**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/Streaks**
MATERIAL LOCATION: **2nd & 3rd Floor Corridors, Band (102), Drama Office, 112, 113, 114, 317, 401, 437, 439, 440, 446, 450, 451, 400 closet, 337**
MATERIAL QUANTITY: **20525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd&3rd Fir Corridors,Band (102),Drama Of.,112,113,114,317,401,437,439,440,446,450, 400 closet, 337**

MATERIAL QUANTITY: **20525**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Removed from 308**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **28M**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/Streaks Mastic**
MATERIAL LOCATION: **2nd&3rd Flr Corridors,Band (102),Drama Of.,112,113,114,317,401,437,439,440,446,450, 400 closet, 337**
MATERIAL QUANTITY: **20525** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Carpet mastic**

MATERIAL LOCATION: **3rd Floor Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Mechanical Rooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Fire doors**
MATERIAL LOCATION: **Basement Mechanical Rooms**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**
MATERIAL DESCRIPTION: **Exterior brick (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Exterior brick (Non-AHERA)**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**
MATERIAL DESCRIPTION: **Exterior brick mortar (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Exterior brick mortar (Non-AHERA)**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Roof flashing (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Roof flashing (Non-AHERA)**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Insulation inside vault doors**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second, Third, & Fourth Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Insulation inside vault doors**

MATERIAL LOCATION: **Second, Third, & Fourth Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **4" Maroon baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **4" Maroon baseboard**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **4" Maroon baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **4" Maroon baseboard adhesive**
MATERIAL LOCATION: **North Building Corridors**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Drywall and Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **North Building**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **Drywall and Joint Compound**
MATERIAL LOCATION: **North Building**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Drywall and Joint Compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Drywall and Joint Compound**

MATERIAL LOCATION: **South Building**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Purple carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **402-405, 408-427, 429-436, 441-445, 448, 300-304, 307, 310, 312, 314, 316, 318-322, 324, 326**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Purple carpet mastic**

MATERIAL LOCATION: **402-405, 408-427, 429-436, 441-445, 448, 300-304, 307, 310, 312, 314, 316, 318-322, 324, 326**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Purple carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **270, Counselor, Office, Attendance**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Not observed in main office - 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **Purple carpet mastic**
MATERIAL LOCATION: **270, Counselor, Office, Attendance**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown, black, gray Streaks**
HISTORICAL AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage
Previous Repair**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage
Previous Repair**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South & north Building Corridors, Room 443, 472, 474, 474A, 474B, 474D,449**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6000** DAMAGE UNITS: **SF**
COMMENTS: **Damage in hallway near 3rd flr lunchroom**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown, black, gray Streaks**
MATERIAL LOCATION: **South & north Building Corridors, Room 443, 472, 474, 474A, 474B, 474D,449**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **1010** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown, black, gray Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South & north Building Corridors, Rooms, 449, 451**

MATERIAL QUANTITY: **3000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Brown, black, gray Streaks Mastic**
MATERIAL LOCATION: **South & north Building Corridors, Rooms, 449, 451**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **Lab Counters and Sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building Science Rooms**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Lab Counters and Sinks**

MATERIAL LOCATION: **South Building Science Rooms**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **ROTC Basement Classroom, 265, counseling office**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Brown Streaks**
MATERIAL LOCATION: **ROTC Basement Classroom, 265, counseling office**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown Streaks Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **ROTC Basement Classroom (In Building Suspension room), 265, counseling office**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/Brown Streaks Mastic**
MATERIAL LOCATION: **ROTC Basement Classroom (In Building Suspension room), 265, counseling office**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Blue stage curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Blue stage curtain**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Red stage curtain**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Red stage curtain**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Floor sheeting**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **464**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Floor sheeting**
MATERIAL LOCATION: **464**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **Lab tops, counters & sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 464**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Lab tops, counters & sinks**

MATERIAL LOCATION: **Room 464**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Blue carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **374, 270, 268**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Blue carpet mastic**
MATERIAL LOCATION: **374, 270, 268**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Tectum panels**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ROTC Rifle Range**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Tectum panels**

MATERIAL LOCATION: **ROTC Rifle Range**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Adhesive beneath tectum panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium, 113, 114, 101, 102**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Adhesive beneath tectum panels**
MATERIAL LOCATION: **Auditorium, 113, 114, 101, 102**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & White Floor Tile**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & White Floor Tile Mastic**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Floor Tile**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Floor Tile Mastic**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **2" Black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **2" Black baseboard**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **2" Black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **2" Black baseboard mastic**

MATERIAL LOCATION: **Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Caulk around sink**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 172**
MATERIAL QUANTITY: **3** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Caulk around sink**

MATERIAL LOCATION: **Room 172**

MATERIAL QUANTITY: **3**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Exterior door caulk - Non-AHERA**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 172**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Exterior door caulk - Non-AHERA**

MATERIAL LOCATION: **Room 172**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Basement Corridor**
MATERIAL QUANTITY: **607** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in basement hallway**

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**
MATERIAL LOCATION: **Basement Corridor**
MATERIAL QUANTITY: **607** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **4** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Corridor, Break Room, 3 basement locker rooms, Auditorium dressing rooms, auditorium entran**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**
MATERIAL LOCATION: **Basement Corridor, Break Room, 3 basement locker rooms, Auditorium dressing rooms, auditorium entran**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **2Nd floor roof field - (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Second Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **2Nd floor roof field - (Non-AHERA)**

MATERIAL LOCATION: **Second Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Roof flashing - (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Roof flashing - (Non-AHERA)**

MATERIAL LOCATION: **2nd Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Beige Caulk on Metal - (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Beige Caulk on Metal - (Non-AHERA)**

MATERIAL LOCATION: **2nd Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **Black metal sealant - (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Black metal sealant - (Non-AHERA)**

MATERIAL LOCATION: **2nd Floor Roof off ROTC Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53091 BUILDING ID: 1300
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Benyamen Maradkel
SCHOOL NAME: Farragut Academy INSPECTION DATE: 7/12/2022
ADDRESS: 2345 S. Christiana IDPH LICENSE NO: 100-20411

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 67
MATERIAL DESCRIPTION: Caulk Around Bottom of Sink
HISTORICAL AHERA DAMAGE CATEGORY 6
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE: No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 103**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Caulk Around Bottom of Sink**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **4**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **Non-skid stair treads**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Non-skid stair treads**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY:

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **4" Brown vinyl baseboard mastic**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY:

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Spray on Fire Proofing**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Structural Beams and Components Throughout North Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Spray on Fire Proofing**
MATERIAL LOCATION: **Structural Beams and Components Throughout North Building**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Gray carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Gray carpet mastic**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **Adhesive on Wall**
HISTORICAL AHERA DAMAGE CATEGORY **6**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Storage across from 172**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Adhesive on Wall**

MATERIAL LOCATION: **Storage across from 172**

MATERIAL QUANTITY: **60**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Exterior door caulk - (Non-AHERA)**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Exterior door caulk - (Non-AHERA)**

MATERIAL LOCATION: **South Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Colored Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 463**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Colored Specks Floor Tile**

MATERIAL LOCATION: **Room 463**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Colored Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 463**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12" x 12" White w/Multi-Colored Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 463**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile w/ Blue Streaks w/Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage
Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms throughout on 3rd and 4th floor north building. Teachers lounge, Copy Room 175,200, 202, Faculty Center faculty dining room.**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in room 407,336, abated from 344-346**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **80**
MATERIAL DESCRIPTION: **12" x 12" White Vinyl Floor Tile w/ Blue Streaks w/Mastic**
MATERIAL LOCATION: **Classrooms throughout on 3rd and 4th floor north building. Teachers lounge, Copy Room 175,200, 202, Faculty Center faculty dining room.**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **6** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" Blue and Light Blue checked Vinyl Floor Tile and glue**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **272, 161**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **81**
MATERIAL DESCRIPTION: **12" x 12" Blue and Light Blue checked Vinyl Floor Tile and glue**
MATERIAL LOCATION: **272, 161**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12" x 12" Off-White and Brown checked Vinyl Floor Tile& and Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **167**

MATERIAL QUANTITY: **500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **82**
MATERIAL DESCRIPTION: **12" x 12" Off-White and Brown checked Vinyl Floor Tile& and Mastic**
MATERIAL LOCATION: **167**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Blue and gray checked Vinyl Floor Tile& Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **163 -165, 160**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Buckling**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **83**
MATERIAL DESCRIPTION: **12" x 12" Blue and gray checked Vinyl Floor Tile& Mastic**
MATERIAL LOCATION: **163 -165, 160**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" White w/ tan Streaks Vinyl Floor Tile & glue**
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration
Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **P.E. Office 130A, 130B,474C, 372, 365, 461, 463, 462 465**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **5000** DAMAGE UNITS: **SF**
COMMENTS: **Damage is located in Room 130A, and 130B, 462, 465, and 4th & 2nd floor corridors, 365**

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" White w/ tan Streaks Vinyl Floor Tile & glue**
MATERIAL LOCATION: **P.E. Office 130A, 130B,474C, 372, 365, 461, 463, 462 465**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **55** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **18" x 18" Blue Gray Floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **18" x 18" Blue Gray Floor tile**
MATERIAL LOCATION: **2nd floor lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85m**
MATERIAL DESCRIPTION: **Mastic for HA 85**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **2nd floor lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **85m**
MATERIAL DESCRIPTION: **Mastic for HA 85**
MATERIAL LOCATION: **2nd floor lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **18" x 18"**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **3rd Floor Lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **18" x 18"**
MATERIAL LOCATION: **3rd Floor Lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86m**
MATERIAL DESCRIPTION: **Mastic for HA 86**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Third floor lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **86m**
MATERIAL DESCRIPTION: **Mastic for HA 86**
MATERIAL LOCATION: **Third floor lunchroom**
MATERIAL QUANTITY: **2850** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **Light Blue mottle lineloum**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 464**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Light Blue mottle lineloum**

MATERIAL LOCATION: **Room 464**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87M**
MATERIAL DESCRIPTION: **Mastic for HA 87**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 464**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **87M**

MATERIAL DESCRIPTION: **Mastic for HA 87**

MATERIAL LOCATION: **Room 464**

MATERIAL QUANTITY:

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ Brown Streaks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 374**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ Brown Streaks**

MATERIAL LOCATION: **Room 374**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88M**
MATERIAL DESCRIPTION: **Mastic for HA 88**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rom 374**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **88M**

MATERIAL DESCRIPTION: **Mastic for HA 88**

MATERIAL LOCATION: **Rom 374**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue W/lite Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a Pattern**

MATERIAL QUANTITY: **105**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue W/lite Blue Floor Tile**
MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a Pattern**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89M**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue W/lite Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a pattern**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **89M**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue W/lite Blue Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a pattern**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" Dark Yellow W/White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a pattern**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **12" x 12" Dark Yellow W/White Floor Tile**
MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a pattern**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90M**
MATERIAL DESCRIPTION: **12" x 12" Dark Yellow W/White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a pattern**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **90M**
MATERIAL DESCRIPTION: **12" x 12" Dark Yellow W/White Floor Tile Mastic**
MATERIAL LOCATION: **1st, 2nd, and 3rd floor in Hallway as a pattern**
MATERIAL QUANTITY: **105** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Cardboard pipe insulation**
MATERIAL LOCATION: **Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Hard Joint Compound on Aircell Pipe Insulation**
MATERIAL LOCATION: **Basement Corridors, Work Rooms, Storage Rooms, and Mechanical Spaces**
MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-100**
MATERIAL DESCRIPTION: **Aircell pipe insulation debris**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Unexcavated spaces beneath the basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **HA-100**

MATERIAL DESCRIPTION: **Aircell pipe insulation debris**

MATERIAL LOCATION: **Unexcavated spaces beneath the basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HA-101**
MATERIAL DESCRIPTION: **White woven copper Wire Insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Old stage light fixtures in Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUIDLING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **HA-101**

MATERIAL DESCRIPTION: **White woven copper Wire Insulation**

MATERIAL LOCATION: **Old stage light fixtures in Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **4" Gray baseboard adhesive**

MATERIAL LOCATION: **Room 400, 402, 408**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **4" Gray baseboard adhesive**

MATERIAL LOCATION: **Room 400, 402, 408**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Dark Yellow linoleum**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **97**
MATERIAL DESCRIPTION: **Dark Yellow linoleum**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **108**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Beige Specks Floor Tile Mastic**
MATERIAL LOCATION: **Room 464**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Beige Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 464**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Black desk tops**
MATERIAL LOCATION: **451, 400, 402, 408**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **95**
MATERIAL DESCRIPTION: **Black desk tops**
MATERIAL LOCATION: **451, 400, 402, 408**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **102**
MATERIAL DESCRIPTION: **2 x 2 Pinhole ceiling tiles**
MATERIAL LOCATION: **Room 400**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **2 x 2 Pinhole ceiling tiles**

MATERIAL LOCATION: **Room 400**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **110**
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Main office**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **15** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:
Damage in main office

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: Chicago Public Schools UNIT NUMBER: 53091 BUIDLING ID: 1300
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Benyamen Maradkel
SCHOOL NAME: Farragut Academy INSPECTION DATE: 7/12/2022
ADDRESS: 2345 S. Christiana IDPH LICENSE NO: 100-20411

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: 93
MATERIAL DESCRIPTION: 4" Blue baseboard
MATERIAL LOCATION: Classrooms throughout 4th floor, 3rd floor north building corridors
MATERIAL QUANTITY: 500 MATERIAL UNITS: SF
MATERIAL CATEGORY: MISC FRIABLE: No
ASBESTOS TYPE: Assumed
DISTURBANCE POTENTIAL: LOW CONDITION: No Damage
AHERA DAMAGE CATEGORY: 5 ACBM with potential for significant damage
ACCESSIBILITY: Within Reach DAMAGE REASON:
DAMAGE QUANTITY: 0 DAMAGE REASON:
DAMAGE UNITS: SF
COMMENTS:

Inspector's Signature:



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **93**
MATERIAL DESCRIPTION: **4" Blue baseboard**
MATERIAL LOCATION: **Classrooms throughout 4th floor, 3rd floor north building corridors**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **Gray, Dark Yellow, and Dark Blue Linoleum Mastic**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **1075** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **99**
MATERIAL DESCRIPTION: **Gray, Dark Yellow, and Dark Blue Linoleum Mastic**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **1075** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Black multicolor terrazzo**

MATERIAL LOCATION: **border of corridors in South building, 2nd floor Rotc gym hallway, stairwells in South building**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **104**
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile**
MATERIAL LOCATION: **Throughout South building corridors and classrooms**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **10** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
Damage in outside 3rd floor lunchroom hallway

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile**

MATERIAL LOCATION: **Throughout South building corridors and classrooms**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Throughout South building corridors and classrooms**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **10** DAMAGE REASON:
DAMAGE UNITS: **SF**

COMMENTS:
Damage in outside 3rd floor lunchroom hallway

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **105**
MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile Mastic**
MATERIAL LOCATION: **Throughout South building corridors and classrooms**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Specks Floor Tile**

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**

AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

COMMENTS:
Damage in main office

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Specks Floor Tile**

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **4" Blue baseboard adhesive**
MATERIAL LOCATION: **Classrooms throughout 4th floor, 3rd floor north building corridors**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **94**
MATERIAL DESCRIPTION: **4" Blue baseboard adhesive**
MATERIAL LOCATION: **Classrooms throughout 4th floor, 3rd floor north building corridors**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 07/14/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **Gray linoleum**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **07/12/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **96**
MATERIAL DESCRIPTION: **Gray linoleum**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **4" Gray baseboard**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **100**
MATERIAL DESCRIPTION: **4" Gray baseboard**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Black chalkboards**
MATERIAL LOCATION: **throughout north & South building classrooms**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **106**
MATERIAL DESCRIPTION: **Black chalkboards**
MATERIAL LOCATION: **throughout north & South building classrooms**
MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **107**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Beige Specks Floor Tile**
MATERIAL LOCATION: **Room 464**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Beige Specks Floor Tile**

MATERIAL LOCATION: **Room 464**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**
SCHOOL NAME: **Farragut Academy** INSPECTION DATE: **7/12/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Dark Blue linoleum**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 07/12/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53091** BUILDING ID: **1300**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Farragut Academy** REVIEW DATE: **7/14/2022**
ADDRESS: **2345 S. Christiana** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **98**
MATERIAL DESCRIPTION: **Dark Blue linoleum**
MATERIAL LOCATION: **Room 400, 402, 408**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **07/14/2022**

APPENDIX B

Inspector and Management Planner Licenses

Benyamen Maradkel

Illinois Licensed Building Inspector



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 20411

ISSUED
3/17/2022

EXPIRES
05/15/2023

BENYAMEN C MARADKEL
706 W HACKBERRY DR
ARLINGTON HEIGHTS, IL 6000
Environmental Health



ENDORSEMENTS

INSPECTOR

EXPIRES

5/9/2023

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Benyamen Maradkel

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090703

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed