

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0617
SCHOOL NAME: Curie Metro High School
ADDRESS OF SCHOOL: 4959 S. Archer
CITY: Chicago, IL, 60632

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/7/2019**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 9/20/2022 ENROLLMENT 2835
IDPH INSPECTOR LICENSE NUMBER: 100-20129
IDPH LICENSED INSPECTOR NAME (Please Print): Joshua Karlson
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



9/30/2022

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Curie Metro High School

4959 S. Archer
Chicago, IL, 60632

Unit: 53101
Building ID: 1820

IDPH ID Number: 14-016-2990-0617

REPORT DATE:

Friday, September 30, 2022

Prepared for:

Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

09/30/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 53101 Region: 04 IDPH ID: 14-016-2990-0617

School: Curie Metro High School Building ID: 1820

Address: 4959 S. Archer

Chicago, IL, 60632

Building Contact: Frank, Dominic

Contact Phone: 7734567346

Current Building Owners: Chicago Public Schools

Reinspection Date: 9/20/2022

Review Date: 09/30/2022

Inspector: Joshua Karlson

Inspector IDPH License: 100-20129

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: September 30, 2022

RE: Curie Metro High School, Unit 53101
4959 S. Archer
Chicago, IL, 60632

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Curie Metro High School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Curie Metro High School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Curie Metro High School Unit: 53101 Region: 04
Address: 4959 S. Archer Chicago, IL, 60632
IDPH ID: 14-016-2990-0617 Building ID: 1820
Contact: Frank, Dominic Phone: 7734567346

2. Description of Facility

Original Construction: 1973 Additional Construction:
Total Square Footage: 245084 No of Floors: 3
Current Occupancy: 2835

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602


4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Joshua Karlson


Inspector IDPH license # 100-20129
Reinspection Date: 9/20/2022


Signature:
Date: 9/20/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466



Signature:
Date: 09/30/2022

7. Review Date: 09/30/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 9/30/2022

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Curie Metro High School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1820:

11	Duct work tape
15	Inner duct insulation
16	Spray-on fire proofing
19	Fire doors
27	Dry wall
28A	Drywall joint compound
2B	2' x 4' Ceiling
31A	Interior casing caulk
7	Plaster

70	Vault door insulation
72	2' x 2' Ceiling Tile w/ Pinholes
73	12" x 12" Light Gray w/ Gray and White Streak Floor Tile
74	Mastic assoc. W/12" x 12" Light Gray w/ Gray and White Streak Floor Tile
75	Tongue and Groove Wood Flooring
76	12" x 12" Tan w/ Brown and White Streak Floor Tile
77	Mastic assoc. W/ 12" x 12" Tan w/ Brown and White Streak Floor Tile
78	12" x 12" Brown Mottled Floor Tile
79	Mastic for 12" x 12" Brown Mottled Floor Tile
8	2' x 4' Insulation
80	12" x 12" Tan Mottled Floor Tile
81	Mastic assoc. W/ 12" x 12" Tan Mottled Floor Tile
82	12" x 12" White w/ Tan Speck Floor Tile
83	Mastic assoc. W/ 12" x 12" White w/ Tan Speck Floor Tile
84	12" x 12" Tan and White Mottled Floor Tile
85	Mastic Associated w/ 12" x 12" Tan and White Mottled Floor Tile
86	12" x 12" Peach Mottled Floor Tile
87	12" x 12" Dark Blue Mottled Floor Tile
88	12" x 12" Dark Red Mottled Floor Tile
89	Mastic Associated w/ 12" x 12" Peach, Dark Blue and Dark Red Mottled Floor Tile

- 90 Orange, Gray and Beige Vinyl Flooring
- 91 Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring
- 92 Transite lined cabinets

B. The following new homogenous areas have been identified for Building 1820:

72	2' x 2' Ceiling Tile w/ Pinholes
73	12" x 12" Light Gray w/ Gray and White Streak Floor Tile
74	Mastic assoc. W/12" x 12" Light Gray w/ Gray and White Streak Floor Tile
75	Tongue and Groove Wood Flooring
76	12" x 12" Tan w/ Brown and White Streak Floor Tile
77	Mastic assoc. W/ 12" x 12" Tan w/ Brown and White Streak Floor Tile
78	12" x 12" Brown Mottled Floor Tile
79	Mastic for 12" x 12" Brown Mottled Floor Tile
80	12" x 12" Tan Mottled Floor Tile
81	Mastic assoc. W/ 12" x 12" Tan Mottled Floor Tile
82	12" x 12" White w/ Tan Speck Floor Tile
83	Mastic assoc. W/ 12" x 12" White w/ Tan Speck Floor Tile
84	12" x 12" Tan and White Mottled Floor Tile
85	Mastic Associated w/ 12" x 12" Tan and White Mottled Floor Tile
86	12" x 12" Peach Mottled Floor Tile
87	12" x 12" Dark Blue Mottled Floor Tile
88	12" x 12" Dark Red Mottled Floor Tile
89	Mastic Associated w/ 12" x 12" Peach, Dark Blue and Dark Red Mottled Floor Tile
90	Orange, Gray and Beige Vinyl Flooring

- 91 Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring
- 92 Transite lined cabinets

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	2' x 4' Fiberglass Ceiling Panel
12	Fiberglass duct insulation
15	Inner duct insulation
16	Spray-on fire proofing
17	2' x 4' Sound Baffles
18	Metal Encased Sound baffles
20	Fiberglass batting above lights
22.10	12" x 12" White w/Brown Specks Floor Tile
22.11	12" x 12" Pinkish Beige Mix Floor Tile
22.12	12" x 12" Light Gray w/Brown Streaks Floor Tile
22.13	12" x 12" White w/Peach Specks Floor Tile
22.14	12" x 12" White Floor Tile
22.3	12" x 12" Off-White Floor Tile Brown/White Speckles
22.4	12" x 12" Brown Vinyl Floor Tile w/ Brown & White Speckles
22.5	12" x 12" Cream VAT w/ White Speckles
22.6	12" x 12" Black Vinyl Floor Tile w/ Black & Brown Speckles
22.7	12" x 12" Vinyl Floor Tile w/ Brown, White, and Tan Speckles
22.8	12" x 12" Off-White Floor Tile w/Brown, Tan, White Speckles
22.9	12" x 12" Yellow Floor Tile w/Tan, Yellow, White Speckles
23.1A	Mastic under 12" x 12" Vinyl Floor Tile Brown, Tan, White Speckles
23.1B	Mastic Under 12" x 12" Off-White Vinyl Floor Tile w/ Yel & Brown Speckle
23.1C	Mastic for 12" x 12" Off-White VAT w/ Brown & White Speckles
23.1D	Mastic for 12" x 12" Brown VAT w/ Brown & White Speckles
23.1E	Mastic for 12" x 12" Cream VAT, White Speckles
23.1F	Mastic for 12" x 12" Black VAT w/ Blk & Brown Speckles
23.2	Mastic for 12" x 12" VAT, Brown, Tan, & White Speckles
23.3	12" x 12" Off-White Floor Tile w/Brown, Tan, White Speck Mastic
23.4	12" x 12" Yellow w/Tan, Yell, White Speckles Floor Tile Mastic

23.5	12" x 12" White w/Brown Specks Floor Tile Mastic
23.6	12" x 12" Pinkish Beige Mix Floor Tile Mastic
23.7	12" x 12" Light Gray w/Brown Streaks Floor Tile Mastic
23.8	12" x 12" White w/Peach Specks Floor Tile Mastic
23.9	12" x 12" White Floor Tile Mastic
24	4" Black baseboard
25	4" Black baseboard mastic
27	Dry wall
28A	Drywall joint compound
2B	2' x 4' Ceiling
31A	Interior casing caulk
34	Carpet mastic
34.1	Gray carpet adhesive
34.10	Brown/green/light brown carpet adhesive
34.11	Green carpet adhesive
34.2	Brown carpet adhesive
34.4	Bright blue carpet adhesive
34.5	Light brown carpet adhesive
34.6	Gray/white mix carpet adhesive
34.7	Brown/light brown carpet adhesive
34.8	Gray/red carpet adhesive
34.9	Blue/blue/orange carpet adhesive
36	A building roof material
37	B building roof material
38	Blue floor matting adhesive
39	Red floor matting adhesive
4	Fiberglass pipe
40	White stair treads
41	White stair treads adhesive
42	4" Black vinyl baseboard
43	4" Black vinyl baseboard adhesive
44	4" Brown vinyl baseboard
45	4" Brown vinyl baseboard adhesive
46	Chalk board/poster board/ marker board adhesive
47	Brown/gray swirl flooring
48	Brown/gray swirl flooring adhesive
49	2' x 4' Lay in Ceiling Panels
50	Lab counters & sinks
51	Fume hood
52	Lab table top
53	Lab sink tops
54	Flange gaskets
55	Cement mat.on f.glass insul. Jacket water heater
58	Interior Materials in Kilns
59	Tan mix terrazzo flooring
6	Fiberglass duct insulation
60	Gray mix carpet adhesive

61	Black stairway landing tread
62	Black stairway adhesive
63	Brown stairway tread
64	Brown stairway tread adhesive
65	Yellowish terrazzo
66	9" x 9" Carmel w/White Streaks Vinyl Floor Tile
67	9" x 9" Carmel w/White Streaks Vinyl Floor Tile Mastic
68	12" x 12" Carmel Vinyl Floor Tile
69	12" x 12" Carmel Vinyl Floor Tile Mastic
7	Plaster
70	Vault door insulation
72	2' x 2' Ceiling Tile w/ Pinholes
73	12" x 12" Light Gray w/ Gray and White Streak Floor Tile
74	Mastic assoc. W/12" x 12" Light Gray w/ Gray and White Streak Floor Tile
75	Tongue and Groove Wood Flooring
76	12" x 12" Tan w/ Brown and White Streak Floor Tile
77	Mastic assoc. W/ 12" x 12" Tan w/ Brown and White Streak Floor Tile
78	12" x 12" Brown Mottled Floor Tile
79	Mastic for 12" x 12" Brown Mottled Floor Tile
8	2' x 4' Insulation
80	12" x 12" Tan Mottled Floor Tile
81	Mastic assoc. W/ 12" x 12" Tan Mottled Floor Tile
82	12" x 12" White w/ Tan Speck Floor Tile
83	Mastic assoc. W/ 12" x 12" White w/ Tan Speck Floor Tile
84	12" x 12" Tan and White Mottled Floor Tile
85	Mastic Associated w/ 12" x 12" Tan and White Mottled Floor Tile
86	12" x 12" Peach Mottled Floor Tile
87	12" x 12" Dark Blue Mottled Floor Tile
88	12" x 12" Dark Red Mottled Floor Tile
89	Mastic Associated w/ 12" x 12" Peach, Dark Blue and Dark Red Mottled Floor Tile
9.2	Trasite Board Around Ceiling and Sky Lights
90	Orange, Gray and Beige Vinyl Flooring
91	Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring
92	Transite lined cabinets

The following areas were deemed to be inaccessible:

67	9" x 9" Carmel w/White Streaks Vinyl Floor Tile Mastic
69	12" x 12" Carmel Vinyl Floor Tile Mastic
70	Vault door insulation
72	2' x 2' Ceiling Tile w/ Pinholes
91	Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Joshua Karlson, IDPH License # 100-20129. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Curie Metro High School Building 1820 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1 A	1' x 1' Ceiling Tile			A Building - Lobby Hallway Stairwells, Building B Corridor, 630, 612, 616, Sound Lab, 620, Quinn Hall, 523, 514, 510, 536C, Basement Corridor	NO_ACBM	MISC								
10	2' x 4' Fiberglass Ceiling Panel			Building A -TV Studio Closet	ASSUMED	TSI								
11	Duct work tape	1,040	SF	A Building - Metal Shop	CHR	TSI	Y	NONE	0	SF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM		LOW
12	Fiberglass duct insulation			A Building - Metal Shop	ASSUMED	TSI								
13	Tank breaching	600	SF	B Building - Pool Equipment Room	CHR	TSI	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
14	Tank insulation	320	SF	B Building - Pool Equipment Room	AMO	TSI	Y	NONE	0	SF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
15	Inner duct insulation	500	SF	B Building - Auditorium	ASSUMED	TSI	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
16	Spray-on fire proofing	1,600	SF	Building B - Small Room at Rear of Auditorium	ASSUMED	SURFACE	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
17	2' x 4' Sound Baffles	3,500	SF	Building B - Rooms 510, 514, and 616	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
18	Metal Encased Sound baffles	2,000	SF	B Building - Little Theatre	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
19	Fire doors	23,730	SF	Throughout Building A and B, Original Doors	CHR	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
20	Fiberglass batting above lights	50,000	SF	A Building - Classrooms, Corridors, Main Office, Library	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
21	Klieg lights	1,000	LF	B Building - Room 606 in Stage Cat Walk	CHR	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
22.1	12" x 12" Cream/Brown/Tan/White Speckles Floor Tile	52,000	SF	B Building - Classrooms, Lockers, Lunch	CHR	MISC	N	LOC	100	SF	No	ACBM with the potential for damage	5	LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Rooms, 619, 629, 627 Building A-throughout										
22.10	12" x 12" White w/Brown Specks Floor Tile	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.11	12" x 12" Pinkish Beige Mix Floor Tile	28,000	SF	See Locations in the Comments Section Below	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.12	12" x 12" Light Gray w/Brown Streaks Floor Tile	13,000	SF	Room 143,148,152,159,160,165,380,381, 382, 341, 339, 336A, 336D	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.13	12" x 12" White w/Peach Specks Floor Tile	600	SF	Principal's Office & Conference Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.14	12" x 12" White Floor Tile	81	SF	Room 620	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.3	12" x 12" Off-White Floor Tile Brown/White Speckles	1,160	SF	A & B Buildings, Class Rooms and Corridors, 169	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.4	12" x 12" Brown Vinyl Floor Tile w/ Brown & White Speckles	25,000	SF	A Building, Classrooms, Office, Corridor by 145	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.5	12" x 12" Cream VAT w/ White Speckles	2,000	SF	A Building, Faculty Dining Area	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.6	12" x 12" Black Vinyl Floor Tile w/ Black & Brown Speckles	8,000	SF	B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635, 639, 642	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.7	12" x 12" Vinyl Floor Tile w/ Brown, White, and Tan Speckles	3,200	SF	A Building, 3rd and 2nd Floor Rooms, Lunchrooms, 3rd Floor Kitchen	ASSUMED	MISC	N	LOC	3	SF	No	ACBM with the potential for damage	5	LOW
22.8	12" x 12" Off-White Floor Tile w/Brown, Tan, White Speckles	1,160	SF	160 West Section, 161 and 144, 162, 158	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
22.9	12" x 12" Yellow Floor Tile w/Tan, Yellow, White Speckles	1,200	SF	Room 150	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.1	12" x 12" VAT Mastic	125,500	SF	HA was split into HA 23.1A-23.1F	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.1A	Mastic under 12" x 12" Vinyl Floor Tile Brown, Tan, White Speckles	52,000	SF	B Building, Classrooms,	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Lockers, Lunch Rooms, 611A Building A-Throughout										
23.1B	Mastic Under 12" x 12" Off-White Vinyl Floor Tile w/ Yel & Brown Speckle	15,000	SF	Building A and Building B Throughout	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.1C	Mastic for 12" x 12" Off-White VAT w/ Brown & White Speckles	20,000	SF	Building A -2nd, 3rd Flr Hall 263, Building, B 1st Flr Hall, 619, 629	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.1D	Mastic for 12" x 12" Brown VAT w/ Brown & White Speckles	25,000	SF	bdg A: 1st Flr Hall, 334, 364, 366, 367	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.1E	Mastic for 12" x 12" Cream VAT, White Speckles	2,000	SF	Building A: 1st flr NW Corner Faculty Dining Area	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.1F	Mastic for 12" x 12" Black VAT w/ Blk & Brown Speckles	8,000	SF	Building B: 1st Flr Hall, 2nd Flr Hall, Room 635,643, 639, 642	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.2	Mastic for 12" x 12" VAT, Brown, Tan, & White Speckles	17,500	SF	Throughout Building A Class Rooms-249, 290	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.3	12" x 12" Off-White Floor Tile w/Brown, Tan, White Speck Mastic	1,160	SF	Room 160, 162	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.4	12" x 12" Yellow w/Tan, Yell, White Speckles Floor Tile Mastic	1,200	SF	Room 150	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.5	12" x 12" White w/Brown Specks Floor Tile Mastic	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.6	12" x 12" Pinkish Beige Mix Floor Tile Mastic	28,000	SF	See Locations in the Comments Section Below	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.7	12" x 12" Light Gray w/Brown Streaks Floor Tile Mastic	13,000	SF	Room 159, 382, 341, 339, 336A, 336D	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.8	12" x 12" White w/Peach Specks Floor Tile Mastic	600	SF	Principal's Office & Conference Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
23.9	12" x 12" White Floor Tile Mastic	81	SF	Room 620	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
24	4" Black baseboard	150	LF	A Building, Basement	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
25	4" Black baseboard mastic	200	LF	A Building Basement	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
33	Fiberglass pipe fitting			B Building, Pool Equipment Room	NO_ACBM	MISC								
34	Carpet mastic	28,000	SF	A Building, Offices, Classrooms, Auditorium, 520	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.1	Gray carpet adhesive	3,875	SF	Office, Spotlight Room, Projection Room, 242B, 525B & 611A, 235A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.10	Brown/green/light brown carpet adhesive	750	SF	Room 613	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.11	Green carpet adhesive			Room 236C	ASSUMED	MISC								
34.2	Brown carpet adhesive	6,000	SF	Library 234, All Rooms Branching Off, 242B	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.3	Blue carpet adhesive			Main Office Rear Room, Rooms 165, 167A, 238	NO_ACBM	MISC								
34.4	Bright blue carpet adhesive	1,320	SF	Room 270	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.5	Light brown carpet adhesive	750	SF	Room 153	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.6	Gray/white mix carpet adhesive	1,700	SF	Room 145, 168A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.7	Brown/light brown carpet adhesive	1,320	SF	Rooms 192 & 193	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.8	Gray/red carpet adhesive	5,950	SF	Auditorium Balcony	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
34.9	Blue/blue/orange carpet adhesive	2,404	SF	Rooms 611, 612, 616 & 620	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
35	Science lab black tables			A Building Rooms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360	NO_ACBM	MISC								
36	A building roof material			A Building Roof	ASSUMED	SURFACE								
37	B building roof material			B Building Roof	ASSUMED	SURFACE								
38	Blue floor matting adhesive	2,400	SF	Room 544	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
39	Red floor matting adhesive	2,500	SF	Room 540	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
4	Fiberglass pipe			Throughout Building A and B	ASSUMED	TSI								
40	White stair treads	90	SF	Pool Steps	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
41	White stair treads adhesive	90	SF	Pool Steps	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
42	4" Black vinyl baseboard	266	LF	Rooms 144 & 167, 168	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
43	4" Black vinyl baseboard adhesive	266	SF	Rooms 144 & 167, 168	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
44	4" Brown vinyl baseboard	156	LF	Rooms 146B, 150	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
45	4" Brown vinyl baseboard adhesive	156	LF	Rooms 146B, 150	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
46	Chalk board/poster board/ marker board adhesive	11,000	SF	Classrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
47	Brown/gray swirl flooring	1,320	SF	Room 340	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
48	Brown/gray swirl flooring adhesive	1,320	SF	Room 340	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
49	2' x 4' Lay in Ceiling Panels	1,320	SF	Room 340, 159, 381, 380, Basement Kitchen	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
5	Fiberglass pipe hard fitting			Throughout Building A and B	NO_ACBM	TSI								
50	Lab counters & sinks	200	SF	Room 340	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
51	Fume hood	20	SF	Room 340	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
52	Lab table top	20	SF	Room 346	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
53	Lab sink tops	45	SF	Rooms 346, 349	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
54	Flange gaskets	8	SF	Pool Equipment Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
55	Cement mat.on f.glass insul. Jacket water heater	200	SF	NE Penthouse	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
56	Tank insulation			NW Penthouse	ABATED	TSI								
57	Tank insulation			Equipment Room Behind Second Floor Men's Bathroom	ABATED	TSI								
58	Interior Materials in Kilns	200	SF	Room 627	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
59	Tan mix terrazzo flooring	14,000	SF	Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
6	Fiberglass duct insulation			Throughout Building A	ASSUMED	TSI								
60	Gray mix carpet adhesive	800	SF	Room 145	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
61	Black stairway landing tread	500	SF	Stairway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
62	Black stairway adhesive	500	SF	Stairways	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
63	Brown stairway tread	300	SF	Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
64	Brown stairway tread adhesive	300	SF	Auditorium	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
65	Yellowish terrazzo	3,000	SF	Gym Lobby	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
66	9" x 9" Carmel w/White Streaks Vinyl Floor Tile	200	SF	Room 538A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
67	9" x 9" Carmel w/White Streaks Vinyl Floor Tile Mastic	200	SF	Room 538A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
68	12" x 12" Carmel Vinyl Floor Tile	550	SF	1st Floor Middle Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
69	12" x 12" Carmel Vinyl Floor Tile Mastic	550	PERCENT	1st Floor Middle Hallway	ASSUMED	MISC	N	NONE	0	PERCENT	No	ACBM with the potential for damage		LOW
7	Plaster	5,000	SF	Men's Room and Rooms 623B, 525, 309, 201, Hall, B20	ASSUMED	SURFACE	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
70	Vault door insulation	42	SF	Main Office	ASSUMED	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
71	Hot water storage tank insulation			Penthouses NE and NW	ABATED	TSI								
72	2' x 2' Ceiling Tile w/ Pinholes	7,000	SF	Room 639, 642, Building B - Floor 1 and 2 Corridor, 619 629, 627, Hoffman Hall, 332	ASSUMED	MISC	Y	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
73	12" x 12" Light Gray w/ Gray and White Streak Floor Tile	900	SF	Room 612, 613, 332	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
74	Mastic assoc. W/12" x 12" Light Gray w/ Gray and White Streak Floor Tile	900	SF	Room 612, 613, 332	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
75	Tongue and Groove Wood Flooring	1,200	SF	616, Quinn Hall, Gym	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
76	12" x 12" Tan w/ Brown and White Streak Floor Tile	1,000	SF	Room 620	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
77	Mastic assoc. W/ 12" x 12" Tan w/ Brown	1,000	SF	Room 620	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the		LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	and White Streak Floor Tile											potential for damage		
78	12" x 12" Brown Mottled Floor Tile	3,000	SF	Building B - First Floor Corridor	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
79	Mastic for 12" x 12" Brown Mottled Floor Tile	3,000	SF	Building B - First Floor Corridor	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
8	2' x 4' Insulation	350,000	SF	Classroom Hallways, Main Office, Library, (A/B Buildings)	ASSUMED	TSI	Y	NONE	0	SF	Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
80	12" x 12" Tan Mottled Floor Tile	2,000	SF	Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282, 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
81	Mastic assoc. W/ 12" x 12" Tan Mottled Floor Tile	1,100	SF	Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282, 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
82	12" x 12" White w/ Tan Speck Floor Tile	400	SF	Room 154, Hall by 195, 197, Hall by 2nd Floor Lockers Building A, 237, 239/242 Offices, 2nd Floor East Corridor, 235E, 245, 244, 243, Basement Corridor	ASSUMED	MISC	N	LOC	10	SF	Yes	ACBM with the potential for damage	5	LOW
83	Mastic assoc. W/ 12" x 12" White w/ Tan Speck Floor Tile	400	SF	Room 154, Hall by 195, 197, Hall by 2nd Floor Lockers Building A, 237, 239/242 Offices, 2nd Floor East Corridor, 235E, 245, 244, 243, Basement Corridor	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
84	12" x 12" Tan and White Mottled Floor Tile	1,200	SF	Faculty Lounge 141	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
85	Mastic Associated w/ 12" x 12" Tan and White Mottled Floor Tile	1,200	SF	Faculty Lounge 141	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
86	12" x 12" Peach Mottled Floor Tile	2,500	SF	Library, 236B, 236A, 235B, 235C	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
87	12" x 12" Dark Blue Mottled Floor Tile	100	SF	Library 236B, 236A, 235B, 235C	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
88	12" x 12" Dark Red Mottled Floor Tile	100	SF	Library, 236B, 236A 235B, 235C	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
89	Mastic Associated w/ 12" x 12" Peach, Dark Blue and Dark Red Mottled Floor Tile	2,700	SF	Library, 236B, 236A, 235B, 235C	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
9.1	Transite Board Lab Hood, Classrooms and Pool	3,252	SF	Rooms 346, 349, 350, 352, 353, 354B, 363 & 360	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
9.2	Trasite Board Around Ceiling and Sky Lights	3,252	SF	Sky Light Board in Pool	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
90	Orange, Gray and Beige Vinyl Flooring	1,000	SF	Room 363	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
91	Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring	1,000	SF	Room 363	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
92	Transite lined cabinets	75	SF	Room 352	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 9/20/2022
Inspector Name Joshua Karlson
100-20129 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1 A	Damage in hall outside of 642
10	Not observed 2022
11	
12	Not observed 2022
13	
14	
15	
16	
17	
18	
19	
20	
21	
22.1	Damage in 2nd Floor Kitchen
22.10	
22.11	
22.12	
22.13	
22.14	
22.3	
22.4	
22.5	
22.6	
22.7	Damage in 3rd Floor Kitchen

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
22.8	
22.9	
23.1	
23.1A	
23.1B	
23.1C	
23.1D	
23.1E	
23.1F	
23.2	
23.3	
23.4	
23.5	
23.6	
23.7	
23.8	
23.9	
24	
25	
26	
27	
28A	
28B	
29	
2A	
2B	
3	
30	
31A	

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
31B	
32A	
32B	
33	
34	
34.1	
34.10	
34.11	Not observed 2022
34.2	Not observed in Library 234
34.3	
34.4	
34.5	
34.6	
34.7	
34.8	
34.9	Not observed in 612, 620
35	
36	Not observed 2022
37	Not observed 2022
38	
39	
4	Not observed 2022
40	
41	
42	
43	
44	
45	
46	

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
47	
48	
49	
5	Damage in B12
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	Not observed 2022
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	

Chicago Public Schools

School Curie Metro High School Unit 53101 Building ID 1820

Address 4959 S. Archer Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	
82	Damage in Basement Corridor
83	
84	
85	
86	
87	
88	
89	
9.1	
9.2	
90	
91	
92	

Chicago Public Schools

School Curie Metro High School **Unit** 53101 **Building ID** 1820

Address 4959 S. Archer **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1 A	1' x 1' Ceiling Tile			A Building - Lobby Hallway Stairwells, Building B Corridor, 630, 612, 616, Sound Lab, 620, Quinn Hall, 523, 514, 510, 536C, Basement Corridor	No ACBM	MISC					
10	2' x 4' Fiberglass Ceiling Panel			Building A -TV Studio Closet	Assumed	TSI					Follow O&M Plan
11	Duct work tape	1,040	SF	A Building - Metal Shop	Chrysotile	TSI	Yes	0	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
12	Fiberglass duct insulation			A Building - Metal Shop	Assumed	TSI					Follow O&M Plan
13	Tank breeching	600	SF	B Building - Pool Equipment Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Tank insulation	320	SF	B Building - Pool Equipment Room	Amosite	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	Inner duct insulation	500	SF	B Building - Auditorium	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Spray-on fire proofing	1,600	SF	Building B - Small Room at Rear of Auditorium	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
17	2' x 4' Sound Baffles	3,500	SF	Building B - Rooms 510, 514, and 616	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Metal Encased Sound baffles	2,000	SF	B Building - Little Theatre	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Fire doors	23,730	SF	Throughout Building A and B, Original Doors	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
20	Fiberglass batting above lights	50,000	SF	A Building - Classrooms, Corridors, Main Office, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Klieg lights	1,000	LF	B Building - Room 606 in Stage Cat Walk	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22.1	12" x 12" Cream/Brown/Tan/White Speckles Floor Tile	52,000	SF	B Building - Classrooms, Lockers, Lunch Rooms, 619, 629, 627 Building A-throughout	Chrysotile	MISC	No	100	SF	6 ACBM with the potential for damage	Repair
22.10	12" x 12" White w/Brown Specks Floor Tile	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.11	12" x 12" Pinkish Beige Mix Floor Tile	28,000	SF	See Locations in the Comments Section Below	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.12	12" x 12" Light Gray w/Brown Streaks Floor Tile	13,000	SF	Room 143,148,152,159,160,165,380,381, 382, 341, 339, 336A, 336D	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.13	12" x 12" White w/Peach Specks Floor Tile	600	SF	Principal's Office & Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.14	12" x 12" White Floor Tile	81	SF	Room 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.3	12" x 12" Off-White Floor Tile Brown/White	1,160	SF	A & B Buildings, Class Rooms and	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Speckles			Corridors, 169							
22.4	12" x 12" Brown Vinyl Floor Tile w/ Brown & White Speckles	25,000	SF	A Building, Classrooms, Office, Corridor by 145	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.5	12" x 12" Cream VAT w/ White Speckles	2,000	SF	A Building, Faculty Dining Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.6	12" x 12" Black Vinyl Floor Tile w/ Black & Brown Speckles	8,000	SF	B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635, 639, 642	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.7	12" x 12" Vinyl Floor Tile w/ Brown, White, and Tan Speckles	3,200	SF	A Building, 3rd and 2nd Floor Rooms, Lunchrooms, 3rd Floor Kitchen	Assumed	MISC	No	3	SF	6 ACBM with the potential for damage	Repair
22.8	12" x 12" Off-White Floor Tile w/Brown, Tan, White Speckles	1,160	SF	160 West Section, 161 and 144, 162, 158	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22.9	12" x 12" Yellow Floor Tile w/Tan, Yellow, White Speckles	1,200	SF	Room 150	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1	12" x 12" VAT Mastic	125,500	SF	HA was split into HA 23.1A-23.1F	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1A	Mastic under 12" x 12" Vinyl Floor Tile Brown, Tan, White Speckles	52,000	SF	B Building, Classrooms, Lockers, Lunch Rooms, 611A Building A-Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1B	Mastic Under 12" x 12" Off-White Vinyl Floor Tile w/ Yel & Brown Speckle	15,000	SF	Building A and Building B Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1C	Mastic for 12" x 12" Off-White VAT w/ Brown & White Speckles	20,000	SF	Building A -2nd, 3rd Flr Hall 263, Building B 1st Flr Hall, 619, 629	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1D	Mastic for 12" x 12" Brown VAT w/ Brown & White Speckles	25,000	SF	bldg A: 1st Flr Hall, 334, 364, 366, 367	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1E	Mastic for 12" x 12" Cream VAT, White Speckles	2,000	SF	Building A: 1st flr NW Corner Faculty Dining Area	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.1F	Mastic for 12" x 12" Black VAT w/ Blk & Brown Speckles	8,000	SF	Building B: 1st Flr Hall, 2nd Flr Hall, Room 635,643, 639, 642	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.2	Mastic for 12" x 12" VAT, Brown, Tan, & White Speckles	17,500	SF	Throughout Building A Class Rooms-249, 290	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.3	12" x 12" Off-White Floor Tile w/Brown, Tan, White Speck Mastic	1,160	SF	Room 160, 162	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.4	12" x 12" Yellow w/Tan, Yell, White Speckles Floor Tile Mastic	1,200	SF	Room 150	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.5	12" x 12" White w/Brown Specks Floor Tile Mastic	4,500	SF	Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.6	12" x 12" Pinkish Beige Mix Floor Tile Mastic	28,000	SF	See Locations in the Comments Section Below	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
23.7	12" x 12" Light Gray w/Brown Streaks Floor Tile Mastic	13,000	SF	Room 159, 382, 341, 339, 336A, 336D	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.8	12" x 12" White w/Peach Specks Floor Tile Mastic	600	SF	Principal's Office & Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23.9	12" x 12" White Floor Tile Mastic	81	SF	Room 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	4" Black baseboard	150	LF	A Building, Basement	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
25	4" Black baseboard mastic	200	LF	A Building Basement	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
26	Main water fitting	32	SF	A Building Pump Room	Chrysotile	TSI	Yes	0	SF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
27	Dry wall	1,000	SF	Stairway to Roof, Basement Corridor, Rooms 163, 164, 165, 524	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28A	Drywall joint compound	200	LF	A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
28B	Drywall Joint compound			Rooms 524, 163, 164, 165	No ACBM	SURFACE					
29	Exterior brick			Exterior of Building	No ACBM	MISC					
2A	2' x 4' Ceiling Tile			A Building, Kitchen	No ACBM	MISC					
2B	2' x 4' Ceiling	9,600	SF	B Building, Pool	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
3	Spray-on fire proofing			Throughout Building	No ACBM	SURFACE					
30	Exterior brick mortar - non ahera			Exterior of Building	No ACBM	MISC					
31A	Interior casing caulk	7,000	LF	A Building, 3rd Floor (Room 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
31B	Interior casing caulk	7,000	LF	B building, Auditorium E. Hallway S. Door, Room 536, 1st Floor Hallway Storage Cabinet	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
32A	Exterior casing caulk - non ahera			A Building, (Room 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	No ACBM	MISC					
32B	Exterior casing caulk - non ahera			A Building, (Room 187, 159, SW Entrance), B Building (N, NE, SE Entrances)	No ACBM	MISC					
33	Fiberglass pipe fitting			B Building, Pool Equipment Room	No ACBM	MISC					
34	Carpet mastic	28,000	SF	A Building, Offices, Classrooms, Auditorium, 520	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.1	Gray carpet adhesive	3,875	SF	Office, Spotlight Room, Projection	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Room, 242B,525B & 611A, 235A							
34.10	Brown/green/light brown carpet adhesive	750	SF	Room 613	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.11	Green carpet adhesive			Room 236C	Assumed	MISC					Follow O&M Plan
34.2	Brown carpet adhesive	6,000	SF	Library 234, All Rooms Branching Off, 242B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.3	Blue carpet adhesive			Main Office Rear Room, Rooms 165, 167A,238	No ACBM	MISC					
34.4	Bright blue carpet adhesive	1,320	SF	Room 270	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.5	Light brown carpet adhesive	750	SF	Room 153	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.6	Gray/white mix carpet adhesive	1,700	SF	Room 145, 168A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.7	Brown/light brown carpet adhesive	1,320	SF	Rooms 192 & 193	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.8	Gray/red carpet adhesive	5,950	SF	Auditorium Balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34.9	Blue/blue/orange carpet adhesive	2,404	SF	Rooms 611, 612, 616 & 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Science lab black tables			A Building Rooms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360	No ACBM	MISC					
36	A building roof material			A Building Roof	Assumed	SURFACE					Follow O&M Plan
37	B building roof material			B Building Roof	Assumed	SURFACE					Follow O&M Plan
38	Blue floor matting adhesive	2,400	SF	Room 544	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Red floor matting adhesive	2,500	SF	Room 540	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
4	Fiberglass pipe			Throughout Building A and B	Assumed	TSI					Follow O&M Plan
40	White stair treads	90	SF	Pool Steps	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	White stair treads adhesive	90	SF	Pool Steps	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	4" Black vinyl baseboard	266	LF	Rooms 144 & 167, 168	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
43	4" Black vinyl baseboard adhesive	266	SF	Rooms 144 & 167, 168	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	4" Brown vinyl baseboard	156	LF	Rooms 146B, 150	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
45	4" Brown vinyl baseboard adhesive	156	LF	Rooms 146B, 150	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
46	Chalk board/poster board/ marker board adhesive	11,000	SF	Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Brown/gray swirl flooring	1,320	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Brown/gray swirl flooring adhesive	1,320	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	2' x 4' Lay in Ceiling Panels	1,320	SF	Room 340, 159, 381, 380, Basement Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
5	Fiberglass pipe hard fitting			Throughout Building A and B	No ACBM	TSI					
50	Lab counters & sinks	200	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Fume hood	20	SF	Room 340	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
52	Lab table top	20	SF	Room 346	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Lab sink tops	45	SF	Rooms 346, 349	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Flange gaskets	8	SF	Pool Equipment Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Cement mat on f.glass insul. Jacket water heater	200	SF	NE Penthouse	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Tank insulation			NW Penthouse	Abated	TSI					
57	Tank insulation			Equipment Room Behind Second Floor Men's Bathroom	Abated	TSI					
58	Interior Materials in Kilns	200	SF	Room 627	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Tan mix terrazzo flooring	14,000	SF	Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Fiberglass duct insulation			Throughout Building A	Assumed	TSI					Follow O&M Plan
60	Gray mix carpet adhesive	800	SF	Room 145	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Black stairway landing tread	500	SF	Stairway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Black stairway adhesive	500	SF	Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Brown stairway tread	300	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Brown stairway tread adhesive	300	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Yellowish terrazzo	3,000	SF	Gym Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	9" x 9" Carmel w/White Streaks Vinyl Floor Tile	200	SF	Room 538A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	9" x 9" Carmel w/White Streaks Vinyl Floor Tile Mastic	200	SF	Room 538A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Carmel Vinyl Floor Tile	550	SF	1st Floor Middle Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Carmel Vinyl Floor Tile Mastic	550	PERCENT	1st Floor Middle Hallway	Assumed	MISC	No	0	PERCENT	6 ACBM with the potential for damage	Follow O&M Plan
7	Plaster	5,000	SF	Men's Room and Rooms 623B, 525, 309, 201, Hall, B20	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Vault door insulation	42	SF	Main Office	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
71	Hot water storage tank insulation			Penthouses NE and NW	Abated	TSI					
72	2' x 2' Ceiling Tile w/ Pinholes	7,000	SF	Room 639, 642, Building B - Floor 1 and 2 Corridor, 619 629, 627, Hoffman Hall, 332	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" Light Gray w/ Gray and White Streak Floor Tile	900	SF	Room 612, 613, 332	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	Mastic assoc. W/12" x 12" Light Gray w/ Gray and White Streak Floor Tile	900	SF	Room 612, 613, 332	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Tongue and Groove Wood Flooring	1,200	SF	616, Quinn Hall, Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
76	12" x 12" Tan w/ Brown and White Streak Floor Tile	1,000	SF	Room 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Mastic assoc. W/ 12" x 12" Tan w/ Brown and White Streak Floor Tile	1,000	SF	Room 620	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Brown Mottled Floor Tile	3,000	SF	Building B - First Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Mastic for 12" x 12" Brown Mottled Floor Tile	3,000	SF	Building B - First Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
8	2' x 4' Insulation	350,000	SF	Classroom Hallways, Main Office, Library, (A/B Buildings)	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
80	12" x 12" Tan Mottled Floor Tile	2,000	SF	Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282, 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Mastic assoc. W/ 12" x 12" Tan Mottled Floor Tile	1,100	SF	Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282, 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12" x 12" White w/ Tan Speck Floor Tile	400	SF	Room 154, Hall by 195, 197, Hall by 2nd Floor Lockers Building A, 237, 239/242 Offices, 2nd Floor East Corridor, 235E, 245, 244, 243, Basement Corridor	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
83	Mastic assoc. W/ 12" x 12" White w/ Tan Speck Floor Tile	400	SF	Room 154, Hall by 195, 197, Hall by 2nd Floor Lockers Building A, 237, 239/242 Offices, 2nd Floor East Corridor, 235E, 245, 244, 243, Basement Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Tan and White Mottled Floor Tile	1,200	SF	Faculty Lounge 141	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Mastic Associated w/ 12" x 12" Tan and White Mottled Floor Tile	1,200	SF	Faculty Lounge 141	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Peach Mottled Floor Tile	2,500	SF	Library, 236B, 236A, 235B, 235C	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" Dark Blue Mottled Floor Tile	100	SF	Library 236B, 236A, 235B, 235C	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	12" x 12" Dark Red Mottled Floor Tile	100	SF	Library, 236B, 236A, 235B, 235C	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Mastic Associated w/ 12" x 12" Peach, Dark Blue and Dark Red Mottled Floor Tile	2,700	SF	Library, 236B, 236A, 235B, 235C	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
9.1	Transite Board Lab Hood, Classrooms and Pool	3,252	SF	Rooms 346, 349, 350, 352, 353, 354B,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				363 & 360							
9.2	Trasite Board Around Ceiling and Sky Lights	3,252	SF	Sky Light Board in Pool	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	Orange, Gray and Beige Vinyl Flooring	1,000	SF	Room 363	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring	1,000	SF	Room 363	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	Transite lined cabinets	75	SF	Room 352	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Curie Metro High School
Address 4959 S. Archer

Unit 53101
 Chicago, IL, 60632

Building ID 1820
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	9/30/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1 A	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22.1	
22.10	
22.11	
22.12	
22.13	
22.14	
22.3	
22.4	
22.5	
22.6	
22.7	
22.8	
22.9	
23.1	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
23.1A	
23.1B	
23.1C	
23.1D	
23.1E	
23.1F	
23.2	
23.3	
23.4	
23.5	
23.6	
23.7	
23.8	
23.9	
24	
25	
26	
27	
28A	
28B	
29	
2A	
2B	
3	
30	
31A	
31B	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
32A	
32B	
33	
34	
34.1	
34.10	
34.11	
34.2	
34.3	
34.4	
34.5	
34.6	
34.7	
34.8	
34.9	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	

Chicago Public Schools

School Curie Metro High School
Address 4959 S. Archer

Unit 53101
 Chicago, IL, 60632

Building ID 1820
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
9.1	
9.2	
90	
91	
92	

Chicago Public Schools

School Curie Metro High School

Unit 53101

Building ID 1820

Address 4959 S. Archer

Chicago, IL, 60632

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1 A**
MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building - Lobby Hallway Stairwells, Building B Corridor, 630, 612, 616, Sound Lab, 620, Quinn Hall, 523, 514, 510, 536C, Basement Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Damage in hall outside of 642**

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **1 A**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **A Building - Lobby Hallway Stairwells, Building B Corridor, 630, 612, 616, Sound Lab, 620, Quinn Hall, 523, 514, 510, 536C, Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 09/30/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **2' x 4' Fiberglass Ceiling Panel**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building A -TV Studio Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **10**
MATERIAL DESCRIPTION: **2' x 4' Fiberglass Ceiling Panel**
MATERIAL LOCATION: **Building A -TV Studio Closet**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Duct work tape**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Delamination
Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **A Building - Metal Shop**

MATERIAL QUANTITY: **1040**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **11**
MATERIAL DESCRIPTION: **Duct work tape**
MATERIAL LOCATION: **A Building - Metal Shop**
MATERIAL QUANTITY: **1040** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Fiberglass duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building - Metal Shop**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Fiberglass duct insulation**
MATERIAL LOCATION: **A Building - Metal Shop**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Tank breeching**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building - Pool Equipment Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Tank breaching**
MATERIAL LOCATION: **B Building - Pool Equipment Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building - Pool Equipment Room**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **14**
MATERIAL DESCRIPTION: **Tank insulation**
MATERIAL LOCATION: **B Building - Pool Equipment Room**
MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Inner duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building - Auditorium**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **15**
MATERIAL DESCRIPTION: **Inner duct insulation**
MATERIAL LOCATION: **B Building - Auditorium**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Spray-on fire proofing**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B - Small Room at Rear of Auditorium**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **16**
MATERIAL DESCRIPTION: **Spray-on fire proofing**
MATERIAL LOCATION: **Building B - Small Room at Rear of Auditorium**
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2' x 4' Sound Baffles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B - Rooms 510, 514, and 616**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **17**
MATERIAL DESCRIPTION: **2' x 4' Sound Baffles**
MATERIAL LOCATION: **Building B - Rooms 510, 514, and 616**
MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Metal Encased Sound baffles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building - Little Theatre**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **18**
MATERIAL DESCRIPTION: **Metal Encased Sound baffles**
MATERIAL LOCATION: **B Building - Little Theatre**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Fire doors**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Throughout Building A and B, Original Doors**
MATERIAL QUANTITY: **23730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **19**
MATERIAL DESCRIPTION: **Fire doors**
MATERIAL LOCATION: **Throughout Building A and B, Original Doors**
MATERIAL QUANTITY: **23730** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Fiberglass batting above lights**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **A Building - Classrooms, Corridors, Main Office, Library**

MATERIAL QUANTITY: **50000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Fiberglass batting above lights**
MATERIAL LOCATION: **A Building - Classrooms, Corridors, Main Office, Library**
MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Klieg lights**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building - Room 606 in Stage Cat Walk**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **Klieg lights**
MATERIAL LOCATION: **B Building - Room 606 in Stage Cat Walk**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.1**
MATERIAL DESCRIPTION: **12" x 12" Cream/Brown/Tan/White Speckles Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with potential for significant damage**
HISTORICAL DAMAGE REASON: **Water**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building - Classrooms, Lockers, Lunch Rooms, 619, 629, 627 Building A-throughout**
MATERIAL QUANTITY: **52000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 2nd Floor Kitchen**

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.1**
MATERIAL DESCRIPTION: **12" x 12" Cream/Brown/Tan/White Speckles Floor Tile**
MATERIAL LOCATION: **B Building - Classrooms, Lockers, Lunch Rooms, 619, 629, 627 Building A-throughout**
MATERIAL QUANTITY: **52000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **100** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.10**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.10**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Specks Floor Tile**
MATERIAL LOCATION: **Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.11**
MATERIAL DESCRIPTION: **12" x 12" Pinkish Beige Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **See Locations in the Comments Section Below**

MATERIAL QUANTITY: **28000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.11**
MATERIAL DESCRIPTION: **12" x 12" Pinkish Beige Mix Floor Tile**
MATERIAL LOCATION: **See Locations in the Comments Section Below**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.12**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/Brown Streaks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 143,148,152,159,160,165,380,381, 382, 341, 339, 336A, 336D**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.12**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/Brown Streaks Floor Tile**
MATERIAL LOCATION: **Room 143,148,152,159,160,165,380,381, 382, 341, 339, 336A, 336D**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.13**
MATERIAL DESCRIPTION: **12" x 12" White w/Peach Specks Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principal's Office & Conference Room**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.13**
MATERIAL DESCRIPTION: **12" x 12" White w/Peach Specks Floor Tile**
MATERIAL LOCATION: **Principal's Office & Conference Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.14**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 620**
MATERIAL QUANTITY: **81** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.14**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **Room 620**

MATERIAL QUANTITY: **81**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.3**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Brown/White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A & B Buildings, Class Rooms and Corridors, 169**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.3**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Brown/White Speckles**
MATERIAL LOCATION: **A & B Buildings, Class Rooms and Corridors, 169**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.4**
MATERIAL DESCRIPTION: **12" x 12" Brown Vinyl Floor Tile w/ Brown & White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **A Building, Classrooms, Office, Corridor by 145**

MATERIAL QUANTITY: **25000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.4**
MATERIAL DESCRIPTION: **12" x 12" Brown Vinyl Floor Tile w/ Brown & White Speckles**
MATERIAL LOCATION: **A Building, Classrooms, Office, Corridor by 145**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.5**
MATERIAL DESCRIPTION: **12" x 12" Cream VAT w/ White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **A Building, Faculty Dining Area**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.5**
MATERIAL DESCRIPTION: **12" x 12" Cream VAT w/ White Speckles**
MATERIAL LOCATION: **A Building, Faculty Dining Area**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.6**
MATERIAL DESCRIPTION: **12" x 12" Black Vinyl Floor Tile w/ Black & Brown Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635, 639, 642**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.6**
MATERIAL DESCRIPTION: **12" x 12" Black Vinyl Floor Tile w/ Black & Brown Speckles**
MATERIAL LOCATION: **B Building, 1st & 2nd Floor Hallway, Rooms 643, and 635, 639, 642**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.7**
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile w/ Brown, White, and Tan Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building, 3rd and 2nd Floor Rooms, Lunchrooms, 3rd Floor Kitchen**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damage in 3rd Floor Kitchen**

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.7**
MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile w/ Brown, White, and Tan Speckles**
MATERIAL LOCATION: **A Building, 3rd and 2nd Floor Rooms, Lunchrooms, 3rd Floor Kitchen**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.8**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown, Tan, White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **160 West Section, 161 and 144, 162, 158**

MATERIAL QUANTITY: **1160**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.8**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown, Tan, White Speckles**
MATERIAL LOCATION: **160 West Section, 161 and 144, 162, 158**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22.9**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/Tan, Yellow, White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 150**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **22.9**
MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/Tan, Yellow, White Speckles**
MATERIAL LOCATION: **Room 150**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.1**
MATERIAL DESCRIPTION: **12" x 12" VAT Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **HA was split into HA 23.1A-23.1F**
MATERIAL QUANTITY: **125500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.1**
MATERIAL DESCRIPTION: **12" x 12" VAT Mastic**
MATERIAL LOCATION: **HA was split into HA 23.1A-23.1F**
MATERIAL QUANTITY: **125500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.1A**
MATERIAL DESCRIPTION: **Mastic under 12" x 12" Vinyl Floor Tile Brown, Tan, White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building, Classrooms, Lockers, Lunch Rooms, 611A Building A-Throughout**
MATERIAL QUANTITY: **52000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.1A**
MATERIAL DESCRIPTION: **Mastic under 12" x 12" Vinyl Floor Tile Brown, Tan, White Speckles**
MATERIAL LOCATION: **B Building, Classrooms, Lockers, Lunch Rooms, 611A Building A-Throughout**
MATERIAL QUANTITY: **52000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.1B**
MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Off-White Vinyl Floor Tile w/ Yel & Brown Speckle**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A and Building B Throughout**

MATERIAL QUANTITY: **15000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.1B**
MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Off-White Vinyl Floor Tile w/ Yel & Brown Speckle**
MATERIAL LOCATION: **Building A and Building B Throughout**
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.1C**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Off-White VAT w/ Brown & White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A -2nd, 3rd Flr Hall 263, Building. B 1st Flr Hall, 619, 629**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.1C**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Off-White VAT w/ Brown & White Speckles**
MATERIAL LOCATION: **Building A -2nd, 3rd Flr Hall 263, Building. B 1st Flr Hall, 619, 629**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.1D**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Brown VAT w/ Brown & White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **bldg A: 1st Flr Hall, 334, 364, 366, 367**

MATERIAL QUANTITY: **25000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.1D**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Brown VAT w/ Brown & White Speckles**
MATERIAL LOCATION: **bldg A: 1st Flr Hall, 334, 364, 366, 367**
MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.1E**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Cream VAT, White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Building A: 1st flr NW Corner Faculty Dining Area**

MATERIAL QUANTITY: **2000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.1E**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Cream VAT, White Speckles**
MATERIAL LOCATION: **Building A: 1st flr NW Corner Faculty Dining Area**
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.1F**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Black VAT w/ Blk & Brown Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Building B: 1st Flr Hall, 2nd Flr Hall, Room 635,643, 639, 642**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.1F**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" Black VAT w/ Blk & Brown Speckles**
MATERIAL LOCATION: **Building B: 1st Flr Hall, 2nd Flr Hall, Room 635,643, 639, 642**
MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.2**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" VAT, Brown, Tan, & White Speckles**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building A Class Rooms-249, 290**

MATERIAL QUANTITY: **17500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.2**
MATERIAL DESCRIPTION: **Mastic for 12" x 12" VAT, Brown, Tan, & White Speckles**
MATERIAL LOCATION: **Throughout Building A Class Rooms-249, 290**
MATERIAL QUANTITY: **17500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.3**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown, Tan, White Speck Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 160, 162**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.3**
MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile w/Brown, Tan, White Speck Mastic**
MATERIAL LOCATION: **Room 160, 162**
MATERIAL QUANTITY: **1160** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.4**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/Tan, Yell,White Speckles Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 150**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.4**
MATERIAL DESCRIPTION: **12" x 12" Yellow w/Tan, Yell,White Speckles Floor Tile Mastic**
MATERIAL LOCATION: **Room 150**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.5**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.5**
MATERIAL DESCRIPTION: **12" x 12" White w/Brown Specks Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 127, 129, 195/196, 226-231, 256, 327, 329, 331, 333, 170, 168**
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.6**
MATERIAL DESCRIPTION: **12" x 12" Pinkish Beige Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **See Locations in the Comments Section Below**

MATERIAL QUANTITY: **28000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.6**
MATERIAL DESCRIPTION: **12" x 12" Pinkish Beige Mix Floor Tile Mastic**
MATERIAL LOCATION: **See Locations in the Comments Section Below**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.7**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/Brown Streaks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 159, 382, 341, 339, 336A, 336D**

MATERIAL QUANTITY: **13000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.7**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/Brown Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 159, 382, 341, 339, 336A, 336D**
MATERIAL QUANTITY: **13000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.8**
MATERIAL DESCRIPTION: **12" x 12" White w/Peach Specks Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Principal's Office & Conference Room**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.8**
MATERIAL DESCRIPTION: **12" x 12" White w/Peach Specks Floor Tile Mastic**
MATERIAL LOCATION: **Principal's Office & Conference Room**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23.9**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 620**
MATERIAL QUANTITY: **81** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **23.9**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**
MATERIAL LOCATION: **Room 620**
MATERIAL QUANTITY: **81** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **4" Black baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building, Basement**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **4" Black baseboard**
MATERIAL LOCATION: **A Building, Basement**
MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **4" Black baseboard mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building Basement**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____

Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **4" Black baseboard mastic**
MATERIAL LOCATION: **A Building Basement**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Main water fitting**
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION: **Repair**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **A Building Pump Room**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **26**
MATERIAL DESCRIPTION: **Main water fitting**
MATERIAL LOCATION: **A Building Pump Room**
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Dry wall**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairway to Roof, Basement Corridor, Rooms 163, 164, 165, 524**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **27**
MATERIAL DESCRIPTION: **Dry wall**
MATERIAL LOCATION: **Stairway to Roof, Basement Corridor, Rooms 163, 164, 165, 524**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **Drywall joint compound**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **28A**
MATERIAL DESCRIPTION: **Drywall joint compound**
MATERIAL LOCATION: **A Building, Stairway to Roof, Basement Hallway, Rooms 163, 164, 165, and 524**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28B**
MATERIAL DESCRIPTION: **Drywall Joint compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 524, 163, 164, 165**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **28B**
MATERIAL DESCRIPTION: **Drywall Joint compound**
MATERIAL LOCATION: **Rooms 524, 163, 164, 165**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**
MATERIAL DESCRIPTION: **Exterior brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Exterior brick**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2A**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building, Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **A Building, Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**
MATERIAL DESCRIPTION: **2' x 4' Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **B Building, Pool**
MATERIAL QUANTITY: **9600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **2B**
MATERIAL DESCRIPTION: **2' x 4' Ceiling**
MATERIAL LOCATION: **B Building, Pool**
MATERIAL QUANTITY: **9600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **Spray-on fire proofing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **3**
MATERIAL DESCRIPTION: **Spray-on fire proofing**
MATERIAL LOCATION: **Throughout Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31A**
MATERIAL DESCRIPTION: **Interior casing caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **A Building, 3rd Floor (Room 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance)**

MATERIAL QUANTITY: **7000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **31A**
MATERIAL DESCRIPTION: **Interior casing caulk**
MATERIAL LOCATION: **A Building, 3rd Floor (Room 313, Elec. Box), 2nd Floor (SW Stairway, Rm 164 Entrance)**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31B**
MATERIAL DESCRIPTION: **Interior casing caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **B building, Auditorium E. Hallway S. Door, Room 536, 1st Floor Hallway Storage Cabinet**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: 

Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **31B**
MATERIAL DESCRIPTION: **Interior casing caulk**
MATERIAL LOCATION: **B building, Auditorium E. Hallway S. Door, Room 536, 1st Floor Hallway Storage Cabinet**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32A**
MATERIAL DESCRIPTION: **Exterior casing caulk - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building, (Room 187, 159, SW Entrance), B Building (N, NE, SE Entrances)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **32A**
MATERIAL DESCRIPTION: **Exterior casing caulk - non ahera**
MATERIAL LOCATION: **A Building, (Room 187, 159, SW Entrance), B Building (N, NE, SE Entrances)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32B**
MATERIAL DESCRIPTION: **Exterior casing caulk - non ahera**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building, (Room 187, 159, SW Entrance), B Building (N, NE, SE Entrances)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **32B**
MATERIAL DESCRIPTION: **Exterior casing caulk - non ahera**
MATERIAL LOCATION: **A Building, (Room 187, 159, SW Entrance), B Building (N, NE, SE Entrances)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Fiberglass pipe fitting**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **B Building, Pool Equipment Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **33**
MATERIAL DESCRIPTION: **Fiberglass pipe fitting**
MATERIAL LOCATION: **B Building, Pool Equipment Room**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **A Building, Offices, Classrooms, Auditorium, 520**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34**
MATERIAL DESCRIPTION: **Carpet mastic**
MATERIAL LOCATION: **A Building, Offices, Classrooms, Auditorium, 520**
MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.1**
MATERIAL DESCRIPTION: **Gray carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Office, Spotlight Room, Projection Room, 242B,525B & 611A, 235A**
MATERIAL QUANTITY: **3875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.1**
MATERIAL DESCRIPTION: **Gray carpet adhesive**
MATERIAL LOCATION: **Office, Spotlight Room, Projection Room, 242B,525B & 611A, 235A**
MATERIAL QUANTITY: **3875** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.10**
MATERIAL DESCRIPTION: **Brown/green/light brown carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 613**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.10**
MATERIAL DESCRIPTION: **Brown/green/light brown carpet adhesive**
MATERIAL LOCATION: **Room 613**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.11**
MATERIAL DESCRIPTION: **Green carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 236C**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.11**

MATERIAL DESCRIPTION: **Green carpet adhesive**

MATERIAL LOCATION: **Room 236C**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.2**
MATERIAL DESCRIPTION: **Brown carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Library 234, All Rooms Branching Off, 242B**

MATERIAL QUANTITY: **6000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Library 234**

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.2**
MATERIAL DESCRIPTION: **Brown carpet adhesive**
MATERIAL LOCATION: **Library 234, All Rooms Branching Off, 242B**
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.3**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office Rear Room, Rooms 165, 167A,238**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.3**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
MATERIAL LOCATION: **Main Office Rear Room, Rooms 165, 167A,238**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.4**
MATERIAL DESCRIPTION: **Bright blue carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 270**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.4**
MATERIAL DESCRIPTION: **Bright blue carpet adhesive**
MATERIAL LOCATION: **Room 270**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.5**
MATERIAL DESCRIPTION: **Light brown carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 153**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.5**
MATERIAL DESCRIPTION: **Light brown carpet adhesive**
MATERIAL LOCATION: **Room 153**
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.6**
MATERIAL DESCRIPTION: **Gray/white mix carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 145, 168A**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.6**
MATERIAL DESCRIPTION: **Gray/white mix carpet adhesive**
MATERIAL LOCATION: **Room 145, 168A**
MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.7**
MATERIAL DESCRIPTION: **Brown/light brown carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 192 & 193**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.7**
MATERIAL DESCRIPTION: **Brown/light brown carpet adhesive**
MATERIAL LOCATION: **Rooms 192 & 193**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.8**
MATERIAL DESCRIPTION: **Gray/red carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium Balcony**
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.8**
MATERIAL DESCRIPTION: **Gray/red carpet adhesive**
MATERIAL LOCATION: **Auditorium Balcony**
MATERIAL QUANTITY: **5950** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34.9**
MATERIAL DESCRIPTION: **Blue/blue/orange carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 611, 612, 616 & 620**

MATERIAL QUANTITY: **2404**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not observed in 612, 620**

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **34.9**
MATERIAL DESCRIPTION: **Blue/blue/orange carpet adhesive**
MATERIAL LOCATION: **Rooms 611, 612, 616 & 620**
MATERIAL QUANTITY: **2404** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**
MATERIAL DESCRIPTION: **Science lab black tables**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building Rooms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Science lab black tables**

MATERIAL LOCATION: **A Building Rooms 346, 347, 349, 350, 351, 353, 354, 355, 383, 363, 361 & 360**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **A building roof material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **A Building Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **36**
MATERIAL DESCRIPTION: **A building roof material**
MATERIAL LOCATION: **A Building Roof**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**
MATERIAL DESCRIPTION: **B building roof material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **B Building Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **B building roof material**

MATERIAL LOCATION: **B Building Roof**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Blue floor matting adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 544**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Blue floor matting adhesive**
MATERIAL LOCATION: **Room 544**
MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Red floor matting adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 540**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **39**
MATERIAL DESCRIPTION: **Red floor matting adhesive**
MATERIAL LOCATION: **Room 540**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **Fiberglass pipe**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building A and B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **4**
MATERIAL DESCRIPTION: **Fiberglass pipe**
MATERIAL LOCATION: **Throughout Building A and B**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **White stair treads**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Steps**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **40**
MATERIAL DESCRIPTION: **White stair treads**
MATERIAL LOCATION: **Pool Steps**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **White stair treads adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Steps**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **41**
MATERIAL DESCRIPTION: **White stair treads adhesive**
MATERIAL LOCATION: **Pool Steps**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 144 & 167, 168**
MATERIAL QUANTITY: **266** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**
COMMENTS:

Inspector's Signature: _____

Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard**
MATERIAL LOCATION: **Rooms 144 & 167, 168**
MATERIAL QUANTITY: **266** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 144 & 167, 168**
MATERIAL QUANTITY: **266** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **43**
MATERIAL DESCRIPTION: **4" Black vinyl baseboard adhesive**
MATERIAL LOCATION: **Rooms 144 & 167, 168**
MATERIAL QUANTITY: **266** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 146B, 150**
MATERIAL QUANTITY: **156** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **44**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
MATERIAL LOCATION: **Rooms 146B, 150**
MATERIAL QUANTITY: **156** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 146B, 150**
MATERIAL QUANTITY: **156** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **45**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
MATERIAL LOCATION: **Rooms 146B, 150**
MATERIAL QUANTITY: **156** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Chalk board/poster board/ marker board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **46**
MATERIAL DESCRIPTION: **Chalk board/poster board/ marker board adhesive**
MATERIAL LOCATION: **Classrooms**
MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Brown/gray swirl flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Brown/gray swirl flooring**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Brown/gray swirl flooring adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **48**
MATERIAL DESCRIPTION: **Brown/gray swirl flooring adhesive**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **2' x 4' Lay in Ceiling Panels**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 340, 159, 381, 380, Basement Kitchen**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **49**
MATERIAL DESCRIPTION: **2' x 4' Lay in Ceiling Panels**
MATERIAL LOCATION: **Room 340, 159, 381, 380, Basement Kitchen**
MATERIAL QUANTITY: **1320** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Fiberglass pipe hard fitting**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building A and B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Damage in B12**

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **5**
MATERIAL DESCRIPTION: **Fiberglass pipe hard fitting**
MATERIAL LOCATION: **Throughout Building A and B**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Lab counters & sinks**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **50**
MATERIAL DESCRIPTION: **Lab counters & sinks**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Fume hood**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **51**
MATERIAL DESCRIPTION: **Fume hood**
MATERIAL LOCATION: **Room 340**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Lab table top**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 346**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **52**
MATERIAL DESCRIPTION: **Lab table top**
MATERIAL LOCATION: **Room 346**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Lab sink tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 346, 349**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **53**
MATERIAL DESCRIPTION: **Lab sink tops**
MATERIAL LOCATION: **Rooms 346, 349**
MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Flange gaskets**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Pool Equipment Room**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **54**
MATERIAL DESCRIPTION: **Flange gaskets**
MATERIAL LOCATION: **Pool Equipment Room**
MATERIAL QUANTITY: **8** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Cement mat.on f.glass insul. Jacket water heater**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **NE Penthouse**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **55**
MATERIAL DESCRIPTION: **Cement mat.on f.glass insul. Jacket water heater**
MATERIAL LOCATION: **NE Penthouse**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **NW Penthouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Tank insulation**

MATERIAL LOCATION: **NW Penthouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Equipment Room Behind Second Floor Men's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **57**
MATERIAL DESCRIPTION: **Tank insulation**
MATERIAL LOCATION: **Equipment Room Behind Second Floor Men's Bathroom**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Interior Materials in Kilns**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 627**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **58**
MATERIAL DESCRIPTION: **Interior Materials in Kilns**
MATERIAL LOCATION: **Room 627**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Tan mix terrazzo flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **59**
MATERIAL DESCRIPTION: **Tan mix terrazzo flooring**
MATERIAL LOCATION: **Kitchen, 1st-3rd Floor Service Areas, Stairwells, Room 359**
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Fiberglass duct insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **6**
MATERIAL DESCRIPTION: **Fiberglass duct insulation**
MATERIAL LOCATION: **Throughout Building A**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Gray mix carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 145**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **Gray mix carpet adhesive**
MATERIAL LOCATION: **Room 145**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Black stairway landing tread**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairway**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **Black stairway landing tread**
MATERIAL LOCATION: **Stairway**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Black stairway adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Stairways**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **Black stairway adhesive**
MATERIAL LOCATION: **Stairways**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Brown stairway tread**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **Brown stairway tread**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Brown stairway tread adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **64**
MATERIAL DESCRIPTION: **Brown stairway tread adhesive**
MATERIAL LOCATION: **Auditorium**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Yellowish terrazzo**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Gym Lobby**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **Yellowish terrazzo**
MATERIAL LOCATION: **Gym Lobby**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9" x 9" Carmel w/White Streaks Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 538A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **66**
MATERIAL DESCRIPTION: **9" x 9" Carmel w/White Streaks Vinyl Floor Tile**
MATERIAL LOCATION: **Room 538A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **9" x 9" Carmel w/White Streaks Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Room 538A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **9" x 9" Carmel w/White Streaks Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **Room 538A**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Carmel Vinyl Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Middle Hallway**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **68**
MATERIAL DESCRIPTION: **12" x 12" Carmel Vinyl Floor Tile**
MATERIAL LOCATION: **1st Floor Middle Hallway**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Carmel Vinyl Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **1st Floor Middle Hallway**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **PERCENT**
DAMAGE QUANTITY: DAMAGE UNITS: **PERCENT**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **69**
MATERIAL DESCRIPTION: **12" x 12" Carmel Vinyl Floor Tile Mastic**
MATERIAL LOCATION: **1st Floor Middle Hallway**
MATERIAL QUANTITY: **550** MATERIAL UNITS: **PERCENT**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **PERCENT**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Men's Room and Rooms 623B, 525, 309, 201, Hall, B20**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **7**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Men's Room and Rooms 623B, 525, 309, 201, Hall, B20**
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Vault door insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Vault door insulation**
MATERIAL LOCATION: **Main Office**
MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Hot water storage tank insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON: **Deterioration
Vibration
Water**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Penthouses NE and NW**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Hot water storage tank insulation**

MATERIAL LOCATION: **Penthouses NE and NW**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **2' x 4' Insulation**
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classroom Hallways, Main Office, Library, (A/B Buildings)**
MATERIAL QUANTITY: **350000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **8**
MATERIAL DESCRIPTION: **2' x 4' Insulation**
MATERIAL LOCATION: **Classroom Hallways, Main Office, Library, (A/B Buildings)**
MATERIAL QUANTITY: **350000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.1**
MATERIAL DESCRIPTION: **Transite Board Lab Hood, Classrooms and Pool**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 346, 349, 350, 352, 353, 354B, 363 & 360**
MATERIAL QUANTITY: **3252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **9.1**
MATERIAL DESCRIPTION: **Transite Board Lab Hood, Classrooms and Pool**
MATERIAL LOCATION: **Rooms 346, 349, 350, 352, 353, 354B, 363 & 360**
MATERIAL QUANTITY: **3252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9.2**
MATERIAL DESCRIPTION: **Trasite Board Around Ceiling and Sky Lights**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Sky Light Board in Pool**
MATERIAL QUANTITY: **3252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **9.2**
MATERIAL DESCRIPTION: **Trasite Board Around Ceiling and Sky Lights**
MATERIAL LOCATION: **Sky Light Board in Pool**
MATERIAL QUANTITY: **3252** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **85**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Tan and White Mottled Floor Tile**
MATERIAL LOCATION: **Faculty Lounge 141**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Tan and White Mottled Floor Tile**

MATERIAL LOCATION: **Faculty Lounge 141**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **78**
MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile**
MATERIAL LOCATION: **Building B - First Floor Corridor**
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Brown Mottled Floor Tile**

MATERIAL LOCATION: **Building B - First Floor Corridor**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Mastic assoc. W/ 12" x 12" White w/ Tan Speck Floor Tile**

MATERIAL LOCATION: **Room 154, Hall by 195, 197, Hall by 2nd Floor Lockers Building A, 237, 239/242 Offices, 2nd Floor East Corridor, 235E, 245, 244, 243, Basement Corridor**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **89**
MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Peach, Dark Blue and Dark Red Mottled Floor Tile**
MATERIAL LOCATION: **Library, 236B, 236A, 235B, 235C**
MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Mastic Associated w/ 12" x 12" Peach, Dark Blue and Dark Red Mottled Floor Tile**

MATERIAL LOCATION: **Library, 236B, 236A, 235B, 235C**

MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **77**
MATERIAL DESCRIPTION: **Mastic assoc. W/ 12" x 12" Tan w/ Brown and White Streak Floor Tile**
MATERIAL LOCATION: **Room 620**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Mastic assoc. W/ 12" x 12" Tan w/ Brown and White Streak Floor Tile**

MATERIAL LOCATION: **Room 620**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Mastic assoc. W/ 12" x 12" Tan Mottled Floor Tile**

MATERIAL LOCATION: **Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**

ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Mastic assoc. W/ 12" x 12" Tan Mottled Floor Tile**

MATERIAL LOCATION: **Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **91**
MATERIAL DESCRIPTION: **Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring**
MATERIAL LOCATION: **Room 363**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **Mastic Associated w/ Orange, Gray and Beige Vinyl Flooring**

MATERIAL LOCATION: **Room 363**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12" x 12" Tan Mottled Floor Tile**

MATERIAL LOCATION: **Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282, 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**

ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12" x 12" Tan Mottled Floor Tile**

MATERIAL LOCATION: **Room 167, Corridor by 152, 233, 290, 289, 288, 287, 282, 284, 285, 280, 279, 277, 281, 257, 258, 255, 253, 254, 252, 251, 249, 248, 247, 232, 371, 374, 369, 370, 365**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **12" x 12" Dark Red Mottled Floor Tile**
MATERIAL LOCATION: **Library, 236B, 236A 235B, 235C**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **88**
MATERIAL DESCRIPTION: **12" x 12" Dark Red Mottled Floor Tile**
MATERIAL LOCATION: **Library, 236B, 236A 235B, 235C**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **90**
MATERIAL DESCRIPTION: **Orange, Gray and Beige Vinyl Flooring**
MATERIAL LOCATION: **Room 363**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **Orange, Gray and Beige Vinyl Flooring**

MATERIAL LOCATION: **Room 363**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUIDLING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **92**
MATERIAL DESCRIPTION: **Transite lined cabinets**
MATERIAL LOCATION: **Room 352**
MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Transite lined cabinets**

MATERIAL LOCATION: **Room 352**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile w/ Pinholes**
MATERIAL LOCATION: **Room 639, 642, Building B - Floor 1 and 2 Corridor, 619 629, 627, Hoffman Hall, 332**
MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **Yes**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **2' x 2' Ceiling Tile w/ Pinholes**

MATERIAL LOCATION: **Room 639, 642, Building B - Floor 1 and 2 Corridor, 619 629, 627, Hoffman Hall, 332**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Tongue and Groove Wood Flooring**
MATERIAL LOCATION: **616, Quinn Hall, Gym**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form


LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **75**
MATERIAL DESCRIPTION: **Tongue and Groove Wood Flooring**
MATERIAL LOCATION: **616, Quinn Hall, Gym**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Tan and White Mottled Floor Tile**
MATERIAL LOCATION: **Faculty Lounge 141**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **84**
MATERIAL DESCRIPTION: **12" x 12" Tan and White Mottled Floor Tile**
MATERIAL LOCATION: **Faculty Lounge 141**
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **73**
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray and White Streak Floor Tile**
MATERIAL LOCATION: **Room 612, 613, 332**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates 2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ Gray and White Streak Floor Tile**

MATERIAL LOCATION: **Room 612, 613, 332**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Mastic assoc. W/12" x 12" Light Gray w/ Gray and White Streak Floor Tile**

MATERIAL LOCATION: **Room 612, 613, 332**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____

Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **74**
MATERIAL DESCRIPTION: **Mastic assoc. W/12" x 12" Light Gray w/ Gray and White Streak Floor Tile**
MATERIAL LOCATION: **Room 612, 613, 332**
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **76**
MATERIAL DESCRIPTION: **12" x 12" Tan w/ Brown and White Streak Floor Tile**
MATERIAL LOCATION: **Room 620**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Brown and White Streak Floor Tile**

MATERIAL LOCATION: **Room 620**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS:

SF

DAMAGE QUANTITY: **0**

DAMAGE UNITS:

SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Brown Mottled Floor Tile**

MATERIAL LOCATION: **Building B - First Floor Corridor**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____



Date: **09/20/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Mastic for 12" x 12" Brown Mottled Floor Tile**

MATERIAL LOCATION: **Building B - First Floor Corridor**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Speck Floor Tile**

MATERIAL LOCATION: **Room 154, Hall by 195, 197, Hall by 2nd Floor Lockers Building A, 237, 239/242 Offices, 2nd Floor East Corridor, 235E, 245, 244, 243, Basement Corridor**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC** FRIABLE: **No**

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW** CONDITION: **Damaged**

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

COMMENTS:
Damage in Basement Corridor

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**

ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Speck Floor Tile**

MATERIAL LOCATION: **Room 154, Hall by 195, 197, Hall by 2nd Floor Lockers Building A, 237, 239/242 Offices, 2nd Floor East Corridor, 235E, 245, 244, 243, Basement Corridor**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Joshua Karlson**
SCHOOL NAME: **Curie Metro High School** INSPECTION DATE: **9/20/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Peach Mottled Floor Tile**
MATERIAL LOCATION: **Library, 236B, 236A, 235B, 235C**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____



Date: 09/20/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form


LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **86**
MATERIAL DESCRIPTION: **12" x 12" Peach Mottled Floor Tile**
MATERIAL LOCATION: **Library, 236B, 236A, 235B, 235C**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **09/30/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **53101** BUILDING ID: **1820**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Curie Metro High School** REVIEW DATE: **9/30/2022**
ADDRESS: **4959 S. Archer** IDPH LICENSE NO: **100-20129**

HOMOGENEOUS AREA: **87**
MATERIAL DESCRIPTION: **12" x 12" Dark Blue Mottled Floor Tile**
MATERIAL LOCATION: **Library 236B, 236A, 235B, 235C**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: **09/30/2022**

APPENDIX B

Inspector and Management Planner Licenses



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Joshua Karlson

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/8/2022

Exam Date: 4/8/2022

Expiration Date: 4/8/2023

Certificate Number: BIR2204081028

Kathy DeSalvo, Director



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER

100 - 20129

ISSUED

4/15/2022

EXPIRES

05/15/2023

**JOSHUA E KARLSON
15504 S LAVERGNE AVE
OAK FOREST, IL 60452**

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

4/8/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed