

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2225  
SCHOOL NAME: Grant School  
ADDRESS OF SCHOOL: 145 S. Campbell  
CITY: Chicago, IL, 60612

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **5/9/2019**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/7/2022 ENROLLMENT 445  
IDPH INSPECTOR LICENSE NUMBER: 100-20411  
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel  
IDPH MP LICENSE NUMBER: 100-19466  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074



7/14/2022

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Grant School**

145 S. Campbell  
Chicago, IL, 60612

Unit: 55011  
Building ID: 3610

IDPH ID Number: 14-016-2990-2225

**REPORT DATE:**

Thursday, July 14, 2022

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/14/2022

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 31091            Region: 03            IDPH ID: 14-016-2990-2225

School: Grant School            Building ID: 3610

Address: 145 S. Campbell  
Chicago, IL, 60612

Building Contact:            Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/7/2022

Review Date: 07/14/2022

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Evan Christian  
100-19466

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 14, 2022

RE: Grant School, Unit 55011  
145 S. Campbell  
Chicago, IL, 60612

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Grant School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Grant School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Grant School  
Address: 145 S. Campbell  
IDPH ID: 14-016-2990-2225  
Contact:

Unit: 31091  
Chicago, IL, 60612  
Building ID: 3610  
Phone:

Region: 03

### 2. Description of Facility

Original Construction:  
Total Square Footage:  
Current Occupancy: 445

Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant


MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900

Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Benyamen Maradkel


Inspector IDPH license # 100-20411  
Reinspection Date: 7/7/2022

Signature:   
Date: 7/7/2022

### 6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature:   
Date: 07/14/2022

### 7. Review Date: 07/14/2022

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 7/14/2022

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Grant School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3610:

103	Light gray linoleum
11A	12" x 12" Off-White w/Brown Specks Floor Tile
11C	12" x 12" Off-White w/Beige mix Floor Tile
123	12" x 12" Light Blue w/ White Specks Floor Tile
124	Mastic Under 12" x 12" Light Blue w/ White Specks Floor Tile
14G	9" x 9" Light Brown w/mixed Streaks Floor Tile Mastic
17C	12" x 12" Off-White & Beige w/Brown Specks Floor Tile Mastic
96	2" x 2" Brown Ceramic Grout

99

12" x 12" Black w/White Dots Floor Tile

99M

12" x 12" Black w/White Dots Floor Tile Mastic



B. The following new homogenous areas have been identified for Building 3610:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	12" x 12" Blue w/White Spec's Floor Tile
100M	12" x 12" Blue w/White Spec's Floor Tile Mastic
101	12" x 12" Beige Floor Tile
101M	12" x 12" Beige Floor Tile Mastic
103	Light gray linoleum
103M	Light gray linoleum mastic
104	Tan/black terrazzo flooring
105	Light&drk rust ceramic grout
105M	Light & drk. Rust ceramic grout adhesive
106	2" x 2" Brown Ceramic Grout
106M	2" x 2" Brown Ceramic Grout Adhesive
107	12" x 12" Gray w/White Spec's Floor Tile
107M	12" x 12" Gray w/White Spec's Floor Tile Mastic
108	12" x 12" Gray w/Black Spec's Floor Tile
108M	12" x 12" Gray w/Black Spec's Floor Tile Mastic
109	Drk. Brown carpet - adhesive
10A	12" x 12" Off-White w/Brown Specks Floor Tile
10B	12" x 12" Light Green w/off-White Streaks Floor Tile
10D	12" x 12" Light Beige w/off-White Specks Floor Tile
110	Black/tan terrazzo flooring & baseboards
111	2" x 2" Brown Ceramic Grout
111M	2" x 2" Brown Ceramic Grout Adhesive
112	12" x 12" Gray & White Floor Tile
112M	12" x 12" Gray & White Floor Tile Mastic
113	Light gray linoleum
113M	Light gray linoleum adhesive
114	Brown carpet mastic
115	12" x 12" Brown w/White Spec's Floor Tile
115M	12" x 12" Brown w/White Spec's Floor Tile Mastic
116	12" x 12" Black w/White Dots Floor Tile
116M	12" x 12" Black w/White Dots Floor Tile Mastic
117	12" x 12" Black/Maroon Floor Tile
117M	12" x 12" Black/Maroon Floor Tile Mastic
118	12" x 12" White Ceramic Grout
118M	12" x 12" White Ceramic Grout Adhesive
119	12" x 12" Gray w/ White Streaks Floor Tile
119M	12" x 12" Gray w/White Spec's Floor Tile Mastic
11A	12" x 12" Off-White w/Brown Specks Floor Tile
11C	12" x 12" Off-White w/Beige mix Floor Tile
11D	12" x 12" Dark Gray Mix w/Brown & off-White

	Floor Tile
11E	12" x 12" Gray w/Brown & off-White Streaks Floor Tile
120	12" x 12" red w/dark red floor tile
120M	12" x 12" red w/dark red floor tile mastic
121	12" x 12" blue w/dark blue floor tile
121M	12" x 12" blue w/dark blue floor tile mastic
122	Red baseboard
122M	Red baseboard adhesive
123	12" x 12" Light Blue w/ White Specks Floor Tile
124	Mastic Under 12" x 12" Light Blue w/ White Specks Floor Tile
125	12" x 12" Gray w/ Dark Gray Specks Floor Tile
126	Mastic Under 12" x 12" Gray w/ Dark Gray Specks Floor Tile
136	9" x 9" Brown Floor Tile
137	9" x 9" Brown Floor Tile Mastic
138	12" x 12" White Floor Tile
139	12" x 12" White Floor Tile Mastic
31	Corkboard above Blackboards
32	Corkboard Mastic above Blackboards
39	Boiler door backing material
3B	9" x 9" Light Gray w/off-White Streaks Floor Tile
42	Tar-like fiberglass insulation jacket
43	Incinerator Lining Material between Brick & Metal
44	Fiberglass insulation jacket
5C	12" x 12" Light Gray w/Multi-color Streaks Floor Tile
5D	12" x 12" Dark Gray w/mixed Streaks Floor Tile
5E	12" x 12" Off-White w/Brown spcks/Streaks Floor Tile
6C	9" x 9" Gray w/off-White & Brown Streaks Floor Tile
6E	9" x 9" Gray w/White dots Floor Tile
78	Black vinyl baseboard
7A	9" x 9" Gray w/off-White & Brown Streaks Floor Tile
85	Incinerator interior refractory materials
86	Interior smoke stack lining
87	Roofing materials - non- ahera
88	Roofing Materials - Non-AHERA
89	Roofing materials - non ahera
91	Fire door insulation
96	2" x 2" Brown Ceramic Grout
96M	2" x 2" Brown Ceramic Grout Adhesive
97	Light & dark green ceramic grout
97M	Light & dark green ceramic grout adhesive
98	Green/black terrazzo flooring

99	12" x 12" Black w/White Dots Floor Tile
99M	12" x 12" Black w/White Dots Floor Tile Mastic
C	Tank packing

The following areas were deemed to be inaccessible:

100M	12" x 12" Blue w/White Spec's Floor Tile Mastic
103M	Light gray linoleum mastic
105M	Light & drk. Rust ceramic grout adhesive
106M	2" x 2" Brown Ceramic Grout Adhesive
107M	12" x 12" Gray w/White Spec's Floor Tile Mastic
108M	12" x 12" Gray w/Black Spec's Floor Tile Mastic
111M	2" x 2" Brown Ceramic Grout Adhesive
112M	12" x 12" Gray & White Floor Tile Mastic
113M	Light gray linoleum adhesive
117M	12" x 12" Black/Maroon Floor Tile Mastic
118M	12" x 12" White Ceramic Grout Adhesive
120M	12" x 12" red w/dark red floor tile mastic
121M	12" x 12" blue w/dark blue floor tile mastic
122M	Red baseboard adhesive
124	Mastic Under 12" x 12" Light Blue w/ White Specks Floor Tile
126	Mastic Under 12" x 12" Gray w/ Dark Gray Specks Floor Tile
14G	9" x 9" Light Brown w/mixed Streaks Floor Tile Mastic
17C	12" x 12" Off-White & Beige w/Brown Specks Floor Tile Mastic
26	Vault door insulation
86	Interior smoke stack lining
91	Fire door insulation
96M	2" x 2" Brown Ceramic Grout Adhesive
97M	Light & dark green ceramic grout adhesive
99M	12" x 12" Black w/White Dots Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Grant School Building 3610 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Acoustical ceiling plaster			1958 Addition - Throughout Building	NO_ACBM	SURFACE								
100	12" x 12" Blue w/White Spec's Floor Tile	1,800	SF	Building 1958 - Room 331 and Building 1953 - Room 318A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
100M	12" x 12" Blue w/White Spec's Floor Tile Mastic	1,800	SF	Building 1958 - Room 331 and Building 1953 - Room 318A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
101	12" x 12" Beige Floor Tile			Building 1958 - Room 333	ASSUMED	MISC								
101M	12" x 12" Beige Floor Tile Mastic			Building 1958 - Room 333	ASSUMED	MISC								
103	Light gray linoleum	1,500	SF	1953 Building - Room 121, 239-237	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
103M	Light gray linoleum mastic	3,100	SF	1953 Building - Room 121, 239-237	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
104	Tan/black terrazzo flooring	1,000	SF	1st, 2nd, 3rd and 4th Floor Stairwell, Landings, Baseboard in Corridors	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
105	Light&drk rust ceramic grout	100	SF	1953 Building - Vestibule	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
105M	Light & drk. Rust ceramic grout adhesive	100	SF	1953 Building - Vestibule	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
106	2" x 2" Brown Ceramic Grout	600	SF	1953 Building - 3rd & 4th Boy's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
106M	2" x 2" Brown Ceramic Grout Adhesive	600	SF	1953 Building - 3rd & 4th Floor Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
107	12" x 12" Gray w/White Spec's Floor Tile	10,100	SF	1953 Building - 1st, 2nd,3rd & 4th Fl. Corridors, Main/Principals Office, Rooms 222,223,221A, 221,121,123,121,226,236,129,125,131, kitchen, 232	ASSUMED	MISC	N	NONE	0	SF	No	Damaged or significantly damaged friable misc. ACBM		LOW
107M	12" x 12" Gray w/White Spec's Floor Tile Mastic	8,000	SF	1953 Building - 1st, 2nd, 3rd & 4th Fl	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors, Main/Principals Office, Rooms 223,221A, 222,322,121,123,121 and 221,236,129,125,131, kitchen, 232										
108	12" x 12" Gray w/Black Spec's Floor Tile	8,300	SF	1953 Building - Rooms 320,321,323,324, 419-425,424,423,224,421,420, 725,723, 721, 720	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
108M	12" x 12" Gray w/Black Spec's Floor Tile Mastic	8,500	SF	1953 Building - Rooms 321,322,123,121,221, 419-425,424,423,224,421,420, 320,325, 725,723,721, 720	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
109	Drk. Brown carpet - adhesive			1953 Building Room 120 Band Room	ASSUMED	MISC								
10A	12" x 12" Off-White w/Brown Specks Floor Tile			1953 Addition - Main Office Bathroom	ASSUMED	MISC								
10B	12" x 12" Light Green w/off-White Streaks Floor Tile			1953 Addition - Principal's Office Entrance, and Basement Rooms 022, 224	ASSUMED	MISC								
10C	12" x 12" Brick Red w/off-White Streaks Floor Tile			1953 Addition - Basement Room 021	CHR	MISC								
10D	12" x 12" Light Beige w/off-White Specks Floor Tile			1953 Addition - Principal's Office	ASSUMED	MISC								
10E	12" x 12" Green w/Multi-color Streaks Floor Tile 226 - NOT VISIBLE			1953 Addition - Rooms 122, 124, Women's Bathroom by 226, 221, 222, 223 and 225	CHR	MISC								
110	Black/tan terrazzo flooring & baseboards	6,000	SF	Building 1925 - 1st, 2nd, 3rd & 4th Floor Stairwells, Landings, Corridors	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
111	2" x 2" Brown Ceramic Grout	1,000	SF	1925 Building - 2nd, 3rd, & 4th Floor Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
111M	2" x 2" Brown Ceramic Grout Adhesive	1,000	SF	1925 Building - 2nd, 3rd, 4th Floor Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
112	12" x 12" Gray & White Floor Tile	9,000	SF	1925 Building - 1st, 2nd, 3rd & 4th Fl Corridors, Walkways, Room 226, and Engineer's Office, 231, 136	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
112M	12" x 12" Gray & White Floor Tile Mastic	9,000	SF	1925 Building - 1st, 2nd, 3rd & 4th Fl. Corridors, Walkways, Room 226, and Engineer's Office, 231	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
113	Light gray linoleum	2,500	SF	1925 Building - Rooms 429, 426 and 427	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
113M	Light gray linoleum adhesive	2,500	SF	1925 Building - Rooms 429, 426 and 427	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
114	Brown carpet mastic			1925 Building - Room 128, Janitors Bathroom, Band Room	ASSUMED	MISC								
115	12" x 12" Brown w/White Spec's Floor Tile		SF	1925 Building - Room 326	ASSUMED	MISC				SF				
115M	12" x 12" Brown w/White Spec's Floor Tile Mastic		SF	1925 Building - Room 326	ASSUMED	MISC				SF				
116	12" x 12" Black w/White Dots Floor Tile			1925 Building - 1st Floor	ASSUMED	MISC								
116M	12" x 12" Black w/White Dots Floor Tile Mastic			1925 Building - Wheel Chair Ramps to 1953 & 1958 Buildings	ASSUMED	MISC								
117	12" x 12" Black/Maroon Floor Tile	50	SF	1925 Building - Engineer Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
117M	12" x 12" Black/Maroon Floor Tile Mastic	300	SF	1925 Building - Engineer Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
118	12" x 12" White Ceramic Grout	36	SF	1925 Building - Engineer Office	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bathroom										
118M	12" x 12" White Ceramic Grout Adhesive	36	SF	1925 Building - Engineer Office Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
119	12" x 12" Gray w/ White Streaks Floor Tile	1,000	SF	1958 Building - 1st, 2nd and 3rd Floor Corridors, Rooms 133, 134, 331, 158 and Cafeteria.	ASSUMED	MISC	N	LOC	10	SF	No	ACBM with the potential for damage	5	LOW
119M	12" x 12" Gray w/White Spec's Floor Tile Mastic			1958 Building - 1st, 2nd, 3rd Floor Corridor, Rooms 133, 134, 331, 158 and Cafeteria	ASSUMED	MISC								
11A	12" x 12" Off-White w/Brown Specks Floor Tile	1,000	SF	1958 Addition - Rooms 134, 333, 335, 2nd Floor Women's Bathroom and 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
11B	12" x 12" Light Green Floor Tile			1958 Addition - Room 134, and 2nd Floor Women's Bathroom	CHR	MISC								
11C	12" x 12" Off-White w/Beige mix Floor Tile	1,000	SF	1958 Addition - Kitchen, 1st Floor Corridor, and Room 131	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
11D	12" x 12" Dark Gray Mix w/Brown & off-White Floor Tile			1958 Addition - Kitchen, 1st Floor Corridor, and Room 131	ASSUMED	MISC								
11E	12" x 12" Gray w/Brown & off-White Streaks Floor Tile			1958 Addition - Throughout Building in patches	ASSUMED	MISC								
120	12" x 12" red w/dark red floor tile	3,070	SF	Gym Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
120M	12" x 12" red w/dark red floor tile mastic	4,070	SF	Gym Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
121	12" x 12" blue w/dark blue floor tile	1,000	SF	Gym Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
121M	12" x 12" blue w/dark blue floor tile mastic	4,070	SF	Gym Hallway	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
122	Red baseboard	250	LF	Gym Hallway	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the		LOW

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
122M	Red baseboard adhesive	250	LF	Gym Hallway	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
123	12" x 12" Light Blue w/ White Specks Floor Tile	37,000	SF	2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
124	Mastic Under 12" x 12" Light Blue w/ White Specks Floor Tile	37,000	SF	2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
125	12" x 12" Gray w/ Dark Gray Specks Floor Tile	1,100	SF	Room 128 (Band room), 239	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
126	Mastic Under 12" x 12" Gray w/ Dark Gray Specks Floor Tile	800	SF	Room 128 (Band room) 239	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
12A	9" x 9" Olive Grn w/Beige & black Streaks Floor Tile Mastic			1925 Building - 3rd Floor Men's Bathroom	ABATED	MISC								
12B	9" x 9" Light Gray w/off-White Streaks Floor Tile Mastic ABATED			1925 Building - 3rd Floor Men's Bathroom	ABATED	MISC								
12C	9" x 9" Light Green w/Multi-color Streaks Floor Tile Mastic ABATED			1925 Building - Basement, 1st, 2nd & 3rd Floor Corridors	ABATED	MISC								
12D	9" x 9" Tan w/Beige & Brown Streaks Floor Tile Mastic ABATED			1925 Building - Basement Room 111	ABATED	MISC								
12E	9" x 9" Choc. Brown w/Beige and Brown Streaks Floor Tile Mastic ABATED			1925 Building - Basement Room 111	ABATED	MISC								
12F	9" x 9" Maroon Floor Tile Mastic			1925 Building - Basement Engineer's Office Area	ABATED	MISC								
12G	9" x 9" Gray w/Multi-colored Streaks Floor Tile Mastic			1925 Building - 1st & 3rd Floor Corridors, 3rd Floor Men's Bathroom, and 1st Floor Janitor's Toilet	CHR	MISC								
136	9" x 9" Brown Floor Tile		SF	2nd and 3rd floor janitor closet	ASSUMED	MISC				SF				
137	9" x 9" Brown Floor Tile Mastic		SF	2nd and 3rd floor janitor closet	ASSUMED	MISC				SF				
138	12" x 12" White Floor Tile		SF	Engineer restroom	ASSUMED	MISC				SF				
139	12" x 12" White Floor Tile Mastic		SF	Engineer restroom	ASSUMED	MISC				SF				





# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18B	Light chocolate brown linoleum mastic (adhesive)			1925 Building - Gym	NO_ACBM	MISC								
19A	Green mix sink top linoleum mastic			1953 Addition - Basement Room 021	NO_ACBM	MISC								
19B	Multi-colored mix linoleum mastic			1953 Addition - Rooms 121 and 123	NO_ACBM	MISC								
20	Sink top linoleum mastic			1958 Addition - Rooms 133, 134, 136	NO_ACBM	MISC								
21	Vibration collar (isolator)			1925 Building - 3rd Floor Fan Room	NO_ACBM	MISC								
22A	Vibration collar (absorbers)			1953 Addition - Basement Fan Room #3	NO_ACBM	MISC								
22B	Vibration collar (absorber)			1958 Addition - 2nd Floor Fan Room	NO_ACBM	MISC								
23	Electrical wiring insulation	10	LF	1925 Building - Assembly Hall Projection Booth	CHR	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
24	Transite			1925 Building - Assembly Hall Projection Booth	NO_ACBM	MISC								
25	Vault insulation		SF	1953 Addition - Main Office	CHR	MISC				SF				
26	Vault door insulation	32	SF	1958 Building - Kitchen Office	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
27	Chocolate colored linoleum			1925 Building - Gym	NO_ACBM	MISC								
28	Chocolate colored linoleum mastic			1925 Building - Gym	NO_ACBM	MISC								
29	Black border terrazzo			1925 Building - 2nd, 3rd and 4th Floor Corridors	CHR	MISC								
2A	Plaster			1953 Addition - Throughout Building	NO_ACBM	SURFACE								
2B	Plaster			1925 Building - Throughout Building	NO_ACBM	SURFACE								
2C	Plaster			1958 Addition - Throughout Building	NO_ACBM	SURFACE								
30	Black border tile mastic		SF	1925 Building - 1st, 2nd and 3rd Floor	CHR	MISC				SF				











# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Streaks Floor Tile ABATED			Floor Corridor										
7E	9" x 9" Light Tan w/off-White & Brown Streaks Floor Tile ABATED			1958 Addition - 3rd Floor Corridor	ABATED	MISC								
7F	9" x 9" Dark Choc. W/off-white streaks floor tile abated			1958 Addition - 2nd & 3rd Floor Women's Bathrooms	ABATED	MISC								
7G	9" x 9" Light Brown w/mixed Streaks Floor Tile	14,000	SF	1958 Addition - Rooms 136, 230-239, 332, 334, 336 and 337, 330, 338, 339, 234, 235	CHR	MISC	N	LOC	34	SF	No	ACBM with potential for significant damage	5	LOW
80	Fan door lining			1958 Addition - 2nd Floor Fan Room	NO_ACBM	MISC								
81	Sink coat (sink bottom caulk)			1958 Addition - Rooms 130, 132, 133, 134, and 136	NO_ACBM	MISC								
82	Exterior joint caulk (wall bridging caulk) Non-AHERA			1958 Addition (wall connecting 1958 Addition to 1925 Building)	CHR	MISC								
83	9" x 9" Light Green w/Beige & black Streaks Floor Tile ABATED			1958 Addition - 1st Floor Women's Bathroom (by Room 136)	ABATED	MISC								
84	9" x 9" Light Green w/Beige & black Streaks Floor Tile Mastic ABATED			1958 Addition - 1st Floor Women's Bathroom (by Room 136)	ABATED	MISC								
85	Incinerator interior refractory materials		SF	Boiler Room	ASSUMED	MISC				SF				
86	Interior smoke stack lining	250	SF	Boiler Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
87	Roofing materials - non- ahera			1925 Building	ASSUMED	MISC								
88	Roofing Materials - Non-AHERA			1953 Addition	ASSUMED	MISC								
89	Roofing materials - non ahera			1958 Addition	ASSUMED	MISC								
8A	Green mix sink top linoleum			1953 Addition - Basement Room 021	NO_ACBM	MISC								
8B	Multi-colored mix linoleum			1953 Addition - Rooms 121, 123	NO_ACBM	MISC								
9	Sink top linoleum			1958 Addition - Rooms 133, 134, 136	NO_ACBM	MISC								
90	Boiler gaskets			1925 Building - Boiler Room	NO_ACBM	MISC								
91	Fire door insulation	32	SF	Basement Boiler	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room								potential for damage		
92	12" x 12" Burgundy Floor Tile ABATED			Lunchroom	ABATED	MISC								
93	12" x 12" Burgundy Floor Tile Mastic ABATED			Lunchroom	ABATED	MISC								
94	Burgundy carpet adhesive abated			1953 Addition - Principal's Office	ABATED	MISC								
95	Gray mix carpet adhesive abated			Computer Room 226	ABATED	MISC								
96	2" x 2" Brown Ceramic Grout	500	LF	1958 Building - 1st, 2nd, 3rd Boy's/ Girl's & Women's Bathroom	ASSUMED	MISC	N	NONE	0	LF	Yes	ACBM with the potential for damage		LOW
96M	2" x 2" Brown Ceramic Grout Adhesive	1,800	SF	1958 Building - 1st, 2nd, 3rd Floor Boy's/ Girl's and Women's Bathroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
97	Light & dark green ceramic grout	400	SF	1958 Building - Entrances (Foyer)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
97M	Light & dark green ceramic grout adhesive	400	SF	1958 Building - Entrances ( Foyer)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
98	Green/black terrazzo flooring	2,000	SF	1958 Building - Stairwell and Landings	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
99	12" x 12" Black w/White Dots Floor Tile	150	SF	1958 Building - Room 152, Storage and Kitchen Office	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
99M	12" x 12" Black w/White Dots Floor Tile Mastic	150	SF	1958 Building - Room 152, Storage, Kitchen Office	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
C	Tank packing	65	LF	boiler room, 1925 bldg	ASSUMED	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Aircell pipe insulation	496	LF	1925 Building - Assembly Hall Store Room, Attic	CHR	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Aircell pipe joint compound	25	LF	1925 Building - Assembly Hall Store Room, Attic	CHR	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Paperwrap pipe insulation	75	LF	1925 Building - Assembly Hall Store Room, BOILER ROOM	CHR	TSI	Y	LOC	4	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
G	Paperwrap pipe insulation joint compound	10	LF	1925 Building - Assembly Hall Store Room	CHR	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
H	Water main packing	15	LF	1925 Building	CHR	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW
K	Joint Compound on Fiberglass Pipe Insulation			1925 Building - Boiler Room	NO_ACBM	TSI								
T	Joint Compound on Fiberglass Pipe Insulation	50	LF	1953 Addition - Fan Room	CHR	TSI	Y	NONE	0	LF	No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>7/7/2022</b>
Inspector Name <b><u>Benyamen Maradkel</u></b>
<b>100-20411</b> <b>5/15/2023</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
1	
100	
100M	
101	Not observed 2022
101M	Not observed 2022
103	Not Observed in Room 121 - 2022
103M	
104	
105	
105M	
106	
106M	
107	
107M	
108	Gray tile not observed in Room 325 - now beige
108M	Gray tile not observed in Room 325 - now beige
109	Not observed 2022
10A	Not observed 2022
10B	Not observed 2022
10C	Not observed 2022
10D	Not observed 2022
10E	Not observed 2022
110	
111	

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
111M	
112	Not observed in Room 327 - hardwood
112M	Not observed in Room 327 - hardwood
113	
113M	
114	Not observed 2022
115	Not observed 2022 - Hardwood
115M	Not observed 2022 - Hardwood
116	Not observed 2022
116M	Not observed 2022
117	
117M	
118	
118M	
119	Damage found in Cafeteria, not observed in Room 331
119M	Not observed 2022
11A	
11B	Not observed 2022
11C	Not observed in Room 131, kitchen
11D	Not observed 2022
11E	Not observed 2022
120	
120M	
121	
121M	
122	
122M	
123	Not observed on wheel chair ramp
124	Not observed on wheel chair ramp

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
125	
126	
12A	
12B	
12C	
12D	
12E	
12F	
12G	Not observed 2022
136	Not observed 2022
137	Not observed 2022
138	Not observed 2022 - has ceramic
139	Not observed 2022 - has ceramic
13A	
13B	Not observed 2022
13C	Not observed 2022
13D	Not observed 2022
13E	Not observed 2022
13F	
14A	Not observed 2022
14B	Not observed 2022
14C	Not observed 2022
14D	Not observed 2022
14E	Not observed 2022
14F	Not observed 2022
14G	
15A	
15B	Not observed 2022
15C	



# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
15D	
15E	Not observed 2022
16A	Not observed 2022
16B	Not observed 2022
16C	Not observed 2022
16D	
16E	Not observed 2022
17A	Not observed 2022
17B	Not observed 2022
17C	
17D	
17E	
18A	
18B	
19A	
19B	
20	
21	
22A	
22B	
23	
24	
25	Not observed 2022
26	
27	
28	
29	Not observed 2022
2A	
2B	

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
2C	
30	Not observed 2022
31	Not observed 2022
32	Not observed 2022
33	
34	
35	
36	
37	
38	
39	
3A	
3B	Not observed 2022
3C	
3D	
3E	
3F	
3G	
40	
41	
42	No access 2022
43	Not observed 2022
44	No access 2022
45	
46	
47	
48	
49	
4A	

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
4B	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
5A	
5B	Not observed 2022
5C	Not observed 2022
5D	Not observed 2022
5E	Not observed 2022
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
6A	
6B	Not observed 2022
6C	Not observed 2022

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
6D	Not observed 2022
6E	Not observed 2022
6F	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
7A	Not observed 2022
7B	
7C	
7D	
7E	
7F	
7G	Not observed in 239, 133 - 2022. Damage in Room 334
80	
81	
82	
83	
84	
85	Not observed 2022
86	Inaccessible 2022
87	
88	

# Chicago Public Schools

School Grant School Unit 31091 Building ID 3610

Address 145 S. Campbell Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
89	
8A	
8B	
9	
90	
91	
92	
93	
94	
95	
96	
96M	
97	
97M	
98	
99	
99M	
C	
D	
E	
F	Damage in boiler room
G	
H	
K	
T	

# Chicago Public Schools

**School** Grant School **Unit** 31091 **Building ID** 3610

**Address** 145 S. Campbell **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Acoustical ceiling plaster			1958 Addition - Throughout Building	No ACBM	SURFACE					
100	12" x 12" Blue w/White Spec's Floor Tile	1,800	SF	Building 1958 - Room 331 and Building 1953 - Room 318A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100M	12" x 12" Blue w/White Spec's Floor Tile Mastic	1,800	SF	Building 1958 - Room 331 and Building 1953 - Room 318A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Beige Floor Tile			Building 1958 - Room 333	Assumed	MISC					Follow O&M Plan
101M	12" x 12" Beige Floor Tile Mastic			Building 1958 - Room 333	Assumed	MISC					Follow O&M Plan
103	Light gray linoleum	1,500	SF	1953 Building - Room 121, 239-237	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103M	Light gray linoleum mastic	3,100	SF	1953 Building - Room 121, 239-237	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	Tan/black terrazzo flooring	1,000	SF	1st, 2nd, 3rd and 4th Floor Stairwell, Landings, Baseboard in Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	Light&drk rust ceramic grout	100	SF	1953 Building - Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105M	Light & drk. Rust ceramic grout adhesive	100	SF	1953 Building - Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106	2" x 2" Brown Ceramic Grout	600	SF	1953 Building - 3rd & 4th Boy's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
106M	2" x 2" Brown Ceramic Grout Adhesive	600	SF	1953 Building - 3rd & 4th Floor Boy's Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
107	12" x 12" Gray w/White Spec's Floor Tile	10,100	SF	1953 Building - 1st, 2nd,3rd & 4th Fl. Corridors, Main/Principals Office, Rooms 222,223,221A, 221,121,123,121,226,236,129,125,131, kitchen, 232	Assumed	MISC	No	0	SF	4 Damaged or significantly damaged friable misc. ACBM	Follow O&M Plan
107M	12" x 12" Gray w/White Spec's Floor Tile Mastic	8,000	SF	1953 Building - 1st, 2nd, 3rd & 4th Fl Corridors, Main/Principals Office, Rooms 223,221A,222,322,121,123,121 and 221,236,129,125,131, kitchen, 232	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12" x 12" Gray w/Black Spec's Floor Tile	8,300	SF	1953 Building - Rooms 320,321,323,324, 419-425,424,423,224,421,420, 725,723, 721, 720	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108M	12" x 12" Gray w/Black Spec's Floor Tile Mastic	8,500	SF	1953 Building - Rooms 321,322,123,121,221, 419-425,424,423,224,421,420, 320,325, 725,723,721, 720	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	Drk. Brown carpet - adhesive			1953 Building Room 120 Band Room	Assumed	MISC					Follow O&M Plan
10A	12" x 12" Off-White w/Brown Specks Floor Tile			1953 Addition - Main Office Bathroom	Assumed	MISC					Follow O&M Plan



# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10B	12" x 12" Light Green w/off-White Streaks Floor Tile			1953 Addition - Principal's Office Entrance, and Basement Rooms 022, 224	Assumed	MISC					Follow O&M Plan
10C	12" x 12" Brick Red w/off-White Streaks Floor Tile			1953 Addition - Basement Room 021	Chrysotile	MISC					Follow O&M Plan
10D	12" x 12" Light Beige w/off-White Specks Floor Tile			1953 Addition - Principal's Office	Assumed	MISC					Follow O&M Plan
10E	12" x 12" Green w/Multi-color Streaks Floor Tile226 - NOT VISIBLE			1953 Addition - Rooms 122, 124, Women's Bathroom by 226, 221, 222, 223 and 225	Chrysotile	MISC					Follow O&M Plan
110	Black/tan terrazzo flooring & baseboards	6,000	SF	Building 1925 - 1st, 2nd, 3rd & 4th Floor Stairwells, Landings, Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	2" x 2" Brown Ceramic Grout	1,000	SF	1925 Building - 2nd, 3rd, & 4th Floor Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111M	2" x 2" Brown Ceramic Grout Adhesive	1,000	SF	1925 Building - 2nd, 3rd, 4th Floor Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12" x 12" Gray & White Floor Tile	9,000	SF	1925 Building - 1st, 2nd, 3rd & 4th Fl Corridors, Walkways, Room 226, and Engineer's Office, 231, 136	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112M	12" x 12" Gray & White Floor Tile Mastic	9,000	SF	1925 Building - 1st, 2nd, 3rd & 4th Fl. Corridors, Walkways, Room 226, and Engineer's Office, 231	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	Light gray linoleum	2,500	SF	1925 Building - Rooms 429, 426 and 427	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113M	Light gray linoleum adhesive	2,500	SF	1925 Building - Rooms 429, 426 and 427	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
114	Brown carpet mastic			1925 Building - Room 128, Janitors Bathroom, Band Room	Assumed	MISC					Follow O&M Plan
115	12" x 12" Brown w/White Spec's Floor Tile		SF	1925 Building - Room 326	Assumed	MISC			SF		Follow O&M Plan
115M	12" x 12" Brown w/White Spec's Floor Tile Mastic		SF	1925 Building - Room 326	Assumed	MISC			SF		Follow O&M Plan
116	12" x 12" Black w/White Dots Floor Tile			1925 Building - 1st Floor	Assumed	MISC					Follow O&M Plan
116M	12" x 12" Black w/White Dots Floor Tile Mastic			1925 Building - Wheel Chair Ramps to 1953 & 1958 Buildings	Assumed	MISC					Follow O&M Plan
117	12" x 12" Black/Maroon Floor Tile	50	SF	1925 Building - Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117M	12" x 12" Black/Maroon Floor Tile Mastic	300	SF	1925 Building - Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118	12" x 12" White Ceramic Grout	36	SF	1925 Building - Engineer Office Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
118M	12" x 12" White Ceramic Grout Adhesive	36	SF	1925 Building - Engineer Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Grant School  
Address 145 S. Campbell

Unit 31091  
Chicago, IL, 60612

Building ID 3610  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Bathroom							
119	12" x 12" Gray w/ White Streaks Floor Tile	1,000	SF	1958 Building - 1st, 2nd and 3rd Floor Corridors, Rooms 133, 134, 331, 158 and Cafeteria.	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
119M	12" x 12" Gray w/White Spec's Floor Tile Mastic			1958 Building - 1st, 2nd, 3rd Floor Corridor, Rooms 133, 134, 331, 158 and Cafeteria	Assumed	MISC					Follow O&M Plan
11A	12" x 12" Off-White w/Brown Specks Floor Tile	1,000	SF	1958 Addition - Rooms 134, 333, 335, 2nd Floor Women's Bathroom and 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11B	12" x 12" Light Green Floor Tile			1958 Addition - Room 134, and 2nd Floor Women's Bathroom	Chrysotile	MISC					Follow O&M Plan
11C	12" x 12" Off-White w/Beige mix Floor Tile	1,000	SF	1958 Addition - Kitchen, 1st Floor Corridor, and Room 131	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11D	12" x 12" Dark Gray Mix w/Brown & off-White Floor Tile			1958 Addition - Kitchen, 1st Floor Corridor, and Room 131	Assumed	MISC					Follow O&M Plan
11E	12" x 12" Gray w/Brown & off-White Streaks Floor Tile			1958 Addition - Throughout Building in patches	Assumed	MISC					Follow O&M Plan
120	12" x 12" red w/dark red floor tile	3,070	SF	Gym Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
120M	12" x 12" red w/dark red floor tile mastic	4,070	SF	Gym Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12" x 12" blue w/dark blue floor tile	1,000	SF	Gym Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
121M	12" x 12" blue w/dark blue floor tile mastic	4,070	SF	Gym Hallway	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
122	Red baseboard	250	LF	Gym Hallway	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
122M	Red baseboard adhesive	250	LF	Gym Hallway	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
123	12" x 12" Light Blue w/ White Specks Floor Tile	37,000	SF	2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
124	Mastic Under 12" x 12" Light Blue w/ White Specks Floor Tile	37,000	SF	2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" x 12" Gray w/ Dark Gray Specks Floor Tile	1,100	SF	Room 128 (Band room), 239	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
126	Mastic Under 12" x 12" Gray w/ Dark Gray Specks Floor Tile	800	SF	Room 128 (Band room) 239	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12A	9" x 9" Olive Grn w/Beige & black Streaks Floor Tile Mastic			1925 Building - 3rd Floor Men's Bathroom	Abated	MISC					
12B	9" x 9" Light Gray w/off-White Streaks Floor Tile			1925 Building - 3rd Floor Men's	Abated	MISC					

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic ABATED			Bathroom							
12C	9" x 9" Light Green w/Multi-color Streaks Floor Tile Mastic ABATED			1925 Building - Basement, 1st, 2nd & 3rd Floor Corridors	Abated	MISC					
12D	9" x 9" Tan w/Beige & Brown Streaks Floor Tile Mastic ABATED			1925 Building - Basement Room 111	Abated	MISC					
12E	9" x 9" Choc. Brown w/Beige and Brown Streaks Floor Tile Mastic ABATED			1925 Building - Basement Room 111	Abated	MISC					
12F	9" x 9" Maroon Floor Tile Mastic			1925 Building - Basement Engineer's Office Area	Abated	MISC					Follow O&M Plan
12G	9" x 9" Gray w/Multi-colored Streaks Floor Tile Mastic			1925 Building - 1st & 3rd Floor Corridors, 3rd Floor Men's Bathroom, and 1st Floor Janitor's Toilet	Chrysotile	MISC					Follow O&M Plan
136	9" x 9" Brown Floor Tile		SF	2nd and 3rd floor janitor closet	Assumed	MISC			SF		Follow O&M Plan
137	9" x 9" Brown Floor Tile Mastic		SF	2nd and 3rd floor janitor closet	Assumed	MISC			SF		Follow O&M Plan
138	12" x 12" White Floor Tile		SF	Engineer restroom	Assumed	MISC			SF		Follow O&M Plan
139	12" x 12" White Floor Tile Mastic		SF	Engineer restroom	Assumed	MISC			SF		Follow O&M Plan
13A	9" x 9" Light Green w/Beige & blk Streaks Floor Tile Mastic			1953 Addition - 1st, 2nd & 3rd Floor Corridors	Abated	MISC					
13B	9" x 9" Dark Brown Floor Tile Mastic			1953 Addition - Basement Room 120	Chrysotile	MISC					Follow O&M Plan
13C	9" x 9" Gray w/off-White & Brown Streaks Floor Tile Mastic			1953 Addition - Basement Room 024	Chrysotile	MISC					Follow O&M Plan
13D	9" x 9" Tan w/Beige & tan Streaks Floor Tile Mastic			1953 Building - Basement Room 024	Chrysotile	MISC					Follow O&M Plan
13E	9" x 9" Gray w/White dots Floor Tile Mastic			1953 Addition - Basement Room 023	Chrysotile	MISC					Follow O&M Plan
13F	9" x 9" Green w/Multi-colored Streaks Floor Tile Mastic ABATED			1953 Addition - 1st, 2nd, & 3rd Floor Corridors	Abated	MISC					
14A	9" x 9" Gray w/off-White & Brown Streaks Floor Tile Mastic			1958 Addition - Rooms 136, 235, 236, 238, 331, 334, 338, and 3rd Floor Corridor	Chrysotile	MISC					Follow O&M Plan
14B	9" x 9" Tan w/off-White Streaks Floor Tile Mastic			1958 Addition - 3rd Floor Corridor	Chrysotile	MISC					Follow O&M Plan
14C	9" x 9" Cream w/off-White & Brown Streaks Floor Tile Mastic			1958 Addition - 1st Floor Women's Bathroom, 3rd Floor Corridor and Women's Toilet	Chrysotile	MISC					Follow O&M Plan
14D	9" x 9" Brown w/off-White & Brown Streaks Floor Tile Mastic			1958 Addition - 3rd Floor Corridor	Chrysotile	MISC					Follow O&M Plan
14E	9" x 9" Light Tan w/off-White & Brown Streaks Floor Tile Mastic			1958 Addition - 3rd Floor Corridor	Chrysotile	MISC					Follow O&M Plan

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
14F	9" x 9" Dark Choc. W/off-white streaks floor tile mastic			1958 Addition - 2nd & 3rd Floor Women's Bathrooms	Chrysotile	MISC					Follow O&M Plan
14G	9" x 9" Light Brown w/mixed Streaks Floor Tile Mastic	5,000	SF	1958 Addition - Distributed randomly throughout Building in patches, 2nd & 3rd Floor Facility Bathroom, Room 231,230,233	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15A	12" x 12" Brown mix Floor Tile w/Mastic			130	No ACBM	MISC					
15B	12" x 12" Green mix w/Multi-color Streaks Floor Tile Mastic			1925 Building - Room 104	Chrysotile	MISC					Follow O&M Plan
15C	12" x 12" Light gray w/Multi-color Streaks Floor Tile Mastic			1925 Building - Basement Room 110	No ACBM	MISC					
15D	12" x 12" Dark Gray w/mixed Streaks Floor Tile Mastic			1925 Building - Basement Room 110	No ACBM	MISC					
15E	12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic			1925 Building - 1st & 2nd Floor Corridor	Chrysotile	MISC					Follow O&M Plan
16A	12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic			1953 Addition - Main Office Bathroom	Chrysotile	MISC					Follow O&M Plan
16B	12" x 12" Light Green w/Off-White Streaks Floor Tile Mastic			1953 Addition - Principals Office Entrance, Basement Rooms 022, 024	Chrysotile	MISC					Follow O&M Plan
16C	12" x 12" Brick Red w/Off-White Streaks Floor Tile Mastic			1953 Addition - Basement Room 021	Chrysotile	MISC					Follow O&M Plan
16D	12" x 12" Light Beige w/off-White Specks Floor Tile Mastic			1953 Addition - Principals Office	No ACBM	SURFACE					
16E	12" x 12" Green w/Multi-colored Streaks Floor Tile Mastic			1953 Addition - Rooms 120, Bathroom, Womens Teachers Toilets, Main Office, 221-223, 225, 321-327	Chrysotile	MISC					Follow O&M Plan
17A	12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic			1958 Addition - 3rd Floor Corridor, 2nd Floor Womens Bathroom	Chrysotile	MISC					Follow O&M Plan
17B	12" x 12" Light Green Floor Tile Mastic			1958 Addition - Room 134, and 2nd Floor Womens Bathroom	Chrysotile	MISC					Follow O&M Plan
17C	12" x 12" Off-White & Beige w/Brown Specks Floor Tile Mastic	2,000	SF	1958 Addition - 1st Floor Corridor, Kitchen, and Room 131, 133, 325	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17D	12" x 12" Dark Gray w/Brown & off-White spcks Floor Tile Mastic			1958 Addition - 1st Floor Corridor	Abated	MISC					
17E	12" x 12" Gray w/Brown & off-White Streaks Floor Tile Mastic			1958 Addition - Throughout Building in patches	No ACBM	MISC					

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
18A	Black linoleum mastic (adhesive)			1925 Building - Basement West Corridor	No ACBM	MISC					
18B	Light chocolate brown linoleum mastic (adhesive)			1925 Building - Gym	No ACBM	MISC					
19A	Green mix sink top linoleum mastic			1953 Addition - Basement Room 021	No ACBM	MISC					
19B	Multi-colored mix linoleum mastic			1953 Addition - Rooms 121 and 123	No ACBM	MISC					
20	Sink top linoleum mastic			1958 Addition - Rooms 133, 134, 136	No ACBM	MISC					
21	Vibration collar (isolator)			1925 Building - 3rd Floor Fan Room	No ACBM	MISC					
22A	Vibration collar (absorbers)			1953 Addition - Basement Fan Room #3	No ACBM	MISC					
22B	Vibration collar (absorber)			1958 Addition - 2nd Floor Fan Room	No ACBM	MISC					
23	Electrical wiring insulation	10	LF	1925 Building - Assembly Hall Projection Booth	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
24	Transite			1925 Building - Assembly Hall Projection Booth	No ACBM	MISC					
25	Vault insulation		SF	1953 Addition - Main Office	Chrysotile	MISC			SF		Follow O&M Plan
26	Vault door insulation	32	SF	1958 Building - Kitchen Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Chocolate colored linoleum			1925 Building - Gym	No ACBM	MISC					
28	Chocolate colored linoleum mastic			1925 Building - Gym	No ACBM	MISC					
29	Black border terrazzo			1925 Building - 2nd, 3rd and 4th Floor Corridors	Chrysotile	MISC					Follow O&M Plan
2A	Plaster			1953 Addition - Throughout Building	No ACBM	SURFACE					
2B	Plaster			1925 Building - Throughout Building	No ACBM	SURFACE					
2C	Plaster			1958 Addition - Throughout Building	No ACBM	SURFACE					
30	Black border tile mastic		SF	1925 Building - 1st, 2nd and 3rd Floor Corridors	Chrysotile	MISC			SF		Follow O&M Plan
31	Corkboard above Blackboards			1925 Building - Classrooms Throughout	Assumed	MISC					Follow O&M Plan
32	Corkboard Mastic above Blackboards			1925 Building - Classrooms Throughout	Assumed	MISC					Follow O&M Plan
33	Interior fan door lining			1925 Building - 3rd Floor Fan Room	No ACBM	MISC					
34	Brown vinyl baseboard			1925 Building - 1st, 2nd and 3rd Floor Corridors	No ACBM	MISC					
35	Brown vinyl baseboard mastic (adhesive)			1925 Building - 1st, 2nd and 3rd Floor Corridors	No ACBM	MISC					
36	Black vinyl baseboard			1925 Building - Basement Corridor	No ACBM	MISC					
37	Black vinyl baseboard mastic (adhesive)			1925 Building - Basement Corridor	No ACBM	MISC					
38	9" x 9" Choc. W/beige & brown streaks floor tile			1925 Building - Basement Room 127	Abated	MISC					

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	mastic										
39	Boiler door backing material	20	LF	1925 Building - Basement Boiler Room	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
3A	9" x 9" Olive Green w/Beige & blk Streaks Floor Tile ABATED			1925 Building - 3rd Floor Men's Bathroom	Abated	MISC					
3B	9" x 9" Light Gray w/off-White Streaks Floor Tile			1925 Building - 3rd Floor Men's Bathroom	Assumed	MISC					Follow O&M Plan
3C	9" x 9" Light Green w/Multi-color Streaks Floor Tile ABATED			1925 Building - Basement, 1st and 2nd Floor Corridors	Abated	MISC					
3D	9" x 9" Tan w/Beige & Brown Streaks Floor Tile ABATED			1925 Building - Basement Room 127	Abated	MISC					
3E	9" x 9" Choc. Brown w/Beige & Brown Streaks Floor Tile ABATED			1925 Building - Basement Room 127	Abated	MISC					
3F	9" x 9" Maroon Floor tile ABATED			1925 Building - Basement Engineer's Office Areas	Abated	MISC					
3G	9" x 9" Gray w/Multi-colored Streaks Floor Tile ABATED			1925 Building - 1st & 3rd Floor Corridors, 3rd Floor Men's Bathroom, and 1st Floor Janitors Toilet	Abated	MISC					
40	Interior brick			1925 Building - Basement Corridor	No ACBM	MISC					
41	Interior brick mortar			1925 Building - Basement Corridor	No ACBM	MISC					
42	Tar-like fiberglass insulation jacket			1925 Building - Assembly Hall Crawlspace	Assumed	MISC					Follow O&M Plan
43	Incinerator Lining Material between Brick & Metal			1925 Building - Basement Boiler Room	Assumed	MISC					Follow O&M Plan
44	Fiberglass insulation jacket			1925 Building - Assembly Hall Crawlspace	Assumed	TSI					Follow O&M Plan
45	2' x 4' Lay-in Ceiling Tile			1953 Addition - Basement Room 023,427, 429,426A	No ACBM	MISC					
46	Caulk on metal windows			1925 Building - Throughout Building	No ACBM	MISC					
47	Exterior door caulk			1925 Building	No ACBM	MISC					
48	Exterior joint caulk (bridging caulk) - non ahera			1925 Building	No ACBM	MISC					
49	Exterior brick - non ahera			1925 Building	No ACBM	MISC					
4A	Black linoleum			1925 Building - Basement West Corridor	No ACBM	MISC					
4B	Light chocolate brown linoleum			1925 Building - Gym	No ACBM	MISC					
50	Exterior brick mortar - non ahera			1925 Building	No ACBM	MISC					
51	Interior brick			1953 Addition - Basement	No ACBM	MISC					
52	Interior brick mortar			1953 Addition - Basement	No ACBM	MISC					

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
53	Black vinyl baseboard			1953 Addition - Throughout Building	No ACBM	MISC					
54	Black vinyl baseboard mastic (adhesive)			1953 Addition - Throughout Building	No ACBM	MISC					
55	Door Lining Insulation in Mechanical Units	20	LF	1953 Addition - Basement Fan Areas	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
56	Sheet rock			1953 Addition - Basement Room 024	No ACBM	MISC					
57	Joint Compound of Sheet Rock			1953 Addition - Basement Room 024	No ACBM	MISC					
58	Tar-like covering			1953 Addition - 2nd Floor Fan Room	No ACBM	MISC					
59	Exterior window caulk (metal windows) - non ahera			1953 Addition	Undefined	MISC					Follow O&M Plan
5A	12" x 12" Brown Leopard Print Floor Tile ABATED			1925 Building - 2nd Floor Co-Ed Teachers Bathroom	Abated	MISC					
5B	12" x 12" Green mix w/Multi-color Streaks Floor Tile			1925 Building - Room 104	Chrysotile	MISC					Follow O&M Plan
5C	12" x 12" Light Gray w/Multi-color Streaks Floor Tile			1925 Building - Basement Room 110	Assumed	MISC					Follow O&M Plan
5D	12" x 12" Dark Gray w/mixed Streaks Floor Tile			1925 Building - Basement Room 110	Assumed	MISC					Follow O&M Plan
5E	12" x 12" Off-White w/Brown spcks/Streaks Floor Tile			1925 Building - 1st & 2nd Floor Corridors	Assumed	MISC					Follow O&M Plan
60	Exterior door caulk - non ahera			1953 Addition	Chrysotile	MISC					Follow O&M Plan
61	Exterior joint caulk (bridging) - non ahera			1953 Addition	No ACBM	MISC					
62	Exterior brick - non ahera			1953 Addition	No ACBM	MISC					
63	Exterior brick mortar - non ahera			1953 Addition	No ACBM	MISC					
64	Black vinyl baseboard			1958 Addition - Throughout Building	No ACBM	MISC					
65	Black vinyl baseboard mastic (adhesive)			1958 Addition - Throughout Building	No ACBM	MISC					
66	Interior brick			1958 Addition - Throughout Building	No ACBM	MISC					
67	Interior brick mortar			1958 Addition - Throughout Building	No ACBM	MISC					
68	Corkboard-like Material above Blackboards			1958 Addition - Throughout Classrooms	No ACBM	MISC					
69	Mastic on Corkboard-like Material above Blackboard			1958 Addition - Throughout Classrooms	No ACBM	MISC					
6A	9" x 9" Light Green w/Beige & black Streaks Floor Tile ABATED			1953 Addition - 1st, 2nd and 3rd Floor Corridors	Abated	MISC					
6B	9" x 9" Dark Brown Floor Tile			1953 Addition - Basement Room 024	Chrysotile	MISC					Follow O&M Plan
6C	9" x 9" Gray w/off-White & Brown Streaks Floor Tile			1953 Addition - Basement Room 024	Assumed	MISC					Follow O&M Plan
6D	9" x 9" Tan w/Beige & tan Streaks Floor Tile			1953 Addition - Basement Room 024	Chrysotile	MISC					Follow O&M Plan
6E	9" x 9" Gray w/White dots Floor Tile			1953 Addition - Basement Room 023	Assumed	MISC					Follow O&M Plan
6F	9" x 9" Green w/Multi-colored Streaks Floor Tile ABATED			1953 Addition - 2nd and 3rd Floor Corridors	Abated	MISC					
70	Fiberglass duct insulation jacket			1958 Addition - 2nd Floor Fan Room	No ACBM	TSI					

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
71	Sink coat (sink bottom sealant)			1958 Addition - Room 133, 134, and 136	No ACBM	MISC					
72	Black & brown mix carpet mastic (adhesive)			1958 Addition - Room 133	No ACBM	MISC					
73	Exterior window caulk (metal windows) Non-AHERA			1958 Addition	Chrysotile	MISC					Follow O&M Plan
74	Exterior door caulk - Non-AHERA			1958 Addition	Chrysotile	MISC					Follow O&M Plan
75	Exterior joint caulk (bridging caulk) Non-AHERA			1958 Addition	No ACBM	MISC					
76	Exterior brick - non ahera			1958 Addition	No ACBM	MISC					
77	Exterior brick mortar - non ahera			1958 Addition	No ACBM	MISC					
78	Black vinyl baseboard	15	LF	1953 Addition - Main Office Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
79	Black vinyl baseboard mastic (adhesive)			1953 Addition - Main Office Bathroom	No ACBM	MISC					
7A	9" x 9" Gray w/off-White & Brown Streaks Floor Tile			1958 Addition - Room 136, 235, 236, 238, 331, 334, 338, and 3rd Floor Corridor	Assumed	MISC					Follow O&M Plan
7B	9" x 9" Tan w/off-White Streaks Floor Tile ABATED			1958 Addition - 3rd Floor Corridor	Abated	MISC					
7C	9" x 9" Cream w/off-White & Brown Streaks Floor Tile ABATED			1958 Addition - 1st Floor Women's Bathroom, 3rd Floor Corridor and Women's Toilet	Abated	MISC					
7D	9" x 9" Brown w/off-White & Brown Streaks Floor Tile ABATED			1958 Addition - 3rd Floor Corridor	Abated	MISC					
7E	9" x 9" Light Tan w/off-White & Brown Streaks Floor Tile ABATED			1958 Addition - 3rd Floor Corridor	Abated	MISC					
7F	9" x 9" Dark Choc. W/off-white streaks floor tile abated			1958 Addition - 2nd & 3rd Floor Women's Bathrooms	Abated	MISC					
7G	9" x 9" Light Brown w/mixed Streaks Floor Tile	14,000	SF	1958 Addition - Rooms 136, 230-239, 332, 334, 336 and 337, 330, 338, 339, 234, 235	Chrysotile	MISC	No	34	SF	5 ACBM with potential for significant damage	Repair
80	Fan door lining			1958 Addition - 2nd Floor Fan Room	No ACBM	MISC					
81	Sink coat (sink bottom caulk)			1958 Addition - Rooms 130, 132, 133, 134, and 136	No ACBM	MISC					
82	Exterior joint caulk (wall bridging caulk) Non-AHERA			1958 Addition (wall connecting 1958 Addition to 1925 Building)	Chrysotile	MISC					Follow O&M Plan
83	9" x 9" Light Green w/Beige & black Streaks Floor Tile ABATED			1958 Addition - 1st Floor Women's Bathroom (by Room 136)	Abated	MISC					
84	9" x 9" Light Green w/Beige & black Streaks Floor Tile Mastic ABATED			1958 Addition - 1st Floor Women's Bathroom (by Room 136)	Abated	MISC					



# Chicago Public Schools

School Grant School  
Address 145 S. Campbell

Unit 31091  
Chicago, IL, 60612

Building ID 3610  
Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
85	Incinerator interior refractory materials		SF	Boiler Room	Assumed	MISC			SF		Follow O&M Plan
86	Interior smoke stack lining	250	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Roofing materials - non- ahera			1925 Building	Assumed	MISC					Follow O&M Plan
88	Roofing Materials - Non-AHERA			1953 Addition	Assumed	MISC					Follow O&M Plan
89	Roofing materials - non ahera			1958 Addition	Assumed	MISC					Follow O&M Plan
8A	Green mix sink top linoleum			1953 Addition - Basement Room 021	No ACBM	MISC					
8B	Multi-colored mix linoleum			1953 Addition - Rooms 121, 123	No ACBM	MISC					
9	Sink top linoleum			1958 Addition - Rooms 133, 134, 136	No ACBM	MISC					
90	Boiler gaskets			1925 Building - Boiler Room	No ACBM	MISC					
91	Fire door insulation	32	SF	Basement Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" Burgundy Floor Tile ABATED			Lunchroom	Abated	MISC					
93	12" x 12" Burgundy Floor Tile Mastic ABATED			Lunchroom	Abated	MISC					
94	Burgundy carpet adhesive abated			1953 Addition - Principal's Office	Abated	MISC					
95	Gray mix carpet adhesive abated			Computer Room 226	Abated	MISC					
96	2" x 2" Brown Ceramic Grout	500	LF	1958 Building - 1st, 2nd, 3rd Boy's/ Girl's & Women's Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
96M	2" x 2" Brown Ceramic Grout Adhesive	1,800	SF	1958 Building - 1st, 2nd, 3rd Floor Boy's/ Girl's and Women's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	Light & dark green ceramic grout	400	SF	1958 Building - Entrances (Foyer)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97M	Light & dark green ceramic grout adhesive	400	SF	1958 Building - Entrances ( Foyer)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Green/black terrazzo flooring	2,000	SF	1958 Building - Stairwell and Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12" x 12" Black w/White Dots Floor Tile	150	SF	1958 Building - Room 152, Storage and Kitchen Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99M	12" x 12" Black w/White Dots Floor Tile Mastic	150	SF	1958 Building - Room 152, Storage, Kitchen Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Tank packing	65	LF	boiler room, 1925 bldg	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Aircell pipe insulation	496	LF	1925 Building - Assembly Hall Store Room, Attic	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Aircell pipe joint compound	25	LF	1925 Building - Assembly Hall Store Room, Attic	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Paperwrap pipe insulation	75	LF	1925 Building - Assembly Hall Store Room, BOILER ROOM	Chrysotile	TSI	Yes	4	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Encapsulate
G	Paperwrap pipe insulation joint compound	10	LF	1925 Building - Assembly Hall Store Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
 Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
H	Water main packing	15	LF	1925 Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Joint Compound on Fiberglass Pipe Insulation			1925 Building - Boiler Room	No ACBM	TSI					
T	Joint Compound on Fiberglass Pipe Insulation	50	LF	1953 Addition - Fan Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

HA Number	Management Comments
-----------	---------------------

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
 Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	7/14/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
100	
100M	
101	
101M	
103	
103M	
104	
105	
105M	
106	
106M	
107	
107M	
108	
108M	
109	
10A	
10B	
10C	
10D	
10E	
110	
111	
111M	
112	
112M	

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
 Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
113	
113M	
114	
115	
115M	
116	
116M	
117	
117M	
118	
118M	
119	
119M	
11A	
11B	
11C	
11D	
11E	
120	
120M	
121	
121M	
122	
122M	
123	
124	
125	

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
 Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
126	
12A	
12B	
12C	
12D	
12E	
12F	
12G	
136	
137	
138	
139	
13A	
13B	
13C	
13D	
13E	
13F	
14A	
14B	
14C	
14D	
14E	
14F	
14G	
15A	
15B	

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
15C	
15D	
15E	
16A	
16B	
16C	
16D	
16E	
17A	
17B	
17C	
17D	
17E	
18A	
18B	
19A	
19B	
20	
21	
22A	
22B	
23	
24	
25	
26	
27	
28	

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
29	
2A	
2B	
2C	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	
3B	
3C	
3D	
3E	
3F	
3G	
40	
41	
42	
43	
44	
45	

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
46	
47	
48	
49	
4A	
4B	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
5A	
5B	
5C	
5D	
5E	
60	
61	
62	
63	
64	
65	



# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
 Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
66	
67	
68	
69	
6A	
6B	
6C	
6D	
6E	
6F	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
7A	
7B	
7C	
7D	
7E	
7F	
7G	

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
 Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
8A	
8B	
9	
90	
91	
92	
93	
94	
95	
96	
96M	
97	
97M	
98	
99	
99M	
C	

# Chicago Public Schools

**School** Grant School  
**Address** 145 S. Campbell

**Unit** 31091  
Chicago, IL, 60612

**Building ID** 3610  
**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
D	
E	
F	
G	
H	
K	
T	

# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2022 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**  
MATERIAL DESCRIPTION: **Acoustical ceiling plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Acoustical ceiling plaster**

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/White Spec's Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building 1958 - Room 331 and Building 1953 - Room 318A**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/White Spec's Floor Tile**  
MATERIAL LOCATION: **Building 1958 - Room 331 and Building 1953 - Room 318A**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **100M**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/White Spec's Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building 1958 - Room 331 and Building 1953 - Room 318A**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **100M**  
MATERIAL DESCRIPTION: **12" x 12" Blue w/White Spec's Floor Tile Mastic**  
MATERIAL LOCATION: **Building 1958 - Room 331 and Building 1953 - Room 318A**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building 1958 - Room 333**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**  
MATERIAL LOCATION: **Building 1958 - Room 333**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **101M**  
MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building 1958 - Room 333**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **101M**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Building 1958 - Room 333**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Light gray linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Building - Room 121, 239-237**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not Observed in Room 121 - 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Light gray linoleum**  
MATERIAL LOCATION: **1953 Building - Room 121, 239-237**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **103M**  
MATERIAL DESCRIPTION: **Light gray linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Building - Room 121, 239-237**  
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **103M**  
MATERIAL DESCRIPTION: **Light gray linoleum mastic**  
MATERIAL LOCATION: **1953 Building - Room 121, 239-237**  
MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Tan/black terrazzo flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Floor Stairwell, Landings, Baseboard in Corridors**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **104**  
MATERIAL DESCRIPTION: **Tan/black terrazzo flooring**  
MATERIAL LOCATION: **1st, 2nd, 3rd and 4th Floor Stairwell, Landings, Baseboard in Corridors**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Light&drk rust ceramic grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Building - Vestibule**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **105**  
MATERIAL DESCRIPTION: **Light&drk rust ceramic grout**  
MATERIAL LOCATION: **1953 Building - Vestibule**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105M**  
MATERIAL DESCRIPTION: **Light & drk. Rust ceramic grout adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Building - Vestibule**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **105M**  
MATERIAL DESCRIPTION: **Light & drk. Rust ceramic grout adhesive**  
MATERIAL LOCATION: **1953 Building - Vestibule**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **31091**    BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School**    INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Building - 3rd & 4th Boy's Bathroom**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout**  
MATERIAL LOCATION: **1953 Building - 3rd & 4th Boy's Bathroom**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106M**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building - 3rd & 4th Floor Boy's Bathrooms**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **106M**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout Adhesive**  
MATERIAL LOCATION: **1953 Building - 3rd & 4th Floor Boy's Bathrooms**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/White Spec's Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **4 Damaged or significantly damaged friable misc. ACBM**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **4. Damaged or significantly damaged friable misc. ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building - 1st, 2nd,3rd & 4th Fl. Corridors, Main/Principals Office, Rooms 222,223,221A,221,121,123,121,226,236,129,125,131, kitchen, 232**

MATERIAL QUANTITY: **10100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **107**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/White Spec's Floor Tile**  
MATERIAL LOCATION: **1953 Building - 1st, 2nd,3rd & 4th Fl. Corridors, Main/Principals Office, Rooms 222,223,221A, 221,121,123,121,226,236,129,125,131, kitchen, 232**  
MATERIAL QUANTITY: **10100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **107M**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/White Spec's Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building - 1st, 2nd, 3rd & 4th FI Corridors, Main/Principals Office, Rooms 223,221A,222,322,121,123,121 and 221,236,129,125,131, kitchen, 232**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **107M**

MATERIAL DESCRIPTION: **12" x 12" Gray w/White Spec's Floor Tile Mastic**

MATERIAL LOCATION: **1953 Building - 1st, 2nd, 3rd & 4th Fl Corridors, Main/Principals Office, Rooms 223,221A, 222,322,121,123,121 and 221,236,129,125,131, kitchen, 232**

MATERIAL QUANTITY: **8000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Black Spec's Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building - Rooms 320,321,323,324, 419-425,424,423,224,421,420, 725,723, 721, 720**

MATERIAL QUANTITY: **8300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Gray tile not observed in Room 325 - now beige**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **108**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Black Spec's Floor Tile**  
MATERIAL LOCATION: **1953 Building - Rooms 320,321,323,324, 419-425,424,423,224,421,420, 725,723, 721, 720**  
MATERIAL QUANTITY: **8300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **108M**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Black Spec's Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Building - Rooms 321,322,123,121,221, 419-425,424,423,224,421,420, 320,325, 725,723,721, 720**

MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Gray tile not observed in Room 325 - now beige**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **108M**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Black Spec's Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Building - Rooms 321,322,123,121,221, 419-425,424,423,224,421,420, 320,325, 725,723,721, 720**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Drk. Brown carpet - adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building Room 120 Band Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **109**  
MATERIAL DESCRIPTION: **Drk. Brown carpet - adhesive**  
MATERIAL LOCATION: **1953 Building Room 120 Band Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10A**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**

MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/off-White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Principal's Office Entrance, and Basement Rooms 022, 224**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **10B**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/off-White Streaks Floor Tile**  
MATERIAL LOCATION: **1953 Addition - Principal's Office Entrance, and Basement Rooms 022, 224**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10C**  
MATERIAL DESCRIPTION: **12" x 12" Brick Red w/off-White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 021**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **10C**

MATERIAL DESCRIPTION: **12" x 12" Brick Red w/off-White Streaks Floor Tile**

MATERIAL LOCATION: **1953 Addition - Basement Room 021**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10D**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/off-White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **10D**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/off-White Specks Floor Tile**

MATERIAL LOCATION: **1953 Addition - Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10E**  
MATERIAL DESCRIPTION: **12" x 12" Green w/Multi-color Streaks Floor Tile226 - NOT VISIBLE**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Rooms 122, 124, Women's Bathroom by 226, 221, 222, 223 and 225**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **10E**  
MATERIAL DESCRIPTION: **12" x 12" Green w/Multi-color Streaks Floor Tile226 - NOT VISIBLE**  
MATERIAL LOCATION: **1953 Addition - Rooms 122, 124, Women's Bathroom by 226, 221, 222, 223 and 225**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Black/tan terrazzo flooring & baseboards**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Building 1925 - 1st, 2nd, 3rd & 4th Floor Stairwells, Landings, Corridors**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **110**  
MATERIAL DESCRIPTION: **Black/tan terrazzo flooring & baseboards**  
MATERIAL LOCATION: **Building 1925 - 1st, 2nd, 3rd & 4th Floor Stairwells, Landings, Corridors**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - 2nd, 3rd, & 4th Floor Bathrooms**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **111**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout**  
MATERIAL LOCATION: **1925 Building - 2nd, 3rd, & 4th Floor Bathrooms**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **111M**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - 2nd, 3rd, 4th Floor Bathrooms**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **111M**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout Adhesive**  
MATERIAL LOCATION: **1925 Building - 2nd, 3rd, 4th Floor Bathrooms**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12" x 12" Gray & White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building - 1st, 2nd, 3rd & 4th Fl Corridors, Walkways, Room 226, and Engineer's Office, 231, 136**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 327 - hardwood**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **112**  
MATERIAL DESCRIPTION: **12" x 12" Gray & White Floor Tile**  
MATERIAL LOCATION: **1925 Building - 1st, 2nd, 3rd & 4th FI Corridors, Walkways, Room 226, and Engineer's Office, 231, 136**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **112M**  
MATERIAL DESCRIPTION: **12" x 12" Gray & White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building - 1st, 2nd, 3rd & 4th Fl. Corridors, Walkways, Room 226, and Engineer's Office, 231**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 327 - hardwood**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **112M**  
MATERIAL DESCRIPTION: **12" x 12" Gray & White Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - 1st, 2nd, 3rd & 4th Fl. Corridors, Walkways, Room 226, and Engineer's Office, 231**  
MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **Light gray linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - Rooms 429, 426 and 427**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **113**  
MATERIAL DESCRIPTION: **Light gray linoleum**  
MATERIAL LOCATION: **1925 Building - Rooms 429, 426 and 427**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **113M**  
MATERIAL DESCRIPTION: **Light gray linoleum adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building - Rooms 429, 426 and 427**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **113M**  
MATERIAL DESCRIPTION: **Light gray linoleum adhesive**  
MATERIAL LOCATION: **1925 Building - Rooms 429, 426 and 427**  
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Brown carpet mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Room 128, Janitors Bathroom, Band Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **114**  
MATERIAL DESCRIPTION: **Brown carpet mastic**  
MATERIAL LOCATION: **1925 Building - Room 128, Janitors Bathroom, Band Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Spec's Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Room 326**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022 - Hardwood**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **115**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Spec's Floor Tile**  
MATERIAL LOCATION: **1925 Building - Room 326**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **115M**  
MATERIAL DESCRIPTION: **12" x 12" Brown w/White Spec's Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Room 326**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022 - Hardwood**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **115M**

MATERIAL DESCRIPTION: **12" x 12" Brown w/White Spec's Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building - Room 326**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116**  
MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile**

MATERIAL LOCATION: **1925 Building - 1st Floor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **116M**  
MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Wheel Chair Ramps to 1953 & 1958 Buildings**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **116M**

MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building - Wheel Chair Ramps to 1953 & 1958 Buildings**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12" x 12" Black/Maroon Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building - Engineer Office**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **117**  
MATERIAL DESCRIPTION: **12" x 12" Black/Maroon Floor Tile**  
MATERIAL LOCATION: **1925 Building - Engineer Office**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **117M**  
MATERIAL DESCRIPTION: **12" x 12" Black/Maroon Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building - Engineer Office**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **117M**  
MATERIAL DESCRIPTION: **12" x 12" Black/Maroon Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - Engineer Office**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **31091**    BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School**    INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12" x 12" White Ceramic Grout**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building - Engineer Office Bathroom**

MATERIAL QUANTITY: **36**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **118**  
MATERIAL DESCRIPTION: **12" x 12" White Ceramic Grout**  
MATERIAL LOCATION: **1925 Building - Engineer Office Bathroom**  
MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **118M**  
MATERIAL DESCRIPTION: **12" x 12" White Ceramic Grout Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building - Engineer Office Bathroom**

MATERIAL QUANTITY: **36**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **118M**  
MATERIAL DESCRIPTION: **12" x 12" White Ceramic Grout Adhesive**  
MATERIAL LOCATION: **1925 Building - Engineer Office Bathroom**  
MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Building - 1st, 2nd and 3rd Floor Corridors, Rooms 133, 134, 331, 158 and Cafeteria.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Damage found in Cafeteria, not observed in Room 331**

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **119**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile**  
MATERIAL LOCATION: **1958 Building - 1st, 2nd and 3rd Floor Corridors, Rooms 133, 134, 331, 158 and Cafeteria.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **119M**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/White Spec's Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Building - 1st, 2nd, 3rd Floor Corridor, Rooms 133, 134, 331, 158 and Cafeteria**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **119M**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/White Spec's Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Building - 1st, 2nd, 3rd Floor Corridor, Rooms 133, 134, 331, 158 and Cafeteria**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958 Addition - Rooms 134, 333, 335, 2nd Floor Women's Bathroom and 3rd Floor Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **11A**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **1958 Addition - Rooms 134, 333, 335, 2nd Floor Women's Bathroom and 3rd Floor Corridor**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11B**  
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Room 134, and 2nd Floor Women's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **11B**

MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile**

MATERIAL LOCATION: **1958 Addition - Room 134, and 2nd Floor Women's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 31091    BUIDLING ID: 3610  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Grant School    INSPECTION DATE: 7/7/2022  
ADDRESS: 145 S. Campbell    IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11C  
MATERIAL DESCRIPTION: 12" x 12" Off-White w/Beige mix Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Assumed    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958 Addition - Kitchen, 1st Floor Corridor, and Room 131**

MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**

DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 131, kitchen**

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **11C**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Beige mix Floor Tile**  
MATERIAL LOCATION: **1958 Addition - Kitchen, 1st Floor Corridor, and Room 131**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mix w/Brown & off-White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Kitchen, 1st Floor Corridor, and Room 131**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **11D**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray Mix w/Brown & off-White Floor Tile**  
MATERIAL LOCATION: **1958 Addition - Kitchen, 1st Floor Corridor, and Room 131**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **31091**    BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School**    INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11E**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & off-White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building in patches**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **11E**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & off-White Streaks Floor Tile**  
MATERIAL LOCATION: **1958 Addition - Throughout Building in patches**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12" x 12" red w/dark red floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym Hallway**

MATERIAL QUANTITY: **3070**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **120**  
MATERIAL DESCRIPTION: **12" x 12" red w/dark red floor tile**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **3070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **120M**  
MATERIAL DESCRIPTION: **12" x 12" red w/dark red floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym Hallway**

MATERIAL QUANTITY: **4070**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **120M**  
MATERIAL DESCRIPTION: **12" x 12" red w/dark red floor tile mastic**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **4070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12" x 12" blue w/dark blue floor tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **121**  
MATERIAL DESCRIPTION: **12" x 12" blue w/dark blue floor tile**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **121M**  
MATERIAL DESCRIPTION: **12" x 12" blue w/dark blue floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **4070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **121M**  
MATERIAL DESCRIPTION: **12" x 12" blue w/dark blue floor tile mastic**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **4070** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Red baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **122**  
MATERIAL DESCRIPTION: **Red baseboard**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **122M**  
MATERIAL DESCRIPTION: **Red baseboard adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **122M**  
MATERIAL DESCRIPTION: **Red baseboard adhesive**  
MATERIAL LOCATION: **Gym Hallway**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722**  
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed on wheel chair ramp**

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **123**  
MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ White Specks Floor Tile**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722**  
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Light Blue w/ White Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722**  
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Not observed on wheel chair ramp**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **124**  
MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Light Blue w/ White Specks Floor Tile**  
MATERIAL LOCATION: **2nd, 3rd, and 4th Floor Corridors, Wheel Chair Ramps, Room 120, 724, 722**  
MATERIAL QUANTITY: **37000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 128 (Band room), 239**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **125**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray Specks Floor Tile**  
MATERIAL LOCATION: **Room 128 (Band room), 239**  
MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Gray w/ Dark Gray Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 128 (Band room) 239**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **126**  
MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Gray w/ Dark Gray Specks Floor Tile**  
MATERIAL LOCATION: **Room 128 (Band room) 239**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **9" x 9" Olive Grn w/Beige & black Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12A**  
MATERIAL DESCRIPTION: **9" x 9" Olive Grn w/Beige & black Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **9" x 9" Light Gray w/off-White Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12B**  
MATERIAL DESCRIPTION: **9" x 9" Light Gray w/off-White Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12C**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Multi-color Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement, 1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12C**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Multi-color Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1925 Building - Basement, 1st, 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12D**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & Brown Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12D**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & Brown Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1925 Building - Basement Room 111**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12E**  
MATERIAL DESCRIPTION: **9" x 9" Choc. Brown w/Beige and Brown Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12E**  
MATERIAL DESCRIPTION: **9" x 9" Choc. Brown w/Beige and Brown Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1925 Building - Basement Room 111**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12F**  
MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Engineer's Office Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12F**  
MATERIAL DESCRIPTION: **9" x 9" Maroon Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - Basement Engineer's Office Area**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12G**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/Multi-colored Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st & 3rd Floor Corridors, 3rd Floor Men's Bathroom, and 1st Floor Janitor's Toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **12G**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/Multi-colored Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - 1st & 3rd Floor Corridors, 3rd Floor Men's Bathroom, and 1st Floor Janitor's Toilet**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd floor janitor closet**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **136**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**  
MATERIAL LOCATION: **2nd and 3rd floor janitor closet**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd floor janitor closet**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **137**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**  
MATERIAL LOCATION: **2nd and 3rd floor janitor closet**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with potential for significant damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer restroom**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022 - has ceramic**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **138**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**  
MATERIAL LOCATION: **Engineer restroom**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer restroom**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022 - has ceramic**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **139**  
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**  
MATERIAL LOCATION: **Engineer restroom**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & blk Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - 1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **13A**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & blk Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - 1st, 2nd & 3rd Floor Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13B**  
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **13B**  
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - Basement Room 120**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13C**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **13C**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - Basement Room 024**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13D**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & tan Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Building - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **13D**

MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & tan Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1953 Building - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13E**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/White dots Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 023**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **13E**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/White dots Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - Basement Room 023**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13F**  
MATERIAL DESCRIPTION: **9" x 9" Green w/Multi-colored Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - 1st, 2nd, & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **13F**  
MATERIAL DESCRIPTION: **9" x 9" Green w/Multi-colored Streaks Floor Tile Mastic ABATED**  
MATERIAL LOCATION: **1953 Addition - 1st, 2nd, & 3rd Floor Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Rooms 136, 235, 236, 238, 331, 334, 338, and 3rd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14A**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - Rooms 136, 235, 236, 238, 331, 334, 338, and 3rd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14B**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/off-White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14B**

MATERIAL DESCRIPTION: **9" x 9" Tan w/off-White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 31091    BUILDING ID: 3610  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Grant School    INSPECTION DATE: 7/7/2022  
ADDRESS: 145 S. Campbell    IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14C  
MATERIAL DESCRIPTION: 9" x 9" Cream w/off-White & Brown Streaks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Addition - 1st Floor Women's Bathroom, 3rd Floor Corridor and Women's Toilet

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS: Not observed 2022

Inspector's Signature:



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14C**  
MATERIAL DESCRIPTION: **9" x 9" Cream w/off-White & Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - 1st Floor Women's Bathroom, 3rd Floor Corridor and Women's Toilet**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14D**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/off-White & Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14D**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/off-White & Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14E**  
MATERIAL DESCRIPTION: **9" x 9" Light Tan w/off-White & Brown Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14E**  
MATERIAL DESCRIPTION: **9" x 9" Light Tan w/off-White & Brown Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14F**  
MATERIAL DESCRIPTION: **9" x 9" Dark Choc. W/off-white streaks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 2nd & 3rd Floor Women's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14F**  
MATERIAL DESCRIPTION: **9" x 9" Dark Choc. W/off-white streaks floor tile mastic**  
MATERIAL LOCATION: **1958 Addition - 2nd & 3rd Floor Women's Bathrooms**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14G**  
MATERIAL DESCRIPTION: **9" x 9" Light Brown w/mixed Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958 Addition - Distributed randomly throughout Building in patches, 2nd & 3rd Floor Facility Bathroom, Room 231,230,233**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **14G**  
MATERIAL DESCRIPTION: **9" x 9" Light Brown w/mixed Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - Distributed randomly throughout Building in patches, 2nd & 3rd Floor Facility Bathroom, Room 231,230,233**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15A**  
MATERIAL DESCRIPTION: **12" x 12" Brown mix Floor Tile w/Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **15A**

MATERIAL DESCRIPTION: **12" x 12" Brown mix Floor Tile w/Mastic**

MATERIAL LOCATION: **130**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **12" x 12" Green mix w/Multi-color Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **15B**  
MATERIAL DESCRIPTION: **12" x 12" Green mix w/Multi-color Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - Room 104**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15C**  
MATERIAL DESCRIPTION: **12" x 12" Light gray w/Multi-color Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **15C**  
MATERIAL DESCRIPTION: **12" x 12" Light gray w/Multi-color Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - Basement Room 110**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15D**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/mixed Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **15D**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/mixed Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building - Basement Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15E**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st & 2nd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **15E**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building - 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **16A**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16B**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/Off-White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Principals Office Entrance, Basement Rooms 022, 024**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **16B**  
MATERIAL DESCRIPTION: **12" x 12" Light Green w/Off-White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - Principals Office Entrance, Basement Rooms 022, 024**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16C**  
MATERIAL DESCRIPTION: **12" x 12" Brick Red w/Off-White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 021**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **16C**

MATERIAL DESCRIPTION: **12" x 12" Brick Red w/Off-White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1953 Addition - Basement Room 021**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16D**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/off-White Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Principals Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **16D**  
MATERIAL DESCRIPTION: **12" x 12" Light Beige w/off-White Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - Principals Office**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16E**  
MATERIAL DESCRIPTION: **12" x 12" Green w/Multi-colored Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Rooms 120, Bathroom, Womens Teachers Toilets, Main Office, 221-223, 225, 321-327**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **16E**  
MATERIAL DESCRIPTION: **12" x 12" Green w/Multi-colored Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1953 Addition - Rooms 120, Bathroom, Womens Teachers Toilets, Main Office, 221-223, 225, 321-327**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor, 2nd Floor Womens Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **17A**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown Specks/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor, 2nd Floor Womens Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17B**  
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Room 134, and 2nd Floor Womens Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **17B**  
MATERIAL DESCRIPTION: **12" x 12" Light Green Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - Room 134, and 2nd Floor Womens Bathroom**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools    UNIT NUMBER: 31091    BUILDING ID: 3610  
CITY/STATE: Chicago, Illinois    AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Grant School    INSPECTION DATE: 7/7/2022  
ADDRESS: 145 S. Campbell    IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17C  
MATERIAL DESCRIPTION: 12" x 12" Off-White & Beige w/Brown Specks Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY 6  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Chrysotile    FRIABLE: No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958 Addition - 1st Floor Corridor, Kitchen, and Room 131, 133, 325**

MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**

DAMAGE QUANTITY:    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **17C**  
MATERIAL DESCRIPTION: **12" x 12" Off-White & Beige w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - 1st Floor Corridor, Kitchen, and Room 131, 133, 325**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17D**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/Brown & off-White spcks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

---

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **17D**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/Brown & off-White spcks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - 1st Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17E**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & off-White Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building in patches**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **17E**  
MATERIAL DESCRIPTION: **12" x 12" Gray w/Brown & off-White Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Addition - Throughout Building in patches**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **Black linoleum mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement West Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18A**  
MATERIAL DESCRIPTION: **Black linoleum mastic (adhesive)**  
MATERIAL LOCATION: **1925 Building - Basement West Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18B**  
MATERIAL DESCRIPTION: **Light chocolate brown linoleum mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **18B**

MATERIAL DESCRIPTION: **Light chocolate brown linoleum mastic (adhesive)**

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **Green mix sink top linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 021**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **19A**  
MATERIAL DESCRIPTION: **Green mix sink top linoleum mastic**  
MATERIAL LOCATION: **1953 Addition - Basement Room 021**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19B**  
MATERIAL DESCRIPTION: **Multi-colored mix linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Rooms 121 and 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **19B**

MATERIAL DESCRIPTION: **Multi-colored mix linoleum mastic**

MATERIAL LOCATION: **1953 Addition - Rooms 121 and 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **Sink top linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Rooms 133, 134, 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Sink top linoleum mastic**

MATERIAL LOCATION: **1958 Addition - Rooms 133, 134, 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **Vibration collar (isolator)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 3rd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Vibration collar (isolator)**

MATERIAL LOCATION: **1925 Building - 3rd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22A**  
MATERIAL DESCRIPTION: **Vibration collar (absorbers)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Fan Room #3**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **Vibration collar (absorbers)**

MATERIAL LOCATION: **1953 Addition - Basement Fan Room #3**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22B**  
MATERIAL DESCRIPTION: **Vibration collar (absorber)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **22B**

MATERIAL DESCRIPTION: **Vibration collar (absorber)**

MATERIAL LOCATION: **1958 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Electrical wiring insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Projection Booth**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **Electrical wiring insulation**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Projection Booth**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **Transite**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Assembly Hall Projection Booth**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Transite**

MATERIAL LOCATION: **1925 Building - Assembly Hall Projection Booth**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Vault insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Main Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Vault insulation**

MATERIAL LOCATION: **1953 Addition - Main Office**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Vault door insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Building - Kitchen Office**  
MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Vault door insulation**

MATERIAL LOCATION: **1958 Building - Kitchen Office**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **Chocolate colored linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Chocolate colored linoleum**

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **Chocolate colored linoleum mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Chocolate colored linoleum mastic**

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **Black border terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 2nd, 3rd and 4th Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Black border terrazzo**

MATERIAL LOCATION: **1925 Building - 2nd, 3rd and 4th Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2A**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1953 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1925 Building - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2C**  
MATERIAL DESCRIPTION: **Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **2C**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Black border tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **Black border tile mastic**  
MATERIAL LOCATION: **1925 Building - 1st, 2nd and 3rd Floor Corridors**  
MATERIAL QUANTITY: MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **Corkboard above Blackboards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Classrooms Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Corkboard above Blackboards**

MATERIAL LOCATION: **1925 Building - Classrooms Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Corkboard Mastic above Blackboards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Classrooms Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Corkboard Mastic above Blackboards**

MATERIAL LOCATION: **1925 Building - Classrooms Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Interior fan door lining**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 3rd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Interior fan door lining**

MATERIAL LOCATION: **1925 Building - 3rd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Brown vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Brown vinyl baseboard**

MATERIAL LOCATION: **1925 Building - 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Brown vinyl baseboard mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Brown vinyl baseboard mastic (adhesive)**

MATERIAL LOCATION: **1925 Building - 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Black vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Black vinyl baseboard**

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **31091**    BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School**    INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **31091**    BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School**    INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **9" x 9" Choc. W/beige & brown streaks floor tile mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **9" x 9" Choc. W/beige & brown streaks floor tile mastic**

MATERIAL LOCATION: **1925 Building - Basement Room 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Boiler door backing material**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - Basement Boiler Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **Boiler door backing material**  
MATERIAL LOCATION: **1925 Building - Basement Boiler Room**  
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**  
MATERIAL DESCRIPTION: **9" x 9" Olive Green w/Beige & blk Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3A**

MATERIAL DESCRIPTION: **9" x 9" Olive Green w/Beige & blk Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3B**  
MATERIAL DESCRIPTION: **9" x 9" Light Gray w/off-White Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3B**

MATERIAL DESCRIPTION: **9" x 9" Light Gray w/off-White Streaks Floor Tile**

MATERIAL LOCATION: **1925 Building - 3rd Floor Men's Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3C**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Multi-color Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement, 1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3C**

MATERIAL DESCRIPTION: **9" x 9" Light Green w/Multi-color Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1925 Building - Basement, 1st and 2nd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3D**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & Brown Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3D**

MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & Brown Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1925 Building - Basement Room 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3E**  
MATERIAL DESCRIPTION: **9" x 9" Choc. Brown w/Beige & Brown Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3E**

MATERIAL DESCRIPTION: **9" x 9" Choc. Brown w/Beige & Brown Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1925 Building - Basement Room 127**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3F**  
MATERIAL DESCRIPTION: **9" x 9" Maroon Floor tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Engineer's Office Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3F**

MATERIAL DESCRIPTION: **9" x 9" Maroon Floor tile ABATED**

MATERIAL LOCATION: **1925 Building - Basement Engineer's Office Areas**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3G**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/Multi-colored Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st & 3rd Floor Corridors, 3rd Floor Men's Bathroom, and 1st Floor Janitors Toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **3G**

MATERIAL DESCRIPTION: **9" x 9" Gray w/Multi-colored Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1925 Building - 1st & 3rd Floor Corridors, 3rd Floor Men's Bathroom, and 1st Floor Janitors Toilet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Interior brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Interior brick**

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **Interior brick mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Interior brick mortar**

MATERIAL LOCATION: **1925 Building - Basement Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **Tar-like fiberglass insulation jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Assembly Hall Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No access 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Tar-like fiberglass insulation jacket**

MATERIAL LOCATION: **1925 Building - Assembly Hall Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Incinerator Lining Material between Brick & Metal**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Incinerator Lining Material between Brick & Metal**

MATERIAL LOCATION: **1925 Building - Basement Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **Fiberglass insulation jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Assembly Hall Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **No access 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Fiberglass insulation jacket**

MATERIAL LOCATION: **1925 Building - Assembly Hall Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 023,427, 429,426A**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Tile**

MATERIAL LOCATION: **1953 Addition - Basement Room 023,427, 429,426A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **Caulk on metal windows**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Caulk on metal windows**

MATERIAL LOCATION: **1925 Building - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Exterior door caulk**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Exterior door caulk**

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Exterior joint caulk (bridging caulk) - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Exterior joint caulk (bridging caulk) - non ahera**

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Exterior brick - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Exterior brick - non ahera**

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4A**  
MATERIAL DESCRIPTION: **Black linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement West Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **4A**

MATERIAL DESCRIPTION: **Black linoleum**

MATERIAL LOCATION: **1925 Building - Basement West Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4B**  
MATERIAL DESCRIPTION: **Light chocolate brown linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **4B**

MATERIAL DESCRIPTION: **Light chocolate brown linoleum**

MATERIAL LOCATION: **1925 Building - Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **Interior brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Interior brick**

MATERIAL LOCATION: **1953 Addition - Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **Interior brick mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Interior brick mortar**

MATERIAL LOCATION: **1953 Addition - Basement**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **Black vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Black vinyl baseboard**

MATERIAL LOCATION: **1953 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**

MATERIAL LOCATION: **1953 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **Door Lining Insulation in Mechanical Units**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1953 Addition - Basement Fan Areas**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Door Lining Insulation in Mechanical Units**

MATERIAL LOCATION: **1953 Addition - Basement Fan Areas**

MATERIAL QUANTITY: **20**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **Sheet rock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Sheet rock**

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Joint Compound of Sheet Rock**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Joint Compound of Sheet Rock**

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Tar-like covering**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Tar-like covering**

MATERIAL LOCATION: **1953 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **Exterior window caulk (metal windows) - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Undefined** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Exterior window caulk (metal windows) - non ahera**

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A**  
MATERIAL DESCRIPTION: **12" x 12" Brown Leopard Print Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 2nd Floor Co-Ed Teachers Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **5A**

MATERIAL DESCRIPTION: **12" x 12" Brown Leopard Print Floor Tile ABATED**

MATERIAL LOCATION: **1925 Building - 2nd Floor Co-Ed Teachers Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5B**  
MATERIAL DESCRIPTION: **12" x 12" Green mix w/Multi-color Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **5B**

MATERIAL DESCRIPTION: **12" x 12" Green mix w/Multi-color Streaks Floor Tile**

MATERIAL LOCATION: **1925 Building - Room 104**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5C**  
MATERIAL DESCRIPTION: **12" x 12" Light Gray w/Multi-color Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **5C**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/Multi-color Streaks Floor Tile**

MATERIAL LOCATION: **1925 Building - Basement Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5D**  
MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/mixed Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Basement Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **5D**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray w/mixed Streaks Floor Tile**

MATERIAL LOCATION: **1925 Building - Basement Room 110**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5E**  
MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown spcks/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - 1st & 2nd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **5E**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/Brown spcks/Streaks Floor Tile**

MATERIAL LOCATION: **1925 Building - 1st & 2nd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **Exterior door caulk - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Exterior door caulk - non ahera**

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **Exterior joint caulk (bridging) - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Exterior joint caulk (bridging) - non ahera**

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **Exterior brick - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Exterior brick - non ahera**

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Black vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Black vinyl baseboard**

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Interior brick**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Interior brick**

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Interior brick mortar**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Interior brick mortar**

MATERIAL LOCATION: **1958 Addition - Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Corkboard-like Material above Blackboards**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Corkboard-like Material above Blackboards**

MATERIAL LOCATION: **1958 Addition - Throughout Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **Mastic on Corkboard-like Material above Blackboard**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Throughout Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Mastic on Corkboard-like Material above Blackboard**

MATERIAL LOCATION: **1958 Addition - Throughout Classrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6A**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & black Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **6A**

MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & black Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1953 Addition - 1st, 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6B**  
MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **6B**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown Floor Tile**

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6C**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **6C**

MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile**

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6D**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & tan Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **6D**

MATERIAL DESCRIPTION: **9" x 9" Tan w/Beige & tan Streaks Floor Tile**

MATERIAL LOCATION: **1953 Addition - Basement Room 024**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6E**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/White dots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 023**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **6E**

MATERIAL DESCRIPTION: **9" x 9" Gray w/White dots Floor Tile**

MATERIAL LOCATION: **1953 Addition - Basement Room 023**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6F**  
MATERIAL DESCRIPTION: **9" x 9" Green w/Multi-colored Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **6F**

MATERIAL DESCRIPTION: **9" x 9" Green w/Multi-colored Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1953 Addition - 2nd and 3rd Floor Corridors**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **Fiberglass duct insulation jacket**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Fiberglass duct insulation jacket**

MATERIAL LOCATION: **1958 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **Sink coat (sink bottom sealant)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Room 133, 134, and 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Sink coat (sink bottom sealant)**

MATERIAL LOCATION: **1958 Addition - Room 133, 134, and 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **Black & brown mix carpet mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Room 133**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Black & brown mix carpet mastic (adhesive)**

MATERIAL LOCATION: **1958 Addition - Room 133**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **Exterior window caulk (metal windows) Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Exterior window caulk (metal windows) Non-AHERA**

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **Exterior door caulk - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Exterior door caulk - Non-AHERA**

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 31091 BUIDLING ID: 3610  
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Benyamen Maradkel  
SCHOOL NAME: Grant School INSPECTION DATE: 7/7/2022  
ADDRESS: 145 S. Campbell IDPH LICENSE NO: 100-20411

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 75  
MATERIAL DESCRIPTION: Exterior joint caulk (bridging caulk) Non-AHERA  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1958 Addition

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/07/2022



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Exterior joint caulk (bridging caulk) Non-AHERA**

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **Exterior brick - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Exterior brick - non ahera**

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Exterior brick mortar - non ahera**

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **Black vinyl baseboard**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **Black vinyl baseboard**  
MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Black vinyl baseboard mastic (adhesive)**

MATERIAL LOCATION: **1953 Addition - Main Office Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7A**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Room 136, 235, 236, 238, 331, 334, 338, and 3rd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7A**  
MATERIAL DESCRIPTION: **9" x 9" Gray w/off-White & Brown Streaks Floor Tile**  
MATERIAL LOCATION: **1958 Addition - Room 136, 235, 236, 238, 331, 334, 338, and 3rd Floor Corridor**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7B**  
MATERIAL DESCRIPTION: **9" x 9" Tan w/off-White Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7B**

MATERIAL DESCRIPTION: **9" x 9" Tan w/off-White Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7C**  
MATERIAL DESCRIPTION: **9" x 9" Cream w/off-White & Brown Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 1st Floor Women's Bathroom, 3rd Floor Corridor and Women's Toilet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7C**  
MATERIAL DESCRIPTION: **9" x 9" Cream w/off-White & Brown Streaks Floor Tile ABATED**  
MATERIAL LOCATION: **1958 Addition - 1st Floor Women's Bathroom, 3rd Floor Corridor and Women's Toilet**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7D**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/off-White & Brown Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7D**

MATERIAL DESCRIPTION: **9" x 9" Brown w/off-White & Brown Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7E**  
MATERIAL DESCRIPTION: **9" x 9" Light Tan w/off-White & Brown Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7E**

MATERIAL DESCRIPTION: **9" x 9" Light Tan w/off-White & Brown Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1958 Addition - 3rd Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7F**  
MATERIAL DESCRIPTION: **9" x 9" Dark Choc. W/off-white streaks floor tile abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 2nd & 3rd Floor Women's Bathrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7F**

MATERIAL DESCRIPTION: **9" x 9" Dark Choc. W/off-white streaks floor tile abated**

MATERIAL LOCATION: **1958 Addition - 2nd & 3rd Floor Women's Bathrooms**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7G**  
MATERIAL DESCRIPTION: **9" x 9" Light Brown w/mixed Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON: **Physical Damage**  
HISTORICAL RESPONSE ACTION: **Remove**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Addition - Rooms 136, 230-239, 332, 334, 336 and 337, 330, 338, 339, 234, 235**  
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **14000** DAMAGE UNITS: **SF**  
COMMENTS: **Not observed in 239, 133 - 2022. Damage in Room 334**

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **7G**  
MATERIAL DESCRIPTION: **9" x 9" Light Brown w/mixed Streaks Floor Tile**  
MATERIAL LOCATION: **1958 Addition - Rooms 136, 230-239, 332, 334, 336 and 337, 330, 338, 339, 234, 235**  
MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **34** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Fan door lining**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Fan door lining**

MATERIAL LOCATION: **1958 Addition - 2nd Floor Fan Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **31091**    BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School**    INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Sink coat (sink bottom caulk)**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Rooms 130, 132, 133, 134, and 136**

MATERIAL QUANTITY:    MATERIAL UNITS:

DAMAGE QUANTITY:    DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Sink coat (sink bottom caulk)**

MATERIAL LOCATION: **1958 Addition - Rooms 130, 132, 133, 134, and 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Exterior joint caulk (wall bridging caulk) Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition (wall connecting 1958 Addition to 1925 Building)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Exterior joint caulk (wall bridging caulk) Non-AHERA**

MATERIAL LOCATION: **1958 Addition (wall connecting 1958 Addition to 1925 Building)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & black Streaks Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 1st Floor Women's Bathroom (by Room 136)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & black Streaks Floor Tile ABATED**

MATERIAL LOCATION: **1958 Addition - 1st Floor Women's Bathroom (by Room 136)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & black Streaks Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - 1st Floor Women's Bathroom (by Room 136)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **9" x 9" Light Green w/Beige & black Streaks Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1958 Addition - 1st Floor Women's Bathroom (by Room 136)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **Incinerator interior refractory materials**  
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **Incinerator interior refractory materials**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **Interior smoke stack lining**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS: **Inaccessible 2022**

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **Interior smoke stack lining**  
MATERIAL LOCATION: **Boiler Room**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **Roofing materials - non- ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Roofing materials - non- ahera**

MATERIAL LOCATION: **1925 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **Roofing Materials - Non-AHERA**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Roofing Materials - Non-AHERA**

MATERIAL LOCATION: **1953 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Roofing materials - non ahera**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Roofing materials - non ahera**

MATERIAL LOCATION: **1958 Addition**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8A**  
MATERIAL DESCRIPTION: **Green mix sink top linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Basement Room 021**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **8A**

MATERIAL DESCRIPTION: **Green mix sink top linoleum**

MATERIAL LOCATION: **1953 Addition - Basement Room 021**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8B**  
MATERIAL DESCRIPTION: **Multi-colored mix linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Rooms 121, 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **8B**

MATERIAL DESCRIPTION: **Multi-colored mix linoleum**

MATERIAL LOCATION: **1953 Addition - Rooms 121, 123**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**  
MATERIAL DESCRIPTION: **Sink top linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1958 Addition - Rooms 133, 134, 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Sink top linoleum**

MATERIAL LOCATION: **1958 Addition - Rooms 133, 134, 136**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **Boiler gaskets**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **Boiler gaskets**

MATERIAL LOCATION: **1925 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **Fire door insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Boiler Room**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **Fire door insulation**

MATERIAL LOCATION: **Basement Boiler Room**

MATERIAL QUANTITY: **32**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12" x 12" Burgundy Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Burgundy Floor Tile ABATED**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **31091**    BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School**    INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell**    IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **12" x 12" Burgundy Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated**    FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Burgundy Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **Burgundy carpet adhesive abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1953 Addition - Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **Burgundy carpet adhesive abated**

MATERIAL LOCATION: **1953 Addition - Principal's Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **Gray mix carpet adhesive abated**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Computer Room 226**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Gray mix carpet adhesive abated**

MATERIAL LOCATION: **Computer Room 226**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Building - 1st, 2nd, 3rd Boy's/ Girl's & Women's Bathroom**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout**  
MATERIAL LOCATION: **1958 Building - 1st, 2nd, 3rd Boy's/ Girl's & Women's Bathroom**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96M**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Building - 1st, 2nd, 3rd Floor Boy's/ Girl's and Women's Bathroom**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **96M**  
MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Grout Adhesive**  
MATERIAL LOCATION: **1958 Building - 1st, 2nd, 3rd Floor Boy's/ Girl's and Women's Bathroom**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **Light & dark green ceramic grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Building - Entrances (Foyer)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **Light & dark green ceramic grout**  
MATERIAL LOCATION: **1958 Building - Entrances (Foyer)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **97M**  
MATERIAL DESCRIPTION: **Light & dark green ceramic grout adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958 Building - Entrances ( Foyer)**

MATERIAL QUANTITY: **400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **97M**  
MATERIAL DESCRIPTION: **Light & dark green ceramic grout adhesive**  
MATERIAL LOCATION: **1958 Building - Entrances ( Foyer)**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Green/black terrazzo flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Building - Stairwell and Landings**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **Green/black terrazzo flooring**  
MATERIAL LOCATION: **1958 Building - Stairwell and Landings**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1958 Building - Room 152, Storage and Kitchen Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile**  
MATERIAL LOCATION: **1958 Building - Room 152, Storage and Kitchen Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **99M**  
MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1958 Building - Room 152, Storage, Kitchen Office**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **99M**  
MATERIAL DESCRIPTION: **12" x 12" Black w/White Dots Floor Tile Mastic**  
MATERIAL LOCATION: **1958 Building - Room 152, Storage, Kitchen Office**  
MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Tank packing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **boiler room, 1925 bldg**  
MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Tank packing**  
MATERIAL LOCATION: **boiler room, 1925 bldg**  
MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room, Attic**  
MATERIAL QUANTITY: **496** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Aircell pipe insulation**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room, Attic**  
MATERIAL QUANTITY: **496** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Aircell pipe joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room, Attic**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Aircell pipe joint compound**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room, Attic**  
MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room, BOILER ROOM**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**  
COMMENTS: **Damage in boiler room**

Inspector's Signature: \_\_\_\_\_



Date: 07/07/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room, BOILER ROOM**  
MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **4** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Paperwrap pipe insulation joint compound**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Paperwrap pipe insulation joint compound**  
MATERIAL LOCATION: **1925 Building - Assembly Hall Store Room**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Water main packing**  
HISTORICAL AHERA DAMAGE CATEGORY **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

**2022 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Water main packing**  
MATERIAL LOCATION: **1925 Building**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**



# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUILDING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **1925 Building - Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 07/14/2022

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Benyamen Maradkel**  
SCHOOL NAME: **Grant School** INSPECTION DATE: **7/7/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 Any remaining friable ACBM or friable suspect ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1953 Addition - Fan Room**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **07/07/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **31091** BUIDLING ID: **3610**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**  
SCHOOL NAME: **Grant School** REVIEW DATE: **7/14/2022**  
ADDRESS: **145 S. Campbell** IDPH LICENSE NO: **100-20411**

---

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **1953 Addition - Fan Room**

MATERIAL QUANTITY: **50**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **07/14/2022**

# Chicago Public Schools

Carnow, Conibear and Associates

*2022 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---

# Benyamen Maradkel

Illinois Licensed Building Inspector



**ASBESTOS  
PROFESSIONAL  
LICENSE**

**ID NUMBER**  
**100 - 20411**

**ISSUED**  
**3/17/2022**

**EXPIRES**  
**05/15/2023**

**BENYAMEN C MARADKEL**  
**706 W HACKBERRY DR**  
**ARLINGTON HEIGHTS, IL 6000**  
*Environmental Health*



**ENDORSEMENTS**

INSPECTOR

**EXPIRES**

5/9/2023

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Benyamen Maradkel**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090703

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director





OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519

  
Kathy DeSalvo, Director



# ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

**100 - 19466**

ISSUED

**4/22/2022**

EXPIRES

**05/15/2023**

**EVAN I CHRISTIAN**  
**1119 N HOYNE AVE, APT 1**  
**CHICAGO, IL 60622**

Environmental Health



## ENDORSEMENTS

## TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Evan Christian**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed