

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM**

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-0058
SCHOOL NAME: Second Chance High School (Satellite of Peace & Education Coalition High School)
ADDRESS OF SCHOOL: 5114 S. Elizabeth
CITY: Chicago, IL, 60609-

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 5/13/2019

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 11/9/2022 ENROLLMENT 114
IDPH INSPECTOR LICENSE NUMBER: 100-19554
IDPH LICENSED INSPECTOR NAME (Please Print): Carol Ashman
IDPH MP LICENSE NUMBER: 100-19466
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Evan Christian

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 11/18/2022
Signature of Designated Person *Date*

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Second Chance High School (Satellite of Peace & Education Coalition High School)

5114 S. Elizabeth
Chicago, IL, 60609-

Unit: 67021
Building ID: 5643

IDPH ID Number: 14-016-2990-0058

REPORT DATE:

Friday, November 18, 2022

Prepared for:

**Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602**

Prepared by:

Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, Il, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

11/18/2022

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2022 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25152 Region: 04 IDPH ID: 14-016-2990-0058

School: Second Chance High School (Satellite of Peace & Education Coalition High School) Building ID: 5643
Address: 5114 S. Elizabeth

Chicago, IL, 60609-

Building Contact: Klupshas, Thomas

Contact Phone: 7082145842

Current Building Owners: Chicago Public Schools

Reinspection Date: 11/9/2022

Review Date: 11/18/2022

Inspector: Carol Ashman

Inspector IDPH License: 100-19554

Management Planner: Evan Christian

Management Planner IDPH License: 100-19466

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Evan Christian
100-19466

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: November 18, 2022

RE: Second Chance High School (Satellite of Peace & Education Coalition High School), Unit 67021
5114 S. Elizabeth
Chicago, IL, 60609-

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2022 asbestos three year re-inspection has been completed at Second Chance High School (Satellite of Peace & Education Coalition High School) , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Second Chance High School (Satellite of Peace & Education Coalition High School), there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Second Chance High School (Satellite of Peace & Education Coalition High School) Unit: 25152 Region: 04
Address: 5114 S. Elizabeth Chicago, IL, 60609-
IDPH ID: 14-016-2990-0058 Building ID: 5643
Contact: Klupshas, Thomas Phone: 7082145842

2. Description of Facility

Original Construction: 1956 Additional Construction:
Total Square Footage: 22322 No of Floors: 2
Current Occupancy: 114

3. LEA Designated Person

Contact: Richard J. Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Carol Ashman


Inspector IDPH license # 100-19554
Reinspection Date: 11/9/2022

Signature:
Date: 11/9/2022

6. Management Planner

Management Planner Name: Evan Christian

Management Planner IDPH license # 100-19466


Signature: 
Date: 11/18/2022

7. Review Date: 11/18/2022

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 11/18/2022

Name: Richard J. Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Second Chance High School (Satellite of Peace & Education Coalition High School). This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5643:

070	Light tan laminate flooring
FTM-001	12" x 12" White w/color Specks's Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 5643:

070

Light tan laminate flooring

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

003	12" x 12" Gray Floor Tile
005	12" x 12" Light Brown Floor Tile
007	12" x 12" Gray Speckled Floor Tile
009	12" x 12" Brown Streaked Floor Tile
011	12" x 12" Brown and Gray Mix Floor Tile
013	9"x9" green floor tile
014	9"x9" green floor tile mastic
015	Gray floor tile
051	Poster board adhesive
052	Chalk board adhesive
053	Sink countertop laminate
054	Sink countertop laminate adhesive
055	Sink counter caulk
056	Tub caulk
057	Sink counter top laminate
058	Sink counter top laminate adhesive
059	Sink counter top caulk
060	Mirror adhesive
061	Mirror adhesive
062	Insulation in Firedoors
065	Tan and Gray Terrazzo Flooring
066	12" x 12" Light Green w/ Dark Green Floor Tile
067	12" x 12" Light Green w/ Dark Green Floor Tile Mastic
068	Tan Linoleum and Backing
069	Blue carpet adhesive
070	Light tan laminate flooring
70	Green carpet mastic
71	Lab counter tops
72	Lab table tops
FT-001	12" x 12" White w/color Specks's Floor Tile
FT-002	12" x 12" Tan Floor Tile and Mastic
FTM-001	12" x 12" White w/color Specks's Floor Tile Mastic

The following areas were deemed to be inaccessible:

014	9"x9" green floor tile mastic
051	Poster board adhesive
052	Chalk board adhesive
058	Sink counter top laminate adhesive

060	Mirror adhesive
061	Mirror adhesive
067	12" x 12" Light Green w/ Dark Green Floor Tile Mastic
069	Blue carpet adhesive
70	Green carpet mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Evan Christian, IDPH License # 100-19466. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Second Chance High School (Satellite of Peace & Education Coalition High School) Building 5643 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) Unit 25152 Building ID

5643

Address 5114 S. Elizabeth Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	9"x9" green floor tile	5,600	SF	Classrooms 102, 104, 202, 205, 221 (not observed)	CHR	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
002	9"x9" green floor tile mastic		SF	Classrooms 102, 104, 202, 205, 221	CHR	MISC				SF				
003	12" x 12" Gray Floor Tile	7,200	SF	Rooms 103A, 120, 122, 125, 127 and adj Corridor, 203A, 221, 223, 224 (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
004	12" x 12" Gray Floor Tile Mastic			Classrooms 103A, 120, 122, 125, 127 and Adjacent Corridor, 203A, 221, 223, 224	NO_ACBM	MISC								
005	12" x 12" Light Brown Floor Tile	5,600	SF	Classrooms 103A, 104, 203, 204, 205, 225F, 225D and Adjacent Corridor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
006	12" x 12" Light Brown Floor Tile Mastic			Classrooms 103A, 104, 203, 204, 205, 225F, 225D and Adjacent Corridor	NO_ACBM	MISC								
007	12" x 12" Gray Speckled Floor Tile	4,800	SF	Classrooms 106, 112 and Adjacent Corridor, 115, 117, 216, 218	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
008	12" x 12" Gray Speckled Floor Tile Mastic			Rooms 106, 112 and adj. Corridor, 115, 117, 216, 218	NO_ACBM	MISC								
009	12" x 12" Brown Streaked Floor Tile	1,000	SF	Room 111 and Adjacent Corridor	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
010	12" x 12" Brown Streaked Floor Tile Mastic			Room 111 and Adjacent Corridor	NO_ACBM	MISC								
011	12" x 12" Brown and Gray Mix Floor Tile	1,800	SF	Rooms 106, 107	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
012	12" x 12" Brown and Gray Mix Floor Tile Mastic			Rooms 106, 107	NO_ACBM	MISC								
013	9"x9" green floor tile	1,400	SF	Rooms 107A, 208 (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
014	9"x9" green floor tile mastic	1,400	SF	Rooms 107A, 208 (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
015	Gray floor tile	600	SF	Room 225A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the		LOW

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) Unit 25152 Building ID

5643

Address 5114 S. Elizabeth Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				observed)										
050	Leveling compound			Classroom 207 (not observed)	NO_ACBM	MISC								
051	Poster board adhesive	300	SF	Classrooms 103, 104, 123 (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
052	Chalk board adhesive	450	SF	Rooms 120, 202, 221 (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
053	Sink countertop laminate	70	SF	South Building Girl' and Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
054	Sink countertop laminate adhesive	70	SF	South Building Girl' and Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
055	Sink counter caulk	20	LF	South Building Girl' and Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
056	Tub caulk	10	LF	225F (not observed)	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
057	Sink counter top laminate	90	SF	North Building Girl's and Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
058	Sink counter top laminate adhesive	90	SF	North Building Girl's and Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
059	Sink counter top caulk	30	LF	North Building Girl's and Boy's Bathrooms	ASSUMED	MISC	N	NONE	0	LF	No	ACBM with the potential for damage		LOW
060	Mirror adhesive	25	SF	South Building Girl's and Boy's Bathrooms (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
061	Mirror adhesive	25	SF	North Building Girl's and Boy's Bathrooms (not observed)	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
062	Insulation in Firedoors		SF	South Building	ASSUMED	MISC				SF				
063	Black mastic under carpeting			Classrooms 215, 216 (not observed)	NO_ACBM	MISC								
064	Brown carpet adhesive			Classroom 215	NO_ACBM	MISC								
065	Tan and Gray Terrazzo Flooring	7,500	SF	1st and 2nd Floor Corridors and Stairs, 119A	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) Unit 25152 Building ID

5643

Address 5114 S. Elizabeth Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
066	12" x 12" Light Green w/ Dark Green Floor Tile		SF	Room 107	ASSUMED	MISC				SF				
067	12" x 12" Light Green w/ Dark Green Floor Tile Mastic	800	SF	Room 107	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
068	Tan Linoleum and Backing	800	SF	Room 120	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
069	Blue carpet adhesive	3,200	SF	Rooms 200, 205, 212 and Day Care Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
070	Light tan laminate flooring	500	SF	Room 120	ASSUMED	MISC	N	NONE	0	SF	Yes	ACBM with the potential for damage		LOW
70	Green carpet mastic	300	SF	Room 230	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
71	Lab counter tops	200	SF	Room 120	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
72	Lab table tops	300	SF	Room 120	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
A	Aircell pipe insulation		LF	South Building, throughout the crawl space	CHR	TSI				LF				
A1	Aircell pipe insulation	1,500	LF	North Building throughout the crawlspace, tunnels - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
B	Cementitious Joint Insulation Assoc w/Aircell	100	LF	South Building	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
B1	Cementitious joint insulation- aircell pipe insula	100	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
C	Paper wrap pipe insulation	1,000	LF	South Building	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
C1	Paperwrap pipe insulation	1,000	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
D	Cementitious joint insulation assoc. W/paper wrap	70	LF	South Building	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		HIGH

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) Unit 25152 Building ID

5643

Address 5114 S. Elizabeth Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
D1	Joint insulation assoc.w/paperwrap pipe insulation	70	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
E	Aircell Pipe insulation	1,500	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
E1	Aircell pipe insulation	1,500	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
F	Cementitious Joint Insulation Assoc w/Aircell	100	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
F1	Joint insulation assoc. W/aircell pipe insulation	100	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				
FT-001	12" x 12" White w/color Specks's Floor Tile	20,000	SF	102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineers office (111), 113, 115, 116, lunchroom	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
FT-002	12" x 12" Tan Floor Tile and Mastic	700	SF	Rooms 202 Storage Room	ASSUMED	MISC	N	NONE	0	SF	No	ACBM with the potential for damage		LOW
FTM-001	12" x 12" White w/color Specks's Floor Tile Mastic	20,000	SF	102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineer's office (111), 113, 115, 116, lunchroom, 212, 204	ASSUMED	MISC	N	DIST	10	SF	Yes	ACBM with potential for significant damage	4	LOW
G	Paperwrap pipe insulation	1,000	LF	South Building	CHR	TSI	Y	NONE	0	LF	No	Damaged or significantly damaged friable thermal system insulating ACBM		MODERATE
G1	Paperwrap pipe insulation	1,000	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) **Unit** 25152 **Building ID**

5643

Address 5114 S. Elizabeth **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
H	Cementitious Joint Insulation Assoc w/Paper Wrap	70	LF	North Building - NOT CPS LEASED OR OWNED 2016	CHR	TSI		NONE	0	LF				

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) Unit 25152 Building ID

5643

Address 5114 S. Elizabeth Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 11/9/2022
Inspector Name Carol Ashman
100-19554 5/15/2023
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
002	Not observed 2022
003	
004	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) **Unit** 25152 **Building ID**

5643

Address 5114 S. Elizabeth **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
023	
024	
025	
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) Unit 25152 Building ID

5643

Address 5114 S. Elizabeth Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
051	
052	
053	
054	
055	
056	
057	
058	
059	
060	
061	
062	Not observed 2022
063	
064	
065	
066	Not observed 2022
067	
068	
069	
070	
70	
71	
72	
A	Engineer reported it was abated 2 yrs ago (need to check), Not observed 2022
A1	NOT CPS LEASED OR OWNED
B	
B1	NOT CPS LEASED OR OWNED
C	

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School) **Unit** 25152 **Building ID**

5643

Address 5114 S. Elizabeth **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
C1	NOT CPS LEASED OR OWNED
D	
D1	NOT CPS LEASED OR OWNED
E	NOT CPS LEASED OR OWNED
E1	NOT CPS LEASED OR OWNED
F	NOT CPS LEASED OR OWNED
F1	NOT CPS LEASED OR OWNED
FT-001	
FT-002	
FTM-001	Damaged in rooms 114, 115, engineer's office (111)
G	
G1	NOT CPS LEASED OR OWNED
H	NOT CPS LEASED OR OWNED

Table II

Management Planner's Review

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)
 Address 5114 S. Elizabeth

Unit 25152
 Chicago, IL, 60609-

Building ID 5643
 Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	9"x9" green floor tile	5,600	SF	Classrooms 102, 104, 202, 205, 221 (not observed)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
002	9"x9" green floor tile mastic		SF	Classrooms 102, 104, 202, 205, 221	Chrysotile	MISC			SF		Follow O&M Plan
003	12" x 12" Gray Floor Tile	7,200	SF	Rooms 103A, 120, 122, 125, 127 and adj Corridor, 203A, 221, 223, 224 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004	12" x 12" Gray Floor Tile Mastic			Classrooms 103A, 120, 122, 125, 127 and Adjacent Corridor, 203A, 221, 223, 224	No ACBM	MISC					
005	12" x 12" Light Brown Floor Tile	5,600	SF	Classrooms 103A, 104, 203, 204, 205, 225F, 225D and Adjacent Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
006	12" x 12" Light Brown Floor Tile Mastic			Classrooms 103A, 104, 203, 204, 205, 225F, 225D and Adjacent Corridor	No ACBM	MISC					
007	12" x 12" Gray Speckled Floor Tile	4,800	SF	Classrooms 106, 112 and Adjacent Corridor, 115, 117, 216, 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
008	12" x 12" Gray Speckled Floor Tile Mastic			Rooms 106, 112 and adj. Corridor, 115, 117, 216, 218	No ACBM	MISC					
009	12" x 12" Brown Streaked Floor Tile	1,000	SF	Room 111 and Adjacent Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
010	12" x 12" Brown Streaked Floor Tile Mastic			Room 111 and Adjacent Corridor	No ACBM	MISC					
011	12" x 12" Brown and Gray Mix Floor Tile	1,800	SF	Rooms 106, 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
012	12" x 12" Brown and Gray Mix Floor Tile Mastic			Rooms 106, 107	No ACBM	MISC					
013	9"x9" green floor tile	1,400	SF	Rooms 107A, 208 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
014	9"x9" green floor tile mastic	1,400	SF	Rooms 107A, 208 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
015	Gray floor tile	600	SF	Room 225A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
016	Gray floor tile mastic			Room 225A	No ACBM	MISC					
017	Brown carpet adhesive			Rooms 102, 120, 202, 204, 225A, 225B	No ACBM	MISC					
018	Blue/purple carpet adhesive			Classrooms 104, 104A, 120, 122, 123, 124, 202, 204, 205, 221, 223, 224	No ACBM	MISC					
019	Blue/purple carpet adhesive			Rooms 107, 107A, 114, 115, 116, 117, 208, 216, 217, 218	No ACBM	MISC					
020	Plaster			Walls and ceilings in South Building	No ACBM	SURFACE					
021	Plaster			Walls and ceilings in North Building	No ACBM	SURFACE					

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)

Unit 25152

Building ID 5643

Address 5114 S. Elizabeth

Chicago, IL, 60609-

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
022	Paper			Beneath ceiling joists	No ACBM	MISC					
023	4" Blue vinyl baseboard			Staiway Vestibules, Corridors, Reception Area, and Classroom 102	No ACBM	MISC					
024	4" Blue vinyl baseboard adhesive			Staiway Vestibules, Corridors, Reception Area, and Classroom 102	No ACBM	MISC					
025	4" Gray vinyl baseboard			Classrooms 103A, 125, 127, 131	No ACBM	MISC					
026	4" Gray vinyl baseboard adhesive			Classrooms 103A, 125, 127, 131	No ACBM	MISC					
027	4" Purple vinyl baseboard			Classroom 130 and Adjacent Corridor	No ACBM	MISC					
028	4" Purple vinyl baseboard adhesive			Classroom 130 and Adjacent Corridor	No ACBM	MISC					
029	4" Dark blue vinyl baseboard			Rooms 103, 104, 104A, 122, 123, 124, 125, 202, 203 Kitchen, 204, 221, 223, 224, 225, 225D, 225E, 2nd	No ACBM	MISC					
030	4" Dark blue vinyl baseboard adhesive			Rooms 103, 104, 104A, 122, 123, 124, 125, 202, 203 kitchen, 204, 221, 223, 224, 225, 225D, 225E, 2nd	No ACBM	MISC					
031	4" Maroon vinyl baseboard			Classroom 120	No ACBM	MISC					
032	4" Maroon vinyl baseboard adhesive			Classroom 120	No ACBM	MISC					
033	4" Brown vinyl baseboard			Classrooms 225A and 225B	No ACBM	MISC					
034	4" Brown vinyl baseboard adhesive			Room 225A and 225B	No ACBM	MISC					
035	4" Dark blue vinyl baseboard			Rooms 107, 107A, 115, 116, 117, 207, 207A, 208, 210 and Adjacent Corridor, 216, 218	No ACBM	MISC					
036	4" Dark blue vinyl baseboard adhesive			Rooms 107, 107A, 115, 116, 117, 207, 207A, 208, 210 and Adjacent Corridor, 216, 218	No ACBM	MISC					
037	4" Purple vinyl baseboard			Classrooms 106, 110, 111	No ACBM	MISC					
038	4" Purple vinyl baseboard adhesive			Classrooms 106, 110, 111	No ACBM	MISC					
039	4" Gray vinyl baseboard			Storage Room 112	No ACBM	MISC					
040	4" Gray vinyl baseboard adhesive			Storage Room 112	No ACBM	MISC					
041	4" Brown vinyl baseboard			Storage Room 114, Office 215	No ACBM	MISC					
042	4" Brown vinyl baseboard adhesive			Storage Room 114, Office 215	No ACBM	MISC					
043	4" Blue vinyl baseboard			Stairways, Corridor Adjacent to 114	No ACBM	MISC					

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)
 Address 5114 S. Elizabeth

Unit 25152
 Chicago, IL, 60609-

Building ID 5643
 Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
044	4" Blue vinyl baseboard			Stairways, Corridor Adjacent to 114	No ACBM	MISC					
045	Leveling compound			Classroom 205 (not observed)	No ACBM	MISC					
046	Black Mastic on Leveling Compound			Classroom 205 (not observed)	No ACBM	MISC					
047	White sink undercoating			Classrooms 103A, 203 (not observed)	No ACBM	MISC					
048	White sink undercoating			Classrooms 106, 207A	No ACBM	MISC					
049	Insulation of fire door			North Building (not observed)	No ACBM	MISC					
050	Leveling compound			Classroom 207 (not observed)	No ACBM	MISC					
051	Poster board adhesive	300	SF	Classrooms 103, 104, 123 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
052	Chalk board adhesive	450	SF	Rooms 120, 202, 221 (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
053	Sink countertop laminate	70	SF	South Building Girl' and Boy;s Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
054	Sink countertop laminate adhesive	70	SF	South Building Girl' and Boy;s Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
055	Sink counter caulk	20	LF	South Building Girl' and Boy;s Bathrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
056	Tub caulk	10	LF	225F (not observed)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
057	Sink counter top laminate	90	SF	North Building Girl's and Boy's Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
058	Sink counter top laminate adhesive	90	SF	North Building Girl's and Boy's Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
059	Sink counter top caulk	30	LF	North Building Girl's and Boy's Bathrooms	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
060	Mirror adhesive	25	SF	South Building Girl's and Boy's Bathrooms (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
061	Mirror adhesive	25	SF	North Building Girl's and Boy's Bathrooms (not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
062	Insulation in Firedoors		SF	South Building	Assumed	MISC			SF		Follow O&M Plan
063	Black mastic under carpeting			Classrooms 215, 216 (not observed)	No ACBM	MISC					
064	Brown carpet adhesive			Classroom 215	No ACBM	MISC					
065	Tan and Gray Terrazzo Flooring	7,500	SF	1st and 2nd Floor Corridors and Stairs, 119A	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)

Unit 25152

Building ID 5643

Address 5114 S. Elizabeth

Chicago, IL, 60609-

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
066	12" x 12" Light Green w/ Dark Green Floor Tile		SF	Room 107	Assumed	MISC			SF		Follow O&M Plan
067	12" x 12" Light Green w/ Dark Green Floor Tile Mastic	800	SF	Room 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
068	Tan Linoleum and Backing	800	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
069	Blue carpet adhesive	3,200	SF	Rooms 200, 205, 212 and Day Care Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
070	Light tan laminate flooring	500	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Green carpet mastic	300	SF	Room 230	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Lab counter tops	200	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Lab table tops	300	SF	Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell pipe insulation		LF	South Building, throughout the crawl space	Chrysotile	TSI			LF		Follow O&M Plan
A1	Aircell pipe insulation	1,500	LF	North Building throughout the crawlspace, tunnels - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
B	Cementitious Joint Insulation Assoc w/Aircell	100	LF	South Building	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
B1	Cementitious joint insulation- aircell pice insula	100	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
C	Paper wrap pipe insulation	1,000	LF	South Building	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
C1	Paperwrap pipe insulation	1,000	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
D	Cementitious joint insulation assoc. W/paper wrap	70	LF	South Building	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
D1	Joint insulation assoc.w/paperwrap pipe insulation	70	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
E	Aircell Pipe insulation	1,500	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
E1	Aircell pipe insulation	1,500	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
F	Cementitious Joint Insulation Assoc w/Aircell	100	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)

Unit 25152
Chicago, IL, 60609-

Building ID 5643
Region 04

Address 5114 S. Elizabeth

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
F1	Joint insulation assoc. W/aircell pipe insulation	100	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
FT-001	12" x 12" White w/color Specks's Floor Tile	20,000	SF	102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineers office (111), 113, 115, 116, lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FT-002	12" x 12" Tan Floor Tile and Mastic	700	SF	Rooms 202 Storage Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FTM-001	12" x 12" White w/color Specks's Floor Tile Mastic	20,000	SF	102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineer's office (111), 113, 115, 116, lunchroom, 212, 204	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Repair
G	Paperwrap pipe insulation	1,000	LF	South Building	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
G1	Paperwrap pipe insulation	1,000	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan
H	Cementitious Joint Insulation Assoc w/Paper Wrap	70	LF	North Building - NOT CPS LEASED OR OWNED 2016	Chrysotile	TSI		0	LF		Follow O&M Plan

Chicago Public Schools

School	Second Chance High School (Satellite of Peace & Education Coalition High School)	Unit	25152	Building ID	5643
Address	5114 S. Elizabeth	Chicago, IL, 60609-		Region	04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
 600 West Van Buren St., Ste 500
 Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	11/18/2022
Manager Planner Name	Evan Christian
100-19466	5/15/2023
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	
003	
004	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)

Unit 25152

Building ID 5643

Address 5114 S. Elizabeth

Chicago, IL, 60609-

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)
Address 5114 S. Elizabeth

Unit 25152
Chicago, IL, 60609-

Building ID 5643
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
041	
042	
043	
044	
045	
046	
047	
048	
049	
050	
051	
052	
053	
054	
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)
Address 5114 S. Elizabeth

Unit 25152
 Chicago, IL, 60609-

Building ID 5643
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
 600 West Van Buren St., Ste 500
 Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
066	
067	
068	
069	
070	
70	
71	
72	
A	
A1	
B	
B1	
C	
C1	
D	
D1	
E	
E1	
F	
F1	
FT-001	
FT-002	
FTM-001	
G	
G1	

Chicago Public Schools

School Second Chance High School (Satellite of Peace & Education Coalition High School)
Address 5114 S. Elizabeth

Unit 25152
Chicago, IL, 60609-

Building ID 5643
Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900

Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
H	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **9"x9" green floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 102, 104, 202, 205, 221 (not observed)**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **9"x9" green floor tile**
MATERIAL LOCATION: **Classrooms 102, 104, 202, 205, 221 (not observed)**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **9"x9" green floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 102, 104, 202, 205, 221**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **002**
MATERIAL DESCRIPTION: **9"x9" green floor tile mastic**
MATERIAL LOCATION: **Classrooms 102, 104, 202, 205, 221**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 103A, 120, 122, 125, 127 and adj Corridor, 203A, 221, 223, 224 (not observed)**

MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **003**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**
MATERIAL LOCATION: **Rooms 103A, 120, 122, 125, 127 and adj Corridor, 203A, 221, 223, 224 (not observed)**
MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 103A, 120, 122, 125, 127 and Adjacent Corridor, 203A, 221, 223, 224**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **004**
MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms 103A, 120, 122, 125, 127 and Adjacent Corridor, 203A, 221, 223, 224**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Classrooms 103A, 104, 203, 204, 205, 225F, 225D and Adjacent. Corridor**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **005**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**
MATERIAL LOCATION: **Classrooms 103A, 104, 203, 204, 205, 225F, 225D and Adjacent. Corridor**
MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms103A, 104, 203, 204, 205, 225F, 225D and Adjacent Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **006**
MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile Mastic**
MATERIAL LOCATION: **Classrooms 103A, 104, 203, 204, 205, 225F, 225D and Adjacent Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckled Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 106, 112 and Adjacent Corridor, 115, 117, 216, 218**

MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **007**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckled Floor Tile**
MATERIAL LOCATION: **Classrooms 106, 112 and Adjacent Corridor, 115, 117, 216, 218**
MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckled Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 106, 112 and adj. Corridor, 115, 117, 216, 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **008**
MATERIAL DESCRIPTION: **12" x 12" Gray Speckled Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 106, 112 and adj. Corridor, 115, 117, 216, 218**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **12" x 12" Brown Streaked Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 111 and Adjacent Corridor**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **009**
MATERIAL DESCRIPTION: **12" x 12" Brown Streaked Floor Tile**
MATERIAL LOCATION: **Room 111 and Adjacent Corridor**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" Brown Streaked Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111 and Adjacent Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **010**
MATERIAL DESCRIPTION: **12" x 12" Brown Streaked Floor Tile Mastic**
MATERIAL LOCATION: **Room 111 and Adjacent Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12" x 12" Brown and Gray Mix Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 106, 107**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **011**
MATERIAL DESCRIPTION: **12" x 12" Brown and Gray Mix Floor Tile**
MATERIAL LOCATION: **Rooms 106, 107**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Brown and Gray Mix Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 106, 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **012**
MATERIAL DESCRIPTION: **12" x 12" Brown and Gray Mix Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 106, 107**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **9"x9" green floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 107A, 208 (not observed)**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **013**
MATERIAL DESCRIPTION: **9"x9" green floor tile**
MATERIAL LOCATION: **Rooms 107A, 208 (not observed)**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **9"x9" green floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 107A, 208 (not observed)**

MATERIAL QUANTITY: **1400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **014**
MATERIAL DESCRIPTION: **9"x9" green floor tile mastic**
MATERIAL LOCATION: **Rooms 107A, 208 (not observed)**
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Gray floor tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 225A**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **015**
MATERIAL DESCRIPTION: **Gray floor tile**
MATERIAL LOCATION: **Room 225A**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Gray floor tile mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 225A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **016**
MATERIAL DESCRIPTION: **Gray floor tile mastic**
MATERIAL LOCATION: **Room 225A**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **Brown carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 102, 120, 202, 204, 225A, 225B**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **017**
MATERIAL DESCRIPTION: **Brown carpet adhesive**
MATERIAL LOCATION: **Rooms 102, 120, 202, 204, 225A, 225B**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Blue/purple carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 104, 104A, 120, 122, 123, 124, 202, 204, 205, 221, 223, 224**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **018**
MATERIAL DESCRIPTION: **Blue/purple carpet adhesive**
MATERIAL LOCATION: **Classrooms 104, 104A, 120, 122, 123, 124, 202, 204, 205, 221, 223, 224**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Blue/purple carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 107, 107A, 114, 115, 116, 117, 208, 216, 217, 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **019**
MATERIAL DESCRIPTION: **Blue/purple carpet adhesive**
MATERIAL LOCATION: **Rooms 107, 107A, 114, 115, 116, 117, 208, 216, 217, 218**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Walls and ceilings in South Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **020**
MATERIAL DESCRIPTION: **Plaster**
MATERIAL LOCATION: **Walls and ceilings in South Building**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **021**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Walls and ceilings in North Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **021**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Walls and ceilings in North Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Paper**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Beneath ceiling joists**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **022**
MATERIAL DESCRIPTION: **Paper**
MATERIAL LOCATION: **Beneath ceiling joists**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Staiway Vestibules, Corridors, Reception Area, and Classroom 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **023**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
MATERIAL LOCATION: **Staiway Vestibules, Corridors, Reception Area, and Classroom 102**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Staiway Vestibules, Corridors, Reception Area, and Classroom 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **024**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard adhesive**
MATERIAL LOCATION: **Staiway Vestibules, Corridors, Reception Area, and Classroom 102**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 103A, 125, 127, 131**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **025**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
MATERIAL LOCATION: **Classrooms 103A, 125, 127, 131**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 103A, 125, 127, 131**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **026**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
MATERIAL LOCATION: **Classrooms 103A, 125, 127, 131**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 130 and Adjacent Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **027**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard**
MATERIAL LOCATION: **Classroom 130 and Adjacent Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 130 and Adjacent Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **028**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard adhesive**
MATERIAL LOCATION: **Classroom 130 and Adjacent Corridor**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 103, 104, 104A, 122, 123, 124, 125, 202, 203 Kitchen, 204, 221, 223, 224, 225, 225D, 225E, 2nd**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **029**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard**
MATERIAL LOCATION: **Rooms 103, 104, 104A, 122, 123, 124, 125, 202, 203 Kitchen, 204, 221, 223, 224, 225, 225D, 225E, 2nd**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 103, 104, 104A, 122, 123, 124, 125, 202, 203 kitchen, 204, 221, 223, 224, 225, 225D, 225E, 2nd**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **030**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard adhesive**
MATERIAL LOCATION: **Rooms 103, 104, 104A, 122, 123, 124, 125, 202, 203 kitchen, 204, 221, 223, 224, 225, 225D, 225E, 2nd**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **4" Maroon vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 120**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **031**
MATERIAL DESCRIPTION: **4" Maroon vinyl baseboard**
MATERIAL LOCATION: **Classroom 120**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **4" Maroon vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **032**
MATERIAL DESCRIPTION: **4" Maroon vinyl baseboard adhesive**
MATERIAL LOCATION: **Classroom 120**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 225A and 225B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **033**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
MATERIAL LOCATION: **Classrooms 225A and 225B**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 225A and 225B**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **034**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
MATERIAL LOCATION: **Room 225A and 225B**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 107, 107A, 115, 116, 117, 207, 207A, 208, 210 and Adjacent Corridor, 216, 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **035**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard**
MATERIAL LOCATION: **Rooms 107, 107A, 115, 116, 117, 207, 207A, 208, 210 and Adjacent Corridor, 216, 218**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 107, 107A, 115, 116, 117, 207, 207A, 208, 210 and Adjacent Corridor, 216, 218**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **036**
MATERIAL DESCRIPTION: **4" Dark blue vinyl baseboard adhesive**
MATERIAL LOCATION: **Rooms 107, 107A, 115, 116, 117, 207, 207A, 208, 210 and Adjacent Corridor, 216, 218**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 106, 110, 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **037**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard**
MATERIAL LOCATION: **Classrooms 106, 110, 111**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 106, 110, 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **038**
MATERIAL DESCRIPTION: **4" Purple vinyl baseboard adhesive**
MATERIAL LOCATION: **Classrooms 106, 110, 111**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Storage Room 112**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **039**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard**
MATERIAL LOCATION: **Storage Room 112**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Storage Room 112**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **040**
MATERIAL DESCRIPTION: **4" Gray vinyl baseboard adhesive**
MATERIAL LOCATION: **Storage Room 112**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Storage Room 114, Office 215**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **041**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard**
MATERIAL LOCATION: **Storage Room 114, Office 215**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Storage Room 114, Office 215**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **042**
MATERIAL DESCRIPTION: **4" Brown vinyl baseboard adhesive**
MATERIAL LOCATION: **Storage Room 114, Office 215**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways, Corridor Adjacent to 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **043**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
MATERIAL LOCATION: **Stairways, Corridor Adjacent to 114**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Stairways, Corridor Adjacent to 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **044**
MATERIAL DESCRIPTION: **4" Blue vinyl baseboard**
MATERIAL LOCATION: **Stairways, Corridor Adjacent to 114**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Leveling compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 205 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **045**
MATERIAL DESCRIPTION: **Leveling compound**
MATERIAL LOCATION: **Classroom 205 (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Black Mastic on Leveling Compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 205 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **046**
MATERIAL DESCRIPTION: **Black Mastic on Leveling Compound**
MATERIAL LOCATION: **Classroom 205 (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **White sink undercoating**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 103A, 203 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **047**
MATERIAL DESCRIPTION: **White sink undercoating**
MATERIAL LOCATION: **Classrooms 103A, 203 (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **White sink undercoating**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 106, 207A**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **048**
MATERIAL DESCRIPTION: **White sink undercoating**
MATERIAL LOCATION: **Classrooms 106, 207A**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **Insulation of fire door**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **049**
MATERIAL DESCRIPTION: **Insulation of fire door**
MATERIAL LOCATION: **North Building (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **Leveling compound**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 207 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **050**
MATERIAL DESCRIPTION: **Leveling compound**
MATERIAL LOCATION: **Classroom 207 (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Poster board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Classrooms 103, 104, 123 (not observed)**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **051**
MATERIAL DESCRIPTION: **Poster board adhesive**
MATERIAL LOCATION: **Classrooms 103, 104, 123 (not observed)**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Chalk board adhesive**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **Rooms 120, 202, 221 (not observed)**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **052**
MATERIAL DESCRIPTION: **Chalk board adhesive**
MATERIAL LOCATION: **Rooms 120, 202, 221 (not observed)**
MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Sink countertop laminate**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Building Girl' and Boy;s Bathrooms**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Sink countertop laminate**
MATERIAL LOCATION: **South Building Girl' and Boy;s Bathrooms**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Sink countertop laminate adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Building Girl' and Boy;s Bathrooms**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **054**
MATERIAL DESCRIPTION: **Sink countertop laminate adhesive**
MATERIAL LOCATION: **South Building Girl' and Boy;s Bathrooms**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Sink counter caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **South Building Girl' and Boy;s Bathrooms**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **055**
MATERIAL DESCRIPTION: **Sink counter caulk**
MATERIAL LOCATION: **South Building Girl' and Boy;s Bathrooms**
MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **Tub caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **225F (not observed)**

MATERIAL QUANTITY: **10**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **056**
MATERIAL DESCRIPTION: **Tub caulk**
MATERIAL LOCATION: **225F (not observed)**
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **Sink counter top laminate**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **057**
MATERIAL DESCRIPTION: **Sink counter top laminate**
MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Sink counter top laminate adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **058**
MATERIAL DESCRIPTION: **Sink counter top laminate adhesive**
MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms**
MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Sink counter top caulk**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **059**
MATERIAL DESCRIPTION: **Sink counter top caulk**
MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms**
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Mirror adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **South Building Girl's and Boy's Bathrooms (not observed)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Mirror adhesive**
MATERIAL LOCATION: **South Building Girl's and Boy's Bathrooms (not observed)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **Mirror adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms (not observed)**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **Mirror adhesive**
MATERIAL LOCATION: **North Building Girl's and Boy's Bathrooms (not observed)**
MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **Insulation in Firedoors**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Building**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **Insulation in Firedoors**
MATERIAL LOCATION: **South Building**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **Black mastic under carpeting**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms 215, 216 (not observed)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **063**
MATERIAL DESCRIPTION: **Black mastic under carpeting**
MATERIAL LOCATION: **Classrooms 215, 216 (not observed)**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **Brown carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 215**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **064**
MATERIAL DESCRIPTION: **Brown carpet adhesive**
MATERIAL LOCATION: **Classroom 215**
MATERIAL QUANTITY: MATERIAL UNITS:
DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **Tan and Gray Terrazzo Flooring**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Corridors and Stairs, 119A**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **065**
MATERIAL DESCRIPTION: **Tan and Gray Terrazzo Flooring**
MATERIAL LOCATION: **1st and 2nd Floor Corridors and Stairs, 119A**
MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Dark Green Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed 2022**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **066**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Dark Green Floor Tile**
MATERIAL LOCATION: **Room 107**
MATERIAL QUANTITY: MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Dark Green Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **067**
MATERIAL DESCRIPTION: **12" x 12" Light Green w/ Dark Green Floor Tile Mastic**
MATERIAL LOCATION: **Room 107**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **Tan Linoleum and Backing**
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY: **800**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **068**
MATERIAL DESCRIPTION: **Tan Linoleum and Backing**
MATERIAL LOCATION: **Room 120**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 200, 205, 212 and Day Care Room**

MATERIAL QUANTITY: **3200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **069**
MATERIAL DESCRIPTION: **Blue carpet adhesive**
MATERIAL LOCATION: **Rooms 200, 205, 212 and Day Care Room**
MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Green carpet mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 230**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **70**
MATERIAL DESCRIPTION: **Green carpet mastic**
MATERIAL LOCATION: **Room 230**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Lab counter tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY: **200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **71**
MATERIAL DESCRIPTION: **Lab counter tops**
MATERIAL LOCATION: **Room 120**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Lab table tops**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY: **300**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **72**
MATERIAL DESCRIPTION: **Lab table tops**
MATERIAL LOCATION: **Room 120**
MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Air Erosion/Flow Deterioration Physical Damage**
HISTORICAL RESPONSE ACTION: **Remove**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Building, throughout the crawl space**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Engineer reported it was abated 2 yrs ago (need to check), Not observed 2022**

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **A**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **South Building, throughout the crawl space**
MATERIAL QUANTITY: MATERIAL UNITS: **LF**
DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A1**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building throughout the crawlspace, tunnels - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **A1**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **North Building throughout the crawlspace, tunnels - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation Assoc w/Aircell**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACBM**
HISTORICAL DAMAGE REASON: **Air Erosion/Flow
Deterioration
Physical Damage**
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **South Building**

MATERIAL QUANTITY: **100**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation Assoc w/Aircell**
MATERIAL LOCATION: **South Building**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Cementitious joint insulation- aircell pice insula**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **B1**
MATERIAL DESCRIPTION: **Cementitious joint insulation- aircell pice insula**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25152 BUIDLING ID: 5643
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Carol Ashman
SCHOOL NAME: Second Chance High School (Satellite of Peace & Education Coalition High School) INSPECTION DATE: 11/9/2022
ADDRESS: 5114 S. Elizabeth IDPH LICENSE NO: 100-19554

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: C
MATERIAL DESCRIPTION: Paper wrap pipe insulation
HISTORICAL AHERA DAMAGE CATEGORY: 1 Damaged or significantly damaged friable thermal system insulating ACBM
HISTORICAL DAMAGE REASON: Air Erosion/Flow Deterioration Physical Damage
HISTORICAL RESPONSE ACTION: Remove
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: South Building

MATERIAL QUANTITY: 1000

MATERIAL UNITS: LF

DAMAGE QUANTITY:

DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: _____

Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **C**
MATERIAL DESCRIPTION: **Paper wrap pipe insulation**
MATERIAL LOCATION: **South Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C1**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **C1**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: Chicago Public Schools UNIT NUMBER: 25152 BUIDLING ID: 5643
CITY/STATE: Chicago, Illinois AHERA INSPECTOR: Carol Ashman
SCHOOL NAME: Second Chance High School (Satellite of Peace & Education Coalition High School) INSPECTION DATE: 11/9/2022
ADDRESS: 5114 S. Elizabeth IDPH LICENSE NO: 100-19554

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D
MATERIAL DESCRIPTION: Cementitious joint insulation assoc. W/paper wrap
HISTORICAL AHERA DAMAGE CATEGORY: 1 Damaged or significantly damaged friable thermal system insulating ACBM
HISTORICAL DAMAGE REASON: Air Erosion/Flow
Deterioration
Physical Damage
HISTORICAL RESPONSE ACTION: Remove
ASBESTOS TYPE: Chrysotile FRIABLE: Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: HIGH

MATERIAL LOCATION: South Building

MATERIAL QUANTITY: 70

MATERIAL UNITS: LF

DAMAGE QUANTITY:

DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature: _____

Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **D**
MATERIAL DESCRIPTION: **Cementitious joint insulation assoc. W/paper wrap**
MATERIAL LOCATION: **South Building**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D1**
MATERIAL DESCRIPTION: **Joint insulation assoc.w/paperwrap pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **D1**
MATERIAL DESCRIPTION: **Joint insulation assoc.w/paperwrap pipe insulation**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **E**
MATERIAL DESCRIPTION: **Aircell Pipe insulation**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E1**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **E1**
MATERIAL DESCRIPTION: **Aircell pipe insulation**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation Assoc w/Aircell**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **F**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation Assoc w/Aircell**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F1**
MATERIAL DESCRIPTION: **Joint insulation assoc. W/aircell pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **F1**
MATERIAL DESCRIPTION: **Joint insulation assoc. W/aircell pipe insulation**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-001**
MATERIAL DESCRIPTION: **12" x 12" White w/color Specks's Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineers office (111), 113, 115, 116, lunchroom**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **FT-001**
MATERIAL DESCRIPTION: **12" x 12" White w/color Specks's Floor Tile**
MATERIAL LOCATION: **102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineers office (111), 113, 115, 116, lunchroom**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FT-002**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile and Mastic**
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 202 Storage Room**

MATERIAL QUANTITY: **700**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **FT-002**
MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile and Mastic**
MATERIAL LOCATION: **Rooms 202 Storage Room**
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **FTM-001**
MATERIAL DESCRIPTION: **12" x 12" White w/color Specks's Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY: **5 ACBM with the potential for damage**
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Other**
DISTURBANCE POTENTIAL: **LOW**
MATERIAL LOCATION: **102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineer's office (111), 113, 115, 116, lunchroom, 212, 204**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS: **Damaged in rooms 114, 115, engineer's office (111)**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **FTM-001**
MATERIAL DESCRIPTION: **12" x 12" White w/color Specks's Floor Tile Mastic**
MATERIAL LOCATION: **102B, 102A, Admin office, 130, 100, 127, 125, 124, 123, 103, 122, 104, 117, side hallways throughout 1st floor, 115, 112, engineer's office (111), 113, 115, 116, lunchroom, 212, 204**
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY: **1 Damaged or significantly damaged friable thermal system insulating ACM**
HISTORICAL DAMAGE REASON: **Air Erosion/Flow Deterioration Physical Damage**
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **South Building**

MATERIAL QUANTITY: **1000**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____

Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **G**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
MATERIAL LOCATION: **South Building**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G1**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **G1**
MATERIAL DESCRIPTION: **Paperwrap pipe insulation**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: **11/18/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation Assoc w/Paper Wrap**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **NOT CPS LEASED OR OWNED**

Inspector's Signature: _____ Date: 11/09/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUIDLING ID: **5643**
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **H**
MATERIAL DESCRIPTION: **Cementitious Joint Insulation Assoc w/Paper Wrap**
MATERIAL LOCATION: **North Building - NOT CPS LEASED OR OWNED 2016**
MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____



Date: 11/18/2022

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** INSPECTION DATE: **11/9/2022**
ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **070**
MATERIAL DESCRIPTION: **Light tan laminate flooring**
MATERIAL LOCATION: **Room 120**
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE QUANTITY: **0** DAMAGE REASON:
DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature: _____ Date: **11/09/2022**

Chicago Public Schools

Carnow, Conibear and Associates

2022 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25152** BUILDING ID: **5643**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Evan Christian**

SCHOOL NAME: **Second Chance High School (Satellite of Peace & Education Coalition High School)** REVIEW DATE: **11/18/2022**

ADDRESS: **5114 S. Elizabeth** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **070**

MATERIAL DESCRIPTION: **Light tan laminate flooring**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: _____



Date: 11/18/2022

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otsafety.com

2022

OCCUPATIONAL TRAINING & SUPPLY, INC.



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Carol Ashman

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 5/16/2022

Exam Date: 5/16/2022




Expiration Date: 5/16/2023

Certificate Number: BIR2205161413


Kathy Desalvo, Director

Carol Ashman

Illinois Licensed Building Inspector

 ILLINOIS DEPARTMENT OF PUBLIC HEALTH IDPH INTEGRATING SCIENCE EMPOWERING COMMUNITY	ASBESTOS PROFESSIONAL LICENSE	
ID NUMBER 100 - 19554	ISSUED 4/19/2022	EXPIRES 05/15/2023
CAROL L ASHMAN 1633 Mc KAY ST WAUKEGAN, IL 60087 Environmental Health		

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/7/2022
PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/28/2023

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012581

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/3/2022

Exam Date: 11/3/2022

Expiration Date: 11/3/2023

Certificate Number: MPR2211033519


Kathy DeSalvo, Director



ASBESTOS PROFESSIONAL LICENSE

ID NUMBER

100 - 19466

ISSUED

4/22/2022

EXPIRES

05/15/2023

EVAN I CHRISTIAN
1119 N HOYNE AVE, APT 1
CHICAGO, IL 60622

Environmental Health



ENDORSEMENTS

TC EXPIRES

INSPECTOR

10/8/2022

MANAGEMENT PLANNER

11/1/2022

PROJECT MANAGER


3/28/2023

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action

This license issued under authority of the State of Illinois
Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 10/8/2021

Exam Date: 10/8/2021

Expiration Date: 10/8/2022

Certificate Number: BIR2110082264

Kathy DeSalvo, Director



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Evan Christian

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113639

Kathy DeSalvo, Director -

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed