

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2412
SCHOOL NAME: Prussing School
ADDRESS OF SCHOOL: 4650 N Menard Avenue
CITY: Chicago, IL, 60630

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/1/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 2/27/2025 ENROLLMENT 661
IDPH INSPECTOR LICENSE NUMBER: 100-11093
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 3/20/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Prussing School

4650 N Menard Avenue
Chicago, IL, 60630

Unit: 25031
Building ID: 5510

IDPH ID Number: 14-016-2990-2412

REPORT DATE:
Thursday, March 20, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Specialty Consulting, Inc.

2942 W. Van Buren Street
Chicago, IL, 60612
Phone (312) 319-7575
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

03/20/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25031 Region: 01 IDPH ID: 14-016-2990-2412

School: Prussing School Building ID: 5510

Address: 4650 N Menard Avenue

Chicago, IL, 60630

Building Contact: Rooney, Brian Contact Phone: 3125436491

Current Building Owners: Chicago Public Schools

Reinspection Date: 2/27/2025

Review Date: 03/20/2025

Inspector: David Avila

Inspector IDPH License: 100-11093

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: March 20, 2025

RE: Prussing School, Unit 25031
4650 N Menard Avenue
Chicago, IL, 60630

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Prussing School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Prussing School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Prussing School Unit: 25031 Region: 01
Address: 4650 N Menard Avenue Chicago, IL, 60630
IDPH ID: 14-016-2990-2412 Building ID: 5510
Contact: Rooney, Brian Phone: 3125436491

2. Description of Facility

Original Construction: 1927 Additional Construction: 2019
Total Square Footage: 66493 No of Floors: 2
Current Occupancy: 661

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: David Avila

Inspector IDPH license # 100-11093
Reinspection Date: 2/27/2025

Signature:
Date: 2/27/2025



6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342

Signature:
Date: 03/20/2025




7. Review Date: 03/20/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 3/20/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Prussing School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 5510:

B. The following new homogenous areas have been identified for Building 5510:

- 66 2' x 2' Pinhole Ceiling Tile
- 67 12"x12" Royal Blue with white specks VFT
- 68 12"x12" Royal Blue with white specks VFT Mastic
- 69 12"x12" White with specks VFT
- 70 12"x12" White with specks VFT Mastic
- 71 12"x12" Sky Blue with specks VFT
- 72 12"x12" Sky Blue with specks VFT Mastic
- 73 12"x12" Yellow with specks VFT
- 74 12"x12" Yellow with specks VFT Mastic
- 75 2' x 2' Pinhole Ceiling Tile
- 76 Drywall System
- 77 12"x12" Beige with specks VFT
- 78 12"x12" Beige with specks VFT Mastic
- 79 Drywall System
- 80 2' x 2' Pinhole Ceiling Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|-----|---|
| 26 | 12"x12" Beige w/ Multiple Streaks VFT |
| 32 | Interior Window Caulk |
| 33 | Blown In Insulation |
| 34 | 2' x 4' White w/ Speckles Ceiling Tile |
| 36 | 2' x 8' Tectum Walls |
| 37 | Spray Applied Plaster Wall |
| 38 | 12"x12" Gray w/ Brown Streaks VFT |
| 39 | 12"x12" Off White w/ Brown Streaks VFT |
| 40 | 12"x12" Light Blue w/ White Streaks VFT |
| 41 | 2'x4' White Plain Ceiling Tile |
| 42 | 12"x12" Gray w/ Brown Streaks VFT Mastic |
| 43 | 12"x12" Off White w/ Brown Streaks VFT Mastic |
| 45 | Terrazzo |
| 46 | Decorative Plaster |
| 47 | Drywall, Tape and Compound |
| 48 | Drywall, Tape and Compound - Mobile no longer on-site |
| 49 | 2'x4' White Ceiling Tiles - Mobile no longer on-site |
| 50 | 12"x12" White w/Streaks VFT - Mobile no longer on-site |
| 50A | 12"x12" White w/Streaks VFT Mastic - Mobile no longer on-site |
| 51 | Drywall, Tape, and Compound - Mobile no longer on-site |
| 52 | 2'x4' White Ceiling Tiles - Mobile no longer on-site |
| 53 | 12"x12" White w/Streaks VFT - Mobile no longer on-site |
| 53A | 12"X12" White w/Streaks VFT Mastic - Mobile no longer on-site |
| 54 | Blue Linoleum - Mobile no longer on-site |
| 54A | Blue Linoleum Mastic - Mobile no longer on-site |
| 55 | Pink Linoleum - Mobile no longer on-site |
| 55A | Pink Linoleum Mastic - Mobile no longer on-site |
| 56 | Fire Doors |
| 57 | Breaching Insulation |
| 58 | Lining Insulation |
| 59 | Incineration Burner Gasket |
| 60 | BEH Baldwin EHRCT Hill Insulation Cement |
| 61 | Kaylo Block Insulation |
| 62 | 12"x12" White w/ Gray Specks VFT |
| 63 | 12"x12" White w/ Gray Specks VFT Mastic |
| 64 | 12"x12" Blue w/ Specks VFT |

| | |
|----|---|
| 65 | 12"x12" Blue w/ Specks VFT Mastic |
| 66 | 2' x 2' Pinhole Ceiling Tile |
| 67 | 12"x12" Royal Blue with white specks VFT |
| 68 | 12"x12" Royal Blue with white specks VFT Mastic |
| 69 | 12"x12" White with specks VFT |
| 70 | 12"x12" White with specks VFT Mastic |
| 71 | 12"x12" Sky Blue with specks VFT |
| 72 | 12"x12" Sky Blue with specks VFT Mastic |
| 73 | 12"x12" Yellow with specks VFT |
| 74 | 12"x12" Yellow with specks VFT Mastic |
| 75 | 2' x 2' Pinhole Ceiling Tile |
| 76 | Drywall System |
| 77 | 12"x12" Beige with specks VFT |
| 78 | 12"x12" Beige with specks VFT Mastic |
| 79 | Drywall System |
| 80 | 2' x 2' Pinhole Ceiling Tile |
| A | Carpet Mastic |

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 12/27/2024
12/27/2024

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Prussing School Building 5510 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 03 | MJP E/F/V on Mag Block Pipe Insulation | 24 | FITTING | Crawl Space, Engine Rooms/Auditorium Tunnel, & All Mechanical Areas, Room 101, Kitchen - Main Building | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 06 | MJP E/F/V on Aircell Pipe Insulation | 166 | FITTING | Engine Room, E. Crawl Space, N. Crawl Space, SW Tunnel, & Aud. Crawl Spaces - Main Building | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 08 | MJP E/F/V on Cardboard Pipe Insulation | 121 | FITTING | Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 09 | Cardboard Pipe Insulation | 2,255 | LF | S. Auditorium, Engine Room/Assembly Hall Tunnel, SW Tunnel, & Main Tunnel - Main Building | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 10 | Debris On Dirt Floor | 35,000 | SF | North Crawl Spaces, Main East Crawl Spaces, & SW Tunnel - Main Building | CHR | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 11 | Duct Insulation | 2,000 | SF | Main East Crawl Spaces & North Crawl Spaces - Main Building | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 12 | Aircell Pipe Insulation | 3,000 | LF | Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 13 | Mag Block Pipe Insulation | 450 | LF | Engine Room, Main Tunnel, South Fan Room, North Fan Room, North Engine Room, S. | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 36 | 2' x 8' Tectum Walls | 5,000 | SF | Building - ABATED Gymnasium - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 37 | Spray Applied Plaster Wall | 600 | SF | Auditorium Hallway and Stage and Vestibule - Main Building | ASSUMED | SURFACE | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 38 | 12"x12" Gray w/ Brown Streaks VFT | 400 | SF | Room 210 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 39 | 12"x12" Off White w/ Brown Streaks VFT | 400 | SF | Rooms 210 and 113 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 40 | 12"x12" Light Blue w/ White Streaks VFT | 1,458 | SF | Rooms 215 (under carpet), 105, 105.5 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 41 | 2'x4' White Plain Ceiling Tile | 1,400 | SF | Rooms 200A, 101A, 212 - Main Building | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 42 | 12"x12" Gray w/ Brown Streaks VFT Mastic | 400 | SF | Room 210 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 43 | 12"x12" Off White w/ Brown Streaks VFT Mastic | 400 | SF | Rooms 210 and 113 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 44 | 12"x12" Light Blue w/ White Streaks Mastic | 1,458 | SF | Room 215 (Under Carpet), 105, 105.5 - Main Building | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 45 | Terrazzo | 4,800 | SF | Assembly Rear Stage Stairs, Vestibule, and Balcony Stairs; Stairwell Treads & Landings & Vestibules; Rm 215 Stairs; 1st and 2nd Floor Corridor Border & Classroom Entrances; Room 200 & Closet; Vestibule in Room 103 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 46 | Decorative Plaster | 200 | SF | Assembly Hall Stage - Main Building | ASSUMED | SURFACE | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 47 | Drywall, Tape and Compound | 300 | SF | Rooms 114 and 200B - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 48 | Drywall, Tape and Compound - Mobile no longer on-site | 5,000 | SF | Throughout 1999 Mobile - Mobile no | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | longer on-site | | | | | | | | | | |
| 49 | 2'x4' White Ceiling Tiles - Mobile no longer on-site | 3,500 | SF | Throughout 1999 Mobile - Mobile no longer on-site | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 50 | 12"x12" White w/Streaks VFT - Mobile no longer on-site | 3,500 | SF | Throughout 1999 Mobile - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 50A | 12"x12" White w/Streaks VFT Mastic - Mobile no longer on-site | 3,500 | SF | Throughout 1999 Mobile - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 51 | Drywall, Tape, and Compound - Mobile no longer on-site | 10,500 | SF | Throughout 2003 Mobile - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 52 | 2'x4' White Ceiling Tiles - Mobile no longer on-site | 6,500 | SF | Throughout 2003 Mobile - Mobile no longer on-site | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 53 | 12"x12" White w/Streaks VFT - Mobile no longer on-site | 6,000 | SF | Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 53A | 12"X12" White w/Streaks VFT Mastic - Mobile no longer on-site | 6,000 | SF | Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 54 | Blue Linoleum - Mobile no longer on-site | 250 | SF | Boys Toilet - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 54A | Blue Linoleum Mastic - Mobile no longer on-site | 250 | SF | Boys Toilet - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 55 | Pink Linoleum - Mobile no longer on-site | 250 | SF | Girls Toilet - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 55A | Pink Linoleum Mastic - Mobile no longer on-site | 250 | SF | Girls Toilet - Mobile no longer on-site | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 56 | Fire Doors | 2 | EA | Balcony and Projector Room - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 57 | Breaching Insulation | 100 | SF | Boiler Room - Main Building | ASSUMED | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 58 | Lining Insulation | 4 | SF | Incinerator Hatch in Boiler Room - Main Building | ASSUMED | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 59 | Incineration Burner Gasket | 2 | LF | Boiler Room - Main Building | ASSUMED | TSI | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 60 | BEH Baldwin EHRCT Hill Insulation Cement | 50 | LF | Unfinished Pipe Space - Main Building | ASSUMED | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 61 | Kaylo Block Insulation | 10 | SF | Unfinished Pipe Space - Main Building | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 62 | 12"x12" White w/ Gray Specks VFT | 800 | SF | Room 101 and 103 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 63 | 12"x12" White w/ Gray Specks VFT Mastic | 800 | SF | Room 101 and 103 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 64 | 12"x12" Blue w/ Specks VFT | 800 | SF | Room 101 and 103 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 65 | 12"x12" Blue w/ Specks VFT Mastic | 800 | SF | Room 101 and 103 - Main Building | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 66 | 2' x 2' Pinhole Ceiling Tile | 1,600 | SF | Room 101, 103 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 67 | 12"x12" Royal Blue with white specks VFT | 300 | SF | West Modular Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 68 | 12"x12" Royal Blue with white specks VFT Mastic | 300 | SF | West Modular Corridor | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 69 | 12"x12" White with specks VFT | 1,345 | SF | Corridor, rooms 03, 04, 05, 06 - West Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 70 | 12"x12" White with specks VFT Mastic | 1,345 | SF | Corridor, rooms 03, 04, 05, 06 - West Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 71 | 12"x12" Sky Blue with specks VFT | 1,045 | SF | Rooms 03, 04, 05, 06 - West Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 72 | 12"x12" Sky Blue with specks VFT Mastic | 1,045 | SF | Rooms 03, 04, 05, 06 - West Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 73 | 12"x12" Yellow with specks VFT | 1,045 | SF | Rooms 03, 04, 05, 06 - West Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 74 | 12"x12" Yellow with specks VFT Mastic | 1,045 | SF | Rooms 03, 04, 05, 06 - West Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 75 | 2' x 2' Pinhole Ceiling Tile | 4,300 | SF | Throughout - West Modular | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 76 | Drywall System | 4,000 | SF | Throughout - West Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 77 | 12"x12" Beige with specks VFT | 5,050 | SF | Throughout - East Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 78 | 12"x12" Beige with specks VFT Mastic | 5,050 | SF | Throughout - East Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 79 | Drywall System | 4,000 | SF | Throughout - East Modular | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 80 | 2' x 2' Pinhole Ceiling Tile | 5,430 | SF | Throughout - East Modular | ASSUMED | MISC | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| A | Carpet Mastic | 4,200 | SF | Engineer's Office, and Rooms 212, 213-215, Assembly Aisles, Library (Room 213) | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Prussing School Unit 25031 Building ID 5510
Address 4650 N Menard Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| |
|---|
| Reinspection Date <u>2/27/2025</u> |
| Inspector Name <u>David Avila</u> |
| <u>100-11093</u> <u>5/15/2026</u> |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 03 | |
| 06 | |
| 08 | |
| 09 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 17 | |
| 25 | |
| 26 | |
| 28 | |
| 29 | |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 40 | |
| 41 | |

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 47 | |
| 48 | |
| 49 | |
| 50 | |
| 50A | |
| 51 | |
| 52 | |
| 53 | |
| 53A | |
| 54 | |
| 54A | |
| 55 | |
| 55A | |
| 56 | |
| 57 | |
| 58 | |
| 59 | |
| 60 | |
| 61 | |
| 62 | |
| 63 | |
| 64 | |
| 65 | |
| 66 | |

Chicago Public Schools

School Prussing School **Unit** 25031 **Building ID** 5510
Address 4650 N Menard Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 67 | |
| 68 | |
| 69 | |
| 70 | |
| 71 | |
| 72 | |
| 73 | |
| 74 | |
| 75 | |
| 76 | |
| 77 | |
| 78 | |
| 79 | |
| 80 | |
| A | |

Table II
Management Planner's Review

Chicago Public Schools

School Prussing School

Unit 25031

Building ID 5510

Address 4650 N Menard Avenue

Chicago, IL, 60630

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 03 | MJP E/F/V on Mag Block Pipe Insulation | 24 | FITTING | Crawl Space, Engine Rooms/Auditorium Tunnel, & All Mechanical Areas, Room 101, Kitchen - Main Building | Chrysotile | TSI | Yes | 0 | FITTING | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06 | MJP E/F/V on Aircell Pipe Insulation | 166 | FITTING | Engine Room, E. Crawl Space, N. Crawl Space, SW Tunnel, & Aud. Crawl Spaces - Main Building | Chrysotile | TSI | Yes | 0 | FITTING | 6 ACBM with the potential for damage | Follow O&M Plan |
| 08 | MJP E/F/V on Cardboard Pipe Insulation | 121 | FITTING | Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building | Chrysotile | TSI | Yes | 0 | FITTING | 6 ACBM with the potential for damage | Follow O&M Plan |
| 09 | Cardboard Pipe Insulation | 2,255 | LF | S. Auditorium, Engine Room/Assembly Hall Tunnel, SW Tunnel, & Main Tunnel - Main Building | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10 | Debris On Dirt Floor | 35,000 | SF | North Crawl Spaces, Main East Crawl Spaces, & SW Tunnel - Main Building | Chrysotile | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11 | Duct Insulation | 2,000 | SF | Main East Crawl Spaces & North Crawl Spaces - Main Building | Chrysotile | TSI | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12 | Aircell Pipe Insulation | 3,000 | LF | Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 13 | Mag Block Pipe Insulation | 450 | LF | Engine Room, Main Tunnel, South Fan Room, North Fan Room, North Engine Room, S. Auditorium Engine Rm - Main Building | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 17 | 9"x9" Grey w/ Pink Streaks VFT | 1,920 | SF | Room 300B Closet, Room 300A (Principals & Asst. Principals Off. & Conference Room) Engineer's Office (under Carpet) - Main Building - NOT OBSERVED | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 25 | 9"x9" Brown w/ White Streaks VFT (Abated) | | | Room 110, MDF Room (103 Closet) (Abated) - Main Building | Abated | MISC | | | | | |
| 26 | 12"x12" Beige w/ Multiple Streaks VFT | 12,115 | SF | 1st & 2nd Floor Corridors, Rooms 200B & 200A, 212, 214, 114, 111, 101A, 100 Office, Gym Office, Room 108 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28 | 9"x9" Brown w/ White Streaks VFT Mastic (Abated) | | | Room 110, MDF Room (103 Closet) | Abated | MISC | | | | | |

Chicago Public Schools

School Prussing School

Unit 25031

Building ID 5510

Address 4650 N Menard Avenue

Chicago, IL, 60630

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| | | | | (Abated) - Main Building | | | | | | | |
| 29 | 12"x12" Beige w/ Multiple Streaks VFT Mastic | 12,115 | SF | 1st & 2nd Floor Corridors, Rooms 200B & 200A, 114, 111, 101A, 100 Office, 212, 214, Gym Office, Room 108 - Main Building | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31 | Exterior Window Caulk | 2,000 | LF | Exterior Windows - Main Building | Chrysotile | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32 | Interior Window Caulk | 2,000 | LF | Interior Windows - Main Building | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 33 | Blown In Insulation | 20,000 | SF | Attic - Main Building | Assumed | SURFACE | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 34 | 2' x 4' White w/ Speckles Ceiling Tile | 20,000 | SF | Stairwells, 2nd Floor Corridor, Room 200, 200B, 213 (Library), 214, 215 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 35 | 2' x 2' Tectum Ceiling Tile - ABATED | | | Gymnasium - Main Building - ABATED | Abated | MISC | | | | | |
| 36 | 2' x 8' Tectum Walls | 5,000 | SF | Gymnasium - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 37 | Spray Applied Plaster Wall | 600 | SF | Auditorium Hallway and Stage and Vestibule - Main Building | Assumed | SURFACE | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 38 | 12"x12" Gray w/ Brown Streaks VFT | 400 | SF | Room 210 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 39 | 12"x12" Off White w/ Brown Streaks VFT | 400 | SF | Rooms 210 and 113 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 40 | 12"x12" Light Blue w/ White Streaks VFT | 1,458 | SF | Rooms 215 (under carpet), 105, 105.5 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 41 | 2'x4' White Plain Ceiling Tile | 1,400 | SF | Rooms 200A, 101A, 212 - Main Building | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 42 | 12"x12" Gray w/ Brown Streaks VFT Mastic | 400 | SF | Room 210 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 43 | 12"x12" Off White w/ Brown Streaks VFT Mastic | 400 | SF | Rooms 210 and 113 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 44 | 12"x12" Light Blue w/ White Streaks Mastic | 1,458 | SF | Room 215 (Under Carpet), 105, 105.5 - Main Building | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 45 | Terrazzo | 4,800 | SF | Assembly Rear Stage Stairs, Vestibule, and Balcony Stairs; Stairwell Treads & Landings & Vestibules; Rm 215 Stairs; 1st and 2nd Floor Corridor Border & Classroom Entrances; Room 200 & Closet; Vestibule in Room 103 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 46 | Decorative Plaster | 200 | SF | Assembly Hall Stage - Main Building | Assumed | SURFACE | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 47 | Drywall, Tape and Compound | 300 | SF | Rooms 114 and 200B - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 48 | Drywall, Tape and Compound - Mobile no longer on-site | 5,000 | SF | Throughout 1999 Mobile - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Prussing School

Unit 25031

Building ID 5510

Address 4650 N Menard Avenue

Chicago, IL, 60630

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|---|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 49 | 2'x4' White Ceiling Tiles - Mobile no longer on-site | 3,500 | SF | Throughout 1999 Mobile - Mobile no longer on-site | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 50 | 12"x12" White w/Streaks VFT - Mobile no longer on-site | 3,500 | SF | Throughout 1999 Mobile - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 50A | 12"x12" White w/Streaks VFT Mastic - Mobile no longer on-site | 3,500 | SF | Throughout 1999 Mobile - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 51 | Drywall, Tape, and Compound - Mobile no longer on-site | 10,500 | SF | Throughout 2003 Mobile - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 52 | 2'x4' White Ceiling Tiles - Mobile no longer on-site | 6,500 | SF | Throughout 2003 Mobile - Mobile no longer on-site | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 53 | 12"x12" White w/Streaks VFT - Mobile no longer on-site | 6,000 | SF | Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 53A | 12"X12" White w/Streaks VFT Mastic - Mobile no longer on-site | 6,000 | SF | Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 54 | Blue Linoleum - Mobile no longer on-site | 250 | SF | Boys Toilet - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 54A | Blue Linoleum Mastic - Mobile no longer on-site | 250 | SF | Boys Toilet - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 55 | Pink Linoleum - Mobile no longer on-site | 250 | SF | Girls Toilet - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 55A | Pink Linoleum Mastic - Mobile no longer on-site | 250 | SF | Girls Toilet - Mobile no longer on-site | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 56 | Fire Doors | 2 | EA | Balcony and Projector Room - Main Building | Assumed | MISC | No | 0 | EA | 6 ACBM with the potential for damage | Follow O&M Plan |
| 57 | Breaching Insulation | 100 | SF | Boiler Room - Main Building | Assumed | TSI | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 58 | Lining Insulation | 4 | SF | Incinerator Hatch in Boiler Room - Main Building | Assumed | TSI | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 59 | Incineration Burner Gasket | 2 | LF | Boiler Room - Main Building | Assumed | TSI | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 60 | BEH Baldwin EHRCT Hill Insulation Cement | 50 | LF | Unfinished Pipe Space - Main Building | Assumed | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 61 | Kaylo Block Insulation | 10 | SF | Unfinished Pipe Space - Main Building | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 62 | 12"x12" White w/ Gray Specks VFT | 800 | SF | Room 101 and 103 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 63 | 12"x12" White w/ Gray Specks VFT Mastic | 800 | SF | Room 101 and 103 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 64 | 12"x12" Blue w/ Specks VFT | 800 | SF | Room 101 and 103 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 65 | 12"x12" Blue w/ Specks VFT Mastic | 800 | SF | Room 101 and 103 - Main Building | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 66 | 2' x 2' Pinhole Ceiling Tile | 1,600 | SF | Room 101, 103 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 67 | 12"x12" Royal Blue with white specks VFT | 300 | SF | West Modular Corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 68 | 12"x12" Royal Blue with white specks VFT Mastic | 300 | SF | West Modular Corridor | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 69 | 12"x12" White with specks VFT | 1,345 | SF | Corridor, rooms 03, 04, 05, 06 - West | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Prussing School

Unit 25031

Building ID 5510

Address 4650 N Menard Avenue

Chicago, IL, 60630

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 70 | 12"x12" White with specks VFT Mastic | 1,345 | SF | Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 71 | 12"x12" Sky Blue with specks VFT | 1,045 | SF | Corridor, rooms 03, 04, 05, 06 - West Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 72 | 12"x12" Sky Blue with specks VFT Mastic | 1,045 | SF | Rooms 03, 04, 05, 06 - West Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 73 | 12"x12" Yellow with specks VFT | 1,045 | SF | Rooms 03, 04, 05, 06 - West Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 74 | 12"x12" Yellow with specks VFT Mastic | 1,045 | SF | Rooms 03, 04, 05, 06 - West Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 75 | 2' x 2' Pinhole Ceiling Tile | 4,300 | SF | Throughout - West Modular | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 76 | Drywall System | 4,000 | SF | Throughout - West Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 77 | 12"x12" Beige with specks VFT | 5,050 | SF | Throughout - East Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 78 | 12"x12" Beige with specks VFT Mastic | 5,050 | SF | Throughout - East Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 79 | Drywall System | 4,000 | SF | Throughout - East Modular | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 80 | 2' x 2' Pinhole Ceiling Tile | 5,430 | SF | Throughout - East Modular | Assumed | MISC | Yes | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| A | Carpet Mastic | 4,200 | SF | Engineer's Office, and Rooms 212, 213-215, Assembly Aisles, Library (Room 213) | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Prussing School

Unit 25031

Building ID 5510

Address 4650 N Menard Avenue

Chicago, IL, 60630

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|------------|
| Review Date | 3/20/2025 |
| Manager Planner Name | Jigar Shah |
| 100-07342 | 5/15/2026 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 03 | |
| 06 | |
| 08 | |
| 09 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 17 | |
| 25 | |
| 26 | |
| 28 | |
| 29 | |
| 31 | |
| 32 | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |

Chicago Public Schools

School Prussing School

Unit 25031

Building ID 5510

Address 4650 N Menard Avenue

Chicago, IL, 60630

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 47 | |
| 48 | |
| 49 | |
| 50 | |
| 50A | |
| 51 | |
| 52 | |
| 53 | |
| 53A | |
| 54 | |
| 54A | |
| 55 | |
| 55A | |
| 56 | |
| 57 | |
| 58 | |
| 59 | |
| 60 | |
| 61 | |
| 62 | |

Chicago Public Schools

School Prussing School

Unit 25031

Building ID 5510

Address 4650 N Menard Avenue

Chicago, IL, 60630

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 63 | |
| 64 | |
| 65 | |
| 66 | |
| 67 | |
| 68 | |
| 69 | |
| 70 | |
| 71 | |
| 72 | |
| 73 | |
| 74 | |
| 75 | |
| 76 | |
| 77 | |
| 78 | |
| 79 | |
| 80 | |
| A | |

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA RE/INSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 03 | | |
| MATERIAL DESCRIPTION: | MJP E/F/V on Mag Block Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----------------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Crawl Space, Engine Rooms/Auditorium Tunnel, & All Mechanical Areas, Room 101, Kitchen - Main Building | | |
| MATERIAL QUANTITY: | 24 | MATERIAL UNITS: | FITTING |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | FITTING |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **MJP E/F/V on Mag Block Pipe Insulation**

MATERIAL LOCATION: **Crawl Space, Engine Rooms/Auditorium Tunnel, & All Mechanical Areas, Room 101, Kitchen - Main Building**

MATERIAL QUANTITY: **24** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 06 | | |
| MATERIAL DESCRIPTION: | MJP E/F/V on Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|---------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Engine Room, E. Crawl Space, N. Crawl Space, SW Tunnel, & Aud. Crawl Spaces - Main Building | | |
| MATERIAL QUANTITY: | 166 | MATERIAL UNITS: | FITTING |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | FITTING |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Engine Room, E. Crawl Space, N. Crawl Space, SW Tunnel, & Aud. Crawl Spaces - Main Building**

MATERIAL QUANTITY: **166** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 08 | | |
| MATERIAL DESCRIPTION: | MJP E/F/V on Cardboard Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----------------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building | | |
| MATERIAL QUANTITY: | 121 | MATERIAL UNITS: | FITTING |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | FITTING |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building**

MATERIAL QUANTITY: **121** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 09 | | |
| MATERIAL DESCRIPTION: | Cardboard Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **S. Auditorium, Engine Room/Assembly Hall Tunnel, SW Tunnel, & Main Tunnel - Main Building**

MATERIAL QUANTITY: **2255** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **02/27/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **S. Auditorium, Engine Room/Assembly Hall Tunnel, SW Tunnel, & Main Tunnel - Main Building**

MATERIAL QUANTITY: **2255** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 10 | | |
| MATERIAL DESCRIPTION: | Debris On Dirt Floor | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | North Crawl Spaces, Main East Crawl Spaces, & SW Tunnel - Main Building | | |
| MATERIAL QUANTITY: | 35000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Debris On Dirt Floor**

MATERIAL LOCATION: **North Crawl Spaces, Main East Crawl Spaces, & SW Tunnel - Main Building**

MATERIAL QUANTITY: **35000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 11 | | |
| MATERIAL DESCRIPTION: | Duct Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Main East Crawl Spaces & North Crawl Spaces - Main Building | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Duct Insulation**

MATERIAL LOCATION: **Main East Crawl Spaces & North Crawl Spaces - Main Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 12 | | |
| MATERIAL DESCRIPTION: | Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building

MATERIAL QUANTITY: 3000 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm. - Main Building**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 13 | | |
| MATERIAL DESCRIPTION: | Mag Block Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Engine Room, Main Tunnel, South Fan Room, North Fan Room, North Engine Room, S. Auditorium Engine Rm - Main Building | | |
| MATERIAL QUANTITY: | 450 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Engine Room, Main Tunnel, South Fan Room, North Fan Room, North Engine Room, S. Auditorium Engine Rm - Main Building**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 17 | | |
| MATERIAL DESCRIPTION: | 9"x9" Grey w/ Pink Streaks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 300B Closet, Room 300A (Principals & Asst. Principals Off. & Conference Room) Engineer's Office (under Carpet) - Main Building - NOT OBSERVED | | |
| MATERIAL QUANTITY: | 1920 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9"x9" Grey w/ Pink Streaks VFT**

MATERIAL LOCATION: **Room 300B Closet, Room 300A
(Principals & Asst. Principals Off.& Conference Room) Engineer's Office (under Carpet) - Main Building - NOT OBSERVED**

MATERIAL QUANTITY: **1920** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25

MATERIAL DESCRIPTION: 9"x9" Brown w/ White Streaks VFT (Abated)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110, MDF Room (103 Closet) (Abated) - Main Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT (Abated)**

MATERIAL LOCATION: **Room 110, MDF Room (103 Closet) (Abated) - Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 26 | | |
| MATERIAL DESCRIPTION: | 12"x12" Beige w/ Multiple Streaks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 200B & 200A, 212, 214, 114, 111, 101A, 100 Office, Gym Office, Room 108 - Main Building**

MATERIAL QUANTITY: **12115** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/27/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Multiple Streaks VFT**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 200B & 200A, 212, 214, 114, 111, 101A, 100 Office, Gym Office, Room 108 - Main Building**

MATERIAL QUANTITY: **12115** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: 9"x9" Brown w/ White Streaks VFT Mastic (Abated)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110, MDF Room (103 Closet) (Abated) - Main Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9"x9" Brown w/ White Streaks VFT Mastic (Abated)**

MATERIAL LOCATION: **Room 110, MDF Room (103 Closet) (Abated) - Main Building**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 29 | | |
| MATERIAL DESCRIPTION: | 12"x12" Beige w/ Multiple Streaks VFT Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 200B & 200A, 114, 111, 101A, 100 Office, 212, 214, Gym Office, Room 108 - Main Building**

MATERIAL QUANTITY: **12115** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/27/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Multiple Streaks VFT Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 200B & 200A, 114, 111, 101A, 100 Office, 212, 214, Gym Office, Room 108 - Main Building**

MATERIAL QUANTITY: **12115** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 31 | | |
| MATERIAL DESCRIPTION: | Exterior Window Caulk | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Exterior Windows - Main Building | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **Exterior Windows - Main Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 32 | | |
| MATERIAL DESCRIPTION: | Interior Window Caulk | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Interior Windows - Main Building | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Interior Windows - Main Building**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 33 | | |
| MATERIAL DESCRIPTION: | Blown In Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Attic - Main Building | | |
| MATERIAL QUANTITY: | 20000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Blown In Insulation**

MATERIAL LOCATION: **Attic - Main Building**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 34 | | |
| MATERIAL DESCRIPTION: | 2' x 4' White w/ Speckles Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Stairwells, 2nd Floor Corridor, Room 200, 200B, 213 (Library), 214, 215 - Main Building | | |
| MATERIAL QUANTITY: | 20000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **2' x 4' White w/ Speckles Ceiling Tile**

MATERIAL LOCATION: **Stairwells, 2nd Floor Corridor, Room 200, 200B, 213 (Library), 214, 215 - Main Building**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35
MATERIAL DESCRIPTION: 2' x 2' Tectum Ceiling Tile - ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gymnasium - Main Building - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **2' x 2' Tectum Ceiling Tile - ABATED**

MATERIAL LOCATION: **Gymnasium - Main Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 36 | | |
| MATERIAL DESCRIPTION: | 2' x 8' Tectum Walls | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Gymnasium - Main Building | | |
| MATERIAL QUANTITY: | 5000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **02/27/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **2' x 8' Tectum Walls**

MATERIAL LOCATION: **Gymnasium - Main Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 37 | | |
| MATERIAL DESCRIPTION: | Spray Applied Plaster Wall | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Auditorium Hallway and Stage and Vestibule - Main Building | | |
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Spray Applied Plaster Wall**

MATERIAL LOCATION: **Auditorium Hallway and Stage and Vestibule - Main Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 38 | | |
| MATERIAL DESCRIPTION: | 12"x12" Gray w/ Brown Streaks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 210 - Main Building | | |
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Brown Streaks VFT**

MATERIAL LOCATION: **Room 210 - Main Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 39 | | |
| MATERIAL DESCRIPTION: | 12"x12" Off White w/ Brown Streaks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rooms 210 and 113 - Main Building | | |
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Streaks VFT**

MATERIAL LOCATION: **Rooms 210 and 113 - Main Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 40 | | |
| MATERIAL DESCRIPTION: | 12"x12" Light Blue w/ White Streaks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rooms 215 (under carpet), 105, 105.5 - Main Building | | |
| MATERIAL QUANTITY: | 1458 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks VFT**

MATERIAL LOCATION: **Rooms 215 (under carpet), 105, 105.5 - Main Building**

MATERIAL QUANTITY: **1458** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 41 | | |
| MATERIAL DESCRIPTION: | 2'x4' White Plain Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 200A, 101A, 212 - Main Building | | |
| MATERIAL QUANTITY: | 1400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **2'x4' White Plain Ceiling Tile**

MATERIAL LOCATION: **Rooms 200A, 101A, 212 - Main Building**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 42 | | |
| MATERIAL DESCRIPTION: | 12"x12" Gray w/ Brown Streaks VFT Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 210 - Main Building | | |
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Room 210 - Main Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 43 | | |
| MATERIAL DESCRIPTION: | 12"x12" Off White w/ Brown Streaks VFT Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 210 and 113 - Main Building | | |
| MATERIAL QUANTITY: | 400 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12"x12" Off White w/ Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 210 and 113 - Main Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 44 | | |
| MATERIAL DESCRIPTION: | 12"x12" Light Blue w/ White Streaks Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 215 (Under Carpet), 105, 105.5 - Main Building | | |
| MATERIAL QUANTITY: | 1458 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12"x12" Light Blue w/ White Streaks Mastic**

MATERIAL LOCATION: **Room 215 (Under Carpet), 105, 105.5 - Main Building**

MATERIAL QUANTITY: **1458** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 45 | | |
| MATERIAL DESCRIPTION: | Terrazzo | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Assembly Rear Stage Stairs, Vestbule, and Balcony Stairs; Stairwell Treads & Landings & Vestibules; Rm 215 Stairs; 1st and 2nd Floor Corridor Border & Classroom Entrances; Room 200 & Closet; Vestbule in Room 103 - Main Building | | |
| MATERIAL QUANTITY: | 4800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Assembly Rear Stage Stairs, Vestibule, and Balcony Stairs; Stairwell Treads & Landings & Vestibules; Rm 215 Stairs; 1st and 2nd Floor Corridor Border & Classroom Entrances; Room 200 & Closet; Vestibule in Room 103 - Main Building**

MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 46 | | |
| MATERIAL DESCRIPTION: | Decorative Plaster | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Assembly Hall Stage - Main Building | | |
| MATERIAL QUANTITY: | 200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Assembly Hall Stage - Main Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 47 | | |
| MATERIAL DESCRIPTION: | Drywall, Tape and Compound | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|------------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rooms 114 and 200B - Main Building | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Drywall, Tape and Compound**

MATERIAL LOCATION: **Rooms 114 and 200B - Main Building**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 48 | | |
| MATERIAL DESCRIPTION: | Drywall, Tape and Compound - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Throughout 1999 Mobile - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 5000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Drywall, Tape and Compound - Mobile no longer on-site**

MATERIAL LOCATION: **Throughout 1999 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 49 | | |
| MATERIAL DESCRIPTION: | 2'x4' White Ceiling Tiles - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout 1999 Mobile - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 3500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **2'x4' White Ceiling Tiles - Mobile no longer on-site**

MATERIAL LOCATION: **Throughout 1999 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 50 | | |
| MATERIAL DESCRIPTION: | 12"x12" White w/Streaks VFT - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Throughout 1999 Mobile - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 3500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12"x12" White w/Streaks VFT - Mobile no longer on-site**

MATERIAL LOCATION: **Throughout 1999 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 50A | | |
| MATERIAL DESCRIPTION: | 12"x12" White w/Streaks VFT Mastic - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout 1999 Mobile - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 3500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **50A**

MATERIAL DESCRIPTION: **12"x12" White w/Streaks VFT Mastic - Mobile no longer on-site**

MATERIAL LOCATION: **Throughout 1999 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 51 | | |
| MATERIAL DESCRIPTION: | Drywall, Tape, and Compound - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Throughout 2003 Mobile - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 10500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **02/27/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Drywall, Tape, and Compound - Mobile no longer on-site**

MATERIAL LOCATION: **Throughout 2003 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **10500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 52 | | |
| MATERIAL DESCRIPTION: | 2'x4' White Ceiling Tiles - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout 2003 Mobile - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 6500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **2'x4' White Ceiling Tiles - Mobile no longer on-site**

MATERIAL LOCATION: **Throughout 2003 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 53 | | |
| MATERIAL DESCRIPTION: | 12"x12" White w/Streaks VFT - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/27/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x12" White w/Streaks VFT - Mobile no longer on-site**

MATERIAL LOCATION: **Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 53A | | |
| MATERIAL DESCRIPTION: | 12"X12" White w/Streaks VFT Mastic - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 6000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

| | | | | | |
|-----------------------|--|-----------------|-----------|--|--|
| HOMOGENEOUS AREA: | 53A | | | | |
| MATERIAL DESCRIPTION: | 12"X12" White w/Streaks VFT Mastic - Mobile no longer on-site | | | | |
| MATERIAL LOCATION: | Hallways, Classrooms, Closets & Mechanical Room in 2003 Mobile - Mobile no longer on-site | | | | |
| MATERIAL QUANTITY: | 6000 | MATERIAL UNITS: | SF | | |
| DAMAGE QUANTITY: | 0 | DAMAGE UNITS: | SF | | |

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 54 | | |
| MATERIAL DESCRIPTION: | Blue Linoleum - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Boys Toilet - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Blue Linoleum - Mobile no longer on-site**

MATERIAL LOCATION: **Boys Toilet - Mobile no longer on-site**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 54A | | |
| MATERIAL DESCRIPTION: | Blue Linoleum Mastic - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boys Toilet - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **54A**

MATERIAL DESCRIPTION: **Blue Linoleum Mastic - Mobile no longer on-site**

MATERIAL LOCATION: **Boys Toilet - Mobile no longer on-site**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 55 | | |
| MATERIAL DESCRIPTION: | Pink Linoleum - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Girls Toilet - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Pink Linoleum - Mobile no longer on-site**

MATERIAL LOCATION: **Girls Toilet - Mobile no longer on-site**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 55A | | |
| MATERIAL DESCRIPTION: | Pink Linoleum Mastic - Mobile no longer on-site | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Girls Toilet - Mobile no longer on-site | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **55A**

MATERIAL DESCRIPTION: **Pink Linoleum Mastic - Mobile no longer on-site**

MATERIAL LOCATION: **Girls Toilet - Mobile no longer on-site**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 56 | | |
| MATERIAL DESCRIPTION: | Fire Doors | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Balcony and Projector Room - Main Building | | |
| MATERIAL QUANTITY: | 2 | MATERIAL UNITS: | EA |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | EA |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Balcony and Projector Room - Main Building**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 57 | | |
| MATERIAL DESCRIPTION: | Breaching Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room - Main Building | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Breaching Insulation**

MATERIAL LOCATION: **Boiler Room - Main Building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 58 | | |
| MATERIAL DESCRIPTION: | Lining Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Incinerator Hatch in Boiler Room - Main Building | | |
| MATERIAL QUANTITY: | 4 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Lining Insulation**

MATERIAL LOCATION: **Incinerator Hatch in Boiler Room - Main Building**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 59 | | |
| MATERIAL DESCRIPTION: | Incineration Burner Gasket | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room - Main Building | | |
| MATERIAL QUANTITY: | 2 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Incineration Burner Gasket**

MATERIAL LOCATION: **Boiler Room - Main Building**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 60 | | |
| MATERIAL DESCRIPTION: | BEH Baldwin EHRCT Hill Insulation Cement | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Unfinished Pipe Space - Main Building | | |
| MATERIAL QUANTITY: | 50 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **BEH Baldwin EHRCT Hill Insulation Cement**

MATERIAL LOCATION: **Unfinished Pipe Space - Main Building**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | 61 | | |
| MATERIAL DESCRIPTION: | Kaylo Block Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Unfinished Pipe Space - Main Building | | |
| MATERIAL QUANTITY: | 10 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Kaylo Block Insulation**

MATERIAL LOCATION: **Unfinished Pipe Space - Main Building**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 62 | | |
| MATERIAL DESCRIPTION: | 12"x12" White w/ Gray Specks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 101 and 103 - Main Building | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specks VFT**

MATERIAL LOCATION: **Room 101 and 103 - Main Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 63 | | |
| MATERIAL DESCRIPTION: | 12"x12" White w/ Gray Specks VFT Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 101 and 103 - Main Building | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specks VFT Mastic**

MATERIAL LOCATION: **Room 101 and 103 - Main Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 64 | | |
| MATERIAL DESCRIPTION: | 12"x12" Blue w/ Specks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 101 and 103 - Main Building | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12"x12" Blue w/ Specks VFT**

MATERIAL LOCATION: **Room 101 and 103 - Main Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 65 | | |
| MATERIAL DESCRIPTION: | 12"x12" Blue w/ Specks VFT Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 101 and 103 - Main Building | | |
| MATERIAL QUANTITY: | 800 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUILDING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12"x12" Blue w/ Specks VFT Mastic**

MATERIAL LOCATION: **Room 101 and 103 - Main Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | A | | |
| MATERIAL DESCRIPTION: | Carpet Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, and Rooms 212, 213-215, Assembly Aisles, Library (Room 213)**

MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/27/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|-------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Jigar Shah | | |
| SCHOOL NAME: | Prussing School | REVIEW DATE: | 3/20/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Engineer's Office, and Rooms 212, 213-215, Assembly Aisles, Library (Room 213)**

MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|---|-----------------|----|
| HOMOGENEOUS AREA: | 68 | | |
| MATERIAL DESCRIPTION: | 12"x12" Royal Blue with white specks VFT Mastic | | |
| MATERIAL LOCATION: | West Modular Corridor | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12"x12" Royal Blue with white specks VFT Mastic**

MATERIAL LOCATION: **West Modular Corridor**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|-----|
| HOMOGENEOUS AREA: | 75 | | |
| MATERIAL DESCRIPTION: | 2' x 2' Pinhole Ceiling Tile | | |
| MATERIAL LOCATION: | Throughout - West Modular | | |
| MATERIAL QUANTITY: | 4300 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | Yes |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **2' x 2' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Throughout - West Modular**

MATERIAL QUANTITY: **4300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| HOMOGENEOUS AREA: | 79 | | |
| MATERIAL DESCRIPTION: | Drywall System | | |
| MATERIAL LOCATION: | Throughout - East Modular | | |
| MATERIAL QUANTITY: | 4000 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | MODERATE | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **Throughout - East Modular**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| HOMOGENEOUS AREA: | 73 | | |
| MATERIAL DESCRIPTION: | 12"x12" Yellow with specks VFT | | |
| MATERIAL LOCATION: | Rooms 03, 04, 05, 06 - West Modular | | |
| MATERIAL QUANTITY: | 1045 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | MODERATE | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12"x12" Yellow with specks VFT**

MATERIAL LOCATION: **Rooms 03, 04, 05, 06 - West Modular**

MATERIAL QUANTITY: **1045** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|-----|
| HOMOGENEOUS AREA: | 80 | | |
| MATERIAL DESCRIPTION: | 2' x 2' Pinhole Ceiling Tile | | |
| MATERIAL LOCATION: | Throughout - East Modular | | |
| MATERIAL QUANTITY: | 5430 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | Yes |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **2' x 2' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Throughout - East Modular**

MATERIAL QUANTITY: **5430** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| HOMOGENEOUS AREA: | 66 | | |
| MATERIAL DESCRIPTION: | 2' x 2' Pinhole Ceiling Tile | | |
| MATERIAL LOCATION: | Room 101, 103 | | |
| MATERIAL QUANTITY: | 1600 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **2' x 2' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Room 101, 103**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | | |
|------------------------|--|-----------------|------------|--|
| HOMOGENEOUS AREA: | 67 | | | |
| MATERIAL DESCRIPTION: | 12"x12" Royal Blue with white specks VFT | | | |
| MATERIAL LOCATION: | West Modular Corridor | | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF | |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No | |
| ASBESTOS TYPE: | Assumed | | | |
| DISTURBANCE POTENTIAL: | MODERATE | | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | |
| COMMENTS: | | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x12" Royal Blue with white specks VFT**

MATERIAL LOCATION: **West Modular Corridor**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|---|-----------------|----|
| HOMOGENEOUS AREA: | 70 | | |
| MATERIAL DESCRIPTION: | 12"x12" White with specks VFT Mastic | | |
| MATERIAL LOCATION: | Corridor, rooms 03, 04, 05, 06 - West Modular | | |
| MATERIAL QUANTITY: | 1345 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12"x12" White with specks VFT Mastic**

MATERIAL LOCATION: **Corridor, rooms 03, 04, 05, 06 - West Modular**

MATERIAL QUANTITY: **1345** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| HOMOGENEOUS AREA: | 77 | | |
| MATERIAL DESCRIPTION: | 12"x12" Beige with specks VFT | | |
| MATERIAL LOCATION: | Throughout - East Modular | | |
| MATERIAL QUANTITY: | 5050 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | MODERATE | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12"x12" Beige with specks VFT**

MATERIAL LOCATION: **Throughout - East Modular**

MATERIAL QUANTITY: **5050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| HOMOGENEOUS AREA: | 71 | | |
| MATERIAL DESCRIPTION: | 12"x12" Sky Blue with specks VFT | | |
| MATERIAL LOCATION: | Rooms 03, 04, 05, 06 - West Modular | | |
| MATERIAL QUANTITY: | 1045 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | MODERATE | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12"x12" Sky Blue with specks VFT**

MATERIAL LOCATION: **Rooms 03, 04, 05, 06 - West Modular**

MATERIAL QUANTITY: **1045** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | | | |
|------------------------|---------------------------------------|-----------------|----|--|--|
| HOMOGENEOUS AREA: | 74 | | | | |
| MATERIAL DESCRIPTION: | 12"x12" Yellow with specks VFT Mastic | | | | |
| MATERIAL LOCATION: | Rooms 03, 04, 05, 06 - West Modular | | | | |
| MATERIAL QUANTITY: | 1045 | MATERIAL UNITS: | SF | | |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No | | |
| ASBESTOS TYPE: | Assumed | | | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | | | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | | |
| COMMENTS: | | | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12"x12" Yellow with specks VFT Mastic**

MATERIAL LOCATION: **Rooms 03, 04, 05, 06 - West Modular**

MATERIAL QUANTITY: **1045** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| HOMOGENEOUS AREA: | 76 | | |
| MATERIAL DESCRIPTION: | Drywall System | | |
| MATERIAL LOCATION: | Throughout - West Modular | | |
| MATERIAL QUANTITY: | 4000 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | MODERATE | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **Throughout - West Modular**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | | | |
|------------------------|---|-----------------|----|--|--|
| HOMOGENEOUS AREA: | 72 | | | | |
| MATERIAL DESCRIPTION: | 12"x12" Sky Blue with specks VFT Mastic | | | | |
| MATERIAL LOCATION: | Rooms 03, 04, 05, 06 - West Modular | | | | |
| MATERIAL QUANTITY: | 1045 | MATERIAL UNITS: | SF | | |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No | | |
| ASBESTOS TYPE: | Assumed | | | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | | | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | | |
| COMMENTS: | | | | | |

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12"x12" Sky Blue with specks VFT Mastic**

MATERIAL LOCATION: **Rooms 03, 04, 05, 06 - West Modular**

MATERIAL QUANTITY: **1045** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| HOMOGENEOUS AREA: | 78 | | |
| MATERIAL DESCRIPTION: | 12"x12" Beige with specks VFT Mastic | | |
| MATERIAL LOCATION: | Throughout - East Modular | | |
| MATERIAL QUANTITY: | 5050 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | LOW | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12"x12" Beige with specks VFT Mastic**

MATERIAL LOCATION: **Throughout - East Modular**

MATERIAL QUANTITY: **5050** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/20/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 25031 | BUIDLING ID: | 5510 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Prussing School | INSPECTION DATE: | 2/27/2025 | | |
| ADDRESS: | 4650 N Menard Avenue | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | |
|------------------------|---|-----------------|----|
| HOMOGENEOUS AREA: | 69 | | |
| MATERIAL DESCRIPTION: | 12"x12" White with specks VFT | | |
| MATERIAL LOCATION: | Corridor, rooms 03, 04, 05, 06 - West Modular | | |
| MATERIAL QUANTITY: | 1345 | MATERIAL UNITS: | SF |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No |
| ASBESTOS TYPE: | Assumed | | |
| DISTURBANCE POTENTIAL: | MODERATE | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | |
| | | DAMAGE REASON: | |
| | | DAMAGE UNITS: | SF |

COMMENTS:

Inspector's Signature:



Date: 02/27/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25031** BUIDLING ID: **5510**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Prussing School** REVIEW DATE: **3/20/2025**

ADDRESS: **4650 N Menard Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12"x12" White with specks VFT**

MATERIAL LOCATION: **Corridor, rooms 03, 04, 05, 06 - West Modular**

MATERIAL QUANTITY: **1345** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:




Date: **03/20/2025**

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092141

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/10/2021

Exam Date: 9/10/2021

Expiration Date: 9/10/2022

Certificate Number: BIR2109101942


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, IL

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/2025



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

|  ASBESTOS PROFESSIONAL LICENSE | | ENDORSEMENTS | TC EXPIRES |
|---|---|---|------------------------|
| ID NUMBER 100 - 11093 | ISSUED 4/30/2025 | EXPIRES 05/15/2026 | INSPECTOR 9/13/2025 |
| DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health |  | PROJECT MANAGER AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | 9/14/2025 |
| PROTECTING HEALTH, IMPROVING LIVES <i>Nationally Accredited by PHAB</i> | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2409132631
Course Date: 9/13/2024
Exam Date: 9/13/2024
Expiration Date: 9/13/2025



Issue Date: 9/13/2024

Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours



525-535 West Jefferson Street • Springfield, Illinois

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 11093

ISSUED
2/28/2022 EXPIRES
05/15/2023

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11093**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| | | | | | |
|--|----------------------------|--|--|---------------------|-------------------|
| | | ASBESTOS PROFESSIONAL LICENSE | | ENDORSEMENTS | TC EXPIRES |
| ID NUMBER 100 - 11093 | ISSUED 2/28/2022 | EXPIRES 05/15/2023 | | INSPECTOR | 9/10/2022 |
| DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health | | PROJECT MANAGER AIR SAMPLING PROFESSIONAL <i>Alteration of this license shall result in legal action.</i> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 11093

ISSUED
4/8/2024

EXPIRES
05/15/2025

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE | | | ENDORSEMENTS | TC EXPIRES |
|---|---|-----------------------|---|--|
| ID NUMBER 100 - 11093 | ISSUED 4/8/2024 | EXPIRES 05/15/2025 | INSPECTOR | 9/15/2024 |
| DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health |  | | | PROJECT MANAGER AIR SAMPLING PROFESSIONAL |
| | | | Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

6/9/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE | | | ENDORSEMENTS | TC EXPIRES |
|--|---------------------------|------------------------------|---|---|
| ID NUMBER 100 - 07342 | ISSUED 6/9/2025 | EXPIRES 05/15/2026 | INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL | 3/7/2026 1/27/2026 3/7/2026 4/7/2026 |
| JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health | | | Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022


Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761

IDPH

ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 07342

ISSUED
4/1/2022

EXPIRES
05/15/2023

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612


4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

| ENDORSEMENTS | TC EXPIRES |
|---------------------------|------------|
| INSPECTOR | 3/9/2023 |
| PROJECT DESIGNER | 3/24/2023 |
| MANAGEMENT PLANNER | 3/9/2023 |
| PROJECT MANAGER | 3/2/2023 |
| AIR SAMPLING PROFESSIONAL | |

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 07342

ISSUED
4/8/2024

EXPIRES
05/15/2025

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612


4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

| ENDORSEMENTS | TC EXPIRES |
|--|------------|
| INSPECTOR | 3/8/2025 |
| PROJECT DESIGNER | 3/7/2025 |
| MANAGEMENT PLANNER | 3/8/2025 |
| PROJECT MANAGER | 3/25/2024 |
| AIR SAMPLING PROFESSIONAL | |
| <p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p> | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/8/2024

Exam Date: 3/8/2024

Expiration Date: 3/8/2025

Certificate Number: MPR2403081126

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: MPR2503070948

Course Credit Hours: MPR 4 Hours

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|------|--|
| MATERIAL | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | Loc | Localized |
| | Dist | Distributed |