

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2090  
SCHOOL NAME: Bradwell School  
ADDRESS OF SCHOOL: 7736 S. Burnham  
CITY: Chicago, IL, 60649

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 7/28/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 5/14/2025 ENROLLMENT 505  
IDPH INSPECTOR LICENSE NUMBER: 100-11070  
IDPH LICENSED INSPECTOR NAME (Please Print): Mallory Jones  
IDPH MP LICENSE NUMBER: 100-01784  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 6/3/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Bradwell School**

7736 S. Burnham  
Chicago, IL, 60649

Unit: 22291  
Building ID: 2340

IDPH ID Number: 14-016-2990-2090

**REPORT DATE:**  
Tuesday, June 03, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**TEM Environmental, Inc.**

174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone 630-790-0880  
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

06/02/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 22291      Region: 05      IDPH ID: 14-016-2990-2090

School: Bradwell School      Building ID: 2340

Address: 7736 S. Burnham

Chicago, IL, 60649

Building Contact: Moriarty, Daniel      Contact Phone: 7737102547

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/14/2025

Review Date: 06/02/2025

Inspector: Mallory Jones


Inspector IDPH License: 100-11070

Management Planner: Steven Geneser

Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Steven Geneser  
100-01784

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: June 03, 2025

RE: Bradwell School, Unit 22291  
7736 S. Burnham  
Chicago, IL, 60649

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Bradwell School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Bradwell School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Bradwell School  
Address: 7736 S. Burnham  
IDPH ID: 14-016-2990-2090  
Contact: Moriarty, Daniel

Unit: 22291  
Chicago, IL, 60649  
Building ID: 2340  
Phone: 7737102547

Region: 05

### 2. Description of Facility

Original Construction: 1937  
Total Square Footage: 28236  
Current Occupancy: 505

Additional Construction: 1895,1927,1978  
No of Floors: 3

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074


### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector


Inspector Name: Mallory Jones

  
Signature:  
Date: 5/14/2025

Inspector IDPH license # 100-11070  
Reinspection Date: 5/14/2025

### 6. Management Planner

Management Planner Name: Steven Geneser

  
Signature:  
Date: 06/02/2025

Management Planner IDPH license # 100-01784

### 7. Review Date: 06/02/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

  
Signature: *Richard J. Schleyer*  
Date: 6/3/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Bradwell School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2340:

117	12"x12" White Vinyl Floor Tile
117M	Mastic associated w/12"x12" White Vinyl Floor Tile
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 2340:

117                    12"x12" White Vinyl Floor Tile

117M                Mastic associated w/12"x12" White Vinyl Floor Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	9"x9" Tan Floor Tile NOT OBSERVED
04	Hard Coat Plaster
05	Rough Coat Plaster
06	Troweled on Plaster
07	2'x4' Lay In Ceiling Tile
08	Green Linoleum
09	Fiberglass Lay In Ceiling Panels
10	Fire Proof Curtains
100	Green Terrazzo
103	12x12 Green w/White Floor Tile
104	12x12 Green w/White Floor Tile Mastic
107	12x12 Brown w/White Floor Tile
108	12x12 Brown w/White Floor Tile Mastic
109	2x2 Light Tan Ceramic Tile NOT OBSERVED
11	Fire Door
110	2"x2" Light Tan Ceramic Tile Grout NOT OBSERVED
111	12x12 Beige w/Dark Spots Floor Tile
112	12x12 Beige w/Dark Spots Floor Tile Mastic
113	Blue Carpet Mastic
114	12x12 Grey w/White Streaks Floor Tile
115	Beige Linoleum
116	Beige Linoleum Adhesive
117	12"x12" White Vinyl Floor Tile
117M	Mastic associated w/12"x12" White Vinyl Floor Tile
12	Hard Coat Plaster
13	Hard Coat Plaster
14	Hard Coat Plaster
15	Hard Coat Plaster
16	Baseboard-NOT OBSERVED
17	Baseboard Mastic-NOT OBSERVED
18	Incinerator Insulation
19	Fire Brick Mortar
20	9x9 Green Floor Tile NOT OBSERVED
21	9x9 Green Floor Tile Mastic NOT OBSERVED
28	12x12 Orange Floor Tile
29	12x12 Orange Floor Tile Mastic
30	12x12 Light Beige Floor Tile
31	12x12 Light Beige Floor Tile Mastic
34	Linoleum NOT OBSERVED
35	Linoleum Mastic NOT OBSERVED
39	Gold Carpet Mastic NOT OBSERVED

40	Green Carpet Mastic
41	Red Carpet Mastic NOT OBSERVED
42	Transite Panels
43	Vibration Damper
44	Drywall
45	Drywall Compound
46	Drywall
47	Drywall Compound
52	9x9 Gray Floor Tile
58	9x9 Dark Brown Floor Tile
64	12x12 Beige Floor Tile
66	12x12 Brown Floor Tile NOT OBSERVED
68	12x12 Light Brown Floor Tile NOT OBSERVED
69	12x12 Light Brown Floor Tile Mastic NOT OBSERVED
72	12x12 Light Tan Floor Tile NOT OBSERVED
73	12x12 Light Tan Floor Tile Mastic NOT OBSERVED
76	12x12 Beige Floor Tile NOT OBSERVED
78	12x12 Light Brown Floor Tile NOT OBSERVED
79	12x12 Light Brown Floor Tile Mastic NOT OBSERVED
80	12x12 Brown Floor Tile NOT OBSERVED
81	12x12 Brown Floor Tile Mastic NOT OBSERVED
82	12x12 Orange Floor Tile
83	Green Carpet Adhesive NOT OBSERVED
84	12x12 Orange Floor Tile Mastic
85	12x12 Brown Floor Tile (Duplicate of HA-80) NOT OBSERVED
86	White w/Brown Streaks Floor Tile
87	12x12 Dark Brown w/Light Brown Streaks Floor Tile NOT OBSERVED
88	12x12 Dark Brown w/Light Brown Streaks Floor Tile Mastic NOT OBSERVED
89	12x12 Brown w/Black & White Streaks Floor Tile NOT OBSERVED
90	12x12 Brown w/Black & White Streaks Floor Tile Mastic NOT OBSERVED
91	Chalkboards
91A	Chalkboard Adhesive
92	Mastic Beneath Wood Flooring
93	Terrazzo
94	Accoustical Plaster
95	Grey & Black Terrazzo
96	Blue Carpet Adhesive NOT OBSERVED
97	12x12 White w/Grey & Brown Floor Tile
98	12x12 White w/Grey & Brown Floor Tile Mastic
99	Tan Terrazzo

A	Vibration Duct Sleeves
B	Vibration Dampers
I	Fiberglass Duct Covers
K	Fiberglass Tank Insulation
Mod-7	Drywall NOT OBSERVED
N	Fiberglass Duct Wrap
NEW	Newly Installed Suspect ACM
U	Boiler Gaskets

The following areas were deemed to be inaccessible:

05	Rough Coat Plaster
108	12x12 Brown w/White Floor Tile Mastic
11	Fire Door
112	12x12 Beige w/Dark Spots Floor Tile Mastic
113	Blue Carpet Mastic
15	Hard Coat Plaster
18	Incinerator Insulation
23	9x9 Beige and 9x9 Dark Brown Floor Tile Mastic
27	12x12 Beige Floor Tile Mastic
29	12x12 Orange Floor Tile Mastic
31	12x12 Light Beige Floor Tile Mastic
33	12x12 Off-White Floor Tile Mastic
35	Linoleum Mastic NOT OBSERVED
40	Green Carpet Mastic
53	9x9 Gray Floor Tile Mastic
55	9x9 Gray Floor Tile Mastic
59	9x9 Dark Brown Floor Tile Mastic
65	12x12 Beige Floor Tile Mastic
67	12x12 Brown Floor Tile Mastic
69	12x12 Light Brown Floor Tile Mastic NOT OBSERVED
73	12x12 Light Tan Floor Tile Mastic NOT OBSERVED
77	12x12 Beige Floor Tile Mastic
79	12x12 Light Brown Floor Tile Mastic NOT OBSERVED
81	12x12 Brown Floor Tile Mastic NOT OBSERVED
83	Green Carpet Adhesive NOT OBSERVED
84	12x12 Orange Floor Tile Mastic
88	12x12 Dark Brown w/Light Brown Streaks Floor Tile Mastic NOT OBSERVED
90	12x12 Brown w/Black & White Streaks Floor Tile Mastic NOT OBSERVED
91A	Chalkboard Adhesive
92	Mastic Beneath Wood Flooring

98	12x12 White w/Grey & Brown Floor Tile Mastic
P	Aircell Pipe Insulation
R	Pipe Joint Insulation On Aircell Insulated Piping
S	Paper Wrap Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mallory Jones, IDPH License # 100-11070. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

### III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

#### IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 6/19/2023  
8/6/2024

## V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

## VI. CONCLUSIONS

The Bradwell School Building 2340 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	9"x9" Tan Floor Tile NOT OBSERVED	2,400	SF	Basement Storage Room (Old Lunchroom)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02	12x12 Light Beige Floor Tile NOT OBSERVED			1926 Building-Room 300	CHR	MISC					No			
03	Burlap Wall Covering ABATED			Classrooms 117, 118, 119, 120, 218, 308, 309	ABATED	MISC								
04	Hard Coat Plaster	340,000	SF	Throughout 1926 Facility	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
05	Rough Coat Plaster	1,000	SF	Auditorium	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Troweled on Plaster	2,340	SF	Mechanical Rooms	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
07	2'x4' Lay In Ceiling Tile	2,340	SF	Food Service and Gym	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
08	Green Linoleum	3,600	SF	Gym and Storage, 318	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Fiberglass Lay In Ceiling Panels	3,600	SF	Gym and Office Washroom	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
10	Fire Proof Curtains	1,000	SF	Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
100	Green Terrazzo	200	SF	1st Floor Elevator Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	12x12 Brown w/Black Floor Tile ABATED			Room 206	ABATED	MISC								
102	12x12 Brown w/Black Floor Tile Mastic ABATED			Room 206	ABATED	MISC								
103	12x12 Green w/White Floor Tile	400	SF	2nd & 3rd Floor Elevator Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12x12 Green w/White Floor Tile Mastic	400	SF	2nd & 3rd Floor Elevator Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
105	12x12 Light Grey w/Dark Grey & White Floor Tile ABATED			Room 309	ABATED	MISC								
106	12x12 Light Grey w/Dark Grey & White Floor Tile Mastic ABATED			Room 309	ABATED	MISC								
107	12x12 Brown w/White Floor Tile	4,400	SF	Rooms 117, 119, 219, Basement Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
108	12x12 Brown w/White Floor Tile Mastic	4,400	SF	Rooms 117, 119, 219 & Basement Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
109	2x2 Light Tan Ceramic Tile NOT	90	SF	Room 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	OBSERVED			Kindergarten Restroom								potential for damage		
11	Fire Door	6	SF	1978 Building- 2nd Floor Mechanical Room, Stairway and 3rd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
110	2"x2" Light Tan Ceramic Tile Grout NOT OBSERVED	90	SF	Room 112 Kindergarten Restroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
111	12x12 Beige w/Dark Spots Floor Tile	170	SF	Room 319 Coat Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
112	12x12 Beige w/Dark Spots Floor Tile Mastic	170	SF	Room 319 Coat Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
113	Blue Carpet Mastic	1,000	SF	Room 104, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
114	12x12 Grey w/White Streaks Floor Tile	2,000	SF	Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
115	Beige Linoleum	1,243	SF	Room 206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
116	Beige Linoleum Adhesive	1,243	SF	Room 206	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
117	12"x12" White Vinyl Floor Tile	1,444	SF	Classrooms 304 & 310	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
117M	Mastic associated w/12"x12" White Vinyl Floor Tile	1,444	SF	Classrooms 304 & 310	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
12	Hard Coat Plaster	12,100	SF	1894 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
13	Hard Coat Plaster	36,000	SF	1926 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Hard Coat Plaster	7,200	SF	1936 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
15	Hard Coat Plaster	10,000	SF	1978 Building	ASSUMED	SURFACE	N		0		No	ACBM with the potential for damage		LOW
16	Baseboard-NOT OBSERVED			1978 Building- Gym, Student Dining, Faculty Dining, Store Room	ASSUMED	MISC		NONE	0			ACBM with the potential for damage		
17	Baseboard Mastic-NOT OBSERVED			1978 Building- Gym, Student Dining, Faculty Dining, Store Room	ASSUMED	MISC								
18	Incinerator Insulation	1,950	SF	Boiler Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Fire Brick Mortar	200	SF	Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

## ***Inspector's Comments are Summarized at the End of the Report***

Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
52	9x9 Gray Floor Tile	420	SF	1926 Building- Counselor's Office, Nurse's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	9x9 Gray Floor Tile Mastic	420	SF	1926 Building- Room 107, Nurse's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	9x9 Gray Floor Tile	320	SF	1926 Building- Room 107	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	9x9 Gray Floor Tile Mastic	320	SF	1926 Building- Room 107	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12x12 Off-White Floor Tile ABATED			1926 Building- Assistant Principal's Office	ABATED	MISC								
57	12x12 Off-White Floor Tile Mastic ABATED			1926 Building- Assistant Principal's Office	ABATED	MISC								
58	9x9 Dark Brown Floor Tile	1,000	SF	1926 Building- Room 110	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	9x9 Dark Brown Floor Tile Mastic	1,000	SF	1926 Building- Classroom 110	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	9x9 Black Floor Tile NOT OBSERVED			1926 Building- 2nd & 3rd Floor Corridors	CHR	MISC								
61	9x9 Black Floor Tile NOT OBSERVED			1926 Building- 2nd & 3rd Floor Corridors	CHR	MISC						ACBM with potential for significant damage		
62	9x9 Black Floor Tile NOT OBSERVED			1936 Building- 2nd Floor Corridor	CHR	MISC						ACBM with the potential for damage		
63	Mastic associated with 9x9 Black Floor Tile NOT OBSERVED			1936 Building- 2nd & 3rd Floor Corridors	CHR	MISC						ACBM with the potential for damage		
64	12x12 Beige Floor Tile	6,000	SF	1926 Building- Rooms 113, 203, 204, 205, 212, 301, 305, 309	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12x12 Beige Floor Tile Mastic	6,000	SF	1926 Building- Classrooms 113, 203, 204, 205, 212, 301, 305 & 309	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12x12 Brown Floor Tile NOT OBSERVED	3,920	SF	1926 Building- 1st Floor Corridor and Library (Under Green Carpet)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	12x12 Brown Floor Tile Mastic	3,920	SF	1926 Building- 1st	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridor & Library (Under Green Carpet)								potential for damage		
68	12x12 Light Brown Floor Tile NOT OBSERVED	1,540	SF	1926 Building- Kindergarten	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12x12 Light Brown Floor Tile Mastic NOT OBSERVED	1,540	SF	1926 Building- Kindergarten	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	12x12 Medium Brown Floor Tile ABATED			1926 Building- Room 105	ABATED	MISC								
71	12x12 Medium Brown Floor Tile Mastic ABATED			1926 Building- Room 105	ABATED	MISC								
72	12x12 Light Tan Floor Tile NOT OBSERVED	680	SF	1926 Building- Principal's Office, Storeroom, Secretary's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12x12 Light Tan Floor Tile Mastic NOT OBSERVED	680	SF	1926 Building- Principal's Office, Storeroom, Secretary's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	12x12 Beige Floor Tile NOT OBSERVED	3,900	SF	1936 Building- Rooms 112, 113, 114, 310	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	12x12 Beige Floor Tile Mastic	3,900	SF	1936 Building- Rooms 112, 113, 114, 310	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12x12 Light Brown Floor Tile NOT OBSERVED	940	SF	1936 Building- 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12x12 Light Brown Floor Tile Mastic NOT OBSERVED	940	SF	1936 Building- 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	12x12 Brown Floor Tile NOT OBSERVED	940	SF	1936 Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12x12 Brown Floor Tile Mastic NOT OBSERVED	940	SF	1936 Building- 1st Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12x12 Orange Floor Tile	4,100	SF	1894 Building- 1st, 2nd, & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
83	Green Carpet Adhesive NOT OBSERVED	1,200	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
84	12x12 Orange Floor Tile Mastic	4,100	SF	1894 Building- 1st, 2nd, & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12x12 Brown Floor Tile (Duplicate of HA-80) NOT OBSERVED			1936 Building- 1st Floor Corridor	ASSUMED	MISC								
86	White w/Brown Streaks Floor Tile			1926 Building- 3rd	ASSUMED	MISC			0					

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Floor Corridor										
87	12x12 Dark Brown w/Light Brown Streaks Floor Tile NOT OBSERVED	176	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	12x12 Dark Brown w/Light Brown Streaks Floor Tile Mastic NOT OBSERVED	176	SF	Engineer's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	12x12 Brown w/Black & White Streaks Floor Tile NOT OBSERVED	99	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
90	12x12 Brown w/Black & White Streaks Floor Tile Mastic NOT OBSERVED	99	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	Chalkboards	2,000	SF	Throughout Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91A	Chalkboard Adhesive	2,000	SF	Throughout Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	Mastic Beneath Wood Flooring	640	SF	Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	Terrazzo	1,500	SF	Entrances and Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
94	Acoustical Plaster	3,000	SF	Auditorium	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
95	Grey & Black Terrazzo	10,000	SF	Hallway (Trim) & Stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	Blue Carpet Adhesive NOT OBSERVED			Room 106	ASSUMED	MISC		NONE	0					
97	12x12 White w/Grey & Brown Floor Tile	25,000	SF	1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	12x12 White w/Grey & Brown Floor Tile Mastic	25,000	SF	1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	Tan Terrazzo	400	SF	1st Floor Elevator Lobby	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Vibration Duct Sleeves	20	SF	Mechanical Areas	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Vibration Dampers	30	SF	1978 Building-Mechanical Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Aircell Pipe Insulation	110	LF	1894 Building-Locker Room, Store room, Lunch room, 1st, 2nd Floor Corridor	CHR	TSI	Y	LOC	5		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
D	Fittings on Aircell Insulation	10	LF	1894 Building-Locker room, store room, Lunch room,	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building Demolished										
Mod-13	Blue Carpet Mastic ABATED			Throughout Classrooms- Building Demolished	ABATED	MISC								
Mod-2	Wall Panels ABATED			Throughout Modular Building- Building Demolished	ABATED	MISC								
Mod-4	9"x9" Tan Floor Tile ABATED			Gym and Store Room - Building Demolished	ABATED	MISC								
Mod-5	Baseboard ABATED			Gym, Mechanical Equipment Room, Store Room - Building Demolished	ABATED	MISC								
Mod-6	Baseboard Mastic ABATED			Gym, Mechanical Equipment Room, Store Room - Building Demolished	ABATED	MISC								
Mod-7	Drywall NOT OBSERVED			Throughout Building - Building Demolished	ASSUMED	MISC								
Mod-8	12x12 Beige Floor Tile ABATED			Throughout Corridor - Building Demolished	ABATED	MISC								
Mod-9	12x12 Beige Floor Tile Mastic ABATED			Throughout Corridor- Building Demolished	ABATED	MISC								
Mod-B	Pipe Fitting Insulation on Fiberglass Insulated Piping ABATED			Boys' and Girls' Toilets	ABATED	TSI								
N	Fiberglass Duct Wrap	200	LF	Above Lunchroom	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan or After Renovations	ASSUMED	MISC		UNKNO WN	0		Yes	ACBM with the potential for damage		
O	Aircell Pipe Insulation	390	LF	1926 Building- Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room, Store Room, and Unexcavated Area										
P	Aircell Pipe Insulation	150	LF	1936 Building-Crawlspace	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
Q	Pipe Fittings on Aircell Insulated Piping	75	LF	1926 Building-Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump Room, Storeroom, and Unexcavated Area	CHR	TSI	Y	DIST	10		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	MODERATE
R	Pipe Joint Insulation On Aircell Insulated Piping	15	LF	1936 Building-Crawlspace	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
S	Paper Wrap Insulation	200	LF	1926 Building-Crawlspace	CHR	TSI	Y	LOC	20		No	Damaged or significantly damaged friable thermal system insulating ACBM	5	MODERATE
T	Pipe Fitting Insulation on Paper Wrap Insulated Piping ABATED			1926 Building-Crawlspace	ABATED	TSI								
U	Boiler Gaskets	30	LF	1926 Building-Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
V	Pipe Fitting Insulation on Fiberglass Insulated Piping	8	LF	1894 Building-Locker Room, Store Room, Lunch Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
W	Fittings on Fiberglass ABATED			1926 Building-Basement Unexcavated Area	ABATED	TSI								
X	Pipe Fitting Insulation on Fiberglass Insulated Piping	20	LF	1936 Building-Crawlspace	CHR	TSI	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Bradwell School Unit 22291 Building ID 2340  
Address 7736 S. Burnham Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>5/14/2025</u>
Inspector Name	<u>Mallory Jones</u>
100-11070	<u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
01	Not Observed 2025, Green concrete floor
02	Not Observed 2022, 2025
03	
04	
05	
06	
07	
08	
09	
10	
100	
101	
102	
103	
104	
105	
106	
107	2025: Basement Storage- Concrete Floor
108	2025: Basement Storage- Concrete Floor
109	2025- 12"x12" White Ceramic
11	
110	Not Observed 2025. 12"x12" White Floor Tile
111	
112	

# Chicago Public Schools

School Bradwell School Unit 22291 Building ID 2340  
Address 7736 S. Burnham Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
113	
114	
115	
116	
117	
117M	
12	
13	
14	
15	
16	Not observed 2022, 2025
17	Not observed in 2022, 2025
18	
19	
20	Not Observed 2022, 2025- No Room 218
21	not observed in 2022, 2025
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	Not Observed 2025. 12"x12" White Ceramic

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
35	Not Observed 2025
37	Building Demolished
38	not observed in 2022, 2025
39	Not Observed 2025. Hardwood Floor
40	
41	not observed in 2022, 2025
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	2025: 12"x12" Grey & 12"x12" Green Floor Tile
55	
56	Assistant Principal's Office is Hardwood Floor
57	Assistant Principal's Office is Hardwood Floor
58	
59	
60	not observed 2022, 2025: 12"x12" White FT
61	not observed 2022, 2025: 12"x12" White FT
62	Not Observed 2022, 2025. 12"x12" White FT
63	Not Observed 2022, 2025. 12"x12" White FT
64	2025: Room 202 is Hardwood Floor

# Chicago Public Schools

**School** Bradwell School **Unit** 22291 **Building ID** 2340  
**Address** 7736 S. Burnham **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
65	
66	
67	
68	Not Observed 2019, 2022, 2025
69	Not Observed 2025. 12"x12" White FT
70	
71	
72	Not Observed 2025
73	Not Observed 2025
76	Not Observed 2025. 12"x12" White FT
77	
78	Not Observed 2025
79	Not Observed 2025
80	Not Observed 2025
81	Not Observed 2025
82	
83	Not Observed 2025
84	
85	Not Observed 2025
86	Not observed 2022, 2025
87	Not Observed 2025
88	Not Observed 2025
89	Not Observed 2025. Concrete Floor
90	Not Observed 2025
91	
91A	
92	
93	
94	

# Chicago Public Schools

School Bradwell School Unit 22291 Building ID 2340  
Address 7736 S. Burnham Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
95	
96	
97	
98	
99	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
Mod-1	
Mod-10	
Mod-11	
Mod-12	
Mod-13	
Mod-2	
Mod-4	
Mod-5	
Mod-6	
Mod-7	
Mod-8	

# Chicago Public Schools

School Bradwell School Unit 22291 Building ID 2340  
Address 7736 S. Burnham Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
Mod-9	
Mod-B	
N	
NEW	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	9"x9" Tan Floor Tile NOT OBSERVED	2,400	SF	Basement Storage Room (Old Lunchroom)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12x12 Light Beige Floor Tile NOT OBSERVED			1926 Building- Room 300	Chrysotile	MISC					
03	Burlap Wall Covering ABATED			Classrooms 117, 118, 119, 120, 218, 308, 309	Abated	MISC					
04	Hard Coat Plaster	340,000	SF	Throughout 1926 Facility	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Rough Coat Plaster	1,000	SF	Auditorium	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Troweled on Plaster	2,340	SF	Mechanical Rooms	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	2'x4' Lay In Ceiling Tile	2,340	SF	Food Service and Gym	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
08	Green Linoleum	3,600	SF	Gym and Storage, 318	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Fiberglass Lay In Ceiling Panels	3,600	SF	Gym and Office Washroom	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
10	Fire Proof Curtains	1,000	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
100	Green Terrazzo	200	SF	1st Floor Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12x12 Brown w/Black Floor Tile ABATED			Room 206	Abated	MISC					
102	12x12 Brown w/Black Floor Tile Mastic ABATED			Room 206	Abated	MISC					
103	12x12 Green w/White Floor Tile	400	SF	2nd & 3rd Floor Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12x12 Green w/White Floor Tile Mastic	400	SF	2nd & 3rd Floor Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12x12 Light Grey w/Dark Grey & White Floor Tile ABATED			Room 309	Abated	MISC					
106	12x12 Light Grey w/Dark Grey & White Floor Tile Mastic ABATED			Room 309	Abated	MISC					
107	12x12 Brown w/White Floor Tile	4,400	SF	Rooms 117, 119, 219, Basement Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
108	12x12 Brown w/White Floor Tile Mastic	4,400	SF	Rooms 117, 119, 219 & Basement Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
109	2x2 Light Tan Ceramic Tile NOT OBSERVED	90	SF	Room 112 Kindergarten Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Fire Door	6	SF	1978 Building- 2nd Floor Mechanical Room, Stairway and 3rd Floor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
110	2"x2" Light Tan Ceramic Tile Grout NOT OBSERVED	90	SF	Room 112 Kindergarten Restroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12x12 Beige w/Dark Spots Floor Tile	170	SF	Room 319 Coat Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
112	12x12 Beige w/Dark Spots Floor Tile Mastic	170	SF	Room 319 Coat Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
113	Blue Carpet Mastic	1,000	SF	Room 104, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
114	12x12 Grey w/White Streaks Floor Tile	2,000	SF	Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Beige Linoleum	1,243	SF	Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
116	Beige Linoleum Adhesive	1,243	SF	Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117	12"x12" White Vinyl Floor Tile	1,444	SF	Classrooms 304 & 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
117M	Mastic associated w/12"x12" White Vinyl Floor Tile	1,444	SF	Classrooms 304 & 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Hard Coat Plaster	12,100	SF	1894 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Hard Coat Plaster	36,000	SF	1926 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Hard Coat Plaster	7,200	SF	1936 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Hard Coat Plaster	10,000	SF	1978 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Baseboard-NOT OBSERVED			1978 Building- Gym, Student Dining, Faculty Dining, Store Room	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan
17	Baseboard Mastic-NOT OBSERVED			1978 Building- Gym, Student Dining, Faculty Dining, Store Room	Assumed	MISC					Follow O&M Plan
18	Incinerator Insulation	1,950	SF	Boiler Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Fire Brick Mortar	200	SF	Boiler Room	Assumed	TSI	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9x9 Green Floor Tile NOT OBSERVED			1894 Building- Room 218, Corridor	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan
21	9x9 Green Floor Tile Mastic NOT OBSERVED			1894 Building- Corridor	Assumed	MISC		0			Follow O&M Plan
22	9x9 Beige and 9x9 Dark Brown Floor Tile	800	SF	1926 Building- Room 110	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	9x9 Beige and 9x9 Dark Brown Floor Tile Mastic	800	SF	1926 Building- Room 110	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	9x9 Dark Brown Floor Tile ABATED			1936 Building- 1st Floor Corridor	Abated	MISC					
25	9x9 Dark Brown Floor Tile ABATED			1936 Building- 2nd Floor corridor	Abated	MISC					
26	12x12 Beige Floor Tile	700	SF	1894 Building- Room 217	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Beige Floor Tile Mastic	700	SF	1894 Building- Room 217	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12x12 Orange Floor Tile	790	SF	1926 Building- Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12x12 Orange Floor Tile Mastic	790	SF	1926 Building- Room 206	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12x12 Light Beige Floor Tile	5,700	SF	1936 Building- 1st, 2nd, and 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12x12 Light Beige Floor Tile Mastic	5,700	SF	1936 Building- 1st, 2nd & 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12x12 Off-White Floor Tile	6,200	SF	1978 Building- 1st Floor Student Dining, Lobby, Office, Store Room, and Faculty Dining	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12x12 Off-White Floor Tile Mastic	6,200	SF	1978 Building- 1st Floor Student Dining, Lobby, Office, Store Room, and Faculty Dining	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
34	Linoleum NOT OBSERVED	150	SF	Kindergarten Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Linoleum Mastic NOT OBSERVED	150	SF	Kindergarten Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9"x9" Tan Floor Tile Mastic ABATED			Basement Storage Room (Old Lunchroom) Building Demolished	Abated	MISC					
38	12x12 Light Beige Floor Tile Mastic NOT OBSERVED			1926 Building- Room 300	Chrysotile	MISC					Follow O&M Plan
39	Gold Carpet Mastic NOT OBSERVED	1,000	SF	1984 Building- Room 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Green Carpet Mastic	700	SF	1926 Building- 1st Floor Conference Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Red Carpet Mastic NOT OBSERVED			Room 106 Office	Assumed	MISC					Follow O&M Plan
42	Transite Panels	40	SF	1926 Building- 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Vibration Damper	30	SF	Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Drywall	630	SF	1894 Building- Locker Room and Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Drywall Compound	300	SF	1894 Building- Locker Room and Store Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Drywall	2,680	SF	1978 Building- 1st Floor Men's and Women's Toilets, Store Room, 2nd Floor Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Drywall Compound	1,340	SF	1978 Building- 1st Floor Men's and Women's Toilets, Store Room, 2nd Floor Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	9x9 Dark Brown Floor Tile ABATED			1894 Building- 1st, 2nd & 3rd Floor Corridors	Abated	MISC					
49	9x9 Dark Brown Floor Tile Mastic Abated			1894 Building- 1st, 2nd, and 3rd Floor Corridors	Abated	MISC					
50	9x9 Black Floor Tile ABATED			1894 Building- 1st and 2nd Floor Corridors	Abated	MISC					
51	9x9 Black Floor Tile Mastic ABATED			1894 Building- 1st, 2nd and 3rd Floor Corridor	Abated	MISC					
52	9x9 Gray Floor Tile	420	SF	1926 Building- Counselor's Office, Nurse's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	9x9 Gray Floor Tile Mastic	420	SF	1926 Building- Room 107, Nurse's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	9x9 Gray Floor Tile	320	SF	1926 Building- Room 107	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	9x9 Gray Floor Tile Mastic	320	SF	1926 Building- Room 107	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
56	12x12 Off-White Floor Tile ABATED			1926 Building- Assistant Principal's Office	Abated	MISC					
57	12x12 Off-White Floor Tile Mastic ABATED			1926 Building- Assistant Principal's Office	Abated	MISC					
58	9x9 Dark Brown Floor Tile	1,000	SF	1926 Building- Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	9x9 Dark Brown Floor Tile Mastic	1,000	SF	1926 Building- Classroom 110	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	9x9 Black Floor Tile NOT OBSERVED			1926 Building- 2nd & 3rd Floor Corridors	Chrysotile	MISC					Follow O&M Plan
61	9x9 Black Floor Tile NOT OBSERVED			1926 Building- 2nd & 3rd Floor Corridors	Chrysotile	MISC				5 ACBM with potential for significant damage	Follow O&M Plan
62	9x9 Black Floor Tile NOT OBSERVED			1936 Building- 2nd Floor Corridor	Chrysotile	MISC				6 ACBM with the potential for damage	
63	Mastic associated with 9x9 Black Floor Tile NOT OBSERVED			1936 Building- 2nd & 3rd Floor Corridors	Chrysotile	MISC				6 ACBM with the potential for damage	Follow O&M Plan
64	12x12 Beige Floor Tile	6,000	SF	1926 Building- Rooms 113, 203, 204, 205, 212, 301, 305, 309	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12x12 Beige Floor Tile Mastic	6,000	SF	1926 Building- Classrooms 113, 203, 204, 205, 212, 301, 305 & 309	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12x12 Brown Floor Tile NOT OBSERVED	3,920	SF	1926 Building- 1st Floor Corridor and Library (Under Green Carpet)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12x12 Brown Floor Tile Mastic	3,920	SF	1926 Building- 1st Floor Corridor & Library (Under Green Carpet)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12x12 Light Brown Floor Tile NOT OBSERVED	1,540	SF	1926 Building- Kindergarten	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12x12 Light Brown Floor Tile Mastic NOT OBSERVED	1,540	SF	1926 Building- Kindergarten	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12x12 Medium Brown Floor Tile ABATED			1926 Building- Room 105	Abated	MISC					
71	12x12 Medium Brown Floor Tile Mastic ABATED			1926 Building- Room 105	Abated	MISC					
72	12x12 Light Tan Floor Tile NOT OBSERVED	680	SF	1926 Building- Principal's Office, Storeroom, Secretary's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12x12 Light Tan Floor Tile Mastic NOT OBSERVED	680	SF	1926 Building- Principal's Office, Storeroom, Secretary's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12x12 Beige Floor Tile NOT OBSERVED	3,900	SF	1936 Building- Rooms 112, 113, 114, 310	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12x12 Beige Floor Tile Mastic	3,900	SF	1936 Building- Rooms 112, 113, 114, 310	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12x12 Light Brown Floor Tile NOT OBSERVED	940	SF	1936 Building- 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12x12 Light Brown Floor Tile Mastic NOT	940	SF	1936 Building- 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
<b>OBSERVED</b>											
80	12x12 Brown Floor Tile NOT OBSERVED	940	SF	1936 Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12x12 Brown Floor Tile Mastic NOT OBSERVED	940	SF	1936 Building- 1st Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12x12 Orange Floor Tile	4,100	SF	1894 Building- 1st, 2nd, & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Green Carpet Adhesive NOT OBSERVED	1,200	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12x12 Orange Floor Tile Mastic	4,100	SF	1894 Building- 1st, 2nd, & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12x12 Brown Floor Tile (Duplicate of HA-80) NOT OBSERVED			1936 Building- 1st Floor Corridor	Assumed	MISC					Follow O&M Plan
86	White w/Brown Streaks Floor Tile			1926 Building- 3rd Floor Corridor	Assumed	MISC		0			
87	12x12 Dark Brown w/Light Brown Streaks Floor Tile NOT OBSERVED	176	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	12x12 Dark Brown w/Light Brown Streaks Floor Tile Mastic NOT OBSERVED	176	SF	Engineer's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12x12 Brown w/Black & White Streaks Floor Tile NOT OBSERVED	99	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12x12 Brown w/Black & White Streaks Floor Tile Mastic NOT OBSERVED	99	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	Chalkboards	2,000	SF	Throughout Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91A	Chalkboard Adhesive	2,000	SF	Throughout Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	Mastic Beneath Wood Flooring	640	SF	Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	Terrazzo	1,500	SF	Entrances and Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	Acoustical Plaster	3,000	SF	Auditorium	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
95	Grey & Black Terrazzo	10,000	SF	Hallway (Trim) & Stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	Blue Carpet Adhesive NOT OBSERVED			Room 106	Assumed	MISC		0			Follow O&M Plan
97	12x12 White w/Grey & Brown Floor Tile	25,000	SF	1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12x12 White w/Grey & Brown Floor Tile Mastic	25,000	SF	1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	Tan Terrazzo	400	SF	1st Floor Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Vibration Duct Sleeves	20	SF	Mechanical Areas	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Vibration Dampers	30	SF	1978 Building- Mechanical Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	110	LF	1894 Building- Locker Room, Store	Chrysotile	TSI	Yes	5	LF	1 Damaged or significantly damaged	Repair

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				room, Lunch room, 1st, 2nd Floor Corridor						friable thermal system insulating ACBM	
D	Fittings on Aircell Insulation	10	LF	1894 Building- Locker room, store room, Lunch room, 1st, 2nd Floor Corridor	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Cardboard Pipe Insulation	1,000	LF	1894 Building- Basement, Pipe Chase and Tunnel	Chrysotile	TSI	Yes	0	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Follow O&M Plan
F	Joint Insulation On Cardboard Insulated Piping	150	LF	1984 Building- Basement, Tunnel and Pipe Chases	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Mag-Block Pipe Insulation	40	LF	1894 Building- Lunchroom, Store Room, Locker Room, and Engineers Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Pipe Fitting Insulation on Mag Block Insulated Piping	4	LF	1894 Building- Lunchroom, Store Room, Locker Room, and Engine Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Fiberglass Duct Covers	1,000	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Duct Insulation	1,600	SF	1978 Building- Mechanical Room	Crocidolite	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Fiberglass Tank Insulation	2,400	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Tank Insulation ABATED			1894 Building- Boiler Room	Abated	TSI					
M	Vibration Duct Sleeves	220	SF	Mechanical Rooms	Crocidolite	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Mod-1	9"x9" Tan Floor Tile Mastic ABATED			Gym and Storeroom- Building Demolished	Abated	MISC					
Mod-10	12" x 12" Brown Floor Tile ABATED			Throughout Corridor - Building Demolished	Abated	MISC					
Mod-11	12" x 12" Brown Floor Tile Mastic ABATED			Throughout Corridor - Building Demolished	Abated	MISC					
Mod-12	Orange Carpet Mastic ABATED			Office, Teachers Lounge, Principal's Office, Store Room - Building Demolished	Abated	MISC					
Mod-13	Blue Carpet Mastic ABATED			Throughout Classrooms- Building Demolished	Abated	MISC					
Mod-2	Wall Panels ABATED			Throughout Modular Building- Building Demolished	Abated	MISC					

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
Mod-4	9"x9" Tan Floor Tile ABATED			Gym and Store Room - Building Demolished	Abated	MISC					
Mod-5	Baseboard ABATED			Gym, Mechanical Equipment Room, Store Room - Building Demolished	Abated	MISC					
Mod-6	Baseboard Mastic ABATED			Gym, Mechanical Equipment Room, Store Room - Building Demolished	Abated	MISC					
Mod-7	Drywall NOT OBSERVED			Throughout Building - Building Demolished	Assumed	MISC					
Mod-8	12x12 Beige Floor Tile ABATED			Throughout Corridor - Building Demolished	Abated	MISC					
Mod-9	12x12 Beige Floor Tile Mastic ABATED			Throughout Corridor- Building Demolished	Abated	MISC					
Mod-B	Pipe Fitting Insulation on Fiberglass Insulated Piping ABATED			Boys' and Girls' Toilets	Abated	TSI					
N	Fiberglass Duct Wrap	200	LF	Above Lunchroom	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan or After Renovations	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan
O	Aircell Pipe Insulation	390	LF	1926 Building- Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump Room, Store Room, and Unexcavated Area	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
P	Aircell Pipe Insulation	150	LF	1936 Building- Crawlspace	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
Q	Pipe Fittings on Aircell Insulated Piping	75	LF	1926 Building- Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump Room, Storeroom, and Unexcavated Area	Chrysotile	TSI	Yes	10	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
R	Pipe Joint Insulation On Aircell Insulated Piping	15	LF	1936 Building- Crawlspace	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
S	Paper Wrap Insulation	200	LF	1926 Building- Crawlspace	Chrysotile	TSI	Yes	20	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
T	Pipe Fitting Insulation on Paper Wrap Insulated Piping ABATED			1926 Building- Crawlspace	Abated	TSI					
U	Boiler Gaskets	30	LF	1926 Building- Boiler Room	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
V	Pipe Fitting Insulation on Fiberglass Insulated Piping	8	LF	1894 Building- Locker Room, Store Room, Lunch Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
W	Fittings on Fiberglass ABATED			1926 Building- Basement Unexcavated Area	Abated	TSI					
X	Pipe Fitting Insulation on Fiberglass Insulated Piping	20	LF	1936 Building- Crawlspace	Chrysotile	TSI	No	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Review Date	6/2/2025
Manager Planner Name	Steven Geneser
100-01784	5/15/2026
Manager IDPH License No/Expiration	

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
11	
110	
111	
112	
113	
114	
115	

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
116	
117	
117M	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
91A	

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	Repair response action selective to area of damage only
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
Mod-1	
Mod-10	
Mod-11	
Mod-12	
Mod-13	
Mod-2	

# Chicago Public Schools

**School** Bradwell School

**Unit** 22291

**Building ID** 2340

**Address** 7736 S. Burnham

Chicago, IL, 60649

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
Mod-4	
Mod-5	
Mod-6	
Mod-7	
Mod-8	
Mod-9	
Mod-B	
N	
NEW	
O	
P	
Q	Repair response action selective to areas of damage only
R	
S	Repair response action selective to area of damage only
T	
U	
V	
W	
X	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**TEM Environmental, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUILDING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	9"x9" Tan Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Storage Room (Old Lunchroom)		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025, Green concrete floor		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Basement Storage Room (Old Lunchroom)**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02	
MATERIAL DESCRIPTION:	12x12 Light Beige Floor Tile NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- Room 300

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022, 2025

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **12x12 Light Beige Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- Room 300**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Burlap Wall Covering ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Classrooms 117, 118, 119, 120, 218, 308, 309**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Burlap Wall Covering ABATED**

MATERIAL LOCATION: **Classrooms 117, 118, 119, 120, 218, 308, 309**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1926 Facility		
MATERIAL QUANTITY:	340000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout 1926 Facility**

MATERIAL QUANTITY: **340000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	Rough Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Rough Coat Plaster**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	Troweled on Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical Rooms		
MATERIAL QUANTITY:	2340	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Troweled on Plaster**

MATERIAL LOCATION: **Mechanical Rooms**

MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	2'x4' Lay In Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Food Service and Gym		
MATERIAL QUANTITY:	2340	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **2'x4' Lay In Ceiling Tile**

MATERIAL LOCATION: **Food Service and Gym**

MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Green Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym and Storage, 318		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Green Linoleum**

MATERIAL LOCATION: **Gym and Storage, 318**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	Fiberglass Lay In Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym and Office Washroom		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Fiberglass Lay In Ceiling Panels**

MATERIAL LOCATION: **Gym and Office Washroom**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Fire Proof Curtains		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Fire Proof Curtains**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	Green Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Elevator Lobby		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Green Terrazzo**

MATERIAL LOCATION: **1st Floor Elevator Lobby**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 101

MATERIAL DESCRIPTION: 12x12 Brown w/Black Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Room 206

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **12x12 Brown w/Black Floor Tile ABATED**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12x12 Brown w/Black Floor Tile Mastic ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12x12 Brown w/Black Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	12x12 Green w/White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Elevator Lobby		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12x12 Green w/White Floor Tile**

MATERIAL LOCATION: **2nd & 3rd Floor Elevator Lobby**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	104		
MATERIAL DESCRIPTION:	12x12 Green w/White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Elevator Lobby		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12x12 Green w/White Floor Tile Mastic**

MATERIAL LOCATION: **2nd & 3rd Floor Elevator Lobby**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12x12 Light Grey w/Dark Grey & White Floor Tile ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12x12 Light Grey w/Dark Grey & White Floor Tile ABATED**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **12x12 Light Grey w/Dark Grey & White Floor Tile Mastic ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **12x12 Light Grey w/Dark Grey & White Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 309**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>107</b>		
MATERIAL DESCRIPTION:	<b>12x12 Brown w/White Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 117, 119, 219, Basement Storage</b>		
MATERIAL QUANTITY:	<b>4400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025: Basement Storage- Concrete Floor</b>		

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **12x12 Brown w/White Floor Tile**

MATERIAL LOCATION: **Rooms 117, 119, 219, Basement Storage**

MATERIAL QUANTITY: **4400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>108</b>		
MATERIAL DESCRIPTION:	<b>12x12 Brown w/White Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 117, 119, 219 &amp; Basement Storage</b>		
MATERIAL QUANTITY:	<b>4400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025: Basement Storage- Concrete Floor</b>		

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12x12 Brown w/White Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 117, 119, 219 & Basement Storage**

MATERIAL QUANTITY: **4400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	109		
MATERIAL DESCRIPTION:	2x2 Light Tan Ceramic Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 112 Kindergarten Restroom		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- 12"x12" White Ceramic		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **2x2 Light Tan Ceramic Tile NOT OBSERVED**

MATERIAL LOCATION: **Room 112 Kindergarten Restroom**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Fire Door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building- 2nd Floor Mechanical Room, Stairway and 3rd Floor		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Fire Door**

MATERIAL LOCATION: **1978 Building- 2nd Floor Mechanical Room, Stairway and 3rd Floor**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	110		
MATERIAL DESCRIPTION:	2"x2" Light Tan Ceramic Tile Grout NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 112 Kindergarten Restroom		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. 12"x12" White Floor Tile		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **2"x2" Light Tan Ceramic Tile Grout NOT OBSERVED**

MATERIAL LOCATION: **Room 112 Kindergarten Restroom**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	12x12 Beige w/Dark Spots Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 319 Coat Room		
MATERIAL QUANTITY:	170	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **12x12 Beige w/Dark Spots Floor Tile**

MATERIAL LOCATION: **Room 319 Coat Room**

MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12x12 Beige w/Dark Spots Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 319 Coat Room		
MATERIAL QUANTITY:	170	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12x12 Beige w/Dark Spots Floor Tile Mastic**

MATERIAL LOCATION: **Room 319 Coat Room**

MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104, Principal's Office		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 104, Principal's Office**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	12x12 Grey w/White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **12x12 Grey w/White Streaks Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	Beige Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206		
MATERIAL QUANTITY:	1243	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **Beige Linoleum**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY: **1243** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	116		
MATERIAL DESCRIPTION:	Beige Linoleum Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206		
MATERIAL QUANTITY:	1243	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **Beige Linoleum Adhesive**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY: **1243** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building		
MATERIAL QUANTITY:	12100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **1894 Building**

MATERIAL QUANTITY: **12100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>13</b>		
MATERIAL DESCRIPTION:	<b>Hard Coat Plaster</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1926 Building</b>		
MATERIAL QUANTITY:	<b>36000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **1926 Building**

MATERIAL QUANTITY: **36000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building		
MATERIAL QUANTITY:	7200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **1936 Building**

MATERIAL QUANTITY: **7200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **1978 Building**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16	
MATERIAL DESCRIPTION:	Baseboard-NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1978 Building- Gym, Student Dining, Faculty Dining, Store Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed 2022, 2025

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Baseboard-NOT OBSERVED**

MATERIAL LOCATION: **1978 Building- Gym, Student Dining, Faculty Dining, Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17

MATERIAL DESCRIPTION: Baseboard Mastic-NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1978 Building- Gym, Student Dining, Faculty Dining, Store Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not observed in 2022, 2025

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Baseboard Mastic-NOT OBSERVED**

MATERIAL LOCATION: **1978 Building- Gym, Student Dining, Faculty Dining, Store Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Incinerator Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Incinerator Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Fire Brick Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Fire Brick Mortar**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20	
MATERIAL DESCRIPTION:	9x9 Green Floor Tile NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1894 Building- Room 218, Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2022, 2025- No Room 218**

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9x9 Green Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1894 Building- Room 218, Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>21</b>		
MATERIAL DESCRIPTION:	<b>9x9 Green Floor Tile Mastic NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1894 Building- Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **not observed in 2022, 2025**

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9x9 Green Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1894 Building- Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUILDING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	9x9 Beige and 9x9 Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 110		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9x9 Beige and 9x9 Dark Brown Floor Tile**

MATERIAL LOCATION: **1926 Building- Room 110**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUILDING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	9x9 Beige and 9x9 Dark Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 110		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9x9 Beige and 9x9 Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **1926 Building- Room 110**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24

MATERIAL DESCRIPTION: 9x9 Dark Brown Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1936 Building- 1st Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile ABATED**

MATERIAL LOCATION: **1936 Building- 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25

MATERIAL DESCRIPTION: 9x9 Dark Brown Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1936 Building- 2nd Floor corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile ABATED**

MATERIAL LOCATION: **1936 Building- 2nd Floor corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Room 217		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**

MATERIAL LOCATION: **1894 Building- Room 217**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Room 217		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**

MATERIAL LOCATION: **1894 Building- Room 217**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12x12 Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 206		
MATERIAL QUANTITY:	790	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**

MATERIAL LOCATION: **1926 Building- Room 206**

MATERIAL QUANTITY: **790** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12x12 Orange Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 206		
MATERIAL QUANTITY:	790	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**

MATERIAL LOCATION: **1926 Building- Room 206**

MATERIAL QUANTITY: **790** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12x12 Light Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- 1st, 2nd, and 3rd Floor Corridor		
MATERIAL QUANTITY:	5700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12x12 Light Beige Floor Tile**

MATERIAL LOCATION: **1936 Building- 1st, 2nd, and 3rd Floor Corridor**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12x12 Light Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- 1st, 2nd & 3rd Floor Corridor		
MATERIAL QUANTITY:	5700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12x12 Light Beige Floor Tile Mastic**

MATERIAL LOCATION: **1936 Building- 1st, 2nd & 3rd Floor Corridor**

MATERIAL QUANTITY: **5700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12x12 Off-White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building- 1st Floor Student Dining, Lobby, Office, Store Room, and Faculty Dining		
MATERIAL QUANTITY:	6200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile**

MATERIAL LOCATION: **1978 Building- 1st Floor Student Dining, Lobby, Office, Store Room, and Faculty Dining**

MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12x12 Off-White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building- 1st Floor Student Dining, Lobby, Office, Store Room, and Faculty Dining		
MATERIAL QUANTITY:	6200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic**

MATERIAL LOCATION: **1978 Building- 1st Floor Student Dining, Lobby, Office, Store Room, and Faculty Dining**

MATERIAL QUANTITY: **6200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Linoleum NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kindergarten Washroom		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. 12"x12" White Ceramic		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Linoleum NOT OBSERVED**

MATERIAL LOCATION: **Kindergarten Washroom**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	Linoleum Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kindergarten Washroom		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Linoleum Mastic NOT OBSERVED**

MATERIAL LOCATION: **Kindergarten Washroom**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37

MATERIAL DESCRIPTION: 9"x9" Tan Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Basement Storage Room (Old Lunchroom) Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Building Demolished

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Basement Storage Room (Old Lunchroom) Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38	
MATERIAL DESCRIPTION:	12x12 Light Beige Floor Tile Mastic NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- Room 300

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: not observed in 2022, 2025

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12x12 Light Beige Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- Room 300**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Gold Carpet Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1984 Building- Room 111		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. Hardwood Floor		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Gold Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **1984 Building- Room 111**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Green Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- 1st Floor Conference Room

MATERIAL QUANTITY: 700 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Green Carpet Mastic**

MATERIAL LOCATION: **1926 Building- 1st Floor Conference Room**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Red Carpet Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Room 106 Office**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **not observed in 2022, 2025**

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Red Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **Room 106 Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Transite Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- 3rd Floor Corridor		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **1926 Building- 3rd Floor Corridor**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Vibration Damper		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical Room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Vibration Damper**

MATERIAL LOCATION: **Mechanical Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Locker Room and Store Room		
MATERIAL QUANTITY:	630	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **1894 Building- Locker Room and Store Room**

MATERIAL QUANTITY: **630** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Locker Room and Store Room		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **1894 Building- Locker Room and Store Room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building- 1st Floor Men's and Women's Toilets, Store Room, 2nd Floor Mechanical Room		
MATERIAL QUANTITY:	2680	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **1978 Building- 1st Floor Men's and Women's Toilets, Store Room, 2nd Floor Mechanical Room**

MATERIAL QUANTITY: **2680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building- 1st Floor Men's and Women's Toilets, Store Room, 2nd Floor Mechanical Room		
MATERIAL QUANTITY:	1340	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **1978 Building- 1st Floor Men's and Women's Toilets, Store Room, 2nd Floor Mechanical Room**

MATERIAL QUANTITY: **1340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 48

MATERIAL DESCRIPTION: 9x9 Dark Brown Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1894 Building- 1st, 2nd & 3rd Floor Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile ABATED**

MATERIAL LOCATION: **1894 Building- 1st, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic Abated**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1894 Building- 1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic Abated**

MATERIAL LOCATION: **1894 Building- 1st, 2nd, and 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1894 Building- 1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile ABATED**

MATERIAL LOCATION: **1894 Building- 1st and 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 51  
MATERIAL DESCRIPTION: 9x9 Black Floor Tile Mastic ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1894 Building- 1st, 2nd and 3rd Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1894 Building- 1st, 2nd and 3rd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	9x9 Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Counselor's Office, Nurse's Office		
MATERIAL QUANTITY:	420	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **9x9 Gray Floor Tile**

MATERIAL LOCATION: **1926 Building- Counselor's Office, Nurse's Office**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	9x9 Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 107, Nurse's Office		
MATERIAL QUANTITY:	420	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic**

MATERIAL LOCATION: **1926 Building- Room 107, Nurse's Office**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	9x9 Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 107		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025: 12"x12" Grey & 12"x12" Green Floor Tile		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **9x9 Gray Floor Tile**

MATERIAL LOCATION: **1926 Building- Room 107**

MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	9x9 Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 107		
MATERIAL QUANTITY:	320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **9x9 Gray Floor Tile Mastic**

MATERIAL LOCATION: **1926 Building- Room 107**

MATERIAL QUANTITY: **320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1926 Building- Assistant Principal's Office**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS: **Assistant Principal's Office is Hardwood Floor**

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile ABATED**

MATERIAL LOCATION: **1926 Building- Assistant Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1926 Building- Assistant Principal's Office**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Assistant Principal's Office is Hardwood Floor**

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12x12 Off-White Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1926 Building- Assistant Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	9x9 Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Room 110		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile**

MATERIAL LOCATION: **1926 Building- Room 110**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	9x9 Dark Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Classroom 110		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **9x9 Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **1926 Building- Classroom 110**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Chrysotile** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1926 Building- 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS: **not observed 2022, 2025: 12"x12" White FT**

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61	
MATERIAL DESCRIPTION:	9x9 Black Floor Tile NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with potential for significant damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- 2nd & 3rd Floor Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: not observed 2022, 2025: 12"x12" White FT

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62	
MATERIAL DESCRIPTION:	9x9 Black Floor Tile NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1936 Building- 2nd Floor Corridor

MATERIAL QUANTITY:


MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2022, 2025. 12"x12" White FT

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- 2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63	
MATERIAL DESCRIPTION:	Mastic associated with 9x9 Black Floor Tile NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1936 Building- 2nd & 3rd Floor Corridors

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2022, 2025. 12"x12" White FT

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Mastic associated with 9x9 Black Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Rooms 113, 203, 204, 205, 212, 301, 305, 309		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025: Room 202 is Hardwood Floor		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**

MATERIAL LOCATION: **1926 Building- Rooms 113, 203, 204, 205, 212, 301, 305, 309**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Classrooms 113, 203, 204, 205, 212, 301, 305 & 309		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**

MATERIAL LOCATION: **1926 Building- Classrooms 113, 203, 204, 205, 212, 301, 305 & 309**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- 1st Floor Corridor and Library (Under Green Carpet)		
MATERIAL QUANTITY:	3920	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- 1st Floor Corridor and Library (Under Green Carpet)**

MATERIAL QUANTITY: **3920** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- 1st Floor Corridor & Library (Under Green Carpet)		
MATERIAL QUANTITY:	3920	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**

MATERIAL LOCATION: **1926 Building- 1st Floor Corridor & Library (Under Green Carpet)**

MATERIAL QUANTITY: **3920** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12x12 Light Brown Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Kindergarten		
MATERIAL QUANTITY:	1540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2019, 2022, 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- Kindergarten**

MATERIAL QUANTITY: **1540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12x12 Light Brown Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Kindergarten		
MATERIAL QUANTITY:	1540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. 12"x12" White FT		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- Kindergarten**

MATERIAL QUANTITY: **1540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 70

MATERIAL DESCRIPTION: 12x12 Medium Brown Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- Room 105

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12x12 Medium Brown Floor Tile ABATED**

MATERIAL LOCATION: **1926 Building- Room 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 71

MATERIAL DESCRIPTION: 12x12 Medium Brown Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- Room 105

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12x12 Medium Brown Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1926 Building- Room 105**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	12x12 Light Tan Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Principal's Office, Storeroom, Secretary's Office		
MATERIAL QUANTITY:	680	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12x12 Light Tan Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- Principal's Office, Storeroom, Secretary's Office**

MATERIAL QUANTITY: **680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	12x12 Light Tan Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Principal's Office, Storeroom, Secretary's Office		
MATERIAL QUANTITY:	680	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12x12 Light Tan Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1926 Building- Principal's Office, Storeroom, Secretary's Office**

MATERIAL QUANTITY: **680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- Rooms 112, 113, 114, 310		
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. 12"x12" White FT		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- Rooms 112, 113, 114, 310**

MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12x12 Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- Rooms 112, 113, 114, 310		
MATERIAL QUANTITY:	3900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**

MATERIAL LOCATION: **1936 Building- Rooms 112, 113, 114, 310**

MATERIAL QUANTITY: **3900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12x12 Light Brown Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- 3rd Floor Corridor		
MATERIAL QUANTITY:	940	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- 3rd Floor Corridor**

MATERIAL QUANTITY: **940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12x12 Light Brown Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- 3rd Floor Corridor		
MATERIAL QUANTITY:	940	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- 3rd Floor Corridor**

MATERIAL QUANTITY: **940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>80</b>		
MATERIAL DESCRIPTION:	<b>12x12 Brown Floor Tile NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1936 Building- 1st Floor Corridor</b>		
MATERIAL QUANTITY:	<b>940</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed 2025</b>		

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- 1st Floor Corridor**

MATERIAL QUANTITY: **940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- 1st Floor Corridor		
MATERIAL QUANTITY:	940	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- 1st Floor Corridor**

MATERIAL QUANTITY: **940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	12x12 Orange Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- 1st, 2nd, & 3rd Floor Corridors		
MATERIAL QUANTITY:	4100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12x12 Orange Floor Tile**

MATERIAL LOCATION: **1894 Building- 1st, 2nd, & 3rd Floor Corridors**

MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	Green Carpet Adhesive NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **Green Carpet Adhesive NOT OBSERVED**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	12x12 Orange Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- 1st, 2nd, & 3rd Floor Corridors		
MATERIAL QUANTITY:	4100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12x12 Orange Floor Tile Mastic**

MATERIAL LOCATION: **1894 Building- 1st, 2nd, & 3rd Floor Corridors**

MATERIAL QUANTITY: **4100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	85	
MATERIAL DESCRIPTION:	12x12 Brown Floor Tile (Duplicate of HA-80) NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1936 Building- 1st Floor Corridor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed 2025

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile (Duplicate of HA-80) NOT OBSERVED**

MATERIAL LOCATION: **1936 Building- 1st Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mallory Jones</b>		
SCHOOL NAME:	<b>Bradwell School</b>	INSPECTION DATE:	<b>5/14/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **White w/Brown Streaks Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1926 Building- 3rd Floor Corridor**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Not observed 2022, 2025**

Inspector's Signature: 

Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **White w/Brown Streaks Floor Tile**

MATERIAL LOCATION: **1926 Building- 3rd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	12x12 Dark Brown w/Light Brown Streaks Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	176	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12x12 Dark Brown w/Light Brown Streaks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **176** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	12x12 Dark Brown w/Light Brown Streaks Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	176	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12x12 Dark Brown w/Light Brown Streaks Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **176** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	12x12 Brown w/Black & White Streaks Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Washroom		
MATERIAL QUANTITY:	99	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. Concrete Floor		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12x12 Brown w/Black & White Streaks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **99** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12x12 Brown w/Black & White Streaks Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Washroom		
MATERIAL QUANTITY:	99	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12x12 Brown w/Black & White Streaks Floor Tile MasticNOT OBSERVED**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **99** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	Chalkboards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Classrooms		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **Chalkboards**

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91A		
MATERIAL DESCRIPTION:	Chalkboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Classrooms		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **91A**

MATERIAL DESCRIPTION: **Chalkboard Adhesive**

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	Mastic Beneath Wood Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stage		
MATERIAL QUANTITY:	640	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Mastic Beneath Wood Flooring**

MATERIAL LOCATION: **Stage**

MATERIAL QUANTITY: **640** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrances and Corridors		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Entrances and Corridors**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	Acoustical Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **Accoustical Plaster**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	95		
MATERIAL DESCRIPTION:	Grey & Black Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallway (Trim) & Stairwells		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **Grey & Black Terrazzo**

MATERIAL LOCATION: **Hallway (Trim) & Stairwells**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive NOT OBSERVED**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	97		
MATERIAL DESCRIPTION:	12x12 White w/Grey & Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **12x12 White w/Grey & Brown Floor Tile**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	12x12 White w/Grey & Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **12x12 White w/Grey & Brown Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Halls, Café, & Lower-Level Hall**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	99		
MATERIAL DESCRIPTION:	Tan Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Elevator Lobby		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Tan Terrazzo**

MATERIAL LOCATION: **1st Floor Elevator Lobby**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Vibration Duct Sleeves		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical Areas		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Vibration Duct Sleeves**

MATERIAL LOCATION: **Mechanical Areas**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Vibration Dampers		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building- Mechanical Room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Vibration Dampers**

MATERIAL LOCATION: **1978 Building- Mechanical Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---


### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1894 Building- Locker Room, Store room, Lunch room, 1st, 2nd Floor Corridor		
MATERIAL QUANTITY:	110	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1894 Building- Locker Room, Store room, Lunch room, 1st, 2nd Floor Corridor**

MATERIAL QUANTITY: **110** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repair response action selective to area of damage only

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Fittings on Aircell Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Locker room, store room, Lunch room, 1st, 2nd Floor Corridor		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Fittings on Aircell Insulation**

MATERIAL LOCATION: **1894 Building- Locker room, store room, Lunch room, 1st, 2nd Floor Corridor**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **1894 Building- Basement, Pipe Chase and Tunnel**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY:  DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **1894 Building- Basement, Pipe Chase and Tunnel**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Joint Insulation On Cardboard Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1984 Building- Basement, Tunnel and Pipe Chases		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Joint Insulation On Cardboard Insulated Piping**

MATERIAL LOCATION: **1984 Building- Basement, Tunnel and Pipe Chases**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Mag-Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Lunchroom, Store Room, Locker Room, and Engineers Room		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Mag-Block Pipe Insulation**

MATERIAL LOCATION: **1894 Building- Lunchroom, Store Room, Locker Room, and Engineers Room**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Pipe Fitting Insulation on Mag Block Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Lunchroom, Store Room, Locker Room, and Engine Room		
MATERIAL QUANTITY:	4	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation on Mag Block Insulated Piping**

MATERIAL LOCATION: **1894 Building- Lunchroom, Store Room, Locker Room, and Engine Room**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Fiberglass Duct Covers		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Fiberglass Duct Covers**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Crocidolite	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1978 Building- Mechanical Room		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Duct Insulation**

MATERIAL LOCATION: **1978 Building- Mechanical Room**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Fiberglass Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Fiberglass Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: Tank Insulation ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1894 Building- Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

MATERIAL LOCATION: **1894 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Vibration Duct Sleeves		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Crocidolite	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical Rooms		
MATERIAL QUANTITY:	220	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Vibration Duct Sleeves**

MATERIAL LOCATION: **Mechanical Rooms**

MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Mod-1

MATERIAL DESCRIPTION: 9"x9" Tan Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym and Storeroom- Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-1**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Gym and Storeroom- Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Mod-10

MATERIAL DESCRIPTION: 12" x 12" Brown Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Throughout Corridor - Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-10**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile ABATED**

MATERIAL LOCATION: **Throughout Corridor - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Mod-11

MATERIAL DESCRIPTION: 12" x 12" Brown Floor Tile Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Throughout Corridor - Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-11**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Throughout Corridor - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Mod-12

MATERIAL DESCRIPTION: Orange Carpet Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Office, Teachers Lounge, Principal's Office, Store Room - Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-12**

MATERIAL DESCRIPTION: **Orange Carpet Mastic ABATED**

MATERIAL LOCATION: **Office, Teachers Lounge, Principal's Office, Store Room - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Mod-13

MATERIAL DESCRIPTION: Blue Carpet Mastic ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Throughout Classrooms- Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-13**

MATERIAL DESCRIPTION: **Blue Carpet Mastic ABATED**

MATERIAL LOCATION: **Throughout Classrooms- Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Mod-2**

MATERIAL DESCRIPTION: **Wall Panels ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Modular Building- Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-2**

MATERIAL DESCRIPTION: **Wall Panels ABATED**

MATERIAL LOCATION: **Throughout Modular Building- Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Mod-4

MATERIAL DESCRIPTION: 9"x9" Tan Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym and Store Room - Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-4**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile ABATED**

MATERIAL LOCATION: **Gym and Store Room - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Mod-5		
MATERIAL DESCRIPTION:	Baseboard ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym, Mechanical Equipment Room, Store Room - Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-5**

MATERIAL DESCRIPTION: **Baseboard ABATED**

MATERIAL LOCATION: **Gym, Mechanical Equipment Room, Store Room - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Mod-6		
MATERIAL DESCRIPTION:	Baseboard Mastic ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Gym, Mechanical Equipment Room, Store Room - Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-6**

MATERIAL DESCRIPTION: **Baseboard Mastic ABATED**

MATERIAL LOCATION: **Gym, Mechanical Equipment Room, Store Room - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Mod-7**

MATERIAL DESCRIPTION: **Drywall NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Building - Building Demolished**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-7**

MATERIAL DESCRIPTION: **Drywall NOT OBSERVED**

MATERIAL LOCATION: **Throughout Building - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Mod-8

MATERIAL DESCRIPTION: 12x12 Beige Floor Tile ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Throughout Corridor - Building Demolished

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-8**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile ABATED**

MATERIAL LOCATION: **Throughout Corridor - Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Mod-9**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Throughout Corridor- Building Demolished**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-9**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Throughout Corridor- Building Demolished**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Mod-B		
MATERIAL DESCRIPTION:	Pipe Fitting Insulation on Fiberglass Insulated Piping ABATED		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Boys' and Girls' Toilets

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Mod-B**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation on Fiberglass Insulated Piping ABATED**

MATERIAL LOCATION: **Boys' and Girls' Toilets**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUILDING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Fiberglass Duct Wrap		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Above Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Fiberglass Duct Wrap**

MATERIAL LOCATION: **Above Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Installed After Implementation of Management Plan or After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

## HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

**MATERIAL LOCATION: Installed After Implementation of Management Plan or After Renovations**

**MATERIAL QUANTITY:**

## MATERIAL UNITS:

**DAMAGE QUANTITY:**

### DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

## Follow O&M Plan

### Comments:

Management Planner's Signature:

Steven B. Genes

Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	0		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**


MATERIAL LOCATION: **1926 Building- Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump Room, Store Room, and Unexcavated Area**

MATERIAL QUANTITY: **390** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **05/14/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1926 Building- Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump Room, Store Room, and Unexcavated Area**

MATERIAL QUANTITY: **390** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUILDING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- Crawlspace		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1936 Building- Crawlspace**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUILDING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Q		
MATERIAL DESCRIPTION:	Pipe Fittings on Aircell Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes


## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1926 Building- Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump Room, Storeroom, and Unexcavated Area		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Pipe Fittings on Aircell Insulated Piping**

MATERIAL LOCATION: **1926 Building- Assistant Principal's Office, 1st Floor Corridor, Room 200, Boiler Room, Pump Room, Storeroom, and Unexcavated Area**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repair response action selective to areas of damage only

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	Pipe Joint Insulation On Aircell Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- Crawlspace		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Pipe Joint Insulation On Aircell Insulated Piping**

MATERIAL LOCATION: **1936 Building- Crawlspace**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	S		
MATERIAL DESCRIPTION:	Paper Wrap Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes


## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage Deterioration		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1926 Building- Crawlspace		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **Paper Wrap Insulation**

MATERIAL LOCATION: **1926 Building- Crawlspace**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repair response action selective to area of damage only

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: T

MATERIAL DESCRIPTION: Pipe Fitting Insulation on Paper Wrap Insulated Piping ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- Crawlspace

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation on Paper Wrap Insulated Piping ABATED**

MATERIAL LOCATION: **1926 Building- Crawlspace**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUILDING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	U		
MATERIAL DESCRIPTION:	Boiler Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1926 Building- Boiler Room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **1926 Building- Boiler Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	V		
MATERIAL DESCRIPTION:	Pipe Fitting Insulation on Fiberglass Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1894 Building- Locker Room, Store Room, Lunch Room		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **V**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation on Fiberglass Insulated Piping**

MATERIAL LOCATION: **1894 Building- Locker Room, Store Room, Lunch Room**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: W

MATERIAL DESCRIPTION: Fittings on Fiberglass ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1926 Building- Basement Unexcavated Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUILDING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **W**

MATERIAL DESCRIPTION: **Fittings on Fiberglass ABATED**

MATERIAL LOCATION: **1926 Building- Basement Unexcavated Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	X		
MATERIAL DESCRIPTION:	Pipe Fitting Insulation on Fiberglass Insulated Piping		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1936 Building- Crawlspace		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22291</b>	BUIDLING ID:	<b>2340</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Steven Geneser</b>		
SCHOOL NAME:	<b>Bradwell School</b>	REVIEW DATE:	<b>6/2/2025</b>		
ADDRESS:	<b>7736 S. Burnham</b>	IDPH LICENSE NO:	<b>100-11070</b>		

---

HOMOGENEOUS AREA: **X**

MATERIAL DESCRIPTION: **Pipe Fitting Insulation on Fiberglass Insulated Piping**

MATERIAL LOCATION: **1936 Building- Crawlspace**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION


## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	117		
MATERIAL DESCRIPTION:	12"x12" White Vinyl Floor Tile		
MATERIAL LOCATION:	Classrooms 304 & 310		
MATERIAL QUANTITY:	1444	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22291** BUIDLING ID: **2340**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bradwell School** REVIEW DATE: **6/2/2025**

ADDRESS: **7736 S. Burnham** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **12"x12" White Vinyl Floor Tile**

MATERIAL LOCATION: **Classrooms 304 & 310**

MATERIAL QUANTITY: **1444** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/02/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION


## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22291	BUIDLING ID:	2340
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mallory Jones		
SCHOOL NAME:	Bradwell School	INSPECTION DATE:	5/14/2025		
ADDRESS:	7736 S. Burnham	IDPH LICENSE NO:	100-11070		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	117M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" White Vinyl Floor Tile				
MATERIAL LOCATION:	Classrooms 304 & 310				
MATERIAL QUANTITY:	1444	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/14/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22291** BUIDLING ID: **2340**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Geneser**

SCHOOL NAME: **Bradwell School** REVIEW DATE: **6/2/2025**

ADDRESS: **7736 S. Burnham** IDPH LICENSE NO: **100-11070**

HOMOGENEOUS AREA: **117M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" White Vinyl Floor Tile**

MATERIAL LOCATION: **Classrooms 304 & 310**

MATERIAL QUANTITY: **1444** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/02/2025**

## APPENDIX B

---

### Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**MALLORY JONES**  
524 HOMELAND ROAD  
MATTESON, IL 60443

3/16/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11070

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER 100 - 11070	ISSUED 3/16/2022	EXPIRES 05/15/2023	SUPERVISOR/WORKER 3/9/2023
<b>MALLORY JONES</b> 524 HOMELAND ROAD MATTESON, IL 60443 Environmental Health		PROJECT MANAGER AIR SAMPLING PROFESSIONAL <b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	6/5/2022

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MALLORY JONES  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/09/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

03/09/2022

Course Dates:

03/09/2023

Expires:

2203BIR06

Certificate Number:

Director of Training

Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

**MALLORY JONES**  
524 HOMELAND ROAD  
MATTESON, IL 60443

3/23/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11070

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

Front of License		Back of License	
 <b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b> SUPERVISOR/WORKER INSPECTOR	<b>TC EXPIRES</b> 5/31/2024 3/9/2025
ID NUMBER <b>100 - 11070</b>	ISSUED <b>3/23/2024</b>	EXPIRES <b>05/15/2025</b>	PROJECT MANAGER AIR SAMPLING PROFESSIONAL
<b>MALLORY JONES</b> 524 HOMELAND ROAD MATTESON, IL 60443 Environmental Health		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

MALLORY JONES  
524 HOMELAND ROAD  
MATTESON, IL 60443

3/7/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11070

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11070	ISSUED 3/7/2025	EXPIRES 05/15/2026	SUPERVISOR/WORKER INSPECTOR	5/29/2025 3/9/2025
<b>MALLORY JONES</b> 524 HOMELAND ROAD MATTESON, IL 60443 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	5/29/2025
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
Nationally Accredited by PHAB

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MALLORY L. JONES has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the examination on 03/19/2025 with a minimum score of 70% or better. Training was in accordance with U.S.E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

Course Dates: 03/19/2025  
Expires: 03/19/2026  
Certificate Number: 2503BIR04

Phone: 312-491-0081


Director of Training  
Nicholas J. Penef  
Doctor of Public Health

FORM # A-010B

A handwritten signature in black ink that appears to read "Nicholas J. Penef".



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR 4/5/2024

MANAGEMENT PLANNER 4/5/2024

PROJECT MANAGER 4/4/2024

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**

This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

STEVEN B GENESER  
210 BARNSIDE CIRCLE  
GENEVA, IL 60134


6/6/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 01784

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/7/2026
MANAGEMENT PLANNER	5/7/2026
PROJECT MANAGER	5/6/2026
AIR SAMPLING PROFESSIONAL	
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

**Reliable  
Environmental  
Solutions, Inc.  R E S**

*This is to certify that*

**Steve Geneser**

*has on 5/7/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: May 7, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: May 7, 2025

Expiration Date: May 7, 2026

Certificate Number: MPR/0561

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

**Reliable  
Environmental  
Solutions, Inc.      R E S**

*This is to certify that*

**Steve Geneser**

*has on 5/7/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: May 7, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: May 7, 2025

Expiration Date: May 7, 2026

Certificate Number: BIR/1252



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)



*This is to certify that*

**Steve Geneser**

*has on 5/8/24, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: May 8, 2024

Examination Date: May 8, 2024

Expiration Date: May 8, 2025

Certificate Number: MPR/0531

**COURSE LENGTH: 4 HOURS**

A handwritten signature in black ink that reads "William S. Williams".

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed