

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2103  
SCHOOL NAME: Burke School  
ADDRESS OF SCHOOL: 5356 S. King Dr.  
CITY: Chicago, IL, 60615

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 12/12/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/18/2025 ENROLLMENT 288  
IDPH INSPECTOR LICENSE NUMBER: 100-20411  
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel  
IDPH MP LICENSE NUMBER: 100-18488  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 4/11/2025

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Burke School**

5356 S. King Dr.  
Chicago, IL, 60615

Unit: 22411  
Building ID: 2460

IDPH ID Number: 14-016-2990-2103

**REPORT DATE:**  
Friday, April 11, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

04/11/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 22411      Region: 04      IDPH ID: 14-016-2990-2103

School: Burke School      Building ID: 2460

Address: 5356 S. King Dr.

Chicago, IL, 60615

Building Contact: Robinson, Renault      Contact Phone: 7736194557

Current Building Owners: Chicago Public Schools

Reinspection Date: 3/18/2025

Review Date: 04/11/2025

Inspector: Benyamen Maradkel


Inspector IDPH License: 100-20411

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Mike Serio  
100-18488

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 11, 2025

RE: Burke School, Unit 22411  
5356 S. King Dr.  
Chicago, IL, 60615

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Burke School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Burke School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

## 1. School Information

School: Burke School Unit: 22411 Region: 04  
Address: 5356 S. King Dr. Chicago, IL, 60615  
IDPH ID: 14-016-2990-2103 Building ID: 2460  
Contact: Robinson, Renault Phone: 7736194557

## 2. Description of Facility

Original Construction: 1913 Additional Construction: 1916  
Total Square Footage: 47913 No of Floors: 3  
Current Occupancy: 288

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

#### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

## 5. Inspector

Inspector Name: Benyamen Maradkel

Inspector IDPH license # 100-20411  
Reinspection Date: 3/18/2025

*Barry*

Signature: 

## 6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488

Signature: Michael J. Serr

Date: 04/11/2025

7. Review Date: 04/11/2025

## 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Signature:

Date: 4/11/2025

Name: Richard J. Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Burke School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2460:

10	Orange Linoleum Mastic
11	Interior Door Caulk
12	Exterior Door Caulk - Non-AHERA
13	Interior Tan Brick
20	Roofing Material - Non-AHERA
21	Interior Window Glazing
22	6" Vinyl Baseboard (Gray)
25	12" x 12" Self Stick Floor Tile Off-White-Bottom Layer
28	9" x 9" Brown Floor Tile w/ Beige & Rust Streaks Mastic

29	Drywall Joint Compound
2A	12" x 12" Beige w/ Tan Specks Floor Tile
30	Gray Carpet Mastic
31	12" x 12" Beige Stick on Vinyl Floor Tile
32	12" x 12" Beige Stick on Vinyl Floor Tile Mastic
34	Chalkboards
36	Plastic Wall Covering Adhesive
37	Tongue and Groove Wood Floor Vapor Barrier /Fill
38	Red Firestop
39	12" x 12" Tan Mottled Floor Tile
4	Orange Linoleum Flooring
40	12" x 12" Tan Mottled Floor Tile Mastic
41	Blue-Green Mix Carpet Mastic
43	12" x 12" Royal Blue Floor Tile Mastic
5	12" x 12 " Blue Floor Tile
7	12" x 12" Blue Floor Tile Mastic
7A	12" x 12" Beige Floor Tile w/ Tan Streaks Mastic
7C	12" x 12" Beige Floor Tile Mastic
A	Plaster
F	Mag Block Pipe Insulation
J	Boiler Breeching
L	Duo Temp Pipe Fittings
M	Mag Block Pipe Insulation

- N                   Fittings on Mag Block Pipe Insulation
- Q                   Fiberglass Pipe Insulation
- S                   Fire Doors

B. The following new homogenous areas have been identified for Building 2460:

- 41 Blue-Green Mix Carpet Mastic
- 42 12" x 12" Royal Blue Floor Tile
- 43 12" x 12" Royal Blue Floor Tile Mastic
- 44 Gray Ceramic Floor Tile & Grout
- 45 Blue Ceramic Floor Tile & Grout
- 46 Tan Ceramic Floor Tile & Grout

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	Orange Linoleum Mastic
19	Boiler Gaskets
20	Roofing Material - Non-AHERA
21	Interior Window Glazing
24	12" x 12" Self Stick Floor Tile Brown/Rust Square Pattern
25	12" x 12" Self Stick Floor Tile Off-White-Bottom Layer
29	Drywall Joint Compound
2A	12" x 12" Beige w/ Tan Specks Floor Tile
30	Gray Carpet Mastic
31	12" x 12" Beige Stick on Vinyl Floor Tile
32	12" x 12" Beige Stick on Vinyl Floor Tile Mastic
33	Multicolored Carpet Mastic
34	Chalkboards
35	White Duct Seam Tape
36	Plastic Wall Covering Adhesive
37	Tongue and Groove Wood Floor Vapor Barrier /Fill
38	Red Firestop
39	12" x 12" Tan Mottled Floor Tile
40	12" x 12" Tan Mottled Floor Tile Mastic
41	Blue-Green Mix Carpet Mastic
42	12" x 12" Royal Blue Floor Tile
43	12" x 12" Royal Blue Floor Tile Mastic
44	Gray Ceramic Floor Tile & Grout
45	Blue Ceramic Floor Tile & Grout
46	Tan Ceramic Floor Tile & Grout
5	12" x 12 " Blue Floor Tile
7A	12" x 12" Beige Floor Tile w/ Tan Streaks Mastic
7C	12" x 12" Beige Floor Tile Mastic
7D	12" x 12" Beige Floor Tile w/ Green Specks Mastic
O	Boiler Stack Insulation
P	Fire Brick Insulation - Inside Boiler
R	Fittings For Water Main TSI
S	Fire Doors

The following areas were deemed to be inaccessible:

32	12" x 12" Beige Stick on Vinyl Floor Tile Mastic
38	Red Firestop

40                    12" x 12" Tan Mottled Floor Tile Mastic  
S                    Fire Doors

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Burke School Building 2460 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Burke School **Unit** 22411 **Building ID** 2460  
**Address** 5356 S. King Dr. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
10	Orange Linoleum Mastic	2,500	SF	Auditorium	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
11	Interior Door Caulk	1,000	LF	Interior Doors Which Open to Exterior of School, North, South, East, West	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
12	Exterior Door Caulk - Non-AHERA			Exterior Doors On the North, South, East, West, Sides of the School	CHR	MISC					Yes			
13	Interior Tan Brick			Throughout Facility	NO_ACBM	MISC					Yes			
14	Interior Tan Brick Mortar			Throughout Facility	NO_ACBM	MISC					No			
15	Exterior Brick - Non-AHERA			Building Exterior	NO_ACBM	MISC					No			
16	Exterior Brick Mortar - Non-AHERA			Building Exterior	NO_ACBM	MISC					No			
17	Interior White Brick			Boiler Room, Pump Room, Hot Deck	NO_ACBM	MISC					No			
18	Interior White Brick Mortar			Boiler Room, Pump Room, Hot Deck	NO_ACBM	MISC					No			
19	Boiler Gaskets			Boiler Room	ASSUMED	MISC								
20	Roofing Material - Non-AHERA			Roof	ASSUMED	MISC					Yes			
21	Interior Window Glazing	70	LF	Roof Skylights - Boiler Room, Room 313 & 3rd Floor Mens Bathroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
22	6" Vinyl Baseboard (Gray)			Kitchen Areas	NO_ACBM	MISC					Yes			
23	6" Vinyl Baseboard (Brown & Gray) Mastic			Kitchen Area	NO_ACBM	MISC					No			
24	12" x 12" Self Stick Floor Tile Brown/Rust Square Pattern	10	SF	Teachers' Bathroom 2nd Floor 213	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
25	12" x 12" Self Stick Floor Tile Off-White-Bottom Layer	10	SF	Teachers' Bathroom 2nd Floor 213	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
26	Drywall			Room 110, Kitchen/Lunchroom Areas	NO_ACBM	MISC					No			
27	9" x 9" Brown Floor Tile w/ Beige & Rust Streaks			Principal's Office	CHR	MISC					No			
28	9" x 9" Brown Floor Tile w/ Beige & Rust Streaks Mastic			Principal's Office	CHR	MISC					Yes			
29	Drywall Joint Compound	200	SF	Room 110, Kitchen/Lunchroom Areas	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
2A	12" x 12" Beige w/ Tan Specks Floor Tile	500	SF	Room 110, 113	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Burke School **Unit** 22411 **Building ID** 2460  
**Address** 5356 S. King Dr. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
2B	12" x 12" Orange Floor Tile			Main Office - Under Carpet	CHR	MISC								
2C	12" x 12" Beige Floor Tile	550	SF	Kitchen and 1st Floor Janitor's Closet	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
2D	12" x 12" Beige w/ Green Specks Floor Tile			Room 301	NO_ACBM	MISC								
3	9" x 9" Tan Floor Tile			Main Office	CHR	MISC								
30	Gray Carpet Mastic			Main Office	ASSUMED	MISC					Yes			
31	12" x 12" Beige Stick on Vinyl Floor Tile	112	SF	2nd Floor Teachers' Lounge	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
32	12" x 12" Beige Stick on Vinyl Floor Tile	112	SF	2nd Floor Teacher Lounge	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
33	Multicolored Carpet Mastic			Main Office and Principal Office	ASSUMED	MISC								
34	Chalkboards	5,960	SF	All Classrooms On 1st, 2nd, and 3rd Floors	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
35	White Duct Seam Tape	500	SF	Above Plaster Ceiling in First Floor Corridor	ASSUMED	MISC								
36	Plastic Wall Covering Adhesive	40	SF	Kitchen	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
37	Tongue and Groove Wood Floor Vapor Barrier /Fill	10,000	SF	Room 110, Engineer's Office, 101, 111, 112, 104, 103, 102, 110, 201, 202, 213, 203, 204, 205, 212, 211, 206, 210, 207, 209, 208, Gym, 308, 309, 307, 306, 311, 312, 313, 304, 303, 302, 310, 305	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
38	Red Firestop	1	SF	1st Floor Hallway	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
39	12" x 12" Tan Mottled Floor Tile	1,000	SF	Room 301	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
4	Orange Linoleum Flooring	2,500	SF	Auditorium/Lunchroom	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
40	12" x 12" Tan Mottled Floor Tile Mastic	1,000	SF	Room 301	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
41	Blue-Green Mix Carpet Mastic	400	SF	Room 110	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		HIGH

# Chicago Public Schools

**School** Burke School **Unit** 22411 **Building ID** 2460  
**Address** 5356 S. King Dr. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
42	12" x 12" Royal Blue Floor Tile	300	SF	Patches Throughout 1st Floor Hallway, Main Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		HIGH
43	12" x 12" Royal Blue Floor Tile Mastic	300	SF	Patches Throughout 1st Floor Hallway, Main Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		HIGH
44	Gray Ceramic Floor Tile & Grout	300	SF	1st Floor Girls Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		HIGH
45	Blue Ceramic Floor Tile & Grout	400	SF	2nd & 3rd Floor Boys Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		HIGH
46	Tan Ceramic Floor Tile & Grout	800	SF	2nd & 3rd Floor Girls Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		HIGH
5	12" x 12" Blue Floor Tile	3,800	SF	1st Hallway Floor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
6	9" x 9" Tan Floor Tile Mastic			Main Office	CHR	MISC								
7	12" x 12" Blue Floor Tile Mastic	3,800	SF	1st Floor Hallway	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
7A	12" x 12" Beige Floor Tile w/ Tan Streaks Mastic	100	SF	Room 110	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
7B	12" x 12" Orange Floor Tile Mastic			Main Office	CHR	MISC								
7C	12" x 12" Beige Floor Tile Mastic	550	SF	Kitchen and 1st Floor Janitor's Closet	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
7D	12" x 12" Beige Floor Tile w/ Green Specks Mastic			Room 301	ASSUMED	MISC								
A	Plaster			Throughout	NO_ACBM	SURFACE					Yes			
B	Fittings on Fiberglass Pipe Insulation			Boiler Room and Main Office Bathroom	NO_ACBM	TSI					No			
E	Boiler Insulation	1,400	SF	Boiler Room	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Mag Block Pipe Insulation	650	LF	Water Main in Boiler Room, and Fan Room	AMO	TSI	Y	LOC	13	LF	Yes	Damaged or significantly damaged friable thermal system insulating ACBM	5	LOW
J	Boiler Breeching			Boiler Room	NO_ACBM	MISC					Yes			
K	Duo Temp Pipe Insulation	15	LF	Pump Room North Wall	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Duo Temp Pipe Fittings	5	LF	Pump Room North Wall	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
M	Mag Block Pipe Insulation	625	LF	Engineer's Office,	CHR	TSI	Y	NONE			Yes	Any remaining friable		LOW

# Chicago Public Schools

**School** Burke School **Unit** 22411 **Building ID** 2460  
**Address** 5356 S. King Dr. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, and Room 104 (East Wall, Top of Closet), Room 113, Room 201							ACBM or friable suspect ACBM			
N	Fittings on Mag Block Pipe Insulation	85	LF	Engineer's Office, Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, 1st Floor Girls Bathroom, Room 104 (N, Center Storage), 2 2nd Floor Janitor's Closets, 2nd Floor Girls and Boys Bathrooms, 3rd Floor Boys Toilet, and 3rd Floor Jan. Closet, 113	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
O	Boiler Stack Insulation	300	SF	Boiler Room	ASSUMED	TSI								
P	Fire Brick Insulation - Inside Boiler			Boiler Room, Fan Rooms - Room 106 Eng., 3rd Floor Roof Access (Above Ladder)	ASSUMED	MISC								
Q	Fiberglass Pipe Insulation			Boiler Room	NO_ACBM	TSI					Yes			
R	Fittings For Water Main TSI	19	LF	Main Office Closet and Main Office Bathroom	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
S	Fire Doors	100	SF	Vacuum Air Chambers (2)	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Burke School Unit 22411 Building ID 2460  
Address 5356 S. King Dr. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>3/18/2025</u>
Inspector Name <u>Benyamen Maradkel</u>
<u>100-20411</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	Material not observed - 2025
20	
21	
22	
23	
24	
25	
26	
27	Material not observed - 2025
28	Material not observed - 2025
29	
2A	
2B	Material not observed - 2025
2C	
2D	Material not observed - 2025

# Chicago Public Schools

School Burke School Unit 22411 Building ID 2460  
Address 5356 S. King Dr. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
3	Material not observed - 2025
30	Material not observed - 2025
31	
32	
33	Material not observed - 2025
34	
35	Material in inaccessible area(s) - 2025
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
5	
6	Material not observed - 2025
7	
7A	
7B	Material not observed - 2025
7C	
7D	Material not observed - 2025
A	
B	
E	

# Chicago Public Schools

**School** Burke School **Unit** 22411 **Building ID** 2460  
**Address** 5356 S. King Dr. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
F	Damage found in: Boiler Room
J	
K	
L	
M	
N	
O	Material in inaccessible area(s) - 2025
P	Material not observed - 2025
Q	
R	
S	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

School Burke School

Unit 22411

Building ID 2460

Address 5356 S. King Dr.

Chicago, IL, 60615

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10	Orange Linoleum Mastic	2,500	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Interior Door Caulk	1,000	LF	Interior Doors Which Open to Exterior of School, North, South, East, West	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Exterior Door Caulk - Non-AHERA			Exterior Doors On the North, South, East, West, Sides of the School	Chrysotile	MISC					
13	Interior Tan Brick			Throughout Facility	No ACBM	MISC					
14	Interior Tan Brick Mortar			Throughout Facility	No ACBM	MISC					
15	Exterior Brick - Non-AHERA			Building Exterior	No ACBM	MISC					
16	Exterior Brick Mortar - Non-AHERA			Building Exterior	No ACBM	MISC					
17	Interior White Brick			Boiler Room, Pump Room, Hot Deck	No ACBM	MISC					
18	Interior White Brick Mortar			Boiler Room, Pump Room, Hot Deck	No ACBM	MISC					
19	Boiler Gaskets			Boiler Room	Assumed	MISC					
20	Roofing Material - Non-AHERA			Roof	Assumed	MISC					
21	Interior Window Glazing	70	LF	Roof Skylights - Boiler Room, Room 313 & 3rd Floor Mens Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
22	6" Vinyl Baseboard (Gray)			Kitchen Areas	No ACBM	MISC					
23	6" Vinyl Baseboard (Brown & Gray) Mastic			Kitchen Area	No ACBM	MISC					
24	12" x 12" Self Stick Floor Tile Brown/Rust Square Pattern	10	SF	Teachers' Bathroom 2nd Floor 213	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12" x 12" Self Stick Floor Tile Off-White-Bottom Layer	10	SF	Teachers' Bathroom 2nd Floor 213	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Drywall			Room 110, Kitchen/Lunchroom Areas	No ACBM	MISC					
27	9" x 9" Brown Floor Tile w/ Beige & Rust Streaks			Principal's Office	Chrysotile	MISC					
28	9" x 9" Brown Floor Tile w/ Beige & Rust Streaks Mastic			Principal's Office	Chrysotile	MISC					
29	Drywall Joint Compound	200	SF	Room 110, Kitchen/Lunchroom Areas	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2A	12" x 12" Beige w/ Tan Specks Floor Tile	500	SF	Room 110, 113	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2B	12" x 12" Orange Floor Tile			Main Office - Under Carpet	Chrysotile	MISC					
2C	12" x 12" Beige Floor Tile	550	SF	Kitchen and 1st Floor Janitor's Closet	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2D	12" x 12" Beige w/ Green Specks Floor Tile			Room 301	No ACBM	MISC					
3	9" x 9" Tan Floor Tile			Main Office	Chrysotile	MISC					
30	Gray Carpet Mastic			Main Office	Assumed	MISC					
31	12" x 12" Beige Stick on Vinyl Floor Tile	112	SF	2nd Floor Teachers' Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12" x 12" Beige Stick on Vinyl Floor Tile Mastic	112	SF	2nd Floor Teacher Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Multicolored Carpet Mastic			Main Office and Principal Office	Assumed	MISC					

# Chicago Public Schools

**School** Burke School

**Unit** 22411

**Building ID** 2460

**Address** 5356 S. King Dr.

Chicago, IL, 60615

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
34	Chalkboards	5,960	SF	All Classrooms On 1st, 2nd, and 3rd Floors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	White Duct Seam Tape	500	SF	Above Plaster Ceiling in First Floor Corridor	Assumed	MISC			SF		Follow O&M Plan
36	Plastic Wall Covering Adhesive	40	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Tongue and Groove Wood Floor Vapor Barrier /Fill	10,000	SF	Room 110, Engineer's Office, 101, 111, 112, 104, 103, 102, 110, 201, 202, 213, 203, 204, 205, 212, 211, 206, 210, 207, 209, 208, Gym, 308, 309, 307, 306, 311, 312, 313, 304, 303, 302, 310, 305	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Red Firestop	1	SF	1st Floor Hallway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12" x 12" Tan Mottled Floor Tile	1,000	SF	Room 301	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	Orange Linoleum Flooring	2,500	SF	Auditorium/Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12" x 12" Tan Mottled Floor Tile Mastic	1,000	SF	Room 301	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Blue-Green Mix Carpet Mastic	400	SF	Room 110	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Royal Blue Floor Tile	300	SF	Patches Throughout 1st Floor Hallway, Main Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Royal Blue Floor Tile Mastic	300	SF	Patches Throughout 1st Floor Hallway, Main Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Gray Ceramic Floor Tile & Grout	300	SF	1st Floor Girls Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Blue Ceramic Floor Tile & Grout	400	SF	2nd & 3rd Floor Boys Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Tan Ceramic Floor Tile & Grout	800	SF	2nd & 3rd Floor Girls Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	12" x 12" Blue Floor Tile	3,800	SF	1st Hallway Floor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	9" x 9" Tan Floor Tile Mastic			Main Office	Chrysotile	MISC					
7	12" x 12" Blue Floor Tile Mastic	3,800	SF	1st Floor Hallway	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7A	12" x 12" Beige Floor Tile w/ Tan Streaks Mastic	100	SF	Room 110	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7B	12" x 12" Orange Floor Tile Mastic			Main Office	Chrysotile	MISC					
7C	12" x 12" Beige Floor Tile Mastic	550	SF	Kitchen and 1st Floor Janitor's Closet	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7D	12" x 12" Beige Floor Tile w/ Green Specks Mastic			Room 301	Assumed	MISC					
A	Plaster			Throughout	No ACBM	SURFACE					
B	Fittings on Fiberglass Pipe Insulation			Boiler Room and Main Office Bathroom	No ACBM	TSI					
E	Boiler Insulation	1,400	SF	Boiler Room	Chrysotile	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Mag Block Pipe Insulation	650	LF	Water Main in Boiler Room, and Fan Room	Amosite	TSI	Yes	13	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair

# Chicago Public Schools

**School** Burke School

**Unit** 22411

**Building ID** 2460

**Address** 5356 S. King Dr.

Chicago, IL, 60615

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
J	Boiler Breeching			Boiler Room	No ACBM	MISC					
K	Duo Temp Pipe Insulation	15	LF	Pump Room North Wall	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
L	Duo Temp Pipe Fittings	5	LF	Pump Room North Wall	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
M	Mag Block Pipe Insulation	625	LF	Engineer's Office, Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, and Room 104 (East Wall, Top of Closet), Room 113, Room 201	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
N	Fittings on Mag Block Pipe Insulation	85	LF	Engineer's Office, Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, 1st Floor Girls Bathroom, Room 104 (N. Center Storage), 2 2nd Floor Janitor's Closets, 2nd Floor Girls and Boys Bathrooms, 3rd Floor Boys Toilet, and 3rd Floor Jan. Closet, 113	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
O	Boiler Stack Insulation	300	SF	Boiler Room	Assumed	TSI			SF		Follow O&M Plan
P	Fire Brick Insulation - Inside Boiler			Boiler Room, Fan Rooms - Room 106 Eng., 3rd Floor Roof Access (Above Ladder)	Assumed	MISC					
Q	Fiberglass Pipe Insulation			Boiler Room	No ACBM	TSI					
R	Fittings For Water Main TSI	19	LF	Main Office Closet and Main Office Bathroom	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
S	Fire Doors	100	SF	Vacuum Air Chambers (2)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Burke School

**Unit** 22411

**Building ID** 2460

**Address** 5356 S. King Dr.

Chicago, IL, 60615

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/11/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
10	Sample to determine ACM content prior to disturbance.
11	
12	Non-AHERA
13	
14	
15	Non-AHERA
16	Non-AHERA
17	
18	
19	If identified, continue O&M
20	Non-AHERA
21	Sample to determine ACM content prior to disturbance.
22	

# Chicago Public Schools

**School** Burke School

**Unit** 22411

**Building ID** 2460

**Address** 5356 S. King Dr.

Chicago, IL, 60615

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
23	
24	Sample to determine ACM content prior to disturbance.
25	Sample to determine ACM content prior to disturbance.
26	
27	If identified, continue O&M
28	If identified, continue O&M
29	Sample to determine ACM content prior to disturbance.
2A	Sample to determine ACM content prior to disturbance.
2B	If identified, continue O&M
2C	
2D	If identified, continue O&M
3	If identified, continue O&M
30	If identified, continue O&M
31	Sample to determine ACM content prior to disturbance.
32	Sample to determine ACM content prior to disturbance.
33	If identified, continue O&M
34	Sample to determine ACM content prior to disturbance.
35	If identified, continue O&M
36	Sample to determine ACM content prior to disturbance.
37	Sample to determine ACM content prior to disturbance.
38	Sample to determine ACM content prior to disturbance.
39	Sample to determine ACM content prior to disturbance.
4	
40	Sample to determine ACM content prior to disturbance.
41	Sample to determine ACM content prior to disturbance.
42	Sample to determine ACM content prior to disturbance.
43	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Burke School

**Unit** 22411

**Building ID** 2460

**Address** 5356 S. King Dr.

Chicago, IL, 60615

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
44	Sample to determine ACM content prior to disturbance.
45	Sample to determine ACM content prior to disturbance.
46	Sample to determine ACM content prior to disturbance.
5	Sample to determine ACM content prior to disturbance.
6	If identified, continue O&M
7	
7A	Sample to determine ACM content prior to disturbance.
7B	If identified, continue O&M
7C	Sample to determine ACM content prior to disturbance.
7D	If identified, continue O&M
A	
B	
E	
F	Remove or repair damaged TSI to intact.
J	
K	
L	
M	
N	
O	If identified, continue O&M
P	If identified, continue O&M
Q	
R	Sample to determine ACM content prior to disturbance.
S	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Burke School

**Unit** 22411

**Building ID** 2460

**Address** 5356 S. King Dr.

Chicago, IL, 60615

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>10</b>		
MATERIAL DESCRIPTION:	<b>Orange Linoleum Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium</b>		
MATERIAL QUANTITY:	<b>2500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Orange Linoleum Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Interior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Interior Doors Which Open to Exterior of School, North, South, East, West		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **Interior Doors Which Open to Exterior of School, North, South, East, West**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12	
MATERIAL DESCRIPTION:	Exterior Door Caulk - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior Doors On the North, South, East, West, Sides of the School

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior Doors On the North, South, East, West, Sides of the School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13  
MATERIAL DESCRIPTION: Interior Tan Brick  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Interior Tan Brick**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14  
MATERIAL DESCRIPTION: Interior Tan Brick Mortar  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Interior Tan Brick Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17  
MATERIAL DESCRIPTION: Interior White Brick  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room, Pump Room, Hot Deck

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Interior White Brick**

MATERIAL LOCATION: **Boiler Room, Pump Room, Hot Deck**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Interior White Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room, Pump Room, Hot Deck**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Interior White Brick Mortar**

MATERIAL LOCATION: **Boiler Room, Pump Room, Hot Deck**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19	
MATERIAL DESCRIPTION:	Boiler Gaskets	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20  
MATERIAL DESCRIPTION: Roofing Material - Non-AHERA  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Non-AHERA

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>21</b>		
MATERIAL DESCRIPTION:	<b>Interior Window Glazing</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Roof Skylights - Boiler Room, Room 313 &amp; 3rd Floor Mens Bathroom</b>		
MATERIAL QUANTITY:	<b>70</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Interior Window Glazing**

MATERIAL LOCATION: **Roof Skylights - Boiler Room, Room 313 & 3rd Floor Mens Bathroom**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22  
MATERIAL DESCRIPTION: 6" Vinyl Baseboard (Gray)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen Areas

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **6" Vinyl Baseboard (Gray)**

MATERIAL LOCATION: **Kitchen Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23  
MATERIAL DESCRIPTION: 6" Vinyl Baseboard (Brown & Gray) Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen Area

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **6" Vinyl Baseboard (Brown & Gray) Mastic**

MATERIAL LOCATION: **Kitchen Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12" x 12" Self Stick Floor Tile Brown/Rust Square Pattern		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers' Bathroom 2nd Floor 213		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Self Stick Floor Tile Brown/Rust Square Pattern**

MATERIAL LOCATION: **Teachers' Bathroom 2nd Floor 213**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12" x 12" Self Stick Floor Tile Off-White-Bottom Layer		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers' Bathroom 2nd Floor 213		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Self Stick Floor Tile Off-White-Bottom Layer**

MATERIAL LOCATION: **Teachers' Bathroom 2nd Floor 213**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26  
MATERIAL DESCRIPTION: Drywall  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 110, Kitchen/Lunchroom Areas

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Room 110, Kitchen/Lunchroom Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27  
MATERIAL DESCRIPTION: 9" x 9" Brown Floor Tile w/ Beige & Rust Streaks  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Principal's Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Beige & Rust Streaks**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: 9" x 9" Brown Floor Tile w/ Beige & Rust Streaks Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Principal's Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile w/ Beige & Rust Streaks Mastic**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 110, Kitchen/Lunchroom Areas		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Room 110, Kitchen/Lunchroom Areas**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige w/ Tan Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110, 113</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Tan Specks Floor Tile**

MATERIAL LOCATION: **Room 110, 113**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office - Under Carpet**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile**

MATERIAL LOCATION: **Main Office - Under Carpet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2C</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen and 1st Floor Janitor's Closet</b>		
MATERIAL QUANTITY:	<b>550</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **2C**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Kitchen and 1st Floor Janitor's Closet**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 2D

MATERIAL DESCRIPTION: 12" x 12" Beige w/ Green Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 301

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **2D**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Green Specks Floor Tile**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 3  
MATERIAL DESCRIPTION: 9" x 9" Tan Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 30  
MATERIAL DESCRIPTION: Gray Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>31</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Stick on Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2nd Floor Teachers' Lounge</b>		
MATERIAL QUANTITY:	<b>112</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Beige Stick on Vinyl Floor Tile**

MATERIAL LOCATION: **2nd Floor Teachers' Lounge**

MATERIAL QUANTITY: **112** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>32</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Stick on Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2nd Floor Teacher Lounge</b>		
MATERIAL QUANTITY:	<b>112</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Beige Stick on Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Teacher Lounge**

MATERIAL QUANTITY: **112** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33	
MATERIAL DESCRIPTION:	Multicolored Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office and Principal Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Multicolored Carpet Mastic**

MATERIAL LOCATION: **Main Office and Principal Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Chalkboards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Classrooms On 1st, 2nd, and 3rd Floors		
MATERIAL QUANTITY:	5960	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Chalkboards**

MATERIAL LOCATION: **All Classrooms On 1st, 2nd, and 3rd Floors**

MATERIAL QUANTITY: **5960** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	White Duct Seam Tape		
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Above Plaster Ceiling in First Floor Corridor

MATERIAL QUANTITY: 500 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS: Material in inaccessible area(s) - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **White Duct Seam Tape**

MATERIAL LOCATION: **Above Plaster Ceiling in First Floor Corridor**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>36</b>		
MATERIAL DESCRIPTION:	<b>Plastic Wall Covering Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen</b>		
MATERIAL QUANTITY:	<b>40</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Plastic Wall Covering Adhesive**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Tongue and Groove Wood Floor Vapor Barrier /Fill		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 110, Engineer's Office, 101, 111, 112, 104, 103, 102, 110, 201, 202, 213, 203, 204, 205, 212, 211, 206, 210, 207, 209, 208, Gym, 308, 309, 307, 306, 311, 312, 313, 304, 303, 302, 310, 305**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Tongue and Groove Wood Floor Vapor Barrier /Fill**

MATERIAL LOCATION: **Room 110, Engineer's Office, 101, 111, 112, 104, 103, 102, 110, 201, 202, 213, 203, 204, 205, 212, 211, 206, 210, 207, 209, 208, Gym, 308, 309, 307, 306, 311, 312, 313, 304, 303, 302, 310, 305**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

#### Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Red Firestop		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Hallway		
MATERIAL QUANTITY:	1	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Red Firestop**

MATERIAL LOCATION: **1st Floor Hallway**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>39</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan Mottled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 301</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Tan Mottled Floor Tile**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	Orange Linoleum Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium/Lunchroom		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Orange Linoleum Flooring**

MATERIAL LOCATION: **Auditorium/Lunchroom**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>40</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan Mottled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 301</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12" x 12" Tan Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	12" x 12 " Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Hallway Floor		
MATERIAL QUANTITY:	3800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **12" x 12 " Blue Floor Tile**

MATERIAL LOCATION: **1st Hallway Floor**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 6  
MATERIAL DESCRIPTION: 9" x 9" Tan Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>7</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blue Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Hallway</b>		
MATERIAL QUANTITY:	<b>3800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Hallway**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>7A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Floor Tile w/ Tan Streaks Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110</b>		
MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **7A**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Tan Streaks Mastic**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7B

MATERIAL DESCRIPTION: 12" x 12" Orange Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **7B**

MATERIAL DESCRIPTION: **12" x 12" Orange Floor Tile Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>7C</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen and 1st Floor Janitor's Closet</b>		
MATERIAL QUANTITY:	<b>550</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **7C**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen and 1st Floor Janitor's Closet**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7D

MATERIAL DESCRIPTION: 12" x 12" Beige Floor Tile w/ Green Specks Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 301

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **7D**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Green Specks Mastic**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A  
MATERIAL DESCRIPTION: Plaster  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM      FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout

MATERIAL QUANTITY:      MATERIAL UNITS:

DAMAGE QUANTITY:      DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room and Main Office Bathroom**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Boiler Room and Main Office Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Boiler Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	1 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Amosite	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Water Main in Boiler Room, and Fan Room		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Damage found in: Boiler Room		

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Water Main in Boiler Room, and Fan Room**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **13** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Remove or repair damaged TSI to intact.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Boiler Breeching**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Boiler Breeching**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Duo Temp Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pump Room North Wall		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Duo Temp Pipe Insulation**

MATERIAL LOCATION: **Pump Room North Wall**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUILDING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Duo Temp Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pump Room North Wall		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Duo Temp Pipe Fittings**

MATERIAL LOCATION: **Pump Room North Wall**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, and Room 104 (East Wall, Top of Closet), Room 113, Room 201**

MATERIAL QUANTITY: **625** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Engineer's Office, Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, and Room 104 (East Wall, Top of Closet), Room 113, Room 201**

MATERIAL QUANTITY: **625** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Fittings on Mag Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Engineer's Office, Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, 1st Floor Girls Bathroom, Room 104 (N. Center Storage), 2 2nd Floor Janitor's Closets, 2nd Floor Girls and Boys Bathrooms, 3rd Floor Boys Toilet, and 3rd Floor Jan. Closet, 113**

MATERIAL QUANTITY: **85** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Fittings on Mag Block Pipe Insulation**

MATERIAL LOCATION: **Engineer's Office, Boiler Room, Pump Room, Engine Room, 2nd Floor Teachers' Lounge, 1st Floor Girls Bathroom, Room 104 (N. Center Storage), 2 2nd Floor Janitor's Closets, 2nd Floor Girls and Boys Bathrooms, 3rd Floor Boys Toilet, and 3rd Floor Jan. Closet, 113**

MATERIAL QUANTITY: **85** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>O</b>		
MATERIAL DESCRIPTION:	<b>Boiler Stack Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:	<b>Boiler Room</b>	
--------------------	--------------------	--

MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS: <b>SF</b>
--------------------	------------	---------------------------

DAMAGE QUANTITY:		DAMAGE UNITS: <b>SF</b>
------------------	--	-------------------------

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:



Date: **03/18/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Boiler Stack Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: P

MATERIAL DESCRIPTION: Fire Brick Insulation - Inside Boiler

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room, Fan Rooms - Room 106 Eng., 3rd Floor Roof Access (Above Ladder)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Fire Brick Insulation - Inside Boiler**

MATERIAL LOCATION: **Boiler Room, Fan Rooms - Room 106 Eng., 3rd Floor Roof Access (Above Ladder)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: Q

MATERIAL DESCRIPTION: Fiberglass Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	Fittings For Water Main TSI		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office Closet and Main Office Bathroom		
MATERIAL QUANTITY:	19	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Fittings For Water Main TSI**

MATERIAL LOCATION: **Main Office Closet and Main Office Bathroom**

MATERIAL QUANTITY: **19** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	S		
MATERIAL DESCRIPTION:	Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Vacuum Air Chambers (2)		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUILDING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Burke School</b>	REVIEW DATE:	<b>4/11/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

---

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Vacuum Air Chambers (2)**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/11/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22411</b>	BUIDLING ID:	<b>2460</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Benyamen Maradkel</b>		
SCHOOL NAME:	<b>Burke School</b>	INSPECTION DATE:	<b>3/18/2025</b>		
ADDRESS:	<b>5356 S. King Dr.</b>	IDPH LICENSE NO:	<b>100-20411</b>		

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	<b>45</b>			
MATERIAL DESCRIPTION:	<b>Blue Ceramic Floor Tile &amp; Grout</b>			
MATERIAL LOCATION:	<b>2nd &amp; 3rd Floor Boys Bathroom</b>			
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>	
MATERIAL CATEGORY:	<b>MISC</b>	FRIABLE:	<b>No</b>	
ASBESTOS TYPE:	<b>Assumed</b>			
DISTURBANCE POTENTIAL:	<b>HIGH</b>	CONDITION:	<b>No Damage</b>	
AHERA DAMAGE CATEGORY:	<b>6 ACBM with the potential for damage</b>			
ACCESSIBILITY:	<b>Within Reach</b>	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	<b>SF</b>	
COMMENTS:				

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22411** BUIDLING ID: **2460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Burke School** REVIEW DATE: **4/11/2025**

ADDRESS: **5356 S. King Dr.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Blue Ceramic Floor Tile & Grout**

MATERIAL LOCATION: **2nd & 3rd Floor Boys Bathroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Tan Ceramic Floor Tile & Grout		
MATERIAL LOCATION:	2nd & 3rd Floor Girls Bathroom		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22411** BUIDLING ID: **2460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Burke School** REVIEW DATE: **4/11/2025**

ADDRESS: **5356 S. King Dr.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Tan Ceramic Floor Tile & Grout**

MATERIAL LOCATION: **2nd & 3rd Floor Girls Bathroom**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	43			
MATERIAL DESCRIPTION:	12" x 12" Royal Blue Floor Tile Mastic			
MATERIAL LOCATION:	Patches Throughout 1st Floor Hallway, Main Office			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22411** BUIDLING ID: **2460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Burke School** REVIEW DATE: **4/11/2025**

ADDRESS: **5356 S. King Dr.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Royal Blue Floor Tile Mastic**

MATERIAL LOCATION: **Patches Throughout 1st Floor Hallway, Main Office**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	42			
MATERIAL DESCRIPTION:	12" x 12" Royal Blue Floor Tile			
MATERIAL LOCATION:	Patches Throughout 1st Floor Hallway, Main Office			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22411** BUIDLING ID: **2460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Burke School** REVIEW DATE: **4/11/2025**

ADDRESS: **5356 S. King Dr.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Royal Blue Floor Tile**

MATERIAL LOCATION: **Patches Throughout 1st Floor Hallway, Main Office**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	41			
MATERIAL DESCRIPTION:	Blue-Green Mix Carpet Mastic			
MATERIAL LOCATION:	Room 110			
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22411** BUIDLING ID: **2460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Burke School** REVIEW DATE: **4/11/2025**

ADDRESS: **5356 S. King Dr.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Blue-Green Mix Carpet Mastic**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/11/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22411	BUIDLING ID:	2460
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	Burke School	INSPECTION DATE:	3/18/2025		
ADDRESS:	5356 S. King Dr.	IDPH LICENSE NO:	100-20411		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	44			
MATERIAL DESCRIPTION:	Gray Ceramic Floor Tile & Grout			
MATERIAL LOCATION:	1st Floor Girls Bathroom			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	

COMMENTS:

Inspector's Signature:



Date: 03/18/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22411** BUIDLING ID: **2460**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Burke School** REVIEW DATE: **4/11/2025**

ADDRESS: **5356 S. King Dr.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Gray Ceramic Floor Tile & Grout**

MATERIAL LOCATION: **1st Floor Girls Bathroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/11/2025

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Benyamen Maradkel

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: BIR2503070918


Course Credit Hours: BIR 4 Hrs.

Kristina Miczek, Training Manager

# Benyamen Maradkel

---

## Illinois Licensed Building Inspector



### ENDORSEMENTS

INSPECTOR

### TC EXPIRES

3/7/2026

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

---

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Serio**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed