

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2119
SCHOOL NAME: Carty School
ADDRESS OF SCHOOL: 3740 N Panama Avenue
CITY: Chicago, IL, 60634

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/29/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 2/4/2025 ENROLLMENT 810
IDPH INSPECTOR LICENSE NUMBER: 100-07210
IDPH LICENSED INSPECTOR NAME (Please Print): Michael Holvay
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 2/19/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Canty School

3740 N Panama Avenue
Chicago, IL, 60634

Unit: 22541
Building ID: 2620

IDPH ID Number: 14-016-2990-2119

REPORT DATE:
Wednesday, February 19, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Specialty Consulting, Inc.

2942 W. Van Buren Street

Chicago, IL, 60612

Phone (312) 319-7575

Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

02/19/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22541 Region: 01 IDPH ID: 14-016-2990-2119

School: Carty School Building ID: 2620

Address: 3740 N Panama Avenue

Chicago, IL, 60634

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 2/4/2025

Review Date: 02/19/2025

Inspector: Michael Holvay

Inspector IDPH License: 100-07210

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: February 19, 2025

RE: Carty School, Unit 22541
3740 N Panama Avenue
Chicago, IL, 60634

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Carty School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Carty School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Carty School Unit: 22541 Region: 01
Address: 3740 N Panama Avenue Chicago, IL, 60634
IDPH ID: 14-016-2990-2119 Building ID: 2620
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 4900 No of Floors:
Current Occupancy: 810

3. LEA Designated Person

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Michael Holvay


Michael Holvay
Project Manager

Signature: _____
Date: 2/4/2025

6. Management Planner

Management Planner Name: Jigar Shah

Troyanov, Svetlana
Signature:
Date: 02/19/2025

Management Planner IDPH license # 100-07342

7. Review Date: 02/19/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schlegel

Date: 2/19/2025

Name: Richard J Schleifer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Carty School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 2620:

B. The following new homogenous areas have been identified for Building 2620:

- 54 12" x 12" White with Multicolor Specs VFT
- 55 12" x 12" White w/ Multicolor Specs VFT Mastic
- 56 2' x 4' White w/ Holes Ceiling Tile
- 57 Vinyl Baseboard Mastic
- 58 Drywall System
- 59 Carpet Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

25	12"x12" White w/ Tan Spots VFT
38	Carpet Mastic
39	12"x12" White w/blue specks VFT
40	12"x12" White w/blue specks VFT Mastic
41	Terrazzo
42	Drywall, Tape, and Compound
43	Fire Doors - REMOVED
44	Terrazzo
46	Vinyl Baseboard Mastic
50	2' x 2' Green Vinyl floor tile
50A	2' x 2' Green Vinyl floor tile Mastic
51	2' x 2' Orange vinyl floor tile
51A	2' x 2' Orange vinyl floor tile Mastic
52	2' x 2' White w/ brown streaks VFT
52A	2' x 2' White w/ brown streaks VFT Mastic
53	12" x 12" Sand VFT
53A	12" x 12" Sand VFT Mastic
54	12" x 12" White with Multicolor Specs VFT
55	12" x 12" White w/ Multicolor Specs VFT Mastic
56	2' x 4' White w/ Holes Ceiling Tile
57	Vinyl Baseboard Mastic
58	Drywall System
59	Carpet Mastic

The following areas were deemed to be inaccessible:

51	2' x 2' Orange vinyl floor tile
I	Aircell Duct Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Michael Holvay, IDPH License # 100-07210. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	4/7/2023
	4/7/2023
	4/7/2023
	4/7/2023
	11/26/2024
	11/26/2024
	11/26/2024

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Canty School Building 2620 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
05	12"x12" Cream VFT	4,130	SF	1st & 2nd Floor Corridors - 1936 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
06	9"x9" Gray w/ Black & Tan Streaks VFT - ABATED IN 2006			Engineer's Office - ABATED IN 2006 (1936)	ABATED	MISC								
07	12"x12" Cream VFT Mastic	4,130	SF	1st & 2nd Floor Corridors - 1936 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	9"x9" Gray w/ Black & Tan Streaks VFT Mastic - ABATED IN 2006			Engineer's Office - ABATED IN 2006 (1936)	ABATED	MISC								
09	12"x12" Tan with brown streaks VFT	5,720	SF	Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
10	9"x9" Tan with brown streaks VFT	1,020	SF	1st & 2nd Floor Corridors - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
11	12"x12" Tan with brown streaks VFT Mastic	5,720	SF	Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	9"x9" Tan with brown streaks VFT Mastic	1,020	SF	1st and 2nd Floor Corridors - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" Light Beige w/ Maroon streaks VFT	1,376	SF	Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
14	12"x12" Light Beige w/ Maroon streaks VFT Mastic	1,376	SF	Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	9"x9" Light Beige w/ Maroon streaks VFT	1,020	SF	1st and 2nd Floor Hallways - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
16	9"x9" Light Beige w/ Maroon streaks VFT Mastic	1,020	SF	1st and 2nd Floor Hallways - 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	9"x9" Light Beige w/ Maroon streaks VFT	540	SF	1st and 2nd Floor North Corridors - 1936	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17A	9"x9" Light Beige w/ Maroon streaks VFT Mastic	540	SF	1st and 2nd Floor North Corridors - 1936	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	9"x9" Tan w/ brown streaks VFT	540	SF	1st and 2nd Floor North Corridors -	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

Chicago Public Schools

School Cnty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Mobile (No Longer on site)										
49	Drywall, tape and compound - REMOVED			Throughout 2000 Mobile (No Longer on site)		MISC								
50	2' x 2' Green Vinyl floor tile	120	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
50A	2' x 2' Green Vinyl floor tile Mastic	120	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	2' x 2' Orange vinyl floor tile	180	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51A	2' x 2' Orange vinyl floor tile Mastic	180	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	2' x 2' White w/ brown streaks VFT	300	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52A	2' x 2' White w/ brown streaks VFT Mastic	300	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12" x 12" Sand VFT	100	SF	1st floor corridor by main entrance - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53A	12" x 12" Sand VFT Mastic	100	SF	1st floor corridor by main entrance - 1936 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12" x 12" White with Multicolor Specs VFT	4,500	SF	Throughout Branch Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
55	12" x 12" White w/ Multicolor Specs VFT Mastic	4,500	SF	Throughout Branch Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
56	2' x 4' White w/ Holes Ceiling Tile	4,700	SF	Throughout Branch Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
57	Vinyl Baseboard Mastic	5,000	LF	Throughout Branch Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58	Drywall System	12,500	SF	Throughout Branch Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Carpet Mastic	120	SF	Copy Room - Branch Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	Cardboard Pipe Insulation	100	LF	Basement Passage - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP E/F/V on Cardboard Pipe Insulation	10	FITTING	Basement Passage - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	Aircell Pipe Insulation	400	LF	1st Floor Teacher's Lunchroom and Storeroom, Transformer Room and the NE and SW Pipe Space - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Aircell Pipe Insulation	160	FITTING	1st Floor Teacher's Lunchroom and Storeroom, NE Pipe Space and Transformer Room - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Preform Pipe Insulation	226	LF	Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washroom - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	MJP E/F/V on Preform Pipe Insulation	75	FITTING	Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washrooms - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Aircell Duct Insulation	100	SF	East & West Basement Pipe Spaces - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Mag Block Tank Insulation (Abated)	0		Boiler Room (Abated)- 1936	ABATED	TSI			0					
L	Boiler Jacket Insulation	690	SF	Boiler Room - 1936	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
N	Cardboard Pipe Insulation	74	LF	1st and 2nd Floor	CHR	TSI	Y	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage/Pump Room, 1st Fl Boy's Room, Toilet, Boiler Room - 1952								potential for damage		
O	MJP E/F/V on Cardboard Pipe Insulation	20	FITTING	1st and 2nd Floor Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage - 1952	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
P	Aircell Pipe Insulation	45	LF	1st Floor Janitor's Closet - 1952	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Q	MJP E/F/V on Aircell Pipe Insulation	5	FITTING	1st Floor Janitor's Closet - 1952	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
R	Preform Pipe Insulation	425	LF	Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
S	MJP E/F/V on Preform Pipe Insulation	55	FITTING	Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
T	Aircell Pipe Insulation	300	LF	Auditorium Crawlspace - 1950 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
U	MJP E/F/V on Aircell Pipe Insulation	40	FITTING	Auditorium Crawlspace - 1950 Addition	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
V	Hard Coat Plaster			Auditorium Crawlspace - 1950 Addition	NO_ACBM				0					
W	2'x4' Ceiling Tile			Auditorium Crawlspace - 1950 Addition	NO_ACBM				0					

Chicago Public Schools

School Carty School Unit 22541 Building ID 2620
Address 3740 N Panama Avenue Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date 2/4/2025
Inspector Name Michael Holvay
100-07210 5/15/2026
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
05	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
17A	
18	
18A	
19	
20	
21	
22	
23	
24	
25	
25A	

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
26	
27	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
45A	
46	
47	
48	
49	
50	
50A	
51	
51A	
52	

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
52A	
53	
53A	
54	Branch Building is located at 8300 W. Addison
55	Branch Building is located at 8300 W. Addison
56	Branch Building is located at 8300 W. Addison
57	Branch Building is located at 8300 W. Addison
58	Branch Building is located at 8300 W. Addison
59	Branch Building is located at 8300 W. Addison
C	
D	
E	
F	
G	
H	
I	
J	
L	
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	

Chicago Public Schools

School Carty School **Unit** 22541 **Building ID** 2620
Address 3740 N Panama Avenue **Region** 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
05	12"x12" Cream VFT	4,130	SF	1st & 2nd Floor Corridors - 1936 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9"x9" Gray w/ Black & Tan Streaks VFT - ABATED IN 2006			Engineer's Office - ABATED IN 2006 (1936)	Abated	MISC					
07	12"x12" Cream VFT Mastic	4,130	SF	1st & 2nd Floor Corridors - 1936 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	9"x9" Gray w/ Black & Tan Streaks VFT Mastic - ABATED IN 2006			Engineer's Office - ABATED IN 2006 (1936)	Abated	MISC					
09	12"x12" Tan with brown streaks VFT	5,720	SF	Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9"x9" Tan with brown streaks VFT	1,020	SF	1st & 2nd Floor Corridors - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12"x12" Tan with brown streaks VFT Mastic	5,720	SF	Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9"x9" Tan with brown streaks VFT Mastic	1,020	SF	1st and 2nd Floor Corridors - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Light Beige w/ Maroon streaks VFT	1,376	SF	Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Light Beige w/ Maroon streaks VFT Mastic	1,376	SF	Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9"x9" Light Beige w/ Maroon streaks VFT	1,020	SF	1st and 2nd Floor Hallways - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9"x9" Light Beige w/ Maroon streaks VFT Mastic	1,020	SF	1st and 2nd Floor Hallways - 1952	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	9"x9" Light Beige w/ Maroon streaks VFT	540	SF	1st and 2nd Floor North Corridors - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17A	9"x9" Light Beige w/ Maroon streaks VFT Mastic	540	SF	1st and 2nd Floor North Corridors - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	9"x9" Tan w/ brown streaks VFT	540	SF	1st and 2nd Floor North Corridors - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18A	9"x9" Tan w/ brown streak VFT Mastic	540	SF	1st and 2nd Floor North Corridors - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	9"x9" Dark Gray w/ Tan Streaks VFT (Under HA# 49 & 50)	100	SF	1st floor Engineer's Office (old office) (Under HA# 49 & 50) - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9"x9" Dark Gray w/ Tan Streaks VFT Mastic (Under HA# 49 & 50)	100	SF	1st floor Engineer's Office (old office) (Under HA# 49 & 50) - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9"x9" Gray w/ Black Streaks VFT (Under HA# 49 & 50)	150	SF	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	9"x9" Gray w/ Black Streaks VFT Mastic (Under HA# 49 & 50)	150	SF	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	9"x9" Black VFT (Under HA# 49 & 50)	150	SF	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
24	9"x9" Black VFT Mastic (Under HA# 49 & 50)	150	SF	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" White w/ Tan Spots VFT	96	SF	Room 114 - 1936	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	12"x12" White w/ Tan Spots VFT Mastic	96	SF	Room 114 - 1936	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Hard Coat Plaster			Rooms 114, 115, 212, 213 and 214 - 1952	No ACBM						
27	2'x4' Ceiling Tile			1st & 2nd Floor Corridor - 1952	No ACBM						
29	Red Linoleum (Painted Black)			Library (under the carpet), Teacher's Lounge Washroom, 211B and hall by 211B- 1936	No ACBM						
30	Yellow Linoleum (Painted Black)			2nd Floor North Corridor (211C) - 1936	No ACBM						
31	Green Linoleum (Painted Black)			Teacher's Washroom (211C) - 1936	No ACBM						
32	Hard Coat Plaster			1st Floor Corridor - 1936	No ACBM						
33	2'x4' Ceiling Tile			1st & 2nd Floor Corridor - 1936	No ACBM						
34	MJP E/F/V on Fiberglass Pipe Insulation			Throughout Basement - 1936	No ACBM						
35	12"x12" White w/speckles VFT - REMOVED			Throughout 2000 Mobile (No Longer on site)	MISC						
36	12"x12" White w/speckles VFT - REMOVED			Throughout 2000 Mobile (No Longer on site)	MISC						
37	2'x2' Ceiling Tile - REMOVED			Throughout 2000 Mobile (No Longer on site)	MISC						
38	Carpet Mastic	700	SF	Room 207 (Library)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"x12" White w/blue specks VFT	1,200	SF	1st Floor Teachers Lounge, Storage Room and Asst. Prin. Office - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" White w/blue specks VFT Mastic	1,200	SF	1st Floor Teachers Lounge, Storage Room and Asst. Prin. Office - 1936 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Terrazzo	500	SF	Stairwells - 1936	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Drywall, Tape, and Compound	300	SF	2nd Floor Corridor Next to Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Fire Doors - REMOVED	1	EA	Mechanical Room in 2000 Mobile (No Longer on site)	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
44	Terrazzo	300	SF	Stairwells - 1952	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Duplicate HA - Same as HA# 39					MISC					
45A	Duplicate HA - Same HA as HA# 40					MISC					
46	Vinyl Baseboard Mastic	50	LF	2nd Floor Corridor Next to Room 207 -	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				1936							
47	Vinyl Baseboard Mastic - REMOVED			Throughout 2000 Mobile (No Longer on site)		MISC					
48	Textured Ceiling Paint - REMOVED			Throughout 2000 Mobile (No Longer on site)		MISC					
49	Drywall, tape and compound - REMOVED			Throughout 2000 Mobile (No Longer on site)		MISC					
50	2' x 2' Green Vinyl floor tile	120	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50A	2' x 2' Green Vinyl floor tile Mastic	120	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	2' x 2' Orange vinyl floor tile	180	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51A	2' x 2' Orange vinyl floor tile Mastic	180	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	2' x 2' White w/ brown streaks VFT	300	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52A	2' x 2' White w/ brown streaks VFT Mastic	300	SF	1st and 2nd floor link to corridor to new addition building - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12" x 12" Sand VFT	100	SF	1st floor corridor by main entrance - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53A	12" x 12" Sand VFT Mastic	100	SF	1st floor corridor by main entrance - 1936 building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" White with Multicolor Specs VFT	4,500	SF	Throughout Branch Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" White w/ Multicolor Specs VFT Mastic	4,500	SF	Throughout Branch Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	2' x 4' White w/ Holes Ceiling Tile	4,700	SF	Throughout Branch Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Vinyl Baseboard Mastic	5,000	LF	Throughout Branch Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
58	Drywall System	12,500	SF	Throughout Branch Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Carpet Mastic	120	SF	Copy Room - Branch Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation	100	LF	Basement Passage - 1936	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Cardboard Pipe Insulation	10	FITTING	Basement Passage - 1936	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
E	Aircell Pipe Insulation	400	LF	1st Floor Teacher's Lunchroom and Storeroom, Transformer Room and the NE and SW Pipe Space - 1936	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Aircell Pipe Insulation	160	FITTING	1st Floor Teacher's Lunchroom and Storeroom, NE Pipe Space and	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Transformer Room - 1936							
G	Preform Pipe Insulation	226	LF	Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washroom - 1936	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	MJP E/F/V on Preform Pipe Insulation	75	FITTING	Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washrooms - 1936	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
I	Aircell Duct Insulation	100	SF	East & West Basement Pipe Spaces - 1936	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J	Mag Block Tank Insulation (Abated)	0		Boiler Room (Abated)- 1936	Abated	TSI		0			Follow O&M Plan
L	Boiler Jacket Insulation	690	SF	Boiler Room - 1936	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Cardboard Pipe Insulation	74	LF	1st and 2nd Floor Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage/Pump Room, 1st Fl Boy's Toilet, Boiler Room - 1952	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
O	MJP E/F/V on Cardboard Pipe Insulation	20	FITTING	1st and 2nd Floor Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage - 1952	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
P	Aircell Pipe Insulation	45	LF	1st Floor Janitor's Closet - 1952	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q	MJP E/F/V on Aircell Pipe Insulation	5	FITTING	1st Floor Janitor's Closet - 1952	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
R	Preform Pipe Insulation	425	LF	Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
S	MJP E/F/V on Preform Pipe Insulation	55	FITTING	Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
T	Aircell Pipe Insulation	300	LF	Auditorium Crawlspase - 1950 Addition	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
U	MJP E/F/V on Aircell Pipe Insulation	40	FITTING	Auditorium Crawlspase - 1950 Addition	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
V	Hard Coat Plaster			Auditorium Crawlspase - 1950 Addition	No ACBM			0			
W	2x4' Ceiling Tile			Auditorium Crawlspase - 1950 Addition	No ACBM			0			

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	2/19/2025
Manager Planner Name	Jigar Shah
100-07342	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
05	
06	
07	
08	
09	
10	
11	
12	
13	

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
14	
15	
16	
17	
17A	
18	
18A	
19	
20	
21	
22	
23	
24	
25	
25A	
26	
27	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
39	
40	
41	
42	
43	
44	
45	
45A	
46	
47	
48	
49	
50	
50A	
51	
51A	
52	
52A	
53	
53A	
54	
55	
56	
57	
58	
59	
C	

Chicago Public Schools

School Carty School

Unit 22541

Building ID 2620

Address 3740 N Panama Avenue

Chicago, IL, 60634

Region 01

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
D	
E	
F	
G	
H	
I	
J	
L	
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	12"x12" Cream VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st & 2nd Floor Corridors - 1936 Bldg.		
MATERIAL QUANTITY:	4130	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12"x12" Cream VFT**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936 Bldg.**

MATERIAL QUANTITY: **4130** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	9"x9" Gray w/ Black & Tan Streaks VFT - ABATED IN 2006		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office - ABATED IN 2006 (1936)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & Tan Streaks VFT - ABATED IN 2006**

MATERIAL LOCATION: **Engineer's Office - ABATED IN 2006 (1936)**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	12"x12" Cream VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st & 2nd Floor Corridors - 1936 Bldg.		
MATERIAL QUANTITY:	4130	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12"x12" Cream VFT Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1936 Bldg.**

MATERIAL QUANTITY: **4130** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	9"x9" Gray w/ Black & Tan Streaks VFT Mastic - ABATED IN 2006		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office - ABATED IN 2006 (1936)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **9"x9" Gray w/ Black & Tan Streaks VFT Mastic - ABATED IN 2006**

MATERIAL LOCATION: **Engineer's Office - ABATED IN 2006 (1936)**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12"x12" Tan with brown streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952		
MATERIAL QUANTITY:	5720	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x12" Tan with brown streaks VFT**

MATERIAL LOCATION: **Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952**

MATERIAL QUANTITY: **5720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	9"x9" Tan with brown streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st & 2nd Floor Corridors - 1952		
MATERIAL QUANTITY:	1020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9"x9" Tan with brown streaks VFT**

MATERIAL LOCATION: **1st & 2nd Floor Corridors - 1952**

MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12"x12" Tan with brown streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952		
MATERIAL QUANTITY:	5720	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12"x12" Tan with brown streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 107-110, 206-209, 2nd Floor Women's Restroom - 1952**

MATERIAL QUANTITY: **5720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	9"x9" Tan with brown streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Corridors - 1952		
MATERIAL QUANTITY:	1020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9"x9" Tan with brown streaks VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - 1952**

MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12"x12" Light Beige w/ Maroon streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952		
MATERIAL QUANTITY:	1376	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12"x12" Light Beige w/ Maroon streaks VFT**

MATERIAL LOCATION: **Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952**

MATERIAL QUANTITY: **1376** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12"x12" Light Beige w/ Maroon streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952		
MATERIAL QUANTITY:	1376	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12"x12" Light Beige w/ Maroon streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 107-110, 206-209, , 2nd Floor Women's Restroom - 1952**

MATERIAL QUANTITY: **1376** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	9"x9" Light Beige w/ Maroon streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st and 2nd Floor Hallways - 1952		
MATERIAL QUANTITY:	1020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Maroon streaks VFT**

MATERIAL LOCATION: **1st and 2nd Floor Hallways - 1952**

MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	9"x9" Light Beige w/ Maroon streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Hallways - 1952		
MATERIAL QUANTITY:	1020	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Maroon streaks VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Hallways - 1952**

MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	9"x9" Light Beige w/ Maroon streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st and 2nd Floor North Corridors - 1936		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Maroon streaks VFT**

MATERIAL LOCATION: **1st and 2nd Floor North Corridors - 1936**

MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17A		
MATERIAL DESCRIPTION:	9"x9" Light Beige w/ Maroon streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor North Corridors - 1936		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **17A**

MATERIAL DESCRIPTION: **9"x9" Light Beige w/ Maroon streaks VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor North Corridors - 1936**

MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	9"x9" Tan w/ brown streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st and 2nd Floor North Corridors - 1936		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **9"x9" Tan w/ brown streaks VFT**

MATERIAL LOCATION: **1st and 2nd Floor North Corridors - 1936**

MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18A		
MATERIAL DESCRIPTION:	9"x9" Tan w/ brown streak VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor North Corridors - 1936		
MATERIAL QUANTITY:	540	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **9"x9" Tan w/ brown streak VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor North Corridors - 1936**

MATERIAL QUANTITY: **540** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	9"x9" Dark Gray w/ Tan Streaks VFT (Under HA# 49 & 50)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st floor Engineer's Office (old office) (Under HA# 49 & 50) - 1936		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9"x9" Dark Gray w/ Tan Streaks VFT (Under HA# 49 & 50)**

MATERIAL LOCATION: **1st floor Engineer's Office (old office) (Under HA# 49 & 50) - 1936**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	9"x9" Dark Gray w/ Tan Streaks VFT Mastic (Under HA# 49 & 50)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st floor Engineer's Office (old office) (Under HA# 49 & 50) - 1936		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9"x9" Dark Gray w/ Tan Streaks VFT Mastic (Under HA# 49 & 50)**

MATERIAL LOCATION: **1st floor Engineer's Office (old office) (Under HA# 49 & 50) - 1936**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	9"x9" Gray w/ Black Streaks VFT (Under HA# 49 & 50)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9"x9" Gray w/ Black Streaks VFT (Under HA# 49 & 50)**

MATERIAL LOCATION: **1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	9"x9" Gray w/ Black Streaks VFT Mastic (Under HA# 49 & 50)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9"x9" Gray w/ Black Streaks VFT Mastic (Under HA# 49 & 50)**

MATERIAL LOCATION: **1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	9"x9" Black VFT (Under HA# 49 & 50)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **9"x9" Black VFT (Under HA# 49 & 50)**

MATERIAL LOCATION: **1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	9"x9" Black VFT Mastic (Under HA# 49 & 50)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9"x9" Black VFT Mastic (Under HA# 49 & 50)**

MATERIAL LOCATION: **1st Floor Teacher's Lounge (Under HA# 49 & 50) - 1936**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12"x12" White w/ Tan Spots VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 114 - 1936		
MATERIAL QUANTITY:	96	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT**

MATERIAL LOCATION: **Room 114 - 1936**

MATERIAL QUANTITY: **96** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25A		
MATERIAL DESCRIPTION:	12"x12" White w/ Tan Spots VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114 - 1936		
MATERIAL QUANTITY:	96	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **25A**

MATERIAL DESCRIPTION: **12"x12" White w/ Tan Spots VFT Mastic**

MATERIAL LOCATION: **Room 114 - 1936**

MATERIAL QUANTITY: **96** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26

MATERIAL DESCRIPTION: Hard Coat Plaster

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Rooms 114, 115, 212, 213 and 214 - 1952

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Rooms 114, 115, 212, 213 and 214 - 1952**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27
MATERIAL DESCRIPTION: 2'x4' Ceiling Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Corridor - 1952

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**

MATERIAL LOCATION: **1st & 2nd Floor Corridor - 1952**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 29
MATERIAL DESCRIPTION: Red Linoleum (Painted Black)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library (under the carpet), Teacher's Lounge Washroom, 211B and hall by 211B- 1936

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Red Linoleum (Painted Black)**

MATERIAL LOCATION: **Library (under the carpet), Teacher's Lounge Washroom, 211B and hall by 211B- 1936**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30	
MATERIAL DESCRIPTION:	Yellow Linoleum (Painted Black)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 2nd Floor North Corridor (211C) - 1936

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Yellow Linoleum (Painted Black)**

MATERIAL LOCATION: **2nd Floor North Corridor (211C) - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31
MATERIAL DESCRIPTION: Green Linoleum (Painted Black)
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Teacher's Washroom (211C) - 1936

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Green Linoleum (Painted Black)**

MATERIAL LOCATION: **Teacher's Washroom (211C) - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32

MATERIAL DESCRIPTION: Hard Coat Plaster

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: 1st Floor Corridor - 1936

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **1st Floor Corridor - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33
MATERIAL DESCRIPTION: 2'x4' Ceiling Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:


DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Corridor - 1936

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**

MATERIAL LOCATION: **1st & 2nd Floor Corridor - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34

MATERIAL DESCRIPTION: MJP E/F/V on Fiberglass Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: Throughout Basement - 1936

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Basement - 1936**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35
MATERIAL DESCRIPTION:	12"x12" White w/speckles VFT - REMOVED
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" White w/speckles VFT - REMOVED**

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36
MATERIAL DESCRIPTION:	12"x12" White w/speckles VFT - REMOVED
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12" White w/speckles VFT - REMOVED**

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37
MATERIAL DESCRIPTION:	2'x2' Ceiling Tile - REMOVED
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 2000 Mobile (No Longer on site)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **2'x2' Ceiling Tile - REMOVED**

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 207 (Library)		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 207 (Library)**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12"x12" White w/blue specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st Floor Teachers Lounge, Storage Room and Asst. Prin. Office - 1936 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" White w/blue specks VFT**

MATERIAL LOCATION: **1st Floor Teachers Lounge, Storage Room and Asst. Prin. Office - 1936 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12"x12" White w/blue specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teachers Lounge, Storage Room and Asst. Prin. Office - 1936 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" White w/blue specks VFT Mastic**

MATERIAL LOCATION: **1st Floor Teachers Lounge, Storage Room and Asst. Prin. Office - 1936 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Stairwells - 1936		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairwells - 1936**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Drywall, Tape, and Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor Next to Room 207		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Drywall, Tape, and Compound**

MATERIAL LOCATION: **2nd Floor Corridor Next to Room 207**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Fire Doors - REMOVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical Room in 2000 Mobile (No Longer on site)		
MATERIAL QUANTITY:	1	MATERIAL UNITS:	EA
DAMAGE QUANTITY:		DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Fire Doors - REMOVED**

MATERIAL LOCATION: **Mechanical Room in 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Stairwells - 1952		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Stairwells - 1952**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45
MATERIAL DESCRIPTION:	Duplicate HA - Same as HA# 39
HISTORICAL AHERA DAMAGE CATEGORY	
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Duplicate HA - Same as HA# 39**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45A
MATERIAL DESCRIPTION:	Duplicate HA - Same HA as HA# 40
HISTORICAL AHERA DAMAGE CATEGORY	
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **45A**

MATERIAL DESCRIPTION: **Duplicate HA - Same HA as HA# 40**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor Next to Room 207 - 1936		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **2nd Floor Corridor Next to Room 207 - 1936**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47
MATERIAL DESCRIPTION:	Vinyl Baseboard Mastic - REMOVED
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 2000 Mobile (No Longer on site)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic - REMOVED**

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48
MATERIAL DESCRIPTION:	Textured Ceiling Paint - REMOVED
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 2000 Mobile (No Longer on site)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Textured Ceiling Paint - REMOVED**

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49
MATERIAL DESCRIPTION:	Drywall, tape and compound - REMOVED
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 2000 Mobile (No Longer on site)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Drywall, tape and compound - REMOVED**

MATERIAL LOCATION: **Throughout 2000 Mobile (No Longer on site)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	2' x 2' Green Vinyl floor tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st and 2nd floor link to corridor to new addition building - 1936 building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Michael Holvay
Project Manager

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **2' x 2' Green Vinyl floor tile**

MATERIAL LOCATION: **1st and 2nd floor link to corridor to new addition building - 1936 building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50A		
MATERIAL DESCRIPTION:	2' x 2' Green Vinyl floor tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd floor link to corridor to new addition building - 1936 building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **50A**

MATERIAL DESCRIPTION: **2' x 2' Green Vinyl floor tile Mastic**

MATERIAL LOCATION: **1st and 2nd floor link to corridor to new addition building - 1936 building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	2' x 2' Orange vinyl floor tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st and 2nd floor link to corridor to new addition building - 1936 building		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **2' x 2' Orange vinyl floor tile**

MATERIAL LOCATION: **1st and 2nd floor link to corridor to new addition building - 1936 building**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51A		
MATERIAL DESCRIPTION:	2' x 2' Orange vinyl floor tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd floor link to corridor to new addition building - 1936 building		
MATERIAL QUANTITY:	180	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **51A**

MATERIAL DESCRIPTION: **2' x 2' Orange vinyl floor tile Mastic**

MATERIAL LOCATION: **1st and 2nd floor link to corridor to new addition building - 1936 building**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	2' x 2' White w/ brown streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st and 2nd floor link to corridor to new addition building - 1936 building		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **2' x 2' White w/ brown streaks VFT**

MATERIAL LOCATION: **1st and 2nd floor link to corridor to new addition building - 1936 building**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52A		
MATERIAL DESCRIPTION:	2' x 2' White w/ brown streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd floor link to corridor to new addition building - 1936 building		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **52A**

MATERIAL DESCRIPTION: **2' x 2' White w/ brown streaks VFT Mastic**

MATERIAL LOCATION: **1st and 2nd floor link to corridor to new addition building - 1936 building**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12" x 12" Sand VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st floor corridor by main entrance - 1936 building		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Sand VFT**

MATERIAL LOCATION: **1st floor corridor by main entrance - 1936 building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53A		
MATERIAL DESCRIPTION:	12" x 12" Sand VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st floor corridor by main entrance - 1936 building		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **53A**

MATERIAL DESCRIPTION: **12" x 12" Sand VFT Mastic**

MATERIAL LOCATION: **1st floor corridor by main entrance - 1936 building**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Passage - 1936		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement Passage - 1936**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Passage - 1936		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement Passage - 1936**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Delamination		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teacher's Lunchroom and Storeroom, Transformer Room and the NE and SW Pipe Space - 1936		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1st Floor Teacher's Lunchroom and Storeroom, Transformer Room and the NE and SW Pipe Space - 1936**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teacher's Lunchroom and Storeroom, NE Pipe Space and Transformer Room - 1936		
MATERIAL QUANTITY:	160	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **1st Floor Teacher's Lunchroom and Storeroom, NE Pipe Space and Transformer Room - 1936**

MATERIAL QUANTITY: **160** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Preform Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washroom - 1936		
MATERIAL QUANTITY:	226	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Preform Pipe Insulation**

MATERIAL LOCATION: **Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washroom - 1936**

MATERIAL QUANTITY: **226** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	MJP E/F/V on Preform Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washrooms - 1936**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: MATERIAL UNITS: **FITTING**

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **MJP E/F/V on Preform Pipe Insulation**

MATERIAL LOCATION: **Basement Tunnel and Passage, Boiler, Ash & Coal Rooms, 1st Floor Boy's and Girl's Washrooms - 1936**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Aircell Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East & West Basement Pipe Spaces - 1936		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **East & West Basement Pipe Spaces - 1936**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Mag Block Tank Insulation (Abated)		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room (Abated)- 1936

MATERIAL QUANTITY: 0 MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Mag Block Tank Insulation (Abated)**

MATERIAL LOCATION: **Boiler Room (Abated)- 1936**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Boiler Jacket Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room - 1936		
MATERIAL QUANTITY:	690	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Boiler Jacket Insulation**

MATERIAL LOCATION: **Boiler Room - 1936**

MATERIAL QUANTITY: **690** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage/Pump Room, 1st Fl Boy's Toilet, Boiler Room - 1952**

MATERIAL QUANTITY: **74** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:


Michael Holvay
Project Manager

Inspector's Signature:

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **1st and 2nd Floor Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage/Pump Room, 1st Fl Boy's Toilet, Boiler Room - 1952**

MATERIAL QUANTITY: **74** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage - 1952**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: MATERIAL UNITS: **FITTING**

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: **02/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **1st and 2nd Floor Janitor's Closets, 2nd Floor Teacher's Washroom, Basement with Storage, Break Room, Tunnel and Passage - 1952**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Janitor's Closet - 1952		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1st Floor Janitor's Closet - 1952**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Q		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Janitor's Closet - 1952		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **1st Floor Janitor's Closet - 1952**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	Preform Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952		
MATERIAL QUANTITY:	425	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **Preform Pipe Insulation**

MATERIAL LOCATION: **Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952**

MATERIAL QUANTITY: **425** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	S		
MATERIAL DESCRIPTION:	MJP E/F/V on Preform Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT


This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952		
MATERIAL QUANTITY:	55	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **S**

MATERIAL DESCRIPTION: **MJP E/F/V on Preform Pipe Insulation**

MATERIAL LOCATION: **Store Room, West Store Room, Break Room, Fan Room, Tunnel and Passage - 1952**

MATERIAL QUANTITY: **55** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	T		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Crawlspace - 1950 Addition		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **T**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Auditorium Crawlspace - 1950 Addition**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	U		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Crawlspace - 1950 Addition		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	DAMAGE UNITS: FITTING		
COMMENTS:			

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **U**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Auditorium Crawlspace - 1950 Addition**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: V

MATERIAL DESCRIPTION: Hard Coat Plaster

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium Crawlspace - 1950 Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **V**

MATERIAL DESCRIPTION: Hard Coat Plaster

MATERIAL LOCATION: **Auditorium Crawlspace - 1950 Addition**

MATERIAL QUANTITY: _____ **MATERIAL UNITS:** _____

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Tregaron. chal.

Date: 02/19/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUILDING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: W

MATERIAL DESCRIPTION: 2'x4' Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium Crawlspace - 1950 Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Michael Holvay
Project Manager

Inspector's Signature:

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Canty School	REVIEW DATE:	2/19/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

HOMOGENEOUS AREA: **W**

MATERIAL DESCRIPTION: 2'x4' Ceiling Tile

MATERIAL LOCATION: **Auditorium Crawlspace - 1950 Addition**

MATERIAL QUANTITY: _____ **MATERIAL UNITS:** _____

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:

Tregaron. chal.

Date: 02/19/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)


LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Vinyl Baseboard Mastic		
MATERIAL LOCATION:	Throughout Branch Building		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF

COMMENTS:
Branch Building is located at 8300 W. Addison

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22541** BUIDLING ID: **2620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Canty School** REVIEW DATE: **2/19/2025**

ADDRESS: **3740 N Panama Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout Branch Building**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	Drywall System		
MATERIAL LOCATION:	Throughout Branch Building		
MATERIAL QUANTITY:	12500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
Branch Building is located at 8300 W. Addison

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22541** BUIDLING ID: **2620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Canty School** REVIEW DATE: **2/19/2025**

ADDRESS: **3740 N Panama Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **Throughout Branch Building**

MATERIAL QUANTITY: **12500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12" x 12" White w/ Multicolor Specs VFT Mastic		
MATERIAL LOCATION:	Throughout Branch Building		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
Branch Building is located at 8300 W. Addison

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22541** BUIDLING ID: **2620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Canty School** REVIEW DATE: **2/19/2025**

ADDRESS: **3740 N Panama Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12" x 12" White w/ Multicolor Specs VFT Mastic**

MATERIAL LOCATION: **Throughout Branch Building**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	12" x 12" White with Multicolor Specs VFT		
MATERIAL LOCATION:	Throughout Branch Building		
MATERIAL QUANTITY:	4500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
Branch Building is located at 8300 W. Addison

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22541** BUIDLING ID: **2620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Canty School** REVIEW DATE: **2/19/2025**

ADDRESS: **3740 N Panama Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12" x 12" White with Multicolor Specs VFT**

MATERIAL LOCATION: **Throughout Branch Building**

MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	2' x 4' White w/ Holes Ceiling Tile		
MATERIAL LOCATION:	Throughout Branch Building		
MATERIAL QUANTITY:	4700	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
Branch Building is located at 8300 W. Addison

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22541** BUIDLING ID: **2620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Canty School** REVIEW DATE: **2/19/2025**

ADDRESS: **3740 N Panama Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **2' x 4' White w/ Holes Ceiling Tile**

MATERIAL LOCATION: **Throughout Branch Building**

MATERIAL QUANTITY: **4700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22541	BUIDLING ID:	2620
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Michael Holvay		
SCHOOL NAME:	Canty School	INSPECTION DATE:	2/4/2025		
ADDRESS:	3740 N Panama Avenue	IDPH LICENSE NO:	100-07210		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	Carpet Mastic		
MATERIAL LOCATION:	Copy Room - Branch Building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:
Branch Building is located at 8300 W. Addison

Inspector's Signature:


Michael Holvay
Project Manager

Date: 02/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22541** BUIDLING ID: **2620**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Canty School** REVIEW DATE: **2/19/2025**

ADDRESS: **3740 N Panama Avenue** IDPH LICENSE NO: **100-07210**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Copy Room - Branch Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **02/19/2025**

Chicago Public Schools

Specialty Consulting, Inc.


2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Holvay

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092152

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Holvay

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/10/2021

Exam Date: 9/10/2021

Expiration Date: 9/10/2022

Certificate Number: BIR2109101950


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, IL

MICHAEL HOLVAY
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07210

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 07210	ISSUED 4/30/2025	EXPIRES 05/15/2026	INSPECTOR	9/13/2025
MICHAEL HOLVAY 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	1/11/2026

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois

MICHAEL HOLVAY
2942 W VAN BUREN ST
CHICAGO, IL 60612



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 07210

ISSUED
2/28/2022 EXPIRES
05/15/2023

MICHAEL HOLVAY
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health




2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **07210**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	9/10/2022
PROJECT MANAGER	1/13/2023
AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 07210

ISSUED
4/8/2024

EXPIRES
05/15/2025

MICHAEL HOLVAY
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



MICHAEL HOLVAY
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07210

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 07210	ISSUED 4/8/2024	INSPECTOR	9/15/2024
MICHAEL HOLVAY 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		PROJECT MANAGER AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	1/13/2025

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Michael Holvay

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2409132641

Course Date: 9/13/2024

Exam Date: 9/13/2024

Expiration Date: 9/13/2025



Issue Date: 9/13/2024

Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

A handwritten signature in blue ink, appearing to read 'Tyler Nicholson'.



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

6/9/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 07342	ISSUED 6/9/2025	EXPIRES 05/15/2026	INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/7/2026 1/27/2026 3/7/2026 4/7/2026
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022


Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761

IDPH

ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 07342

ISSUED
4/1/2022

EXPIRES
05/15/2023

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612


4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/9/2023
PROJECT DESIGNER	3/24/2023
MANAGEMENT PLANNER	3/9/2023
PROJECT MANAGER	3/2/2023
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 07342

ISSUED
4/8/2024

EXPIRES
05/15/2025

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612


4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/8/2025
PROJECT DESIGNER	3/7/2025
MANAGEMENT PLANNER	3/8/2025
PROJECT MANAGER	3/25/2024
AIR SAMPLING PROFESSIONAL	
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/8/2024

Exam Date: 3/8/2024

Expiration Date: 3/8/2025

Certificate Number: MPR2403081126

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: MPR2503070948

Course Credit Hours: MPR 4 Hours

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed