

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2286
SCHOOL NAME: Jefferson School
ADDRESS OF SCHOOL: 1522 W. Fillmore
CITY: Chicago, IL, 60607

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/19/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/21/2025 ENROLLMENT 401
IDPH INSPECTOR LICENSE NUMBER: 100-06435
IDPH LICENSED INSPECTOR NAME (Please Print): Jose Escobedo
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 5/9/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Jefferson School

1522 W. Fillmore
Chicago, IL, 60607

Unit: 22711
Building ID: 4190

IDPH ID Number: 14-016-2990-2286

REPORT DATE:
Friday, May 09, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

05/09/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23941 Region: 03 IDPH ID: 14-016-2990-2286

School: Jefferson School Building ID: 4190

Address: 1522 W. Fillmore

Chicago, IL, 60607

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/21/2025

Review Date: 05/09/2025

Inspector: Jose Escobedo

Inspector IDPH License: 100-06435

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 09, 2025

RE: Jefferson School, Unit 22711
1522 W. Fillmore
Chicago, IL, 60607

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Jefferson School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Jefferson School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Jefferson School Unit: 23941 Region: 03
Address: 1522 W. Fillmore Chicago, IL, 60607
IDPH ID: 14-016-2990-2286 Building ID: 4190
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 401

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Jose Escobedo

Inspector IDPH license # 100-06435 Signature:
Reinspection Date: 4/21/2025 Date: 4/21/2025

6. Management Planner

Management Planner Name: Jackson Montgomery


Management Planner IDPH license # 100-20634


Signature:
Date: 05/09/2025

7. Review Date: 05/09/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature: Date: 5/9/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Jefferson School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4190:

1	9" x 9" Dark Green Floor Tile
10	Fireproofing
101	Orange Linoleum Floor
102	Orange Linoleum Floor
103	8" x 16" Glazed CMU
106	8" x 16" CMU Grout
12	9" x 9" Dark Green Floor Tile Mastic
14	Red Linoleum Mastic
15	9" x 9" Brown Floor Tile Mastic

17	Brown Linoleum
22	12" x 12" Beige Floor Tile w/ Gray Streaks
23	12" x 12" Beige Floor Tile Mastic
26	12" x 12" Beige Floor Tile w/ White & Gray Streaks
27	Carpet Mastic
28	Blue Floor Tile Mastic
29	Interior Window Grout
35	Baseboards
44	Exterior Brick Used To Block Windows - Non-AHERA
48	Terrazzo Flooring
49	12" x 12" Blue Floor Tile Mastic
53	12" x 12" Beige Floor Tile w/ Gray & White Streaks
54	Purple Carpet Mastic
55	Linoleum Flooring
5A	9" x 9" Tan Floor Tile (Under Carpet)
64	12" x 12" Brown Speckled Floor Tile
65	12" x 12" Tan Speckled Floor Tile - Mastic
68	12" x 12" Patched Floor Tile
71	Dark Blotted Beige Vinyl Floor Tile Mastic
72	12" x 12" Tan Texture Vinyl Floor Tile
73	12" x 12" Tan Texture Vinyl Floor Tile Mastic
78	12" x 12" Lite Beige Vinyl Floor Tile
79	12" x 12" Lite Beige Vinyl Floor Tile Mastic

- A Air Cell Pipe Insulation
- B Cementitous Joints on Aircell Pipe Insulation
- C Cardboard Pipe Insulation
- D Cementitous Joint Insulation Off Cardboard
- K Aircell Pipe Insulation
- L Cementitous Joint Insulation on Aircell
- M Cardboard Pipe Insulation
- N Cementitous Pipe Joint Insulation Off Cardboard
- O Powder Pipe Insulation
- P Powder Elbows

B. The following new homogenous areas have been identified for Building 4190:

- | | |
|-----|----------------------------|
| 103 | 8" x 16" Glazed CMU |
| 104 | 8" x 16" Glazed CMU Grout |
| 105 | 8" x 16" CMU |
| 106 | 8" x 16" CMU Grout |
| 107 | 2" x 8" Glazed Brick |
| 108 | 2" x 8" Glazed Brick Grout |

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	Hardwood Floors
101	Orange Linoleum Floor
102	Orange Linoleum Floor
103	8" x 16" Glazed CMU
104	8" x 16" Glazed CMU Grout
105	8" x 16" CMU
106	8" x 16" CMU Grout
107	2" x 8" Glazed Brick
108	2" x 8" Glazed Brick Grout
11	Roof Material & Flashing - Non-AHERA
13	12" x 12" Blue Floor Tile
16A	12" x 12" Beige (& Gray) Floor Tile Mastic
16C	12" x 12" Gray (w/ White & Gray) Floor Tile Mastic
21	12" x 12" Brown Floor Tile
22	12" x 12" Beige Floor Tile w/ Gray Streaks
26	12" x 12" Beige Floor Tile w/ White & Gray Streaks
27	Carpet Mastic
28	Blue Floor Tile Mastic
33	Fire Door Insulation
34	Ceramic Tile Grout - Floor
43	Tank Insulation
47	Blue Floor Tile
48	Terrazzo Flooring
49	12" x 12" Blue Floor Tile Mastic
53	12" x 12" Beige Floor Tile w/ Gray & White Streaks
54	Purple Carpet Mastic
60	12" x 12" Gray Speckle Floor Tile
61	12" x 12" Gray Speckle Floor Tile - Mastic
62	2" Brown Vinyl Baseboard
63	2" Brown Vinyl Baseboard - Adhesive
64	12" x 12" Brown Speckled Floor Tile
65	12" x 12" Tan Speckled Floor Tile - Mastic
66	Ceramic Baseboard Grout
67	Ceramic Baseboard Grout - Adhesive
70	Dark Blotted Beige Vinyl Floor Tile
71	Dark Blotted Beige Vinyl Floor Tile Mastic
72	12" x 12" Tan Texture Vinyl Floor Tile
73	12" x 12" Tan Texture Vinyl Floor Tile Mastic
74	Brown Rubber Floor Adhesive
75	2' x 2' Carpet Adhesive
76	2' x 2' Blue Carpet Adhesive
77	Lab Counter Tops

78	12" x 12" Lite Beige Vinyl Floor Tile
79	12" x 12" Lite Beige Vinyl Floor Tile Mastic
80	Pink/Tan Sheet Flooring
81	Pink/Tan Sheet Flooring Mastic
82	6" Gray Vinyl Baseboard
83	6" Gray Vinyl Baseboard Adhesive
84	White Sink Undercoat
9	12" x 12" Brown Floor Tile
A	Air Cell Pipe Insulation
B	Cementitious Joints on Aircell Pipe Insulation
C	Cardboard Pipe Insulation
D	Cementitious Joint Insulation Off Cardboard
E	Powder Pipe Insulation
F	Powder Elbows
G	Boiler Gasket
H	Boiler Packing
J	Kiln
K	Aircell Pipe Insulation
L	Cementitious Joint Insulation on Aircell
M	Cardboard Pipe Insulation
N	Cementitious Pipe Joint Insulation Off Cardboard
O	Powder Pipe Insulation
P	Powder Elbows

The following areas were deemed to be inaccessible:

16A	12" x 12" Beige (& Gray) Floor Tile Mastic
16C	12" x 12" Gray (w/ White & Gray) Floor Tile Mastic
61	12" x 12" Gray Speckle Floor Tile - Mastic
67	Ceramic Baseboard Grout - Adhesive
74	Brown Rubber Floor Adhesive
75	2' x 2' Carpet Adhesive
76	2' x 2' Blue Carpet Adhesive
81	Pink/Tan Sheet Flooring Mastic
83	6" Gray Vinyl Baseboard Adhesive
E	Powder Pipe Insulation
F	Powder Elbows
G	Boiler Gasket
H	Boiler Packing

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jose Escobedo, IDPH License # 100-06435. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634.

Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Jefferson School Building 4190 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	9" x 9" Dark Green Floor Tile			ABATED	ABATED	MISC					Yes			
10	Fireproofing			ABATED	ABATED	MISC					Yes			
100	Hardwood Floors	70,000	SF	Throughout Building, Corridors & Classrooms	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
101	Orange Linoleum Floor			Room 413, Room 413 Closet, Room 414, Room 414 Closet	ASSUMED	MISC					Yes			
102	Orange Linoleum Floor			Room 413, Room 413 Closet, Room 414, Room 414 Closet	ASSUMED	MISC					Yes			
103	8" x 16" Glazed CMU	1,000	SF	3rd Floor, 2nd Floor, 1st Floor Boys Bathroom 1911 Building	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
104	8" x 16" Glazed CMU Grout	500	SF	3rd Floor, 2nd Floor 1st Floor Boys Bathroom 1911 Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
105	8" x 16" CMU	1,400	SF	3rd Floor, 2nd Floor , 1st Floor Boys and Girls Bathroom 1911 Building, Book Room 1884 Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
106	8" x 16" CMU Grout	800	SF	3rd Floor, 2nd Floor, 1st Floor Boys and Girls Bathroom 1911 Building	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
107	2" x 8" Glazed Brick	200	SF	3rd, 2nd, 1st Floor Girls Bathroom 1911	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
108	2" x 8" Glazed Brick Grout	200	SF	3rd Floor, 2nd Floor, 1st Floor Girls Bathroom 1911	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
11	Roof Material & Flashing - Non-AHERA			Roof	ASSUMED	MISC					No			
12	9" x 9" Dark Green Floor Tile Mastic			ABATED	ABATED	MISC					Yes			
13	12" x 12" Blue Floor Tile			Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building	ASSUMED	MISC					No			
14	Red Linoleum Mastic			ABATED	ABATED	MISC					Yes			

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
15	9" x 9" Brown Floor Tile Mastic			ABATED	ABATED	MISC					Yes			
16A	12" x 12" Beige (& Gray) Floor Tile Mastic	5,000	SF	Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16B	12" x 12" Brown Floor Tile Mastic	1,400	SF	Rooms 312, & 113 - 1884 Building	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16C	12" x 12" Gray (w/ White & Gray) Floor Tile Mastic	3,000	SF	Landings by Rooms 310 & 209 & Room 102, room 310	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	Brown Linoleum			1884 Building - Basement-Engineer's Office, Hall & Storage Room	NO_ACBM	MISC					Yes			
19	9" x 9" Tan Floor Tile Mastic (Under Carpet)			ABATED	ABATED	MISC					No			
2	9" x 9" Tan Floor Tile (Under Carpet)			ABATED	ABATED	MISC					No			
20	9" x 9" Brown Floor Tile			ABATED	ABATED	MISC					No			
21	12" x 12" Brown Floor Tile	200	SF	Rooms 113, 312 - 1884 Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
22	12" x 12" Beige Floor Tile w/ Gray Streaks			Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage	ASSUMED	MISC					Yes			
23	12" x 12" Beige Floor Tile Mastic			ABATED	ABATED	MISC					Yes			
24	Pink Linoleum			Room 310	NO_ACBM	MISC					No			
25	2' x 4' Lay-in Ceiling Panels	2,500	SF	girls 2nd & 3rd Floor bathroom , 311, Engineers office, 1st floor girls bathroom 1911 building, lunchroom	CHR	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
26	12" x 12" Beige Floor Tile w/ White & Gray Streaks	4,000	SF	3rd, 2nd, floor Hallway 1911 building, Hall Landings by Room 102 1884 building	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
27	Carpet Mastic	2,000	SF	Room 206	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
28	Blue Floor Tile Mastic			Hall At Exit by Office	ASSUMED	MISC					Yes			
29	Interior Window Grout			Interior Windows	NO_ACBM	SURFACE					Yes			
3	12" x 12" Tan Floor Tile			ABATED	ABATED	MISC					No			
30	Interior Bricks			Throughout 1884 Building	NO_ACBM	MISC					No			

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
31	Interior Brick Mortar			Throughout 1884 Building	NO_ACBM	MISC					No			
32	Cinder Block Mortar			Throughout 1884 Basement	NO_ACBM	MISC					No			
33	Fire Door Insulation	40	SF	Throughout 1911 & 1884 Buildings	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
34	Ceramic Tile Grout - Floor	1,000	SF	Throughout Boys & Girls Bathrooms - 1911 Building, 4th floor boys and girls bathroom 1884 building, principal office bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	Baseboards			Room 113 of the 1884 Building & Room 308 of The 1911 Building	NO_ACBM	MISC					Yes			
36	Baseboard Mastic			Room 113 of the 1884 Building & Room 308 of The 1911 Building	NO_ACBM	MISC					No			
37	Exterior Brick			Exterior of the 1911 Building	NO_ACBM	MISC					No			
38	Exterior Brick Mortar			Exterior of the 1911 Building	NO_ACBM	MISC					No			
39	Exterior Window Grout			Exterior Windows of the 1911 Building	NO_ACBM	MISC					No			
4	Red Linoleum			ABATED	ABATED	MISC					No			
40	Exterior Brick - Non-AHERA			Exterior of the 1884 Building	NO_ACBM	MISC					No			
41	Exterior Mortar - Non-AHERA			Exterior of the 1814 Building	NO_ACBM	MISC					No			
42	Exterior Window Grout - Non-AHERA			Exterior of the 1884 Building	NO_ACBM	MISC					No			
43	Tank Insulation	1,000	SF	Boiler Room	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
44	Exterior Brick Used To Block Windows - Non-AHERA			Exterior of the 1884 Building	NO_ACBM	MISC					Yes			
45	Brick Mortar Used To Block Windows			Exterior of the 1884 Building	NO_ACBM	MISC					No			
46	Spray-on Insulation			Electric Room On the 1st Floor of the	NO_ACBM	SURFACE					No			

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1911 Building, Boiler Room Ceiling by Back Door- 1911 Building										
47	Blue Floor Tile			Hall At Exit by Office	ASSUMED	MISC					No			
48	Terrazzo Flooring			Throughout the 1911 Building Stairs	ASSUMED	MISC					Yes			
49	12" x 12" Blue Floor Tile Mastic			Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building	ASSUMED	MISC					Yes			
53	12" x 12" Beige Floor Tile w/ Gray & White Streaks	1,500	SF	Stair Landings of the 1884 Building & Room 102 of the 1911 Building, 3rd floor and 2nd floor corridor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
54	Purple Carpet Mastic	2,000	SF	Room 206/208	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
55	Linoleum Flooring			ABATED	ABATED	MISC					Yes			
56	Linoleum Flooring Mastic			ABATED	ABATED	MISC					No			
57	Blue Carpet Mastic			Main Office, Principal's Office, Room 202 - 1911 Building	NO_ACBM	MISC					No			
58	4" Brown Vinyl Baseboard			1911 Building Gym/Assembly Hall	NO_ACBM	MISC					No			
59	4" Brown Vinyl Baseboard - Adhesive			1911 Building - Gym/Assembly Hall	NO_ACBM	MISC					No			
5A	9" x 9" Tan Floor Tile (Under Carpet)			ABATED	ABATED	MISC					Yes			
5B	9" x 9" Tan Floor Tile Mastic (Under Carpet)			ABATED	ABATED	MISC					No			
6	Gray Linoleum			Room 210	NO_ACBM	MISC					No			
60	12" x 12" Gray Speckle Floor Tile	840	SF	1911 Building - Old Lunchroom, Room 102, outside 113 and 113 1884 bldg	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
61	12" x 12" Gray Speckle Floor Tile - Mastic	840	SF	1191 Building - Old Lunchroom/Room 102, outside room 113 and 112 1884 bldg	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
62	2" Brown Vinyl Baseboard	100	LF	1911 Building - Old Lunchroom/Room 102	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
63	2" Brown Vinyl Baseboard - Adhesive	100	LF	1911 Building - Old Lunchroom/Room 102	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
64	12" x 12" Brown Speckled Floor Tile	100	SF	1884 Building - Room 103	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
65	12" x 12" Tan Speckled Floor Tile - Mastic	100	SF	1884 Building - Room 103	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
66	Ceramic Baseboard Grout	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
67	Ceramic Baseboard Grout - Adhesive	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
68	12" x 12" Patched Floor Tile			ABATED	ABATED	MISC					Yes			
69	12" x 12" Patched Floor Tile - Mastic			ABATED	ABATED	MISC					No			
7	Plaster			Throughout the 1911 Building	NO_ACBM	SURFACE					No			
70	Dark Blotted Beige Vinyl Floor Tile			Lunchroom, Exit 3 Entrance	ASSUMED	MISC					No			
71	Dark Blotted Beige Vinyl Floor Tile Mastic			Lunchroom, Exit 3 Entrance	ASSUMED	MISC					Yes			
72	12" x 12" Tan Texture Vinyl Floor Tile			West Corridor	ASSUMED	MISC					Yes			
73	12" x 12" Tan Texture Vinyl Floor Tile Mastic			West Corridor	ASSUMED	MISC					Yes			
74	Brown Rubber Floor Adhesive	1,000	SF	Stairwells	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
75	2' x 2' Carpet Adhesive	1,000	SF	Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
76	2' x 2' Blue Carpet Adhesive	1,800	SF	Room 206, 208	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
77	Lab Counter Tops	3		Room 414,313, 314, 214, 114	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
78	12" x 12" Lite Beige Vinyl Floor Tile			Classroom 104 and Corridor	ASSUMED	MISC					Yes			
79	12" x 12" Lite Beige Vinyl Floor Tile Mastic			Classroom 104 and Corridor	ASSUMED	MISC					Yes			
8	Plaster			Throughout the 1884 Building	NO_ACBM	SURFACE					No			
80	Pink/Tan Sheet Flooring	2,400	SF	Rooms 214, 313,	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Jefferson School **Unit** 23941 **Building ID** 4190
Address 1522 W. Fillmore **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				314, 413, 414								potential for damage		
81	Pink/Tan Sheet Flooring Mastic	2,400	SF	Rooms 214, 313, 314, 413, 414	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
82	6" Gray Vinyl Baseboard	240	LF	Rooms 214, 312, 313, 314, 413, 414	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
83	6" Gray Vinyl Baseboard Adhesive	240	LF	Rooms 214, 312, 313, 314, 413, 414	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
84	White Sink Undercoat	1		Room 113	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
9	12" x 12" Brown Floor Tile			Teachers' Bathroom by Room 309	ASSUMED	MISC					No			
A	Air Cell Pipe Insulation			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
B	Cementitious Joints on Aircell Pipe Insulation			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
C	Cardboard Pipe Insulation			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
D	Cementitious Joint Insulation Off Cardboard			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
E	Powder Pipe Insulation	2,100	SF	Pipe Chases and Within Walls, 112 Book room 1884 building, 1st floor hallway 1884 building	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Powder Elbows	100	SF	Pipe Chases and Within Walls	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Boiler Gasket	10	LF	Boiler Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
H	Boiler Packing	100	SF	Boiler Room	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Tank Insulation			ABATED	ABATED	MISC								
J	Kiln				ASSUMED	MISC					No			
K	Aircell Pipe Insulation			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
L	Cementitious Joint Insulation on Aircell			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
M	Cardboard Pipe Insulation			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
N	Cementitious Pipe Joint Insulation Off Cardboard			Pipe Chases and Within Walls	ASSUMED	TSI					Yes			
O	Powder Pipe Insulation			Pipe Chases and	ASSUMED	TSI					Yes			

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190
Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
P	Powder Elbows			Within Walls Pipe Chases and Within Walls	ASSUMED	TSI					Yes			

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190
Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>4/21/2025</u>
Inspector Name <u>Jose Escobedo</u>
<u>100-06435</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
100	
101	Material not observed - 2025
102	Material not observed - 2025
103	
104	
105	
106	
107	
108	
11	Material not observed - 2025
12	
13	Material not observed - 2025
14	
15	
16A	
16B	
16C	
17	
19	
2	
20	
21	

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190
Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
22	Material not observed - 2025
23	
24	
25	
26	
27	
28	Material not observed - 2025
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	Material not observed - 2025
48	Material not observed - 2025

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190
Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
49	Material not observed - 2025
53	
54	
55	
56	
57	
58	
59	
5A	
5B	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	Material not observed - 2025
71	Material not observed - 2025
72	Material not observed - 2025
73	Material not observed - 2025
74	
75	
76	

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190
Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
77	
78	Material not observed - 2025
79	Material not observed - 2025
8	
80	
81	
82	
83	
84	
9	Material not observed - 2025
A	Material not observed - 2025
B	Material not observed - 2025
C	Material not observed - 2025
D	Material not observed - 2025
E	
F	
G	
H	
I	
J	Material not observed - 2025
K	Material not observed - 2025
L	Material not observed - 2025
M	Material not observed - 2025
N	Material not observed - 2025
O	Material not observed - 2025
P	Material not observed - 2025

Chicago Public Schools

School Jefferson School Unit 23941 Building ID 4190
Address 1522 W. Fillmore Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	9" x 9" Dark Green Floor Tile			ABATED	Abated	MISC					
10	Fireproofing			ABATED	Abated	MISC					
100	Hardwood Floors	70,000	SF	Throughout Building, Corridors & Classrooms	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
101	Orange Linoleum Floor			Room 413, Room 413 Closet, Room 414, Room 414 Closet	Assumed	MISC					
102	Orange Linoleum Floor			Room 413, Room 413 Closet, Room 414, Room 414 Closet	Assumed	MISC					
103	8" x 16" Glazed CMU	1,000	SF	3rd Floor, 2nd Floor, 1st Floor Boys Bathroom 1911 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
104	8" x 16" Glazed CMU Grout	500	SF	3rd Floor, 2nd Floor 1st Floor Boys Bathroom 1911 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	8" x 16" CMU	1,400	SF	3rd Floor, 2nd Floor , 1st Floor Boys and Girls Bathroom 1911 Building, Book Room 1884 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
106	8" x 16" CMU Grout	800	SF	3rd Floor, 2nd Floor, 1st Floor Boys and Girls Bathroom 1911 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
107	2" x 8" Glazed Brick	200	SF	3rd, 2nd, 1st Floor Girls Bathroom 1911	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
108	2" x 8" Glazed Brick Grout	200	SF	3rd Floor, 2nd Floor, 1st Floor Girls Bathroom 1911	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Roof Material & Flashing - Non-AHERA			Roof	Assumed	MISC					
12	9" x 9" Dark Green Floor Tile Mastic			ABATED	Abated	MISC					
13	12" x 12" Blue Floor Tile			Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building	Assumed	MISC					
14	Red Linoleum Mastic			ABATED	Abated	MISC					
15	9" x 9" Brown Floor Tile Mastic			ABATED	Abated	MISC					
16A	12" x 12" Beige (& Gray) Floor Tile Mastic	5,000	SF	Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16B	12" x 12" Brown Floor Tile Mastic	1,400	SF	Rooms 312 & 113 - 1884 Building	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16C	12" x 12" Gray (w/ White & Gray) Floor Tile Mastic	3,000	SF	Landings by Rooms 310 & 209 & Room 102, room 310	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Brown Linoleum			1884 Building - Basement- Engineer's Office, Hall & Storage Room	No ACBM	MISC					
19	9" x 9" Tan Floor Tile Mastic (Under Carpet)			ABATED	Abated	MISC					
2	9" x 9" Tan Floor Tile (Under Carpet)			ABATED	Abated	MISC					
20	9" x 9" Brown Floor Tile			ABATED	Abated	MISC					

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
21	12" x 12" Brown Floor Tile	200	SF	Rooms 113, 312 - 1884 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Beige Floor Tile w/ Gray Streaks			Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage	Assumed	MISC					
23	12" x 12" Beige Floor Tile Mastic			ABATED	Abated	MISC					
24	Pink Linoleum			Room 310	No ACBM	MISC					
25	2' x 4' Lay-in Ceiling Panels	2,500	SF	girls 2nd & 3rd Floor bathroom , 311, Engineers office, 1st floor girls bathroom 1911 building, lunchroom	Chrysotile	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
26	12" x 12" Beige Floor Tile w/ White & Gray Streaks	4,000	SF	3rd, 2nd, floor Hallway 1911 building, Hall Landings by Room 102 1884 building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Carpet Mastic	2,000	SF	Room 206	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Blue Floor Tile Mastic			Hall At Exit by Office	Assumed	MISC					
29	Interior Window Grout			Interior Windows	No ACBM	SURFACE					
3	12" x 12" Tan Floor Tile			ABATED	Abated	MISC					
30	Interior Bricks			Throughout 1884 Building	No ACBM	MISC					
31	Interior Brick Mortar			Throughout 1884 Building	No ACBM	MISC					
32	Cinder Block Mortar			Throughout 1884 Basement	No ACBM	MISC					
33	Fire Door Insulation	40	SF	Throughout 1911 & 1884 Buildings	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
34	Ceramic Tile Grout - Floor	1,000	SF	Throughout Boys & Girls Bathrooms - 1911 Building, 4th floor boys and girls bathroom 1884 building, principal office bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Baseboards			Room 113 of the 1884 Building & Room 308 of The1911 Building	No ACBM	MISC					
36	Baseboard Mastic			Room 113 of the 1884 Building & Room 308 of The1911 Building	No ACBM	MISC					
37	Exterior Brick			Exterior of the 1911 Building	No ACBM	MISC					
38	Exterior Brick Mortar			Exterior of the 1911 Building	No ACBM	MISC					
39	Exterior Window Grout			Exterior Windows of the 1911 Building	No ACBM	MISC					
4	Red Linoleum			ABATED	Abated	MISC					
40	Exterior Brick - Non-AHERA			Exterior of the 1884 Building	No ACBM	MISC					
41	Exterior Mortar - Non-AHERA			Exterior of the 1814 Building	No ACBM	MISC					
42	Exterior Window Grout - Non-AHERA			Exterior of the 1884 Building	No ACBM	MISC					
43	Tank Insulation	1,000	SF	Boiler Room	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										suspect ACBM	
44	Exterior Brick Used To Block Windows - Non-AHERA			Exterior of the 1884 Building	No ACBM	MISC					
45	Brick Mortar Used To Block Windows			Exterior of the 1884 Building	No ACBM	MISC					
46	Spray-on Insulation			Electric Room On the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Building	No ACBM	SURFACE					
47	Blue Floor Tile			Hall At Exit by Office	Assumed	MISC					
48	Terrazzo Flooring			Throughout the 1911 Building Stairs	Assumed	MISC					
49	12" x 12" Blue Floor Tile Mastic			Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building	Assumed	MISC					
53	12" x 12" Beige Floor Tile w/ Gray & White Streaks	1,500	SF	Stair Landings of the 1884 Building & Room 102 of the 1911 Building, 3rd floor and 2nd floor corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Purple Carpet Mastic	2,000	SF	Room 206/208	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Linoleum Flooring			ABATED	Abated	MISC					
56	Linoleum Flooring Mastic			ABATED	Abated	MISC					
57	Blue Carpet Mastic			Main Office, Principal's Office, Room 202 - 1911 Building	No ACBM	MISC					
58	4" Brown Vinyl Baseboard			1911 Building Gym/Assembly Hall	No ACBM	MISC					
59	4" Brown Vinyl Baseboard - Adhesive			1911 Building - Gym/Assembly Hall	No ACBM	MISC					
5A	9" x 9" Tan Floor Tile (Under Carpet)			ABATED	Abated	MISC					
5B	9" x 9" Tan Floor Tile Mastic (Under Carpet)			ABATED	Abated	MISC					
6	Gray Linoleum			Room 210	No ACBM	MISC					
60	12" x 12" Gray Speckle Floor Tile	840	SF	1911 Building - Old Lunchroom, Room 102, outside 113 and 113 1884 bldg	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12" x 12" Gray Speckle Floor Tile - Mastic	840	SF	1191 Building - Old Lunchroom/Room 102, outside room 113 and 112 1884 bldg	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
62	2" Brown Vinyl Baseboard	100	LF	1911 Building - Old Lunchroom/Room 102	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
63	2" Brown Vinyl Baseboard - Adhesive	100	LF	1911 Building - Old Lunchroom/Room 102	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Brown Speckled Floor Tile	100	SF	1884 Building - Room 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12" x 12" Tan Speckled Floor Tile - Mastic	100	SF	1884 Building - Room 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
66	Ceramic Baseboard Grout	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
67	Ceramic Baseboard Grout - Adhesive	120	LF	1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Patched Floor Tile			ABATED	Abated	MISC					
69	12" x 12" Patched Floor Tile - Mastic			ABATED	Abated	MISC					
7	Plaster			Throughout the 1911 Building	No ACBM	SURFACE					
70	Dark Blotted Beige Vinyl Floor Tile			Lunchroom, Exit 3 Entrance	Assumed	MISC					
71	Dark Blotted Beige Vinyl Floor Tile Mastic			Lunchroom, Exit 3 Entrance	Assumed	MISC					
72	12" x 12" Tan Texture Vinyl Floor Tile			West Corridor	Assumed	MISC					
73	12" x 12" Tan Texture Vinyl Floor Tile Mastic			West Corridor	Assumed	MISC					
74	Brown Rubber Floor Adhesive	1,000	SF	Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	2' x 2' Carpet Adhesive	1,000	SF	Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
76	2' x 2' Blue Carpet Adhesive	1,800	SF	Room 206, 208	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Lab Counter Tops	3		Room 414,313, 314, 214, 114	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Lite Beige Vinyl Floor Tile			Classroom 104 and Corridor	Assumed	MISC					
79	12" x 12" Lite Beige Vinyl Floor Tile Mastic			Classroom 104 and Corridor	Assumed	MISC					
8	Plaster			Throughout the 1884 Building	No ACBM	SURFACE					
80	Pink/Tan Sheet Flooring	2,400	SF	Rooms 214, 313, 314, 413, 414	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Pink/Tan Sheet Flooring Mastic	2,400	SF	Rooms 214, 313, 314, 413, 414	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
82	6" Gray Vinyl Baseboard	240	LF	Rooms 214, 312, 313, 314, 413, 414	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
83	6" Gray Vinyl Baseboard Adhesive	240	LF	Rooms 214, 312, 313, 314, 413, 414	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
84	White Sink Undercoat	1		Room 113	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
9	12" x 12" Brown Floor Tile			Teachers' Bathroom by Room 309	Assumed	MISC					
A	Air Cell Pipe Insulation			Pipe Chases and Within Walls	Assumed	TSI					
B	Cementitious Joints on Aircell Pipe Insulation			Pipe Chases and Within Walls	Assumed	TSI					
C	Cardboard Pipe Insulation			Pipe Chases and Within Walls	Assumed	TSI					
D	Cementitious Joint Insulation Off Cardboard			Pipe Chases and Within Walls	Assumed	TSI					
E	Powder Pipe Insulation	2,100	SF	Pipe Chases and Within Walls, 112 Book room 1884 building, 1st floor hallway 1884 building	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Powder Elbows	100	SF	Pipe Chases and Within Walls	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Boiler Gasket	10	LF	Boiler Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Boiler Packing	100	SF	Boiler Room	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										suspect ACBM	
I	Tank Insulation			ABATED	Abated	MISC					
J	Kiln				Assumed	MISC					
K	Aircell Pipe Insulation			Pipe Chases and Within Walls	Assumed	TSI					
L	Cementitous Joint Insulation on Aircell			Pipe Chases and Within Walls	Assumed	TSI					
M	Cardboard Pipe Insulation			Pipe Chases and Within Walls	Assumed	TSI					
N	Cementitous Pipe Joint Insulation Off Cardboard			Pipe Chases and Within Walls	Assumed	TSI					
O	Powder Pipe Insulation			Pipe Chases and Within Walls	Assumed	TSI					
P	Powder Elbows			Pipe Chases and Within Walls	Assumed	TSI					

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	5/9/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
100	
101	
102	
103	
104	
105	
106	
107	
108	
11	
12	
13	
14	
15	
16A	
16B	
16C	
17	
19	
2	
20	
21	
22	
23	

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
49	
53	
54	
55	
56	
57	
58	
59	
5A	
5B	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
75	
76	
77	
78	
79	
8	
80	
81	
82	
83	
84	
9	
A	
B	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	

Chicago Public Schools

School Jefferson School

Unit 23941

Building ID 4190

Address 1522 W. Fillmore

Chicago, IL, 60607

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
P	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Fireproofing**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Fireproofing**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	Hardwood Floors		
HISTORICAL AHERA DAMAGE CATEGORY	6 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building, Corridors & Classrooms		
MATERIAL QUANTITY:	70000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Hardwood Floors**

MATERIAL LOCATION: **Throughout Building, Corridors & Classrooms**

MATERIAL QUANTITY: **70000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101	
MATERIAL DESCRIPTION:	Orange Linoleum Floor	
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 413, Room 413 Closet, Room 414, Room 414 Closet

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Orange Linoleum Floor**

MATERIAL LOCATION: **Room 413, Room 413 Closet, Room 414, Room 414 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	Orange Linoleum Floor		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 413, Room 413 Closet, Room 414, Room 414 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **Orange Linoleum Floor**

MATERIAL LOCATION: **Room 413, Room 413 Closet, Room 414, Room 414 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Roof Material & Flashing - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Roof Material & Flashing - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Main Office, Principal's Office - 1911 Building and Room 411 - 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Red Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Red Linoleum Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16A		
MATERIAL DESCRIPTION:	12" x 12" Beige (& Gray) Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **16A**

MATERIAL DESCRIPTION: **12" x 12" Beige (& Gray) Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16B		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 312 & 113 - 1884 Building		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **16B**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 312 & 113 - 1884 Building**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16C		
MATERIAL DESCRIPTION:	12" x 12" Gray (w/ White & Gray) Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Landings by Rooms 310 & 209 & Room 102, room 310		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **16C**

MATERIAL DESCRIPTION: **12" x 12" Gray (w/ White & Gray) Floor Tile Mastic**

MATERIAL LOCATION: **Landings by Rooms 310 & 209 & Room 102, room 310**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Brown Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1884 Building - Basement- Engineer's Office, Hall & Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **1884 Building - Basement- Engineer's Office, Hall & Storage Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic (Under Carpet)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic (Under Carpet)**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile (Under Carpet)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile (Under Carpet)**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 113, 312 - 1884 Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Rooms 113, 312 - 1884 Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Gray Streaks**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Gray Streaks**

MATERIAL LOCATION: **Rooms 202, 302, 308, 312, Corridors, & Auditorium Stage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23

MATERIAL DESCRIPTION: 12" x 12" Beige Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Pink Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Pink Linoleum**

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	2' x 4' Lay-in Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **girls 2nd & 3rd Floor bathroom , 311, Engineers office, 1st floor girls bathroom 1911 building, lunchroom**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

MATERIAL LOCATION: **girls 2nd & 3rd Floor bathroom , 311, Engineers office, 1st floor girls bathroom 1911 building, lunchroom**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/ White & Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd, 2nd, floor Hallway 1911 building, Hall Landings by Room 102 1884 building		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White & Gray Streaks**

MATERIAL LOCATION: **3rd, 2nd, floor Hallway 1911 building, Hall Landings by Room 102 1884 building**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 206**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: Blue Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hall At Exit by Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Blue Floor Tile Mastic**

MATERIAL LOCATION: **Hall At Exit by Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Interior Window Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Interior Windows**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Interior Window Grout**

MATERIAL LOCATION: **Interior Windows**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**
MATERIAL DESCRIPTION: **Interior Bricks**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Interior Bricks**

MATERIAL LOCATION: **Throughout 1884 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31	
MATERIAL DESCRIPTION:	Interior Brick Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32	
MATERIAL DESCRIPTION:	Cinder Block Mortar	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout 1884 Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout 1884 Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Fire Door Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1911 & 1884 Buildings		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Fire Door Insulation**

MATERIAL LOCATION: **Throughout 1911 & 1884 Buildings**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Ceramic Tile Grout - Floor		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Boys & Girls Bathrooms - 1911 Building, 4th floor boys and girls bathroom 1884 building, principal office bathroom**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23941** BUILDING ID: **4190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Jefferson School** REVIEW DATE: **5/9/2025**

ADDRESS: **1522 W. Fillmore** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Ceramic Tile Grout - Floor**

MATERIAL LOCATION: **Throughout Boys & Girls Bathrooms - 1911 Building, 4th floor boys and girls bathroom 1884 building, principal office bathroom**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35	
MATERIAL DESCRIPTION:	Baseboards	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 113 of the 1884 Building & Room 308 of The1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Baseboards**

MATERIAL LOCATION: **Room 113 of the 1884 Building & Room 308 of The 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 113 of the 1884 Building & Room 308 of The1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Room 113 of the 1884 Building & Room 308 of The 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Exterior Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Exterior Brick**

MATERIAL LOCATION: **Exterior of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**
MATERIAL DESCRIPTION: **Exterior Brick Mortar**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Exterior Brick Mortar**

MATERIAL LOCATION: **Exterior of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39	
MATERIAL DESCRIPTION:	Exterior Window Grout	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Windows of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Exterior Window Grout**

MATERIAL LOCATION: **Exterior Windows of the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	Red Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Red Linoleum**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40	
MATERIAL DESCRIPTION:	Exterior Brick - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41	
MATERIAL DESCRIPTION:	Exterior Mortar - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of the 1814 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Exterior Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of the 1814 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42	
MATERIAL DESCRIPTION:	Exterior Window Grout - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Exterior Window Grout - Non-AHERA**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44	
MATERIAL DESCRIPTION:	Exterior Brick Used To Block Windows - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Exterior Brick Used To Block Windows - Non-AHERA**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45	
MATERIAL DESCRIPTION:	Brick Mortar Used To Block Windows	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Brick Mortar Used To Block Windows**

MATERIAL LOCATION: **Exterior of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Spray-on Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Electric Room On the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23941** BULDING ID: **4190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Jefferson School** REVIEW DATE: **5/9/2025**

ADDRESS: **1522 W. Fillmore** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Spray-on Insulation**

MATERIAL LOCATION: **Electric Room On the 1st Floor of the 1911 Building, Boiler Room Ceiling by Back Door- 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**
MATERIAL DESCRIPTION: **Blue Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Hall At Exit by Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Blue Floor Tile**

MATERIAL LOCATION: **Hall At Exit by Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48	
MATERIAL DESCRIPTION:	Terrazzo Flooring	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout the 1911 Building Stairs**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **Throughout the 1911 Building Stairs**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49	
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Main Office & Principal's Office of the 1911 Building & Room 411 of the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/ Gray & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Stair Landings of the 1884 Building & Room 102 of the 1911 Building, 3rd floor and 2nd floor corridor**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ Gray & White Streaks**

MATERIAL LOCATION: **Stair Landings of the 1884 Building & Room 102 of the 1911 Building, 3rd floor and 2nd floor corridor**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Purple Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206/208		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **Room 206/208**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Linoleum Flooring**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Linoleum Flooring**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**
MATERIAL DESCRIPTION: **Linoleum Flooring Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Linoleum Flooring Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57	
MATERIAL DESCRIPTION:	Blue Carpet Masic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Principal's Office, Room 202 - 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Blue Carpet Masonic**

MATERIAL LOCATION: **Main Office, Principal's Office, Room 202 - 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1911 Building Gym/Assembly Hall**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **1911 Building Gym/Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard - Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1911 Building - Gym/Assembly Hall**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard - Adhesive**

MATERIAL LOCATION: **1911 Building - Gym/Assembly Hall**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5A**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile (Under Carpet)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **5A**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile (Under Carpet)**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5B**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic (Under Carpet)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **5B**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic (Under Carpet)**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Gray Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Gray Linoleum**

MATERIAL LOCATION: **Room 210**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12" x 12" Gray Speckle Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - Old Lunchroom, Room 102, outside 113 and 113 1884 bldg		
MATERIAL QUANTITY:	840	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Gray Speckle Floor Tile**

MATERIAL LOCATION: **1911 Building - Old Lunchroom, Room 102, outside 113 and 113 1884 bldg**

MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	12" x 12" Gray Speckle Floor Tile - Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1191 Building - Old Lunchroom/Room 102, outside room 113 and 112 1884 bldg		
MATERIAL QUANTITY:	840	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Gray Speckle Floor Tile - Mastic**

MATERIAL LOCATION: **1191 Building - Old Lunchroom/Room 102, outside room 113 and 112 1884 bldg**

MATERIAL QUANTITY: **840** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	2" Brown Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - Old Lunchroom/Room 102		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **2" Brown Vinyl Baseboard**

MATERIAL LOCATION: **1911 Building - Old Lunchroom/Room 102**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	2" Brown Vinyl Baseboard - Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - Old Lunchroom/Room 102		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **2" Brown Vinyl Baseboard - Adhesive**

MATERIAL LOCATION: **1911 Building - Old Lunchroom/Room 102**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12" x 12" Brown Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1884 Building - Room 103		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **1884 Building - Room 103**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12" x 12" Tan Speckled Floor Tile - Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1884 Building - Room 103		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Tan Speckled Floor Tile - Mastic**

MATERIAL LOCATION: **1884 Building - Room 103**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	Ceramic Baseboard Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Ceramic Baseboard Grout**

MATERIAL LOCATION: **1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	Ceramic Baseboard Grout - Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Ceramic Baseboard Grout - Adhesive**

MATERIAL LOCATION: **1911 Building - 2nd and 3rd Floor Girls' and Teachers' Bathrooms**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Patched Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Patched Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Patched Floor Tile - Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Patched Floor Tile - Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout the 1911 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout the 1911 Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70	
MATERIAL DESCRIPTION:	Dark Blotted Beige Vinyl Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom, Exit 3 Entrance

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Dark Blotted Beige Vinyl Floor Tile**

MATERIAL LOCATION: **Lunchroom, Exit 3 Entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	Dark Blotted Beige Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Exit 3 Entrance**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Dark Blotted Beige Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom, Exit 3 Entrance**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	12" x 12" Tan Texture Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12" x 12" Tan Texture Vinyl Floor Tile**

MATERIAL LOCATION: **West Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	12" x 12" Tan Texture Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12" x 12" Tan Texture Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **West Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	Brown Rubber Floor Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairwells		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **Brown Rubber Floor Adhesive**

MATERIAL LOCATION: **Stairwells**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	2' x 2' Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **2' x 2' Carpet Adhesive**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	2' x 2' Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 206, 208		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **2' x 2' Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 206, 208**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	Lab Counter Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 414,313, 314, 214, 114**

MATERIAL QUANTITY: **3** MATERIAL UNITS:

DAMAGE QUANTITY: MATERIAL UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Lab Counter Tops**

MATERIAL LOCATION: **Room 414,313, 314, 214, 114**

MATERIAL QUANTITY: **3**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78	
MATERIAL DESCRIPTION:	12" x 12" Lite Beige Vinyl Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 104 and Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Lite Beige Vinyl Floor Tile**

MATERIAL LOCATION: **Classroom 104 and Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79	
MATERIAL DESCRIPTION:	12" x 12" Lite Beige Vinyl Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classroom 104 and Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Lite Beige Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Classroom 104 and Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout the 1884 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	Pink/Tan Sheet Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 313, 314, 413, 414		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Pink/Tan Sheet Flooring**

MATERIAL LOCATION: **Rooms 214, 313, 314, 413, 414**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	Pink/Tan Sheet Flooring Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 313, 314, 413, 414		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Pink/Tan Sheet Flooring Mastic**

MATERIAL LOCATION: **Rooms 214, 313, 314, 413, 414**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	6" Gray Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 312, 313, 314, 413, 414		
MATERIAL QUANTITY:	240	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **6" Gray Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 214, 312, 313, 314, 413, 414**

MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	6" Gray Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 312, 313, 314, 413, 414		
MATERIAL QUANTITY:	240	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **6" Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Rooms 214, 312, 313, 314, 413, 414**

MATERIAL QUANTITY: **240** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	White Sink Undercoat		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: **1** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **White Sink Undercoat**

MATERIAL LOCATION: **Room 113**

MATERIAL QUANTITY: **1**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Teachers' Bathroom by Room 309**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Teachers' Bathroom by Room 309**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Air Cell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Air Cell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Cementitious Joints on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cementitious Joints on Aircell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Cementitious Joint Insulation Off Cardboard		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation Off Cardboard**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Powder Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Pipe Chases and Within Walls, 112 Book room 1884 building, 1st floor hallway 1884 building**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Powder Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls, 112 Book room 1884 building, 1st floor hallway 1884 building**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Powder Elbows		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases and Within Walls		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Powder Elbows**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Boiler Gasket		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Boiler Packing		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Boiler Packing**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Tank Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Kiln**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Kiln**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Cementitious Joint Insulation on Aircell		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Cementitious Joint Insulation on Aircell**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Pipe Chases and Within Walls

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature: _____ Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Cementitious Pipe Joint Insulation Off Cardboard		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cementitious Pipe Joint Insulation Off Cardboard**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	Powder Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Powder Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Powder Elbows		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/21/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUILDING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Powder Elbows**

MATERIAL LOCATION: **Pipe Chases and Within Walls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	105			
MATERIAL DESCRIPTION:	8" x 16" CMU			
MATERIAL LOCATION:	3rd Floor, 2nd Floor , 1st Floor Boys and Girls Bathroom 1911 Building, Book Room 1884 Building			
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		
HOMOGENEOUS AREA:	105				
MATERIAL DESCRIPTION:	8" x 16" CMU				
MATERIAL LOCATION:	3rd Floor, 2nd Floor , 1st Floor Boys and Girls Bathroom 1911 Building, Book Room 1884 Building				
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:		DAMAGE UNITS:	SF		

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	106			
MATERIAL DESCRIPTION:	8" x 16" CMU Grout			
MATERIAL LOCATION:	3rd Floor, 2nd Floor, 1st Floor Boys and Girls Bathroom 1911 Building			
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23941** BUIDLING ID: **4190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Jefferson School** REVIEW DATE: **5/9/2025**

ADDRESS: **1522 W. Fillmore** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **8" x 16" CMU Grout**

MATERIAL LOCATION: **3rd Floor, 2nd Floor, 1st Floor Boys and Girls Bathroom 1911 Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *05/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	2" x 8" Glazed Brick		
MATERIAL LOCATION:	3rd, 2nd, 1st Floor Girls Bathroom 1911		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23941** BUIDLING ID: **4190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Jefferson School** REVIEW DATE: **5/9/2025**

ADDRESS: **1522 W. Fillmore** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **2" x 8" Glazed Brick**

MATERIAL LOCATION: **3rd, 2nd, 1st Floor Girls Bathroom 1911**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *05/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	104			
MATERIAL DESCRIPTION:	8" x 16" Glazed CMU Grout			
MATERIAL LOCATION:	3rd Floor, 2nd Floor 1st Floor Boys Bathroom 1911 Building			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23941** BUIDLING ID: **4190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Jefferson School** REVIEW DATE: **5/9/2025**

ADDRESS: **1522 W. Fillmore** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **8" x 16" Glazed CMU Grout**

MATERIAL LOCATION: **3rd Floor, 2nd Floor 1st Floor Boys Bathroom 1911 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *05/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	108			
MATERIAL DESCRIPTION:	2" x 8" Glazed Brick Grout			
MATERIAL LOCATION:	3rd Floor, 2nd Floor, 1st Floor Girls Bathroom 1911			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Jefferson School	REVIEW DATE:	5/9/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **2" x 8" Glazed Brick Grout**

MATERIAL LOCATION: **3rd Floor, 2nd Floor, 1st Floor Girls Bathroom 1911**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23941	BUIDLING ID:	4190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Jefferson School	INSPECTION DATE:	4/21/2025		
ADDRESS:	1522 W. Fillmore	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	103			
MATERIAL DESCRIPTION:	8" x 16" Glazed CMU			
MATERIAL LOCATION:	3rd Floor, 2nd Floor, 1st Floor Boys Bathroom 1911 Building			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/21/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23941** BUIDLING ID: **4190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Jefferson School** REVIEW DATE: **5/9/2025**

ADDRESS: **1522 W. Fillmore** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **8" x 16" Glazed CMU**

MATERIAL LOCATION: **3rd Floor, 2nd Floor, 1st Floor Boys Bathroom 1911 Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *05/09/2025*

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jose Escobedo


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2409132637
Course Date: 9/13/2024
Exam Date: 9/13/2024
Expiration Date: 9/13/2025




Issue Date: 9/13/2024


Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

Jose Escobedo

Air Sampling Professional, Illinois Licensed Building Inspector, Asbestos Project Manager







ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	1/11/2026
INSPECTOR	9/13/2025

PROJECT MANAGER	1/11/2026
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner





2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed