

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2135
SCHOOL NAME: Clissold School
ADDRESS OF SCHOOL: 2350 W. 110th Pl.
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 8/17/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/16/2025 ENROLLMENT 470
IDPH INSPECTOR LICENSE NUMBER: 100-19716
IDPH LICENSED INSPECTOR NAME (Please Print): Imani Robinson
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/13/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Clissold School

2350 W. 110th Pl.
Chicago, IL, 60643

Unit: 22761
Building ID: 2820

IDPH ID Number: 14-016-2990-2135

REPORT DATE:
Friday, June 13, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
TEM Environmental, Inc.

174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone 630-790-0880
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/12/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 22761 Region: 06 IDPH ID: 14-016-2990-2135

School: Clissold School Building ID: 2820

Address: 2350 W. 110th Pl.

Chicago, IL, 60643

Building Contact: Kelly, Mark Contact Phone: 3125093270

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/16/2025

Review Date: 06/12/2025

Inspector: Imani Robinson

Inspector IDPH License: 100-19716

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 13, 2025

RE: Clissold School, Unit 22761
2350 W. 110th Pl.
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Clissold School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Clissold School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Clissold School
Address: 2350 W. 110th Pl.
IDPH ID: 14-016-2990-2135
Contact: Kelly, Mark

Unit: 22761
Chicago, IL, 60643
Building ID: 2820
Phone: 3125093270

Region: 06

2. Description of Facility

Original Construction: 1930
Total Square Footage: 59069
Current Occupancy: 470

Additional Construction:
No of Floors: 3

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Imani Robinson

Inspector IDPH license # 100-19716
Reinspection Date: 5/16/2025


Signature:
Date: 5/16/2025

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613


Signature:
Date: 06/12/2025

7. Review Date: 06/12/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/13/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Clissold School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2820:

27	12x12 Black and red Checkerboard Floor Tile Mastic
28	12"x12" Blue Vinyl Floor Tile
28M	Mastic associated w/12"x12" Blue Vinyl Floor Tile
29	12"x12" Black & Red Checkeboard Vinyl Floor Tile
29M	Mastic associated w/12"x12" Black & Red Checkerboard Vinyl Floor Tile
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 2820:

28	12"x12" Blue Vinyl Floor Tlle
28M	Mastic associated w/12"x12" Blue Vinyl Floor Tlle
29	12"x12" Black & Red Checkeboard Vinyl Floor Tile
29M	Mastic associated w/12"x12" Black & Red Checkerboard Vinyl Floor Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05A	12"x12" Cream w/Tan Specks Floor Tile
05B	12"x12" Cream w/Beige Streaks Floor Tile
05C	12"x12" Cream w/Brown & Maroon Specks Floor Tile
05D	12"x12" Dark Multicolor Beige Floor Tile
05E	12"X12" Cream w/Brown Blotches Floor Tile
05F	12"x12" Light Multicolor Beige Floor Tile
05G	12"x12" Cream w/Blue Streaks Floor Tile
05H	12"x12" Green w/Cream Streaks Floor Tile
05I	Olive Green Carpet Adhesive
07A	9"x9" Red Floor Tile Mastic
07B	9"x9" Black Floor Tile Mastic
07C	9"x9" Beige w/Brown and Cream Streaks Floor Tile
08A	12"x12" Cream w/Tan Specks Floor Tile Mastic
08B	12"x12" Cream w/Beige Streaks Floor Tile Mastic
08D	12"x12" Dark Multicolored Beige Floor Tile Mastic
12	12"x12" Yellow Floor Tile
13	12"x12" Yellow Floor Tile Mastic
14	12"x12" Red Floor Tile
15	12"x12" Red Floor Tile Mastic
16	Terrazzo
17	Plaster Walls and Ceilings
18	2'x4' Lay-In Ceiling Tile with Pinholes and Fissures
19	12"x12" Ceiling Tile
20	12"x12' White w/Blue Specks Floor Tile NOT OBSERVED
20M	12"x12' White w/Blue Specks Floor Tile Mastic NOT OBSERVED
21	2x2 White w/ Pinholes Ceiling Tiles NOT OBSERVED
22	Beige Sheet Flooring NOT OBSERVED
23	Vinyl Baseboard Mastic NOT OBSERVED
24	MJP on Fiberglass Pipe Runs
25	Decorative Plaster
26	12x12 Black and Red Checkerboard Floor Tile
27	12x12 Black and red Checkerboard Floor Tile Mastic
28	12"x12" Blue Vinyl Floor Tile
28M	Mastic associated w12"x12" Blue Vinyl Floor Tile
29	12"x12" Black & Red Checkered Vinyl Floor Tile
29M	Mastic associated w/12"x12" Black & Red Checkerboard Vinyl Floor Tile

NEW

Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

05E	12"X12" Cream w/Brown Blotches Floor Tile
05I	Olive Green Carpet Adhesive
07A	9"x9" Red Floor Tile Mastic
07B	9"x9" Black Floor Tile Mastic
07C	9"x9" Beige w/Brown and Cream Streaks Floor Tile
08A	12"x12" Cream w/Tan Specks Floor Tile Mastic
08B	12"x12" Cream w/Beige Streaks Floor Tile Mastic
08C	12"x12" Cream w/Brown & Maroon Specks Floor Tile Mastic
08D	12"x12" Dark Multicolored Beige Floor Tile Mastic
08E	12"x12" Cream w/Brown Blotches Floor Tile Mastic
08F	12"x12" Light Multicolor Beige Floor Tile Mastic
08H	12"x12" Green w/Cream Streaks Floor Tile Mastic
11	Turquoise Carpet Mastic
13	12"x12" Yellow Floor Tile Mastic
15	12"x12" Red Floor Tile Mastic
19	12"x12" Ceiling Tile
20M	12"x12' White w/Blue Specks Floor Tile Mastic
NOT OBSERVED	
C	Cardboard Pipe Insulation
D	Preformed Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Imani Robinson, IDPH License # 100-19716. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 4/28/2023
6/9/2023
6/28/2024

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Clissold School Building 2820 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Clissold School **Unit** 22761 **Building ID** 2820
Address 2350 W. 110th Pl. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04A	9"x9" Red Floor Tile NOT OBSERVED	3,575	SF	Auditorium, 2nd & 3rd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04B	9"x9" Black Floor Tile	1,000	SF	Assembly Hall	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
04C	9"x9" Beige w/Brown & Cream Streaks Floor Tile	1,175	SF	Rooms 105 & 300	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05A	12"x12" Cream w/Tan Specks Floor Tile	3,250	SF	1st Floor Corridor, Copy Room 210, 214 & 302	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05B	12"x12" Cream w/Beige Streaks Floor Tile	1,950	SF	Rm 102, 104 and 3rd Floor Teachers Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05C	12"x12" Cream w/Brown & Maroon Specks Floor Tile	1,570	SF	Room 103, 303 and 3rd Floor NE Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05D	12"x12" Dark Multicolor Beige Floor Tile	1,770	SF	Rooms 109, 214, 302 and 304	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05E	12"X12" Cream w/Brown Blotches Floor Tile	720	SF	Room 301	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05F	12"x12" Light Multicolor Beige Floor Tile	50	SF	Teacher's Room (PKA Coat Room)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05G	12"x12" Cream w/Blue Streaks Floor Tile	720	SF	Room 202	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05H	12"x12" Green w/Cream Streaks Floor Tile	400	SF	Engineer Office and Lunch Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05I	Olive Green Carpet Adhesive	400	SF	Engineer Office and Lunch Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	Lab Tabletop	1,155	SF	Room 305	NO_ACBM	MISC			0					
07A	9"x9" Red Floor Tile Mastic	3,575	SF	Auditorium, 2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07B	9"x9" Black Floor Tile Mastic	1,000	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07C	9"x9" Beige w/Brown and Cream Streaks Floor Tile	1,175	SF	Rooms 105 and 300	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08A	12"x12" Cream w/Tan Specks Floor Tile Mastic	3,250	SF	1st Floor Corridor, Copy Room 210, Rooms 209, 214 & 302	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08B	12"x12" Cream w/Beige Streaks Floor Tile Mastic	1,950	SF	Rooms 102, 104 & 3rd Floor Teachers Lounge	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08C	12"x12" Cream w/Brown & Maroon Specks Floor Tile Mastic	1,570	SF	Rooms 103, 303 & 3rd Floor NE Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08D	12"x12" Dark Multicolored Beige Floor Tile Mastic	1,370	SF	Rooms 109, 209, 214 & 302	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clissold School **Unit** 22761 **Building ID** 2820
Address 2350 W. 110th Pl. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
08E	12"x12" Cream w/Brown Blotches Floor Tile Mastic	720	SF	Room 301	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08F	12"x12" Light Multicolor Beige Floor Tile Mastic	50	SF	Teachers' Room (PKA Coat Room)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08H	12"x12" Green w/Cream Streaks Floor Tile Mastic	400	SF	Engineer Office, Lunch Lounge	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Gray Carpet Mastic	1,800	SF	Library 205, 207	NO_ACBM	MISC								
11	Turquoise Carpet Mastic	650	SF	Main Office, Case Manager's Office, Principal's Office	NO_ACBM	MISC								
12	12"x12" Yellow Floor Tile	80	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" Yellow Floor Tile Mastic	80	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12"x12" Red Floor Tile	80	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12"x12" Red Floor Tile Mastic	80	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	Terrazzo	2,000	SF	As a Border in All Corridors, Main Office, Stairwells and Foyers	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Plaster Walls and Ceilings	110,000	SF	Throughout Facility	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
18	2"x4' Lay-In Ceiling Tile with Pinholes and Fissures	1,800	SF	Room 205/207	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
19	12"x12" Ceiling Tile	7,500	SF	Assembly Hall	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12' White w/Blue Specks Floor Tile NOT OBSERVED	2,700	SF	Portable Classrooms	ASSUMED	MISC	N	NONE	0		No			LOW
20M	12"x12' White w/Blue Specks Floor Tile Mastic NOT OBSERVED	2,700	SF	Portable Classrooms	ASSUMED	MISC	N	NONE	0		No			LOW
21	2x2 White w/ Pinholes Ceiling Tiles NOT OBSERVED	1,500	SF	Throughout Mobile Unit (except Bathrooms and Mechanical Rooms	ASSUMED	MISC	Y	NONE	0		No			LOW
22	Beige Sheet Flooring NOT OBSERVED	300	SF	Mobile Unit- Girl's and Boys' Restrooms	ASSUMED	MISC	N	NONE	0		No			LOW
23	Vinyl Baseboard Mastic NOT OBSERVED	750	LF	Throughout Mobile Unit	ASSUMED	MISC	N	NONE	0		No			LOW
24	MJP on Fiberglass Pipe Runs	40	LF	Main Building- Pump Room and Basement Areas	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Clissold School **Unit** 22761 **Building ID** 2820
Address 2350 W. 110th Pl. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
25	Decorative Plaster	800	SF	Auditorium	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Black and Red Checkerboard Floor Tile	2,775	SF	2nd & 3rd Floor Corridors and Elevator Lobbies	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Black and red Checkerboard Floor Tile Mastic	2,775		2nd & 3rd Floor Corridors and Elevator Lobbies	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
28	12"x12" Blue Vinyl Floor Tile	750	SF	Room 304	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
28M	Mastic associated w/12"x12" Blue Vinyl Floor Tile	750	SF	Room 304	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
29	12"x12" Black & Red Checkeboard Vinyl Floor Tile	2,575	SF	2nd & 3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
29M	Mastic associated w/12"x12" Black & Red Checkerboard Vinyl Floor Tile	2,575	SF	2nd & 3rd Floor Corridors	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Mag Block Insulation on Water Tanks ABATED			Store Room	ABATED	TSI								
B	Aircell Pipe Insulation	2,000	LF	Throughout Basement, 2nd Floor Corridor by Room 201 & Under Auditorium	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Cardboard Pipe Insulation	900	LF	Basement and Unexcavated Tunnel Area	CHR	TSI	Y		0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Preformed Pipe Insulation	300	LF	Basement Steam Lines and Tunnel	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Aircell Duct Insulation	200	SF	Unexcavated Area South Portion	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	MJP E/F/V on Aircell Pipe Insulation	170	LF	Basement Boiler Room, 2nd Floor Corridor by Room 201	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	MJP E/F/V on Cardboard Pipe Insulation	150	FITTING	Basements, Tunnel Areas and Fan Rooms	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Boiler Gasket NOT OBSERVED	130	LF	Boiler Room	CHR	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	ASSUMED	MISC		UNKNO WN	0		Yes	ACBM with the potential for damage		

Chicago Public Schools

School Clissold School **Unit** 22761 **Building ID** 2820
Address 2350 W. 110th Pl. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Clissold School Unit 22761 Building ID 2820
Address 2350 W. 110th Pl. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>5/16/2025</u>
Inspector Name	<u>Imani Robinson</u>
100-19716	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
04A	Not Observed 2025. New Materials so New HAs Assigned
04B	
04C	
05A	
05B	
05C	
05D	
05E	
05F	
05G	
05H	
05I	
06	
07A	
07B	
07C	
08A	
08B	
08C	
08D	
08E	
08F	
08H	
09	

Chicago Public Schools

School Clissold School Unit 22761 Building ID 2820
Address 2350 W. 110th Pl. Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	Not Observed 2025
20M	Not Observed 2025
21	Not Observed 2025
22	Not Observed 2025
23	Not Observed 2025
24	
25	
26	
27	
28	
28M	
29	
29M	
A	
B	2025- Partially Abated in 2023
C	2025- Area Inaccessible
D	
E	2025- Area Inaccessible
G	
H	

Chicago Public Schools

School Clissold School **Unit** 22761 **Building ID** 2820
Address 2350 W. 110th Pl. **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
I	Not Observed 2025
NEW	

Table II
Management Planner's Review

Chicago Public Schools

School Clissold School

Unit 22761

Building ID 2820

Address 2350 W. 110th Pl.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04A	9"x9" Red Floor Tile NOT OBSERVED	3,575	SF	Auditorium, 2nd & 3rd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04B	9"x9" Black Floor Tile	1,000	SF	Assembly Hall	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04C	9"x9" Beige w/Brown & Cream Streaks Floor Tile	1,175	SF	Rooms 105 & 300	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05A	12"x12" Cream w/Tan Specks Floor Tile	3,250	SF	1st Floor Corridor, Copy Room 210, 214 & 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05B	12"x12" Cream w/Beige Streaks Floor Tile	1,950	SF	Rm 102, 104 and 3rd Floor Teachers Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05C	12"x12" Cream w/Brown & Maroon Specks Floor Tile	1,570	SF	Room 103, 303 and 3rd Floor NE Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05D	12"x12" Dark Multicolor Beige Floor Tile	1,770	SF	Rooms 109, 214, 302 and 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05E	12"x12" Cream w/Brown Blotches Floor Tile	720	SF	Room 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05F	12"x12" Light Multicolor Beige Floor Tile	50	SF	Teacher's Room (PKA Coat Room)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05G	12"x12" Cream w/Blue Streaks Floor Tile	720	SF	Room 202	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05H	12"x12" Green w/Cream Streaks Floor Tile	400	SF	Engineer Office and Lunch Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05I	Olive Green Carpet Adhesive	400	SF	Engineer Office and Lunch Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Lab Tabletop	1,155	SF	Room 305	No ACBM	MISC		0	SF		
07A	9"x9" Red Floor Tile Mastic	3,575	SF	Auditorium, 2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07B	9"x9" Black Floor Tile Mastic	1,000	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07C	9"x9" Beige w/Brown and Cream Streaks Floor Tile	1,175	SF	Rooms 105 and 300	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08A	12"x12" Cream w/Tan Specks Floor Tile Mastic	3,250	SF	1st Floor Corridor, Copy Room 210, Rooms 209, 214 & 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08B	12"x12" Cream w/Beige Streaks Floor Tile Mastic	1,950	SF	Rooms 102, 104 & 3rd Floor Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08C	12"x12" Cream w/Brown & Maroon Specks Floor Tile Mastic	1,570	SF	Rooms 103, 303 & 3rd Floor NE Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08D	12"x12" Dark Multicolored Beige Floor Tile Mastic	1,370	SF	Rooms 109, 209, 214 & 302	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08E	12"x12" Cream w/Brown Blotches Floor Tile Mastic	720	SF	Room 301	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08F	12"x12" Light Multicolor Beige Floor Tile Mastic	50	SF	Teachers' Room (PKA Coat Room)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08H	12"x12" Green w/Cream Streaks Floor Tile Mastic	400	SF	Engineer Office, Lunch Lounge	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Gray Carpet Mastic	1,800	SF	Library 205, 207	No ACBM	MISC			SF		
11	Turquoise Carpet Mastic	650	SF	Main Office, Case Manager's Office, Principal's Office	No ACBM	MISC			SF		
12	12"x12" Yellow Floor Tile	80	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Yellow Floor Tile Mastic	80	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Red Floor Tile	80	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clissold School

Unit 22761

Building ID 2820

Address 2350 W. 110th Pl.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
15	12"x12" Red Floor Tile Mastic	80	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Terrazzo	2,000	SF	As a Border in All Corridors, Main Office, Stairwells and Foyers	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Plaster Walls and Ceilings	110,000	SF	Throughout Facility	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	2'x4' Lay-In Ceiling Tile with Pinholes and Fissures	1,800	SF	Room 205/207	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12"x12" Ceiling Tile	7,500	SF	Assembly Hall	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12' White w/Blue Specks Floor Tile NOT OBSERVED	2,700	SF	Portable Classrooms	Assumed	MISC	No	0	SF		
20M	12"x12' White w/Blue Specks Floor Tile Mastic NOT OBSERVED	2,700	SF	Portable Classrooms	Assumed	MISC	No	0	SF		
21	2x2 White w/ Pinholes Ceiling Tiles NOT OBSERVED	1,500	SF	Throughout Mobile Unit (except Bathrooms and Mechanical Rooms	Assumed	MISC	Yes	0	SF		
22	Beige Sheet Flooring NOT OBSERVED	300	SF	Mobile Unit- Girl's and Boys' Restrooms	Assumed	MISC	No	0	SF		
23	Vinyl Baseboard Mastic NOT OBSERVED	750	LF	Throughout Mobile Unit	Assumed	MISC	No	0	LF		
24	MJP on Fiberglass Pipe Runs	40	LF	Main Building- Pump Room and Basement Areas	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
25	Decorative Plaster	800	SF	Auditorium	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Black and Red Checkerboard Floor Tile	2,775	SF	2nd & 3rd Floor Corridors and Elevator Lobbies	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Black and red Checkerboard Floor Tile Mastic	2,775		2nd & 3rd Floor Corridors and Elevator Lobbies	Assumed	MISC	No	0		6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" Blue Vinyl Floor Tile	750	SF	Room 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28M	Mastic associated w/12"x12" Blue Vinyl Floor Tile	750	SF	Room 304	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" Black & Red Checkered Vinyl Floor Tile	2,575	SF	2nd & 3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29M	Mastic associated w/12"x12" Black & Red Checkered Vinyl Floor Tile	2,575	SF	2nd & 3rd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Mag Block Insulation on Water Tanks ABATED			Store Room	Abated	TSI					
B	Aircell Pipe Insulation	2,000	LF	Throughout Basement, 2nd Floor Corridor by Room 201 & Under Auditorium	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Cardboard Pipe Insulation	900	LF	Basement and Unexcavated Tunnel Area	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Preformed Pipe Insulation	300	LF	Basement Steam Lines and Tunnel	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Aircell Duct Insulation	200	SF	Unexcavated Area South Portion	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Clissold School

Unit 22761

Building ID 2820

Address 2350 W. 110th Pl.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G	MJP E/F/V on Aircell Pipe Insulation	170	LF	Basement Boiler Room, 2nd Floor Corridor by Room 201	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	MJP E/F/V on Cardboard Pipe Insulation	150	FITTING	Basements, Tunnel Areas and Fan Rooms	Chrysotile	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Boiler Gasket NOT OBSERVED	130	LF	Boiler Room	Chrysotile	TSI	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Clissold School

Unit 22761

Building ID 2820

Address 2350 W. 110th Pl.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	6/12/2025
Manager Planner Name	Daniel Juneau
100-03613	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
04A	
04B	
04C	
05A	
05B	
05C	
05D	
05E	
05F	
05G	
05H	
05I	
06	
07A	
07B	
07C	
08A	
08B	
08C	
08D	
08E	
08F	
08H	
09	
11	
12	

Chicago Public Schools

School Clissold School

Unit 22761

Building ID 2820

Address 2350 W. 110th Pl.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13	
14	
15	
16	
17	
18	
19	
20	
20M	
21	
22	
23	
24	
25	
26	
27	
28	
28M	
29	
29M	
A	
B	
C	
D	
E	
G	
H	

Chicago Public Schools

School Clissold School

Unit 22761

Building ID 2820

Address 2350 W. 110th Pl.

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
I	
NEW	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04A		
MATERIAL DESCRIPTION:	9"x9" Red Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, 2nd & 3rd Floor Corridors		
MATERIAL QUANTITY:	3575	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. New Materials so New HAs Assigned		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **04A**

MATERIAL DESCRIPTION: **9"x9" Red Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Auditorium, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **3575** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04B		
MATERIAL DESCRIPTION:	9"x9" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **04B**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04C		
MATERIAL DESCRIPTION:	9"x9" Beige w/Brown & Cream Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105 & 300		
MATERIAL QUANTITY:	1175	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **04C**

MATERIAL DESCRIPTION: **9"x9" Beige w/Brown & Cream Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 105 & 300**

MATERIAL QUANTITY: **1175** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05A		
MATERIAL DESCRIPTION:	12"x12" Cream w/Tan Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, Copy Room 210, 214 & 302		
MATERIAL QUANTITY:	3250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05A**

MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor, Copy Room 210, 214 & 302**

MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05B		
MATERIAL DESCRIPTION:	12"x12" Cream w/Beige Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rm 102, 104 and 3rd Floor Teachers Lounge		
MATERIAL QUANTITY:	1950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05B**

MATERIAL DESCRIPTION: **12"x12" Cream w/Beige Streaks Floor Tile**

MATERIAL LOCATION: **Rm 102, 104 and 3rd Floor Teachers Lounge**

MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05C		
MATERIAL DESCRIPTION:	12"x12" Cream w/Brown & Maroon Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103, 303 and 3rd Floor NE Office		
MATERIAL QUANTITY:	1570	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05C**

MATERIAL DESCRIPTION: **12"x12" Cream w/Brown & Maroon Specks Floor Tile**

MATERIAL LOCATION: **Room 103, 303 and 3rd Floor NE Office**

MATERIAL QUANTITY: **1570** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05D		
MATERIAL DESCRIPTION:	12"x12" Dark Multicolor Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109, 214, 302 and 304		
MATERIAL QUANTITY:	1770	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05D**

MATERIAL DESCRIPTION: **12"x12" Dark Multicolor Beige Floor Tile**

MATERIAL LOCATION: **Rooms 109, 214, 302 and 304**

MATERIAL QUANTITY: **1770** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05E		
MATERIAL DESCRIPTION:	12"X12" Cream w/Brown Blotches Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301		
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05E**

MATERIAL DESCRIPTION: **12"X12" Cream w/Brown Blotches Floor Tile**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05F		
MATERIAL DESCRIPTION:	12"x12" Light Multicolor Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teacher's Room (PKA Coat Room)		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05F**

MATERIAL DESCRIPTION: **12"x12" Light Multicolor Beige Floor Tile**

MATERIAL LOCATION: **Teacher's Room (PKA Coat Room)**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05G		
MATERIAL DESCRIPTION:	12"x12" Cream w/Blue Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 202		
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05G**

MATERIAL DESCRIPTION: **12"x12" Cream w/Blue Streaks Floor Tile**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05H		
MATERIAL DESCRIPTION:	12"x12" Green w/Cream Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer Office and Lunch Lounge		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **05H**

MATERIAL DESCRIPTION: **12"x12" Green w/Cream Streaks Floor Tile**

MATERIAL LOCATION: **Engineer Office and Lunch Lounge**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05I		
MATERIAL DESCRIPTION:	Olive Green Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer Office and Lunch Lounge		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Olive Green Carpet Adhesive**

MATERIAL LOCATION: **Engineer Office and Lunch Lounge**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**
MATERIAL DESCRIPTION: **Lab Tabletop**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:	Room 305	MATERIAL UNITS:	SF
MATERIAL QUANTITY:	1155	DAMAGE UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Lab Tabletop**

MATERIAL LOCATION: **Room 305**

MATERIAL QUANTITY: **1155** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07A		
MATERIAL DESCRIPTION:	9"x9" Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, 2nd & 3rd Floor Corridors		
MATERIAL QUANTITY:	3575	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **07A**

MATERIAL DESCRIPTION: **9"x9" Red Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium, 2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **3575** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07B		
MATERIAL DESCRIPTION:	9"x9" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **07B**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07C		
MATERIAL DESCRIPTION:	9"x9" Beige w/Brown and Cream Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105 and 300		
MATERIAL QUANTITY:	1175	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **07C**

MATERIAL DESCRIPTION: **9"x9" Beige w/Brown and Cream Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 105 and 300**

MATERIAL QUANTITY: **1175** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08A		
MATERIAL DESCRIPTION:	12"x12" Cream w/Tan Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, Copy Room 210, Rooms 209, 214 & 302		
MATERIAL QUANTITY:	3250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **08A**

MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor, Copy Room 210, Rooms 209, 214 & 302**

MATERIAL QUANTITY: **3250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08B		
MATERIAL DESCRIPTION:	12"x12" Cream w/Beige Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 102, 104 & 3rd Floor Teachers' Lounge		
MATERIAL QUANTITY:	1950	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **08B**

MATERIAL DESCRIPTION: **12"x12" Cream w/Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 102, 104 & 3rd Floor Teachers' Lounge**

MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08C		
MATERIAL DESCRIPTION:	12"x12" Cream w/Brown & Maroon Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103, 303 & 3rd Floor NE Office		
MATERIAL QUANTITY:	1570	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **08C**

MATERIAL DESCRIPTION: **12"x12" Cream w/Brown & Maroon Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 103, 303 & 3rd Floor NE Office**

MATERIAL QUANTITY: **1570** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08D		
MATERIAL DESCRIPTION:	12"x12" Dark Multicolored Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109, 209, 214 & 302		
MATERIAL QUANTITY:	1370	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **08D**

MATERIAL DESCRIPTION: **12"x12" Dark Multicolored Beige Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 109, 209, 214 & 302**

MATERIAL QUANTITY: **1370** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08E		
MATERIAL DESCRIPTION:	12"x12" Cream w/Brown Blotches Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301		
MATERIAL QUANTITY:	720	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **08E**

MATERIAL DESCRIPTION: **12"x12" Cream w/Brown Blotches Floor Tile Mastic**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **720** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08F		
MATERIAL DESCRIPTION:	12"x12" Light Multicolor Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers' Room (PKA Coat Room)		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **08F**

MATERIAL DESCRIPTION: **12"x12" Light Multicolor Beige Floor Tile Mastic**

MATERIAL LOCATION: **Teachers' Room (PKA Coat Room)**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08H		
MATERIAL DESCRIPTION:	12"x12" Green w/Cream Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer Office, Lunch Lounge		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **08H**

MATERIAL DESCRIPTION: **12"x12" Green w/Cream Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Engineer Office, Lunch Lounge**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Gray Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library 205, 207**
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Library 205, 207**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Turqoise Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Case Manager's Office, Principal's Office**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Turquoise Carpet Mastic**

MATERIAL LOCATION: **Main Office, Case Manager's Office, Principal's Office**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	12"x12" Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12"x12" Yellow Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12"x12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12"x12" Red Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12"x12" Red Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12"x12" Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12"x12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	As a Border in All Corridors, Main Office, Stairwells and Foyers		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **As a Border in All Corridors, Main Office, Stairwells and Foyers**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Plaster Walls and Ceilings		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	110000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **110000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	2'x4' Lay-In Ceiling Tile with Pinholes and Fissures		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 205/207		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **2'x4' Lay-In Ceiling Tile with Pinholes and Fissures**

MATERIAL LOCATION: **Room 205/207**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12"x12" Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12"x12" Ceiling Tile**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12"x12' White w/Blue Specks Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Portable Classrooms		
MATERIAL QUANTITY:	2700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12"x12' White w/Blue Specks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Portable Classrooms**

MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20M		
MATERIAL DESCRIPTION:	12"x12' White w/Blue Specks Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Portable Classrooms		
MATERIAL QUANTITY:	2700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **20M**

MATERIAL DESCRIPTION: **12"x12' White w/Blue Specks Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Portable Classrooms**

MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	2x2 White w/ Pinholes Ceiling Tiles NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Mobile Unit (except Bathrooms and Mechanical Rooms)		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **2x2 White w/ Pinholes Ceiling Tiles NOT OBSERVED**

MATERIAL LOCATION: **Throughout Mobile Unit (except Bathrooms and Mechanical Rooms)**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Beige Sheet Flooring NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mobile Unit- Girl's and Boys' Restrooms		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Beige Sheet Flooring NOT OBSERVED**

MATERIAL LOCATION: **Mobile Unit- Girl's and Boys' Restrooms**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Vinyl Baseboard Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Mobile Unit		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic NOT OBSERVED**

MATERIAL LOCATION: **Throughout Mobile Unit**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Runs		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Building- Pump Room and Basement Areas		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Runs**

MATERIAL LOCATION: **Main Building- Pump Room and Basement Areas**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Decorative Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12x12 Black and Red Checkerboard Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW	MATERIAL UNITS:	SF
MATERIAL LOCATION:	2nd & 3rd Floor Corridors and Elevator Lobbies		
MATERIAL QUANTITY:	2775	DAMAGE UNITS:	SF
DAMAGE QUANTITY:		COMMENTS:	

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12x12 Black and Red Checkerboard Floor Tile**

MATERIAL LOCATION: **2nd & 3rd Floor Corridors and Elevator Lobbies**

MATERIAL QUANTITY: **2775**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12x12 Black and red Checkerboard Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd & 3rd Floor Corridors and Elevator Lobbies		
MATERIAL QUANTITY:	2775	MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12x12 Black and red Checkerboard Floor Tile Mastic**

MATERIAL LOCATION: **2nd & 3rd Floor Corridors and Elevator Lobbies**

MATERIAL QUANTITY: **2775** MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: Mag Block Insulation on Water Tanks ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Store Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Mag Block Insulation on Water Tanks ABATED**

MATERIAL LOCATION: **Store Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Basement, 2nd Floor Corridor by Room 201 & Under Auditorium		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	2025- Paritally Abated in 2023		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Throughout Basement, 2nd Floor Corridor by Room 201 & Under Auditorium**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement and Unexcavated Tunnel Area		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	2025- Area Inaccessible		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement and Unexcavated Tunnel Area**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Preformed Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Steam Lines and Tunnel		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Preformed Pipe Insulation**

MATERIAL LOCATION: **Basement Steam Lines and Tunnel**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Aircell Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Unexcavated Area South Portion		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Area Inaccessible		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **Unexcavated Area South Portion**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Boiler Room, 2nd Foor Corridor by Room 201		
MATERIAL QUANTITY:	170	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement Boiler Room, 2nd Floor Corridor by Room 201**

MATERIAL QUANTITY: **170** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basements, Tunnel Areas and Fan Rooms		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	DAMAGE UNITS: FITTING		
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUILDING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basements, Tunnel Areas and Fan Rooms**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Boiler Gasket NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	130	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Boiler Gasket NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **130** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Daniel Juneau		
SCHOOL NAME:	Clissold School	REVIEW DATE:	6/12/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12"x12" Blue Vinyl Floor Tile		
MATERIAL LOCATION:	Room 304		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22761** BUIDLING ID: **2820**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Clissold School** REVIEW DATE: **6/12/2025**

ADDRESS: **2350 W. 110th Pl.** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Room 304**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12"x12" Black & Red Checkered Vinyl Floor Tile		
MATERIAL LOCATION:	2nd & 3rd Floor Corridor		
MATERIAL QUANTITY:	2575	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22761** BUIDLING ID: **2820**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Clissold School** REVIEW DATE: **6/12/2025**

ADDRESS: **2350 W. 110th Pl.** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" Black & Red Checkered Vinyl Floor Tile**

MATERIAL LOCATION: **2nd & 3rd Floor Corridor**

MATERIAL QUANTITY: **2575** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	28M				
MATERIAL DESCRIPTION:	Mastic associated w12"x12" Blue Vinyl Floor Tile				
MATERIAL LOCATION:	Room 304				
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22761** BUIDLING ID: **2820**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Clissold School** REVIEW DATE: **6/12/2025**

ADDRESS: **2350 W. 110th Pl.** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **28M**

MATERIAL DESCRIPTION: **Mastic associated w12"x12" Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Room 304**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22761	BUIDLING ID:	2820
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Imani Robinson		
SCHOOL NAME:	Clissold School	INSPECTION DATE:	5/16/2025		
ADDRESS:	2350 W. 110th Pl.	IDPH LICENSE NO:	100-19716		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	29M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Black & Red Checkerboard Vinyl Floor Tile				
MATERIAL LOCATION:	2nd & 3rd Floor Corridors				
MATERIAL QUANTITY:	2575	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22761** BUIDLING ID: **2820**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Clissold School** REVIEW DATE: **6/12/2025**

ADDRESS: **2350 W. 110th Pl.** IDPH LICENSE NO: **100-19716**

HOMOGENEOUS AREA: **29M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Black & Red Checkerboard Vinyl Floor Tile**

MATERIAL LOCATION: **2nd & 3rd Floor Corridors**

MATERIAL QUANTITY: **2575** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/12/2025**

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

**CERTIFICATE OF ACHIEVEMENT
ASBESTOS ABATEMENT**

Accredited by the Illinois Department of Public Health

This is to certify that MANI ROBINSON has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the examination on 03/19/2025 with a minimum score of 70% or better. Training was in accordance with U.S.E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

1

1

02/10/2025

02/10/2015

✓ *W. B. Smith*

卷之三

卷之三

Diseases 8

Diseases of the eye 8



2303BIK01

2303BIK01

FORM # A-010B

Nicholas J. Fellen
Doctor of Public Health

MICHAEL J. FEELEY





TEM ENVIRONMENTAL, INC.
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 03613

ISSUED
3/1/2022

EXPIRES
05/15/2023

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS

INSPECTOR

TC EXPIRES

11/19/2022

MANAGEMENT PLANNER

11/19/2022

PROJECT MANAGER

11/1/2022

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

4/3/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 03613

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

Front of License		Back of License	
	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 03613	ISSUED 4/3/2024	EXPIRES 05/15/2025	INSPECTOR 11/3/2024
DANIEL J JUNEAU 1408 OAKWOOD AVENUE DES PLAINES, IL 60016 Environmental Health			MANAGEMENT PLANNER 11/3/2024 PROJECT MANAGER 11/7/2024 AIR SAMPLING PROFESSIONAL
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

5/8/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 03613

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License


Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 03613	ISSUED 5/8/2025	EXPIRES 05/15/2026	INSPECTOR	11/1/2025
DANIEL J JUNEAU 1408 OAKWOOD AVENUE DES PLAINES, IL 60016 Environmental Health			MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/1/2025 11/13/2025
			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645



Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2024

Exam Date: 11/1/2024

Expiration Date: 11/1/2025

Certificate Number: BIR2411013089

Course Credit Hours: BIR 4 Hours

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2024

Exam Date: 11/1/2024

Expiration Date: 11/1/2025

Certificate Number: MPR2411013107

Course Credit Hours: MPR 4 Hours

A handwritten signature in blue ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed