

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2139  
SCHOOL NAME: Cook School  
ADDRESS OF SCHOOL: 8150 S. Bishop  
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/17/2022

If the address on this form is different than the address of the building, submit a written explanation.

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/21/2025 ENROLLMENT 324  
IDPH INSPECTOR LICENSE NUMBER: 100-04437  
IDPH LICENSED INSPECTOR NAME (Please Print): Mary Hicks  
IDPH MP LICENSE NUMBER: 100-03613  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 6/13/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Cook School**

8150 S. Bishop  
Chicago, IL, 60620

Unit: 22801  
Building ID: 2860

IDPH ID Number: 14-016-2990-2139

**REPORT DATE:**  
Friday, June 13, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**TEM Environmental, Inc.**

174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone 630-790-0880  
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

06/12/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299              Unit: 22801              Region: 05              IDPH ID: 14-016-2990-2139

School: Cook School              Building ID: 2860

Address: 8150 S. Bishop

Chicago, IL, 60620

Building Contact:              Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/21/2025

Review Date: 06/12/2025

Inspector: Mary Hicks

Inspector IDPH License: 100-04437

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



Daniel Juneau  
100-03613

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: June 13, 2025

RE: Cook School, Unit 22801  
8150 S. Bishop  
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Cook School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Cook School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

## 1. School Information

School: Cook School Unit: 22801 Region: 05  
Address: 8150 S. Bishop Chicago, IL, 60620  
IDPH ID: 14-016-2990-2139 Building ID: 2860  
Contact: Phone:

## 2. Description of Facility

Original Construction: Additional Construction:  
Total Square Footage: No of Floors:  
Current Occupancy: 324

### 3. LEA Designated Person

#### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880 Fax: 630-790-0882

## 5. Inspector

Inspector Name: Mary Hicks

Inspector IDPH license # 100-04437  
Reinspection Date: 5/21/2025

Signature:

## 6. Management Planner

Management Planner Name: Daniel Juneau

Signature: 

7 Review Date: 06/12/2025

## 8 | EA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Date: 6/13/2025

Name: Richard J. Schleifer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Cook School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2860:

42	Orange Carpet Mastic NOT OBSERVED
48	Hard Coat Plaster
56	12"x12" Light Blue Floor Tile
56A	Mastic associated with 12"x12" Light Blue Floor Tile
57	12"x12" Dark Blue Floor Tile
57A	Mastic associated with 12"x12" Dark Blue Floor Tile
58	12"x12" Beige w/Speccks Floor Tile
58A	Mastic associated with 12"x12" Beige w/Speccks Floor Tile

59	12"x12" Brown w/Specks Floor Tile
59A	Mastic associated with 12"x12" Brown w/Specks Floor Tile
60	12"x12" Cream w/Black Specks Floor Tile
60A	Mastic associated w/12"x12" Cream w/Black Specks Floor Tile
61	12"x12" Ash Blue w/Specks Floor Tile
61A	Mastic associated with 12"x12" Ash Blue w/Specks Floor Tile
62	12"x12" Cream w/Blue Specks Floor Tile
62M	Mastic associated w/12"x12" Cream w/Blue Specks Floor Tile
A	Aircell Pipe Insulation
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 2860:

62                   12"x12" Cream w/Blue Specks Floor Tile

62M                Mastic associated w/12"x12" Cream w/Blue Specks  
                     Floor Tile

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

03	12"x12" White Floor Tile
07	12"x12" Brown Floor Tile
12	12"x12" Beige Floor Tile
14	12"x12" White Floor Tile
16	Fire Doors
18	Transite Lab Tables
19	Baseboard Mastic
20	Fire Doors
21	Baseboard Mastic
22	Baseboard
24	9"x9" Beige Floor Tile Mastic NOT OBSERVED
30	12"x12" Tan Floor Tile Mastic
32	12"x12" Beige Floor Tile Mastic
33	12"x12" Purple Floor Tile NOT OBSERVED
34	12"x12" Purple Floor Tile Mastic NOT OBSERVED
35	12"x12" Tan Floor Tile
37	Brown Linoleum NOT OBSERVED
38	Brown Linoleum Mastic NOT OBSERVED
39	Purple Carpet Mastic
40	Grey & Blue Carpet Mastic
41	Brown Carpet Mastic
42	Orange Carpet Mastic NOT OBSERVED
43	12"x12" Beige with Specks Floor Tile Mastic
44	Multicolor Carpet Adhesive NOT OBSERVED
45	12"x12" Tan w/ Specks Floor Tile
46	Purple Carpet NOT OBSERVED
47	2'x4' Ceiling Tile w/Chicken Scratch
48	Hard Coat Plaster
49	Hard Coat Plaster
50	12x12 Dark Brown Floor Tile
51	12"x12" Dark Brown Floor Tile Mastic
52	1'x1' Acoustical Ceiling Tile
53	1'x1' Acoustical Ceiling Tile Glue Dots
54	12"x12" Light Beige w/Tan Specks Floor Tile
55	12"x12" Light Beige w/Tan Specks Floor Tile Mastic
56	12"x12" Light Blue Floor Tile
56A	Mastic associated with 12"x12" Light Blue Floor Tile
57	12"x12" Dark Blue Floor Tile
57A	Mastic associated with 12"x12" Dark Blue Floor

	Tile
58	12"x12" Beige w/Specks Floor Tile
58A	Mastic associated with 12"x12" Beige w/Specks Floor Tile
59	12"x12" Brown w/Specks Floor Tile
59A	Mastic associated with 12"x12" Brown w/Specks Floor Tile
60	12"x12" Cream w/Black Specks Floor Tile
60A	Mastic associated w/12"x12" Cream w/Black Specks Floor Tile
61	12"x12" Ash Blue w/Specks Floor Tile
61A	Mastic associated with 12"x12" Ash Blue w/Specks Floor Tile
62	12"x12" Cream w/Blue Specks Floor Tile
62M	Mastic associated w/12"x12" Cream w/Blue Specks Floor Tile
B	Paper Wrap Pipe Insulation
E	Tank Insulation
I	Fittings on Aircell
K	Whiteboard Mastic
L	Old Chalkboards
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

19	Baseboard Mastic
21	Baseboard Mastic
24	9"x9" Beige Floor Tile Mastic NOT OBSERVED
25	12"x12" Orange Floor Tile Mastic
26	12"x12" Brown Floor Tile Mastic
27	12"x12" White Floor Tile Mastic
28	12"x12" Brown Floor Tile Mastic
29	12"x12" White Floor Tile Mastic
30	12"x12" Tan Floor Tile Mastic
31	12"x12" Medium Brown Floor Tile Mastic
32	12"x12" Beige Floor Tile Mastic
34	12"x12" Purple Floor Tile Mastic NOT OBSERVED
36	12"x12" Tan Floor Tile Mastic
39	Purple Carpet Mastic
40	Grey & Blue Carpet Mastic
41	Brown Carpet Mastic
44	Multicolor Carpet Adhesive NOT OBSERVED
51	12"x12" Dark Brown Floor Tile Mastic
52	1'x1' Acoustical Ceiling Tile
53	1'x1' Acoustical Ceiling Tile Glue Dots

55	12"x12" Light Beige w/Tan Specks Floor Tile
	Mastic
A	Aircell Pipe Insulation
I	Fittings on Aircell
K	Whiteboard Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Mary Hicks, IDPH License # 100-04437. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 8/1/2023

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Cook School Building 2860 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	12"x12" White Floor Tile	2,250	SF	1925 Building-Room 102 & 112	ASSUMED	MISC	N	NONE	5		No	ACBM with the potential for damage	5	LOW
04	9"x9" Beige Floor Tile NOT OBSERVED	750	SF	1925 Building-Room 104	CHR	MISC	N	LOC	0		No	ACBM with the potential for damage	5	LOW
05	12"x12" Tan Floor Tile	1,150	SF	1925 Building-Room 113	CHR	MISC	N	NONE	2		No	ACBM with the potential for damage		LOW
07	12"x12" Brown Floor Tile	1,950	SF	Room 110 & 112	ASSUMED	MISC	N	LOC	0		No	ACBM with the potential for damage	5	LOW
08	12"x12" Beige with Specks Floor Tile	750	SF	1925 Building-Room 111	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12"x12" Brown Floor Tile	3,520	SF	1974 Building-Store Rooms, Eng. Office, 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" Beige Floor Tile	1,950	SF	1974 Building-Room 224 & 228	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	12"x12" White Floor Tile	5,600	SF	1974 Building-Room 119, 121, Lunchroom, Teachers' Lunchroom & Corridor	ASSUMED	MISC	N	LOC	10		No	ACBM with the potential for damage	5	LOW
16	Fire Doors	2	EA	1925 Building-Boiler Room, Boiler Room Tunnel	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	Boiler Room Gasket ABATED			1925 Building-Boiler Room	ABATED	TSI								
18	Transite Lab Tables	30	SF	1925 Building-Room 207	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Baseboard Mastic	50	LF	1925 Building-1st Floor Boys' Toilet & Adjacent Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	Fire Doors	2	EA	1974 Building-Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	Baseboard Mastic	1,000	LF	Throughout 1974 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Baseboard	70	LF	1925 Building-Rooms 115A & 216A	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	Baseboard	1,000	LF	Throughout 1974 Building	ANT	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	9"x9" Beige Floor Tile Mastic NOT OBSERVED	750	SF	Room 104	ASSUMED	MISC	N	LOC	0		No	ACBM with the potential for damage	5	LOW
25	12"x12" Orange Floor Tile Mastic	8,650	SF	1st & 2nd Floor	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors								potential for damage		
26	12"x12" Brown Floor Tile Mastic	1,950	SF	1925 Building-Room 110 & 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12"x12" White Floor Tile Mastic	5,600	SF	1974 Building-Room 119, 121, Teachers' Lunchroom, Lunchroom & Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12"x12" Brown Floor Tile Mastic	3,520	SF	1974 Building-Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12"x12" White Floor Tile Mastic	2,250	SF	1925 Building-Rooms 102 & 112	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12"x12" Tan Floor Tile Mastic	1,150	SF	1925 Building-Room 113	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12"x12" Medium Brown Floor Tile Mastic	750	SF	1925 Building-Rooms 111 & 115A	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12"x12" Beige Floor Tile Mastic	1,950	SF	1974 Building-Rooms 224 & 228	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12"x12" Purple Floor Tile NOT OBSERVED	420	SF	1925 Building-Main Office, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12"x12" Purple Floor Tile Mastic NOT OBSERVED	420	SF	1925 Building-Main Office, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	12"x12" Tan Floor Tile	625	SF	1974 Annex Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12"x12" Tan Floor Tile Mastic	625	SF	1974 Annex Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	Brown Linoleum NOT OBSERVED			1925 Building-Storeroom	ASSUMED	MISC								
38	Brown Linoleum Mastic NOT OBSERVED			1925 Building-Storeroom	ASSUMED	MISC								
39	Purple Carpet Mastic	80	SF	1925 Building-Main Office Storeroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Grey & Blue Carpet Mastic	1,125	SF	1925 Building-Teachers' Restroom & Room 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Brown Carpet Mastic	1,500	SF	Principal's Office, Annex Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
42	Orange Carpet Mastic NOT OBSERVED	6,000	SF	1974 Building-Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room	ASSUMED	MISC	N	NONE	0		Yes			LOW
43	12"x12" Beige with Specks Floor Tile Mastic	375	SF	1925 Building-Room 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	Multicolor Carpet Adhesive NOT OBSERVED	1,125	SF	Room 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12"x12" Tan w/Specks Floor Tile	9,000	SF	Rooms 124, 126, 219 & 226	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Purple Carpet NOT OBSERVED	2,000	SF	Library	ASSUMED	MISC	N	NONE	0		No			LOW
47	2"x4" Ceiling Tile w/Chicken Scratch	25,000	SF	1925 Building-Throughout 1st & 2nd Corridors, and All Classrooms	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
48	Hard Coat Plaster	37,500	SF	Throughout 1925 Building	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
49	Hard Coat Plaster	37,500	SF	Throughout 1974 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12x12 Dark Brown Floor Tile	474	SF	1st Floor Restroom and Rooms 115B and 215B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12"x12" Dark Brown Floor Tile Mastic	474	SF	1st Floor Restroom and Rooms 115B and 215B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	1'x1' Acoustical Ceiling Tile	38	SF	Room 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	1'x1' Acoustical Ceiling Tile Glue Dots	38	SF	Room 213	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12"x12" Light Beige w/Tan Specks Floor Tile	725	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12"x12" Light Beige w/Tan Specks Floor Tile Mastic	725	SF	Room 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12"x12" Light Blue Floor Tile	1,200	SF	Rooms 112 & 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
56A	Mastic associated with 12"x12" Light Blue Floor Tile	1,200	SF	Rooms 112 & 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
57	12"x12" Dark Blue Floor Tile	1,200	SF	Rooms 112 & 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
57A	Mastic associated with 12"x12" Dark Blue	1,200	SF	Rooms 112 & 113	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the		LOW

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile											potential for damage		
58	12"x12" Beige w/Specs Floor Tile	1,800	SF	Rooms 111, 112, 113 & 119	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
58A	Mastic associated with 12"x12" Beige w/Specs Floor Tile	1,800	SF	Room 111, 112, 113 & 119	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
59	12"x12" Brown w/Specs Floor Tile	600	SF	Room 110	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
59A	Mastic associated with 12"x12" Brown w/Specs Floor Tile	600	SF	Room 110	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
60	12"x12" Cream w/Black Specks Floor Tile	600	SF	Room 121	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
60A	Mastic associated w/12"x12" Cream w/Black Specks Floor Tile	600	SF	Room 121	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
61	12"x12" Ash Blue w/Specs Floor Tile	1,600	SF	Main Office & Principal's Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
61A	Mastic associated with 12"x12" Ash Blue w/Specs Floor Tile	1,600	SF	Main Office & Principal's Office	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
62	12"x12" Cream w/Blue Specks Floor Tile	600	SF	Room 121	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
62M	Mastic associated w/12"x12" Cream w/Blue Specks Floor Tile	600	SF	Room 121	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation		LF	1925 Building-Basement, Open Crawlspaces	CHR	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM	3	LOW
B	Paper Wrap Pipe Insulation	60	LF	1925 Building-Basement Crawlspaces, Boys' & Girls Bathroom, Pipe Chases Throughout	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Aircell Duct Insulation NOT OBSERVED			Wall, CrawlSpace	CHR	TSI								
E	Tank Insulation	100	SF	Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Fittings on Fiberglass	1	FITTING	1974 Building-Compactor Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	Fittings on Paper Wrap	20	LF	1925 Building-Basement Crawlspaces, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
I	Fittings on Aircell		LF	1925 Building-Crawlspace	ASSUMED	TSI	Y	DIST			No	ACBM with the potential for damage		LOW
J	Incinerator Insulation (ABATED 1990)			1925 Building-Boiler Room	ABATED	TSI								
K	Whiteboard Mastic	750	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L	Old Chalkboards	4,000	SF	Throughout School	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN	0		Yes	ACBM with the potential for damage		

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date 5/21/2025

Inspector Name Mary Hicks

**100-04437**

5/15/2026

Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
03	5 floor tiles with cracks but intact
04	Not Observed 2025, Hardwood Floor
05	2 floor tiles cracked but intact
07	
08	
09	
12	
14	Damage in Lunchroom but intact
16	
17	
18	
19	Hardwood, no baseboards in 115A and 216A
20	
21	
22	Not Observed 2025
23	
24	Not Observed 2025. Hardwood Floor
25	
26	
27	
28	
29	
30	
31	

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
32	
33	Not Observed 2025
34	Not Observed 2025
35	
36	
37	Not Observed Multiple Years, including 2025
38	Not Observed Multiple Years, including 2025
39	
40	Not Observed
41	
42	Not Observed 2022, 2025
43	
44	Not Observed 2025
45	
46	Not Observed 2022, 2025
47	2025- Replaced
48	
49	
50	
51	
52	
53	
54	
55	
56	
56A	
57	
57A	
58	

# Chicago Public Schools

**School** Cook School **Unit** 22801 **Building ID** 2860  
**Address** 8150 S. Bishop **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
58A	
59	
59A	
60	2025- Description Changed
60A	2025- Description Changed
61	
61A	
62	
62M	
A	Partially Abated in August 2023
B	
D	Not Observed 2025. Partially Abated August 2023
E	
F	
H	
I	2025-Partially Abated August 2023
J	
K	
L	
NEW	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Cook School

**Unit** 22801

**Building ID** 2860

**Address** 8150 S. Bishop

Chicago, IL, 60620

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	12"x12" White Floor Tile	2,250	SF	1925 Building- Room 102 & 112	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	9"x9" Beige Floor Tile NOT OBSERVED	750	SF	1925 Building- Room 104	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12"x12" Tan Floor Tile	1,150	SF	1925 Building- Room 113	Chrysotile	MISC	No	2	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	12"x12" Brown Floor Tile	1,950	SF	Rooms 110 & 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Beige with Specks Floor Tile	750	SF	1925 Building- Room 111	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Brown Floor Tile	3,520	SF	1974 Building- Store Rooms, Eng. Office, 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Beige Floor Tile	1,950	SF	1974 Building- Room 224 & 228	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" White Floor Tile	5,600	SF	1974 Building- Room 119, 121, Lunchroom, Teachers' Lunchroom & Corridor	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	Repair
16	Fire Doors	2	EA	1925 Building- Boiler Room, Boiler Room Tunnel	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
17	Boiler Room Gasket ABATED			1925 Building- Boiler Room	Abated	TSI					
18	Transite Lab Tables	30	SF	1925 Building- Room 207	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Baseboard Mastic	50	LF	1925 Building- 1st Floor Boys' Toilet & Adjacent Corridor	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
20	Fire Doors	2	EA	1974 Building- Kitchen	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
21	Baseboard Mastic	1,000	LF	Throughout 1974 Building	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Baseboard	70	LF	1925 Building- Rooms 115A & 216A	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
23	Baseboard	1,000	LF	Throughout 1974 Building	Anthophyllite	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
24	9"x9" Beige Floor Tile Mastic NOT OBSERVED	750	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" Orange Floor Tile Mastic	8,650	SF	1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" Brown Floor Tile Mastic	1,950	SF	1925 Building- Room 110 & 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" White Floor Tile Mastic	5,600	SF	1974 Building- Room 119, 121, Teachers' Lunchroom, Lunchroom & Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" Brown Floor Tile Mastic	3,520	SF	1974 Building- Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" White Floor Tile Mastic	2,250	SF	1925 Building- Rooms 102 & 112	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" Tan Floor Tile Mastic	1,150	SF	1925 Building- Room 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Medium Brown Floor Tile Mastic	750	SF	1925 Building- Rooms 111 & 115A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Beige Floor Tile Mastic	1,950	SF	1974 Building- Rooms 224 & 228	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Cook School

**Unit** 22801

**Building ID** 2860

**Address** 8150 S. Bishop

Chicago, IL, 60620

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
33	12"x12" Purple Floor Tile NOT OBSERVED	420	SF	1925 Building- Main Office, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12"x12" Purple Floor Tile Mastic NOT OBSERVED	420	SF	1925 Building- Main Office, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"x12" Tan Floor Tile	625	SF	1974 Annex Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Tan Floor Tile Mastic	625	SF	1974 Annex Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Brown Linoleum NOT OBSERVED			1925 Building- Storeroom	Assumed	MISC					
38	Brown Linoleum Mastic NOT OBSERVED			1925 Building- Storeroom	Assumed	MISC					
39	Purple Carpet Mastic	80	SF	1925 Building- Main Office Storeroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Grey & Blue Carpet Mastic	1,125	SF	1925 Building- Teachers' Restroom & Room 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Brown Carpet Mastic	1,500	SF	Principal's Office, Annex Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Orange Carpet Mastic NOT OBSERVED	6,000	SF	1974 Building- Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room	Assumed	MISC	No	0	SF		
43	12"x12" Beige with Specks Floor Tile Mastic	375	SF	1925 Building- Room 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Multicolor Carpet Adhesive NOT OBSERVED	1,125	SF	Room 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12"x12" Tan w/Spcks Floor Tile	9,000	SF	Rooms 124, 126, 219 & 226	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Purple Carpet NOT OBSERVED	2,000	SF	Library	Assumed	MISC	No	0	SF		
47	2"x4' Ceiling Tile w/Chicken Scratch	25,000	SF	1925 Building- Throughout 1st & 2nd Corridors, and All Classrooms	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
48	Hard Coat Plaster	37,500	SF	Throughout 1925 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Hard Coat Plaster	37,500	SF	Throughout 1974 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12x12 Dark Brown Floor Tile	474	SF	1st Floor Restroom and Rooms 115B and 215B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12"x12" Dark Brown Floor Tile Mastic	474	SF	1st Floor Restroom and Rooms 115B and 215B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	1'x1' Acoustical Ceiling Tile	38	SF	Room 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	1'x1' Acoustical Ceiling Tile Glue Dots	38	SF	Room 213	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12"x12" Light Beige w/Tan Specks Floor Tile	725	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12"x12" Light Beige w/Tan Specks Floor Tile Mastic	725	SF	Room 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12"x12" Light Blue Floor Tile	1,200	SF	Rooms 112 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56A	Mastic associated with 12"x12" Light Blue Floor Tile	1,200	SF	Rooms 112 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12"x12" Dark Blue Floor Tile	1,200	SF	Rooms 112 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Cook School

**Unit** 22801

**Building ID** 2860

**Address** 8150 S. Bishop

Chicago, IL, 60620

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
57A	Mastic associated with 12"x12" Dark Blue Floor Tile	1,200	SF	Rooms 112 & 113	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"x12" Beige w/Speccks Floor Tile	1,800	SF	Rooms 111, 112, 113 & 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58A	Mastic associated with 12"x12" Beige w/Speccks Floor Tile	1,800	SF	Room 111, 112, 113 & 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12"x12" Brown w/Speccks Floor Tile	600	SF	Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59A	Mastic associated with 12"x12" Brown w/Speccks Floor Tile	600	SF	Room 110	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12"x12" Cream w/Black Specks Floor Tile	600	SF	Room 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60A	Mastic associated w/12"x12" Cream w/Black Specks Floor Tile	600	SF	Room 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12" Ash Blue w/Speccks Floor Tile	1,600	SF	Main Office & Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61A	Mastic associated with 12"x12" Ash Blue w/Speccks Floor Tile	1,600	SF	Main Office & Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12"x12" Cream w/Blue Specks Floor Tile	600	SF	Room 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62M	Mastic associated w/12"x12" Cream w/Blue Specks Floor Tile	600	SF	Room 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation		LF	1925 Building- Basement, Open Crawlspaces	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
B	Paper Wrap Pipe Insulation	60	LF	1925 Building- Basement Crawlspac, Boys' & Girls Bathroom, Pipe Chases Throughout	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Aircell Duct Insulation NOT OBSERVED			Wall, Crawlspac	Chrysotile	TSI					
E	Tank Insulation	100	SF	Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Fittings on Fiberglass	1	FITTING	1974 Building- Compactor Room	Chrysotile	TSI	Yes	0	FITTING	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Fittings on Paper Wrap	20	LF	1925 Building- Basement Crawlspaces, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Fittings on Aircell		LF	1925 Building- Crawlspac	Assumed	TSI	Yes		LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Incinerator Insulation (ABATED 1990)			1925 Building- Boiler Room	Abated	TSI					
K	Whiteboard Mastic	750	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	Old Chalkboards	4,000	SF	Throughout School	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Cook School

**Unit** 22801

**Building ID** 2860

**Address** 8150 S. Bishop

Chicago, IL, 60620

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	6/12/2025
Manager Planner Name	Daniel Juneau
100-03613	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	O&M response action in selective areas of damage only
04	
05	O&M response action for selective areas of damage only
07	
08	
09	
12	

# Chicago Public Schools

**School** Cook School

**Unit** 22801

**Building ID** 2860

**Address** 8150 S. Bishop

Chicago, IL, 60620

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
14	Repair response in selective areas with damage only
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	

# Chicago Public Schools

**School** Cook School

**Unit** 22801

**Building ID** 2860

**Address** 8150 S. Bishop

Chicago, IL, 60620

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
56A	
57	
57A	
58	
58A	
59	
59A	
60	
60A	
61	
61A	
62	

# Chicago Public Schools

**School** Cook School

**Unit** 22801

**Building ID** 2860

**Address** 8150 S. Bishop

Chicago, IL, 60620

**Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

#### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
62M	
A	
B	
D	
E	
F	
H	
I	
J	
K	
L	
NEW	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**TEM Environmental, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

TEM Environmental, Inc.

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>03</b>		
MATERIAL DESCRIPTION:	<b>12"x12" White Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 102 &amp; 112</b>		
MATERIAL QUANTITY:	<b>2250</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>5 floor tiles with cracks but intact</b>		

Inspector's Signature:



Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile**

MATERIAL LOCATION: **1925 Building- Room 102 & 112**

MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

O&M response action in selective areas of damage only

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>04</b>		
MATERIAL DESCRIPTION:	<b>9"x9" Beige Floor Tile NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 104</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed 2025, Hardwood Floor</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Room 104**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>05</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 113</b>		
MATERIAL QUANTITY:	<b>1150</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2 floor tiles cracked but intact</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**

MATERIAL LOCATION: **1925 Building- Room 113**

MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

O&M response action for selective areas of damage only

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>07</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Brown Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110 &amp; 112</b>		
MATERIAL QUANTITY:	<b>1950</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**

MATERIAL LOCATION: **Room 110 & 112**

MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>08</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Beige with Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 111</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12"x12" Beige with Specks Floor Tile**

MATERIAL LOCATION: **1925 Building- Room 111**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>09</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Brown Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Building- Store Rooms, Eng. Office, 1st &amp; 2nd Floor Corridors</b>		
MATERIAL QUANTITY:	<b>3520</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**

MATERIAL LOCATION: **1974 Building- Store Rooms, Eng. Office, 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **3520** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>12</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Beige Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Building- Room 224 &amp; 228</b>		
MATERIAL QUANTITY:	<b>1950</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**

MATERIAL LOCATION: **1974 Building- Room 224 & 228**

MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>14</b>		
MATERIAL DESCRIPTION:	<b>12"x12" White Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Building- Room 119, 121, Lunchroom, Teachers' Lunchroom &amp; Corridor</b>		
MATERIAL QUANTITY:	<b>5600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damage in Lunchroom but intact</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile**

MATERIAL LOCATION: **1974 Building- Room 119, 121, Lunchroom, Teachers' Lunchroom & Corridor**

MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repair response in selective areas with damage only

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>16</b>		
MATERIAL DESCRIPTION:	<b>Fire Doors</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Boiler Room, Boiler Room Tunnel</b>		
MATERIAL QUANTITY:	<b>2</b>	MATERIAL UNITS:	<b>EA</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **1925 Building- Boiler Room, Boiler Room Tunnel**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Boiler Room Gasket ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Boiler Room**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Boiler Room Gasket ABATED**

MATERIAL LOCATION: **1925 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>18</b>		
MATERIAL DESCRIPTION:	<b>Transite Lab Tables</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 207</b>		
MATERIAL QUANTITY:	<b>30</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Transite Lab Tables**

MATERIAL LOCATION: **1925 Building- Room 207**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>19</b>		
MATERIAL DESCRIPTION:	<b>Baseboard Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- 1st Floor Boys' Toilet &amp; Adjacent Corridor</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:	<b>Hardwood, no baseboards in 115A and 216A</b>		

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **1925 Building- 1st Floor Boys' Toilet & Adjacent Corridor**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1974 Building- Kitchen		
MATERIAL QUANTITY:	2	MATERIAL UNITS:	EA
DAMAGE QUANTITY:		DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **1974 Building- Kitchen**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1974 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Throughout 1974 Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: 

Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>22</b>		
MATERIAL DESCRIPTION:	<b>Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Rooms 115A &amp; 216A</b>		
MATERIAL QUANTITY:	<b>70</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:	<b>Not Observed 2025</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **1925 Building- Rooms 115A & 216A**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Anthophyllite	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1974 Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **Throughout 1974 Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>24</b>		
MATERIAL DESCRIPTION:	<b>9"x9" Beige Floor Tile Mastic NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Physical Damage</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 104</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not OBSERVED 2025. Hardwood Floor</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>25</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Orange Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st &amp; 2nd Floor Corridors</b>		
MATERIAL QUANTITY:	<b>8650</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" Orange Floor Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **8650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>26</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Brown Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 110 &amp; 112</b>		
MATERIAL QUANTITY:	<b>1950</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building- Room 110 & 112**

MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>27</b>		
MATERIAL DESCRIPTION:	<b>12"x12" White Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Building- Room 119, 121, Teachers' Lunchroom, Lunchroom &amp; Corridor</b>		
MATERIAL QUANTITY:	<b>5600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**

MATERIAL LOCATION: **1974 Building- Room 119, 121, Teachers' Lunchroom, Lunchroom & Corridor**

MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUILDING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1974 Building- Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors		
MATERIAL QUANTITY:	3520	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/21/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **1974 Building- Storerooms, Electrical Room, Engineer's Office, 1st & 2nd Floor Corridors**

MATERIAL QUANTITY: **3520** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>29</b>		
MATERIAL DESCRIPTION:	<b>12"x12" White Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Rooms 102 &amp; 112</b>		
MATERIAL QUANTITY:	<b>2250</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building- Rooms 102 & 112**

MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>30</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 113</b>		
MATERIAL QUANTITY:	<b>1150</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building- Room 113**

MATERIAL QUANTITY: **1150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>31</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Medium Brown Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Rooms 111 &amp; 115A</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12"x12" Medium Brown Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building- Rooms 111 & 115A**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>32</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Beige Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Building- Rooms 224 &amp; 228</b>		
MATERIAL QUANTITY:	<b>1950</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **1974 Building- Rooms 224 & 228**

MATERIAL QUANTITY: **1950** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>33</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Purple Floor Tile NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Main Office, Principal's Office</b>		
MATERIAL QUANTITY:	<b>420</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed 2025</b>		

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12"x12" Purple Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Main Office, Principal's Office**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>34</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Purple Floor Tile Mastic NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Main Office, Principal's Office</b>		
MATERIAL QUANTITY:	<b>420</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed 2025</b>		

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12"x12" Purple Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Main Office, Principal's Office**

MATERIAL QUANTITY: **420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>35</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Annex Office</b>		
MATERIAL QUANTITY:	<b>625</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**

MATERIAL LOCATION: **1974 Annex Office**

MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: 

Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>36</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Tan Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Annex Office</b>		
MATERIAL QUANTITY:	<b>625</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **1974 Annex Office**

MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Brown Linoleum NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years, including 2025**

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Brown Linoleum NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years, including 2025**

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic NOT OBSERVED**

MATERIAL LOCATION: **1925 Building- Storeroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>39</b>		
MATERIAL DESCRIPTION:	<b>Purple Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Main Office Storeroom</b>		
MATERIAL QUANTITY:	<b>80</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **1925 Building- Main Office Storeroom**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>40</b>		
MATERIAL DESCRIPTION:	<b>Grey &amp; Blue Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Teachers' Restroom &amp; Room 218</b>		
MATERIAL QUANTITY:	<b>1125</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Grey & Blue Carpet Mastic**

MATERIAL LOCATION: **1925 Building- Teachers' Restroom & Room 218**

MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>41</b>		
MATERIAL DESCRIPTION:	<b>Brown Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Principal's Office, Annex Office</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Principal's Office, Annex Office**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature: 

Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Orange Carpet Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1974 Building- Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2022, 2025**

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Orange Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **1974 Building- Rooms 120, 122, 124, 126, Storeroom & Library; Rooms 217, 219-223, 226, Teachers' Lounge, Library Office & AV Room**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>43</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Beige with Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Room 111</b>		
MATERIAL QUANTITY:	<b>375</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12"x12" Beige with Specks Floor Tile Mastic**

MATERIAL LOCATION: **1925 Building- Room 111**

MATERIAL QUANTITY: **375** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>44</b>		
MATERIAL DESCRIPTION:	<b>Multicolor Carpet Adhesive NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 218</b>		
MATERIAL QUANTITY:	<b>1125</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed 2025</b>		

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Multicolor Carpet Adhesive NOT OBSERVED**

MATERIAL LOCATION: **Room 218**

MATERIAL QUANTITY: **1125** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12"x12" Tan w/Speccks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 124, 126, 219 & 226		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12"x12" Tan w/Specs Floor Tile**

MATERIAL LOCATION: **Rooms 124, 126, 219 & 226**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>46</b>		
MATERIAL DESCRIPTION:	<b>Purple Carpet NOT OBSERVED</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Library</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed 2022, 2025</b>		

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Purple Carpet NOT OBSERVED**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>47</b>		
MATERIAL DESCRIPTION:	<b>2'x4' Ceiling Tile w/Chicken Scratch</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1925 Building- Throughout 1st &amp; 2nd Corridors, and All Classrooms</b>		
MATERIAL QUANTITY:	<b>25000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025- Replaced</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tile w/Chicken Scratch**

MATERIAL LOCATION: **1925 Building- Throughout 1st & 2nd Corridors, and All Classrooms**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>48</b>		
MATERIAL DESCRIPTION:	<b>Hard Coat Plaster</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout 1925 Building</b>		
MATERIAL QUANTITY:	<b>37500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout 1925 Building**

MATERIAL QUANTITY: **37500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1974 Building		
MATERIAL QUANTITY:	37500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout 1974 Building**

MATERIAL QUANTITY: **37500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>50</b>		
MATERIAL DESCRIPTION:	<b>12x12 Dark Brown Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Restroom and Rooms 115B and 215B</b>		
MATERIAL QUANTITY:	<b>474</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12x12 Dark Brown Floor Tile**

MATERIAL LOCATION: **1st Floor Restroom and Rooms 115B and 215B**

MATERIAL QUANTITY: **474** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>51</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Dark Brown Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Restroom and Rooms 115B and 215B</b>		
MATERIAL QUANTITY:	<b>474</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12"x12" Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Restroom and Rooms 115B and 215B**

MATERIAL QUANTITY: **474** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>52</b>		
MATERIAL DESCRIPTION:	<b>1'x1' Acoustical Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 213</b>		
MATERIAL QUANTITY:	<b>38</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Tile**

MATERIAL LOCATION: **Room 213**

MATERIAL QUANTITY: **38** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>53</b>		
MATERIAL DESCRIPTION:	<b>1'x1' Acoustical Ceiling Tile Glue Dots</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 213</b>		
MATERIAL QUANTITY:	<b>38</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **1'x1' Acoustical Ceiling Tile Glue Dots**

MATERIAL LOCATION: **Room 213**

MATERIAL QUANTITY: **38** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>54</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Light Beige w/Tan Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 208</b>		
MATERIAL QUANTITY:	<b>725</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12"x12" Light Beige w/Tan Specks Floor Tile**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12"x12" Light Beige w/Tan Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 208		
MATERIAL QUANTITY:	725	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12"x12" Light Beige w/Tan Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 208**

MATERIAL QUANTITY: **725** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>56</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Light Blue Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112 &amp; 113</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12"x12" Light Blue Floor Tile**

MATERIAL LOCATION: **Rooms 112 & 113**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>56A</b>		
MATERIAL DESCRIPTION:	<b>Mastic associated with 12"x12" Light Blue Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112 &amp; 113</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **56A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Light Blue Floor Tile**

MATERIAL LOCATION: **Rooms 112 & 113**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>57</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Dark Blue Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112 &amp; 113</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12"x12" Dark Blue Floor Tile**

MATERIAL LOCATION: **Rooms 112 & 113**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>57A</b>		
MATERIAL DESCRIPTION:	<b>Mastic associated with 12"x12" Dark Blue Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112 &amp; 113</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **57A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Dark Blue Floor Tile**

MATERIAL LOCATION: **Rooms 112 & 113**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>58</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Beige w/Speccks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 111, 112, 113 &amp; 119</b>		
MATERIAL QUANTITY:	<b>1800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12"x12" Beige w/Specs Floor Tile**

MATERIAL LOCATION: **Rooms 111, 112, 113 & 119**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>58A</b>		
MATERIAL DESCRIPTION:	<b>Mastic associated with 12"x12" Beige w/Specs Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 111, 112, 113 &amp; 119</b>		
MATERIAL QUANTITY:	<b>1800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **58A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Beige w/Speccks Floor Tile**

MATERIAL LOCATION: **Room 111, 112, 113 & 119**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>59</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Brown w/Speccks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12"x12" Brown w/Speccks Floor Tile**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>59A</b>		
MATERIAL DESCRIPTION:	<b>Mastic associated with 12"x12" Brown w/Speccks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **59A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Brown w/Specs Floor Tile**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>60</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Cream w/Black Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 121</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025- Description Changed</b>		

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12"x12" Cream w/Black Specks Floor Tile**

MATERIAL LOCATION: **Room 121**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>60A</b>		
MATERIAL DESCRIPTION:	<b>Mastic associated w/12"x12" Cream w/Black Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 121</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>2025- Description Changed</b>		

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **60A**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Cream w/Black Specks Floor Tile**

MATERIAL LOCATION: **Room 121**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>61</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Ash Blue w/Speccks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office &amp; Principal's Office</b>		
MATERIAL QUANTITY:	<b>1600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12"x12" Ash Blue w/Specs Floor Tile**

MATERIAL LOCATION: **Main Office & Principal's Office**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>61A</b>		
MATERIAL DESCRIPTION:	<b>Mastic associated with 12"x12" Ash Blue w/Speccks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office &amp; Principal's Office</b>		
MATERIAL QUANTITY:	<b>1600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **61A**

MATERIAL DESCRIPTION: **Mastic associated with 12"x12" Ash Blue w/Specs Floor Tile**

MATERIAL LOCATION: **Main Office & Principal's Office**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUILDING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Deterioration Delamination		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:	Deterioration Delamination		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Basement, Open Crawlspaces		
MATERIAL QUANTITY:	MATERIAL UNITS:		LF
DAMAGE QUANTITY:	DAMAGE UNITS:		LF
COMMENTS:	Partially Abated in August 2023		

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

**TEM Environmental, Inc.**  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

## HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1925 Building- Basement, Open Crawlspaces**

**MATERIAL QUANTITY:**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY: 0

DAMAGE UNITS: LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

## Repair

### Comments:

Management Planner's Signature:



Date: 06/12/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Paper Wrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1925 Building- Basement Crawlspace, Boys' & Girls Bathroom, Pipe Chases Throughout		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Paper Wrap Pipe Insulation**

MATERIAL LOCATION: **1925 Building- Basement Crawlspace, Boys' & Girls Bathroom, Pipe Chases Throughout**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Aircell Duct Insulation NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Chrysotile** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Wall, Crawlspace**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS: **Not Observed 2025. Partially Abated August 2023**

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Aircell Duct Insulation NOT OBSERVED**

MATERIAL LOCATION: **Wall, Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Tank Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>F</b>		
MATERIAL DESCRIPTION:	<b>Fittings on Fiberglass</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1974 Building- Compactor Room</b>		
MATERIAL QUANTITY:	<b>1</b>	MATERIAL UNITS:	<b>FITTING</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Fittings on Fiberglass**

MATERIAL LOCATION: **1974 Building- Compactor Room**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Fittings on Paper Wrap		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building- Basement Crawlspaces, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Fittings on Paper Wrap**

MATERIAL LOCATION: **1925 Building- Basement Crawlspaces, Boys' & Girls' Bathrooms, Pipe Chases Throughout Building**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Fittings on Aircell		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1925 Building- Crawlspace**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **2025-Partially Abated August 2023**

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Fittings on Aircell**

MATERIAL LOCATION: **1925 Building- Crawlspace**

MATERIAL QUANTITY: MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Incinerator Insulation (ABATED 1990)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1925 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

*Mary Hicks*

Date: **05/21/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Incinerator Insulation (ABATED 1990)**

MATERIAL LOCATION: **1925 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>K</b>		
MATERIAL DESCRIPTION:	<b>Whiteboard Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout</b>		
MATERIAL QUANTITY:	<b>750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Whiteboard Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Old Chalkboards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout School		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUILDING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:	<b>6/12/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Old Chalkboards**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Mary Hicks</b>		
SCHOOL NAME:	<b>Cook School</b>	INSPECTION DATE:	<b>5/21/2025</b>		
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:	<b>100-04437</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>NEW</b>		
MATERIAL DESCRIPTION:	<b>Newly Installed Suspect ACM</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/21/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22801</b>	BUIDLING ID:	<b>2860</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Daniel Juneau</b>		
SCHOOL NAME:	<b>Cook School</b>	REVIEW DATE:		<b>6/12/2025</b>	
ADDRESS:	<b>8150 S. Bishop</b>	IDPH LICENSE NO:		<b>100-04437</b>	

## HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

**Installed After Implementation of Management Plan and After Renovations**

**MATERIAL QUANTITY:**

## MATERIAL UNITS:

**DAMAGE QUANTITY:**

**DAMAGE UNITS:**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

## Follow O&M Plan

### Comments:

Management Planner's Signature:



Date: 06/12/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	62M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Cream w/Blue Specks Floor Tile				
MATERIAL LOCATION:	Room 121				
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:

*Mary Hicks*

Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Cook School** REVIEW DATE: **6/12/2025**

ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **62M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Cream w/Blue Specks Floor Tile**

MATERIAL LOCATION: **Room 121**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/12/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22801	BUIDLING ID:	2860
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Mary Hicks		
SCHOOL NAME:	Cook School	INSPECTION DATE:	5/21/2025		
ADDRESS:	8150 S. Bishop	IDPH LICENSE NO:	100-04437		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12"x12" Cream w/Blue Specks Floor Tile		
MATERIAL LOCATION:	Room 121		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/21/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22801** BUIDLING ID: **2860**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Daniel Juneau**

SCHOOL NAME: **Cook School** REVIEW DATE: **6/12/2025**

ADDRESS: **8150 S. Bishop** IDPH LICENSE NO: **100-04437**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12"x12" Cream w/Blue Specks Floor Tile**

MATERIAL LOCATION: **Room 121**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/12/2025**

**Chicago Public Schools**


**TEM Environmental, Inc.**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/19/2026
MANAGEMENT PLANNER	2/21/2026
PROJECT MANAGER	4/1/2025
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action.**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that MARY HICKS has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the examination on 03/19/2025 with a minimum score of 70% or better. Training was in accordance with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

Course Dates:  
03/19/2025

Expires:  
03/19/2026

Certificate Number:  
2503BIR03

Phone: 312-491-0081

Director of Training  
Nicholas J. Penef

FORM # A-010B

Doctor of Public Health

A handwritten signature in black ink, appearing to read 'Nicholas J. Penef'.



**TEM ENVIRONMENTAL, INC.**  
ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
**100 - 03613**

ISSUED  
**3/1/2022**

EXPIRES  
**05/15/2023**

DANIEL J JUNEAU  
1408 OAKWOOD AVENUE  
DES PLAINES, IL 60016

Environmental Health



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

11/19/2022

MANAGEMENT PLANNER

11/19/2022

PROJECT MANAGER

11/1/2022

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**DANIEL J JUNEAU**  
1408 OAKWOOD AVENUE  
DES PLAINES, IL 60016

4/3/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 03613

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

Front of License		Back of License	
	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER 100 - 03613	ISSUED 4/3/2024	EXPIRES 05/15/2025	INSPECTOR 11/3/2024
<b>DANIEL J JUNEAU</b> 1408 OAKWOOD AVENUE DES PLAINES, IL 60016 Environmental Health			MANAGEMENT PLANNER 11/3/2024 PROJECT MANAGER 11/7/2024 AIR SAMPLING PROFESSIONAL
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

DANIEL J JUNEAU  
1408 OAKWOOD AVENUE  
DES PLAINES, IL 60016

5/8/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 03613

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 03613</b>	ISSUED <b>5/8/2025</b>	EXPIRES <b>05/15/2026</b>	INSPECTOR	11/1/2025
DANIEL J JUNEAU 1408 OAKWOOD AVENUE DES PLAINES, IL 60016 Environmental Health			MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	11/1/2025 11/13/2025
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Dan Juneau**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2024

Exam Date: 11/1/2024

Expiration Date: 11/1/2025

Certificate Number: BIR2411013089

Course Credit Hours: BIR 4 Hours

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2024

Exam Date: 11/1/2024

Expiration Date: 11/1/2025

Certificate Number: MPR2411013107

Course Credit Hours: MPR 4 Hours

A handwritten signature in blue ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed