

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2148  
SCHOOL NAME: Darwin School  
ADDRESS OF SCHOOL: 3116 W. Belden Avenue  
CITY: Chicago, IL, 60647

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/14/2022

If the address on this form is different than the address of the building, submit a written explanation.

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/16/2025 ENROLLMENT 529  
IDPH INSPECTOR LICENSE NUMBER: 100-11255  
IDPH LICENSED INSPECTOR NAME (Please Print): Esteban Nunez  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 5/6/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Darwin School**

3116 W. Belden Avenue  
Chicago, IL, 60647

Unit: 22881  
Building ID: 2960

IDPH ID Number: 14-016-2990-2148

**REPORT DATE:**  
Tuesday, May 06, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Specialty Consulting, Inc.**

2942 W. Van Buren Street  
Chicago, IL, 60612  
Phone (312) 319-7575  
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

05/06/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 22881      Region: 02      IDPH ID: 14-016-2990-2148

School: Darwin School      Building ID: 2960

Address: 3116 W. Belden Avenue

Chicago, IL, 60647

Building Contact: Mahoney, Kevin      Contact Phone: 8722275355

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/16/2025

Review Date: 05/06/2025

Inspector: Esteban Nunez

Inspector IDPH License: 100-11255

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 06, 2025

RE: Darwin School, Unit 22881  
3116 W. Belden Avenue  
Chicago, IL, 60647

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Darwin School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Darwin School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Darwin School      Unit: 22881      Region: 02  
Address: 3116 W. Belden Avenue      Chicago, IL, 60647  
IDPH ID: 14-016-2990-2148      Building ID: 2960  
Contact: Mahoney, Kevin      Phone: 8722275355

### 2. Description of Facility

Original Construction: 1920      Additional Construction: 1900  
Total Square Footage: 38126      No of Floors: 3  
Current Occupancy: 529

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575      Fax: (312) 319-7580

### 5. Inspector

Inspector Name: Esteban Nunez

Inspector IDPH license # 100-11255  
Reinspection Date: 4/16/2025




Signature:  
Date: 4/16/2025

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342




Signature:  
Date: 05/06/2025

### 7. Review Date: 05/06/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/6/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Darwin School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 2960:

82M	12"x12" Dark Blue VFT Mastic
-----	------------------------------

B. The following new homogenous areas have been identified for Building 2960:

76	12"x12" Gray w/ Specs Replacement VFT
76M	12"x12" Gray w/ Specs Replacement VFT Mastic
77	12"x12" White w/ Gray Specs VFT
77M	12"x12" White w/ Gray Specs VFT Mastic
78	12"x12" Beige w/ Tan Specs Replacement VFT
78M	12"x12" Beige w/ Tan Specs Replacement VFT Mastic
79	12"x12" Dark Green VFT
79M	12"x12" Dark Green VFT
80	12"x12" Light Green VFT
80M	12"x12" Light Green VFT Mastic
81	12"x12" Light Blue VFT
81M	12"x12" Light Blue VFT and Mastic
82	12"x12" Dark Blue VFT
82M	12"x12" Dark Blue VFT Mastic
83	12"x12" White w/ Blue Specs VFT
83M	12"x12" White w/ Blue Specs VFT Mastic
84	12"x12" Beige & Tan Replacement VFT
84M	12"x12" Beige & Tan VFT Mastic
85	12"x12" Gray w/ White Specs Replacement VFT
85M	12"x12" Gray w/ White Specs Replacement VFT Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	Plaster Walls and Ceilings
09	1'x1' Ceiling Tile
34	12"x12" Brown Floor Tile
35	12"x12" Brown Floor Tile Mastic
36	12"x12" Off White Floor Tile
38	12"x12" Dark Brown Floor Tile
39	12"x12" Dark Brown Floor Tile Mastic
40	12"x12" Beige Floor Tile
41	12"x12" Beige Floor Tile Mastic
44	12"x12" Black Floor Tile
48	12"x12" White w/ Gray Streaks Floor Tile
49	12"x12" White w/ Gray Streaks Floor Tile Mastic
50	9"x9" Floor Tile (Painted Black)
50M	9"x9" Black Floor Tile Mastic
51	Carpet Adhesive
52	12"x12" Floor Tile (Painted Black)
53	12"x12" Black Floor Tile Mastic
54	Carpet Adhesive
55	Carpet Adhesive
56	Red Linoleum
56M	Red Linoleum Adhesive
57	12"x12" White w/Multi-colored Specks Floor Tile
58	12"x12" White w/Multi-colored Specks Floor Tile Mastic
59	12"x12" Grey w/Specs Floor Tile
60	12"x12" Grey w/Specs Floor Tile Mastic
61	Sink Undercoating
62	Acoustical Plaster
63	12"x12" Gray w/ White Specs VFT
64	12"x12" Gray w/ White Specs Mastic
65	Carpet Mastic (Tile Carpet)
66	12"x12" White w/ black specs VFT
67	12"x12" White w/ Black specs Mastic
68	12"x12" Gray w/ white specs VFT
69	12"x12" Gray W/ white specs Mastic
70	Carpet Mastic
71	12"x12" White w/ beige specs VFT
72	12"x12" White w/ Beige specs Mastic
75	12"x12" White VFT
75M	12"x12" White VFT Mastic
76	12"x12" Gray w/ Specs Replacement VFT
76M	12"x12" Gray w/ Specs Replacement VFT Mastic

77	12"x12" White w/ Gray Specs VFT
77M	12"x12" White w/ Gray Specs VFT Mastic
78	12"x12" Beige w/ Tan Specs Replacement VFT
78M	12"x12" Beige w/ Tan Specs Replacement VFT Mastic
79	12"x12" Dark Green VFT
79M	12"x12" Dark Green VFT
80	12"x12" Light Green VFT
80M	12"x12" Light Green VFT Mastic
81	12"x12" Light Blue VFT
81M	12"x12" Light Blue VFT and Mastic
82	12"x12" Dark Blue VFT
82M	12"x12" Dark Blue VFT Mastic
83	12"x12" White w/ Blue Specs VFT
83M	12"x12" White w/ Blue Specs VFT Mastic
84	12"x12" Beige & Tan Replacement VFT
84M	12"x12" Beige & Tan VFT Mastic
85	12"x12" Gray w/ White Specs Replacement VFT
85M	12"x12" Gray w/ White Specs Replacement VFT Mastic

The following areas were deemed to be inaccessible:

45	12"x12" Black Floor Tile Mastic
50M	9"x9" Black Floor Tile Mastic
51	Carpet Adhesive
53	12"x12" Black Floor Tile Mastic
54	Carpet Adhesive
55	Carpet Adhesive
56M	Red Linoleum Adhesive
58	12"x12" White w/Multi-colored Specks Floor Tile Mastic
60	12"x12" Grey w/Specks Floor Tile Mastic
64	12"x12" Gray w/ White Specs Mastic
65	Carpet Mastic (Tile Carpet)
67	12"x12" White w/ Black specs Mastic
69	12"x12" Gray W/ white specs Mastic
72	12"x12" White w/ Beige specs Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Esteban Nunez, IDPH License # 100-11255. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 6/26/2025

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Darwin School Building 2960 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	Plaster Walls and Ceilings	144,908	SF	Throughout Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
03	12"x12" Tan w/ White Streaks Floor Tile	11,000	SF	Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899  (Rooms: 002, 107, 108, 210, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)	CHR	MISC	N	NONE			No	ACBM with the potential for damage		MODERATE
08	12"x12" Light Brown Floor Tile	4,000	SF	Throughout Modular (See Hatching Maps)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
09	1'x1' Ceiling Tile	4,000	SF	1st & 2nd Floor Corridor, and lunchroom - 1919	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" Tan w/ White Streaks Floor Tile Mastic	11,000	SF	Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899  (Rooms: 002, 210, 304, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	1'x1' Ceiling Tile Mastic			1st & 2nd Floor Corridor, and lunchroom - 1919	NO_ACBM						No			
16	Vinyl Baseboard Mastic			Throughout - 1899	NO_ACBM						No			
17	Wall Board			Throughout Classrooms - 1899	NO_ACBM						No			
18	12"x12" Light Brown Floor Tile Mastic	4,000	SF	Throughout Modular (See Hatching Maps)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	1'x1' Ceiling Tile Mastic			Throughout Modular	NO_ACBM						No			
20	Vinyl Baseboard Mastic			Throughout Modular	NO_ACBM						No			

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
21	Wall Board			Throughout Modular	NO_ACBM						No			
24	Vinyl Baseboard			Throughout - 1899	NO_ACBM						No			
25	Wall Joint Compound			Throughout - 1899	NO_ACBM						No			
26	Vinyl Baseboard			Throughout Modular	NO_ACBM						No			
27	Wall Joint Compound			Throughout Modular	NO_ACBM						No			
30	12"x12" Tan w/ White Streaks Floor Tile	2,100	SF	Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
31	12"x12" Tan w/ White Streaks Floor Tile mastic	2,100	SF	Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Vinyl Baseboard			Throughout - 1919	NO_ACBM						No			
33	Vinyl Baseboard Mastic			Throughout - 1919	NO_ACBM						No			
34	12"x12" Brown Floor Tile	300	SF	Rooms: 210 - 1899  (Rooms: 206, 305 Ward, 306 Ward NOT OBSERVED)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
35	12"x12" Brown Floor Tile Mastic	300	SF	Rooms: 210 - 1899  (Rooms: 206, 306 Ward NOT OBSERVED)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12"x12" Off White Floor Tile	2,000	SF	Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899  (Rooms: 205 Ward NOT OBSERVED)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
37	12"x12" Off White Floor Tile Mastic	2,000	SF	Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899  (Rooms: 205 Ward NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	12"x12" Dark Brown Floor Tile	1,200	SF	Rooms 308B, & 310A - 1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
39	12"x12" Dark Brown Floor Tile Mastic	1,200	SF	Rooms 308B & 310A - 1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12"x12" Beige Floor Tile	1,100	SF	3rd Floor Corridor - 1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
41	12"x12" Beige Floor Tile Mastic	1,100	SF	3rd Floor Corridor -	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				1899										
42	12"x12" Orange Floor Tile			Front of Room 003 - 1899 (Not Observed)	ABATED						No			
43	12"x12" Orange Floor Tile Mastic			Front of Room 003 - 1899 - (Not Observed)	ABATED	MISC			0					
44	12"x12" Black Floor Tile	70	SF	Bottom of Room 003 Stairs - 1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
45	12"x12" Black Floor Tile Mastic	70	SF	Bottom of Room 003 Stairs - 1899	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	Exterior Window Caulk			Modular	NO_ACBM						No			
47	Exterior Window Glaze			Modular	NO_ACBM						No			
48	12"x12" White w/ Gray Streaks Floor Tile	1,500	SF	Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
49	12"x12" White w/ Gray Streaks Floor Tile Mastic	1,500	SF	Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	9"x9" Floor Tile (Painted Black)	95	SF	1899 Bldg: Corridor by Room 002	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
50M	9"x9" Black Floor Tile Mastic	95	SF	1899 Bldg: Corridor by Room 002	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Carpet Adhesive	3,000	SF	1899 Bldg: Room 003, Room 012 (Library), Room 023, Engineer's office, 104  (Basement Corridor - NOT OBSERVED)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Floor Tile (Painted Black)	75	SF	1899 Bldg: 1st Floor Women's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53	12"x12" Black Floor Tile Mastic	75	SF	1899 Bldg: 1st Floor Women's Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Carpet Adhesive	700	SF	1919 Bldg: Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Carpet Adhesive	1,400	SF	1919 Bldg: Assembly Hall Balcony and Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
56	Red Linoleum	500	SF	Room 410 (Pantry) - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56M	Red Linoleum Adhesive	500	SF	Room 410 (Pantry) - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12"x12" White w/Multi-colored Specks Floor Tile	300	SF	Office Room (416), 504, 501, 401 - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58	12"x12" White w/Multi-colored Specks Floor Tile Mastic	300	SF	Office Room (416) - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12"x12" Grey w/Specs Floor Tile	25	SF	Room 401 Modular--NOT OBSERVED, room 210 (1899 building)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
60	12"x12" Grey w/Specs Floor Tile Mastic	25	SF	Room 501 MODULAR-- NOT OBSERVED	ASSUMED	MISC	N		0		No	ACBM with the potential for damage		LOW
61	Sink Undercoating	3	SF	Room 501 MODULAR--NOT OBSERVED	ASSUMED	MISC	N		0		No	ACBM with the potential for damage		
62	Acoustical Plaster	2,000	SF	Auditorium and Balcony	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
63	12"x12" Gray w/ White Specs VFT	1,330	SF	Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112-1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
64	12"x12" Gray w/ White Specs Mastic	1,330	SF	Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112-1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Carpet Mastic (Tile Carpet)	2,000	SF	Library- 1919	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	12"x12" White w/ black specs VFT	2,800	SF	Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
67	12"x12" White w/ Black specs Mastic	2,800	SF	Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	12"x12" Gray w/ white specs VFT	1,600	SF	413, corridor oustise of 413, 510-- Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
69	12"x12" Gray W/ white specs Mastic	1,600	SF	413, corridor outside of 413, 510--	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Modular										
70	Carpet Mastic	1,500	SF	Rooms 408 and 508- Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12"x12" White w/ beige specs VFT	1,200	SF	Rooms 514, 502, 402, 408, 110, 308--modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
72	12"x12" White w/ Beige specs Mastic	1,200	SF	Rooms 514, 502, 402, 408, 110, 308--modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	12"x12" White w/ gray specks VFT			Rooms 402, 502 (ABATED 2018) - Modular	ABATED	MISC			0					
74	12"x12" White w/Gray Specs VFT Mastic			Rooms 402, 502 (ABATED 2018) - Modular	ABATED	MISC			0					
75	12"x12" White VFT	2,000	SF	Rooms 402 and 502 - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
75M	12"x12" White VFT Mastic	2,000	SF	Rooms 402 and 502 - Modular	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	12"x12" Gray w/ Specs Replacement VFT	30	SF	Room 112 - 1899 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
76M	12"x12" Gray w/ Specs Replacement VFT Mastic	30	SF	Room 112 - 1899 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	12"x12" White w/ Gray Specs VFT	1,800	SF	Rooms 208 and 308 - 1899 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
77M	12"x12" White w/ Gray Specs VFT Mastic	1,800	SF	Rooms 208 and 308 - 1899 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12"x12" Beige w/ Tan Specs Replacement VFT	5	SF	3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
78M	12"x12" Beige w/ Tan Specs Replacement VFT Mastic	5	SF	3rd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	12"x12" Dark Green VFT	120	SF	Rooms 504 and 506 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
79M	12"x12" Dark Green VFT	120	SF	Rooms 504 and 506 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	12"x12" Light Green VFT	120	SF	Rooms 504 and 506 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
80M	12"x12" Light Green VFT Mastic	120	SF	Rooms 504 and 506 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	12"x12" Light Blue VFT	150	SF	Rooms 501 and 505 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
81M	12"x12" Light Blue VFT and Mastic	150	SF	Rooms 501 and 505 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	12"x12" Dark Blue VFT	150	SF	Rooms 501 and 505	ASSUMED	MISC	N	NONE	0		No	ACBM with the		MODERATE

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				- Modular Building								potential for damage		
82M	12"x12" Dark Blue VFT Mastic	150	SF	Rooms 501 and 505 - Modular Building	ASSUMED	MISC	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
83	12"x12" White w/ Blue Specs VFT	3,200	SF	Rooms 501, 504, 505, and 506 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
83M	12"x12" White w/ Blue Specs VFT Mastic	3,200	SF	Rooms 501, 504, 505, and 506 - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with potential for significant damage		LOW
84	12"x12" Beige & Tan Replacement VFT	30	SF	1st and 2nd Floor Corridors - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
84M	12"x12" Beige & Tan VFT Mastic	30	SF	1st and 2nd Floor Corridors - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
85	12"x12" Gray w/ White Specs Replacement VFT	200	SF	1st and 2nd Floor Corridors - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
85M	12"x12" Gray w/ White Specs Replacement VFT Mastic	200	SF	1st and 2nd Floor Corridors - Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boiler & Tank Mag Block Insulation (Abated 7/23/09)			Boiler Room - 1899	ABATED	TSI								
B	MJP on Fiberglass Pipe Insulation	610	FITTING	Engineer's Office, Teacher Lunch Area & 012 A & B, 001, 003 - 1899	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
C	Cardboard Pipe Insulation			Engine Room, 003, Tank Room - 1899 (ABATED)	NO_ACBM	TSI								
D	Aircell Pipe Insulation	60	LF	Engineer's Restroom, Rooms 001-003, 012 A & B - 1899	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
F	MJP on Cardboard Pipe Insulation			South Dressing Room	ABATED	TSI								
G	MJP on Aircell Pipe Insulation	130	FITTING	Engineer's Restroom, Rooms 001-003, 012 A & B - 1899	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
H	MJP on Fiberglass Pipe Insulation			1st, 2nd, 3rd, & Basement Toilets, basement custodian storage - 1919	NO_ACBM						No			

Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC) Specialty Consulting, Inc.**

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

School Darwin School Unit 22881 Building ID 2960  
Address 3116 W. Belden Avenue Region 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>4/16/2025</u>
Inspector Name	<u>Esteban Nunez</u>
<b>100-11255</b>	<b>5/15/2026</b>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
01	
03	Not observed in Room 306 and 112
08	
09	
13	not observed in Room 306 and 112
14	
16	
17	
18	
19	
20	
21	
24	
25	
26	
27	
30	
31	
32	
33	
34	
35	
36	
37	

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
50M	
51	
52	
53	
54	
55	
56	
56M	
57	
58	
59	
60	
61	
62	
63	
64	

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
75M	
76	
76M	
77	
77M	
78	
78M	
79	
79M	
80	
80M	
81	
81M	
82	
82M	
83	
83M	
84	

# Chicago Public Schools

**School** Darwin School **Unit** 22881 **Building ID** 2960  
**Address** 3116 W. Belden Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
84M	
85	
85M	
A	
B	
C	
D	
F	
G	
H	
I	
J	
K	
L	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	Plaster Walls and Ceilings	144,908	SF	Throughout Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	12"x12" Tan w/ White Streaks Floor Tile	11,000	SF	Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899  (Rooms: 002, 107, 108, 210, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Light Brown Floor Tile	4,000	SF	Throughout Modular (See Hatching Maps)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	1'x1' Ceiling Tile	4,000	SF	1st & 2nd Floor Corridor, and lunchroom - 1919	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Tan w/ White Streaks Floor Tile Mastic	11,000	SF	Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899  (Rooms: 002, 210, 304, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	1'x1' Ceiling Tile Mastic			1st & 2nd Floor Corridor, and lunchroom - 1919	No ACBM						
16	Vinyl Baseboard Mastic			Throughout - 1899	No ACBM						
17	Wall Board			Throughout Classrooms - 1899	No ACBM						
18	12"x12" Light Brown Floor Tile Mastic	4,000	SF	Throughout Modular (See Hatching Maps)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	1'x1' Ceiling Tile Mastic			Throughout Modular	No ACBM						
20	Vinyl Baseboard Mastic			Throughout Modular	No ACBM						
21	Wall Board			Throughout Modular	No ACBM						
24	Vinyl Baseboard			Throughout - 1899	No ACBM						
25	Wall Joint Compound			Throughout - 1899	No ACBM						
26	Vinyl Baseboard			Throughout Modular	No ACBM						
27	Wall Joint Compound			Throughout Modular	No ACBM						
30	12"x12" Tan w/ White Streaks Floor Tile	2,100	SF	Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Tan w/ White Streaks Floor Tile mastic	2,100	SF	Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575      Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	Vinyl Baseboard			Throughout - 1919	No ACBM						
33	Vinyl Baseboard Mastic			Throughout - 1919	No ACBM						
34	12"x12" Brown Floor Tile	300	SF	Rooms: 210 - 1899  (Rooms: 206, 305 Ward, 306 Ward NOT OBSERVED)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12"x12" Brown Floor Tile Mastic	300	SF	Rooms: 210 - 1899  (Rooms: 206, 306 Ward NOT OBSERVED)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Off White Floor Tile	2,000	SF	Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899  (Rooms: 205 Ward NOT OBSERVED)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Off White Floor Tile Mastic	2,000	SF	Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899  (Rooms: 205 Ward NOT OBSERVED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12"x12" Dark Brown Floor Tile	1,200	SF	Rooms 308B, & 310A - 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12"x12" Dark Brown Floor Tile Mastic	1,200	SF	Rooms 308B & 310A - 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" Beige Floor Tile	1,100	SF	3rd Floor Corridor - 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12"x12" Beige Floor Tile Mastic	1,100	SF	3rd Floor Corridor - 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12"x12" Orange Floor Tile			Front of Room 003 - 1899 (Not Observed)	Abated						
43	12"x12" Orange Floor Tile Mastic			Front of Room 003 - 1899 - (Not Observed)	Abated	MISC		0			Follow O&M Plan
44	12"x12" Black Floor Tile	70	SF	Bottom of Room 003 Stairs - 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12"x12" Black Floor Tile Mastic	70	SF	Bottom of Room 003 Stairs - 1899	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Exterior Window Caulk			Modular	No ACBM						
47	Exterior Window Glaze			Modular	No ACBM						
48	12"x12" White w/ Gray Streaks Floor Tile	1,500	SF	Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12"x12" White w/ Gray Streaks Floor Tile Mastic	1,500	SF	Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	9"x9" Floor Tile (Painted Black)	95	SF	1899 Bldg: Corridor by Room 002	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50M	9"x9" Black Floor Tile Mastic	95	SF	1899 Bldg: Corridor by Room 002	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
51	Carpet Adhesive	3,000	SF	1899 Bldg: Room 003, Room 012 (Library), Room 023, Engineer's office, 104  (Basement Corridor - NOT OBSERVED)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Floor Tile (Painted Black)	75	SF	1899 Bldg: 1st Floor Women's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Black Floor Tile Mastic	75	SF	1899 Bldg: 1st Floor Women's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Carpet Adhesive	700	SF	1919 Bldg: Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Carpet Adhesive	1,400	SF	1919 Bldg: Assembly Hall Balcony and Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Red Linoleum	500	SF	Room 410 (Pantry) - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56M	Red Linoleum Adhesive	500	SF	Room 410 (Pantry) - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12"x12" White w/Multi-colored Specks Floor Tile	300	SF	Office Room (416), 504, 501, 401 - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"x12" White w/Multi-colored Specks Floor Tile Mastic	300	SF	Office Room (416) - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12"x12" Grey w/Specs Floor Tile	25	SF	Room 401 Modular--NOT OBSERVED, room 210 (1899 building)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12"x12" Grey w/Specs Floor Tile Mastic	25	SF	Room 501 MODULAR-- NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Sink Undercoating	3	SF	Room 501 MODULAR--NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Acoustical Plaster	2,000	SF	Auditorium and Balcony	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12"x12" Gray w/ White Specs VFT	1,330	SF	Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112- 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12"x12" Gray w/ White Specs Mastic	1,330	SF	Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112- 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Carpet Mastic (Tile Carpet)	2,000	SF	Library- 1919	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12"x12" White w/ black specs VFT	2,800	SF	Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	12"x12" White w/ Black specs Mastic	2,800	SF	Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12"x12" Gray w/ white specs VFT	1,600	SF	413, corridor outside of 413, 510--	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Modular							
69	12"x12" Gray W/ white specs Mastic	1,600	SF	413, corridor outside of 413, 510-- Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Carpet Mastic	1,500	SF	Rooms 408 and 508-- Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12"x12" White w/ beige specs VFT	1,200	SF	Rooms 514, 502, 402, 408, 110, 308-- modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12"x12" White w/ Beige specs Mastic	1,200	SF	Rooms 514, 502, 402, 408, 110, 308-- modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12"x12" White w/ gray specks VFT			Rooms 402, 502 (ABATED 2018) - Modular	Abated	MISC		0			Follow O&M Plan
74	12"x12" White w/Gray Specs VFT Mastic			Rooms 402, 502 (ABATED 2018) - Modular	Abated	MISC		0			Follow O&M Plan
75	12"x12" White VFT	2,000	SF	Rooms 402 and 502 - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75M	12"x12" White VFT Mastic	2,000	SF	Rooms 402 and 502 - Modular	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12"x12" Gray w/ Specs Replacement VFT	30	SF	Room 112 - 1899 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76M	12"x12" Gray w/ Specs Replacement VFT Mastic	30	SF	Room 112 - 1899 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12"x12" White w/ Gray Specs VFT	1,800	SF	Rooms 208 and 308 - 1899 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77M	12"x12" White w/ Gray Specs VFT Mastic	1,800	SF	Rooms 208 and 308 - 1899 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12"x12" Beige w/ Tan Specs Replacement VFT	5	SF	3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78M	12"x12" Beige w/ Tan Specs Replacement VFT Mastic	5	SF	3rd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12"x12" Dark Green VFT	120	SF	Rooms 504 and 506 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79M	12"x12" Dark Green VFT	120	SF	Rooms 504 and 506 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12"x12" Light Green VFT	120	SF	Rooms 504 and 506 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80M	12"x12" Light Green VFT Mastic	120	SF	Rooms 504 and 506 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12"x12" Light Blue VFT	150	SF	Rooms 501 and 505 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81M	12"x12" Light Blue VFT and Mastic	150	SF	Rooms 501 and 505 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12"x12" Dark Blue VFT	150	SF	Rooms 501 and 505 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
82M	12"x12" Dark Blue VFT Mastic	150	SF	Rooms 501 and 505 - Modular Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12"x12" White w/ Blue Specs VFT	3,200	SF	Rooms 501, 504, 505, and 506 - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83M	12"x12" White w/ Blue Specs VFT Mastic	3,200	SF	Rooms 501, 504, 505, and 506 - Modular Building	Assumed	MISC	No	0	SF	5 ACBM with potential for significant damage	Follow O&M Plan
84	12"x12" Beige & Tan Replacement VFT	30	SF	1st and 2nd Floor Corridors - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575      Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
84M	12"x12" Beige & Tan VFT Mastic	30	SF	1st and 2nd Floor Corridors - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12"x12" Gray w/ White Specs Replacement VFT	200	SF	1st and 2nd Floor Corridors - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85M	12"x12" Gray w/ White Specs Replacement VFT Mastic	200	SF	1st and 2nd Floor Corridors - Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler & Tank Mag Block Insulation (Abated 7/23/09)			Boiler Room - 1899	Abated	TSI					
B	MJP on Fiberglass Pipe Insulation	610	FITTING	Engineer's Office, Teacher Lunch Area & 012 A & B, 001, 003 - 1899	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
C	Cardboard Pipe Insulation			Engine Room, 003, Tank Room - 1899 (ABATED)	No ACBM	TSI					
D	Aircell Pipe Insulation	60	LF	Engineer's Restroom, Rooms 001-003, 012 A & B - 1899	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP on Cardboard Pipe Insulation			South Dressing Room	Abated	TSI					
G	MJP on Aircell Pipe Insulation	130	FITTING	Engineer's Restroom, Rooms 001-003, 012 A & B - 1899	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
H	MJP on Fiberglass Pipe Insulation			1st, 2nd, 3rd, & Basement Toilets, basement custodian storage - 1919	No ACBM						
I	Cardboard Pipe Insulation			Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 - ABATED	No ACBM						
J	MJP on Cardboard Pipe Insulation			Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 - ABATED	Abated	TSI					
K	Aircell Pipe Insulation	150	LF	Rm 204, 106, 015 - 1919 building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	MJP on Aircell Pipe Insulation			Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 (ABATED)	Abated	TSI					

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

*Management Planner's Comments Summarized at the End of the Report*

Review Date	5/6/2025
Manager Planner Name	Jigar Shah
100-07342	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
03	
08	
09	
13	
14	
16	
17	
18	
19	
20	

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
21	
24	
25	
26	
27	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
50M	

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
51	
52	
53	
54	
55	
56	
56M	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
75M	

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
76	
76M	
77	
77M	
78	
78M	
79	
79M	
80	
80M	
81	
81M	
82	
82M	
83	
83M	
84	
84M	
85	
85M	
A	
B	
C	
D	
F	
G	
H	

# Chicago Public Schools

**School** Darwin School

**Unit** 22881

**Building ID** 2960

**Address** 3116 W. Belden Avenue

Chicago, IL, 60647

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
I	
J	
K	
L	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Specialty Consulting, Inc.

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	Plaster Walls and Ceilings		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Throughout Building</b>		
MATERIAL QUANTITY:	<b>144908</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **Plaster Walls and Ceilings**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **144908** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	12"x12" Tan w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899**

**(Rooms: 002, 107, 108, 210, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not observed in Room 306 and 112**

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Darwin School	REVIEW DATE:	5/6/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899**

**(Rooms: 002, 107, 108, 210, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	12"x12" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Throughout Modular (See Hatching Maps)</b>		
MATERIAL QUANTITY:	<b>4000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile**

MATERIAL LOCATION: **Throughout Modular (See Hatching Maps)**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	1'x1' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st & 2nd Floor Corridor, and lunchroom - 1919		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile**

MATERIAL LOCATION: **1st & 2nd Floor Corridor, and lunchroom - 1919**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12"x12" Tan w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899**

**(Rooms: 002, 210, 304, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **not observed in Room 306 and 112**

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Darwin School	REVIEW DATE:	5/6/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms: 110, 112, 201A, 209A, 212, 304, 306, 313 - 1899**

**(Rooms: 002, 210, 304, 306, 312, Main Office, Engineer's Corridor, Girl's & Boy's Washrooms, 2nd Floor Faculty Toilet, MDF - NOT OBSERVED)**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: 1'x1' Ceiling Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Corridor, and lunchroom - 1919

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Corridor, and lunchroom - 1919**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1899**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout - 1899**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17  
MATERIAL DESCRIPTION: Wall Board  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Classrooms - 1899

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Wall Board**

MATERIAL LOCATION: **Throughout Classrooms - 1899**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12"x12" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Modular (See Hatching Maps)		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12"x12" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Throughout Modular (See Hatching Maps)**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Modular**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **1'x1' Ceiling Tile Mastic**

MATERIAL LOCATION: **Throughout Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: Vinyl Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Modular

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21  
MATERIAL DESCRIPTION: Wall Board  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Modular

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Wall Board**

MATERIAL LOCATION: **Throughout Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 24

MATERIAL DESCRIPTION: Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout - 1899

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **Throughout - 1899**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 25  
MATERIAL DESCRIPTION: Wall Joint Compound  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout - 1899

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Wall Joint Compound**

MATERIAL LOCATION: **Throughout - 1899**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26

MATERIAL DESCRIPTION: Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Modular

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **Throughout Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 27  
MATERIAL DESCRIPTION: Wall Joint Compound  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Modular

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Wall Joint Compound**

MATERIAL LOCATION: **Throughout Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12"x12" Tan w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899</b>		
MATERIAL QUANTITY:	<b>2100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12"x12" Tan w/ White Streaks Floor Tile mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899		
MATERIAL QUANTITY:	2100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks Floor Tile mastic**

MATERIAL LOCATION: **Rooms: 110, 112, 201A, 212, 304, 306, 313 - 1899**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32  
MATERIAL DESCRIPTION: Vinyl Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout - 1919

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **Throughout - 1919**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33

MATERIAL DESCRIPTION: Vinyl Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout - 1919

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout - 1919**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms: 210 - 1899**

**(Rooms: 206, 305 Ward, 306 Ward NOT OBSERVED)**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUILDING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**

MATERIAL LOCATION: **Rooms: 210 - 1899**

**(Rooms: 206, 305 Ward, 306 Ward NOT OBSERVED)**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms: 210 - 1899  (Rooms: 206, 306 Ward NOT OBSERVED)		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUILDING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms: 210 - 1899**

**(Rooms: 206, 306 Ward NOT OBSERVED)**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12"x12" Off White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>
MATERIAL LOCATION:	Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899 (Rooms: 205 Ward NOT OBSERVED)

MATERIAL QUANTITY:	2000	MATERIAL UNITS:	<b>SF</b>
--------------------	------	-----------------	-----------

DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
------------------	--	---------------	-----------

COMMENTS:

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile**

MATERIAL LOCATION: **Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899**

**(Rooms: 205 Ward NOT OBSERVED)**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12"x12" Off White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899 (Rooms: 205 Ward NOT OBSERVED)		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 107, 108, 206, 206 Wardrobe, 208 Wardrobe, 306, 312 - 1899**

**(Rooms: 205 Ward NOT OBSERVED)**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature: *Jigar Shah* Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12"x12" Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 308B, & 310A - 1899		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12"x12" Dark Brown Floor Tile**

MATERIAL LOCATION: **Rooms 308B, & 310A - 1899**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12"x12" Dark Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 308B & 310A - 1899		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 308B & 310A - 1899**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>3rd Floor Corridor - 1899</b>		
MATERIAL QUANTITY:	<b>1100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**

MATERIAL LOCATION: **3rd Floor Corridor - 1899**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor - 1899		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Corridor - 1899**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 42  
MATERIAL DESCRIPTION: 12"x12" Orange Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Front of Room 003 - 1899 (Not Observed)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUILDING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12"x12" Orange Floor Tile**

MATERIAL LOCATION: **Front of Room 003 - 1899 (Not Observed)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12"x12" Orange Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Front of Room 003 - 1899 - (Not Observed)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

**Specialty Consulting, Inc.**  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:		<b>Jigar Shah</b>	
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:			<b>5/6/2025</b>
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:			<b>100-11255</b>

## HOMOGENEOUS AREA: 43

MATERIAL DESCRIPTION: 12"x12" Orange Floor Tile Mastic

MATERIAL LOCATION: **Front of Room 003 - 1899 - (Not Observed)**

**MATERIAL QUANTITY:**

## MATERIAL UNITS:

DAMAGE QUANTITY: 0

### DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

## Follow O&M Plan

### Comments:

Management Planner's Signature:

Tregaron. chal.

Date: 05/06/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12"x12" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Bottom of Room 003 Stairs - 1899		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12"x12" Black Floor Tile**

MATERIAL LOCATION: **Bottom of Room 003 Stairs - 1899**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12"x12" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bottom of Room 003 Stairs - 1899		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12"x12" Black Floor Tile Mastic**

MATERIAL LOCATION: **Bottom of Room 003 Stairs - 1899**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46  
MATERIAL DESCRIPTION: Exterior Window Caulk  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 47  
MATERIAL DESCRIPTION: Exterior Window Glaze  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Modular

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Exterior Window Glaze**

MATERIAL LOCATION: **Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12"x12" White w/ Gray Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12"x12" White w/ Gray Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Multipurpose Room (411), 412, 412A, 107, 206, 509 - Modular**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	9"x9" Floor Tile (Painted Black)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1899 Bldg: Corridor by Room 002		
MATERIAL QUANTITY:	95	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **9"x9" Floor Tile (Painted Black)**

MATERIAL LOCATION: **1899 Bldg: Corridor by Room 002**

MATERIAL QUANTITY: **95** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50M		
MATERIAL DESCRIPTION:	9"x9" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1899 Bldg: Corridor by Room 002		
MATERIAL QUANTITY:	95	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **50M**

MATERIAL DESCRIPTION: **9"x9" Black Floor Tile Mastic**

MATERIAL LOCATION: **1899 Bldg: Corridor by Room 002**

MATERIAL QUANTITY: **95** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1899 Bldg: Room 003, Room 012 (Library), Room 023, Engineer's office, 104 (Basement Corridor - NOT OBSERVED)		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUILDING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Carpet Adhesive**

MATERIAL LOCATION: **1899 Bldg: Room 003, Room 012 (Library), Room 023, Engineer's office, 104  
(Basement Corridor - NOT OBSERVED)**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12"x12" Floor Tile (Painted Black)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1899 Bldg: 1st Floor Women's Washroom		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12"x12" Floor Tile (Painted Black)**

MATERIAL LOCATION: **1899 Bldg: 1st Floor Women's Washroom**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12"x12" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1899 Bldg: 1st Floor Women's Washroom		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x12" Black Floor Tile Mastic**

MATERIAL LOCATION: **1899 Bldg: 1st Floor Women's Washroom**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1919 Bldg: Room 104		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Carpet Adhesive**

MATERIAL LOCATION: **1919 Bldg: Room 104**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1919 Bldg: Assembly Hall Balcony and Main Office		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Carpet Adhesive**

MATERIAL LOCATION: **1919 Bldg: Assembly Hall Balcony and Main Office**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Red Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 410 (Pantry) - Modular		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Red Linoleum**

MATERIAL LOCATION: **Room 410 (Pantry) - Modular**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56M		
MATERIAL DESCRIPTION:	Red Linoleum Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 410 (Pantry) - Modular		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **56M**

MATERIAL DESCRIPTION: **Red Linoleum Adhesive**

MATERIAL LOCATION: **Room 410 (Pantry) - Modular**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	12"x12" White w/Multi-colored Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Office Room (416), 504, 501, 401 - Modular		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12"x12" White w/Multi-colored Specks Floor Tile**

MATERIAL LOCATION: **Office Room (416), 504, 501, 401 - Modular**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12"x12" White w/Multi-colored Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office Room (416) - Modular		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12"x12" White w/Multi-colored Specks Floor Tile Mastic**

MATERIAL LOCATION: **Office Room (416) - Modular**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12"x12" Grey w/Speccks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 401 Modular--NOT OBSERVED, room 210 (1899 building)		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Darwin School	REVIEW DATE:	5/6/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12"x12" Grey w/Speccks Floor Tile**

MATERIAL LOCATION: **Room 401 Modular--NOT OBSERVED, room 210 (1899 building)**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12"x12" Grey w/Speccks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 501 MODULAR-- NOT OBSERVED		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12"x12" Grey w/Speccks Floor Tile Mastic**

MATERIAL LOCATION: **Room 501 MODULAR-- NOT OBSERVED**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 501 MODULAR--NOT OBSERVED

MATERIAL QUANTITY: 3 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Sink Undercoating**

MATERIAL LOCATION: **Room 501 MODULAR--NOT OBSERVED**

MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	Acoustical Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Auditorium and Balcony		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Acoustical Plaster**

MATERIAL LOCATION: **Auditorium and Balcony**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	12"x12" Gray w/ White Specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112- 1899		
MATERIAL QUANTITY:	1330	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specs VFT**

MATERIAL LOCATION: **Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112- 1899**

MATERIAL QUANTITY: **1330** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12"x12" Gray w/ White Specs Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112- 1899		
MATERIAL QUANTITY:	1330	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specs Mastic**

MATERIAL LOCATION: **Men's Lounge 210C, MDF Room, 2nd Fl Unisex toilet, 112- 1899**

MATERIAL QUANTITY: **1330** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Carpet Mastic (Tile Carpet)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library- 1919		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Carpet Mastic (Tile Carpet)**

MATERIAL LOCATION: **Library- 1919**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12"x12" White w/ black specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12"x12" White w/ black specs VFT**

MATERIAL LOCATION: **Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12"x12" White w/ Black specs Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x12" White w/ Black specs Mastic**

MATERIAL LOCATION: **Basement corridor, Rooms 023, 002, 108, 306, and 308 - 1899**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12"x12" Gray w/ white specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	413, corridor outside of 413, 510---Modular		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12"x12" Gray w/ white specs VFT**

MATERIAL LOCATION: **413, corridor outside of 413, 510---Modular**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12"x12" Gray W/ white specs Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>413, corridor outside of 413, 510--Modular</b>		
MATERIAL QUANTITY:	<b>1600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12"x12" Gray W/ white specs Mastic**

MATERIAL LOCATION: **413, corridor outside of 413, 510--Modular**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 408 and 508-- Modular		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Rooms 408 and 508-- Modular**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	12"x12" White w/ beige specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 514, 502, 402, 408, 110, 308--modular		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12"x12" White w/ beige specs VFT**

MATERIAL LOCATION: **Rooms 514, 502, 402, 408, 110, 308--modular**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	12"x12" White w/ Beige specs Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 514, 502, 402, 408, 110, 308--modular		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige specs Mastic**

MATERIAL LOCATION: **Rooms 514, 502, 402, 408, 110, 308--modular**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 73

MATERIAL DESCRIPTION: 12"x12" White w/ gray specks VFT

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 402, 502 (ABATED 2018) - Modular

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12"x12" White w/ gray specks VFT**

MATERIAL LOCATION: **Rooms 402, 502 (ABATED 2018) - Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 74

MATERIAL DESCRIPTION: 12"x12" White w/Gray Specs VFT Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 402, 502 (ABATED 2018) - Modular

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12"x12" White w/Gray Specs VFT Mastic**

MATERIAL LOCATION: **Rooms 402, 502 (ABATED 2018) - Modular**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	12"x12" White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Rooms 402 and 502 - Modular</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/16/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12"x12" White VFT**

MATERIAL LOCATION: **Rooms 402 and 502 - Modular**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75M		
MATERIAL DESCRIPTION:	12"x12" White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 402 and 502 - Modular		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **75M**

MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**

MATERIAL LOCATION: **Rooms 402 and 502 - Modular**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: Boiler & Tank Mag Block Insulation (Abated 7/23/09)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room - 1899

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler & Tank Mag Block Insulation (Abated 7/23/09)**

MATERIAL LOCATION: **Boiler Room - 1899**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Office, Teacher Lunch Area & 012 A & B, 001, 003 - 1899		
MATERIAL QUANTITY:	610	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:	DAMAGE UNITS: FITTING		
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Engineer's Office, Teacher Lunch Area & 012 A & B, 001, 003 - 1899**

MATERIAL QUANTITY: **610** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: C

MATERIAL DESCRIPTION: Cardboard Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engine Room, 003, Tank Room - 1899 (ABATED)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Engine Room, 003, Tank Room - 1899 (ABATED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Restroom, Rooms 001-003, 012 A & B - 1899		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Engineer's Restroom, Rooms 001-003, 012 A & B - 1899**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F

MATERIAL DESCRIPTION: MJP on Cardboard Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: South Dressing Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**

MATERIAL LOCATION: **South Dressing Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	MJP on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Engineer's Restroom, Rooms 001-003, 012 A & B - 1899		
MATERIAL QUANTITY:	130	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**

MATERIAL LOCATION: **Engineer's Restroom, Rooms 001-003, 012 A & B - 1899**

MATERIAL QUANTITY: **130** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: MJP on Fiberglass Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st, 2nd, 3rd, & Basement Toilets, basement custodian storage - 1919

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **1st, 2nd, 3rd, & Basement Toilets, basement custodian storage - 1919**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: I

MATERIAL DESCRIPTION: Cardboard Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Darwin School	REVIEW DATE:	5/6/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: I

MATERIAL DESCRIPTION: Cardboard Pipe Insulation

MATERIAL LOCATION: Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 05/06/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: J

MATERIAL DESCRIPTION: MJP on Cardboard Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUILDING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rm 204, 106, 015 - 1919 building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUILDING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Rm 204, 106, 015 - 1919 building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: MJP on Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 (ABATED)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>22881</b>	BUIDLING ID:	<b>2960</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Darwin School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>3116 W. Belden Avenue</b>	IDPH LICENSE NO:	<b>100-11255</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement Corridor, Lunch Room, South Dressing Room, 204, Boys Basement Toliet - 1919 (ABATED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	76M				
MATERIAL DESCRIPTION:	12"x12" Gray w/ Specs Replacement VFT Mastic				
MATERIAL LOCATION:	Room 112 - 1899 Building				
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **76M**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Specs Replacement VFT Mastic**

MATERIAL LOCATION: **Room 112 - 1899 Building**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	12"x12" Gray w/ White Specs Replacement VFT		
MATERIAL LOCATION:	1st and 2nd Floor Corridors - Modular Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specs Replacement VFT**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - Modular Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	78M				
MATERIAL DESCRIPTION:	12"x12" Beige w/ Tan Specs Replacement VFT Mastic				
MATERIAL LOCATION:	3rd Floor Corridor				
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **78M**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Tan Specs Replacement VFT Mastic**

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12"x12" Dark Green VFT		
MATERIAL LOCATION:	Rooms 504 and 506 - Modular Building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12"x12" Dark Green VFT**

MATERIAL LOCATION: **Rooms 504 and 506 - Modular Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12"x12" Light Green VFT		
MATERIAL LOCATION:	Rooms 504 and 506 - Modular Building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12"x12" Light Green VFT**

MATERIAL LOCATION: **Rooms 504 and 506 - Modular Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	82M				
MATERIAL DESCRIPTION:	12"x12" Dark Blue VFT Mastic				
MATERIAL LOCATION:	Rooms 501 and 505 - Modular Building				
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **82M**

MATERIAL DESCRIPTION: **12"x12" Dark Blue VFT Mastic**

MATERIAL LOCATION: **Rooms 501 and 505 - Modular Building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	12"x12" White w/ Blue Specs VFT		
MATERIAL LOCATION:	Rooms 501, 504, 505, and 506 - Modular Building		
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12"x12" White w/ Blue Specs VFT**

MATERIAL LOCATION: **Rooms 501, 504, 505, and 506 - Modular Building**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	84M				
MATERIAL DESCRIPTION:	12"x12" Beige & Tan VFT Mastic				
MATERIAL LOCATION:	1st and 2nd Floor Corridors - Modular Building				
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **84M**

MATERIAL DESCRIPTION: **12"x12" Beige & Tan VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - Modular Building**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	76		
MATERIAL DESCRIPTION:	12"x12" Gray w/ Specs Replacement VFT		
MATERIAL LOCATION:	Room 112 - 1899 Building		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12"x12" Gray w/ Specs Replacement VFT**

MATERIAL LOCATION: **Room 112 - 1899 Building**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	80M				
MATERIAL DESCRIPTION:	12"x12" Light Green VFT Mastic				
MATERIAL LOCATION:	Rooms 504 and 506 - Modular Building				
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **80M**

MATERIAL DESCRIPTION: **12"x12" Light Green VFT Mastic**

MATERIAL LOCATION: **Rooms 504 and 506 - Modular Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	12"x12" Dark Blue VFT		
MATERIAL LOCATION:	Rooms 501 and 505 - Modular Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12"x12" Dark Blue VFT**

MATERIAL LOCATION: **Rooms 501 and 505 - Modular Building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	12"x12" Beige & Tan Replacement VFT		
MATERIAL LOCATION:	1st and 2nd Floor Corridors - Modular Building		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12"x12" Beige & Tan Replacement VFT**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - Modular Building**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Tan Specs Replacement VFT		
MATERIAL LOCATION:	3rd Floor Corridor		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Tan Specs Replacement VFT**

MATERIAL LOCATION: **3rd Floor Corridor**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	79M				
MATERIAL DESCRIPTION:	12"x12" Dark Green VFT				
MATERIAL LOCATION:	Rooms 504 and 506 - Modular Building				
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **79M**

MATERIAL DESCRIPTION: **12"x12" Dark Green VFT**

MATERIAL LOCATION: **Rooms 504 and 506 - Modular Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	77M				
MATERIAL DESCRIPTION:	12"x12" White w/ Gray Specs VFT Mastic				
MATERIAL LOCATION:	Rooms 208 and 308 - 1899 Building				
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **77M**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specs VFT Mastic**

MATERIAL LOCATION: **Rooms 208 and 308 - 1899 Building**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12"x12" Light Blue VFT		
MATERIAL LOCATION:	Rooms 501 and 505 - Modular Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12"x12" Light Blue VFT**

MATERIAL LOCATION: **Rooms 501 and 505 - Modular Building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12"x12" White w/ Gray Specs VFT		
MATERIAL LOCATION:	Rooms 208 and 308 - 1899 Building		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Specs VFT**

MATERIAL LOCATION: **Rooms 208 and 308 - 1899 Building**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	81M		
MATERIAL DESCRIPTION:	12"x12" Light Blue VFT and Mastic		
MATERIAL LOCATION:	Rooms 501 and 505 - Modular Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **81M**

MATERIAL DESCRIPTION: **12"x12" Light Blue VFT and Mastic**

MATERIAL LOCATION: **Rooms 501 and 505 - Modular Building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	83M				
MATERIAL DESCRIPTION:	12"x12" White w/ Blue Specs VFT Mastic				
MATERIAL LOCATION:	Rooms 501, 504, 505, and 506 - Modular Building				
MATERIAL QUANTITY:	3200	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	5 ACBM with potential for significant damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **83M**

MATERIAL DESCRIPTION: **12"x12" White w/ Blue Specs VFT Mastic**

MATERIAL LOCATION: **Rooms 501, 504, 505, and 506 - Modular Building**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	22881	BUIDLING ID:	2960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Darwin School	INSPECTION DATE:	4/16/2025		
ADDRESS:	3116 W. Belden Avenue	IDPH LICENSE NO:	100-11255		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	85M		
MATERIAL DESCRIPTION:	12"x12" Gray w/ White Specs Replacement VFT Mastic		
MATERIAL LOCATION:	1st and 2nd Floor Corridors - Modular Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/16/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22881** BUIDLING ID: **2960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Darwin School** REVIEW DATE: **5/6/2025**

ADDRESS: **3116 W. Belden Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **85M**

MATERIAL DESCRIPTION: **12"x12" Gray w/ White Specs Replacement VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - Modular Building**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **05/06/2025**

## APPENDIX B

---

### Inspector and Management Planner Licenses

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR16

Certificate Number:

A handwritten signature in black ink that reads 'Nicholas J. Peneff' followed by 'Ph.D.' in a smaller script.

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
**100 - 11255**

ISSUED  
**2/28/2022**

EXPIRES  
**05/15/2023**

ESTEBAN NUNEZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



**ESTEBAN NUNEZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11255**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 11255</b>	ISSUED <b>2/28/2022</b>	EXPIRES <b>05/15/2023</b>	INSPECTOR	1/15/2023
<b>ESTEBAN NUNEZ</b> 2942 W VAN BUREN ST CHICAGO, IL 60612			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/11/2022
			<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 01/28/2023 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

01/28/2023

Course Dates:

01/28/2024

Expires:

2301BIR27

Certificate Number:

A handwritten signature in black ink that reads 'Nicholas J. Peneff' above 'Director of Training'.

Phone: 312-491-0081

Director of Training


Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois



**ESTEBAN NUNEZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


6/21/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11255

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/23/2025
PROJECT MANAGER	1/15/2025
AIR SAMPLING PROFESSIONAL	
<i>Alteration of this license shall result in legal action</i> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/23/2024 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

02/23/2024

Course Dates:

02/23/2025

Expires:

2402BIR06

Certificate Number:

Director of Training

Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081


FORM # A-010B

A handwritten signature in black ink, appearing to read 'Nicholas J. Peneff', is placed over the typed name and title.



525-535 West Jefferson Street • Springfield, IL

**ESTEBAN NUNEZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11255**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

 <b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER <b>100 - 11255</b>	ISSUED <b>4/30/2025</b>	EXPIRES <b>05/15/2026</b>	INSPECTOR 3/19/2026
<b>ESTEBAN NUNEZ</b> 2942 W VAN BUREN ST CHICAGO, IL 60612		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/14/2025
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

# CERTIFICATE OF ACHIEVEMENT

## ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 03/19/2025 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • [www.public-health-safety.com](http://www.public-health-safety.com)

03/19/2025

Course Dates:

03/19/2026

Expires:

2503BIR05

Certificate Number:

Phone: 312-491-0081

FORM # A-010B

Director of Training

Nicholas J. Penef

Doctor of Public Health

A handwritten signature in black ink that appears to read 'Nicholas J. Penef'.



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

6/9/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 07342</b>	ISSUED <b>6/9/2025</b>	EXPIRES <b>05/15/2026</b>	INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/7/2026 1/27/2026 3/7/2026 4/7/2026
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023


Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

*Kathy DeSalvo*

Kathy DeSalvo, Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.


Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761

IDPH

ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 07342

ISSUED  
4/1/2022

EXPIRES  
05/15/2023

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/9/2023
PROJECT DESIGNER	3/24/2023
MANAGEMENT PLANNER	3/9/2023
PROJECT MANAGER	3/2/2023
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b>	
This license issued under authority of the State of Illinois	
Department of Public Health	
This license is valid only when accompanied by a valid	
training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 07342

ISSUED  
4/8/2024

EXPIRES  
05/15/2025

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/8/2025
PROJECT DESIGNER	3/7/2025
MANAGEMENT PLANNER	3/8/2025
PROJECT MANAGER	3/25/2024
AIR SAMPLING PROFESSIONAL	
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH. IMPROVING LIVES

*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/8/2024

Exam Date: 3/8/2024

Expiration Date: 3/8/2025

Certificate Number: MPR2403081126

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: MPR2503070948

Course Credit Hours: MPR 4 Hours

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed