

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2518  
SCHOOL NAME: Williams School  
ADDRESS OF SCHOOL: 2710 S. Dearborn St.  
CITY: Chicago, IL, 60616

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/23/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/10/2025 ENROLLMENT 306  
IDPH INSPECTOR LICENSE NUMBER: 100-06435  
IDPH LICENSED INSPECTOR NAME (Please Print): Jose Escobedo  
IDPH MP LICENSE NUMBER: 100-18488  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 5/6/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Williams School**

2710 S. Dearborn St.  
Chicago, IL, 60616

Unit: 23011  
Building ID: 6490

IDPH ID Number: 14-016-2990-2518

**REPORT DATE:**  
Tuesday, May 06, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

05/06/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 25891      Region: 04      IDPH ID: 14-016-2990-2518

School: Williams School      Building ID: 6490

Address: 2710 S. Dearborn St.

Chicago, IL, 60616

Building Contact: McCarthy, Thomas      Contact Phone: 7083051706

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/10/2025

Review Date: 05/06/2025

Inspector: Jose Escobedo


Inspector IDPH License: 100-06435

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Mike Serio  
100-18488

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 06, 2025

RE: Williams School, Unit 23011  
2710 S. Dearborn St.  
Chicago, IL, 60616

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Williams School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Williams School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Williams School      Unit: 25891      Region: 04  
Address: 2710 S. Dearborn St.      Chicago, IL, 60616  
IDPH ID: 14-016-2990-2518      Building ID: 6490  
Contact: McCarthy, Thomas      Phone: 7083051706

### 2. Description of Facility

Original Construction: 1950      Additional Construction: 1994  
Total Square Footage: 141400      No of Floors: 3  
Current Occupancy: 306

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Jose Escobedo

Inspector IDPH license # 100-06435      Signature:  
Reinspection Date: 4/10/2025      Date: 4/10/2025

### 6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488


Signature:  
Date: 05/06/2025

### 7. Review Date: 05/06/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/6/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Williams School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6490:

10	Mastic Under 12" x 12" Brown Floor Tile
100	12" x 12" Green w/ White Streak Floor Tile Mastic
101	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile
102	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile Mastic
103	Red and Tan Terrazzo
104	12" x 12" Gray Mottled Floor Tile
105	12" x 12" Yellow Mottled Floor Tile
106	12" x 12" Gray and Yellow Mottled Floor Tile Mastic

107	2" x 2" Gray Ceramic Floor Tile
11	Mastic Under 9" x 9" Beige Vinyl Floor Tile
12	Mastic Under Linoleum Floor Cover
13	Mastic Under Linoleum Counter Tops
23	Vault Door Insulation
24	Exterior Brick - Non-AHERA
27	Roofing Material - Non-AHERA
28	12" x 12" Aqua Floor Tile
29	12" x 12" Aqua Floor Tile Mastic
3	12" x 12" Gray Vinyl Floor Tile
30	12" x 12" White w/ Red Floor Tile
31	12" x 12" White w/ Red Floor Tile Mastic
32	12" x 12" Beige Speckled Floor Tile
4	12" x 12" Brown Vinyl Floor Tile
42	Carpet Mastic
43	9" x 9" Brown Floor Tile
44	9" x 9" Brown Floor Tile Mastic
45	9" x 9" Gray Floor Tile
46	9" x 9" Gray Floor Tile Mastic
47	4" Gray Vinyl Baseboard
48	4" Gray Vinyl Baseboard Mastic
49	Interior Window Caulk
50	Green Linoleum Counter Top
51	Green Linoleum Counter Top Mastic

52	Interior Door Caulk
53	Carpet Mastic
54	Spray-on Fireproofing
55	6" Brown Vinyl Baseboard
56	6" Brown Vinyl Baseboard Mastic
57	Interior Window Caulk
58	2' x 4' Plain Ceiling Tile
59	2' x 2' Fissured Ceiling Tile
6	Linoleum Floor Covering
60	Linoleum Flooring
61	Linoleum Flooring Mastic
62	9" x 9" Green Floor Tile
63	9" x 9" Green Floor Tile Mastic
64	12" x 12" Beige w/ Light Beige Streaks Checkerboard Vinyl Floor Tile
65	12" x 12" Cream w/ Beige Streaks Checkerboard Vinyl Floor Tile
66	Mastic Associated w/ Checkerboard Pattern Floor Tile
67	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile
68	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile Mastic
69	12" x 12" Light Blue Vinyl Floor Tile
7	Acoustical Spray on Plaster
70	12" x 12" Light Blue Vinyl Floor Tile Mastic

71	12" x 12" Vinyl Floor Tile Tan/Checkered
72	12" x 12" Vinyl Floor Tile Tan/Checkered Mastic
73	12" x 12" Vinyl Floor Tile White Checkered
74	12" x 12" Vinyl Floor Tile White Checkered Mastic
75	Red Linoleum
76	Red Linoleum Adhesive
77	Boiler Gasket
78	Pump Gaskets
79	Covebase
80	Covebase Adhesive
81	Drywall
82	Joint Compound
83	12" x 12" Floor Tile Checkered Brown/Streaks
84	12" x 12" Floor Tile Checkered Brown/Streaks Mastic
85	12" x 12" Floor Tile Checkered White/Streak
86	12" x 12" Floor Tile Checkered White/Streak Mastic
87	Tan Linoleum
88	Tan Linoleum Adhesive
89	4" x 4" Vinyl Wall Covering
92	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile Mastic
93	Tongue and Groove Wood Flooring
94	12" x 12" Tan w/ Red Marbling Floor Tile
95	12" x 12" Gray w/ Dark Gray and White Marbling Floor Tile

- 96 12" x 12" Tan and Gray Marbled Floor Tile Mastic
- 97 1' x 1' Dot Pattern Ceiling Tile
- 98 Adhesive Associated w/ 1' x 1' Dot Pattern Ceiling Tile
- 99 12" x 12" Green w/ White Streak Floor Tile
- A Aircell Pipe Insulation
- D Hard Elbows on Aircell
- E Aircell Pipe Insulation
- F Aircell Pipe Insulation
- G Aircell
- H Hard Elbows on Aircell
- I Boiler Insulation

B. The following new homogenous areas have been identified for Building 6490:

107	2" x 2" Gray Ceramic Floor Tile
108	2" x 2" Gray Ceramic Floor Tile Grout
109	5" x 12" Beige Ceramic Wall Tile
110	5" x 12" Beige Ceramic Wall Tile Grout
111	2" x 2" Brown Ceramic Tile
112	2" x 2" Brown Ceramic Tile Grout
113	2' x 2' Beige Ceramic Wall Tile
114	2' x 2' Beige Ceramic Wall Tile Grout
115	6" x 6" Gray Ceramic Tile
116	6" x 6" Gray Ceramic Tile Grout
117	1' x 2' Dark Gray Wall Tile
118	1' x 2' Dark Gray Wall Tile Grout
119	12" x 12" Light Beige Ceramic Floor Tile
120	12" x 12" Light Beige Ceramic Floor Tile Grout
121	16' x 20' Light Gray Wall Tile
122	16' x 20' Light Gray Wall Tile Grout
123	2" x 2" Red Ceramic Floor Tile
124	2" x 2" Red Ceramic Floor Tile Grout
125	4' x 4' Beige Ceramic Wall Tile
126	4' x 4' Beige Ceramic Wall Tile Grout
127	4" x 4" Mosaic Floor Tile
128	4" x 4" Mosaic Floor Tile Grout

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Hard Coat Plaster
100	12" x 12" Green w/ White Streak Floor Tile Mastic
101	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile
102	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile Mastic
103	Red and Tan Terrazzo
104	12" x 12" Gray Mottled Floor Tile
105	12" x 12" Yellow Mottled Floor Tile
106	12" x 12" Gray and Yellow Mottled Floor Tile Mastic
107	2" x 2" Gray Ceramic Floor Tile
108	2" x 2" Gray Ceramic Floor Tile Grout
109	5" x 12" Beige Ceramic Wall Tile
110	5" x 12" Beige Ceramic Wall Tile Grout
111	2" x 2" Brown Ceramic Tile
112	2" x 2" Brown Ceramic Tile Grout
113	2' x 2' Beige Ceramic Wall Tile
114	2' x 2' Beige Ceramic Wall Tile Grout
115	6" x 6" Gray Ceramic Tile
116	6" x 6" Gray Ceramic Tile Grout
117	1' x 2' Dark Gray Wall Tile
118	1' x 2' Dark Gray Wall Tile Grout
119	12" x 12" Light Beige Ceramic Floor Tile
12	Mastic Under Linoleum Floor Cover
120	12" x 12" Light Beige Ceramic Floor Tile Grout
121	16' x 20' Light Gray Wall Tile
122	16' x 20' Light Gray Wall Tile Grout
123	2" x 2" Red Ceramic Floor Tile
124	2" x 2" Red Ceramic Floor Tile Grout
125	4' x 4' Beige Ceramic Wall Tile
126	4' x 4' Beige Ceramic Wall Tile Grout
127	4" x 4" Mosaic Floor Tile
128	4" x 4" Mosaic Floor Tile Grout
13	Mastic Under Linoleum Counter Tops
22	Fire Door Insulation
23	Vault Door Insulation
26	Transite Lab Tables
27	Roofing Material - Non-AHERA
28	12" x 12" Aqua Floor Tile
29	12" x 12" Aqua Floor Tile Mastic
30	12" x 12" White w/ Red Floor Tile

31	12" x 12" White w/ Red Floor Tile Mastic
42	Carpet Mastic
47	4" Gray Vinyl Baseboard
48	4" Gray Vinyl Baseboard Mastic
49	Interior Window Caulk
50	Green Linoleum Counter Top
51	Green Linoleum Counter Top Mastic
52	Interior Door Caulk
53	Carpet Mastic
54	Spray-on Fireproofing
55	6" Brown Vinyl Baseboard
56	6" Brown Vinyl Baseboard Mastic
57	Interior Window Caulk
58	2' x 4' Plain Ceiling Tile
59	2' x 2' Fissured Ceiling Tile
6	Linoleum Floor Covering
60	Linoleum Flooring
61	Linoleum Flooring Mastic
64	12" x 12" Beige w/ Light Beige Streaks Checkerboard Vinyl Floor Tile
65	12" x 12" Cream w/ Beige Streaks Checkerboard Vinyl Floor Tile
66	Mastic Associated w/ Checkerboard Pattern Floor Tile
67	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile
68	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile Mastic
69	12" x 12" Light Blue Vinyl Floor Tile
70	12" x 12" Light Blue Vinyl Floor Tile Mastic
71	12" x 12" Vinyl Floor Tile Tan/Checkered
72	12" x 12" Vinyl Floor Tile Tan/Checkered Mastic
73	12" x 12" Vinyl Floor Tile White Checkered
74	12" x 12" Vinyl Floor Tile White Checkered Mastic
75	Red Linoleum
76	Red Linoleum Adhesive
77	Boiler Gasket
78	Pump Gaskets
79	Covebase
80	Covebase Adhesive
81	Drywall
82	Joint Compound
83	12" x 12" Floor Tile Checkered Brown/Streaks
84	12" x 12" Floor Tile Checkered Brown/Streaks Mastic
85	12" x 12" Floor Tile Checkered White/Streak
86	12" x 12" Floor Tile Checkered White/Streak Mastic
87	Tan Linoleum

88	Tan Linoleum Adhesive
89	4" x 4" Vinyl Wall Covering
90	4" x 4" Vinyl Wall Covering Adhesive
91	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile
92	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile Mastic
93	Tongue and Groove Wood Flooring
94	12" x 12" Tan w/ Red Marbling Floor Tile
95	12" x 12" Gray w/ Dark Gray and White Marbling Floor Tile
96	12" x 12" Tan and Gray Marbled Floor Tile Mastic
97	1' x 1' Dot Pattern Ceiling Tile
98	Adhesive Associated w/ 1' x 1' Dot Pattern Ceiling Tile
99	12" x 12" Green w/ White Streak Floor Tile

The following areas were deemed to be inaccessible:

100	12" x 12" Green w/ White Streak Floor Tile Mastic
102	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile Mastic
106	12" x 12" Gray and Yellow Mottled Floor Tile Mastic
22	Fire Door Insulation
23	Vault Door Insulation
29	12" x 12" Aqua Floor Tile Mastic
42	Carpet Mastic
48	4" Gray Vinyl Baseboard Mastic
49	Interior Window Caulk
52	Interior Door Caulk
53	Carpet Mastic
54	Spray-on Fireproofing
56	6" Brown Vinyl Baseboard Mastic
60	Linoleum Flooring
61	Linoleum Flooring Mastic
66	Mastic Associated w/ Checkerboard Pattern Floor Tile
68	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile Mastic
70	12" x 12" Light Blue Vinyl Floor Tile Mastic
72	12" x 12" Vinyl Floor Tile Tan/Checkered Mastic
74	12" x 12" Vinyl Floor Tile White Checkered Mastic
77	Boiler Gasket
78	Pump Gaskets
80	Covebase Adhesive

82	Joint Compound
84	12" x 12" Floor Tile Checkered Brown/Streaks Mastic
86	12" x 12" Floor Tile Checkered White/Streak Mastic
88	Tan Linoleum Adhesive
92	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile Mastic
96	12" x 12" Tan and Gray Marbled Floor Tile Mastic
97	1' x 1' Dot Pattern Ceiling Tile
98	Adhesive Associated w/ 1' x 1' Dot Pattern Ceiling Tile

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jose Escobedo, IDPH License # 100-06435. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Williams School Building 6490 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Hard Coat Plaster	350,000	SF	Throughout Building	ASSUMED	MISC	N	NONE				ACBM with potential for significant damage		LOW
10	Mastic Under 12" x 12" Brown Floor Tile			Throughout Building	CHR	MISC					Yes			
100	12" x 12" Green w/ White Streak Floor Tile Mastic	800	SF	Clinic 121a, 132, 133	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
101	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile	600	SF	Room 125, 126, 129, 130	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
102	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile Mastic	600	SF	Room 125, 126, 129, 130	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
103	Red and Tan Terrazzo	500	LF	Stairwells	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
104	12" x 12" Gray Mottled Floor Tile	400	SF	Rooms 303, 304, 305, 306, 307, 309, , 316, 318, 319, 301,203,214, 116, 117, basement weight room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
105	12" x 12" Yellow Mottled Floor Tile	400	SF	Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319, 301,203,214, basement, 116	ASSUMED	MISC	N	LOC	5	SF	Yes	ACBM with the potential for damage	3	LOW
106	12" x 12" Gray and Yellow Mottled Floor Tile Mastic	800	SF	Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319,203,214, 116, 117, basement	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
107	2" x 2" Gray Ceramic Floor Tile	1,000	SF	1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
108	2" x 2" Gray Ceramic Floor Tile Grout	1,000	SF	1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
109	5" x 12" Beige Ceramic Wall Tile	2,000	SF	3rd Floor Boys and	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom								potential for damage		
11	Mastic Under 9" x 9" Beige Vinyl Floor Tile			Room 302	CHR	MISC					Yes			
110	5" x 12" Beige Ceramic Wall Tile Grout	2,000	SF	3rd Floor Boys and Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
111	2" x 2" Brown Ceramic Tile	20	SF	3rd Floor North All Gender Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
112	2" x 2" Brown Ceramic Tile Grout	20	SF	3rd Floor North All Gender Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
113	2' x 2' Beige Ceramic Wall Tile	150	SF	3rd Floor North All Gender Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
114	2' x 2' Beige Ceramic Wall Tile Grout	150	SF	3rd Floor North All Gender Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
115	6" x 6" Gray Ceramic Tile	200	SF	3rd Floor South All Genders Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
116	6" x 6" Gray Ceramic Tile Grout	200	SF	3rd Floor South All Genders Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
117	1' x 2' Dark Gray Wall Tile	200	SF	3rd Floor South All Genders Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
118	1' x 2' Dark Gray Wall Tile Grout	200	SF	3rd Floor South All Genders Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
119	12" x 12" Light Beige Ceramic Floor Tile	50	SF	2nd Floor Staff Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
12	Mastic Under Linoleum Floor Cover			Room 115	ASSUMED	MISC					Yes			
120	12" x 12" Light Beige Ceramic Floor Tile Grout	50	SF	2nd Floor Staff Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
121	16' x 20' Light Gray Wall Tile	700	SF	Gymnasium Hallway First Floor - Lobby	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
122	16' x 20' Light Gray Wall Tile Grout	700	SF	Gymnasium Hallway First Floor - Lobby	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
123	2" x 2" Red Ceramic Floor Tile	75	SF	Room 113 Bathroom, Room 115 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
124	2" x 2" Red Ceramic Floor Tile Grout	75	SF	Room 113 Bathroom, Room 115 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
125	4' x 4' Beige Ceramic Wall Tile	75	SF	Room 113 Bathroom, Room 115 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
126	4' x 4' Beige Ceramic Wall Tile Grout	75	SF	Room 113 Bathroom, Room 115 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
127	4" x 4" Mosaic Floor Tile	100	SF	1st Floor Vestibule South End, Room 101 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
128	4" x 4" Mosaic Floor Tile Grout	100	SF	1st Floor Vestibule South End, Room 101 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
13	Mastic Under Linoleum Counter Tops			Rooms 116,	ASSUMED	MISC					Yes			
14	12" x 12" Green Vinyl Floor Tile			ABATED	ABATED	MISC					No			
15	12" x 12" Red Vinyl Floor Tile			ABATED	ABATED	MISC					No			
16	12" x 12" Beige Vinyl Floor Tile			ABATED	ABATED	MISC					No			
17	12" x 12" Light Brown Vinyl Floor Tile			ABATED	ABATED	MISC					No			
18	Mastic Under 12" x 12" Green Vinyl Floor Tile			ABATED	ABATED	MISC					No			
19	Mastic Under 12" x 12" Red Vinyl Floor Tile			ABATED	ABATED	MISC					No			
20	Mastic Under 12" x 12" Beige Vinyl Floor Tile			ABATED	ABATED	MISC					No			
21	Mastic Under 12" x 12" Light Brown Vinyl Floor Tile			ABATED	ABATED	MISC					No			
22	Fire Door Insulation	5,000	SF	Boiler Room and Air Tunnels	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
23	Vault Door Insulation	25	SF	Main Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
24	Exterior Brick - Non-AHERA			Building Structure	NO_ACBM	MISC					Yes			
25	Exterior Brick Mortar - Non-AHERA			Exterior Building Structure	NO_ACBM	MISC					No			
26	Transite Lab Tables	200	SF	Room 302	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
27	Roofing Material - Non-AHERA			Roof	ASSUMED	MISC					Yes			
28	12" x 12" Aqua Floor Tile	800	SF	Main Office, Room 109, 115, 117	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
29	12" x 12" Aqua Floor Tile Mastic	800	SF	Main Office, Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the		LOW

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				203, 109, 115, 117								potential for damage		
3	12" x 12" Gray Vinyl Floor Tile	45,000	SF	Throughout Building	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
30	12" x 12" White w/ Red Floor Tile			Room 103	ASSUMED	MISC					Yes			
31	12" x 12" White w/ Red Floor Tile Mastic			Room 103	ASSUMED	MISC					Yes			
32	12" x 12" Beige Speckled Floor Tile			ABATED	ABATED	MISC					Yes			
33	12" x 12" Beige Speckled Floor Tile Mastic			ABATED	ABATED	MISC					No			
34	12" x 12" Brown Speckled Floor Tile			ABATED	ABATED	MISC					No			
35	12" x 12" Brown Speckled Floor Tile Mastic			ABATED	ABATED	MISC					No			
36	12" x 12" White w/ Rainbow Specks Floor Tile			ABATED	ABATED	MISC					No			
37	12" x 12" White w/ Rainbow Specks Floor Tile Mastic			ABATED	ABATED	MISC					No			
38	12" x 12" Light Brown w/ White & Brown Streaks Floor Tile			ABATED	ABATED	MISC					No			
39	12" x 12" Brown w/ White & Brown Streaks Floor Tile			ABATED	ABATED	MISC					No			
4	12" x 12" Brown Vinyl Floor Tile			ABATED	ABATED	MISC					Yes			
40	12" x 12" Gray w/ White & Black Streaks Floor Tile			ABATED	ABATED	MISC					No			
41	12" x 12" Gray w/ White & Black Streaks Floor Tile Mastic			Room 214	CHR	MISC					No			
42	Carpet Mastic	1,000	SF	Library, Room 203, Main Office, 100, 103, 221, 321	ASSUMED	MISC	N	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
43	9" x 9" Brown Floor Tile			3rd Floor Teachers' Bathroom	CHR	MISC					Yes			
44	9" x 9" Brown Floor Tile Mastic			3rd Floor Teachers' Bathroom	CHR	MISC					Yes			
45	9" x 9" Gray Floor Tile			3rd Floor Teachers' Bathroom	CHR	MISC					Yes			
46	9" x 9" Gray Floor Tile Mastic			3rd Floor Teachers' Bathroom	CHR	MISC					Yes			
47	4" Gray Vinyl Baseboard	5,000	LF	Rooms 203, 214	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
48	4" Gray Vinyl Baseboard Mastic	5,000	LF	Rooms 203, 214	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
49	Interior Window Caulk	8,000	LF	Throughout	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
5	9" x 9" Beige Vinyl Floor Tile			Room 302	CHR	MISC					No			
50	Green Linoleum Counter Top			Room 115	ASSUMED	MISC					Yes			
51	Green Linoleum Counter Top Mastic			Room 115	ASSUMED	MISC					Yes			

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
52	Interior Door Caulk	50	LF	West Entrance	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
53	Carpet Mastic	400	SF	Auditorium (1954 Addition)	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
54	Spray-on Fireproofing	5,000	SF	Auditorium (1954 Addition)	ASSUMED	SURFACE	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
55	6" Brown Vinyl Baseboard	450	LF	Lunchroom (1995 Addition) and Room 302	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
56	6" Brown Vinyl Baseboard Mastic	450	LF	Lunchroom (1995 Addition) and Room 302	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
57	Interior Window Caulk	100	LF	Lunchroom (1995 Addition)	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
58	2' x 4' Plain Ceiling Tile	4,000	SF	Lunchroom (1995 Addition), Basement Weight Room	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
59	2' x 2' Fissured Ceiling Tile	1,000	LF	Hallway by Lunchroom (1995 Addition), 121a Clinic	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
6	Linoleum Floor Covering			Room 102	ASSUMED	MISC					Yes			
60	Linoleum Flooring	5,000	SF	Lunchroom/Serving Area (1995 Addition) 302, 107, 110, 314, 317	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
61	Linoleum Flooring Mastic	5,000	SF	Lunchroom/ Serving Area (1995 Addition) 300, 107, 110, 314, 317	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
62	9" x 9" Green Floor Tile			Basement: Recreation Room	CHR	MISC					Yes			
63	9" x 9" Green Floor Tile Mastic			Basement: Recreation Room	CHR	MISC					Yes			
64	12" x 12" Beige w/ Light Beige Streaks Checkerboard Vinyl Floor Tile	8,625	SF	1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room	ASSUMED	MISC	N	NONE			Yes	ACBM with potential for significant damage		LOW

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
65	12" x 12" Cream w/ Beige Streaks Checkerboard Vinyl Floor Tile	8,625	SF	1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room	ASSUMED	MISC	N	NONE			Yes	ACBM with potential for significant damage		LOW
66	Mastic Associated w/ Checkerboard Pattern Floor Tile	17,250	SF	1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
67	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile	1,425	SF	Rooms 215, 109, 115, 211	ASSUMED	MISC	N	NONE			Yes	ACBM with potential for significant damage		LOW
68	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile Mastic	1,425	SF	Rooms 215, 109, 115, 211,221	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
69	12" x 12" Light Blue Vinyl Floor Tile	525	SF	Rooms 215, 211, 121a	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
7	Acoustical Spray on Plaster			ABATED	ABATED	SURFACE					Yes			
70	12" x 12" Light Blue Vinyl Floor Tile Mastic	525	SF	Rooms 215	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
71	12" x 12" Vinyl Floor Tile Tan/Checkered	400	SF	North Basement Corridors, Teachers' Lunchrooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
72	12" x 12" Vinyl Floor Tile Tan/Checkered Mastic	400	SF	North Basement Corridors, Teachers' Lunchrooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
73	12" x 12" Vinyl Floor Tile White Checkered	400	SF	North Basement Corridors, Teachers' Lunchrooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
74	12" x 12" Vinyl Floor Tile White Checkered Mastic	400	SF	North Basement Corridors, Teachers' Lunchrooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
75	Red Linoleum			Basement, Weight Room	ASSUMED	MISC					Yes			
76	Red Linoleum Adhesive			Basement, Weight Room	ASSUMED	MISC					Yes			
77	Boiler Gasket	10	SF	Boiler Room	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable		LOW

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												ACBM or friable suspect ACBM		
78	Pump Gaskets	10	SF	Boiler Room	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
79	Covebase	200	SF	North Basement Corridors, Teachers' Lunchroom, Weight Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
8	Linoleum Counter Tops			Rooms 115, 116, 117	NO_ACBM	MISC					No			
80	Covebase Adhesive	200	SF	North Basement Corridors, Teachers' Lunchroom, Weight Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
81	Drywall	14,000	SF	North Addition, Basement-3rd Floors, 117	ASSUMED	SURFACE	N	NONE			Yes	ACBM with the potential for damage		LOW
82	Joint Compound	14,000	LF	North Addition, Basement-3rd Floors	ASSUMED	SURFACE	N	NONE			Yes	ACBM with the potential for damage		LOW
83	12" x 12" Floor Tile Checkered Brown/Streaks	400	SF	Room 216, 204	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
84	12" x 12" Floor Tile Checkered Brown/Streaks Mastic	400	SF	Room 216, 305, 307	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
85	12" x 12" Floor Tile Checkered White/Streak	2,000	SF	Room 216,	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
86	12" x 12" Floor Tile Checkered White/Streak Mastic	2,000	SF	Room 216, 305, 307, 204,	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
87	Tan Linoleum	1,188	SF	Rooms 314, 317	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
88	Tan Linoleum Adhesive	1,188	SF	Rooms 314, 317	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
89	4" x 4" Vinyl Wall Covering			MATERIAL REMOVED	ASSUMED	MISC					Yes			
9	Mastic Under 12" x 12" Gray Vinyl Floor Tile			Throughout Building, 115 Bathroom	CHR	MISC					No			
90	4" x 4" Vinyl Wall Covering Adhesive			MATERIAL REMOVED	ASSUMED	MISC					No			
91	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile	2,039	SF	Basement Recreation Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
92	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile Mastic	2,039	SF	Basement Recreation Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
93	Tongue and Groove Wood Flooring	800	SF	Auditorium, Gym	ASSUMED	MISC	N	NONE			Yes	ACBM with the		LOW

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
94	12" x 12" Tan w/ Red Marbling Floor Tile	400	SF	Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom	ASSUMED	MISC	N	NONE			Yes	ACBM with potential for significant damage		LOW
95	12" x 12" Gray w/ Dark Gray and White Marbling Floor Tile	400	SF	Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
96	12" x 12" Tan and Gray Marbled Floor Tile Mastic	800	SF	Room 105, 104, 106, 108, 112, 114, 119, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
97	1' x 1' Dot Pattern Ceiling Tile	800	SF	Room 110, 102	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
98	Adhesive Associated w/ 1' x 1' Dot Pattern Ceiling Tile	800	SF	Room 110	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
99	12" x 12" Green w/ White Streak Floor Tile	800	SF	Clinic 121a, 132, 133	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation	4,300	LF	Throughout Building	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Aircell Pipe Insulation	2,050	LF	Throughout Building	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
C	Hard Elbows on Aircell	600	LF	Throughout Building	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Hard Elbows on Aircell	350	LF	Throughout Building	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Aircell Pipe Insulation	500	LF	Throughout Building	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable		LOW

# Chicago Public Schools

School Williams School Unit 25891 Building ID 6490  
Address 2710 S. Dearborn St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
											suspect ACBM			
F	Aircell Pipe Insulation	1,500	LF	Throughout Building	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Aircell	500	LF	Throughout Building	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
H	Hard Elbows on Aircell	50	SF	Throughout Building	CHR	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Boiler Insulation			ABATED	ABATED	TSI					Yes			
O	Boiler Gaskets			ABATED	ABATED	TSI					No			

# Chicago Public Schools

School Williams School Unit 25891 Building ID 6490  
Address 2710 S. Dearborn St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>4/10/2025</u>
Inspector Name <u>Jose Escobedo</u>
<u>100-06435</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	Material not observed - 2025
100	
101	
102	
103	
104	
105	Damage in front of basement elevator
106	
107	
108	
109	
11	Material not observed - 2025
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
12	Material not observed - 2025

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
120	
121	
122	
123	
124	
125	
126	
127	
128	
13	Material not observed - 2025
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	Material not observed - 2025
31	Material not observed - 2025

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	Material not observed - 2025
42	
43	Material not observed - 2025
44	Material not observed - 2025
45	Material not observed - 2025
46	Material not observed - 2025
47	
48	
49	
5	Material not observed - 2025
50	Material not observed - 2025
51	Material not observed - 2025
52	
53	
54	
55	
56	
57	
58	

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
59	
6	Material not observed - 2025
60	
61	
62	Material not observed - 2025
63	Material not observed - 2025
64	
65	
66	Associated with HA's 64 & 65
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	Material not observed - 2025
76	Material not observed - 2025
77	
78	
79	
8	
80	
81	
82	
83	
84	

# Chicago Public Schools

School Williams School Unit 25891 Building ID 6490  
Address 2710 S. Dearborn St. Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
85	
86	
87	
88	
89	
9	Material not observed - 2025
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	
D	
E	
F	
G	
H	
I	
O	

# Chicago Public Schools

**School** Williams School **Unit** 25891 **Building ID** 6490  
**Address** 2710 S. Dearborn St. **Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Hard Coat Plaster	350,000	SF	Throughout Building	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
10	Mastic Under 12" x 12" Brown Floor Tile			Throughout Building	Chrysotile	MISC					Follow O&M Plan
100	12" x 12" Green w/ White Streak Floor Tile Mastic	800	SF	Clinic 121a, 132, 133	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile	600	SF	Room 125, 126, 129, 130	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile Mastic	600	SF	Room 125, 126, 129, 130	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Red and Tan Terrazzo	500	LF	Stairwells	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" Gray Mottled Floor Tile	400	SF	Rooms 303, 304, 305, 306, 307, 309, , 316, 318, 319, 301,203,214, 116, 117, basement weight room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Yellow Mottled Floor Tile	400	SF	Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319, 301,203,214, basement , 116	Assumed	MISC	No	5	SF	6 ACBM with the potential for damage	Remove
106	12" x 12" Gray and Yellow Mottled Floor Tile Mastic	800	SF	Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319,203,214, 116, 117, basement	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
107	2" x 2" Gray Ceramic Floor Tile	1,000	SF	1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
108	2" x 2" Gray Ceramic Floor Tile Grout	1,000	SF	1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
109	5" x 12" Beige Ceramic Wall Tile	2,000	SF	3rd Floor Boys and Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Mastic Under 9" x 9" Beige Vinyl Floor Tile			Room 302	Chrysotile	MISC					Follow O&M Plan
110	5" x 12" Beige Ceramic Wall Tile Grout	2,000	SF	3rd Floor Boys and Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
111	2" x 2" Brown Ceramic Tile	20	SF	3rd Floor North All Gender Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Williams School

Unit 25891

Building ID 6490

Address 2710 S. Dearborn St.

Chicago, IL, 60616

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
112	2" x 2" Brown Ceramic Tile Grout	20	SF	3rd Floor North All Gender Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
113	2' x 2' Beige Ceramic Wall Tile	150	SF	3rd Floor North All Gender Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
114	2' x 2' Beige Ceramic Wall Tile Grout	150	SF	3rd Floor North All Gender Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
115	6" x 6" Gray Ceramic Tile	200	SF	3rd Floor South All Genders Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
116	6" x 6" Gray Ceramic Tile Grout	200	SF	3rd Floor South All Genders Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
117	1' x 2' Dark Gray Wall Tile	200	SF	3rd Floor South All Genders Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
118	1' x 2' Dark Gray Wall Tile Grout	200	SF	3rd Floor South All Genders Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
119	12" x 12" Light Beige Ceramic Floor Tile	50	SF	2nd Floor Staff Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Mastic Under Linoleum Floor Cover			Room 115	Assumed	MISC					Follow O&M Plan
120	12" x 12" Light Beige Ceramic Floor Tile Grout	50	SF	2nd Floor Staff Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
121	16' x 20' Light Gray Wall Tile	700	SF	Gymnasium Hallway First Floor - Lobby	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
122	16' x 20' Light Gray Wall Tile Grout	700	SF	Gymnasium Hallway First Floor - Lobby	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
123	2" x 2" Red Ceramic Floor Tile	75	SF	Room 113 Bathroom, Room 115 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
124	2" x 2" Red Ceramic Floor Tile Grout	75	SF	Room 113 Bathroom, Room 115 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
125	4' x 4' Beige Ceramic Wall Tile	75	SF	Room 113 Bathroom, Room 115 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
126	4' x 4' Beige Ceramic Wall Tile Grout	75	SF	Room 113 Bathroom, Room 115 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
127	4" x 4" Mosaic Floor Tile	100	SF	1st Floor Vestibule South End, Room 101 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
128	4" x 4" Mosaic Floor Tile Grout	100	SF	1st Floor Vestibule South End, Room 101 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Mastic Under Linoleum Counter Tops			Rooms 116,	Assumed	MISC					Follow O&M Plan
14	12" x 12" Green Vinyl Floor Tile			ABATED	Abated	MISC					
15	12" x 12" Red Vinyl Floor Tile			ABATED	Abated	MISC					
16	12" x 12" Beige Vinyl Floor Tile			ABATED	Abated	MISC					
17	12" x 12" Light Brown Vinyl Floor Tile			ABATED	Abated	MISC					
18	Mastic Under 12" x 12" Green Vinyl Floor Tile			ABATED	Abated	MISC					
19	Mastic Under 12" x 12" Red Vinyl Floor Tile			ABATED	Abated	MISC					
20	Mastic Under 12" x 12" Beige Vinyl Floor Tile			ABATED	Abated	MISC					
21	Mastic Under 12" x 12" Light Brown Vinyl Floor Tile			ABATED	Abated	MISC					
22	Fire Door Insulation	5,000	SF	Boiler Room and Air Tunnels	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Vault Door Insulation	25	SF	Main Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Williams School

Unit 25891

Building ID 6490

Address 2710 S. Dearborn St.

Chicago, IL, 60616

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
24	Exterior Brick - Non-AHERA			Building Structure	No ACBM	MISC					
25	Exterior Brick Mortar - Non-AHERA			Exterior Building Structure	No ACBM	MISC					
26	Transite Lab Tables	200	SF	Room 302	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Roofing Material - Non-AHERA			Roof	Assumed	MISC					
28	12" x 12" Aqua Floor Tile	800	SF	Main Office, Room 109, 115, 117	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Aqua Floor Tile Mastic	800	SF	Main Office, Room 203, 109, 115, 117	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3	12" x 12" Gray Vinyl Floor Tile	45,000	SF	Throughout Building	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" White w/ Red Floor Tile			Room 103	Assumed	MISC					Follow O&M Plan
31	12" x 12" White w/ Red Floor Tile Mastic			Room 103	Assumed	MISC					Follow O&M Plan
32	12" x 12" Beige Speckled Floor Tile			ABATED	Abated	MISC					
33	12" x 12" Beige Speckled Floor Tile Mastic			ABATED	Abated	MISC					
34	12" x 12" Brown Speckled Floor Tile			ABATED	Abated	MISC					
35	12" x 12" Brown Speckled Floor Tile Mastic			ABATED	Abated	MISC					
36	12" x 12" White w/ Rainbow Specks Floor Tile			ABATED	Abated	MISC					
37	12" x 12" White w/ Rainbow Specks Floor Tile Mastic			ABATED	Abated	MISC					
38	12" x 12" Light Brown w/ White & Brown Streaks Floor Tile			ABATED	Abated	MISC					
39	12" x 12" Brown w/ White & Brown Streaks Floor Tile			ABATED	Abated	MISC					
4	12" x 12" Brown Vinyl Floor Tile			ABATED	Abated	MISC					
40	12" x 12" Gray w/ White & Black Streaks Floor Tile			ABATED	Abated	MISC					
41	12" x 12" Gray w/ White & Black Streaks Floor Tile Mastic			Room 214	Chrysotile	MISC					Follow O&M Plan
42	Carpet Mastic	1,000	SF	Library, Room 203, Main Office, 100, 103, 221, 321	Assumed	MISC	No		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
43	9" x 9" Brown Floor Tile			3rd Floor Teachers' Bathroom	Chrysotile	MISC					Follow O&M Plan
44	9" x 9" Brown Floor Tile Mastic			3rd Floor Teachers' Bathroom	Chrysotile	MISC					Follow O&M Plan
45	9" x 9" Gray Floor Tile			3rd Floor Teachers' Bathroom	Chrysotile	MISC					Follow O&M Plan
46	9" x 9" Gray Floor Tile Mastic			3rd Floor Teachers' Bathroom	Chrysotile	MISC					Follow O&M Plan
47	4" Gray Vinyl Baseboard	5,000	LF	Rooms 203, 214	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
48	4" Gray Vinyl Baseboard Mastic	5,000	LF	Rooms 203, 214	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
49	Interior Window Caulk	8,000	LF	Throughout	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
5	9" x 9" Beige Vinyl Floor Tile			Room 302	Chrysotile	MISC					Follow O&M Plan
50	Green Linoleum Counter Top			Room 115	Assumed	MISC					Follow O&M Plan

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
51	Green Linoleum Counter Top Mastic			Room 115	Assumed	MISC					Follow O&M Plan
52	Interior Door Caulk	50	LF	West Entrance	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
53	Carpet Mastic	400	SF	Auditorium (1954 Addition)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Spray-on Fireproofing	5,000	SF	Auditorium (1954 Addition)	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
55	6" Brown Vinyl Baseboard	450	LF	Lunchroom (1995 Addition) and Room 302	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
56	6" Brown Vinyl Baseboard Mastic	450	LF	Lunchroom (1995 Addition) and Room 302	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
57	Interior Window Caulk	100	LF	Lunchroom (1995 Addition)	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
58	2' x 4' Plain Ceiling Tile	4,000	SF	Lunchroom (1995 Addition), Basement Weight Room	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
59	2' x 2' Fissured Ceiling Tile	1,000	LF	Hallway by Lunchroom (1995 Addition), 121a Clinic	Assumed	MISC	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
6	Linoleum Floor Covering			Room 102	Assumed	MISC					Follow O&M Plan
60	Linoleum Flooring	5,000	SF	Lunchroom/Serving Area (1995 Addition) 302, 107, 110, 314, 317	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Linoleum Flooring Mastic	5,000	SF	Lunchroom/ Serving Area (1995 Addition) 300, 107, 110, 314, 317	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
62	9" x 9" Green Floor Tile			Basement: Recreation Room	Chrysotile	MISC					Follow O&M Plan
63	9" x 9" Green Floor Tile Mastic			Basement: Recreation Room	Chrysotile	MISC					Follow O&M Plan
64	12" x 12" Beige w/ Light Beige Streaks Checkerboard Vinyl Floor Tile	8,625	SF	1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
65	12" x 12" Cream w/ Beige Streaks Checkerboard Vinyl Floor Tile	8,625	SF	1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
66	Mastic Associated w/ Checkerboard Pattern Floor Tile	17,250	SF	1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Williams School

Unit 25891

Building ID 6490

Address 2710 S. Dearborn St.

Chicago, IL, 60616

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
67	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile	1,425	SF	Rooms 215, 109, 115, 211	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
68	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile Mastic	1,425	SF	Rooms 215, 109, 115, 211, 221	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Light Blue Vinyl Floor Tile	525	SF	Rooms 215, 211, 121a	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Acoustical Spray on Plaster			ABATED	Abated	SURFACE					
70	12" x 12" Light Blue Vinyl Floor Tile Mastic	525	SF	Rooms 215	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12" x 12" Vinyl Floor Tile Tan/Checkered	400	SF	North Basement Corridors, Teachers' Lunchrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" x 12" Vinyl Floor Tile Tan/Checkered Mastic	400	SF	North Basement Corridors, Teachers' Lunchrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" Vinyl Floor Tile White Checkered	400	SF	North Basement Corridors, Teachers' Lunchrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Vinyl Floor Tile White Checkered Mastic	400	SF	North Basement Corridors, Teachers' Lunchrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Red Linoleum			Basement, Weight Room	Assumed	MISC					Follow O&M Plan
76	Red Linoleum Adhesive			Basement, Weight Room	Assumed	MISC					Follow O&M Plan
77	Boiler Gasket	10	SF	Boiler Room	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
78	Pump Gaskets	10	SF	Boiler Room	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
79	Covebase	200	SF	North Basement Corridors, Teachers' Lunchroom, Weight Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Linoleum Counter Tops			Rooms 115, 116, 117	No ACBM	MISC					
80	Covebase Adhesive	200	SF	North Basement Corridors, Teachers' Lunchroom, Weight Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Drywall	14,000	SF	North Addition, Basement-3rd Floors, 117	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
82	Joint Compound	14,000	LF	North Addition, Basement-3rd Floors	Assumed	SURFACE	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" Floor Tile Checkered Brown/Streaks	400	SF	Room 216, 204	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
84	12" x 12" Floor Tile Checkered Brown/Streaks Mastic	400	SF	Room 216, 305, 307	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
85	12" x 12" Floor Tile Checkered White/Streak	2,000	SF	Room 216,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Floor Tile Checkered White/Streak Mastic	2,000	SF	Room 216, 305, 307, 204,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Tan Linoleum	1,188	SF	Rooms 314, 317	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Tan Linoleum Adhesive	1,188	SF	Rooms 314, 317	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School Williams School

Unit 25891

Building ID 6490

Address 2710 S. Dearborn St.

Chicago, IL, 60616

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
89	4" x 4" Vinyl Wall Covering			MATERIAL REMOVED	Assumed	MISC					
9	Mastic Under 12" x 12" Gray Vinyl Floor Tile			Throughout Building, 115 Bathroom	Chrysotile	MISC					Follow O&M Plan
90	4" x 4" Vinyl Wall Covering Adhesive			MATERIAL REMOVED	Assumed	MISC					
91	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile	2,039	SF	Basement Recreation Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile Mastic	2,039	SF	Basement Recreation Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
93	Tongue and Groove Wood Flooring	800	SF	Auditorium, Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Tan w/ Red Marbling Floor Tile	400	SF	Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom	Assumed	MISC	No		SF	5 ACBM with potential for significant damage	Follow O&M Plan
95	12" x 12" Gray w/ Dark Gray and White Marbling Floor Tile	400	SF	Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
96	12" x 12" Tan and Gray Marbled Floor Tile Mastic	800	SF	Room 105, 104, 106, 108, 112, 114, 119, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
97	1' x 1' Dot Pattern Ceiling Tile	800	SF	Room 110, 102	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Adhesive Associated w/ 1' x 1' Dot Pattern Ceiling Tile	800	SF	Room 110	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12" x 12" Green w/ White Streak Floor Tile	800	SF	Clinic 121a, 132, 133	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation	4,300	LF	Throughout Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Aircell Pipe Insulation	2,050	LF	Throughout Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Hard Elbows on Aircell	600	LF	Throughout Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Hard Elbows on Aircell	350	LF	Throughout Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Aircell Pipe Insulation	500	LF	Throughout Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Aircell Pipe Insulation	1,500	LF	Throughout Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Aircell	500	LF	Throughout Building	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
H	Hard Elbows on Aircell	50	SF	Throughout Building	Chrysotile	TSI	Yes		SF	suspect ACBM 7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Boiler Insulation			ABATED	Abated	TSI					
O	Boiler Gaskets			ABATED	Abated	TSI					

HA Number	Management Comments
-----------	---------------------

# Chicago Public Schools

School Williams School

Unit 25891

Building ID 6490

Address 2710 S. Dearborn St.

Chicago, IL, 60616

Region 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Review Date	5/6/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	Sample to determine ACM content prior to disturbance.
10	If identified, continue O&M
100	Sample to determine ACM content prior to disturbance.
101	Sample to determine ACM content prior to disturbance.
102	Sample to determine ACM content prior to disturbance.
103	Sample to determine ACM content prior to disturbance.
104	Sample to determine ACM content prior to disturbance.
105	Sample to determine ACM content, remove and replace damaged material.
106	Sample to determine ACM content prior to disturbance.
107	Sample to determine ACM content prior to disturbance.
108	Sample to determine ACM content prior to disturbance.
109	Sample to determine ACM content prior to disturbance.
11	If identified, continue O&M
110	Sample to determine ACM content prior to disturbance.
111	Sample to determine ACM content prior to disturbance.
112	Sample to determine ACM content prior to disturbance.
113	Sample to determine ACM content prior to disturbance.
114	Sample to determine ACM content prior to disturbance.
115	Sample to determine ACM content prior to disturbance.
116	Sample to determine ACM content prior to disturbance.
117	Sample to determine ACM content prior to disturbance.
118	Sample to determine ACM content prior to disturbance.
119	Sample to determine ACM content prior to disturbance.
12	If identified, continue O&M
120	Sample to determine ACM content prior to disturbance.
121	Sample to determine ACM content prior to disturbance.
122	Sample to determine ACM content prior to disturbance.

### *Management Planner's Comments Summarized at the End of the Report*

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
123	Sample to determine ACM content prior to disturbance.
124	Sample to determine ACM content prior to disturbance.
125	Sample to determine ACM content prior to disturbance.
126	Sample to determine ACM content prior to disturbance.
127	Sample to determine ACM content prior to disturbance.
128	Sample to determine ACM content prior to disturbance.
13	If identified, continue O&M
14	
15	
16	
17	
18	
19	
20	
21	
22	Sample to determine ACM content prior to disturbance.
23	Sample to determine ACM content prior to disturbance.
24	Non-AHERA
25	Non-AHERA
26	Sample to determine ACM content prior to disturbance.
27	Non-AHERA
28	Sample to determine ACM content prior to disturbance.
29	Sample to determine ACM content prior to disturbance.
3	
30	If identified, continue O&M
31	If identified, continue O&M
32	

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	If identified, continue O&M
42	Sample to determine ACM content prior to disturbance.
43	If identified, continue O&M
44	If identified, continue O&M
45	If identified, continue O&M
46	If identified, continue O&M
47	Sample to determine ACM content prior to disturbance.
48	Sample to determine ACM content prior to disturbance.
49	Sample to determine ACM content prior to disturbance.
5	If identified, continue O&M
50	If identified, continue O&M
51	If identified, continue O&M
52	Sample to determine ACM content prior to disturbance.
53	Sample to determine ACM content prior to disturbance.
54	Sample to determine ACM content prior to disturbance.
55	Sample to determine ACM content prior to disturbance.
56	Sample to determine ACM content prior to disturbance.
57	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
58	Sample to determine ACM content prior to disturbance.
59	Sample to determine ACM content prior to disturbance.
6	If identified, continue O&M
60	Sample to determine ACM content prior to disturbance.
61	Sample to determine ACM content prior to disturbance.
62	If identified, continue O&M
63	If identified, continue O&M
64	Sample to determine ACM content prior to disturbance.
65	Sample to determine ACM content prior to disturbance.
66	Sample to determine ACM content prior to disturbance.
67	Sample to determine ACM content prior to disturbance.
68	Sample to determine ACM content prior to disturbance.
69	Sample to determine ACM content prior to disturbance.
7	
70	Sample to determine ACM content prior to disturbance.
71	Sample to determine ACM content prior to disturbance.
72	Sample to determine ACM content prior to disturbance.
73	Sample to determine ACM content prior to disturbance.
74	Sample to determine ACM content prior to disturbance.
75	If identified, continue O&M
76	If identified, continue O&M
77	Sample to determine ACM content prior to disturbance.
78	Sample to determine ACM content prior to disturbance.
79	Sample to determine ACM content prior to disturbance.
8	
80	Sample to determine ACM content prior to disturbance.
81	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
82	Sample to determine ACM content prior to disturbance.
83	Sample to determine ACM content prior to disturbance.
84	Sample to determine ACM content prior to disturbance.
85	Sample to determine ACM content prior to disturbance.
86	Sample to determine ACM content prior to disturbance.
87	Sample to determine ACM content prior to disturbance.
88	Sample to determine ACM content prior to disturbance.
89	
9	If identified, continue O&M
90	
91	Sample to determine ACM content prior to disturbance.
92	Sample to determine ACM content prior to disturbance.
93	Sample to determine ACM content prior to disturbance.
94	Sample to determine ACM content prior to disturbance.
95	Sample to determine ACM content prior to disturbance.
96	Sample to determine ACM content prior to disturbance.
97	Sample to determine ACM content prior to disturbance.
98	Sample to determine ACM content prior to disturbance.
99	Sample to determine ACM content prior to disturbance.
A	
B	
C	
D	
E	
F	
G	
H	

# Chicago Public Schools

**School** Williams School

**Unit** 25891

**Building ID** 6490

**Address** 2710 S. Dearborn St.

Chicago, IL, 60616

**Region** 04

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
I	
O	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>1</b>		
MATERIAL DESCRIPTION:	<b>Hard Coat Plaster</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b> <b>Vibration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout Building</b>		
MATERIAL QUANTITY:	<b>350000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **350000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10	
MATERIAL DESCRIPTION:	Mastic Under 12" x 12" Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>100</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Green w/ White Streak Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Clinic 121a, 132, 133</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **12" x 12" Green w/ White Streak Floor Tile Mastic**

MATERIAL LOCATION: **Clinic 121a, 132, 133**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>101</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blue w/ White and Dark Blue Streak Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 125, 126, 129, 130</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ White and Dark Blue Streak Floor Tile**

MATERIAL LOCATION: **Room 125, 126, 129, 130**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12" x 12" Blue w/ White and Dark Blue Streak Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 125, 126, 129, 130		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ White and Dark Blue Streak Floor Tile Mastic**

MATERIAL LOCATION: **Room 125, 126, 129, 130**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>103</b>		
MATERIAL DESCRIPTION:	<b>Red and Tan Terrazzo</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Stairwells</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Red and Tan Terrazzo**

MATERIAL LOCATION: **Stairwells**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>104</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray Mottled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 303, 304, 305, 306, 307, 309, , 316, 318, 319, 301,203,214, 116, 117, basement weight room**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" Gray Mottled Floor Tile**

MATERIAL LOCATION: **Rooms 303, 304, 305, 306, 307, 309, , 316, 318, 319, 301,203,214, 116, 117, basement weight room**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>105</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Yellow Mottled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	<b>Deterioration</b>		
DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319, 301,203,214, basement , 116</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:	<b>Damage in front of basement elevator</b>		

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12" x 12" Yellow Mottled Floor Tile**

MATERIAL LOCATION: **Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319, 301,203,214, basement , 116**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content, remove and replace damaged material.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>106</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray and Yellow Mottled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319, 203, 214, 116, 117, basement</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **12" x 12" Gray and Yellow Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 303, 304, 305, 306, 307, 309, 316, 318, 319, 203, 214, 116, 117, basement**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>11</b>	
MATERIAL DESCRIPTION:	<b>Mastic Under 9" x 9" Beige Vinyl Floor Tile</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Mastic Under 9" x 9" Beige Vinyl Floor Tile**

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>12</b>	
MATERIAL DESCRIPTION:	<b>Mastic Under Linoleum Floor Cover</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 115**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Mastic Under Linoleum Floor Cover**

MATERIAL LOCATION: **Room 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>13</b>	
MATERIAL DESCRIPTION:	<b>Mastic Under Linoleum Counter Tops</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 116,**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Mastic Under Linoleum Counter Tops**

MATERIAL LOCATION: **Rooms 116,**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Green Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Green Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Red Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Beige Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Beige Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17

MATERIAL DESCRIPTION: 12" x 12" Light Brown Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Green Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Green Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>19</b>	
MATERIAL DESCRIPTION:	<b>Mastic Under 12" x 12" Red Vinyl Floor Tile</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	<b>Abated</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Red Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Beige Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Beige Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Light Brown Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Light Brown Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>22</b>		
MATERIAL DESCRIPTION:	<b>Fire Door Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boiler Room and Air Tunnels</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Fire Door Insulation**

MATERIAL LOCATION: **Boiler Room and Air Tunnels**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Vault Door Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Vault Door Insulation**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>24</b>	
MATERIAL DESCRIPTION:	<b>Exterior Brick - Non-AHERA</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	<b>No ACBM</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Structure**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Building Structure**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior Building Structure**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior Building Structure**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>26</b>		
MATERIAL DESCRIPTION:	<b>Transite Lab Tables</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 302</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Transite Lab Tables**

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>28</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Aqua Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office, Room 109, 115, 117</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile**

MATERIAL LOCATION: **Main Office, Room 109, 115, 117**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>29</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Aqua Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office, Room 203, 109, 115, 117</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Aqua Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Room 203, 109, 115, 117**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>3</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout Building</b>		
MATERIAL QUANTITY:	<b>45000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Gray Vinyl Floor Tile**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>30</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Red Floor Tile</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" White w/ Red Floor Tile**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31

MATERIAL DESCRIPTION: 12" x 12" White w/ Red Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 103

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" White w/ Red Floor Tile Mastic**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34

MATERIAL DESCRIPTION: 12" x 12" Brown Speckled Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 35  
MATERIAL DESCRIPTION: 12" x 12" Brown Speckled Floor Tile Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" White w/ Rainbow Specks Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" White w/ Rainbow Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37

MATERIAL DESCRIPTION: 12" x 12" White w/ Rainbow Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" White w/ Rainbow Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>38</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Light Brown w/ White &amp; Brown Streaks Floor Tile</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	<b>Abated</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White & Brown Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 39

MATERIAL DESCRIPTION: 12" x 12" Brown w/ White & Brown Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White & Brown Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 4

MATERIAL DESCRIPTION: 12" x 12" Brown Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" Brown Vinyl Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 40

MATERIAL DESCRIPTION: 12" x 12" Gray w/ White & Black Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White & Black Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41	
MATERIAL DESCRIPTION:	12" x 12" Gray w/ White & Black Streaks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 214

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White & Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 214**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>42</b>		
MATERIAL DESCRIPTION:	<b>Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Library, Room 203, Main Office, 100, 103, 221, 321</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Library, Room 203, Main Office, 100, 103, 221, 321**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 43  
MATERIAL DESCRIPTION: 9" x 9" Brown Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Teachers' Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **3rd Floor Teachers' Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teachers' Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Teachers' Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Teachers' Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**

MATERIAL LOCATION: **3rd Floor Teachers' Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46	
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Teachers' Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Teachers' Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>47</b>		
MATERIAL DESCRIPTION:	<b>4" Gray Vinyl Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 203, 214</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**

MATERIAL LOCATION: **Rooms 203, 214**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>48</b>		
MATERIAL DESCRIPTION:	<b>4" Gray Vinyl Baseboard Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 203, 214</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Rooms 203, 214**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>49</b>		
MATERIAL DESCRIPTION:	<b>Interior Window Caulk</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout</b>		
MATERIAL QUANTITY:	<b>8000</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 5  
MATERIAL DESCRIPTION: 9" x 9" Beige Vinyl Floor Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Chrysotile FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 302

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Beige Vinyl Floor Tile**

MATERIAL LOCATION: **Room 302**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Green Linoleum Counter Top**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 115**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Green Linoleum Counter Top**

MATERIAL LOCATION: **Room 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51	
MATERIAL DESCRIPTION:	Green Linoleum Counter Top Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 115

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Green Linoleum Counter Top Mastic**

MATERIAL LOCATION: **Room 115**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>52</b>		
MATERIAL DESCRIPTION:	<b>Interior Door Caulk</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>West Entrance</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **West Entrance**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>53</b>		
MATERIAL DESCRIPTION:	<b>Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium (1954 Addition)</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Auditorium (1954 Addition)**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>54</b>		
MATERIAL DESCRIPTION:	<b>Spray-on Fireproofing</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium (1954 Addition)</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Spray-on Fireproofing**

MATERIAL LOCATION: **Auditorium (1954 Addition)**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>55</b>		
MATERIAL DESCRIPTION:	<b>6" Brown Vinyl Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Lunchroom (1995 Addition) and Room 302</b>		
MATERIAL QUANTITY:	<b>450</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **6" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Lunchroom (1995 Addition) and Room 302**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>56</b>		
MATERIAL DESCRIPTION:	<b>6" Brown Vinyl Baseboard Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Lunchroom (1995 Addition) and Room 302</b>		
MATERIAL QUANTITY:	<b>450</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **6" Brown Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Lunchroom (1995 Addition) and Room 302**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Interior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom (1995 Addition)		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Lunchroom (1995 Addition)**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>58</b>		
MATERIAL DESCRIPTION:	<b>2' x 4' Plain Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Lunchroom (1995 Addition), Basement Weight Room</b>		
MATERIAL QUANTITY:	<b>4000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **2' x 4' Plain Ceiling Tile**

MATERIAL LOCATION: **Lunchroom (1995 Addition), Basement Weight Room**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	2' x 2' Fissured Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallway by Lunchroom (1995 Addition), 121a Clinic		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **2' x 2' Fissured Ceiling Tile**

MATERIAL LOCATION: **Hallway by Lunchroom (1995 Addition), 121a Clinic**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>6</b>	
MATERIAL DESCRIPTION:	<b>Linoleum Floor Covering</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Linoleum Floor Covering**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>60</b>		
MATERIAL DESCRIPTION:	<b>Linoleum Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Lunchroom/Serving Area (1995 Addition) 302, 107, 110, 314, 317</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Linoleum Flooring**

MATERIAL LOCATION: **Lunchroom/Serving Area (1995 Addition) 302, 107, 110, 314, 317**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>61</b>		
MATERIAL DESCRIPTION:	<b>Linoleum Flooring Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Lunchroom/ Serving Area (1995 Addition) 300, 107, 110, 314, 317</b>		
MATERIAL QUANTITY:	<b>5000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Linoleum Flooring Mastic**

MATERIAL LOCATION: **Lunchroom/ Serving Area (1995 Addition) 300, 107, 110, 314, 317**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement: Recreation Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**

MATERIAL LOCATION: **Basement: Recreation Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement: Recreation Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

MATERIAL LOCATION: **Basement: Recreation Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUILDING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Light Beige Streaks Checkerboard Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room**

MATERIAL QUANTITY: **8625** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Light Beige Streaks Checkerboard Vinyl Floor Tile**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room**

MATERIAL QUANTITY: **8625** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

#### Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>65</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Cream w/ Beige Streaks Checkerboard Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room**

MATERIAL QUANTITY: **8625** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ Beige Streaks Checkerboard Vinyl Floor Tile**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room**

MATERIAL QUANTITY: **8625** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUILDING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	Mastic Associated w/ Checkerboard Pattern Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room**

MATERIAL QUANTITY: **17250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **Associated with HA's 64 & 65**

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUILDING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Mastic Associated w/ Checkerboard Pattern Floor Tile**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, Room 101, Rooms 113 - 119, Principal's Office, 200, 202, 214, 301, 3rd Floor Teachers' Bathroom, 121a, Basement Weight Room**

MATERIAL QUANTITY: **17250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

#### Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>67</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 215, 109, 115, 211**

MATERIAL QUANTITY: **1425** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 215, 109, 115, 211**

MATERIAL QUANTITY: **1425** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 215, 109, 115, 211,221		
MATERIAL QUANTITY:	1425	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Dark Beige Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 215, 109, 115, 211,221**

MATERIAL QUANTITY: **1425** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>69</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Blue Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 215, 211, 121a</b>		
MATERIAL QUANTITY:	<b>525</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	<b>SF</b>		
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 215, 211, 121a**

MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7

MATERIAL DESCRIPTION: Acoustical Spray on Plaster

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Acoustical Spray on Plaster**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>70</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Blue Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 215</b>		
MATERIAL QUANTITY:	<b>525</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 215**

MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile Tan/Checkered		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North Basement Corridors, Teachers' Lunchrooms		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Tan/Checkered**

MATERIAL LOCATION: **North Basement Corridors, Teachers' Lunchrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>72</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Vinyl Floor Tile Tan/Checkered Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>North Basement Corridors, Teachers' Lunchrooms</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile Tan/Checkered Mastic**

MATERIAL LOCATION: **North Basement Corridors, Teachers' Lunchrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>73</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Vinyl Floor Tile White Checkered</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>North Basement Corridors, Teachers' Lunchrooms</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White Checkered**

MATERIAL LOCATION: **North Basement Corridors, Teachers' Lunchrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74		
MATERIAL DESCRIPTION:	12" x 12" Vinyl Floor Tile White Checkered Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North Basement Corridors, Teachers' Lunchrooms		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12" x 12" Vinyl Floor Tile White Checkered Mastic**

MATERIAL LOCATION: **North Basement Corridors, Teachers' Lunchrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Red Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement, Weight Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Red Linoleum**

MATERIAL LOCATION: **Basement, Weight Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 76  
MATERIAL DESCRIPTION: Red Linoleum Adhesive  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement, Weight Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Red Linoleum Adhesive**

MATERIAL LOCATION: **Basement, Weight Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>77</b>		
MATERIAL DESCRIPTION:	<b>Boiler Gasket</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boiler Room</b>		
MATERIAL QUANTITY:	<b>10</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>78</b>		
MATERIAL DESCRIPTION:	<b>Pump Gaskets</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Boiler Room</b>		
MATERIAL QUANTITY:	<b>10</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BULDING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **Pump Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>79</b>		
MATERIAL DESCRIPTION:	<b>Covebase</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>North Basement Corridors, Teachers' Lunchroom, Weight Room</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Covebase**

MATERIAL LOCATION: **North Basement Corridors, Teachers' Lunchroom, Weight Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Linoleum Counter Tops**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 115, 116, 117**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Linoleum Counter Tops**

MATERIAL LOCATION: **Rooms 115, 116, 117**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>80</b>		
MATERIAL DESCRIPTION:	<b>Covebase Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>North Basement Corridors, Teachers' Lunchroom, Weight Room</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Covebase Adhesive**

MATERIAL LOCATION: **North Basement Corridors, Teachers' Lunchroom, Weight Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>81</b>		
MATERIAL DESCRIPTION:	<b>Drywall</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Vibration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>North Addition, Basement-3rd Floors, 117</b>		
MATERIAL QUANTITY:	<b>14000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **North Addition, Basement-3rd Floors, 117**

MATERIAL QUANTITY: **14000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>82</b>		
MATERIAL DESCRIPTION:	<b>Joint Compound</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>North Addition, Basement-3rd Floors</b>		
MATERIAL QUANTITY:	<b>14000</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **Joint Compound**

MATERIAL LOCATION: **North Addition, Basement-3rd Floors**

MATERIAL QUANTITY: **14000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>83</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Floor Tile Checkered Brown/Streaks</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216, 204</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Checkered Brown/Streaks**

MATERIAL LOCATION: **Room 216, 204**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>84</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Floor Tile Checkered Brown/Streaks Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216, 305, 307</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Checkered Brown/Streaks Mastic**

MATERIAL LOCATION: **Room 216, 305, 307**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>85</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Floor Tile Checkered White/Streak</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216,</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Checkered White/Streak**

MATERIAL LOCATION: **Room 216,**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>86</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Floor Tile Checkered White/Streak Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 216, 305, 307, 204,</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile Checkered White/Streak Mastic**

MATERIAL LOCATION: **Room 216, 305, 307, 204,**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>87</b>		
MATERIAL DESCRIPTION:	<b>Tan Linoleum</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 314, 317</b>		
MATERIAL QUANTITY:	<b>1188</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Tan Linoleum**

MATERIAL LOCATION: **Rooms 314, 317**

MATERIAL QUANTITY: **1188** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>88</b>		
MATERIAL DESCRIPTION:	<b>Tan Linoleum Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 314, 317</b>		
MATERIAL QUANTITY:	<b>1188</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Tan Linoleum Adhesive**

MATERIAL LOCATION: **Rooms 314, 317**

MATERIAL QUANTITY: **1188** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>89</b>	
MATERIAL DESCRIPTION:	<b>4" x 4" Vinyl Wall Covering</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **4" x 4" Vinyl Wall Covering**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9	
MATERIAL DESCRIPTION:	Mastic Under 12" x 12" Gray Vinyl Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building, 115 Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Mastic Under 12" x 12" Gray Vinyl Floor Tile**

MATERIAL LOCATION: **Throughout Building, 115 Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>90</b>	
MATERIAL DESCRIPTION:	<b>4" x 4" Vinyl Wall Covering Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **4" x 4" Vinyl Wall Covering Adhesive**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>91</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement Recreation Room</b>		
MATERIAL QUANTITY:	<b>2039</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile**

MATERIAL LOCATION: **Basement Recreation Room**

MATERIAL QUANTITY: **2039** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>92</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement Recreation Room</b>		
MATERIAL QUANTITY:	<b>2039</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Multi-Color (Gray, Blue, Green) Floor Tile Mastic**

MATERIAL LOCATION: **Basement Recreation Room**

MATERIAL QUANTITY: **2039** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>93</b>		
MATERIAL DESCRIPTION:	<b>Tongue and Groove Wood Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Auditorium, Gym</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **Tongue and Groove Wood Flooring**

MATERIAL LOCATION: **Auditorium, Gym**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>94</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan w/ Red Marbling Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Red Marbling Floor Tile**

MATERIAL LOCATION: **Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>95</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray w/ Dark Gray and White Marbling Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Gray and White Marbling Floor Tile**

MATERIAL LOCATION: **Room 105, 104, 106, 108, 112, 114, 119, 205, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

#### Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	96		
MATERIAL DESCRIPTION:	12" x 12" Tan and Gray Marbled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 105, 104, 106, 108, 112, 114, 119, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **12" x 12" Tan and Gray Marbled Floor Tile Mastic**

MATERIAL LOCATION: **Room 105, 104, 106, 108, 112, 114, 119, 218, 219, 217, 212, 210, 213, 208, 211, 209, 207, 206, 205, 201, 311, 308, 313, 310, 312, 315, 321 Bathroom**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>97</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' Dot Pattern Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110, 102</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **1' x 1' Dot Pattern Ceiling Tile**

MATERIAL LOCATION: **Room 110, 102**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>98</b>		
MATERIAL DESCRIPTION:	<b>Adhesive Associated w/ 1' x 1' Dot Pattern Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 110</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Adhesive Associated w/ 1' x 1' Dot Pattern Ceiling Tile**

MATERIAL LOCATION: **Room 110**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>99</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Green w/ White Streak Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Clinic 121a, 132, 133</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **12" x 12" Green w/ White Streak Floor Tile**

MATERIAL LOCATION: **Clinic 121a, 132, 133**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>A</b>		
MATERIAL DESCRIPTION:	<b>Aircell Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout Building</b>		
MATERIAL QUANTITY:	<b>4300</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **4300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>B</b>		
MATERIAL DESCRIPTION:	<b>Aircell Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout Building</b>		
MATERIAL QUANTITY:	<b>2050</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **2050**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Hard Elbows on Aircell		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Hard Elbows on Aircell**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Hard Elbows on Aircell		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Hard Elbows on Aircell**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **1500**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>G</b>		
MATERIAL DESCRIPTION:	<b>Aircell</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout Building</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Aircell**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>H</b>		
MATERIAL DESCRIPTION:	<b>Hard Elbows on Aircell</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout Building</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Hard Elbows on Aircell**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Boiler Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Boiler Gaskets**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUILDING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Williams School</b>	REVIEW DATE:	<b>5/6/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	<b>121</b>			
MATERIAL DESCRIPTION:	<b>16' x 20' Light Gray Wall Tile</b>			
MATERIAL LOCATION:	<b>Gymnasium Hallway First Floor - Lobby</b>			
MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>	
MATERIAL CATEGORY:	<b>MISC</b>	FRIABLE:	<b>No</b>	
ASBESTOS TYPE:	<b>Assumed</b>			
DISTURBANCE POTENTIAL:	<b>LOW</b>	CONDITION:	<b>No Damage</b>	
AHERA DAMAGE CATEGORY:	<b>6 ACBM with the potential for damage</b>			
ACCESSIBILITY:	<b>Within Reach</b>	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	<b>SF</b>	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **16' x 20' Light Gray Wall Tile**

MATERIAL LOCATION: **Gymnasium Hallway First Floor - Lobby**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	128		
MATERIAL DESCRIPTION:	4" x 4" Mosaic Floor Tile Grout		
MATERIAL LOCATION:	1st Floor Vestibule South End, Room 101 Bathroom		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **128**

MATERIAL DESCRIPTION: **4" x 4" Mosaic Floor Tile Grout**

MATERIAL LOCATION: **1st Floor Vestibule South End, Room 101 Bathroom**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	107			
MATERIAL DESCRIPTION:	2" x 2" Gray Ceramic Floor Tile			
MATERIAL LOCATION:	1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **2" x 2" Gray Ceramic Floor Tile**

MATERIAL LOCATION: **1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	111		
MATERIAL DESCRIPTION:	2" x 2" Brown Ceramic Tile		
MATERIAL LOCATION:	3rd Floor North All Gender Bathroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Tile**

MATERIAL LOCATION: **3rd Floor North All Gender Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	123		
MATERIAL DESCRIPTION:	2" x 2" Red Ceramic Floor Tile		
MATERIAL LOCATION:	Room 113 Bathroom, Room 115 Bathroom		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **2" x 2" Red Ceramic Floor Tile**

MATERIAL LOCATION: **Room 113 Bathroom, Room 115 Bathroom**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	113		
MATERIAL DESCRIPTION:	2' x 2' Beige Ceramic Wall Tile		
MATERIAL LOCATION:	3rd Floor North All Gender Bathroom		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **2' x 2' Beige Ceramic Wall Tile**

MATERIAL LOCATION: **3rd Floor North All Gender Bathroom**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	122			
MATERIAL DESCRIPTION:	16' x 20' Light Gray Wall Tile Grout			
MATERIAL LOCATION:	Gymnasium Hallway First Floor - Lobby			
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **16' x 20' Light Gray Wall Tile Grout**

MATERIAL LOCATION: **Gymnasium Hallway First Floor - Lobby**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	109			
MATERIAL DESCRIPTION:	5" x 12" Beige Ceramic Wall Tile			
MATERIAL LOCATION:	3rd Floor Boys and Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom			
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **5" x 12" Beige Ceramic Wall Tile**

MATERIAL LOCATION: **3rd Floor Boys and Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	124			
MATERIAL DESCRIPTION:	2" x 2" Red Ceramic Floor Tile Grout			
MATERIAL LOCATION:	Room 113 Bathroom, Room 115 Bathroom			
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **2" x 2" Red Ceramic Floor Tile Grout**

MATERIAL LOCATION: **Room 113 Bathroom, Room 115 Bathroom**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	108			
MATERIAL DESCRIPTION:	2" x 2" Gray Ceramic Floor Tile Grout			
MATERIAL LOCATION:	1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **2" x 2" Gray Ceramic Floor Tile Grout**

MATERIAL LOCATION: **1st Floor Boys and Girls Bathroom, 2nd Floor Boys and Girls Bathroom, 3rd Floor Boys and Girls Bathroom, 3rd Floor North All Gender Bathroom**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	2" x 2" Brown Ceramic Tile Grout		
MATERIAL LOCATION:	3rd Floor North All Gender Bathroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **2" x 2" Brown Ceramic Tile Grout**

MATERIAL LOCATION: **3rd Floor North All Gender Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	115		
MATERIAL DESCRIPTION:	6" x 6" Gray Ceramic Tile		
MATERIAL LOCATION:	3rd Floor South All Genders Bathroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **6" x 6" Gray Ceramic Tile**

MATERIAL LOCATION: **3rd Floor South All Genders Bathroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	116			
MATERIAL DESCRIPTION:	6" x 6" Gray Ceramic Tile Grout			
MATERIAL LOCATION:	3rd Floor South All Genders Bathroom			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **6" x 6" Gray Ceramic Tile Grout**

MATERIAL LOCATION: **3rd Floor South All Genders Bathroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	127			
MATERIAL DESCRIPTION:	4" x 4" Mosaic Floor Tile			
MATERIAL LOCATION:	1st Floor Vestibule South End, Room 101 Bathroom			
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **127**

MATERIAL DESCRIPTION: **4" x 4" Mosaic Floor Tile**

MATERIAL LOCATION: **1st Floor Vestibule South End, Room 101 Bathroom**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	110			
MATERIAL DESCRIPTION:	5" x 12" Beige Ceramic Wall Tile Grout			
MATERIAL LOCATION:	3rd Floor Boys and Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom			
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **5" x 12" Beige Ceramic Wall Tile Grout**

MATERIAL LOCATION: **3rd Floor Boys and Girls Bathroom Across 307, 3rd Floor Hallway, 3rd Floor North All Gender Bathroom, 2nd Floor, 2nd Floor Boys Bathroom**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: **05/06/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25891</b>	BUIDLING ID:	<b>6490</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Williams School</b>	INSPECTION DATE:	<b>4/10/2025</b>		
ADDRESS:	<b>2710 S. Dearborn St.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	<b>125</b>			
MATERIAL DESCRIPTION:	<b>4' x 4' Beige Ceramic Wall Tile</b>			
MATERIAL LOCATION:	<b>Room 113 Bathroom, Room 115 Bathroom</b>			
MATERIAL QUANTITY:	<b>75</b>	MATERIAL UNITS:	<b>SF</b>	
MATERIAL CATEGORY:	<b>MISC</b>	FRIABLE:	<b>No</b>	
ASBESTOS TYPE:	<b>Assumed</b>			
DISTURBANCE POTENTIAL:	<b>LOW</b>	CONDITION:	<b>No Damage</b>	
AHERA DAMAGE CATEGORY:	<b>6 ACBM with the potential for damage</b>			
ACCESSIBILITY:	<b>Within Reach</b>	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	<b>SF</b>	
COMMENTS:				

Inspector's Signature:

Date: **04/10/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **4' x 4' Beige Ceramic Wall Tile**

MATERIAL LOCATION: **Room 113 Bathroom, Room 115 Bathroom**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	117			
MATERIAL DESCRIPTION:	1' x 2' Dark Gray Wall Tile			
MATERIAL LOCATION:	3rd Floor South All Genders Bathroom			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **1' x 2' Dark Gray Wall Tile**

MATERIAL LOCATION: **3rd Floor South All Genders Bathroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	118			
MATERIAL DESCRIPTION:	1' x 2' Dark Gray Wall Tile Grout			
MATERIAL LOCATION:	3rd Floor South All Genders Bathroom			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **1' x 2' Dark Gray Wall Tile Grout**

MATERIAL LOCATION: **3rd Floor South All Genders Bathroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	2' x 2' Beige Ceramic Wall Tile Grout		
MATERIAL LOCATION:	3rd Floor North All Gender Bathroom		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **2' x 2' Beige Ceramic Wall Tile Grout**

MATERIAL LOCATION: **3rd Floor North All Gender Bathroom**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	119			
MATERIAL DESCRIPTION:	12" x 12" Light Beige Ceramic Floor Tile			
MATERIAL LOCATION:	2nd Floor Staff Bathroom			
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **12" x 12" Light Beige Ceramic Floor Tile**

MATERIAL LOCATION: **2nd Floor Staff Bathroom**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	126		
MATERIAL DESCRIPTION:	4' x 4' Beige Ceramic Wall Tile Grout		
MATERIAL LOCATION:	Room 113 Bathroom, Room 115 Bathroom		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **4' x 4' Beige Ceramic Wall Tile Grout**

MATERIAL LOCATION: **Room 113 Bathroom, Room 115 Bathroom**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25891	BUIDLING ID:	6490
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Williams School	INSPECTION DATE:	4/10/2025		
ADDRESS:	2710 S. Dearborn St.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	120			
MATERIAL DESCRIPTION:	12" x 12" Light Beige Ceramic Floor Tile Grout			
MATERIAL LOCATION:	2nd Floor Staff Bathroom			
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/10/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25891** BUIDLING ID: **6490**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Williams School** REVIEW DATE: **5/6/2025**

ADDRESS: **2710 S. Dearborn St.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **12" x 12" Light Beige Ceramic Floor Tile Grout**

MATERIAL LOCATION: **2nd Floor Staff Bathroom**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 05/06/2025

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Jose Escobedo**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2409132637  
Course Date: 9/13/2024  
Exam Date: 9/13/2024  
Expiration Date: 9/13/2025



Issue Date: 9/13/2024


  
Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

# Jose Escobedo

---

Air Sampling Professional, Illinois Licensed Building Inspector, Asbestos Project Manager



ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	1/11/2026
INSPECTOR	9/13/2025

PROJECT MANAGER	1/11/2026
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

---



OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

---

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Serio**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed