

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3528
SCHOOL NAME: Edwards Branch
ADDRESS OF SCHOOL: 4950 LaPorte
CITY: Chicago, IL, 60638

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 11/1/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/27/2025 ENROLLMENT 1204
IDPH INSPECTOR LICENSE NUMBER: 100-20994
IDPH LICENSED INSPECTOR NAME (Please Print): Cody Cummins
IDPH MP LICENSE NUMBER: 100-18488
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/23/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: 2024-11-20T00:00:00.000-06:00

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Edwards Branch

4950 LaPorte
Chicago, IL, 60638

Unit: 23081
Building ID: 6221

IDPH ID Number: 14-016-2990-3528

REPORT DATE:
Monday, June 23, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/23/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23081 Region: 04 IDPH ID: 14-016-2990-3528

School: Edwards Branch Building ID: 6221

Address: 4950 LaPorte

Chicago, IL, 60638

Building Contact: Pacewic, James Contact Phone: 3125760259

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/27/2025

Review Date: 06/23/2025

Inspector: Cody Cummins


Inspector IDPH License: 100-20994

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Mike Serio
100-18488

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 23, 2025

RE: Edwards Branch, Unit 23081
4950 LaPorte
Chicago, IL, 60638

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Edwards Branch, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Edwards Branch, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Edwards Branch Unit: 23081 Region: 04
Address: 4950 LaPorte Chicago, IL, 60638
IDPH ID: 14-016-2990-3528 Building ID: 6221
Contact: Pacewic, James Phone: 3125760259

2. Description of Facility

Original Construction: 1961 Additional Construction:
Total Square Footage: 15774 No of Floors: 1
Current Occupancy: 1204

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Cody Cummins



Signature:
Date: 5/27/2025

6. Management Planner

Management Planner Name: Mike Serio



Signature:
Date: 06/23/2025

7. Review Date: 06/23/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/23/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Edwards Branch. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6221:

06	Black Vinyl Baseboard Mastic
07	Black Vinyl Baseboard
09	Interior Window Glazing
11	2' x 4' Ceiling Tile w/ Fake 2' x 2' Pattern
13	12" x 12" Blue Mottle Floor Tile
14	12" x 12" Blue Mottle Floor Tile Mastic
15	Sink Insulation
16	Insulated Firedoors
17	Vault Door

23 Gray Vinyl Baseboard
23A Gray Vinyl Baseboard Mastic

B. The following new homogenous areas have been identified for Building 6221:

- 25 12" x 12" Beige Mottled Vinyl Floor Tile
- 26 12" x 12" Beige Mottled Vinyl Floor Tile Mastic
- 27 Drywall
- 28 Joint Compound
- 29 4" Beige Vinyl Baseboard
- 30 4" Beige Vinyl Baseboard Adhesive
- 31 Gray Sink Undercoating
- 32 1' x 1' Fissured Ceiling Tile
- 33 2' x 4' Tectum Ceiling Tile
- 34 Red Fireproofing Caulk

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05C	9" x 9" Light Brown Floor Tile Mastic
06	Black Vinyl Baseboard Mastic
07	Black Vinyl Baseboard
08	1' x 1' Ceiling Tile Mastic
09	Interior Window Glazing
11	2' x 4' Ceiling Tile w/ Fake 2' x 2' Pattern
12	Fire Proofing - Installed 2005
13	12" x 12" Blue Mottle Floor Tile
14	12" x 12" Blue Mottle Floor Tile Mastic
15	Sink Insulation
16	Insulated Firedoors
17	Vault Door
18	12" x 12" Gray w/ Black Specks Vinyl Floor Tile
18A	12" x 12" Gray w/ Black Specks Vinyl Floor Tile Mastic
19	12" x 12" Blue w/ Black Specks Vinyl Floor Tile
19A	12" x 12" Blue w/ Black Specks Vinyl Floor Tile Mastic
20	12" x 12" Peach w/ Black Specks Vinyl Floor Tile
20A	12" x 12" Peach w/ Black Specks Vinyl Floor Tile Mastic
21	12" x 12" Beige w/ Black Specks Floor Tile
21A	12" x 12" Beige w/ Black Specks Floor Tile Mastic
22	12" x 12" Green w/ Black Specks Vinyl Floor Tile
22A	12" x 12" Green w/ Black Specks Vinyl Floor Tile Mastic
23	Gray Vinyl Baseboard
23A	Gray Vinyl Baseboard Mastic
24	2' x 4' Ceiling Tile
25	12" x 12" Beige Mottled Vinyl Floor Tile
26	12" x 12" Beige Mottled Vinyl Floor Tile Mastic
27	Drywall
28	Joint Compound
29	4" Beige Vinyl Baseboard
30	4" Beige Vinyl Baseboard Adhesive
31	Gray Sink Undercoating
32	1' x 1' Fissured Ceiling Tile
33	2' x 4' Tectum Ceiling Tile
34	Red Fireproofing Caulk

The following areas were deemed to be inaccessible:

05A	9" x 9" Tan Floor Tile Mastic
05B	9" x 9" Brown Floor Tile Mastic
05C	9" x 9" Light Brown Floor Tile Mastic
26	12" x 12" Beige Mottled Vinyl Floor Tile Mastic
28	Joint Compound
30	4" Beige Vinyl Baseboard Adhesive
33	2' x 4' Tectum Ceiling Tile
34	Red Fireproofing Caulk

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Cody Cummins, IDPH License # 100-20994. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Edwards Branch Building 6221 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Edwards Branch **Unit** 23081 **Building ID** 6221
Address 4950 LaPorte **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03A	9" x 9" Tan Floor Tile	10,400	SF	Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
03B	9" x 9" Brown Floor Tile	409	SF	Hallway	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
03C	9" x 9" Light Brown Floor Tile	1,000	SF	Hallway, Main Office, Gymnasium	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
04	4' x 8' Transite Board				CHR	MISC					No			
05A	9" x 9" Tan Floor Tile Mastic	10,400	SF	Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
05B	9" x 9" Brown Floor Tile Mastic	409	SF	Hallway	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
05C	9" x 9" Light Brown Floor Tile Mastic	1,000	SF	Hallway, Main Office, Gymnasium	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
06	Black Vinyl Baseboard Mastic			Office, Room 606, 601, 602, 605, 610	ASSUMED	MISC					Yes			
07	Black Vinyl Baseboard			Office, Room 606, 601, 607, 608, 610	ASSUMED	MISC					Yes			
08	1' x 1' Ceiling Tile Mastic			Throughout Building	ASSUMED	MISC					No			
09	Interior Window Glazing			Throughout Building	ASSUMED	MISC					Yes			
10	Interior Window Caulk			ABATED	ABATED	MISC								
11	2' x 4' Ceiling Tile w/ Faux 2' x 2' Pattern			Corridor, Classrooms, Offices	ASSUMED	MISC					Yes			
12	Fire Proofing - Installed 2005	170	SF	Breezeway & Electrical	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Edwards Branch **Unit** 23081 **Building ID** 6221
Address 4950 LaPorte **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Switchgear Rooms										
13	12" x 12" Blue Mottle Floor Tile			Engineer's Office and Bathroom	ASSUMED	MISC					Yes			
14	12" x 12" Blue Mottle Floor Tile Mastic			Engineer's Office & Bathroom	ASSUMED	MISC					Yes			
15	Sink Insulation			Rooms 601, 604, 605, 606, 607, 608, 609 Room 128, 130,	ASSUMED	MISC					Yes			
16	Insulated Firedoors			Boiler Room, Gym	ASSUMED	MISC					Yes			
17	Vault Door			Office	ASSUMED	MISC					Yes			
18	12" x 12" Gray w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
18A	12" x 12" Gray w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
19	12" x 12" Blue w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
19A	12" x 12" Blue w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
20	12" x 12" Peach w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
20A	12" x 12" Peach w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
21	12" x 12" Beige w/ Black Specks Floor Tile			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
21A	12" x 12" Beige w/ Black Specks Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
22	12" x 12" Green w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
22A	12" x 12" Green w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	ASSUMED	MISC					No			
23	Gray Vinyl Baseboard	10,000	SF	2nd Floor Hallway, 225 Storage, 226,	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Edwards Branch **Unit** 23081 **Building ID** 6221
Address 4950 LaPorte **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom										
23A	Gray Vinyl Baseboard Mastic	10,000	SF	2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
24	2' x 4' Ceiling Tile			DUPLICATE HA	ASSUMED	MISC					No			
25	12" x 12" Beige Mottled Vinyl Floor Tile	50	SF	Rooms 505, 506, 507	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
26	12" x 12" Beige Mottled Vinyl Floor Tile Mastic	50	SF	Rooms 505, 506, 507	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
27	Drywall	2,000	SF	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
28	Joint Compound	2,000	SF	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509	ASSUMED	SURFACE	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
29	4" Beige Vinyl Baseboard	30	LF	Room 507	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
30	4" Beige Vinyl Baseboard Adhesive	30	SF	Room 507	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
31	Gray Sink Undercoating	2	SF	Teacher's Lounge	ASSUMED	SURFACE	N	NONE				ACBM with the potential for damage		LOW
32	1' x 1' Fissured Ceiling Tile	100	SF	Principal's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
33	2' x 4' Tectum Ceiling Tile	1,500	SF	Gymnasium	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
34	Red Fireproofing Caulk	5	LF	South Kitchen, Gymnasium	ASSUMED	SURFACE	Y	NONE				Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School Edwards Branch **Unit** 23081 **Building ID** 6221
Address 4950 LaPorte **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Edwards Branch Unit 23081 Building ID 6221
Address 4950 LaPorte Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>5/27/2025</u>
Inspector Name	<u>Cody Cummins</u>
100-20994	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
03A	
03B	
03C	
04	Material not observed - 2025
05A	
05B	
05C	
06	Material not observed - 2025
07	Material not observed - 2025
08	Material not observed - 2025
09	Material not observed - 2025
10	
11	Material not observed - 2025
12	
13	Material not observed - 2025
14	Material not observed - 2025
15	Material not observed - 2025
16	Material not observed - 2025
17	Material not observed - 2025
18	Material not observed - 2025
18A	Material not observed - 2025
19	Material not observed - 2025
19A	Material not observed - 2025
20	Material not observed - 2025

Chicago Public Schools

School Edwards Branch **Unit** 23081 **Building ID** 6221
Address 4950 LaPorte **Region** 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
20A	Material not observed - 2025
21	Material not observed - 2025
21A	Material not observed - 2025
22	Material not observed - 2025
22A	Material not observed - 2025
23	
23A	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
A	
B	
D	
E	

Table II
Management Planner's Review

Chicago Public Schools

School Edwards Branch

Unit 23081

Building ID 6221

Address 4950 LaPorte

Chicago, IL, 60638

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03A	9" x 9" Tan Floor Tile	10,400	SF	Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
03B	9" x 9" Brown Floor Tile	409	SF	Hallway	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
03C	9" x 9" Light Brown Floor Tile	1,000	SF	Hallway, Main Office, Gymnasium	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
04	4' x 8' Transite Board				Chrysotile	MISC					
05A	9" x 9" Tan Floor Tile Mastic	10,400	SF	Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
05B	9" x 9" Brown Floor Tile Mastic	409	SF	Hallway	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
05C	9" x 9" Light Brown Floor Tile Mastic	1,000	SF	Hallway, Main Office, Gymnasium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
06	Black Vinyl Baseboard Mastic			Office, Room 606, 601, 602, 605, 610	Assumed	MISC					
07	Black Vinyl Baseboard			Office, Room 606, 601, 607, 608, 610	Assumed	MISC					
08	1' x 1' Ceiling Tile Mastic			Throughout Building	Assumed	MISC					
09	Interior Window Glazing			Throughout Building	Assumed	MISC					
10	Interior Window Caulk			ABATED	Abated	MISC					
11	2' x 4' Ceiling Tile w/ Faux 2' x 2' Pattern			Corridor, Classrooms, Offices	Assumed	MISC					
12	Fire Proofing - Installed 2005	170	SF	Breezeway & Electrical Switchgear Rooms	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
13	12" x 12" Blue Mottle Floor Tile			Engineer's Office and Bathroom	Assumed	MISC					
14	12" x 12" Blue Mottle Floor Tile Mastic			Engineer's Office & Bathroom	Assumed	MISC					
15	Sink Insulation			Rooms 601, 604, 605, 606, 607, 608, 609 Room 128, 130,	Assumed	MISC					
16	Insulated Firedoors			Boiler Room, Gym	Assumed	MISC					
17	Vault Door			Office	Assumed	MISC					
18	12" x 12" Gray w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
18A	12" x 12" Gray w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps	Assumed	MISC					

Chicago Public Schools

School Edwards Branch

Unit 23081

Building ID 6221

Address 4950 LaPorte

Chicago, IL, 60638

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic			Owned							
19	12" x 12" Blue w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
19A	12" x 12" Blue w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
20	12" x 12" Peach w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
20A	12" x 12" Peach w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
21	12" x 12" Beige w/ Black Specks Floor Tile			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
21A	12" x 12" Beige w/ Black Specks Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
22	12" x 12" Green w/ Black Specks Vinyl Floor Tile			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
22A	12" x 12" Green w/ Black Specks Vinyl Floor Tile Mastic			Throughout Annex - No Longer Cps Owned	Assumed	MISC					
23	Gray Vinyl Baseboard	10,000	SF	2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23A	Gray Vinyl Baseboard Mastic	10,000	SF	2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	2' x 4' Ceiling Tile			DUPLICATE HA	Assumed	MISC					Follow O&M Plan
25	12" x 12" Beige Mottled Vinyl Floor Tile	50	SF	Rooms 505, 506, 507	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12" x 12" Beige Mottled Vinyl Floor Tile Mastic	50	SF	Rooms 505, 506, 507	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Drywall	2,000	SF	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
28	Joint Compound	2,000	SF	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Edwards Branch

Unit 23081

Building ID 6221

Address 4950 LaPorte

Chicago, IL, 60638

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
29	4" Beige Vinyl Baseboard	30	LF	Room 507	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
30	4" Beige Vinyl Baseboard Adhesive	30	SF	Room 507	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Gray Sink Undercoating	2	SF	Teacher's Lounge	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
32	1' x 1' Fissured Ceiling Tile	100	SF	Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	2' x 4' Tectum Ceiling Tile	1,500	SF	Gymnasium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Red Fireproofing Caulk	5	LF	South Kitchen, Gymnasium	Assumed	SURFACE	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
A	Aircell Pipe Insulation			ABATED	Abated	TSI					
B	Aircell Pipe Joints			ABATED	Abated	TSI					
D	Fiberglass Pipe Joints			ABATED	Abated	TSI					
E	Water Meter Packing			ABATED	Abated	TSI					

Chicago Public Schools

School Edwards Branch

Unit 23081

Building ID 6221

Address 4950 LaPorte

Chicago, IL, 60638

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	6/23/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
03A	
03B	
03C	
04	
05A	
05B	
05C	
06	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
18A	
19	
19A	
20	

Chicago Public Schools

School Edwards Branch

Unit 23081

Building ID 6221

Address 4950 LaPorte

Chicago, IL, 60638

Region 04

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
20A	
21	
21A	
22	
22A	
23	
23A	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
A	
B	
D	
E	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03A		
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508**

MATERIAL QUANTITY: **10400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **03A**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile**

MATERIAL LOCATION: **Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508**

MATERIAL QUANTITY: **10400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03B		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallway		
MATERIAL QUANTITY:	409	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **03B**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile**

MATERIAL LOCATION: **Hallway**

MATERIAL QUANTITY: **409** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03C		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallway, Main Office, Gymnasium		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **03C**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile**

MATERIAL LOCATION: **Hallway, Main Office, Gymnasium**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**
MATERIAL DESCRIPTION: **4' x 8' Transite Board**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **4' x 8' Transite Board**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05A		
MATERIAL DESCRIPTION:	9" x 9" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508**

MATERIAL QUANTITY: **10400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **05A**

MATERIAL DESCRIPTION: **9" x 9" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Gym, Main Office, Principal Office, Teachers' Bathroom, Rooms 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 501, Teacher's Lounge, 503, Unisex Bathroom, Janitor's Closet, 504, 505, 506, 507, 509, 508**

MATERIAL QUANTITY: **10400**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05B		
MATERIAL DESCRIPTION:	9" x 9" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallway		
MATERIAL QUANTITY:	409	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **05B**

MATERIAL DESCRIPTION: **9" x 9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Hallway**

MATERIAL QUANTITY: **409** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05C		
MATERIAL DESCRIPTION:	9" x 9" Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallway, Main Office, Gymnasium		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **05C**

MATERIAL DESCRIPTION: **9" x 9" Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Hallway, Main Office, Gymnasium**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office, Room 606, 601, 602, 605, 610**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Office, Room 606, 601, 602, 605, 610**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07	
MATERIAL DESCRIPTION:	Black Vinyl Baseboard	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office, Room 606, 601, 607, 608, 610**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **Office, Room 606, 601, 607, 608, 610**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Mastic**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**
MATERIAL DESCRIPTION: **Interior Window Glazing**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Interior Window Glazing**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Interior Window Caulk**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11	
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile w/ Faux 2' x 2' Pattern	
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Corridor, Classrooms, Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/ Faux 2' x 2' Pattern**

MATERIAL LOCATION: **Corridor, Classrooms, Offices**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Fire Proofing - Installed 2005		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Breezeway & Electrical Switchgear Rooms		
MATERIAL QUANTITY:	170	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Fire Proofing - Installed 2005**

MATERIAL LOCATION: **Breezeway & Electrical Switchgear Rooms**

MATERIAL QUANTITY: **170** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	12" x 12" Blue Mottle Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Engineer's Office and Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12" x 12" Blue Mottle Floor Tile**

MATERIAL LOCATION: **Engineer's Office and Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14	
MATERIAL DESCRIPTION:	12" x 12" Blue Mottle Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Engineer's Office & Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" Blue Mottle Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office & Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Sink Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 601, 604, 605, 606, 607, 608, 609
Room 128, 130,

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Sink Insulation**

MATERIAL LOCATION: **Rooms 601, 604, 605, 606, 607, 608, 609**

Room 128, 130,

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Insulated Firedoors		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room, Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Insulated Firedoors**

MATERIAL LOCATION: **Boiler Room, Gym**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Vault Door		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Vault Door**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Specks Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Specks Vinyl Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **18A**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black Specks Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black Specks Vinyl Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **19A**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Black Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Peach w/ Black Specks Vinyl Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" Peach w/ Black Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **12" x 12" Peach w/ Black Specks Vinyl Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **20A**

MATERIAL DESCRIPTION: **12" x 12" Peach w/ Black Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21

MATERIAL DESCRIPTION: 12" x 12" Beige w/ Black Specks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Annex - No Longer Cps Owned

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Black Specks Floor Tile**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 21A

MATERIAL DESCRIPTION: 12" x 12" Beige w/ Black Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Annex - No Longer Cps Owned

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **21A**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Black Specks Floor Tile Mastic**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22

MATERIAL DESCRIPTION: 12" x 12" Green w/ Black Specks Vinyl Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Annex - No Longer Cps Owned

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Green w/ Black Specks Vinyl Floor Tile**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22A

MATERIAL DESCRIPTION: 12" x 12" Green w/ Black Specks Vinyl Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Annex - No Longer Cps Owned

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **12" x 12" Green w/ Black Specks Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Throughout Annex - No Longer Cps Owned**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Gray Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard**

MATERIAL LOCATION: **2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23A		
MATERIAL DESCRIPTION:	Gray Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **23A**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard Mastic**

MATERIAL LOCATION: **2nd Floor Hallway, 225 Storage, 226, 228, Storage 127, 128, 130, 230, 232, 234, 236, 237, 239, 241, 243, 245, 247, 249, 3rd Floor Hallway, 319, 325, 326, 328, 330, 332, 334, 336, 337, 339, 341, 338, 343, 345, Lunchroom**

MATERIAL QUANTITY: **10000**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **DUPLICATE HA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **DUPLICATE HA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: Aircell Pipe Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**
MATERIAL DESCRIPTION: **Aircell Pipe Joints**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Aircell Pipe Joints**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: D

MATERIAL DESCRIPTION: Fiberglass Pipe Joints

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Fiberglass Pipe Joints**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: E
MATERIAL DESCRIPTION: Water Meter Packing
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUILDING ID:	6221
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Edwards Branch	REVIEW DATE:	6/23/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Water Meter Packing**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/23/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	4" Beige Vinyl Baseboard		
MATERIAL LOCATION:	Room 507		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard**

MATERIAL LOCATION: **Room 507**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Drywall		
MATERIAL LOCATION:	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Joint Compound		
MATERIAL LOCATION:	Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	SURFACE	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Joint Compound**

MATERIAL LOCATION: **Main Office, Rooms 501, 503, 504, 505, 506, 507, 508, 509**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	1' x 1' Fissured Ceiling Tile		
MATERIAL LOCATION:	Principal's Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **1' x 1' Fissured Ceiling Tile**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	Gray Sink Undercoating		
MATERIAL LOCATION:	Teacher's Lounge		
MATERIAL QUANTITY:	2	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	SURFACE	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Gray Sink Undercoating**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12" x 12" Beige Mottled Vinyl Floor Tile		
MATERIAL LOCATION:	Rooms 505, 506, 507		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 505, 506, 507**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Red Fireproofing Caulk		
MATERIAL LOCATION:	South Kitchen, Gymnasium		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	SURFACE	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Red Fireproofing Caulk**

MATERIAL LOCATION: **South Kitchen, Gymnasium**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12" x 12" Beige Mottled Vinyl Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 505, 506, 507		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 505, 506, 507**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	4" Beige Vinyl Baseboard Adhesive		
MATERIAL LOCATION:	Room 507		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/27/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Room 507**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23081	BUIDLING ID:	6221
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Edwards Branch	INSPECTION DATE:	5/27/2025		
ADDRESS:	4950 LaPorte	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	33			
MATERIAL DESCRIPTION:	2' x 4' Tectum Ceiling Tile			
MATERIAL LOCATION:	Gymnasium			
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: **05/27/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23081** BUIDLING ID: **6221**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Edwards Branch** REVIEW DATE: **6/23/2025**

ADDRESS: **4950 LaPorte** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **2' x 4' Tectum Ceiling Tile**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/23/2025

APPENDIX B

Inspector and Management Planner Licenses



2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Cody Cummins

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial



Class Date: 10/28-29/2024
Examination Date: 10/29/2024
STC Certificate Number: STC-20241029-000103AMPI
Certification Expiration: 10/29/2025

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

Cody Cummins

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/8/2025

AIR SAMPLING PROFESSIONAL

ENDORSEMENTS

TC EXPIRES

Alteration of this license shall result in legal action.
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

MANAGEMENT PLANNER

10/29/2025

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Cody Cummins

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2502280827
Course Date: 2/28/2025
Exam Date: 2/28/2025
Expiration Date: 2/28/2026




Tyler Nicholson, Authorized Signer

Issue Date: 2/28/2025

Course Credit Hours: BIR WI 4 Hours



OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Michael Serio

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed