

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2230
SCHOOL NAME: Gregory School
ADDRESS OF SCHOOL: 3715 W. Polk
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/20/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/13/2025 ENROLLMENT 296
IDPH INSPECTOR LICENSE NUMBER: 100-20994
IDPH LICENSED INSPECTOR NAME (Please Print): Cody Cummins
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/9/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Gregory School

3715 W. Polk
Chicago, IL, 60624

Unit: 23441
Building ID: 3660

IDPH ID Number: 14-016-2990-2230

REPORT DATE:
Wednesday, April 09, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

04/09/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23441 Region: 03 IDPH ID: 14-016-2990-2230

School: Gregory School Building ID: 3660

Address: 3715 W. Polk

Chicago, IL, 60624

Building Contact: Barrett, James Contact Phone: 6303368444

Current Building Owners: Chicago Public Schools

Reinspection Date: 3/13/2025

Review Date: 04/09/2025

Inspector: Cody Cummins

Inspector IDPH License: 100-20994

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 09, 2025

RE: Gregory School, Unit 23441
3715 W. Polk
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Gregory School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Gregory School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Gregory School Unit: 23441 Region: 03
Address: 3715 W. Polk Chicago, IL, 60624
IDPH ID: 14-016-2990-2230 Building ID: 3660
Contact: Barrett, James Phone: 6303368444

2. Description of Facility

Original Construction: 1923 Additional Construction: 1926,1926
Total Square Footage: 85100 No of Floors: 3
Current Occupancy: 296

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Cody Cummins



Signature:
Date: 3/13/2025

6. Management Planner

Management Planner Name: Jackson Montgomery




Signature:
Date: 04/09/2025

7. Review Date: 04/09/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 4/9/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Gregory School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3660:

10	12" x 12" Brown Floor Tile Mastic
12	Linoleum Mastic
14	12" x 12" White Floor Tile
15	12" x 12" White Floor Tile Mastic
19	12" x 12" Rose Floor Tile Mastic
21	12" x 12" Gray Floor Tile
22	12" x 12" Gray Floor Tile Mastic
27	Rose Colored Carpet Mastic
29	Incinerator Ductwork - Interior Material

3	12" x 12" Brown w/ White Specks Floor Tile
36	6"x8" Black Border Tile
37	6"x8" Black Border Tile Mastic
4	Brown Linoleum
41	12" x 12" Brown w/ Specks Floor Tile
43	12" x 12" Brown Floor Tile
44	12" x 12" Brown Vinyl Floor Tile Mastic
45	Brown Linoleum Flooring
46	Brown Linoleum Flooring Adhesive
49	Drywall and Joint Compound
50	Spray on Insulation
56	Foam Insulation
57	12" x 12" Red Floor Tile
59	9" x 9" Beige Floor Tile
6	9" x 9" Green Floor Tile Mastic
60	9" x 9" Beige Floor Tile Mastic
64	12" x 12" Gray w/ White Specks Floor Tile
65	12" x 12" Gray w/ White Specks Floor Tile Mastic
66	12" x 12" Gray w/ Black Floor Tile
67	12" x 12" Gray w/ Black Floor Tile Mastic
7	12" x 12" Brown w/ White Specks Floor Tile Mastic
74	12" x 12" White w/ Gray Streaks Floor Tile
75	12" x 12" White w/ Gray Streaks Floor Tile Mastic
76	12" x 12" Dark Gray Floor Tile

77	12" x 12" Dark Gray Floor Tile Mastic
78	12" x 12" Gray w/ Black Streaks Floor Tile
79	12" x 12" Gray w/ Black Streaks Floor Tile Mastic
8	Paper Backing on Brown Linoleum

B. The following new homogenous areas have been identified for Building 3660:

84	Black Terrazzo
85	12" x 12" Beige w/ Brown Specks Floor Tile
86	12" x 12" Cream w/ White Streaks Floor Tile
87	12" x 12" Cream w/ White Streaks Floor Tile Mastic
88	12" x 12" Beige w/ Brown Specks Floor Tile Mastic
89	Beige Baseboard
90	12" x 12" Green w/ Black & Beige Speck Floor Tile
91	12" x 12" Green w/ Black & Beige Speck Floor Tile Mastic
92	Beige Baseboard Adhesive

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

11	Linoleum
12	Linoleum Mastic
14	12" x 12" White Floor Tile
16	12" x 12" Black Floor Tile
18	12" x 12" Rose Floor Tile
23	12" x 12" Blue Floor Tile
26	2" Black Baseboard Mastic
27	Rose Colored Carpet Mastic
28	Window Glazing
29	Incinerator Ductwork - Interior Material
30	12" x 12" White w/ Blue Specks Floor Tile
31	12" x 12" White w/ Blue Specks Floor Tile Mastic
32	Ceramic Tile Adhesive
33	Ceramic Tile Grout
34	12" x 12" Gray White/Black Multi Floor Tile
35	12" x 12" Gray White/Black Multi Floor Tile Mastic
36	6"x8" Black Border Tile
37	6"x8" Black Border Tile Mastic
38	12" x 12" Gray Floor Tile
39	12" x 12" Gray Floor Tile Mastic
40	Ceramic Tile Grout and Adhesive
41	12" x 12" Brown w/ Specks Floor Tile
42	12" x 12" Brown w/ Specks Floor Tile Mastic
43	12" x 12" Brown Floor Tile
44	12" x 12" Brown Vinyl Floor Tile Mastic
45	Brown Linoleum Flooring
46	Brown Linoleum Flooring Adhesive
47	Beige Terrazzo
48	Sink Under-Coating (White)
49	Drywall and Joint Compound
50	Spray on Insulation
51	Glue Under Multi-Color 2'x 2' Carpet Squares
52	Fiberglass Insulation Covered w/ Paper
53	Fiberglass Wrapped in Paper
54	Plaster Ceiling
55	Paper Insulation
56	Foam Insulation
57	12" x 12" Red Floor Tile
58	12" x 12" Red Floor Tile Mastic
59	9" x 9" Beige Floor Tile
60	9" x 9" Beige Floor Tile Mastic
61	Tongue and Groove Wood Floor

62	12" x 12" Maroon w/ White Specks Floor Tile
63	12" x 12" Maroon w/ White Specks Floor Tile Mastic
64	12" x 12" Gray w/ White Specks Floor Tile
65	12" x 12" Gray w/ White Specks Floor Tile Mastic
66	12" x 12" Gray w/ Black Floor Tile
67	12" x 12" Gray w/ Black Floor Tile Mastic
68	12" x 12" Off-White Ceramic Floor Tile
69	12" x 12" Off-White Ceramic Floor Tile Mastic
70	Gray Ceramic Floor Tile
71	Gray Ceramic Floor Tile Mastic
72	12" x 12" Gray Floor Tile
73	12" x 12" Gray Floor Tile Mastic
74	12" x 12" White w/ Gray Streaks Floor Tile
75	12" x 12" White w/ Gray Streaks Floor Tile Mastic
76	12" x 12" Dark Gray Floor Tile
77	12" x 12" Dark Gray Floor Tile Mastic
78	12" x 12" Gray w/ Black Streaks Floor Tile
79	12" x 12" Gray w/ Black Streaks Floor Tile Mastic
8	Paper Backing on Brown Linoleum
80	12" x 12" Bright Red Floor Tile
81	12" x 12" Bright Red Floor Tile Mastic
82	12" x 12" White Floor Tile
83	12" x 12" White Floor Tile Mastic
84	Black Terrazzo
85	12" x 12" Beige w/ Brown Specks Floor Tile
86	12" x 12" Cream w/ White Streaks Floor Tile
87	12" x 12" Cream w/ White Streaks Floor Tile Mastic
88	12" x 12" Beige w/ Brown Specks Floor Tile Mastic
89	Beige Baseboard
9	12" x 12" Brown Floor Tile
90	12" x 12" Green w/ Black & Beige Speck Floor Tile
91	12" x 12" Green w/ Black & Beige Speck Floor Tile Mastic
92	Beige Baseboard Adhesive

The following areas were deemed to be inaccessible:

17	12" x 12" Black Floor Tile Mastic
22	12" x 12" Gray Floor Tile Mastic
31	12" x 12" White w/ Blue Specks Floor Tile Mastic
32	Ceramic Tile Adhesive
35	12" x 12" Gray White/Black Multi Floor Tile Mastic
39	12" x 12" Gray Floor Tile Mastic
42	12" x 12" Brown w/ Specks Floor Tile Mastic
51	Glue Under Multi-Color 2'x 2' Carpet Squares

53	Fiberglass Wrapped in Paper
58	12" x 12" Red Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Cody Cummins, IDPH License # 100-20994. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Gregory School Building 3660 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Plaster			Throughout	NO_ACBM	SURFACE								
10	12" x 12" Brown Floor Tile Mastic			Office	NO_ACBM	MISC					Yes			
11	Linoleum			Unknown	ASSUMED	MISC					No			
12	Linoleum Mastic			Unknown	ASSUMED	MISC					Yes			
14	12" x 12" White Floor Tile	7,000	SF	2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
15	12" x 12" White Floor Tile Mastic			2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office	NO_ACBM	MISC					Yes			
16	12" x 12" Black Floor Tile	7,000	SF	3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	12" x 12" Black Floor Tile Mastic	7,000	SF	3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
18	12" x 12" Rose Floor Tile	800	SF	Room 308, 310 Closet	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
19	12" x 12" Rose Floor Tile Mastic			Room 308	NO_ACBM	MISC					Yes			
2	9" x 9" Green Floor Tile			Room 102, Bathroom	CHR	MISC					No			
20	Brown Carpet Mastic			Library, Office, Principal's Office, Room 102	NO_ACBM	MISC					No			
21	12" x 12" Gray Floor Tile	30	SF	Room 102, 106	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
22	12" x 12" Gray Floor Tile Mastic	30	SF	Room 102, 106	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
23	12" x 12" Blue Floor Tile	550	SF	Room 107	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
24	12" x 12" Blue Floor Tile Mastic			Room 107	NO_ACBM	MISC					No			
25	2" Black Baseboard			Room 107	NO_ACBM	MISC					No			
26	2" Black Baseboard Mastic	80	LF	Room 107	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
27	Rose Colored Carpet Mastic			2nd Floor Teachers' Lounge, Auditorium	ASSUMED	MISC					Yes			
28	Window Glazing	80	SF	Classroom and Office Door	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Transoms and Skylights										
29	Incinerator Ductwork - Interior Material			Boiler Room	ASSUMED	MISC					Yes			
3	12" x 12" Brown w/ White Specks Floor Tile			Lunchroom, Kitchen Office	CHR	MISC					Yes			
30	12" x 12" White w/ Blue Specks Floor Tile	110	SF	Kitchen Office, Kitchen Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
31	12" x 12" White w/ Blue Specks Floor Tile Mastic	110	SF	Kitchen Office, Kitchen Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
32	Ceramic Tile Adhesive	2,451	SF	Lunchroom, Lunchroom Serving Area	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
33	Ceramic Tile Grout	2,451	SF	Lunchroom, Lunchroom Serving Area	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
34	12" x 12" Gray White/Black Multi Floor Tile	70	SF	Room 102 Storage Area	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	12" x 12" Gray White/Black Multi Floor Tile Mastic	70	SF	Room 102 Storage Area	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
36	6"x8" Black Border Tile			Room 102, Storage Area	ASSUMED	MISC					Yes			
37	6"x8" Black Border Tile Mastic			Room 102, Storage Area	ASSUMED	MISC					Yes			
38	12" x 12" Gray Floor Tile	600	SF	Room 106	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
39	12" x 12" Gray Floor Tile Mastic	600	SF	Room 106	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
4	Brown Linoleum			2nd Floor Teachers' Lounge	NO_ACBM	MISC					Yes			
40	Ceramic Tile Grout and Adhesive	350	SF	Room 209	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
41	12" x 12" Brown w/ Specks Floor Tile	560	SF	Room 318	ASSUMED	MISC	N	LOC	2	SF	Yes	ACBM with the potential for damage	5	LOW
42	12" x 12" Brown w/ Specks Floor Tile Mastic	560	SF	Room 318	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
43	12" x 12" Brown Floor Tile			Boiler Room Bathroom	ASSUMED	MISC					Yes			
44	12" x 12" Brown Vinyl Floor Tile Mastic			Boiler Room Bathroom	ASSUMED	MISC					Yes			
45	Brown Linoleum Flooring			Boiler Room Bathroom	ASSUMED	MISC					Yes			
46	Brown Linoleum Flooring Adhesive			Boiler Room Bathroom	ASSUMED	MISC					Yes			
47	Beige Terrazzo	6,800	SF	1st Floor Hallway,	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				2nd Floor Hallway West & East, 3rd Floor Hallway West & East								potential for damage		
48	Sink Under-Coating (White)	5	SF	Room 103	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
49	Drywall and Joint Compound			Boiler Room	ASSUMED	MISC					Yes			
5	1' x 1' Ceiling Tile			1988 Old Lunchroom, 2nd Floor Corridor Storage and Closet, 318	NO_ACBM	MISC					No			
50	Spray on Insulation			Boiler Room Ceiling Hatch	ASSUMED	TSI					Yes			
51	Glue Under Multi-Color 2'x 2' Carpet Squares	800	SF	Library, 208,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
52	Fiberglass Insulation Covered w/ Paper	300	LF	Basement Pipe Tunnel	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
53	Fiberglass Wrapped in Paper	600	LF	Pipe Chase Rooms Behind Boys and Girls Bathrooms 1st, 2nd, 3rd Floor	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		MODERATE
54	Plaster Ceiling	30,000	SF	Throughout	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
55	Paper Insulation	25	LF	Pipe Tunnels in Basement	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
56	Foam Insulation			Pipe Tunnels in Basement	ASSUMED	TSI					Yes			
57	12" x 12" Red Floor Tile	300	SF	Auditorium	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
58	12" x 12" Red Floor Tile Mastic	300	SF	Auditorium	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
59	9" x 9" Beige Floor Tile			Kitchen Office	ASSUMED	MISC					Yes			
6	9" x 9" Green Floor Tile Mastic			Room 102, Bathroom	CHR	MISC					Yes			
60	9" x 9" Beige Floor Tile Mastic			Kitchen Office	ASSUMED	MISC					Yes			
61	Tongue and Groove Wood Floor	10,000	SF	Rooms 301, 302, 303, Gym, 304, 305, 306, 307, 314, 313, 312, 310, 311, 210, 211, 212, 213, Auditorium Stage,	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				214, 215, 216, 207, 206, 205, 203, 202, 108, 109, 110, 111, 112, 113, 103, 315, 316, 300, 200, 204,										
62	12" x 12" Maroon w/ White Specks Floor Tile	30	SF	Room 308, 310 Closet,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
63	12" x 12" Maroon w/ White Specks Floor Tile Mastic	30	SF	Room 308	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
64	12" x 12" Gray w/ White Specks Floor Tile			3rd Floor Corridor Storage	ASSUMED	MISC					Yes			
65	12" x 12" Gray w/ White Specks Floor Tile Mastic			3rd Floor Corridor Storage	ASSUMED	MISC					Yes			
66	12" x 12" Gray w/ Black Floor Tile			3rd Floor Corridor Storage	ASSUMED	MISC					Yes			
67	12" x 12" Gray w/ Black Floor Tile Mastic			3rd Floor Corridor Storage	ASSUMED	MISC					Yes			
68	12" x 12" Off-White Ceramic Floor Tile	60	SF	209 Teachers' Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
69	12" x 12" Off-White Ceramic Floor Tile Mastic	60	SF	209 Teachers' Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
7	12" x 12" Brown w/ White Specks Floor Tile Mastic			Lunchroom, Kitchen Office	CHR	MISC					Yes			
70	Gray Ceramic Floor Tile	500	SF	3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
71	Gray Ceramic Floor Tile Mastic	500	SF	3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
72	12" x 12" Gray Floor Tile	50	SF	Room 107	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
73	12" x 12" Gray Floor Tile Mastic	50	SF	Room 107	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
74	12" x 12" White w/ Gray Streaks Floor Tile			Room 107	ASSUMED	MISC					Yes			
75	12" x 12" White w/ Gray Streaks Floor Tile Mastic			Room 107	ASSUMED	MISC					Yes			
76	12" x 12" Dark Gray Floor Tile			Room 106 Closet	ASSUMED	MISC					Yes			
77	12" x 12" Dark Gray Floor Tile Mastic			Room 106 Closet	ASSUMED	MISC					Yes			
78	12" x 12" Gray w/ Black Streaks Floor Tile			Boiler Room Bathroom	ASSUMED	MISC					Yes			
79	12" x 12" Gray w/ Black Streaks Floor Tile Mastic			Boiler Room Bathroom	ASSUMED	MISC					Yes			

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
8	Paper Backing on Brown Linoleum			2nd Floor Teachers' Lounge	ASSUMED	MISC					Yes			
80	12" x 12" Bright Red Floor Tile	30	SF	Principal's Office Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
81	12" x 12" Bright Red Floor Tile Mastic	30	SF	Principal's Office Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
82	12" x 12" White Floor Tile	150	SF	Main Office 101	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
83	12" x 12" White Floor Tile Mastic	150	SF	Main Office 101	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
84	Black Terrazzo	1,000	SF	1st Floor Hallway, 2nd Floor Hallway West & East, 3rd Floor Hallway West & East	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
85	12" x 12" Beige w/ Brown Specks Floor Tile	200	SF	Kitchen Storage	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
86	12" x 12" Cream w/ White Streaks Floor Tile	400	SF	101	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
87	12" x 12" Cream w/ White Streaks Floor Tile Mastic	400	SF	101	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
88	12" x 12" Beige w/ Brown Specks Floor Tile Mastic	200	SF	Kitchen Storage	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
89	Beige Baseboard	20	LF	Principal Office Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
9	12" x 12" Brown Floor Tile	700	SF	Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
90	12" x 12" Green w/ Black & Beige Speck Floor Tile	100	SF	Office 102 Storage	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
91	12" x 12" Green w/ Black & Beige Speck Floor Tile Mastic	100	SF	Office 102 Storage	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
92	Beige Baseboard Adhesive	20	LF	Principal Office Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW

Chicago Public Schools

School Gregory School Unit 23441 Building ID 3660
Address 3715 W. Polk Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>3/13/2025</u>
Inspector Name <u>Cody Cummins</u>
<u>100-20994</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	Damage in: Room 318
42	
43	
44	
45	
46	
47	
48	
49	
5	Damage in 318
50	
51	
52	
53	
54	
55	
56	
57	
58	

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	
82	
83	
84	

Chicago Public Schools

School Gregory School **Unit** 23441 **Building ID** 3660
Address 3715 W. Polk **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
85	
86	
87	
88	
89	
9	
90	
91	
92	

Table II
Management Planner's Review

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Plaster			Throughout	No ACBM	SURFACE					
10	12" x 12" Brown Floor Tile Mastic			Office	No ACBM	MISC					
11	Linoleum			Unknown	Assumed	MISC					Follow O&M Plan
12	Linoleum Mastic			Unknown	Assumed	MISC					Follow O&M Plan
14	12" x 12" White Floor Tile	7,000	SF	2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12" x 12" White Floor Tile Mastic			2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office	No ACBM	MISC					
16	12" x 12" Black Floor Tile	7,000	SF	3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12" x 12" Black Floor Tile Mastic	7,000	SF	3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12" x 12" Rose Floor Tile	800	SF	Room 308, 310 Closet	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12" x 12" Rose Floor Tile Mastic			Room 308	No ACBM	MISC					
2	9" x 9" Green Floor Tile			Room 102, Bathroom	Chrysotile	MISC					Follow O&M Plan
20	Brown Carpet Mastic			Library, Office, Principal's Office, Room 102	No ACBM	MISC					
21	12" x 12" Gray Floor Tile	30	SF	Room 102, 106	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Gray Floor Tile Mastic	30	SF	Room 102, 106	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Blue Floor Tile	550	SF	Room 107	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" Blue Floor Tile Mastic			Room 107	No ACBM	MISC					
25	2" Black Baseboard			Room 107	No ACBM	MISC					
26	2" Black Baseboard Mastic	80	LF	Room 107	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
27	Rose Colored Carpet Mastic			2nd Floor Teachers' Lounge, Auditorium	Assumed	MISC					Follow O&M Plan
28	Window Glazing	80	SF	Classroom and Office Door Transoms and Skylights	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Incinerator Ductwork - Interior Material			Boiler Room	Assumed	MISC					Follow O&M Plan
3	12" x 12" Brown w/ White Specks Floor Tile			Lunchroom, Kitchen Office	Chrysotile	MISC					Follow O&M Plan
30	12" x 12" White w/ Blue Specks Floor Tile	110	SF	Kitchen Office, Kitchen Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" White w/ Blue Specks Floor Tile Mastic	110	SF	Kitchen Office, Kitchen Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Ceramic Tile Adhesive	2,451	SF	Lunchroom, Lunchroom Serving Area	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Ceramic Tile Grout	2,451	SF	Lunchroom, Lunchroom Serving Area	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12" x 12" Gray White/Black Multi Floor Tile	70	SF	Room 102 Storage Area	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" x 12" Gray White/Black Multi Floor Tile Mastic	70	SF	Room 102 Storage Area	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
36	6"x8" Black Border Tile			Room 102, Storage Area	Assumed	MISC					Follow O&M Plan
37	6"x8" Black Border Tile Mastic			Room 102, Storage Area	Assumed	MISC					Follow O&M Plan
38	12" x 12" Gray Floor Tile	600	SF	Room 106	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12" x 12" Gray Floor Tile Mastic	600	SF	Room 106	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	Brown Linoleum			2nd Floor Teachers' Lounge	No ACBM	MISC					
40	Ceramic Tile Grout and Adhesive	350	SF	Room 209	Assumed	MISC	No		SF	6 ACBM with the potential for damage	
41	12" x 12" Brown w/ Specks Floor Tile	560	SF	Room 318	Assumed	MISC	No	2	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Brown w/ Specks Floor Tile Mastic	560	SF	Room 318	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12" x 12" Brown Floor Tile			Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
44	12" x 12" Brown Vinyl Floor Tile Mastic			Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
45	Brown Linoleum Flooring			Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
46	Brown Linoleum Flooring Adhesive			Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
47	Beige Terrazzo	6,800	SF	1st Floor Hallway, 2nd Floor Hallway West & East, 3rd Floor Hallway West & East	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Sink Under-Coating (White)	5	SF	Room 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Drywall and Joint Compound			Boiler Room	Assumed	MISC					Follow O&M Plan
5	1' x 1' Ceiling Tile			1988 Old Lunchroom, 2nd Floor Corridor Storage and Closet, 318	No ACBM	MISC					
50	Spray on Insulation			Boiler Room Ceiling Hatch	Assumed	TSI					
51	Glue Under Multi-Color 2'x 2' Carpet Squares	800	SF	Library, 208	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
52	Fiberglass Insulation Covered w/ Paper	300	LF	Basement Pipe Tunnel	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
53	Fiberglass Wrapped in Paper	600	LF	Pipe Chase Rooms Behind Boys and Girls Bathrooms 1st, 2nd, 3rd Floor	Assumed	MISC	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	Plaster Ceiling	30,000	SF	Throughout	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
55	Paper Insulation	25	LF	Pipe Tunnels in Basement	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
56	Foam Insulation			Pipe Tunnels in Basement	Assumed	TSI					Follow O&M Plan
57	12" x 12" Red Floor Tile	300	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Red Floor Tile Mastic	300	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
59	9" x 9" Beige Floor Tile			Kitchen Office	Assumed	MISC					Follow O&M Plan
6	9" x 9" Green Floor Tile Mastic			Room 102, Bathroom	Chrysotile	MISC					Follow O&M Plan
60	9" x 9" Beige Floor Tile Mastic			Kitchen Office	Assumed	MISC					Follow O&M Plan
61	Tongue and Groove Wood Floor	10,000	SF	Rooms 301, 302, 303, Gym, 304, 305,	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				306, 307, 314, 313, 312, 310, 311, 210, 211, 212, 213, Auditorium Stage, 214, 215, 216, 207, 206, 205, 203, 202, 108, 109, 110, 111, 112, 113, 103, 315, 316, 300, 200, 204,							
62	12" x 12" Maroon w/ White Specks Floor Tile	30	SF	Room 308, 310 Closet,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12" x 12" Maroon w/ White Specks Floor Tile Mastic	30	SF	Room 308	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Gray w/ White Specks Floor Tile			3rd Floor Corridor Storage	Assumed	MISC					Follow O&M Plan
65	12" x 12" Gray w/ White Specks Floor Tile Mastic			3rd Floor Corridor Storage	Assumed	MISC					Follow O&M Plan
66	12" x 12" Gray w/ Black Floor Tile			3rd Floor Corridor Storage	Assumed	MISC					Follow O&M Plan
67	12" x 12" Gray w/ Black Floor Tile Mastic			3rd Floor Corridor Storage	Assumed	MISC					Follow O&M Plan
68	12" x 12" Off-White Ceramic Floor Tile	60	SF	209 Teachers' Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Off-White Ceramic Floor Tile Mastic	60	SF	209 Teachers' Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	12" x 12" Brown w/ White Specks Floor Tile Mastic			Lunchroom, Kitchen Office	Chrysotile	MISC					Follow O&M Plan
70	Gray Ceramic Floor Tile	500	SF	3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Gray Ceramic Floor Tile Mastic	500	SF	3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" x 12" Gray Floor Tile	50	SF	Room 107	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	12" x 12" Gray Floor Tile Mastic	50	SF	Room 107	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" White w/ Gray Streaks Floor Tile			Room 107	Assumed	MISC					Follow O&M Plan
75	12" x 12" White w/ Gray Streaks Floor Tile Mastic			Room 107	Assumed	MISC					Follow O&M Plan
76	12" x 12" Dark Gray Floor Tile			Room 106 Closet	Assumed	MISC					Follow O&M Plan
77	12" x 12" Dark Gray Floor Tile Mastic			Room 106 Closet	Assumed	MISC					Follow O&M Plan
78	12" x 12" Gray w/ Black Streaks Floor Tile			Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
79	12" x 12" Gray w/ Black Streaks Floor Tile Mastic			Boiler Room Bathroom	Assumed	MISC					Follow O&M Plan
8	Paper Backing on Brown Linoleum			2nd Floor Teachers' Lounge	Assumed	MISC					Follow O&M Plan
80	12" x 12" Bright Red Floor Tile	30	SF	Principal's Office Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
81	12" x 12" Bright Red Floor Tile Mastic	30	SF	Principal's Office Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
82	12" x 12" White Floor Tile	150	SF	Main Office 101	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
83	12" x 12" White Floor Tile Mastic	150	SF	Main Office 101	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Black Terrazzo	1,000	SF	1st Floor Hallway, 2nd Floor Hallway West & East, 3rd Floor Hallway West & East	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
85	12" x 12" Beige w/ Brown Specks Floor Tile	200	SF	Kitchen Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
86	12" x 12" Cream w/ White Streaks Floor Tile	400	SF	101	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" Cream w/ White Streaks Floor Tile Mastic	400	SF	101	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
88	12" x 12" Beige w/ Brown Specks Floor Tile Mastic	200	SF	Kitchen Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Beige Baseboard	20	LF	Principal Office Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
9	12" x 12" Brown Floor Tile	700	SF	Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Green w/ Black & Beige Speck Floor Tile	100	SF	Office 102 Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Green w/ Black & Beige Speck Floor Tile Mastic	100	SF	Office 102 Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
92	Beige Baseboard Adhesive	20	LF	Principal Office Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/9/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
34	
35	
36	
37	
38	
39	
4	
40	
41	Sample to determine ACM content, remove or repair to intact.
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
57	
58	

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
59	
6	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
8	
80	
81	
82	

Chicago Public Schools

School Gregory School

Unit 23441

Building ID 3660

Address 3715 W. Polk

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
83	
84	
85	
86	
87	
88	
89	
9	
90	
91	
92	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Unknown

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **Unknown**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **12**
MATERIAL DESCRIPTION: **Linoleum Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Unknown**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Linoleum Mastic**

MATERIAL LOCATION: **Unknown**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: 

Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Halls, Mens Bathroom and Engineer's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile**

MATERIAL LOCATION: **3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12" x 12" Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Black Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Hall, Mens Bathroom, Principal's Office and Engineer's Office**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12" x 12" Rose Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 308, 310 Closet		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Rose Floor Tile**

MATERIAL LOCATION: **Room 308, 310 Closet**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Rose Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 308**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" Rose Floor Tile Mastic**

MATERIAL LOCATION: **Room 308**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2	
MATERIAL DESCRIPTION:	9" x 9" Green Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 102, Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile**

MATERIAL LOCATION: **Room 102, Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**
MATERIAL DESCRIPTION: **Brown Carpet Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library, Office, Principal's Office, Room 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Library, Office, Principal's Office, Room 102**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102, 106		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Room 102, 106**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102, 106		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 102, 106**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107		
MATERIAL QUANTITY:	550	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **550** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**
MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **2" Black Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **2" Black Baseboard**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	2" Black Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2" Black Baseboard Mastic**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27	
MATERIAL DESCRIPTION:	Rose Colored Carpet Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Teachers' Lounge, Auditorium**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Rose Colored Carpet Mastic**

MATERIAL LOCATION: **2nd Floor Teachers' Lounge, Auditorium**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Window Glazing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classroom and Office Door Transoms and Skylights		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Window Glazing**

MATERIAL LOCATION: **Classroom and Office Door Transoms and Skylights**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	Incinerator Ductwork - Interior Material	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Incinerator Ductwork - Interior Material**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3	
MATERIAL DESCRIPTION:	12" x 12" Brown w/ White Specks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Lunchroom, Kitchen Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Specks Floor Tile**

MATERIAL LOCATION: **Lunchroom, Kitchen Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Office, Kitchen Bathroom		
MATERIAL QUANTITY:	110	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile**

MATERIAL LOCATION: **Kitchen Office, Kitchen Bathroom**

MATERIAL QUANTITY: **110** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Office, Kitchen Bathroom		
MATERIAL QUANTITY:	110	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Specks Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen Office, Kitchen Bathroom**

MATERIAL QUANTITY: **110** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	Ceramic Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Lunchroom Serving Area		
MATERIAL QUANTITY:	2451	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**

MATERIAL LOCATION: **Lunchroom, Lunchroom Serving Area**

MATERIAL QUANTITY: **2451** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Lunchroom Serving Area		
MATERIAL QUANTITY:	2451	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Lunchroom, Lunchroom Serving Area**

MATERIAL QUANTITY: **2451** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12" x 12" Gray White/Black Multi Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102 Storage Area		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 12" Gray White/Black Multi Floor Tile**

MATERIAL LOCATION: **Room 102 Storage Area**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" x 12" Gray White/Black Multi Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102 Storage Area		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Gray White/Black Multi Floor Tile Mastic**

MATERIAL LOCATION: **Room 102 Storage Area**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	6"x8" Black Border Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102, Storage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **6"x8" Black Border Tile**

MATERIAL LOCATION: **Room 102, Storage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37	
MATERIAL DESCRIPTION:	6"x8" Black Border Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102, Storage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **6"x8" Black Border Tile Mastic**

MATERIAL LOCATION: **Room 102, Storage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 106**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Brown Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **2nd Floor Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Ceramic Tile Grout and Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 209		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Ceramic Tile Grout and Adhesive**

MATERIAL LOCATION: **Room 209**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 318		
MATERIAL QUANTITY:	560	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in: Room 318		

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Specks Floor Tile**

MATERIAL LOCATION: **Room 318**

MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 318		
MATERIAL QUANTITY:	560	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 318**

MATERIAL QUANTITY: **560** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43	
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44	
MATERIAL DESCRIPTION:	12" x 12" Brown Vinyl Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" x 12" Brown Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45	
MATERIAL DESCRIPTION:	Brown Linoleum Flooring	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Brown Linoleum Flooring**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46	
MATERIAL DESCRIPTION:	Brown Linoleum Flooring Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Inspector's Signature:

Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Brown Linoleum Flooring Adhesive**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Beige Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Hallway, 2nd Floor Hallway West & East, 3rd Floor Hallway West & East		
MATERIAL QUANTITY:	6800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Beige Terrazzo**

MATERIAL LOCATION: **1st Floor Hallway, 2nd Floor Hallway West & East, 3rd Floor Hallway West & East**

MATERIAL QUANTITY: **6800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Sink Under-Coating (White)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Sink Under-Coating (White)**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49	
MATERIAL DESCRIPTION:	Drywall and Joint Compound	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:



Inspector's Signature:

Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Drywall and Joint Compound**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1988 Old Lunchroom, 2nd Floor Corridor Storage and Closet, 318**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Damage in 318**

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **1988 Old Lunchroom, 2nd Floor Corridor Storage and Closet, 318**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Spray on Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Ceiling Hatch**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Spray on Insulation**

MATERIAL LOCATION: **Boiler Room Ceiling Hatch**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Glue Under Multi-Color 2'x 2' Carpet Squares		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library, 208,		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Glue Under Multi-Color 2'x 2' Carpet Squares**

MATERIAL LOCATION: **Library, 208,**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Fiberglass Insulation Covered w/ Paper		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement Pipe Tunnel**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Fiberglass Insulation Covered w/ Paper**

MATERIAL LOCATION: **Basement Pipe Tunnel**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Fiberglass Wrapped in Paper		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Pipe Chase Rooms Behind Boys and Girls Bathrooms 1st, 2nd, 3rd Floor		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Fiberglass Wrapped in Paper**

MATERIAL LOCATION: **Pipe Chase Rooms Behind Boys and Girls Bathrooms 1st, 2nd, 3rd Floor**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Plaster Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Plaster Ceiling**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	Paper Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Pipe Tunnels in Basement**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Paper Insulation**

MATERIAL LOCATION: **Pipe Tunnels in Basement**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Foam Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Pipe Tunnels in Basement

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Foam Insulation**

MATERIAL LOCATION: **Pipe Tunnels in Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	9" x 9" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile**

MATERIAL LOCATION: **Kitchen Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6	
MATERIAL DESCRIPTION:	9" x 9" Green Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 102, Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 9" Green Floor Tile Mastic**

MATERIAL LOCATION: **Room 102, Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60	
MATERIAL DESCRIPTION:	9" x 9" Beige Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9" x 9" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	Tongue and Groove Wood Floor		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 301, 302, 303, Gym, 304, 305, 306, 307, 314, 313, 312, 310, 311, 210, 211, 212, 213, Auditorium Stage, 214, 215, 216, 207, 206, 205, 203, 202, 108, 109, 110, 111, 112, 113, 103, 315, 316, 300, 200, 204,**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Tongue and Groove Wood Floor**

MATERIAL LOCATION: **Rooms 301, 302, 303, Gym, 304, 305, 306, 307, 314, 313, 312, 310, 311, 210, 211, 212, 213, Auditorium Stage, 214, 215, 216, 207, 206, 205, 203, 202, 108, 109, 110, 111, 112, 113, 103, 315, 316, 300, 200, 204,**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 308, 310 Closet,		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Maroon w/ White Specks Floor Tile**

MATERIAL LOCATION: **Room 308, 310 Closet,**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	12" x 12" Maroon w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 308		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Maroon w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 308**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64	
MATERIAL DESCRIPTION:	12" x 12" Gray w/ White Specks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridor Storage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Specks Floor Tile**

MATERIAL LOCATION: **3rd Floor Corridor Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65	
MATERIAL DESCRIPTION:	12" x 12" Gray w/ White Specks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Corridor Storage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Corridor Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66	
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Corridor Storage

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Floor Tile**

MATERIAL LOCATION: **3rd Floor Corridor Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67	
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 3rd Floor Corridor Storage

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Corridor Storage**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12" x 12" Off-White Ceramic Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	209 Teachers' Bathroom		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Off-White Ceramic Floor Tile**

MATERIAL LOCATION: **209 Teachers' Bathroom**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12" x 12" Off-White Ceramic Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	209 Teachers' Bathroom		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Off-White Ceramic Floor Tile Mastic**

MATERIAL LOCATION: **209 Teachers' Bathroom**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 7

MATERIAL DESCRIPTION: 12" x 12" Brown w/ White Specks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Chrysotile FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunchroom, Kitchen Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom, Kitchen Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Gray Ceramic Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Gray Ceramic Floor Tile**

MATERIAL LOCATION: **3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	Gray Ceramic Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Gray Ceramic Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Bathrooms, 2nd Floor Bathrooms, 1st Floor Bathrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	74	
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Streaks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75	
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Streaks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 107**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	76	
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile**

MATERIAL LOCATION: **Room 106 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 106 Closet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78	
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Streaks Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Streaks Floor Tile**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	79	
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Streaks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room Bathroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 8

MATERIAL DESCRIPTION: Paper Backing on Brown Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Teachers' Lounge

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Paper Backing on Brown Linoleum**

MATERIAL LOCATION: **2nd Floor Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12" x 12" Bright Red Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office Bathroom		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12" x 12" Bright Red Floor Tile**

MATERIAL LOCATION: **Principal's Office Bathroom**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	81		
MATERIAL DESCRIPTION:	12" x 12" Bright Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office Bathroom		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12" x 12" Bright Red Floor Tile Mastic**

MATERIAL LOCATION: **Principal's Office Bathroom**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office 101		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **03/13/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **Main Office 101**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office 101		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **Main Office 101**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUILDING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	Beige Baseboard		
MATERIAL LOCATION:	Principal Office Bathroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Beige Baseboard**

MATERIAL LOCATION: **Principal Office Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Specks Floor Tile		
MATERIAL LOCATION:	Kitchen Storage		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23441** BUIDLING ID: **3660**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Gregory School** REVIEW DATE: **4/9/2025**

ADDRESS: **3715 W. Polk** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Specks Floor Tile**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *04/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Black & Beige Speck Floor Tile		
MATERIAL LOCATION:	Office 102 Storage		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Green w/ Black & Beige Speck Floor Tile**

MATERIAL LOCATION: **Office 102 Storage**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *04/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	Beige Baseboard Adhesive		
MATERIAL LOCATION:	Principal Office Bathroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Beige Baseboard Adhesive**

MATERIAL LOCATION: **Principal Office Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	12" x 12" Green w/ Black & Beige Speck Floor Tile Mastic		
MATERIAL LOCATION:	Office 102 Storage		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" Green w/ Black & Beige Speck Floor Tile Mastic**

MATERIAL LOCATION: **Office 102 Storage**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	Black Terrazzo		
MATERIAL LOCATION:	1st Floor Hallway, 2nd Floor Hallway West & East, 3rd Floor Hallway West & East		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23441** BUIDLING ID: **3660**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Gregory School** REVIEW DATE: **4/9/2025**

ADDRESS: **3715 W. Polk** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **Black Terrazzo**

MATERIAL LOCATION: **1st Floor Hallway, 2nd Floor Hallway West & East, 3rd Floor Hallway West & East**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	12" x 12" Cream w/ White Streaks Floor Tile		
MATERIAL LOCATION:	101		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23441** BUIDLING ID: **3660**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Gregory School** REVIEW DATE: **4/9/2025**

ADDRESS: **3715 W. Polk** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ White Streaks Floor Tile**

MATERIAL LOCATION: **101**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *04/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	12" x 12" Cream w/ White Streaks Floor Tile Mastic		
MATERIAL LOCATION:	101		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Gregory School	REVIEW DATE:	4/9/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **101**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23441	BUIDLING ID:	3660
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Gregory School	INSPECTION DATE:	3/13/2025		
ADDRESS:	3715 W. Polk	IDPH LICENSE NO:	100-20994		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Specks Floor Tile Mastic		
MATERIAL LOCATION:	Kitchen Storage		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/13/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23441** BUIDLING ID: **3660**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Gregory School** REVIEW DATE: **4/9/2025**

ADDRESS: **3715 W. Polk** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen Storage**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *04/09/2025*

APPENDIX B

Inspector and Management Planner Licenses



2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Cody Cummins

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial



Class Date: 10/28-29/2024
Examination Date: 10/29/2024
STC Certificate Number: STC-20241029-000103AMPI
Certification Expiration: 10/29/2025

David M. Mendoza – President/Training Director
Certified Environmental Specialist
OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

Cody Cummins

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



ENDORSEMENTS

TC EXPIRES

INSPECTOR

3/8/2025

AIR SAMPLING PROFESSIONAL

ENDORSEMENTS

TC EXPIRES

Alteration of this license shall result in legal action.
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

MANAGEMENT PLANNER

10/29/2025

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Cody Cummins

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2502280827
Course Date: 2/28/2025
Exam Date: 2/28/2025
Expiration Date: 2/28/2026






Tyler Nicholson, Authorized Signer

Issue Date: 2/28/2025

Course Credit Hours: BIR WI 4 Hours

Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



ENDORSEMENTS

INSPECTOR

TC EXPIRES

2/22/2025

ENDORSEMENTS

TC EXPIRES

10/29/2025

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed