

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2232
SCHOOL NAME: Grimes School
ADDRESS OF SCHOOL: 5450 W. 64th Pl.
CITY: Chicago, IL, 60638

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 6/17/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/19/2025 ENROLLMENT 365
IDPH INSPECTOR LICENSE NUMBER: 100-20974
IDPH LICENSED INSPECTOR NAME (Please Print): Anthony Porfilio
IDPH MP LICENSE NUMBER: 100-09766
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Szeredy

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/16/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Grimes School

5450 W. 64th Pl.
Chicago, IL, 60638

Unit: 23461
Building ID: 3680

IDPH ID Number: 14-016-2990-2232

REPORT DATE:
Monday, June 16, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
TEM Environmental, Inc.

174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone 630-790-0880
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/13/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23461 Region: 05 IDPH ID: 14-016-2990-2232

School: Grimes School Building ID: 3680

Address: 5450 W. 64th Pl.

Chicago, IL, 60638

Building Contact: Shank, Daniel Contact Phone: 2196714912

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/19/2025

Review Date: 06/13/2025

Inspector: Anthony Porfilio

Inspector IDPH License: 100-20974

Management Planner: Steven Szeredy

Management Planner IDPH License: 100-09766

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Steven Szeredy
100-09766

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 16, 2025

RE: Grimes School, Unit 23461
5450 W. 64th Pl.
Chicago, IL, 60638

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Grimes School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Grimes School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Grimes School
Address: 5450 W. 64th Pl.
IDPH ID: 14-016-2990-2232
Contact: Shank, Daniel

Unit: 23461
Chicago, IL, 60638
Building ID: 3680
Phone: 2196714912

Region: 05

2. Description of Facility

Original Construction: 1953
Total Square Footage: 12302
Current Occupancy: 365

Additional Construction: 1995
No of Floors: 1

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Anthony Porfilio

Inspector IDPH license # 100-20974
Reinspection Date: 5/19/2025


Signature:
Date: 5/19/2025

6. Management Planner

Management Planner Name: Steven Szeregy


Management Planner IDPH license # 100-09766


Signature:
Date: 06/13/2025

7. Review Date: 06/13/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature:

Date: 6/16/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Grimes School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3680:

36	12"x12" White w/Grey Streaks Floor Tile
36M	Mastic associated w/12"x12" White w/Grey Streaks Floor Tile
37	12"x12" Wood Pattern Floor Tile
37M	Mastic associated w/12"x12" Wood Pattern Floor Tile
38	2'x4' Fissured Ceiling Tile
39	4" White Baseboard and Associated Adhesive
NEW	Newly Installed Suspect ACM

B. The following new homogenous areas have been identified for Building 3680:

36	12"x12" White w/Grey Streaks Floor Tile
36M	Mastic associated w/12"x12" White w/Grey Streaks Floor Tile
37	12"x12" Wood Pattern Floor Tile
37M	Mastic associated w/12"x12" Wood Pattern Floor Tile
38	2'x4' Fissured Ceiling Tile
39	4" White Baseboard and Associated Adhesvie

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

21	12x12 Vinyl Floor Tile, Tan w/White and Brown Specks
21A	12x12 Vinyl Floor Tile, Beige w/Brown and White Streaks
21B	12x12 Vinyl Floor Tile, White w/Gray Specks
22	Mastic beneath 12x12 Vinyl Floor Tile, Tan w/White & Brown Specks
22A	Mastic Beneath 12x12 Vinyl Floor Tile
22B	Mastic Beneath 12x12 Vinyl Floor Tile, White w/Gray Specks
25	Drywall
26	Hard Plaster NOT OBSERVED
27	Drywall Joint Compound
29	2x4 Ceiling Tile
30	2x2 Ceiling Tile
31	Brown Linoleum Flooring
32	Brown Linoleum Flooring Mastic
33	Gray Carpet Mastic
34	8" Brown Baseboard
35	8" Brown Baseboard Mastic
36	12"x12" White w/Grey Streaks Floor Tile
36M	Mastic associated w/12"x12" White w/Grey Streaks Floor Tile
37	12"x12" Wood Pattern Floor Tile
37M	Mastic associated w/12"x12" Wood Pattern Floor Tile
38	2'x4' Fissured Ceiling Tile
39	4" White Baseboard and Associated Adhesive
M	Incinerator Insulation NOT OBSERVED
N	Cardboard Insulation
NEW	Newly Installed Suspect ACM

The following areas were deemed to be inaccessible:

22	Mastic beneath 12x12 Vinyl Floor Tile, Tan w/White & Brown Specks
22A	Mastic Beneath 12x12 Vinyl Floor Tile
22B	Mastic Beneath 12x12 Vinyl Floor Tile, White w/Gray Specks
25	Drywall

26	Hard Plaster NOT OBSERVED
27	Drywall Joint Compound
29	2x4 Ceiling Tile
32	Brown Linoleum Flooring Mastic
33	Gray Carpet Mastic
35	8" Brown Baseboard Mastic
N	Cardboard Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Anthony Porfilio, IDPH License # 100-20974. The Management Plan was updated by Steven Szeregy, IDPH License # 100-09766. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Grimes School Building 3680 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Grimes School **Unit** 23461 **Building ID** 3680
Address 5450 W. 64th Pl. **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	8" Black Vinyl Baseboard			Room 100, 101, 102, 103, 104, 106, Main Office, Principal's Office & Restroom	NO_ACBM	MISC								
01A	Mastic Beneath 8" Vinyl Baseboard			Room 100, 102, Main Office, Principal's Office & Restroom, 104	NO_ACBM	MISC								
02	Gray 8" Vinyl Baseboard			Through 1996 Addition	NO_ACBM	MISC								
02A	Mastic Beneath Vinyl Baseboard			Throughout 1996 Addition	NO_ACBM	MISC								
21	12x12 Vinyl Floor Tile, Tan w/White and Brown Specks	7,515	SF	104, 100, Main Office, Principal's Office, Safe, 105, Main Corridor, Teachers' Lounge, 106, 101, 102, Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21A	12x12 Vinyl Floor Tile, Beige w/Brown and White Streaks	1,310	SF	South Entrance, South Vestibule, Room 103 & Room 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21B	12x12 Vinyl Floor Tile, White w/Gray Specks	2,330	SF	Gymnasium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Mastic beneath 12x12 Vinyl Floor Tile, Tan w/White & Brown Specks	7,515	SF	Rooms 100, 101, 102, 104, 105 & 106, Library, Principal's Office, Safe, Main Corridor, Teachers' Lounge, Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22A	Mastic Beneath 12x12 Vinyl Floor Tile	1,310	SF	South Entrance, South Vestibule, Rooms 103 & 106	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22B	Mastic Beneath 12x12 Vinyl Floor Tile, White w/Gray Specks	2,330	SF	Gymnasium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Drywall	11,000	SF	South Vestibule, Above All Ceiling Tile Throughout Handicap Restroom, Kitchen Office and Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	Hard Plaster NOT OBSERVED	800	SF	Engineer's Office and Boiler Room	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Grimes School **Unit** 23461 **Building ID** 3680
Address 5450 W. 64th Pl. **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
27	Drywall Joint Compound	3,000	LF	South Vestibule, Above All Ceiling Tiles Throughout Handicap Restroom, Kitchen Office & Storage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	2x4 Lay-in Fissure Ceiling Tile			Throughout Building	NO_ACBM	MISC								
29	2x4 Ceiling Tile	2,564	SF	Gymnasium	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
30	2x2 Ceiling Tile	848	SF	Kitchen, West Foyer, Gym Office	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
31	Brown Linoleum Flooring	828	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	Brown Linoleum Flooring Mastic	828	SF	Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Gray Carpet Mastic	350	SF	Room 104A, Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	8" Brown Baseboard	60	LF	West Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
35	8" Brown Baseboard Mastic	60	LF	East Foyer	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12"x12" White w/Grey Streaks Floor Tile	20	SF	Teachers' Lounge Washroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
36M	Mastic associated w/12"x12" White w/Grey Streaks Floor Tile	20	SF	Teacher's Lounge Washroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
37	12"x12" Wood Pattern Floor Tile	15	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
37M	Mastic associated w/12"x12" Wood Pattern Floor Tile	15	SF	Engineer's Washroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
38	2'x4' Fissured Ceiling Tile	16	SF	Teacher's Lounge Washroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
39	4" White Baseboard and Associated Adhesive	20	LF	Teachers' Lounge Washroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
L	Boiler Gaskets			Boiler Room	NO_ACBM	TSI								
M	Incinerator Insulation NOT OBSERVED			Boiler Room	ASSUMED	TSI								
N	Cardboard Insulation	20	LF	Bathroom Pipe Chase	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan	ASSUMED	MISC		UNKWN	0		Yes	ACBM with the potential for damage		

Chicago Public Schools

School Grimes School **Unit** 23461 **Building ID** 3680
Address 5450 W. 64th Pl. **Region** 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Grimes School Unit 23461 Building ID 3680
Address 5450 W. 64th Pl. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>5/19/2025</u>
Inspector Name	<u>Anthony Porfilio</u>
100-20974	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
01	Not Observed in Rooms 100, 102, 104 & Washrooms
01A	
02	Only in Art Room (107) & Kitchen
02A	
21	
21A	
21B	
22	
22A	
22B	
25	
26	2025- Not Observed. Brick, CMU & Concrete
27	
28	
29	
30	
31	
32	
33	2025- No Carpet Observed
34	
35	
36	
36M	
37	

Chicago Public Schools

School Grimes School Unit 23461 Building ID 3680
Address 5450 W. 64th Pl. Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
37M	
38	
39	
L	
M	
N	
NEW	
O	
W-1	
W-2	

Table II
Management Planner's Review

Chicago Public Schools

School Grimes School

Unit 23461

Building ID 3680

Address 5450 W. 64th Pl.

Chicago, IL, 60638

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	8" Black Vinyl Baseboard			Room 100, 101, 102, 103, 104, 106, Main Office, Principal's Office & Restroom	No ACBM	MISC					
01A	Mastic Beneath 8" Vinyl Baseboard			Room 100, 102, Main Office, Principal's Office & Restroom, 104	No ACBM	MISC					
02	Gray 8" Vinyl Baseboard			Throught 1996 Addition	No ACBM	MISC					
02A	Mastic Beneath Vinyl Baseboard			Througout 1996 Addition	No ACBM	MISC					
21	12x12 Vinyl Floor Tile, Tan w/White and Brown Specks	7,515	SF	104, 100, Main Office, Principal's Office, Safe, 105, Main Corridor, Teachers' Lounge, 106, 101, 102, Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21A	12x12 Vinyl Floor Tile, Beige w/Brown and White Streaks	1,310	SF	South Entrance, South Vestibule, Room 103 & Room 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21B	12x12 Vinyl Floor Tile, White w/Gray Specks	2,330	SF	Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Mastic beneath 12x12 Vinyl Floor Tile, Tan w/White & Brown Specks	7,515	SF	Rooms 100, 101, 102, 104, 105 & 106, Library, Principal's Office, Safe, Main Corridor, Teachers' Lounge, Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22A	Mastic Beneath 12x12 Vinyl Floor Tile	1,310	SF	South Entrance, South Vestibule, Rooms 103 & 106	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22B	Mastic Beneath 12x12 Vinyl Floor Tile, White w/Gray Specks	2,330	SF	Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Drywall	11,000	SF	South Vestibule, Above All Ceiling Tile Throughout Handicap Restroom, Kitchen Office and Storage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Hard Plaster NOT OBSERVED	800	SF	Engineer's Office and Boiler Room	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Drywall Joint Compound	3,000	LF	South Vestibule, Above All Ceiling Tiles Throughout Handicap Restroom, Kitchen Office & Storage	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
28	2x4 Lay-in Fissure Ceiling Tile			Throughout Building	No ACBM	MISC					
29	2x4 Ceiling Tile	2,564	SF	Gymnasium	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
30	2x2 Ceiling Tile	848	SF	Kitchen, West Foyer, Gym Office	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
31	Brown Linoleum Flooring	828	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	Brown Linoleum Flooring Mastic	828	SF	Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Grimes School

Unit 23461

Building ID 3680

Address 5450 W. 64th Pl.

Chicago, IL, 60638

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
33	Gray Carpet Mastic	350	SF	Room 104A, Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	8" Brown Baseboard	60	LF	West Foyer	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
35	8" Brown Baseboard Mastic	60	LF	East Foyer	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" White w/Grey Streaks Floor Tile	20	SF	Teachers' Lounge Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36M	Mastic associated w/12"x12" White w/Grey Streaks Floor Tile	20	SF	Teacher's Lounge Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Wood Pattern Floor Tile	15	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37M	Mastic associated w/12"x12" Wood Pattern Floor Tile	15	SF	Engineer's Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	2'x4' Fissured Ceiling Tile	16	SF	Teacher's Lounge Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	4" White Baseboard and Associated Adhesive	20	LF	Teachers' Lounge Washroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	Boiler Gaskets			Boiler Room	No ACBM	TSI					
M	Incinerator Insulation NOT OBSERVED			Boiler Room	Assumed	TSI					Follow O&M Plan
N	Cardboard Insulation	20	LF	Bathroom Pipe Chase	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan
O	Cardboard Elbows ABATED			Bathroom Pipe Chase	Abated	TSI					
W-1	Window Caulk			Throughout 1955	No ACBM	MISC					
W-2	Window Caulk			Through 1996 Addition	No ACBM	MISC					

Chicago Public Schools

School Grimes School

Unit 23461

Building ID 3680

Address 5450 W. 64th Pl.

Chicago, IL, 60638

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	6/13/2025
Manager Planner Name	Steven Szeregy
100-09766	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
01A	
02	
02A	
21	
21A	
21B	
22	
22A	
22B	
25	
26	2025 - Not Observed
27	
28	
29	
30	
31	
32	

Chicago Public Schools

School Grimes School

Unit 23461

Building ID 3680

Address 5450 W. 64th Pl.

Chicago, IL, 60638

Region 05

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
33	2025 - Not Observed
34	
35	
36	
36M	
37	
37M	
38	
39	
L	
M	2025 - Not Observed
N	
NEW	
O	
W-1	
W-2	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01

MATERIAL DESCRIPTION: 8" Black Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 100, 101, 102, 103, 104, 106, Main Office, Principal's Office & Restroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Not Observed in Rooms 100, 102, 104 & Washrooms

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **8" Black Vinyl Baseboard**

MATERIAL LOCATION: **Room 100, 101, 102, 103, 104, 106, Main Office, Principal's Office & Restroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01A

MATERIAL DESCRIPTION: Mastic Beneath 8" Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 100, 102, Main Office, Principal's Office & Restroom, 104

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **01A**

MATERIAL DESCRIPTION: **Mastic Beneath 8" Vinyl Baseboard**

MATERIAL LOCATION: **Room 100, 102, Main Office, Principal's Office & Restroom, 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02
MATERIAL DESCRIPTION: Gray 8" Vinyl Baseboard
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throught 1996 Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Only in Art Room (107) & Kitchen

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **Gray 8" Vinyl Baseboard**

MATERIAL LOCATION: **Through 1996 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02A

MATERIAL DESCRIPTION: Mastic Beneath Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Througout 1996 Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **02A**

MATERIAL DESCRIPTION: **Mastic Beneath Vinyl Baseboard**

MATERIAL LOCATION: **Throughout 1996 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12x12 Vinyl Floor Tile, Tan w/White and Brown Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	104, 100, Main Office, Principal's Office, Safe, 105, Main Corridor, Teachers' Lounge, 106, 101, 102, Library		
MATERIAL QUANTITY:	7515	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile, Tan w/White and Brown Specks**

MATERIAL LOCATION: **104, 100, Main Office, Principal's Office, Safe, 105, Main Corridor, Teachers' Lounge, 106, 101, 102, Library**

MATERIAL QUANTITY: **7515** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21A		
MATERIAL DESCRIPTION:	12x12 Vinyl Floor Tile, Beige w/Brown and White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Entrance, South Vestibule, Room 103 & Room 106		
MATERIAL QUANTITY:	1310	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **21A**

MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile, Beige w/Brown and White Streaks**

MATERIAL LOCATION: **South Entrance, South Vestibule, Room 103 & Room 106**

MATERIAL QUANTITY: **1310** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21B		
MATERIAL DESCRIPTION:	12x12 Vinyl Floor Tile, White w/Gray Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium		
MATERIAL QUANTITY:	2330	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **21B**

MATERIAL DESCRIPTION: **12x12 Vinyl Floor Tile, White w/Gray Specks**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **2330** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Mastic beneath 12x12 Vinyl Floor Tile, Tan w/White & Brown Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 100, 101, 102, 104, 105 & 106, Library, Principal's Office, Safe, Main Corridor, Teachers' Lounge, Main Office**

MATERIAL QUANTITY: **7515** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/19/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Mastic beneath 12x12 Vinyl Floor Tile, Tan w/White & Brown Specks**

MATERIAL LOCATION: **Rooms 100, 101, 102, 104, 105 & 106, Library, Principal's Office, Safe, Main Corridor, Teachers' Lounge, Main Office**

MATERIAL QUANTITY: **7515** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22A		
MATERIAL DESCRIPTION:	Mastic Beneath 12x12 Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Entrance, South Vestibule, Rooms 103 & 106		
MATERIAL QUANTITY:	1310	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **22A**

MATERIAL DESCRIPTION: **Mastic Beneath 12x12 Vinyl Floor Tile**

MATERIAL LOCATION: **South Entrance, South Vestibule, Rooms 103 & 106**

MATERIAL QUANTITY: **1310** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22B		
MATERIAL DESCRIPTION:	Mastic Beneath 12x12 Vinyl Floor Tile, White w/Gray Specks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium		
MATERIAL QUANTITY:	2330	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **22B**

MATERIAL DESCRIPTION: **Mastic Beneath 12x12 Vinyl Floor Tile, White w/Gray Specks**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **2330** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Vestibule, Above All Ceiling Tile Throughout Handicap Restroom, Kitchen Office and Storage		
MATERIAL QUANTITY:	11000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **South Vestibule, Above All Ceiling Tile Throughout Handicap Restroom, Kitchen Office and Storage**

MATERIAL QUANTITY: **11000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Hard Plaster NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office and Boiler Room		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Not Observed. Brick, CMU & Concrete		

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Hard Plaster NOT OBSERVED**

MATERIAL LOCATION: **Engineer's Office and Boiler Room**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	South Vestibule, Above All Ceiling Tiles Throughout Handicap Restroom, Kitchen Office & Storage		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **South Vestibule, Above All Ceiling Tiles Throughout Handicap Restroom, Kitchen Office & Storage**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28
MATERIAL DESCRIPTION: 2x4 Lay-in Fissure Ceiling Tile
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **2x4 Lay-in Fissure Ceiling Tile**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	2x4 Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium		
MATERIAL QUANTITY:	2564	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **2x4 Ceiling Tile**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **2564** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	2x2 Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, West Foyer, Gym Office		
MATERIAL QUANTITY:	848	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **2x2 Ceiling Tile**

MATERIAL LOCATION: **Kitchen, West Foyer, Gym Office**

MATERIAL QUANTITY: **848** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	Brown Linoleum Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	828	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Brown Linoleum Flooring**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **828** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	Brown Linoleum Flooring Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	828	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Brown Linoleum Flooring Mastic**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **828** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Gray Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104A, Office		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- No Carpet Observed		

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Gray Carpet Mastic**

MATERIAL LOCATION: **Room 104A, Office**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	8" Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	West Foyer		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **8" Brown Baseboard**

MATERIAL LOCATION: **West Foyer**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	8" Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East Foyer		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUILDING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **8" Brown Baseboard Mastic**

MATERIAL LOCATION: **East Foyer**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: Boiler Gaskets

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Boiler Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: M

MATERIAL DESCRIPTION: Incinerator Insulation NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Incinerator Insulation NOT OBSERVED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Cardboard Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathroom Pipe Chase		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUILDING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cardboard Insulation**

MATERIAL LOCATION: **Bathroom Pipe Chase**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: O

MATERIAL DESCRIPTION: Cardboard Elbows ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Bathroom Pipe Chase

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **Cardboard Elbows ABATED**

MATERIAL LOCATION: **Bathroom Pipe Chase**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: W-1
MATERIAL DESCRIPTION: Window Caulk
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout 1955

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **W-1**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Throughout 1955**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: W-2
MATERIAL DESCRIPTION: Window Caulk
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throught 1996 Addition

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Grimes School	REVIEW DATE:	6/13/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

HOMOGENEOUS AREA: **W-2**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Through 1996 Addition**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12"x12" Wood Pattern Floor Tile		
MATERIAL LOCATION:	Engineer's Washroom		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23461** BUIDLING ID: **3680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szeregy**

SCHOOL NAME: **Grimes School** REVIEW DATE: **6/13/2025**

ADDRESS: **5450 W. 64th Pl.** IDPH LICENSE NO: **100-20974**

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12"x12" Wood Pattern Floor Tile**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. [Signature] Date: 06/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	36M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" White w/Grey Streaks Floor Tile				
MATERIAL LOCATION:	Teacher's Lounge Washroom				
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23461** BUIDLING ID: **3680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szereedy**

SCHOOL NAME: **Grimes School** REVIEW DATE: **6/13/2025**

ADDRESS: **5450 W. 64th Pl.** IDPH LICENSE NO: **100-20974**

HOMOGENEOUS AREA: **36M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" White w/Grey Streaks Floor Tile**

MATERIAL LOCATION: **Teacher's Lounge Washroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. ~ Date: 06/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	2'x4' Fissured Ceiling Tile		
MATERIAL LOCATION:	Teacher's Lounge Washroom		
MATERIAL QUANTITY:	16	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23461** BUIDLING ID: **3680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szereedy**

SCHOOL NAME: **Grimes School** REVIEW DATE: **6/13/2025**

ADDRESS: **5450 W. 64th Pl.** IDPH LICENSE NO: **100-20974**

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **2'x4' Fissured Ceiling Tile**

MATERIAL LOCATION: **Teacher's Lounge Washroom**

MATERIAL QUANTITY: **16** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. [Signature] Date: 06/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	4" White Baseboard and Associated Adhesive		
MATERIAL LOCATION:	Teachers' Lounge Washroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23461** BUIDLING ID: **3680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szeregy**

SCHOOL NAME: **Grimes School** REVIEW DATE: **6/13/2025**

ADDRESS: **5450 W. 64th Pl.** IDPH LICENSE NO: **100-20974**

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **4" White Baseboard and Associated Adhesive**

MATERIAL LOCATION: **Teachers' Lounge Washroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. [Signature] Date: 06/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	37M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Wood Pattern Floor Tile				
MATERIAL LOCATION:	Engineer's Washroom				
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23461** BULDING ID: **3680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szeregy**

SCHOOL NAME: **Grimes School** REVIEW DATE: **6/13/2025**

ADDRESS: **5450 W. 64th Pl.** IDPH LICENSE NO: **100-20974**

HOMOGENEOUS AREA: **37M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Wood Pattern Floor Tile**

MATERIAL LOCATION: **Engineer's Washroom**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. ~ Date: 06/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23461	BUIDLING ID:	3680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Anthony Porfilio		
SCHOOL NAME:	Grimes School	INSPECTION DATE:	5/19/2025		
ADDRESS:	5450 W. 64th Pl.	IDPH LICENSE NO:	100-20974		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12"x12" White w/Grey Streaks Floor Tile		
MATERIAL LOCATION:	Teachers' Lounge Washroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/19/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23461** BUIDLING ID: **3680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szereedy**

SCHOOL NAME: **Grimes School** REVIEW DATE: **6/13/2025**

ADDRESS: **5450 W. 64th Pl.** IDPH LICENSE NO: **100-20974**

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12" White w/Grey Streaks Floor Tile**

MATERIAL LOCATION: **Teachers' Lounge Washroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. [Signature] Date: 06/13/2025


APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield

ANTHONY M PORFILIO
2942 W. VAN BUREN ST.
CHICAGO, IL 60612




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 20974

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License


ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 20974	INSPECTOR	1/4/2026
ANTHONY M PORFILIO 2942 W. VAN BUREN ST. CHICAGO, IL 60612 Environmental Health	PROJECT MANAGER AIR SAMPLING PROFESSIONAL <i>Alteration of this license shall result in legal action</i> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	1/11/2026

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



ENDORSEMENTS

INSPECTOR

TC EXPIRES

1/27/2025

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

1/13/2025

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ANTHONY PORFILIO
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/04/2025 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/04/2025

Course Dates:

01/04/2026

Expires:

2501BIR11

Certificate Number:

Director of Training

Nicholas J. Peneff
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B

A handwritten signature in black ink, appearing to read 'Nicholas J. Peneff, DO



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

STEVEN R SZEREDY
16W451 HILLSIDE LN
WILLOWBROOK, IL 60527

3/27/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09766

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License		Back of License	
	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 09766	ISSUED 3/27/2025	EXPIRES 05/15/2026	INSPECTOR 7/12/2025
STEVEN R SZEREDY 16W451 HILLSIDE LN WILLOWBROOK, IL 60527 Environmental Health		MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/20/2026 7/13/2025
		Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Steven Szeregy

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/20/2025

Exam Date: 2/20/2025

Expiration Date: 2/20/2026

Certificate Number: MPR2502200748

Course Credit Hours: MPR 4 Hours

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed