

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2247  
SCHOOL NAME: Haugen School  
ADDRESS OF SCHOOL: 4540 N Hamlin Avenue  
CITY: Chicago, IL, 60625

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 6/23/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 6/4/2025 ENROLLMENT 1064  
IDPH INSPECTOR LICENSE NUMBER: 100-11093  
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 6/25/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Haugan School**

4540 N Hamlin Avenue  
Chicago, IL, 60625

Unit: 23591  
Building ID: 3810

IDPH ID Number: 14-016-2990-2247

**REPORT DATE:**  
Wednesday, June 25, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Specialty Consulting, Inc.**

2942 W. Van Buren Street  
Chicago, IL, 60612  
Phone (312) 319-7575  
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

06/25/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 23591      Region: 01      IDPH ID: 14-016-2990-2247

School: Haugen School      Building ID: 3810

Address: 4540 N Hamlin Avenue

Chicago, IL, 60625

Building Contact: Imparo, Franco      Contact Phone: 7737103854

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/4/2025

Review Date: 06/25/2025

Inspector: David Avila

Inspector IDPH License: 100-11093

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: June 25, 2025

RE: Haugan School, Unit 23591  
4540 N Hamlin Avenue  
Chicago, IL, 60625

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Haugan School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Haugan School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Haugen School  
Address: 4540 N Hamlin Avenue  
IDPH ID: 14-016-2990-2247  
Contact: Imparo, Franco

Unit: 23591  
Chicago, IL, 60625  
Building ID: 3810  
Phone: 7737103854

Region: 01

### 2. Description of Facility

Original Construction: 1993  
Total Square Footage: 7809  
Current Occupancy: 1064

Additional Construction: 1911  
No of Floors: 1

### 3. LEA Designated Person

Contact: Richard J.Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575

Fax: (312) 319-7580

### 5. Inspector

Inspector Name: David Avila

Inspector IDPH license # 100-11093  
Reinspection Date: 6/4/2025

  
Signature:  
Date: 6/4/2025

### 6. Management Planner

Management Planner Name: Arturo Saenz


Management Planner IDPH license # 100-04019

  
Signature:  
Date: 06/25/2025

### 7. Review Date: 06/25/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

  
Signature: *Richard J. Schleyer*  
Date: 6/25/2025

Name: Richard J.Schleyer

## **II. EXECUTIVE SUMMARY**

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Haugen School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 3810:

B. The following new homogenous areas have been identified for Building 3810:

06A	12"x12" Dark Brown Floor Tile Mastic
71	Replacement 12"x12" Cream w/ specs VFT
72	Replacement 12"x12" Cream w/ specs mastic 1300

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

03	2'x4' Ceiling Tile
06A	12"x12" Dark Brown Floor Tile Mastic
12	12"x12" Beige w/ Tan Streaks VFT
14	12"x12" Beige w/ Tan Streaks VFT
15	12"x12" Beige w/ Tan Streaks VFT Mastic
17	12"x12" White VFT Mastic
19	Green Linoleum Mastic - NOT OBSERVED
24	12"x12" Cream VFT
34	12" x 12" White w/ Gray Spots VFT
34A	12" x 12" White w/ Gray Spots VFT Mastic
36	12" x 12" White w/ Creme Spots VFT
36A	12" x 12" White w/ Creme Spots VFT Mastic
38	Off-White Linoleum
39	Off-White Linoleum Mastic
40	Pink Linoleum
41	Pink Linoleum Mastic
42	Textured Tan Linoleum
43	Textured Tan Linoleum Mastic
44	2' x 2' Yellow w/ Grooves Ceiling Tile
45	2' x 2' Pink w/ Grooves Ceiling Tile
46	2' x 4' White Smooth Ceiling Tile
47	2' x 2' White w/ Grooves Ceiling Tile
48	2' x 4' White w/ Grooves Ceiling Tile
49	Drywall
50	Drywall Joint Compound
51	Tan Vinyl Baseboard
52	Tan Vinyl Baseboard Mastic
53	12"X 12" White w/Black Specks Floor Tile
54	12"X 12" White w/ Black Specks Floor Tile MASTIC
55	12"X12" Off-white w/Tan Specks VFT
55A	12"X12" Off-white w/Tan Specks VFT Mastic
56	Terrazzo
57	12"X12" Light-Beige VFT
57A	12"X12" Light-Beige VFT Mastic
58	12"X12" Tan Speckled VFT
58A	12"X12" Tan Speckled VFT Mastic
59	9"x9" Peach VFT
59A	9"x9" Peach VFT MASTIC
60	12"x12" Tan w/ brown streaks and white streaks VFT (over HA 59&59A)
60A	12"x12" Tan w/ brown streaks and white streaks

	VFT MASTIC (over HA 59&59A)
61	12"x12 Off white w/ beige specks VFT
61A	12"x12 Off white w/ beige specks VFT MASTIC
62	12" x 12" Off white w/ beige specks VFT
62A	12" x 12" Off white w/ beige specks VFT MASTIC
63	12"x12" Off white w/ gray shadows VFT
63A	12"x12" Off white w/ gray shadows VFT MASTIC
64	12"x12" Beige w/ tan streaks VFT
64A	12"x12" Beige w/ tan streaks VFT MASTIC
65	12"x12" White w/ blue specks VFT
65A	12"x12" White w/ blue specks VFT MASTIC
66	Hard Coat Plaster
67	Hard Coat Plaster
68	Carpet Masitc
69	12" x 12" Light Brown w/ White and Brown Streaks VFT
69A	12" x 12" Light Brown w/ White and Brown Streaks VFT Mastic
70	Cream Linoleum
70A	Cream Linoleum Mastic
71	Replacement 12"x12" Cream w/ specs VFT
72	Replacement 12"x12" Cream w/ specs mastic 1300
O	MJP E/F/V on Fiberglass Pipe Insulation
P	Spray-on Insulation - Not Observed
Q	Spray-on Insulation - Not Observed

The following areas were deemed to be inaccessible:

06A	12"x12" Dark Brown Floor Tile Mastic
72	Replacement 12"x12" Cream w/ specs mastic 1300

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:      7/23/2025  
                                  7/23/2025

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Haugan School Building 3810 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
03	2'x4' Ceiling Tile	50	SF	Engineer's Office - 1911 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
04	12"x12" Dark Brown VFT	24,435	SF	Throughout (See Hatching Maps) - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	9"x9" Orange & Brown Spotted VFT - Not Observed	400	SF	Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06	12"x12" Dark Brown VFT Mastic	25,435	SF	Throughout (See Hatching Maps) - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
06A	12"x12" Dark Brown Floor Tile Mastic	25,435	SF	Throughout (See Hatching Maps) - 1911 Bldg.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
07	9"x9" Orange & Brown Spotted VFT Mastic - NOT OBSERVED	400	SF	Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	12"x12" Dark Brown VFT	15,280	SF	Throughout (See Hatching Maps) - 1920 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	12"x12" Dark Brown Mastic	15,280	SF	Throughout (See Hatching Maps) - 1920 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
10	Green Linoleum - NOT OBSERVED	1,200	SF	Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	Green Linoleum Mastic - NOT OBSERVED	600	SF	Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
12	12"x12" Beige w/ Tan Streaks VFT	600	SF	3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet - 1920 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12"x12" Beige w/ Tan Streaks VFT Mastic	600	SF	3rd Floor Boy's Toilet & 2nd Floor Girl's, 1st floor boys & girls restroom -	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
14	12"x12" Beige w/ Tan Streaks VFT	380	SF	1920 Bldg. 2nd and 3rd Floor Girls Bathrooms - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
15	12"x12" Beige w/ Tan Streaks VFT Mastic	380	SF	2nd and 3rd Floor Girls Bathrooms, 1st floor boys & girls restroom - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	12"x12" White VFT	1,650	SF	Room 112, 114 (not observed) & 2nd Floor Teacher's Toilet - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
17	12"x12" White VFT Mastic	1,650	SF	Room 112, 114 & 2nd Floor Teacher's Toilet - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	Green Linoleum - NOT OBSERVED	300	SF	Girl's Toilet (Under HA # 14 & 15), Behind Engineer's Office - 1911 Bldg. (NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
19	Green Linoleum Mastic - NOT OBSERVED	300	SF	Girl's Toilet (under HA # 14 & 15) Behind Engineer's Office - 1911 Bldg. (NOT OBSERVED)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Pink VFT	100	SF	Main Office - 1920 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	12"x12" Pink VFT Mastic	100	SF	Main Office - 1920 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12"x12" Tan VFT - NOT OBSERVED	2,350	SF	Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. (NOT OBSERVED)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12"x12" Tan VFT Mastic - NOT OBSERVED	2,350	SF	Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Cream VFT	300	SF	Room 105 - 1920 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12"x12" Cream VFT Mastic	300	SF	Room 105 - 1920	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.								potential for damage		
26	12"x12" Taupe VFT	300	SF	Room 105 - 1920 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12"x12" Taupe VFT Mastic	300	SF	Room 105 - 1920 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12"x12" White VFT - NOT OBSERVED	875	SF	Room 116 - 1920 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12"x12" White VFT Mastic - NOT OBSERVED	875	SF	Room 116 - 1920 Bldg. - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12"x12" Cream VFT	100	SF	Engineer's Office - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12"x12" Cream VFT Mastic	100	SF	Engineer's Office - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	12"x12" Taupe VFT	100	SF	Engineer's Office - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	12"x12" Taupe VFT Mastic	100	SF	Engineer's Office - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	12" x 12" White w/ Gray Spots VFT	875	SF	Room 301 - 1920 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34A	12" x 12" White w/ Gray Spots VFT Mastic	875	SF	Room 301 - 1920 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	12" x 12" White w/ Creme Spots VFT	1,750	SF	Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36A	12" x 12" White w/ Creme Spots VFT Mastic	1,750	SF	Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	Off-White Linoleum	600	SF	Kitchen Office, Lockerroom, Bathroom - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	Off-White Linoleum Mastic	600	SF	Kitchen Office, Lockerroom, Bathroom - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Pink Linoleum	600	SF	Locker Room Restroom - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Pink Linoleum Mastic	1,200	SF	Locker Room Restroom - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Textured Tan Linoleum	800	SF	Kitchen, Serving	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Area - 1994 Bldg.								potential for damage		
43	Textured Tan Linoleum Mastic	800	SF	Kitchen, Serving Area - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	2' x 2' Yellow w/ Grooves Ceiling Tile	600	SF	Lunchroom, South Kitchen Entrance - 1994 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
45	2' x 2' Pink w/ Grooves Ceiling Tile	600	SF	Lunchroom - 1994 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
46	2' x 4' White Smooth Ceiling Tile	600	SF	Kitchen, Serving Area - 1994 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
47	2' x 2' White w/ Grooves Ceiling Tile	600	SF	Teachers Lounge - 1994 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
48	2' x 4' White w/ Grooves Ceiling Tile	900	SF	Kitchen Office, Lockerroom, Lockerroom Bathroom - 1994 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
49	Drywall	6,000	SF	Throughout - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Drywall Joint Compound	2,000	SF	Throughout - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Tan Vinyl Baseboard	200	LF	Throughout - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	Tan Vinyl Baseboard Mastic	200	LF	Throughout - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"X 12" White w/Black Specks Floor Tile	1,000	SF	Room 311 - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12"X 12" White w/ Black Specks Floor Tile MASTIC	1,000	SF	Room 311 - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12"X12" Off-white w/Tan Specks VFT	800	SF	Room 321 - 1920 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55A	12"X12" Off-white w/Tan Specks VFT Mastic	800	SF	Room 321 - 1920 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Terrazzo	3,000	SF	1st, 2nd, and 3rd Floor Corridors, Janitor's Closets and Stairwells - 1920 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	12"X12" Light-Beige VFT	600	SF	Faculty Lounge - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57A	12"X12" Light-Beige VFT Mastic	600	SF	Faculty Lounge - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12"X12" Tan Speckled VFT	2,500	SF	Lunch Room - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
58A	12"X12" Tan Speckled VFT Mastic	2,500	SF	Lunch Room - 1994 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	9"x9" Peach VFT	46	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59A	9"x9" Peach VFT MASTIC	46	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12"x12" Tan w/ brown streaks and white streaks VFT (over HA 59&59A)	46	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60A	12"x12" Tan w/ brown streaks and white streaks VFT MASTIC (over HA 59&59A)	46	SF	Boiler Room Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12"x12 Off white w/ beige specks VFT	3,500	SF	Rooms 304 (Hardwood Floors) , 306, 303, 307, 308, - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61A	12"x12 Off white w/ beige specks VFT MASTIC	3,500	SF	Rooms 304 (hardwood floor), 306, 303, 307, 308, 309 - 1911 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12" x 12" Off white w/ beige specks VFT	3,500	SF	Rooms 317, 312, 300 (hardwood floor), 320 - 1920 addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62A	12" x 12" Off white w/ beige specks VFT MASTIC	3,500	SF	Rooms 317, 312, 300 (hardwood floor), 320 - 1920 addition	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12"x12" Off white w/ gray shadows VFT	450	SF	Room 109 - principal's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63A	12"x12" Off white w/ gray shadows VFT MASTIC	450	SF	Room 109 - principal's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12"x12" Beige w/ tan streaks VFT	875	SF	Room 116	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64A	12"x12" Beige w/ tan streaks VFT MASTIC	875	SF	Room 116	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
65	12"x12" White w/ blue specks VFT	400	SF	Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65A	12"x12" White w/ blue specks VFT MASTIC	400	SF	Room 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Hard Coat Plaster	80,000	SF	Throughout 1911 Main building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Hard Coat Plaster	80,000	SF	Throughout 1920 Additions	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
68	Carpet Masitc	4,600	SF	2nd Floor Teachers lounge, Rooms 106,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				107, 108, Auditorium										
69	12" x 12" Light Brown w/ White and Brown Streaks VFT	300	SF	Non-labelled Room North of Room 301	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69A	12" x 12" Light Brown w/ White and Brown Streaks VFT Mastic	300	SF	Non-labelled Room North of Room 301	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	Cream Linoleum	600	SF	Room 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70A	Cream Linoleum Mastic	600	SF	Room 111	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Replacement 12"x12" Cream w/ specs VFT	1,300	SF	1st 2nd, and 3rd floor corridors, 314, 306, 303, 224,119, 115, 3rd floor, boys and girls toilets, gym/auditorium.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
72	Replacement 12"x12" Cream w/ specs mastic 1300	1,300	SF	1st 2nd, and 3rd floor corridors, 314, 306, 303, 224,119, 115, 3rd floor, boys and girls toilets, gym/auditorium.	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
C	Aircell Pipe Insulation	1,500	LF	Throughout (See Hatching Maps) - 1911 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP E/F/V on Aircell Pipe Insulation - Not Observed	300	FITTING	Throughout (See Hatching Maps) - 1911 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	Preform Pipe Insulation	50	LF	Engine Room/Tank Room - 1911 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Preform Pipe Insulation	7	FITTING	Engine Room/Tank Room - 1911 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Aircell Pipe Insulation - Not Observed	1,000	LF	Main Office, Counselor's Office, Pipe Tunnels, Room 105 (Abated) - 1920 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	MJP E/F/V on Aircell Pipe Insulation	75	FITTING	Main Office, Counselor's Office, Pipe Tunnels, 1920 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	MJP E/F/V on Fiberglass Pipe Insulation	124	FITTING	Girl's Toilet Chases & Boy's Toilet Chases - 1920 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
J	Boiler Gaskets - Not Observed	80	LF	Boiler Room - 1911 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
K	Cardboard Pipe Insulation - Not Observed	100	LF	Throughout (See Hatching Maps) - 1911 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	MJP E/F/V on Cardboard Pipe Insulation	8	FITTING	Throughout (See Hatching Maps) - 1911 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
M	Cardboard Pipe Insulation	70	LF	Main Office, Air Tunnels - 1920 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
N	MJP E/F/V on Cardboard Pipe Insulation	20	FITTING	Main Office, Air Tunnels - 1920 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	MJP E/F/V on Fiberglass Pipe Insulation	100	FITTING	Throughout (See Hatching Maps) - 1911 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
P	Spray-on Insulation - Not Observed	600	SF	Room 111	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
Q	Spray-on Insulation - Not Observed	5,000	SF	On I-Beams above Ceiling Tiles Throughout 1994 Addition	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Haugen School Unit 23591 Building ID 3810  
Address 4540 N Hamlin Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date 6/4/2025  
Inspector Name David Avila  
**100-11093** 5/15/2026  
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
03	
04	
05	
06	
06A	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	Possibly under carpet
23	
24	
25	

# Chicago Public Schools

**School** Haugen School **Unit** 23591 **Building ID** 3810  
**Address** 4540 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
26	
27	
28	
29	
30	
31	
32	
33	
34	
34A	
36	
36A	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	

# Chicago Public Schools

School Haugan School Unit 23591 Building ID 3810  
Address 4540 N Hamlin Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
55	
55A	
56	
57	
57A	
58	
58A	
59	
59A	
60	
60A	
61	
61A	
62	
62A	
63	
63A	
64	
64A	
65	
65A	
66	
67	
68	
69	
69A	
70	
70A	
71	

# Chicago Public Schools

School Haugen School Unit 23591 Building ID 3810  
Address 4540 N Hamlin Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
72	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	
P	
Q	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Haugen School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575      Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
03	2'x4' Ceiling Tile	50	SF	Engineer's Office - 1911 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
04	12"x12" Dark Brown VFT	24,435	SF	Throughout (See Hatching Maps) - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	9"x9" Orange & Brown Spotted VFT - Not Observed	400	SF	Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06	12"x12" Dark Brown VFT Mastic	25,435	SF	Throughout (See Hatching Maps) - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	12"x12" Dark Brown Floor Tile Mastic	25,435	SF	Throughout (See Hatching Maps) - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07	9"x9" Orange & Brown Spotted VFT Mastic - NOT OBSERVED	400	SF	Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Dark Brown VFT	15,280	SF	Throughout (See Hatching Maps) - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12"x12" Dark Brown Mastic	15,280	SF	Throughout (See Hatching Maps) - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Green Linoleum - NOT OBSERVED	1,200	SF	Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Green Linoleum Mastic - NOT OBSERVED	600	SF	Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12"x12" Beige w/ Tan Streaks VFT	600	SF	3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet - 1920 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12"x12" Beige w/ Tan Streaks VFT Mastic	600	SF	3rd Floor Boy's Toilet & 2nd Floor Girl's, 1st floor boys & girls restroom - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	12"x12" Beige w/ Tan Streaks VFT	380	SF	2nd and 3rd Floor Girls Bathrooms - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	12"x12" Beige w/ Tan Streaks VFT Mastic	380	SF	2nd and 3rd Floor Girls Bathrooms, 1st floor boys & girls restroom - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" White VFT	1,650	SF	Room 112, 114 (not observed) & 2nd Floor Teacher's Toilet - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" White VFT Mastic	1,650	SF	Room 112, 114 & 2nd Floor Teacher's Toilet - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Green Linoleum - NOT OBSERVED	300	SF	Girl's Toilet (Under HA # 14 & 15), Behind Engineer's Office - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Haugen School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				(NOT OBSERVED)							
19	Green Linoleum Mastic - NOT OBSERVED	300	SF	Girl's Toilet (under HA # 14 & 15) Behind Engineer's Office - 1911 Bldg. (NOT OBSERVED)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Pink VFT	100	SF	Main Office - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12"x12" Pink VFT Mastic	100	SF	Main Office - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Tan VFT - NOT OBSERVED	2,350	SF	Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. (NOT OBSERVED)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12"x12" Tan VFT Mastic - NOT OBSERVED	2,350	SF	Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Cream VFT	300	SF	Room 105 - 1920 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" Cream VFT Mastic	300	SF	Room 105 - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" Taupe VFT	300	SF	Room 105 - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" Taupe VFT Mastic	300	SF	Room 105 - 1920 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" White VFT - NOT OBSERVED	875	SF	Room 116 - 1920 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" White VFT Mastic - NOT OBSERVED	875	SF	Room 116 - 1920 Bldg. - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" Cream VFT	100	SF	Engineer's Office - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Cream VFT Mastic	100	SF	Engineer's Office - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Taupe VFT	100	SF	Engineer's Office - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12"x12" Taupe VFT Mastic	100	SF	Engineer's Office - 1911 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	12" x 12" White w/ Gray Spots VFT	875	SF	Room 301 - 1920 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34A	12" x 12" White w/ Gray Spots VFT Mastic	875	SF	Room 301 - 1920 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" White w/ Creme Spots VFT	1,750	SF	Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12" x 12" White w/ Creme Spots VFT Mastic	1,750	SF	Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Off-White Linoleum	600	SF	Kitchen Office, Lockeroom Bathroom - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Off-White Linoleum Mastic	600	SF	Kitchen Office, Lockeroom Bathroom - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Pink Linoleum	600	SF	Locker Room Restroom - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Pink Linoleum Mastic	1,200	SF	Locker Room Restroom - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Haugen School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
42	Textured Tan Linoleum	800	SF	Kitchen, Serving Area - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Textured Tan Linoleum Mastic	800	SF	Kitchen, Serving Area - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	2' x 2' Yellow w/ Grooves Ceiling Tile	600	SF	Lunchroom, South Kitchen Entrance - 1994 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	2' x 2' Pink w/ Grooves Ceiling Tile	600	SF	Lunchroom - 1994 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	2' x 4' White Smooth Ceiling Tile	600	SF	Kitchen, Serving Area - 1994 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	2' x 2' White w/ Grooves Ceiling Tile	600	SF	Teachers Lounge - 1994 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	2' x 4' White w/ Grooves Ceiling Tile	900	SF	Kitchen Office, Lockeroom, Lockeroom Bathroom - 1994 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Drywall	6,000	SF	Throughout - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Drywall Joint Compound	2,000	SF	Throughout - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Tan Vinyl Baseboard	200	LF	Throughout - 1994 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
52	Tan Vinyl Baseboard Mastic	200	LF	Throughout - 1994 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"X 12" White w/Black Specks Floor Tile	1,000	SF	Room 311 - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12"X 12" White w/ Black Specks Floor Tile MASTIC	1,000	SF	Room 311 - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12"X12" Off-white w/Tan Specks VFT	800	SF	Room 321 - 1920 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55A	12"X12" Off-white w/Tan Specks VFT Mastic	800	SF	Room 321 - 1920 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	Terrazzo	3,000	SF	1st, 2nd, and 3rd Floor Corridors, Janitor's Closets and Stairwells - 1920 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12"X12" Light-Beige VFT	600	SF	Faculty Lounge - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57A	12"X12" Light-Beige VFT Mastic	600	SF	Faculty Lounge - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12"X12" Tan Speckled VFT	2,500	SF	Lunch Room - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58A	12"X12" Tan Speckled VFT Mastic	2,500	SF	Lunch Room - 1994 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	9"x9" Peach VFT	46	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59A	9"x9" Peach VFT MASTIC	46	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12"x12" Tan w/ brown streaks and white streaks VFT (over HA 59&59A)	46	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60A	12"x12" Tan w/ brown streaks and white streaks VFT MASTIC (over HA 59&59A)	46	SF	Boiler Room Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12"x12 Off white w/ beige specks VFT	3,500	SF	Rooms 304 (Hardwood Floors) , 306, 303, 307, 308, - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61A	12"x12 Off white w/ beige specks VFT MASTIC	3,500	SF	Rooms 304 (hardwood floor), 306, 303, 307, 308, 309 - 1911 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Off white w/ beige specks VFT	3,500	SF	Rooms 317, 312, 300 (hardwood floor),	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Haugen School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				320 - 1920 addition							
62A	12" x 12" Off white w/ beige specks VFT MASTIC	3,500	SF	Rooms 317, 312, 300 (hardwood floor), 320 - 1920 addition	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12"x12" Off white w/ gray shadows VFT	450	SF	Room 109 - principal's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63A	12"x12" Off white w/ gray shadows VFT MASTIC	450	SF	Room 109 - principal's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12"x12" Beige w/ tan streaks VFT	875	SF	Room 116	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64A	12"x12" Beige w/ tan streaks VFT MASTIC	875	SF	Room 116	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	12"x12" White w/ blue specks VFT	400	SF	Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65A	12"x12" White w/ blue specks VFT MASTIC	400	SF	Room 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Hard Coat Plaster	80,000	SF	Throughout 1911 Main building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Hard Coat Plaster	80,000	SF	Throughout 1920 Additions	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Carpet Mastic	4,600	SF	2nd Floor Teachers lounge, Rooms 106, 107, 108, Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Light Brown w/ White and Brown Streaks VFT	300	SF	Non-labelled Room North of Room 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69A	12" x 12" Light Brown w/ White and Brown Streaks VFT Mastic	300	SF	Non-labelled Room North of Room 301	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	Cream Linoleum	600	SF	Room 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70A	Cream Linoleum Mastic	600	SF	Room 111	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Replacement 12"x12" Cream w/ specs VFT	1,300	SF	1st 2nd, and 3rd floor corridors, 314, 306, 303, 224,119, 115, 3rd floor, boys and girls toilets, gym/auditorium.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Replacement 12"x12" Cream w/ specs mastic 1300	1,300	SF	1st 2nd, and 3rd floor corridors, 314, 306, 303, 224,119, 115, 3rd floor, boys and girls toilets, gym/auditorium.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	1,500	LF	Throughout (See Hatching Maps) - 1911 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Aircell Pipe Insulation - Not Observed	300	FITTING	Throughout (See Hatching Maps) - 1911 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
E	Preform Pipe Insulation	50	LF	Engine Room/Tank Room - 1911 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Preform Pipe Insulation	7	FITTING	Engine Room/Tank Room - 1911 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
G	Aircell Pipe Insulation - Not Observed	1,000	LF	Main Office, Counselor's Office, Pipe Tunnels, Room 105 (Abated) - 1920 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	MJP E/F/V on Aircell Pipe Insulation	75	FITTING	Main Office, Counselor's Office, Pipe Tunnels, 1920 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Haugen School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575      Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
I	MJP E/F/V on Fiberglass Pipe Insulation	124	FITTING	Girl's Toilet Chases & Boy's Toilet Chases - 1920 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
J	Boiler Gaskets - Not Observed	80	LF	Boiler Room - 1911 Bldg.	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Cardboard Pipe Insulation - Not Observed	100	LF	Throughout (See Hatching Maps) - 1911 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	MJP E/F/V on Cardboard Pipe Insulation	8	FITTING	Throughout (See Hatching Maps) - 1911 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
M	Cardboard Pipe Insulation	70	LF	Main Office, Air Tunnels - 1920 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
N	MJP E/F/V on Cardboard Pipe Insulation	20	FITTING	Main Office, Air Tunnels - 1920 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
O	MJP E/F/V on Fiberglass Pipe Insulation	100	FITTING	Throughout (See Hatching Maps) - 1911 Bldg.	Assumed	MISC	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
P	Spray-on Insulation - Not Observed	600	SF	Room 111	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Q	Spray-on Insulation - Not Observed	5,000	SF	On I-Beams above Ceiling Tiles Throughout 1994 Addition	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Haugan School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

***Management Planner's Comments Summarized at the End of the Report***

Review Date	6/25/2025
Manager Planner Name	Arturo Saenz
100-04019	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
03	
04	
05	
06	
06A	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	

# Chicago Public Schools

**School** Haugan School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
34A	
36	
36A	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	

# Chicago Public Schools

**School** Haugan School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
51	
52	
53	
54	
55	
55A	
56	
57	
57A	
58	
58A	
59	
59A	
60	
60A	
61	
61A	
62	
62A	
63	
63A	
64	
64A	
65	
65A	
66	
67	

# Chicago Public Schools

**School** Haugan School

**Unit** 23591

**Building ID** 3810

**Address** 4540 N Hamlin Avenue

Chicago, IL, 60625

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
68	
69	
69A	
70	
70A	
71	
72	
C	
D	
E	
F	
G	
H	
I	
J	
K	
L	
M	
N	
O	
P	
Q	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Specialty Consulting, Inc.

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUILDING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	2'x4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	Engineer's Office - 1911 Bldg.		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **2'x4' Ceiling Tile**

MATERIAL LOCATION: **Engineer's Office - 1911 Bldg.**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	12"x12" Dark Brown VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.		
MATERIAL QUANTITY:	24435	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **12"x12" Dark Brown VFT**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **24435** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	9"x9" Orange & Brown Spotted VFT - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: 05

MATERIAL DESCRIPTION: 9"x9" Orange & Brown Spotted VFT - Not Observed

MATERIAL LOCATION: Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)

MATERIAL QUANTITY: 400 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/25/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	12"x12" Dark Brown VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.		
MATERIAL QUANTITY:	25435	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **12"x12" Dark Brown VFT Mastic**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **25435** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	9"x9" Orange & Brown Spotted VFT Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: 07

MATERIAL DESCRIPTION: 9"x9" Orange & Brown Spotted VFT Mastic - NOT OBSERVED

MATERIAL LOCATION: Room 301 (Under HA # 34) - 1920 Bldg. (NOT OBSERVED)

MATERIAL QUANTITY: 400 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/25/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	12"x12" Dark Brown VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1920 Bldg.		
MATERIAL QUANTITY:	15280	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12"x12" Dark Brown VFT**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1920 Bldg.**

MATERIAL QUANTITY: **15280** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	12"x12" Dark Brown Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1920 Bldg.		
MATERIAL QUANTITY:	15280	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x12" Dark Brown Mastic**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1920 Bldg.**

MATERIAL QUANTITY: **15280** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Green Linoleum - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Green Linoleum - NOT OBSERVED**

MATERIAL LOCATION: **Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Green Linoleum Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Green Linoleum Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Room 111, 3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet (Under HA#13) - 1920 Bldg. (NOT OBSERVED)**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet - 1920 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Tan Streaks VFT**

MATERIAL LOCATION: **3rd Floor Boy's Toilet & 2nd Floor Girl's Toilet - 1920 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Boy's Toilet & 2nd Floor Girl's, 1st floor boys & girls restroom - 1920 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: 13

MATERIAL DESCRIPTION: 12"x12" Beige w/ Tan Streaks VFT Mastic

MATERIAL LOCATION: 3rd Floor Boy's Toilet & 2nd Floor Girl's, 1st floor boys & girls restroom - 1920 Bldg.

MATERIAL QUANTITY: 600 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/25/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Girls Bathrooms - 1911 Bldg.		
MATERIAL QUANTITY:	380	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Tan Streaks VFT**

MATERIAL LOCATION: **2nd and 3rd Floor Girls Bathrooms - 1911 Bldg.**

MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Girls Bathrooms, 1st floor boys & girls restroom - 1911 Bldg.		
MATERIAL QUANTITY:	380	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Tan Streaks VFT Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Girls Bathrooms, 1st floor boys & girls restroom - 1911 Bldg.**

MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12"x12" White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 112, 114 (not observed) & 2nd Floor Teacher's Toilet - 1911 Bldg.		
MATERIAL QUANTITY:	1650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **06/04/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: 16

MATERIAL DESCRIPTION: 12"x12" White VFT

MATERIAL LOCATION: Room 112, 114 (not observed) & 2nd Floor Teacher's Toilet - 1911 Bldg.

MATERIAL QUANTITY: 1650 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/25/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12"x12" White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 112, 114 & 2nd Floor Teacher's Toilet - 1911 Bldg.		
MATERIAL QUANTITY:	1650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**

MATERIAL LOCATION: **Room 112, 114 & 2nd Floor Teacher's Toilet - 1911 Bldg.**

MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Green Linoleum - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's Toilet (Under HA # 14 & 15), Behind Engineer's Office - 1911 Bldg. (NOT OBSERVED)		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Green Linoleum - NOT OBSERVED**

MATERIAL LOCATION: **Girl's Toilet (Under HA # 14 & 15), Behind Engineer's Office - 1911 Bldg. (NOT OBSERVED)**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Green Linoleum Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's Toilet (under HA # 14 & 15) Behind Engineer's Office - 1911 Bldg. (NOT OBSERVED)		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Green Linoleum Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Girl's Toilet (under HA # 14 & 15) Behind Engineer's Office - 1911 Bldg. (NOT OBSERVED)**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12"x12" Pink VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office - 1920 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12"x12" Pink VFT**

MATERIAL LOCATION: **Main Office - 1920 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12"x12" Pink VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office - 1920 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12"x12" Pink VFT Mastic**

MATERIAL LOCATION: **Main Office - 1920 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12"x12" Tan VFT - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. (NOT OBSERVED)		
MATERIAL QUANTITY:	2350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Possibly under carpet		

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12"x12" Tan VFT - NOT OBSERVED**

MATERIAL LOCATION: **Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. (NOT OBSERVED)**

MATERIAL QUANTITY: **2350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12"x12" Tan VFT Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. - NOT OBSERVED		
MATERIAL QUANTITY:	2350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Principals Office (Under Carpet), Room 106 & 107 (Under Carpet) - 1920 Bldg. - NOT OBSERVED**

MATERIAL QUANTITY: **2350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12"x12" Cream VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105 - 1920 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12"x12" Cream VFT**

MATERIAL LOCATION: **Room 105 - 1920 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12"x12" Cream VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105 - 1920 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" Cream VFT Mastic**

MATERIAL LOCATION: **Room 105 - 1920 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12"x12" Taupe VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105 - 1920 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12"x12" Taupe VFT**

MATERIAL LOCATION: **Room 105 - 1920 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12"x12" Taupe VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105 - 1920 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" Taupe VFT Mastic**

MATERIAL LOCATION: **Room 105 - 1920 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12"x12" White VFT - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 116 - 1920 Bldg. - NOT OBSERVED		
MATERIAL QUANTITY:	875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" White VFT - NOT OBSERVED**

MATERIAL LOCATION: **Room 116 - 1920 Bldg. - NOT OBSERVED**

MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12"x12" White VFT Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 116 - 1920 Bldg. - NOT OBSERVED		
MATERIAL QUANTITY:	875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" White VFT Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Room 116 - 1920 Bldg. - NOT OBSERVED**

MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12"x12" Cream VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office - 1911 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"x12" Cream VFT**

MATERIAL LOCATION: **Engineer's Office - 1911 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12"x12" Cream VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office - 1911 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12"x12" Cream VFT Mastic**

MATERIAL LOCATION: **Engineer's Office - 1911 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12"x12" Taupe VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office - 1911 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12"x12" Taupe VFT**

MATERIAL LOCATION: **Engineer's Office - 1911 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12"x12" Taupe VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office - 1911 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12"x12" Taupe VFT Mastic**

MATERIAL LOCATION: **Engineer's Office - 1911 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Spots VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301 - 1920 Bldg.		
MATERIAL QUANTITY:	875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: 34

MATERIAL DESCRIPTION: 12" x 12" White w/ Gray Spots VFT

MATERIAL LOCATION: Room 301 - 1920 Bldg.

MATERIAL QUANTITY: 875 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/25/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34A		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Spots VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301 - 1920 Bldg.		
MATERIAL QUANTITY:	875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **34A**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Spots VFT Mastic**

MATERIAL LOCATION: **Room 301 - 1920 Bldg.**

MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12" x 12" White w/ Creme Spots VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" White w/ Creme Spots VFT**

MATERIAL LOCATION: **Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.**

MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36A		
MATERIAL DESCRIPTION:	12" x 12" White w/ Creme Spots VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **36A**

MATERIAL DESCRIPTION: **12" x 12" White w/ Creme Spots VFT Mastic**

MATERIAL LOCATION: **Room 114 & 112, (9x9 Tile under 12x12) - 1911 Bldg.**

MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Off-White Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Office, Lockerroom Bathroom - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Off-White Linoleum**

MATERIAL LOCATION: **Kitchen Office, Lockerroom Bathroom - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Off-White Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Office, Lockerroom Bathroom - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Off-White Linoleum Mastic**

MATERIAL LOCATION: **Kitchen Office, Lockerroom Bathroom - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Pink Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Locker Room Restroom - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Pink Linoleum**

MATERIAL LOCATION: **Locker Room Restroom - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Pink Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Locker Room Restroom - 1994 Bldg.		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Pink Linoleum Mastic**

MATERIAL LOCATION: **Locker Room Restroom - 1994 Bldg.**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Textured Tan Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, Serving Area - 1994 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Textured Tan Linoleum**

MATERIAL LOCATION: **Kitchen, Serving Area - 1994 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Textured Tan Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, Serving Area - 1994 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Textured Tan Linoleum Mastic**

MATERIAL LOCATION: **Kitchen, Serving Area - 1994 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	2' x 2' Yellow w/ Grooves Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, South Kitchen Entrance - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **2' x 2' Yellow w/ Grooves Ceiling Tile**

MATERIAL LOCATION: **Lunchroom, South Kitchen Entrance - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	2' x 2' Pink w/ Grooves Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **2' x 2' Pink w/ Grooves Ceiling Tile**

MATERIAL LOCATION: **Lunchroom - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	2' x 4' White Smooth Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, Serving Area - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **2' x 4' White Smooth Ceiling Tile**

MATERIAL LOCATION: **Kitchen, Serving Area - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	2' x 2' White w/ Grooves Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers Lounge - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **2' x 2' White w/ Grooves Ceiling Tile**

MATERIAL LOCATION: **Teachers Lounge - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	2' x 4' White w/ Grooves Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen Office, Lockerroom, Lockerroom Bathroom - 1994 Bldg.		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **2' x 4' White w/ Grooves Ceiling Tile**

MATERIAL LOCATION: **Kitchen Office, Lockeroom, Lockeroom Bathroom - 1994 Bldg.**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1994 Bldg.		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout - 1994 Bldg.**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1994 Bldg.		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **Throughout - 1994 Bldg.**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Tan Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1994 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Tan Vinyl Baseboard**

MATERIAL LOCATION: **Throughout - 1994 Bldg.**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	Tan Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1994 Bldg.		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Tan Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout - 1994 Bldg.**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12"X 12" White w/Black Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 311 - 1911 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"X 12" White w/Black Specks Floor Tile**

MATERIAL LOCATION: **Room 311 - 1911 Bldg.**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	12"X 12" White w/ Black Specks Floor Tile MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 311 - 1911 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: 54

MATERIAL DESCRIPTION: 12"X 12" White w/ Black Specks Floor Tile MASTIC

MATERIAL LOCATION: Room 311 - 1911 Bldg.

MATERIAL QUANTITY: 1000 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/25/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12"X12" Off-white w/Tan Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 321 - 1920 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12"X12" Off-white w/Tan Specks VFT**

MATERIAL LOCATION: **Room 321 - 1920 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55A		
MATERIAL DESCRIPTION:	12"X12" Off-white w/Tan Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 321 - 1920 Bldg.		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **55A**

MATERIAL DESCRIPTION: **12"X12" Off-white w/Tan Specks VFT Mastic**

MATERIAL LOCATION: **Room 321 - 1920 Bldg.**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd, and 3rd Floor Corridors, Janitor's Closets and Stairwells - 1920 Bldg.		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **1st, 2nd, and 3rd Floor Corridors, Janitor's Closets and Stairwells - 1920 Bldg.**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	12"X12" Light-Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Faculty Lounge - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12"X12" Light-Beige VFT**

MATERIAL LOCATION: **Faculty Lounge - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57A		
MATERIAL DESCRIPTION:	12"X12" Light-Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Faculty Lounge - 1994 Bldg.		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **57A**

MATERIAL DESCRIPTION: **12"X12" Light-Beige VFT Mastic**

MATERIAL LOCATION: **Faculty Lounge - 1994 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12"X12" Tan Speckled VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunch Room - 1994 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12"X12" Tan Speckled VFT**

MATERIAL LOCATION: **Lunch Room - 1994 Bldg.**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58A		
MATERIAL DESCRIPTION:	12"X12" Tan Speckled VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunch Room - 1994 Bldg.		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **58A**

MATERIAL DESCRIPTION: **12"X12" Tan Speckled VFT Mastic**

MATERIAL LOCATION: **Lunch Room - 1994 Bldg.**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	9"x9" Peach VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room Bathroom		
MATERIAL QUANTITY:	46	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **9"x9" Peach VFT**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: **46** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59A		
MATERIAL DESCRIPTION:	9"x9" Peach VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room Bathroom		
MATERIAL QUANTITY:	46	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **59A**

MATERIAL DESCRIPTION: **9"x9" Peach VFT MASTIC**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: **46** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	12"x12" Tan w/ brown streaks and white streaks VFT (over HA 59&59A)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room Bathroom		
MATERIAL QUANTITY:	46	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12"x12" Tan w/ brown streaks and white streaks VFT (over HA 59&59A)**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: **46** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUILDING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60A		
MATERIAL DESCRIPTION:	12"x12" Tan w/ brown streaks and white streaks VFT MASTIC (over HA 59&59A)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: **46** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/04/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **60A**

MATERIAL DESCRIPTION: **12"x12" Tan w/ brown streaks and white streaks VFT MASTIC (over HA 59&59A)**

MATERIAL LOCATION: **Boiler Room Bathroom**

MATERIAL QUANTITY: **46** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	12"x12 Off white w/ beige specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 304 (Hardwood Floors) , 306, 303, 307, 308, - 1911 Bldg.		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12"x12 Off white w/ beige specks VFT**

MATERIAL LOCATION: **Rooms 304 (Hardwood Floors) , 306, 303, 307, 308, - 1911 Bldg.**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61A		
MATERIAL DESCRIPTION:	12"x12 Off white w/ beige specks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 304 (hardwood floor), 306, 303, 307, 308, 309 - 1911 Bldg.		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: 61A

MATERIAL DESCRIPTION: 12"x12 Off white w/ beige specks VFT MASTIC

MATERIAL LOCATION: Rooms 304 (hardwood floor), 306, 303, 307, 308, 309 - 1911 Bldg.

MATERIAL QUANTITY: 3500 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/25/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12" x 12" Off white w/ beige specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 317, 312, 300 (hardwood floor), 320 - 1920 addition		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Off white w/ beige specks VFT**

MATERIAL LOCATION: **Rooms 317, 312, 300 (hardwood floor), 320 - 1920 addition**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62A		
MATERIAL DESCRIPTION:	12" x 12" Off white w/ beige specks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 317, 312, 300 (hardwood floor), 320 - 1920 addition		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **62A**

MATERIAL DESCRIPTION: **12" x 12" Off white w/ beige specks VFT MASTIC**

MATERIAL LOCATION: **Rooms 317, 312, 300 (hardwood floor), 320 - 1920 addition**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	12"x12" Off white w/ gray shadows VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 109 - principal's office		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12"x12" Off white w/ gray shadows VFT**

MATERIAL LOCATION: **Room 109 - principal's office**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63A		
MATERIAL DESCRIPTION:	12"x12" Off white w/ gray shadows VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 109 - principal's office		
MATERIAL QUANTITY:	450	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **63A**

MATERIAL DESCRIPTION: **12"x12" Off white w/ gray shadows VFT MASTIC**

MATERIAL LOCATION: **Room 109 - principal's office**

MATERIAL QUANTITY: **450** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12"x12" Beige w/ tan streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 116		
MATERIAL QUANTITY:	875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12"x12" Beige w/ tan streaks VFT**

MATERIAL LOCATION: **Room 116**

MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64A		
MATERIAL DESCRIPTION:	12"x12" Beige w/ tan streaks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 116		
MATERIAL QUANTITY:	875	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **64A**

MATERIAL DESCRIPTION: **12"x12" Beige w/ tan streaks VFT MASTIC**

MATERIAL LOCATION: **Room 116**

MATERIAL QUANTITY: **875** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	12"x12" White w/ blue specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12"x12" White w/ blue specks VFT**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65A		
MATERIAL DESCRIPTION:	12"x12" White w/ blue specks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **65A**

MATERIAL DESCRIPTION: **12"x12" White w/ blue specks VFT MASTIC**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1911 Main building		
MATERIAL QUANTITY:	80000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout 1911 Main building**

MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1920 Additions		
MATERIAL QUANTITY:	80000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout 1920 Additions**

MATERIAL QUANTITY: **80000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Teachers lounge, Rooms 106, 107, 108, Auditorium		
MATERIAL QUANTITY:	4600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **2nd Floor Teachers Lounge, Rooms 106, 107, 108, Auditorium**

MATERIAL QUANTITY: **4600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White and Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Non-labelled Room North of Room 301		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White and Brown Streaks VFT**

MATERIAL LOCATION: **Non-labelled Room North of Room 301**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ White and Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Non-labelled Room North of Room 301		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **69A**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ White and Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Non-labelled Room North of Room 301**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	Cream Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **Cream Linoleum**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70A		
MATERIAL DESCRIPTION:	Cream Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **70A**

MATERIAL DESCRIPTION: **Cream Linoleum Mastic**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation - Not Observed**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Preform Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engine Room/Tank Room - 1911 Bldg.		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Preform Pipe Insulation**

MATERIAL LOCATION: **Engine Room/Tank Room - 1911 Bldg.**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	MJP E/F/V on Preform Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engine Room/Tank Room - 1911 Bldg.		
MATERIAL QUANTITY:	7	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **MJP E/F/V on Preform Pipe Insulation**

MATERIAL LOCATION: **Engine Room/Tank Room - 1911 Bldg.**

MATERIAL QUANTITY: **7** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Counselor's Office, Pipe Tunnels, Room 105 (Abated) - 1920 Bldg.		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation - Not Observed**

MATERIAL LOCATION: **Main Office, Counselor's Office, Pipe Tunnels, Room 105 (Abated) - 1920 Bldg.**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Counselor's Office, Pipe Tunnels, 1920 Bldg.		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Main Office, Counselor's Office, Pipe Tunnels, 1920 Bldg.**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girl's Toilet Chases & Boy's Toilet Chases - 1920 Bldg.		
MATERIAL QUANTITY:	124	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Girl's Toilet Chases & Boy's Toilet Chases - 1920 Bldg.**

MATERIAL QUANTITY: **124** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Boiler Gaskets - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room - 1911 Bldg.		
MATERIAL QUANTITY:	80	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUILDING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Boiler Gaskets - Not Observed**

MATERIAL LOCATION: **Boiler Room - 1911 Bldg.**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation - Not Observed**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.		
MATERIAL QUANTITY:	8	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **8** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Air Tunnels - 1920 Bldg.		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Main Office, Air Tunnels - 1920 Bldg.**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Air Tunnels - 1920 Bldg.		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Main Office, Air Tunnels - 1920 Bldg.**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Spray-on Insulation - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Spray-on Insulation - Not Observed**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Q		
MATERIAL DESCRIPTION:	Spray-on Insulation - Not Observed		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	On I-Beams above Ceiling Tiles Throughout 1994 Addition		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Haugan School	REVIEW DATE:	6/25/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Spray-on Insulation - Not Observed**

MATERIAL LOCATION: **On I-Beams above Ceiling Tiles Throughout 1994 Addition**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	06A				
MATERIAL DESCRIPTION:	12"x12" Dark Brown Floor Tile Mastic				
MATERIAL LOCATION:	Throughout (See Hatching Maps) - 1911 Bldg.				
MATERIAL QUANTITY:	25435	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

COMMENTS:

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23591** BUIDLING ID: **3810**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Haugan School** REVIEW DATE: **6/25/2025**

ADDRESS: **4540 N Hamlin Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **12"x12" Dark Brown Floor Tile Mastic**

MATERIAL LOCATION: **Throughout (See Hatching Maps) - 1911 Bldg.**

MATERIAL QUANTITY: **25435** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	71			
MATERIAL DESCRIPTION:	Replacement 12"x12" Cream w/ specs VFT			
MATERIAL LOCATION:	1st 2nd, and 3rd floor corridors, 314, 306, 303, 224, 119, 115, 3rd floor, boys and girls toilets, gym/auditorium.			
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:				

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **Replacement 12"x12" Cream w/ specs VFT**

MATERIAL LOCATION: **1st 2nd, and 3rd floor corridors, 314, 306, 303, 224,119, 115, 3rd floor, boys and girls toilets, gym/auditorium.**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/25/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23591	BUIDLING ID:	3810
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Haugan School	INSPECTION DATE:	6/4/2025		
ADDRESS:	4540 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	72			
MATERIAL DESCRIPTION:	Replacement 12"x12" Cream w/ specs mastic 1300			
MATERIAL LOCATION:	1st 2nd, and 3rd floor corridors, 314, 306, 303, 224, 119, 115, 3rd floor, boys and girls toilets, gym/auditorium.			
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:				

Inspector's Signature:



Date: 06/04/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>23591</b>	BUIDLING ID:	<b>3810</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Haugan School</b>	REVIEW DATE:	<b>6/25/2025</b>		
ADDRESS:	<b>4540 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Replacement 12"x12" Cream w/ specs mastic 1300**

MATERIAL LOCATION: **1st 2nd, and 3rd floor corridors, 314, 306, 303, 224,119, 115, 3rd floor, boys and girls toilets, gym/auditorium.**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **06/25/2025**


## APPENDIX B

---

### Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092141

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**David Avila**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/10/2021

Exam Date: 9/10/2021

Expiration Date: 9/10/2022

Certificate Number: BIR2109101942


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, IL

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/30/2025



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 4/30/2025	INSPECTOR	9/13/2025
DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health	EXPIRES 05/15/2026	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/14/2025
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**David Avila**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2409132631  
Course Date: 9/13/2024  
Exam Date: 9/13/2024  
Expiration Date: 9/13/2025



Issue Date: 9/13/2024

Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours



525-535 West Jefferson Street • Springfield, Illinois

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

2/28/2022



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
**100 - 11093**

ISSUED  
**2/28/2022** EXPIRES  
**05/15/2023**

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11093**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER <b>100 - 11093</b>	ISSUED <b>2/28/2022</b>	EXPIRES <b>05/15/2023</b>		INSPECTOR	9/10/2022
<b>DAVID AVILA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		PROJECT MANAGER AIR SAMPLING PROFESSIONAL <i>Alteration of this license shall result in legal action.</i> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 11093

ISSUED  
4/8/2024

EXPIRES  
05/15/2025

DAVID AVILA  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



DAVID AVILA  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 4/8/2024	EXPIRES 05/15/2025	INSPECTOR	9/15/2024
DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*



## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

*Kathy DeSalvo*  
Kathy DeSalvo, Director



## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

*Kathy DeSalvo*  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

7/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 04019</b>	ISSUED <b>7/8/2024</b>	EXPIRES <b>05/15/2025</b>	INSPECTOR	5/6/2025
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	5/6/2025
			AIR SAMPLING PROFESSIONAL <b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 5/6/2024

Exam Date: 5/6/2024

Expiration Date: 5/6/2025

Certificate Number: MPR2405061823


Course Credit Hours: MPR 8 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois



ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/1/2022
MANAGEMENT PLANNER	11/1/2022
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Ill

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/30/2026



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 04019

ISSUED  
4/30/2025

EXPIRES  
05/15/2026

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/6/2025
MANAGEMENT PLANNER	4/2/2026
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*

**Reliable  
Environmental  
Solutions, Inc.  R E S**

*This is to certify that* **Arturo Saenz**

*has on 4/2/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 2, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: April 2, 2025

Expiration Date: April 2, 2026

Certificate Number: MPR/0560



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed