

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-3521
SCHOOL NAME: South Loop School
ADDRESS OF SCHOOL: 1212 S. Plymouth Ct.
CITY: Chicago, IL, 60605

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 12/16/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/2/2025 ENROLLMENT 894
IDPH INSPECTOR LICENSE NUMBER: 100-20411
IDPH LICENSED INSPECTOR NAME (Please Print): Benyamen Maradkel
IDPH MP LICENSE NUMBER: 100-18488
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/14/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

South Loop School

1212 S. Plymouth Ct.
Chicago, IL, 60605

Unit: 23751
Building ID: 3960

IDPH ID Number: 14-016-2990-3521

REPORT DATE:
Monday, April 14, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

04/14/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23751 Region: 03 IDPH ID: 14-016-2990-3521

School: South Loop School Building ID: 3960

Address: 1212 S. Plymouth Ct.

Chicago, IL, 60605

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/2/2025

Review Date: 04/14/2025

Inspector: Benyamen Maradkel

Inspector IDPH License: 100-20411

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Mike Serio
100-18488

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 14, 2025

RE: South Loop School, Unit 23751
1212 S. Plymouth Ct.
Chicago, IL, 60605

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at South Loop School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at South Loop School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: South Loop School Unit: 23751 Region: 03
Address: 1212 S. Plymouth Ct. Chicago, IL, 60605
IDPH ID: 14-016-2990-3521 Building ID: 3960
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: No of Floors:
Current Occupancy: 894

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Benyamen Maradkel

Inspector IDPH license # 100-20411
Reinspection Date: 4/2/2025


Signature:
Date: 4/2/2025

6. Management Planner

Management Planner Name: Mike Serio


Management Planner IDPH license # 100-18488


Signature:
Date: 04/14/2025

7. Review Date: 04/14/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature: Date: 4/14/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the South Loop School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 3960:

24	Formica Adhesive
33	Liner in Vault Door
35	12" x 12" Brown Mix Floor Tile
36	12" x 12" Brown Mix Floor Tile Mastic
56	TSI Pipe Insulation

B. The following new homogenous areas have been identified for Building 3960:

56

TSI Pipe Insulation

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

- 1 12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks
- 10 Cinderblock
- 11 Cinderblock Mortar
- 12 Soundproofing on Bottom Of Sinks
- 13 Drywall and Compound
- 14 Adhesive Behind Wall Panels
- 15 Window Caulk
- 16 2' x 4' Smooth Ceiling Panels
- 17 Wall Caulk
- 19 Blue Carpet Mastic
- 2 12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks Mastic
- 20 Window Glazing
- 21 Vibration Collars
- 22 Brown Carpet Mastic
- 23 Lab Tables
- 24 Formica Adhesive
- 25 Lab Counter & Sink
- 26 Purple Carpet Mastic
- 27 Stair Treads
- 28 Rolled Flooring
- 29 Rolled Flooring Adhesive
- 3 12" x 12" Light Tan Floor Tile w/ Brown & White Streaks
- 30 Blue Carpet Mastic
- 31 Blue/Green Carpet Mastic
- 32 Blue/Orange Mix Carpet Mastic
- 33 Liner in Vault Door
- 34 Mirror Mastic
- 35 12" x 12" Brown Mix Floor Tile
- 36 12" x 12" Brown Mix Floor Tile Mastic
- 37 Acoustical Panel Mastic
- 38 2' x 4' Tectum Ceiling Tile
- 39 2' x 4' Ceiling Tile
- 4 12" x 12" Light Tan Floor Tile w/ Brown & White Streaks Mastic
- 40 4" Gray Vinyl Baseboard
- 41 4" Gray Vinyl Baseboard Adhesive
- 42 Brown w/ Blue and White Carpet Adhesive
- 43 4" Black Vinyl Baseboard
- 44 4" Black Vinyl Baseboard Adhesive

45	Green Ceramic Flooring and Grout
46	Green Ceramic Flooring Mastic
47	Red Ceramic Flooring & Grout
48	Red Ceramic Flooring Mastic
49	12" x 12" Gray Floor Tile
5	Spray on Fireproofing
50	12" x 12" Gray Floor Tile Mastic
51	12" x 12" Off-White w/ Dark Spots Floor Tile
52	12" x 12" Off-White w/ Dark Spots Floor Tile Mastic
53	1' x 1' Tectum Panels
54	12" x 12" Blue Floor Tile
55	12" x 12" Blue Floor Tile Mastic
56	TSI Pipe Insulation
6	2' x 4' Fissured Lay-in Ceiling Panels
7	Counter Caulk
8	4" Brown Vinyl Baseboard
9	4" Brown Vinyl Baseboard Adhesive

The following areas were deemed to be inaccessible:

10	Cinderblock
14	Adhesive Behind Wall Panels
19	Blue Carpet Mastic
2	12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks Mastic
21	Vibration Collars
22	Brown Carpet Mastic
24	Formica Adhesive
26	Purple Carpet Mastic
29	Rolled Flooring Adhesive
30	Blue Carpet Mastic
34	Mirror Mastic
36	12" x 12" Brown Mix Floor Tile Mastic
37	Acoustical Panel Mastic
4	12" x 12" Light Tan Floor Tile w/ Brown & White Streaks Mastic
41	4" Gray Vinyl Baseboard Adhesive
42	Brown w/ Blue and White Carpet Adhesive
44	4" Black Vinyl Baseboard Adhesive
46	Green Ceramic Flooring Mastic
48	Red Ceramic Flooring Mastic
50	12" x 12" Gray Floor Tile Mastic
52	12" x 12" Off-White w/ Dark Spots Floor Tile Mastic
53	1' x 1' Tectum Panels

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Benyamen Maradkel, IDPH License # 100-20411. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The South Loop School Building 3960 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School South Loop School **Unit** 23751 **Building ID** 3960
Address 1212 S. Plymouth Ct. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks	12,200	SF	Throughout Classrooms, Library, Main Office Vault	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
10	Cinderblock	40,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
11	Cinderblock Mortar	40,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
12	Soundproofing on Bottom Of Sinks	400	SF	Classrooms	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
13	Drywall and Compound	10,000	SF	Throughout Facility	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
14	Adhesive Behind Wall Panels	1,000	SF	Room 213 & Library	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
15	Window Caulk	20,000	LF	Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16	2' x 4' Smooth Ceiling Panels	1,000	SF	Kitchen	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	Wall Caulk	5,000	LF	Throughout Facility	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
18	Duct Caulk	100	LF	Boiler Room	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
19	Blue Carpet Mastic	400	SF	Engineer's Office and Custodian Locker Rooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
2	12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks Mastic	12,200	SF	Throughout Classrooms, Library, Main Office Vault	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
20	Window Glazing	10,000	LF	Throughout Facility	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
21	Vibration Collars	30	LF	2nd Floor Mechanical Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
22	Brown Carpet Mastic	1,000	SF	Room 213	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
23	Lab Tables	200	SF	Rooms 229, 107	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
24	Formica Adhesive	100	SF	Room 229	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
25	Lab Counter & Sink	150	SF	Room 229	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
26	Purple Carpet Mastic	1,200	SF	Room 228	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
27	Stair Treads	500	LF	Stairways	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
28	Rolled Flooring	6,500	SF	Auditorium, Gym,	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School South Loop School **Unit** 23751 **Building ID** 3960
Address 1212 S. Plymouth Ct. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 149								potential for damage		
29	Rolled Flooring Adhesive	2,800	SF	Auditorium, Gym, Room 149	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
3	12" x 12" Light Tan Floor Tile w/ Brown & White Streaks	10,500	SF	Corridors and Classrooms, Stairwells, Engineer's Office, Mens Locker Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
30	Blue Carpet Mastic	200	SF	Auditorium, Womens Locker Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
31	Blue/Green Carpet Mastic			Rooms 137, Conference Room, Room 136	ASSUMED	MISC					No			
32	Blue/Orange Mix Carpet Mastic			Office	ASSUMED	MISC					No			
33	Liner in Vault Door	25	LF	Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
34	Mirror Mastic	400	SF	Bathrooms, Room 149	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	12" x 12" Brown Mix Floor Tile	700	SF	Room 109	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
36	12" x 12" Brown Mix Floor Tile Mastic	700	SF	Room 109	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
37	Acoustical Panel Mastic	200	SF	North Wall of Gym	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
38	2' x 4' Tectum Ceiling Tile	7,500	SF	Gym and Auditorium	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACM or friable suspect ACM		LOW
39	2' x 4' Ceiling Tile	2,000	SF	Rooms 124 and 127	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACM or friable suspect ACM		LOW
4	12" x 12" Light Tan Floor Tile w/ Brown & White Streaks Mastic	10,000	SF	Corridors and Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
40	4" Gray Vinyl Baseboard	150	LF	Auditorium	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
41	4" Gray Vinyl Baseboard Adhesive	150	LF	Auditorium	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
42	Brown w/ Blue and White Carpet Adhesive	1,750	SF	Auditorium	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
43	4" Black Vinyl Baseboard	300	LF	Library Room 228, Stairways, Corridors	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
44	4" Black Vinyl Baseboard Adhesive	300	LF	Library, Room 228, Stairways, Corridors	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
45	Green Ceramic Flooring and Grout	1,200	SF	East & West	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School South Loop School **Unit** 23751 **Building ID** 3960
Address 1212 S. Plymouth Ct. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building 1st and 2nd Floor Boys and Girls Bathrooms								potential for damage		
46	Green Ceramic Flooring Mastic	1,200	SF	East & West Building 1st, and 2nd Floor Boys and Girls Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
47	Red Ceramic Flooring & Grout	1,350	SF	Kitchen, Dishwash Area & Main Entrance	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
48	Red Ceramic Flooring Mastic	1,350	SF	Kitchen, Dishwash Area, & Main Entrance	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
49	12" x 12" Gray Floor Tile	15,000	SF	Main Office, Conference Room, Assistant Principal Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
5	Spray on Fireproofing	22,000	SF	On Roof Panels, Storage 2nd Floor, 1st Floor Pipe Chase	ASSUMED	SURFACE	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
50	12" x 12" Gray Floor Tile Mastic	15,000	SF	Main Office, Conference Room, Assistant Principal Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
51	12" x 12" Off-White w/ Dark Spots Floor Tile	1,200	SF	Auditorium	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
52	12" x 12" Off-White w/ Dark Spots Floor Tile Mastic	1,200	SF	Auditorium	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
53	1' x 1' Tectum Panels	200	SF	Gym Wall (North)	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
54	12" x 12" Blue Floor Tile	500	SF	Room 213 and Southeast Stairwell	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
55	12" x 12" Blue Floor Tile Mastic	500	SF	Room 213 and Southeast Stairwell	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
56	TSI Pipe Insulation	200	LF	1st Floor Mechanical Room	ASSUMED	TSI	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
6	2' x 4' Fissured Lay-in Ceiling Panels	20,200	SF	Classrooms and Corridors, Storage 2nd Floor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
7	Counter Caulk	1,200	LF	Throughout Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
8	4" Brown Vinyl Baseboard	10,000	LF	Throughout Facility	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School South Loop School **Unit** 23751 **Building ID** 3960
Address 1212 S. Plymouth Ct. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
9	4" Brown Vinyl Baseboard Adhesive	8,000	LF	Throughout Facility	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School South Loop School Unit 23751 Building ID 3960
Address 1212 S. Plymouth Ct. Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>4/2/2025</u>
Inspector Name <u>Benyamen Maradkel</u>
<u>100-20411</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	

Chicago Public Schools

School South Loop School **Unit** 23751 **Building ID** 3960
Address 1212 S. Plymouth Ct. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
31	Material not observed - 2025
32	Material not observed - 2025
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	
50	
51	
52	
53	
54	
55	
56	
6	

Chicago Public Schools

School South Loop School **Unit** 23751 **Building ID** 3960
Address 1212 S. Plymouth Ct. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
7	
8	
9	

Table II
Management Planner's Review

Chicago Public Schools

School South Loop School

Unit 23751

Building ID 3960

Address 1212 S. Plymouth Ct.

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks	12,200	SF	Throughout Classrooms, Library, Main Office Vault	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Cinderblock	40,000	SF	Throughout Facility	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Cinderblock Mortar	40,000	SF	Throughout Facility	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Soundproofing on Bottom Of Sinks	400	SF	Classrooms	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Drywall and Compound	10,000	SF	Throughout Facility	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Adhesive Behind Wall Panels	1,000	SF	Room 213 & Library	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Window Caulk	20,000	LF	Classrooms	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
16	2' x 4' Smooth Ceiling Panels	1,000	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Wall Caulk	5,000	LF	Throughout Facility	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
18	Duct Caulk	100	LF	Boiler Room	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
19	Blue Carpet Mastic	400	SF	Engineer's Office and Custodian Locker Rooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2	12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks Mastic	12,200	SF	Throughout Classrooms, Library, Main Office Vault	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Window Glazing	10,000	LF	Throughout Facility	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
21	Vibration Collars	30	LF	2nd Floor Mechanical Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
22	Brown Carpet Mastic	1,000	SF	Room 213	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	Lab Tables	200	SF	Rooms 229, 107	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Formica Adhesive	100	SF	Room 229	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Lab Counter & Sink	150	SF	Room 229	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Purple Carpet Mastic	1,200	SF	Room 228	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Stair Treads	500	LF	Stairways	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
28	Rolled Flooring	6,500	SF	Auditorium, Gym, Room 149	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Rolled Flooring Adhesive	2,800	SF	Auditorium, Gym, Room 149	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3	12" x 12" Light Tan Floor Tile w/ Brown & White Streaks	10,500	SF	Corridors and Classrooms, Stairwells, Engineer's Office, Mens Locker Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
30	Blue Carpet Mastic	200	SF	Auditorium, Womens Locker Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
31	Blue/Green Carpet Mastic			Rooms 137, Conference Room, Room 136	Assumed	MISC					
32	Blue/Orange Mix Carpet Mastic			Office	Assumed	MISC					
33	Liner in Vault Door	25	LF	Office	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
34	Mirror Mastic	400	SF	Bathrooms, Room 149	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" x 12" Brown Mix Floor Tile	700	SF	Room 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Brown Mix Floor Tile Mastic	700	SF	Room 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School South Loop School

Unit 23751

Building ID 3960

Address 1212 S. Plymouth Ct.

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	Acoustical Panel Mastic	200	SF	North Wall of Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	2' x 4' Tectum Ceiling Tile	7,500	SF	Gym and Auditorium	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
39	2' x 4' Ceiling Tile	2,000	SF	Rooms 124 and 127	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
4	12" x 12"Light Tan Floor Tile w/ Brown & White Streaks Mastic	10,000	SF	Corridors and Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	4" Gray Vinyl Baseboard	150	LF	Auditorium	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
41	4" Gray Vinyl Baseboard Adhesive	150	LF	Auditorium	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
42	Brown w/ Blue and White Carpet Adhesive	1,750	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
43	4" Black Vinyl Baseboard	300	LF	Library Room 228, Stairways, Corridors	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
44	4" Black Vinyl Baseboard Adhesive	300	LF	Library, Room 228. Stairways, Corridors	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
45	Green Ceramic Flooring and Grout	1,200	SF	East & West Building 1st and 2nd Floor Boys and Girls Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
46	Green Ceramic Flooring Mastic	1,200	SF	East & West Building 1st, and 2nd Floor Boys and Girls Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Red Ceramic Flooring & Grout	1,350	SF	Kitchen, Dishwash Area & Main Entrance	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Red Ceramic Flooring Mastic	1,350	SF	Kitchen, Dishwash Area, & Main Entrance	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" Gray Floor Tile	15,000	SF	Main Office, Conference Room, Assistant Principal Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	Spray on Fireproofing	22,000	SF	On Roof Panels, Storage 2nd Floor , 1st Floor Pipe Chase	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
50	12" x 12" Gray Floor Tile Mastic	15,000	SF	Main Office, Conference Room, Assistant Principal Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Off-White w/ Dark Spots Floor Tile	1,200	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Off-White w/ Dark Spots Floor Tile Mastic	1,200	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
53	1' x 1' Tectum Panels	200	SF	Gym Wall (North)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Blue Floor Tile	500	SF	Room 213 and Southeast Stairwell	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Blue Floor Tile Mastic	500	SF	Room 213 and Southeast Stairwell	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
56	TSI Pipe Insulation	200	LF	1st Floor Mechanical Room	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
6	2' x 4' Fissured Lay-in Ceiling Panels	20,200	SF	Classrooms and Corridors, Storage 2nd Floor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School South Loop School

Unit 23751

Building ID 3960

Address 1212 S. Plymouth Ct.

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
7	Counter Caulk	1,200	LF	Throughout Classrooms	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
8	4" Brown Vinyl Baseboard	10,000	LF	Throughout Facility	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
9	4" Brown Vinyl Baseboard Adhesive	8,000	LF	Throughout Facility	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan

Review Date	4/14/2025
Manager Planner Name	Mike Serio

HA Number	Management Comments
1	Sample to determine ACM content prior to disturbance.

Chicago Public Schools

School South Loop School

Unit 23751

Building ID 3960

Address 1212 S. Plymouth Ct.

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
10	Sample to determine ACM content prior to disturbance.
11	Sample to determine ACM content prior to disturbance.
12	Sample to determine ACM content prior to disturbance.
13	Sample to determine ACM content prior to disturbance.
14	Sample to determine ACM content prior to disturbance.
15	Sample to determine ACM content prior to disturbance.
16	Sample to determine ACM content prior to disturbance.
17	Sample to determine ACM content prior to disturbance.
18	
19	Sample to determine ACM content prior to disturbance.
2	Sample to determine ACM content prior to disturbance.
20	Sample to determine ACM content prior to disturbance.
21	Sample to determine ACM content prior to disturbance.
22	Sample to determine ACM content prior to disturbance.
23	Sample to determine ACM content prior to disturbance.
24	Sample to determine ACM content prior to disturbance.
25	Sample to determine ACM content prior to disturbance.
26	Sample to determine ACM content prior to disturbance.
27	Sample to determine ACM content prior to disturbance.
28	Sample to determine ACM content prior to disturbance.
29	Sample to determine ACM content prior to disturbance.
3	Sample to determine ACM content prior to disturbance.
30	Sample to determine ACM content prior to disturbance.
31	If identified, continue O&M.
32	If identified, continue O&M.
33	Sample to determine ACM content prior to disturbance.
34	Sample to determine ACM content prior to disturbance.

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

School South Loop School

Unit 23751

Building ID 3960

Address 1212 S. Plymouth Ct.

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
35	Sample to determine ACM content prior to disturbance.
36	Sample to determine ACM content prior to disturbance.
37	Sample to determine ACM content prior to disturbance.
38	Sample to determine ACM content prior to disturbance.
39	Sample to determine ACM content prior to disturbance.
4	Sample to determine ACM content prior to disturbance.
40	Sample to determine ACM content prior to disturbance.
41	Sample to determine ACM content prior to disturbance.
42	Sample to determine ACM content prior to disturbance.
43	Sample to determine ACM content prior to disturbance.
44	Sample to determine ACM content prior to disturbance.
45	Sample to determine ACM content prior to disturbance.
46	Sample to determine ACM content prior to disturbance.
47	Sample to determine ACM content prior to disturbance.
48	Sample to determine ACM content prior to disturbance.
49	Sample to determine ACM content prior to disturbance.
5	Sample to determine ACM content prior to disturbance.
50	Sample to determine ACM content prior to disturbance.
51	Sample to determine ACM content prior to disturbance.
52	Sample to determine ACM content prior to disturbance.
53	Sample to determine ACM content prior to disturbance.
54	Sample to determine ACM content prior to disturbance.
55	Sample to determine ACM content prior to disturbance.
56	Sample to determine ACM content prior to disturbance.
6	Sample to determine ACM content prior to disturbance.
7	Sample to determine ACM content prior to disturbance.
8	Sample to determine ACM content prior to disturbance.

Chicago Public Schools

School South Loop School

Unit 23751

Building ID 3960

Address 1212 S. Plymouth Ct.

Chicago, IL, 60605

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
9	Sample to determine ACM content prior to disturbance.

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Classrooms, Library, Main Office Vault		
MATERIAL QUANTITY:	12200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks**

MATERIAL LOCATION: **Throughout Classrooms, Library, Main Office Vault**

MATERIAL QUANTITY: **12200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Cinderblock		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Cinderblock**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	Cinderblock Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Cinderblock Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Soundproofing on Bottom Of Sinks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Soundproofing on Bottom Of Sinks**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Drywall and Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Drywall and Compound**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Adhesive Behind Wall Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213 & Library		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Adhesive Behind Wall Panels**

MATERIAL LOCATION: **Room 213 & Library**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	2' x 4' Smooth Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Panels**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Wall Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Wall Caulk**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:

5000

MATERIAL UNITS:

LF

DAMAGE QUANTITY:

DAMAGE UNITS:

LF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Duct Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BULDING ID: **3960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **South Loop School** REVIEW DATE: **4/14/2025**

ADDRESS: **1212 S. Plymouth Ct.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Duct Caulk**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office and Custodian Locker Rooms		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Engineer's Office and Custodian Locker Rooms**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2		
MATERIAL DESCRIPTION:	12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Classrooms, Library, Main Office Vault		
MATERIAL QUANTITY:	12200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Dark Tan Floor Tile w/ Brown & White Streaks Mastic**

MATERIAL LOCATION: **Throughout Classrooms, Library, Main Office Vault**

MATERIAL QUANTITY: **12200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Window Glazing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Window Glazing**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Vibration Collars		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Mechanical Room		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Vibration Collars**

MATERIAL LOCATION: **2nd Floor Mechanical Room**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Room 213**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Lab Tables		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 229, 107		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Lab Tables**

MATERIAL LOCATION: **Rooms 229, 107**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Formica Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 229		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Formica Adhesive**

MATERIAL LOCATION: **Room 229**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Lab Counter & Sink		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 229		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Lab Counter & Sink**

MATERIAL LOCATION: **Room 229**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Purple Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 228		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **Room 228**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Stair Treads		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairways		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Stair Treads**

MATERIAL LOCATION: **Stairways**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Rolled Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, Gym, Room 149		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Rolled Flooring**

MATERIAL LOCATION: **Auditorium, Gym, Room 149**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Rolled Flooring Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, Gym, Room 149		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Rolled Flooring Adhesive**

MATERIAL LOCATION: **Auditorium, Gym, Room 149**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3		
MATERIAL DESCRIPTION:	12" x 12" Light Tan Floor Tile w/ Brown & White Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Classrooms, Stairwells, Engineer's Office, Mens Locker Room		
MATERIAL QUANTITY:	10500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile w/ Brown & White Streaks**

MATERIAL LOCATION: **Corridors and Classrooms, Stairwells, Engineer's Office, Mens Locker Room**

MATERIAL QUANTITY: **10500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Blue Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, Womens Locker Room		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Auditorium, Womens Locker Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 31
MATERIAL DESCRIPTION: Blue/Green Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 137, Conference Room, Room 136

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **Blue/Green Carpet Mastic**

MATERIAL LOCATION: **Rooms 137, Conference Room, Room 136**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 32
MATERIAL DESCRIPTION: Blue/Orange Mix Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Blue/Orange Mix Carpet Mastic**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Liner in Vault Door		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Liner in Vault Door**

MATERIAL LOCATION: **Office**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Mirror Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathrooms, Room 149		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Mirror Mastic**

MATERIAL LOCATION: **Bathrooms, Room 149**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" x 12" Brown Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 109		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12" x 12" Brown Mix Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 109		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" Brown Mix Floor Tile Mastic**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Acoustical Panel Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North Wall of Gym		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Acoustical Panel Mastic**

MATERIAL LOCATION: **North Wall of Gym**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	2' x 4' Tectum Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym and Auditorium		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **2' x 4' Tectum Ceiling Tile**

MATERIAL LOCATION: **Gym and Auditorium**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 124 and 127		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**

MATERIAL LOCATION: **Rooms 124 and 127**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	12" x 12" Light Tan Floor Tile w/ Brown & White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridors and Classrooms		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" Light Tan Floor Tile w/ Brown & White Streaks Mastic**

MATERIAL LOCATION: **Corridors and Classrooms**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	4" Gray Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	4" Gray Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **4" Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Brown w/ Blue and White Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Brown w/ Blue and White Carpet Adhesive**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library Room 228, Stairways, Corridors		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Library Room 228, Stairways, Corridors**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library, Room 228. Stairways, Corridors		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Library, Room 228. Stairways, Corridors**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Green Ceramic Flooring and Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East & West Building 1st and 2nd Floor Boys and Girls Bathrooms		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Green Ceramic Flooring and Grout**

MATERIAL LOCATION: **East & West Building 1st and 2nd Floor Boys and Girls Bathrooms**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Green Ceramic Flooring Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East & West Building 1st, and 2nd Floor Boys and Girls Bathrooms		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Green Ceramic Flooring Mastic**

MATERIAL LOCATION: **East & West Building 1st, and 2nd Floor Boys and Girls Bathrooms**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Red Ceramic Flooring & Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, Dishwash Area & Main Entrance		
MATERIAL QUANTITY:	1350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Red Ceramic Flooring & Grout**

MATERIAL LOCATION: **Kitchen, Dishwash Area & Main Entrance**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Red Ceramic Flooring Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Kitchen, Dishwash Area, & Main Entrance		
MATERIAL QUANTITY:	1350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Red Ceramic Flooring Mastic**

MATERIAL LOCATION: **Kitchen, Dishwash Area, & Main Entrance**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Conference Room, Assistant Principal Office		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Main Office, Conference Room, Assistant Principal Office**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	Spray on Fireproofing		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	On Roof Panels, Storage 2nd Floor , 1st Floor Pipe Chase		
MATERIAL QUANTITY:	22000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Spray on Fireproofing**

MATERIAL LOCATION: **On Roof Panels, Storage 2nd Floor , 1st Floor Pipe Chase**

MATERIAL QUANTITY: **22000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Conference Room, Assistant Principal Office		
MATERIAL QUANTITY:	15000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Conference Room, Assistant Principal Office**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Dark Spots Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Dark Spots Floor Tile**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Dark Spots Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Dark Spots Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	1' x 1' Tectum Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Wall (North)		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **1' x 1' Tectum Panels**

MATERIAL LOCATION: **Gym Wall (North)**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213 and Southeast Stairwell		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Room 213 and Southeast Stairwell**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 213 and Southeast Stairwell		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 213 and Southeast Stairwell**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6		
MATERIAL DESCRIPTION:	2' x 4' Fissured Lay-in Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms and Corridors, Storage 2nd Floor		
MATERIAL QUANTITY:	20200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **2' x 4' Fissured Lay-in Ceiling Panels**

MATERIAL LOCATION: **Classrooms and Corridors, Storage 2nd Floor**

MATERIAL QUANTITY: **20200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7		
MATERIAL DESCRIPTION:	Counter Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Classrooms		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Counter Caulk**

MATERIAL LOCATION: **Throughout Classrooms**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8		
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9		
MATERIAL DESCRIPTION:	4" Brown Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **04/02/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUILDING ID:	3960
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	South Loop School	REVIEW DATE:	4/14/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23751	BUIDLING ID:	3960
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Benyamen Maradkel		
SCHOOL NAME:	South Loop School	INSPECTION DATE:	4/2/2025		
ADDRESS:	1212 S. Plymouth Ct.	IDPH LICENSE NO:	100-20411		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	56			
MATERIAL DESCRIPTION:	TSI Pipe Insulation			
MATERIAL LOCATION:	1st Floor Mechanical Room			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	TSI	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:



Date: 04/02/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23751** BUIDLING ID: **3960**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **South Loop School** REVIEW DATE: **4/14/2025**

ADDRESS: **1212 S. Plymouth Ct.** IDPH LICENSE NO: **100-20411**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **TSI Pipe Insulation**

MATERIAL LOCATION: **1st Floor Mechanical Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Benyamen Maradkel

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026


Certificate Number: BIR2503070918

Course Credit Hours: BIR 4 Hrs.

Kristina Miczek, Training Manager

Benyamen Maradkel

Illinois Licensed Building Inspector



ENDORSEMENTS

INSPECTOR

TC EXPIRES

3/7/2026

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Michael Serio

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed