

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2638
SCHOOL NAME: Herzl School CPC
ADDRESS OF SCHOOL: 1401 S. Hamlin Avenue
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 8/30/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/16/2025 ENROLLMENT 454
IDPH INSPECTOR LICENSE NUMBER: 100-07278
IDPH LICENSED INSPECTOR NAME (Please Print): Kenneth Karuhn
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

7/28/2025

Richard J. Schleyer
Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Herzl School CPC

1401 S. Hamlin Avenue
Chicago, IL, 60623

Unit: 23771
Building ID: 3971

IDPH ID Number: 14-016-2990-2638

REPORT DATE:
Monday, July 28, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

07/28/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23772 Region: 03 IDPH ID: 14-016-2990-2638

School: Herzl School CPC Building ID: 3971

Address: 1401 S. Hamlin Avenue

Chicago, IL, 60623

Building Contact: Dwyer, Joseph Contact Phone: 773-757-3251

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/16/2025

Review Date: 07/28/2025

Inspector: Kenneth Karuhn

Inspector IDPH License: 100-07278

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: July 28, 2025

RE: Herzl School CPC, Unit 23771
1401 S. Hamlin Avenue
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Herzl School CPC , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Herzl School CPC, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Herzl School CPC Unit: 23772 Region: 03
Address: 1401 S. Hamlin Avenue Chicago, IL, 60623
IDPH ID: 14-016-2990-2638 Building ID: 3971
Contact: Dwyer, Joseph Phone: 7737573251

2. Description of Facility

Original Construction: 1971 Additional Construction:
Total Square Footage: 8525 No of Floors: 1
Current Occupancy: 454

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Kenneth Karuhn

Inspector IDPH license # 100-07278
Reinspection Date: 7/16/2025

Signature: *[Signature]*
Date: 7/16/2025

6. Management Planner

Management Planner Name: Jackson Montgomery

Management Planner IDPH license # 100-20634

Signature: _____
Date: 07/28/2025

7. Review Date: 07/28/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Signature:

Date: 7/28/2025

Name: Richard J. Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Herzl School CPC. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 3971:

B. The following new homogenous areas have been identified for Building 3971:

- 14 4" White Vinyl Babseboard
- 15 4" White Vinyl Baseboard Adhesive
- 16 Ceramic Tile
- 17 Ceramic Tile Grout
- 18 Ceramic Tile Adhesive
- 19 Drywall
- 20 Joint Compound
- 21 White Sink Undercoating
- 22 12" x 12" Beige and White Streak Floor Tile
- 23 12" x 12" Beige and White Streak Floor Tile Mastic
- 24 4" Dark Gray Vinyl Baseboard
- 25 4" Dark Gray Vinyl Baseboard Adhesive

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

10	12" x 12" Gray w/ White Streaks Floor Tile
11	12" x 12" Gray w/ White Streaks Floor Tile Mastic
12	Beige Multi-Colored Carpet Mastic
14	4" White Vinyl Babseboard
15	4" White Vinyl Baseboard Adhesive
16	Ceramic Tile
17	Ceramic Tile Grout
18	Ceramic Tile Adhesive
19	Drywall
20	Joint Compound
21	White Sink Undercoating
22	12" x 12" Beige and White Streak Floor Tile
23	12" x 12" Beige and White Streak Floor Tile Mastic
24	4" Dark Gray Vinyl Baseboard
25	4" Dark Gray Vinyl Baseboard Adhesive
4	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile
5	9" x 9" Off-White Floor Tile Mastic
6	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile Mastic
7	Green Carpet Mastic

The following areas were deemed to be inaccessible:

11	12" x 12" Gray w/ White Streaks Floor Tile Mastic
18	Ceramic Tile Adhesive
23	12" x 12" Beige and White Streak Floor Tile Mastic
25	4" Dark Gray Vinyl Baseboard Adhesive
5	9" x 9" Off-White Floor Tile Mastic
6	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile Mastic
7	Green Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Kenneth Karuhn, IDPH License # 100-07278. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Herzl School CPC Building 3971 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Herzl School CPC **Unit** 23772 **Building ID** 3971
Address 1401 S. Hamlin Avenue **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	2' x 4' Lay-in Ceiling Panels			Throughout School (Annex)	NO_ACBM	MISC								
10	12" x 12" Gray w/ White Streaks Floor Tile	3,500	SF	Classrooms A, B, C, & D	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
11	12" x 12" Gray w/ White Streaks Floor Tile Mastic	3,500	SF	Classrooms A, B, C, & D	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
12	Beige Multi-Colored Carpet Mastic			Hallways	ASSUMED	MISC								
13	Transite Panels	200	SF	Soffit Above Accordion Doors	CHR	MISC								
14	4" White Vinyl Baseboard	500	LF	All Classrooms and Hallways	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
15	4" White Vinyl Baseboard Adhesive	500	SF	All Classrooms and Hallways	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
16	Ceramic Tile	700	SF	Boys and Girls Bathrooms, Kitchen, and Classrooms	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
17	Ceramic Tile Grout	700	SF	Boys and Girls Bathrooms, Kitchen, and Classrooms	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
18	Ceramic Tile Adhesive	700	SF	Boys and Girls Bathrooms, Kitchen, and Classrooms	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
19	Drywall	200	SF	Milk Room, MDF Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
20	Joint Compound	200	SF	Milk Room, MDF Room	ASSUMED	SURFACE	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
21	White Sink Undercoating	4	SF	Kitchen	ASSUMED	SURFACE	N					ACBM with the potential for damage		LOW
22	12" x 12" Beige and White Streak Floor Tile	200	SF	Kitchen	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
23	12" x 12" Beige and White Streak Floor Tile Mastic	200	SF	Kitchen	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
24	4" Dark Gray Vinyl Baseboard	10	LF	Milk Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
25	4" Dark Gray Vinyl Baseboard Adhesive	10	LF	Milk Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
3	9" x 9" Off-White Floor Tile	1,000	SF	Classrooms A, B, C, & D (Beneath 12" X 12" Floor Tile) and Parent Room	CHR	MISC	N	NONE				ACBM with the potential for damage		MODERATE
4	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile	192	SF	Milk Storage Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		MODERATE
5	9" x 9" Off-White Floor Tile Mastic	100	SF	Classrooms A, B, C,	ASSUMED	MISC	N	NONE				ACBM with the		LOW

Chicago Public Schools

School Herzl School CPC **Unit** 23772 **Building ID** 3971
Address 1401 S. Hamlin Avenue **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Herzl School CPC Unit 23772 Building ID 3971
Address 1401 S. Hamlin Avenue Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>7/16/2025</u>
Inspector Name <u>Kenneth Karuhn</u>
<u>100-07278</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	Material not observed - 2025
13	Material in inaccessible area(s) - 2025
14	
15	
16	
17	
18	
19	
20	
21	
22	Over 9"x9" floor tile off white (HA-05)
23	Over 9"x9" floor tile off white (HA-05)
24	
25	
3	
4	
5	
6	
7	
8	
9	

Chicago Public Schools

School Herzl School CPC **Unit** 23772 **Building ID** 3971
Address 1401 S. Hamlin Avenue **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
B	

Table II
Management Planner's Review

Chicago Public Schools

School Herzl School CPC

Unit 23772

Building ID 3971

Address 1401 S. Hamlin Avenue

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	2' x 4' Lay-in Ceiling Panels			Throughout School (Annex)	No ACBM	MISC					
10	12" x 12" Gray w/ White Streaks Floor Tile	3,500	SF	Classrooms A, B, C, & D	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12" x 12" Gray w/ White Streaks Floor Tile Mastic	3,500	SF	Classrooms A, B, C, & D	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	Beige Multi-Colored Carpet Mastic			Hallways	Assumed	MISC					
13	Transite Panels	200	SF	Soffit Above Accordion Doors	Chrysotile	MISC			SF		
14	4" White Vinyl Baseboard	500	LF	All Classrooms and Hallways	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
15	4" White Vinyl Baseboard Adhesive	500	SF	All Classrooms and Hallways	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Ceramic Tile	700	SF	Boys and Girls Bathrooms, Kitchen, and Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Ceramic Tile Grout	700	SF	Boys and Girls Bathrooms, Kitchen, and Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Ceramic Tile Adhesive	700	SF	Boys and Girls Bathrooms, Kitchen, and Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Drywall	200	SF	Milk Room, MDF Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Joint Compound	200	SF	Milk Room, MDF Room	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
21	White Sink Undercoating	4	SF	Kitchen	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Beige and White Streak Floor Tile	200	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" Beige and White Streak Floor Tile Mastic	200	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	4" Dark Gray Vinyl Baseboard	10	LF	Milk Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
25	4" Dark Gray Vinyl Baseboard Adhesive	10	LF	Milk Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
3	9" x 9" Off-White Floor Tile	1,000	SF	Classrooms A, B, C, & D (Beneath 12" X 12" Floor Tile) and Parent Room	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile	192	SF	Milk Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	9" x 9" Off-White Floor Tile Mastic	100	SF	Classrooms A, B, C, & D (Beneath 12" X 12" Floor Tile) and Parent Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile Mastic	192	SF	Milk Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	Green Carpet Mastic	1,467	SF	Parent Room, Staff Room, Office, Teachers' Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8	4" Brown Vinyl Baseboard			Throughout School	No ACBM	MISC					
9	4" Brown Vinyl Baseboard Adhesive			Throughout School	No ACBM	MISC					
B	Fittings on Fiberglass Pipe Insulation			Throughout School	No ACBM	TSI					

Chicago Public Schools

School Herzl School CPC

Unit 23772

Building ID 3971

Address 1401 S. Hamlin Avenue

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	7/28/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	If identified, continue O&M.
14	
15	

Chicago Public Schools

School Herzl School CPC

Unit 23772

Building ID 3971

Address 1401 S. Hamlin Avenue

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
3	
4	
5	
6	
7	
8	
9	
B	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 1

MATERIAL DESCRIPTION: 2' x 4' Lay-in Ceiling Panels

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School (Annex)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

MATERIAL LOCATION: **Throughout School (Annex)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Classrooms A, B, C, & D		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Classrooms A, B, C, & D**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Classrooms A, B, C, & D		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **07/16/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms A, B, C, & D**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12
MATERIAL DESCRIPTION: Beige Multi-Colored Carpet Mastic
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: Follow O&M Plan
ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Hallways

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Beige Multi-Colored Carpet Mastic**

MATERIAL LOCATION: **Hallways**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13	
MATERIAL DESCRIPTION:	Transite Panels	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Soffit Above Accordion Doors**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:



Date: **07/16/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Soffit Above Accordion Doors**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3		
MATERIAL DESCRIPTION:	9" x 9" Off-White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Classrooms A, B, C, & D (Beneath 12" X 12" Floor Tile) and Parent Room		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **9" x 9" Off-White Floor Tile**

MATERIAL LOCATION: **Classrooms A, B, C, & D (Beneath 12" X 12" Floor Tile) and Parent Room**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Milk Storage Room		
MATERIAL QUANTITY:	192	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **07/16/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile**

MATERIAL LOCATION: **Milk Storage Room**

MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	9" x 9" Off-White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms A, B, C, & D (Beneath 12" X 12" Floor Tile) and Parent Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Off-White Floor Tile Mastic**

MATERIAL LOCATION: **Classrooms A, B, C, & D (Beneath 12" X 12" Floor Tile) and Parent Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Milk Storage Room		
MATERIAL QUANTITY:	192	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **07/16/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Dark Beige Spots Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Milk Storage Room**

MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7		
MATERIAL DESCRIPTION:	Green Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Parent Room, Staff Room, Office, Teachers' Lounge		
MATERIAL QUANTITY:	1467	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Green Carpet Mastic**

MATERIAL LOCATION: **Parent Room, Staff Room, Office, Teachers' Lounge**

MATERIAL QUANTITY: **1467** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 8

MATERIAL DESCRIPTION: 4" Brown Vinyl Baseboard

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **07/16/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **4" Brown Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	4" Dark Gray Vinyl Baseboard Adhesive		
MATERIAL LOCATION:	Milk Room		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **4" Dark Gray Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Milk Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23772** BUIDLING ID: **3971**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Herzl School CPC** INSPECTION DATE: **7/16/2025**
ADDRESS: **1401 S. Hamlin Avenue** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **12" x 12" Beige and White Streak Floor Tile Mastic**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:
Over 9"x9" floor tile off white (HA-05)

Inspector's Signature:



Date: **07/16/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" Beige and White Streak Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Ceramic Tile		
MATERIAL LOCATION:	Boys and Girls Bathrooms, Kitchen, and Classrooms		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Ceramic Tile**

MATERIAL LOCATION: **Boys and Girls Bathrooms, Kitchen, and Classrooms**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Ceramic Tile Grout		
MATERIAL LOCATION:	Boys and Girls Bathrooms, Kitchen, and Classrooms		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23772** BUIDLING ID: **3971**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Herzl School CPC** REVIEW DATE: **7/28/2025**

ADDRESS: **1401 S. Hamlin Avenue** IDPH LICENSE NO: **100-07278**

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Boys and Girls Bathrooms, Kitchen, and Classrooms**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *07/28/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Ceramic Tile Adhesive		
MATERIAL LOCATION:	Boys and Girls Bathrooms, Kitchen, and Classrooms		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**

MATERIAL LOCATION: **Boys and Girls Bathrooms, Kitchen, and Classrooms**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Joint Compound		
MATERIAL LOCATION:	Milk Room, MDF Room		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	SURFACE	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Joint Compound**

MATERIAL LOCATION: **Milk Room, MDF Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	24			
MATERIAL DESCRIPTION:	4" Dark Gray Vinyl Baseboard			
MATERIAL LOCATION:	Milk Room			
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **4" Dark Gray Vinyl Baseboard**

MATERIAL LOCATION: **Milk Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	14			
MATERIAL DESCRIPTION:	4" White Vinyl Babseboard			
MATERIAL LOCATION:	All Classrooms and Hallways			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **4" White Vinyl Babseboard**

MATERIAL LOCATION: **All Classrooms and Hallways**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	22			
MATERIAL DESCRIPTION:	12" x 12" Beige and White Streak Floor Tile			
MATERIAL LOCATION:	Kitchen			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:	Over 9"x9" floor tile off white (HA-05)			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUILDING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Beige and White Streak Floor Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23772** BUIDLING ID: **3971**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Kenneth Karuhn**
SCHOOL NAME: **Herzl School CPC** INSPECTION DATE: **7/16/2025**
ADDRESS: **1401 S. Hamlin Avenue** IDPH LICENSE NO: **100-07278**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **White Sink Undercoating**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **SURFACE** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:



Date: **07/16/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **White Sink Undercoating**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Drywall		
MATERIAL LOCATION:	Milk Room, MDF Room		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Milk Room, MDF Room**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Kenneth Karuhn		
SCHOOL NAME:	Herzl School CPC	INSPECTION DATE:	7/16/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	4" White Vinyl Baseboard Adhesive		
MATERIAL LOCATION:	All Classrooms and Hallways		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 07/16/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23772	BUIDLING ID:	3971
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Herzl School CPC	REVIEW DATE:	7/28/2025		
ADDRESS:	1401 S. Hamlin Avenue	IDPH LICENSE NO:	100-07278		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **4" White Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **All Classrooms and Hallways**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **07/28/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Kenneth Karuhn


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2410112748
Course Date: 10/11/2024
Exam Date: 10/11/2024
Expiration Date: 10/11/2025




Issue Date: 10/11/2024


Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

Ken Karuhn

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager



ENDORSEMENTS

INSPECTOR

TC EXPIRES

10/11/2025

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL



9/14/2025

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/22/2025

AIR SAMPLING PROFESSIONAL
Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

ENDORSEMENTS

TC EXPIRES

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed