

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2273
SCHOOL NAME: Howe School
ADDRESS OF SCHOOL: 720 N. Lorel Avenue
CITY: Chicago, IL, 60644

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 1/11/2023

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/4/2025 ENROLLMENT 332
IDPH INSPECTOR LICENSE NUMBER: 100-11255
IDPH LICENSED INSPECTOR NAME (Please Print): Esteban Nunez
IDPH MP LICENSE NUMBER: 100-07342
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 4/25/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Howe School

720 N. Lorel Avenue
Chicago, IL, 60644

Unit: 23851
Building ID: 4060

IDPH ID Number: 14-016-2990-2273

REPORT DATE:
Friday, April 25, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Specialty Consulting, Inc.

2942 W. Van Buren Street
Chicago, IL, 60612
Phone (312) 319-7575
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

04/25/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23851 Region: 02 IDPH ID: 14-016-2990-2273

School: Howe School Building ID: 4060

Address: 720 N. Lorel Avenue

Chicago, IL, 60644

Building Contact: Stack, Shannon Contact Phone: 7085526011

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/4/2025

Review Date: 04/25/2025

Inspector: Esteban Nunez

Inspector IDPH License: 100-11255

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Jigar Shah
100-07342

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 25, 2025

RE: Howe School, Unit 23851
720 N. Lorel Avenue
Chicago, IL, 60644

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Howe School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Howe School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Howe School Unit: 23851 Region: 02
Address: 720 N. Loret Avenue Chicago, IL, 60644
IDPH ID: 14-016-2990-2273 Building ID: 4060
Contact: Stack, Shannon Phone: 7085526011

2. Description of Facility

Original Construction: 1911 Additional Construction: 1896
Total Square Footage: 42777 No of Floors: 3
Current Occupancy: 332

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: Esteban Nunez

Signature:

Inspector IDPH license # 100-11255
Reinspection Date: 4/4/2025

6. Management Planner

Management Planner Name: Jigar Shah

Signature:

Management Planner IDPH license # 100-07342

7. Review Date: 04/25/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Signature:

Date: 4/25/2025

Name: Richard J. Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Howe School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4060:

15	9"x9" Brown Floor Tile
49	Plaster

B. The following new homogenous areas have been identified for Building 4060:

51	12"x12" Cream w/ White Specs Replacement VFT
51M	12"x12" Cream w/ White Specs Replacement VFT Mastic
52	12"x12" Beige & Tan Streaked Replacement VFT
52M	12"x12" Beige & Tan Streaked Replacement VFT Mastic VFT
53	12"x12" Cream w/ White VFT
53M	12"x12" Cream w/ White VFT Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

39	12"x12" Khaki Colored w/Streaks VFT
40	12"x12" Khaki Colored w/Streaks Mastic
41	Black Trip Vinyl
42	Black Trip Vinyl Adhesive
43	12"x12" Tan w/ Brown Streaks VFT
43M	12"x12" Tan w/ Brown Streaks VFT Mastic
44	12"x12" Off White with Tan Streaks VFT
44M	12"x12" Off White with Tan Streaks VFT Mastic
45	Drywall System
46	2' x 2' White Ceiling Tile
47	12"x12" Tan w/ Cream VFT
48	12"x12" Tan w/ Cream VFT Mastic
49	Plaster
50	Plaster
51	12"x12" Cream w/ White Specs Replacement VFT
51M	12"x12" Cream w/ White Specs Replacement VFT Mastic
52	12"x12" Beige & Tan Streaked Replacement VFT
52M	12"x12" Beige & Tan Streaked Replacement VFT Mastic VFT
53	12"x12" Cream w/ White VFT
53M	12"x12" Cream w/ White VFT Mastic

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Esteban Nunez, IDPH License # 100-11255. The Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 4/22/2024
 4/22/2024

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Howe School Building 4060 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Howe School **Unit** 23851 **Building ID** 4060
Address 720 N. Lorel Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
02	9"x9" Green Floor Tile (Abated 2008)			Room 208, Deck Over Vestibule - 1896 Bldg.	ABATED	MISC								
03	12"x12" Beige Floor Tile (Abated 2008)			South Dressing Room - 1910 Bldg.	ABATED	MISC								
04	9"x9" Green Floor Tile Mastic (Abated 2008)			Room 208 - 1896 Bldg.	ABATED	MISC								
05	12"x12" Beige Floor Tile Mastic (Abated 2008)			South Dressing Room - 1910 Bldg.	ABATED	MISC								
08	12"x12" Off White Floor Tile (ABATED 2010)			Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.	ABATED	MISC								
09	12"x12" Off White Floor Tile Mastic (ABATED 2010)			Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.	ABATED	MISC								
10	12"x12" White Floor Tile (ABATED 2010)			Room 303 - 1910 Bldg.	ABATED	MISC								
11	12"x12" White Floor Tile Mastic (ABATED 2010)			Room 303 - 1910 Bldg.	ABATED	MISC								
12	12"x12" Off-White Floor Tile (ABATED 2010)			NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.	ABATED	MISC								
13	12"x12" Off-White Floor Tile Mastic (ABATED 2010)			NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.	ABATED	MISC					No			
14	Red Linoleum			Auditorium Stairs - 1910 Bldg.	NO_ACBM	MISC					No			
15	9"x9" Brown Floor Tile	150	SF	Small Room North of Boiler Room - 1910 Bldg.	CHR	MISC	N	LOC	15		Yes	ACBM with the potential for damage	3	LOW
16	9"x9" Brown Floor Tile Mastic	150	SF	Small Room North of Boiler Room - 1910 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12"x12" Off-White w/Tan Streaks Floor			Room 306 - 1910	ABATED	MISC					No			

Chicago Public Schools

School Howe School **Unit** 23851 **Building ID** 4060
Address 720 N. Lorel Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile (Not Observed) ABATED 2010			Bldg.										
18	12"x12" Off-White w/Tan Streaks Floor Tile Mastic (Not Observed) ABATED 2010			Room 306 - 1910 Bldg.	ABATED	MISC					No			
19	9"x9" Green w/White & Black Streaks Floor Tile (Not Observed) ABATED 2010			Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.	ABATED	MISC								
20	9"x9" Green w/White & Black Streaks Floor Tile Mastic (Not Observed) ABATED 2010			Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.	ABATED	MISC								
37	12"x12" Off White Floor Tile (ABATED 2010)			Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room	ABATED	MISC								
38	12"x12" Off White Floor Tile Adhesive (Abated in 2010)			Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room	ABATED	MISC								
39	12"x12" Khaki Colored w/Streaks VFT	24	SF	Electric Room in Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
40	12"x12" Khaki Colored w/Streaks Mastic	24	SF	Electric Room in Gym	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	Black Trip Vinyl	200	SF	Stair Landings & Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	Black Trip Vinyl Adhesive	200	SF	Stair Landings & Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12"x12" Tan w/ Brown Streaks VFT	12,300	SF	1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
43M	12"x12" Tan w/ Brown Streaks VFT Mastic	12,300	SF	1896 & 1910 Bldg Addition - 1st, 2nd,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Howe School **Unit** 23851 **Building ID** 4060
Address 720 N. Lorel Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors										
44	12"x12" Off White with Tan Streaks VFT	4,200	SF	1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208; 1896 Bldg. - 1st Floor 104, 105	ASSUMED	MISC	N		0		No	ACBM with the potential for damage		MODERATE
44M	12"x12" Off White with Tan Streaks VFT Mastic	4,200	SF	1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208; 1896 Bldg. - 1st Floor 104, 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	Drywall System	15,000	SF	1910 Bldg. - Throughout 1st, 2nd, 3rd Floors, New 4th Floor Classrooms & Offices Bathrooms; 1896 Classrooms, Storage Offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	2' x 2' White Ceiling Tile	3,500	SF	Throughout New 4th Floor Corridors	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
47	12"x12" Tan w/ Cream VFT	4,880	SF	Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
48	12"x12" Tan w/ Cream VFT Mastic	4,880	SF	Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Plaster	25,000	SF	Throughout - 1896 Building	ASSUMED	SURFACE	N	DIST	250		Yes	ACBM with the potential for damage	5	MODERATE
50	Plaster	50,000	SF	Throughout - 1910 Building Addition	ASSUMED	SURFACE	N	DIST	300		No	ACBM with the potential for damage	10	MODERATE

Chicago Public Schools

School Howe School **Unit** 23851 **Building ID** 4060
Address 720 N. Lorel Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
51	12"x12" Cream w/ White Specs Replacement VFT	25	SF	Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51M	12"x12" Cream w/ White Specs Replacement VFT Mastic	25	SF	Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" Beige & Tan Streaked Replacement VFT	65	SF	Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52M	12"x12" Beige & Tan Streaked Replacement VFT Mastic VFT	65	SF	Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"x12" Cream w/ White VFT	120	SF	2nd and 3rd Floor Elevator Connecting Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53M	12"x12" Cream w/ White VFT Mastic	120	SF	2nd and 3rd Floor Elevator Connecting Corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
D	Cardboard Pipe Insulation	65	LF	1st Floor Corridor, Storeroom by Gymnasium, Storeroom (#100 Pre-K Classroom now) 1896 - 1910 Bldg. Damage Locations: 1st floor corridor, Rm 202 wardrobe, 3rd floor janitor's closet, Rm 100 (pre-k)	CHR	TSI	Y	DIST	22		No	ACBM with potential for significant damage		MODERATE

Chicago Public Schools

School Howe School **Unit** 23851 **Building ID** 4060
Address 720 N. Lorel Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
F	MJP E/F/V on Fiberglass Pipe Insulation	80	FITTING	Boiler Room Toilet, Auditorium Storeroom, NW Boy's Toilet & Corridor, Jan's Closet next to Room 304 - 1910 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	MJP E/F/V on Cardboard Pipe Insulation	5	FITTING	1st Floor Corridor, Store Room by Gymnasium - 1910 Bldg. #100 Pre-K Classroom - 1896 Bldg & Room#202 Wardrobe - 1910	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Howe School Unit 23851 Building ID 4060
Address 720 N. Lorel Avenue Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>4/4/2025</u>
Inspector Name <u>Esteban Nunez</u>
<u>100-11255</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
02	
03	
04	
05	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
37	
38	
39	
40	
41	
42	
43	

Chicago Public Schools

School Howe School **Unit** 23851 **Building ID** 4060
Address 720 N. Lorel Avenue **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
43M	
44	
44M	
45	
46	
47	
48	
49	
50	
51	
51M	
52	
52M	
53	
53M	
D	
F	
G	

Table II
Management Planner's Review

Chicago Public Schools

School Howe School

Unit 23851

Building ID 4060

Address 720 N. Loret Avenue

Chicago, IL, 60644

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
02	9"x9" Green Floor Tile (Abated 2008)			Room 208, Deck Over Vestibule - 1896 Bldg.	Abated	MISC					
03	12"x12" Beige Floor Tile (Abated 2008)			South Dressing Room - 1910 Bldg.	Abated	MISC					
04	9"x9" Green Floor Tile Mastic (Abated 2008)			Room 208 - 1896 Bldg.	Abated	MISC					
05	12"x12" Beige Floor Tile Mastic (Abated 2008)			South Dressing Room - 1910 Bldg.	Abated	MISC					
08	12"x12" Off White Floor Tile (ABATED 2010)			Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.	Abated	MISC					
09	12"x12" Off White Floor Tile Mastic (ABATED 2010)			Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.	Abated	MISC					
10	12"x12" White Floor Tile (ABATED 2010)			Room 303 - 1910 Bldg.	Abated	MISC					
11	12"x12" White Floor Tile Mastic (ABATED 2010)			Room 303 - 1910 Bldg.	Abated	MISC					
12	12"x12" Off-White Floor Tile (ABATED 2010)			NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.	Abated	MISC					
13	12"x12" Off-White Floor Tile Mastic (ABATED 2010)			NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.	Abated	MISC					
14	Red Linoleum			Auditorium Stairs - 1910 Bldg.	No ACBM	MISC					
15	9"x9" Brown Floor Tile	150	SF	Small Room North of Boiler Room - 1910 Bldg.	Chrysotile	MISC	No	15	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9"x9" Brown Floor Tile Mastic	150	SF	Small Room North of Boiler Room - 1910 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Off-White w/Tan Streaks Floor Tile (Not Observed) ABATED 2010			Room 306 - 1910 Bldg.	Abated	MISC					
18	12"x12" Off-White w/Tan Streaks Floor Tile Mastic (Not Observed) ABATED 2010			Room 306 - 1910 Bldg.	Abated	MISC					
19	9"x9" Green w/White & Black Streaks Floor Tile (Not Observed) ABATED 2010			Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.	Abated	MISC					
20	9"x9" Green w/White & Black Streaks Floor Tile Mastic (Not Observed) ABATED 2010			Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.	Abated	MISC					
37	12"x12" Off White Floor Tile (ABATED 2010)			Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room	Abated	MISC					

Chicago Public Schools

School Howe School

Unit 23851

Building ID 4060

Address 720 N. Loret Avenue

Chicago, IL, 60644

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
38	12"x12" Off White Floor Tile Adhesive (Abated in 2010)			Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room	Abated	MISC					
39	12"x12" Khaki Colored w/Streaks VFT	24	SF	Electric Room in Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" Khaki Colored w/Streaks Mastic	24	SF	Electric Room in Gym	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Black Trip Vinyl	200	SF	Stair Landings & Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Black Trip Vinyl Adhesive	200	SF	Stair Landings & Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12"x12" Tan w/ Brown Streaks VFT	12,300	SF	1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43M	12"x12" Tan w/ Brown Streaks VFT Mastic	12,300	SF	1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12"x12" Off White with Tan Streaks VFT	4,200	SF	1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208; 1896 Bldg. - 1st Floor 104, 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44M	12"x12" Off White with Tan Streaks VFT Mastic	4,200	SF	1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208; 1896 Bldg. - 1st Floor 104, 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	Drywall System	15,000	SF	1910 Bldg. - Throughout 1st, 2nd, 3rd Floors, New 4th Floor Classrooms & Offices Bathrooms; 1896 Classrooms, Storage Offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	2' x 2' White Ceiling Tile	3,500	SF	Throughout New 4th Floor Corridors	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12"x12" Tan w/ Cream VFT	4,880	SF	Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12"x12" Tan w/ Cream VFT Mastic	4,880	SF	Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Plaster	25,000	SF	Throughout - 1896 Building	Assumed	SURFACE	No	250	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Howe School

Unit 23851

Building ID 4060

Address 720 N. Loret Avenue

Chicago, IL, 60644

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
50	Plaster	50,000	SF	Throughout - 1910 Building Addition	Assumed	SURFACE	No	300	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12"x12" Cream w/ White Specs Replacement VFT	25	SF	Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51M	12"x12" Cream w/ White Specs Replacement VFT Mastic	25	SF	Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" Beige & Tan Streaked Replacement VFT	65	SF	Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52M	12"x12" Beige & Tan Streaked Replacement VFT Mastic VFT	65	SF	Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Cream w/ White VFT	120	SF	2nd and 3rd Floor Elevator Connecting Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53M	12"x12" Cream w/ White VFT Mastic	120	SF	2nd and 3rd Floor Elevator Connecting Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Cardboard Pipe Insulation	65	LF	1st Floor Corridor, Storeroom by Gymnasium, Storeroom (#100 Pre-K Classroom now) 1896 - 1910 Bldg. Damage Locations: 1st floor corridor, Rm 202 wardrobe, 3rd floor janitor's closet, Rm 100 (pre-k)	Chrysotile	TSI	Yes	22	LF	5 ACBM with potential for significant damage	Follow O&M Plan
F	MJP E/F/V on Fiberglass Pipe Insulation	80	FITTING	Boiler Room Toilet, Auditorium Storeroom, NW Boy's Toilet & Corridor, Jan's Closet next to Room 304 - 1910 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
G	MJP E/F/V on Cardboard Pipe Insulation	5	FITTING	1st Floor Corridor, Store Room by Gymnasium - 1910 Bldg. #100 Pre-K Classroom - 1896 Bldg & Room#202 Wardrobe - 1910	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Howe School

Unit 23851

Building ID 4060

Address 720 N. Loret Avenue

Chicago, IL, 60644

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

Review Date	4/25/2025
Manager Planner Name	Jigar Shah
100-07342	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
02	
03	
04	
05	
08	
09	
10	
11	
12	

Chicago Public Schools

School Howe School

Unit 23851

Building ID 4060

Address 720 N. Loret Avenue

Chicago, IL, 60644

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13	
14	
15	
16	
17	
18	
19	
20	
37	
38	
39	
40	
41	
42	
43	
43M	
44	
44M	
45	
46	
47	
48	
49	
50	
51	
51M	
52	

Chicago Public Schools

School Howe School

Unit 23851

Building ID 4060

Address 720 N. Loret Avenue

Chicago, IL, 60644

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
52M	
53	
53M	
D	
F	
G	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 02

MATERIAL DESCRIPTION: 9"x9" Green Floor Tile (Abated 2008)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 208, Deck Over Vestibule - 1896 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile (Abated 2008)**

MATERIAL LOCATION: **Room 208, Deck Over Vestibule - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 03

MATERIAL DESCRIPTION: 12"x12" Beige Floor Tile (Abated 2008)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: South Dressing Room - 1910 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile (Abated 2008)**

MATERIAL LOCATION: **South Dressing Room - 1910 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic (Abated 2008)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 208 - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **9"x9" Green Floor Tile Mastic (Abated 2008)**

MATERIAL LOCATION: **Room 208 - 1896 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic (Abated 2008)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **South Dressing Room - 1910 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic (Abated 2008)**

MATERIAL LOCATION: **South Dressing Room - 1910 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 08

MATERIAL DESCRIPTION: 12"x12" Off White Floor Tile (ABATED 2010)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile (ABATED 2010)**

MATERIAL LOCATION: **Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile Mastic (ABATED 2010)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

**Specialty Consulting, Inc.
2025 AHERA REINSPECTION**

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile Mastic (ABATED 2010)**

MATERIAL LOCATION: **Central Stairwell Landing between 1st & 2nd Floors, between 2nd & 3rd Floors - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile (ABATED 2010)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 303 - 1910 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile (ABATED 2010)**

MATERIAL LOCATION: **Room 303 - 1910 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: 12"x12" White Floor Tile Mastic (ABATED 2010)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 303 - 1910 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic (ABATED 2010)**

MATERIAL LOCATION: **Room 303 - 1910 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: 12"x12" Off-White Floor Tile (ABATED 2010)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12"x12" Off-White Floor Tile (ABATED 2010)**

MATERIAL LOCATION: **NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13

MATERIAL DESCRIPTION: 12"x12" Off-White Floor Tile Mastic (ABATED 2010)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: 13

MATERIAL DESCRIPTION: 12"x12" Off-White Floor Tile Mastic (ABATED 2010)

MATERIAL LOCATION: NW Stairwell Landing between 1st & 2nd Fls, 2nd & 3rd Fls; 2nd & 3rd Fl Corrs - 1910 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 04/25/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14
MATERIAL DESCRIPTION: Red Linoleum
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium Stairs - 1910 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Red Linoleum**

MATERIAL LOCATION: **Auditorium Stairs - 1910 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	9"x9" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Deterioration Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Deterioration Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Small Room North of Boiler Room - 1910 Bldg.		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile**

MATERIAL LOCATION: **Small Room North of Boiler Room - 1910 Bldg.**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **15** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	9"x9" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Physical Damage Deterioration		
HISTORICAL RESPONSE ACTION:	Encapsulate		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Small Room North of Boiler Room - 1910 Bldg.		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Small Room North of Boiler Room - 1910 Bldg.**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Encapsulate

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 17

MATERIAL DESCRIPTION: 12"x12" Off-White w/Tan Streaks Floor Tile (Not Observed) ABATED 2010

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 306 - 1910 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12"x12" Off-White w/Tan Streaks Floor Tile (Not Observed) ABATED 2010**

MATERIAL LOCATION: **Room 306 - 1910 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 18

MATERIAL DESCRIPTION: 12"x12" Off-White w/Tan Streaks Floor Tile Mastic (Not Observed)
ABATED 2010

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 306 - 1910 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12"x12" Off-White w/Tan Streaks Floor Tile Mastic (Not Observed) ABATED 2010**

MATERIAL LOCATION: **Room 306 - 1910 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9"x9" Green w/White & Black Streaks Floor Tile (Not Observed)
ABATED 2010**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **9"x9" Green w/White & Black Streaks Floor Tile (Not Observed) ABATED 2010**

MATERIAL LOCATION: **Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20

MATERIAL DESCRIPTION: 9"x9" Green w/White & Black Streaks Floor Tile Mastic (Not Observed)
ABATED 2010

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **9"x9" Green w/White & Black Streaks Floor Tile Mastic (Not Observed) ABATED 2010**

MATERIAL LOCATION: **Copy Room (308 Ward), Room 308 (Library) - 1896 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 37

MATERIAL DESCRIPTION: 12"x12" Off White Floor Tile (ABATED 2010)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12"x12" Off White Floor Tile (ABATED 2010)**

MATERIAL LOCATION: **Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38	
MATERIAL DESCRIPTION:	12"x12" Off White Floor Tile Adhesive (Abated in 2010)	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: 38

MATERIAL DESCRIPTION: 12"x12" Off White Floor Tile Adhesive (Abated in 2010)

MATERIAL LOCATION: Room 208, Deck over Vestibule, Central Stairway Landings, NW Stairway Landings, Small Room North of Boiler Room

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:


DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 04/25/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12"x12" Khaki Colored w/Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Electric Room in Gym		
MATERIAL QUANTITY:	24	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" Khaki Colored w/Streaks VFT**

MATERIAL LOCATION: **Electric Room in Gym**

MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12"x12" Khaki Colored w/Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Electric Room in Gym		
MATERIAL QUANTITY:	24	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" Khaki Colored w/Streaks Mastic**

MATERIAL LOCATION: **Electric Room in Gym**

MATERIAL QUANTITY: **24** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Black Trip Vinyl		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stair Landings & Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Black Trip Vinyl**

MATERIAL LOCATION: **Stair Landings & Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Black Trip Vinyl Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stair Landings & Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Black Trip Vinyl Adhesive**

MATERIAL LOCATION: **Stair Landings & Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors		
MATERIAL QUANTITY:	12300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT**

MATERIAL LOCATION: **1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors**

MATERIAL QUANTITY: **12300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43M		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors		
MATERIAL QUANTITY:	12300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **43M**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Brown Streaks VFT Mastic**

MATERIAL LOCATION: **1896 & 1910 Bldg Addition - 1st, 2nd, 3rd Floor Corridor, E to W - Corridors, North & South Ends, Main Offices, Lunchroom, MDF Room, and 2nd and 3rd Floor Elevator Corridors**

MATERIAL QUANTITY: **12300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12"x12" Off White with Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208; 1896 Bldg. - 1st Floor 104, 105		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12"x12" Off White with Tan Streaks VFT**

MATERIAL LOCATION: **1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208;
1896 Bldg. - 1st Floor 104, 105**

MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44M		
MATERIAL DESCRIPTION:	12"x12" Off White with Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208; 1896 Bldg. - 1st Floor 104, 105		
MATERIAL QUANTITY:	4200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **44M**

MATERIAL DESCRIPTION: **12"x12" Off White with Tan Streaks VFT Mastic**

MATERIAL LOCATION: **1910 Bldg. - 3rd Floor 303, 304, 2nd Floor 200 and 208;
1896 Bldg. - 1st Floor 104, 105**

MATERIAL QUANTITY: **4200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	Drywall System		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1910 Bldg. - Throughout 1st, 2nd, 3rd Floors, New 4th Floor Classrooms & Offices
Bathrooms; 1896 Classrooms, Storage Offices**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **1910 Bldg. - Throughout 1st, 2nd, 3rd Floors, New 4th Floor Classrooms & Offices Bathrooms;
1896 Classrooms, Storage Offices**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	2' x 2' White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout New 4th Floor Corridors		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile**

MATERIAL LOCATION: **Throughout New 4th Floor Corridors**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Cream VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor		
MATERIAL QUANTITY:	4880	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Cream VFT**

MATERIAL LOCATION: **Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor**

MATERIAL QUANTITY: **4880** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12"x12" Tan w/ Cream VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor		
MATERIAL QUANTITY:	4880	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12"x12" Tan w/ Cream VFT Mastic**

MATERIAL LOCATION: **Classrooms 401, 402, 403, 404, 402A, 4th Floor Offices, Storage Rooms, Stair Landing, and 4th Floor Corridor**

MATERIAL QUANTITY: **4880** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage Water		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage Water		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout - 1896 Building		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout - 1896 Building**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **250** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:	Water Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Water Physical Damage		
DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout - 1910 Building Addition		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Throughout - 1910 Building Addition**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **300** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	5 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st Floor Corridor, Storeroom by Gymnasium, Storeroom (#100 Pre-K Classroom now 1896 - 1910 Bldg.**
Damage Locations: 1st floor corridor, Rm 202 wardrobe, 3rd floor janitor's closet, Rm 100 (pre-k)

MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **1st Floor Corridor, Storeroom by Gymnasium, Storeroom (#100 Pre-K Classroom now) 1896 - 1910 Bldg.
Damage Locations: 1st floor corridor, Rm 202 wardrobe, 3rd floor janitor's closet, Rm 100 (pre-k)**

MATERIAL QUANTITY: **65** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **22** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

LOW

MATERIAL LOCATION:

Boiler Room Toilet, Auditorium Storeroom, NW Boy's Toilet & Corridor, Jan's Closet next to Room 304 - 1910 Bldg.

MATERIAL QUANTITY:

80

MATERIAL UNITS:

FITTING

DAMAGE QUANTITY:

DAMAGE UNITS:

FITTING

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUILDING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Boiler Room Toilet, Auditorium Storeroom, NW Boy's Toilet & Corridor, Jan's Closet next to Room 304 - 1910 Bldg.**

MATERIAL QUANTITY: **80** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor Corridor, Store Room by Gymnasium - 1910 Bldg. #100 Pre-K Classroom - 1896 Bldg & Room#202 Wardrobe - 1910**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: MATERIAL UNITS: **FITTING**

COMMENTS:

Inspector's Signature:



Date: **04/04/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Loret Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **1st Floor Corridor, Store Room by Gymnasium - 1910 Bldg. #100 Pre-K Classroom - 1896 Bldg & Room#202 Wardrobe - 1910**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12"x12" Cream w/ White Specs Replacement VFT		
MATERIAL LOCATION:	Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23851** BUIDLING ID: **4060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Howe School** REVIEW DATE: **4/25/2025**

ADDRESS: **720 N. Lorel Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12"x12" Cream w/ White Specs Replacement VFT**

MATERIAL LOCATION: **Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12"x12" Cream w/ White VFT		
MATERIAL LOCATION:	2nd and 3rd Floor Elevator Connecting Corridors		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23851** BUIDLING ID: **4060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Howe School** REVIEW DATE: **4/25/2025**

ADDRESS: **720 N. Lorel Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x12" Cream w/ White VFT**

MATERIAL LOCATION: **2nd and 3rd Floor Elevator Connecting Corridors**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	53M				
MATERIAL DESCRIPTION:	12"x12" Cream w/ White VFT Mastic				
MATERIAL LOCATION:	2nd and 3rd Floor Elevator Connecting Corridors				
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23851** BUIDLING ID: **4060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Howe School** REVIEW DATE: **4/25/2025**

ADDRESS: **720 N. Lorel Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **53M**

MATERIAL DESCRIPTION: **12"x12" Cream w/ White VFT Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Elevator Connecting Corridors**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	51M			
MATERIAL DESCRIPTION:	12"x12" Cream w/ White Specs Replacement VFT Mastic			
MATERIAL LOCATION:	Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator			
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:				

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jigar Shah		
SCHOOL NAME:	Howe School	REVIEW DATE:	4/25/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

HOMOGENEOUS AREA: **51M**

MATERIAL DESCRIPTION: **12"x12" Cream w/ White Specs Replacement VFT Mastic**

MATERIAL LOCATION: **Outside Room 404, 4th Floor Corridor near Elevator, Main Office, Principal's Office, Room 105, and 1st Floor Corridor by Elevator**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	52M			
MATERIAL DESCRIPTION:	12"x12" Beige & Tan Streaked Replacement VFT Mastic VFT			
MATERIAL LOCATION:	Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor			
MATERIAL QUANTITY:	65	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23851** BUIDLING ID: **4060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Howe School** REVIEW DATE: **4/25/2025**

ADDRESS: **720 N. Lorel Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **52M**

MATERIAL DESCRIPTION: **12"x12" Beige & Tan Streaked Replacement VFT Mastic VFT**

MATERIAL LOCATION: **Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor**

MATERIAL QUANTITY: **65** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **04/25/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23851	BUIDLING ID:	4060
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Esteban Nunez		
SCHOOL NAME:	Howe School	INSPECTION DATE:	4/4/2025		
ADDRESS:	720 N. Lorel Avenue	IDPH LICENSE NO:	100-11255		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12"x12" Beige & Tan Streaked Replacement VFT		
MATERIAL LOCATION:	Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor		
MATERIAL QUANTITY:	65	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/04/2025

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23851** BUIDLING ID: **4060**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Howe School** REVIEW DATE: **4/25/2025**

ADDRESS: **720 N. Lorel Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12"x12" Beige & Tan Streaked Replacement VFT**

MATERIAL LOCATION: **Room 304, 2nd Floor Connection Corridor, Main Office, Principal's Office and 1st Floor Elevator Corridor**

MATERIAL QUANTITY: **65** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **04/25/2025**

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/15/2022 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/15/2022

Course Dates:

01/15/2023

Expires:

2201BIR16

Certificate Number:

A handwritten signature in black ink, appearing to read 'Nicholas J. Peneff, Director of Training'.

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 11255

ISSUED
2/28/2022

EXPIRES
05/15/2023

ESTEBAN NUNEZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



ESTEBAN NUNEZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11255**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11255	ISSUED 2/28/2022	EXPIRES 05/15/2023	INSPECTOR	1/15/2023
			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/11/2022
<p>ESTEBAN NUNEZ 2942 W VAN BUREN ST CHICAGO, IL 60612</p> <p>Environmental Health</p> <p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 01/28/2023 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

01/28/2023

Course Dates:

01/28/2024

Expires:

2301BIR27

Certificate Number:

A handwritten signature in black ink that reads "Nicholas J. Peneff" above "Director of Training".

Phone: 312-491-0081

Director of Training

Nicholas J. Peneff

Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois



ESTEBAN NUNEZ
2942 W VAN BUREN ST
CHICAGO, IL 60612


6/21/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11255

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/23/2025
PROJECT MANAGER	1/15/2025
AIR SAMPLING PROFESSIONAL	
<i>Alteration of this license shall result in legal action</i> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 02/23/2024 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

02/23/2024

Course Dates:

02/23/2025

Expires:

2402BIR06

Certificate Number:

N. Penef

Phone: 312-491-0081

Director of Training

Nicholas J. Penef


Doctor of Public Health

FORM # A-010B



525-535 West Jefferson Street • Springfield, IL

ESTEBAN NUNEZ
2942 W VAN BUREN ST
CHICAGO, IL 60612



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11255**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11255	ISSUED 4/30/2025	EXPIRES 05/15/2026	INSPECTOR 3/19/2026
ESTEBAN NUNEZ 2942 W VAN BUREN ST CHICAGO, IL 60612		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/14/2025
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the
examination on 03/19/2025 with a minimum score of 70% or better. Training was in accordance
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

03/19/2025

Course Dates:

03/19/2026

Expires:

2503BIR05

Certificate Number:

Phone: 312-491-0081

FORM # A-010B

Director of Training

Nicholas J. Penef

Doctor of Public Health

A handwritten signature in black ink that appears to read 'Nicholas J. Penef'.



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

6/9/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 07342	ISSUED 6/9/2025	EXPIRES 05/15/2026	INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/7/2026 1/27/2026 3/7/2026 4/7/2026
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

Kathy DeSalvo

Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022


Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761

IDPH

ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 07342

ISSUED
4/1/2022

EXPIRES
05/15/2023

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/9/2023
PROJECT DESIGNER	3/24/2023
MANAGEMENT PLANNER	3/9/2023
PROJECT MANAGER	3/2/2023
AIR SAMPLING PROFESSIONAL	
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 07342

ISSUED
4/8/2024

EXPIRES
05/15/2025

JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH
2942 W VAN BUREN ST
CHICAGO, IL 60612


4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/8/2025
PROJECT DESIGNER	3/7/2025
MANAGEMENT PLANNER	3/8/2025
PROJECT MANAGER	3/25/2024
AIR SAMPLING PROFESSIONAL	
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH. IMPROVING LIVES

Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/8/2024

Exam Date: 3/8/2024

Expiration Date: 3/8/2025

Certificate Number: MPR2403081126

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Jigar Shah

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: MPR2503070948

Course Credit Hours: MPR 4 Hours

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed