

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2275
SCHOOL NAME: Hoyne School
ADDRESS OF SCHOOL: 8905 S Crandon
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 7/21/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/13/2025 ENROLLMENT 211
IDPH INSPECTOR LICENSE NUMBER: 100-19716
IDPH LICENSED INSPECTOR NAME (Please Print): Imani Robinson
IDPH MP LICENSE NUMBER: 100-03613
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/5/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Hoyne School

8905 S Crandon
Chicago, IL, 60617

Unit: 23871
Building ID: 4080

IDPH ID Number: 14-016-2990-2275

REPORT DATE:
Thursday, June 05, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
TEM Environmental, Inc.

174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone 630-790-0880
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/03/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23871 Region: 06 IDPH ID: 14-016-2990-2275

School: Hoyne School Building ID: 4080

Address: 8905 S Crandon

Chicago, IL, 60617

Building Contact: Alaniz, Randy Contact Phone: 3125137519

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/13/2025

Review Date: 06/03/2025

Inspector: Imani Robinson

Inspector IDPH License: 100-19716

Management Planner: Daniel Juneau

Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 05, 2025

RE: Hoyne School, Unit 23871
8905 S Crandon
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Hoyne School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Hoyne School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Hoyne School
Address: 8905 S Crandon
IDPH ID: 14-016-2990-2275
Contact: Alaniz, Randy

Unit: 23871
Chicago, IL, 60617
Building ID: 4080
Phone: 3125137519

Region: 06

2. Description of Facility

Original Construction: 1998
Total Square Footage: 10125
Current Occupancy: 211

Additional Construction: 1955
No of Floors: 1

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880

Fax: 630-790-0882

5. Inspector

Inspector Name: Imani Robinson

Inspector IDPH license # 100-19716
Reinspection Date: 5/13/2025


Signature:
Date: 5/13/2025

6. Management Planner

Management Planner Name: Daniel Juneau

Management Planner IDPH license # 100-03613


Signature:
Date: 06/03/2025

7. Review Date: 06/03/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/5/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hoyne School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4080:

| | |
|-----|-----------------------------|
| 47 | Grey Wood Laminate Flooring |
| NEW | Newly Installed Suspect ACM |

B. The following new homogenous areas have been identified for Building 4080:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|-----|--|
| 17 | Black Vinyl Baseboard Mastic |
| 19 | Gray Vinyl Baseboard Mastic |
| 24 | 1 x 1 White Ceiling Tile |
| 25 | Beige and Tan Ceramic Tile Grout |
| 26 | Beige and Tan Ceramic Tile Adhesive |
| 27 | 12 x 12 Light Grey Floor Tile |
| 27M | 12 x 12 Light Grey Floor Tile Mastic |
| 28 | 12 x 12 Beige and White Checkerboard Floor Tile |
| 28M | 12 x 12 Beige and White Checkerboard Floor Tile Mastic |
| 29 | Carpet Adhesive |
| 30 | Insulation in Vault Door |
| 31 | 2 x 2 White Lay-In Ceiling Tile |
| 32 | 9 x 9 Beige Floor Tile |
| 32M | 9 x 9 Beige Floor Tile Mastic |
| 33 | 2 x 4 Yellow Lay-In Ceiling Panels |
| 34 | 2 x 4 White Lay-In Ceiling Tile |
| 35 | 5" x 5" Brown Ceramic Floor Tile Grout |
| 36 | 5" x 5" Brown Ceramic Floor Tile Adhesive |
| 37 | Gray Vinyl Baseboard Panels |
| 38 | Black Fire Retardant |
| 39 | Plaster Ceiling |
| 40 | Ceramic Baseboard Grout |
| 41 | 12" Gray Mottled Vinyl Floor Tile |
| 42 | 12" Gray Mottled Vinyl Floor Tile Mastic |
| 43 | 12" Tan Mottled Vinyl Floor Tile |
| 44 | 12" Tan Mottled Vinyl Floor Tile Mastic |
| 45 | 12" Orange Mottled Vinyl Floor Tile |
| 46 | 12" Orange Vinyl Floor Tile Mastic |
| 47 | Grey Wood Laminate Flooring |
| NEW | Newly Installed Suspect ACM |

The following areas were deemed to be inaccessible:

| | |
|-------|--|
| 08FT1 | 12"x12" Gray Floor Tile Mastic |
| 08FT2 | 12x12 Beige Floor Tile Mastic |
| 26 | Beige and Tan Ceramic Tile Adhesive |
| 27M | 12 x 12 Light Grey Floor Tile Mastic |
| 28M | 12 x 12 Beige and White Checkerboard Floor Tile Mastic |

| | |
|-----|---|
| 29 | Carpet Adhesive |
| 30 | Insulation in Vault Door |
| 32M | 9 x 9 Beige Floor Tile Mastic |
| 36 | 5" x 5" Brown Ceramic Floor Tile Adhesive |
| 42 | 12" Gray Mottled Vinyl Floor Tile Mastic |
| 44 | 12" Tan Mottled Vinyl Floor Tile Mastic |
| 46 | 12" Orange Vinyl Floor Tile Mastic |

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Imani Robinson, IDPH License # 100-19716. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Hoyne School Building 4080 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| | | | | 114 | | | | | | | | | | |
| 12 | Firebrick ABATED | | | Boiler Room | ABATED | TSI | | | | | | | | |
| 13 | Incinerator Door | | | Boiler Room | NO_ACBM | TSI | | | | | | | | |
| 14 | Light Beige Linoleum | 2,020 | SF | Room 106, Kitchen | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 16 | Black Vinyl Baseboard | | | 1939 Bldg. Rooms 101, 102, 103, 104, 111 | NO_ACBM | MISC | | | | | | | | LOW |
| 17 | Black Vinyl Baseboard Mastic | 100 | LF | 1939 Building-Rooms 101, 102, 103, 104 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 18 | Light Beige Linoleum Adhesive NOT OBSERVED | | | Room 106, Kitchen | NO_ACBM | | | | | | | | | |
| 19 | Gray Vinyl Baseboard Mastic | 210 | LF | 1959 Building-Room 101, 102, 103, 104, 111 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 20 | Linoleum ABATED | | | 1959 Building-Rooms 101, 102, 103, 104 | ABATED | MISC | | | | | | | | |
| 22 | Boiler Gaskets ABATED | | | Boiler Room | ABATED | TSI | | | | | | | | |
| 23 | Plaster ABATED | | | Throughout School | ABATED | SURFACE | | | | | | | | |
| 24 | 1 x 1 White Ceiling Tile | 9,824 | SF | North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114 | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 25 | Beige and Tan Ceramic Tile Grout | 996 | SF | East Girls and Boys Washrooms, East and West Entrances | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 26 | Beige and Tan Ceramic Tile Adhesive | 996 | SF | East Girls and Boys Washrooms, East and West Entrances | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 27 | 12 x 12 Light Grey Floor Tile | 2,728 | SF | Multipurpose Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 27M | 12 x 12 Light Grey Floor Tile Mastic | 2,728 | SF | Multipurpose Room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 28 | 12 x 12 Beige and White Checkerboard Floor Tile | 120 | SF | Main Office Restroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 28M | 12 x 12 Beige and White Checkerboard Floor Tile Mastic | 120 | SF | Main Office Restroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 29 | Carpet Adhesive | 748 | SF | Main Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 30 | Insulation in Vault Door | 1 | EA | Main Office | ASSUMED | TSI | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|--|---------------|-----------------------|
| 31 | 2 x 2 White Lay-In Ceiling Tile | 4,484 | SF | Main Office, Rooms 101, 103, 115 and 116 | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 32 | 9 x 9 Beige Floor Tile | 936 | SF | Room 104 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 32M | 9 x 9 Beige Floor Tile Mastic | 936 | SF | Room 104 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 33 | 2 x 4 Yellow Lay-In Ceiling Panels | 1,020 | SF | Kitchen 118 | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 34 | 2 x 4 White Lay-In Ceiling Tile | 216 | SF | Principal's Office | ASSUMED | MISC | Y | NONE | 0 | | No | Any remaining friable ACBM or friable suspect ACBM | | LOW |
| 35 | 5" x 5" Brown Ceramic Floor Tile Grout | 96 | SF | NE Courtyard Entrance | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 36 | 5" x 5" Brown Ceramic Floor Tile Adhesive | 96 | SF | NE Courtyard Entrance | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 37 | Gray Vinyl Baseboard Panels | 210 | LF | 1959 Building- Rooms 101-104 and 111 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 38 | Black Fire Retardant | 1,500 | SF | Throughout 1959 Addition | ASSUMED | SURFACE | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 39 | Plaster Ceiling | 600 | SF | 1998 Addition- Boys and Girls Toilets and Janitor Closet | ASSUMED | SURFACE | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 40 | Ceramic Baseboard Grout | 1,200 | SF | Halls and Classrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 41 | 12" Gray Mottled Vinyl Floor Tile | 525 | SF | Room 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 42 | 12" Gray Mottled Vinyl Floor Tile Mastic | 525 | SF | Room 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 43 | 12" Tan Mottled Vinyl Floor Tile | 150 | SF | Room 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 44 | 12" Tan Mottled Vinyl Floor Tile Mastic | 150 | SF | Room 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 45 | 12" Orange Mottled Vinyl Floor Tile | 75 | SF | Room 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 46 | 12" Orange Vinyl Floor Tile Mastic | 75 | SF | Room 108 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 47 | Grey Wood Laminate Flooring | 1,200 | SF | Main Office Suite: Teachers' Room, Principal's Office, Storeroom, Public Space | ASSUMED | MISC | N | NONE | 0 | | Yes | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| NEW | Newly Installed Suspect ACM | | | Installed After Implementation of Management Plan and After Renovations | ASSUMED | MISC | | UNKNO WN | 0 | | Yes | ACBM with the potential for damage | | |

Chicago Public Schools

School Hoyne School Unit 23871 Building ID 4080
Address 8905 S Crandon Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

| | |
|---|-----------------------|
| Reinspection Date | <u>5/13/2025</u> |
| Inspector Name | <u>Imani Robinson</u> |
| <u>100-19716</u> | <u>5/15/2026</u> |
| Inspector's IDPH License Number / Expiration Date | |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---|
| 04FT1 | |
| 04FT2 | |
| 04FT3 | |
| 05FT1 | |
| 05FT2 | |
| 06 | Not Observed Multiple Years, including 2025 |
| 07 | |
| 08FT1 | |
| 08FT2 | |
| 08FT3 | Room 104 has 9"x9" White w/Specs Floor Tile |
| 09FT1 | |
| 09FT2 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 16 | |
| 17 | |
| 18 | Not Observed 2025 |
| 19 | |
| 20 | |
| 22 | |
| 23 | |

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 27M | |
| 28 | |
| 28M | |
| 29 | |
| 30 | |
| 31 | |
| 32 | |
| 32M | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 47 | |
| NEW | |

Chicago Public Schools

School Hoyne School **Unit** 23871 **Building ID** 4080
Address 8905 S Crandon **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Hoyne School

Unit 23871

Building ID 4080

Address 8905 S Crandon

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 04FT1 | 12x12 Gray Floor Tile | 3,000 | SF | Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, and 111 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 04FT2 | 12x12 Beige Floor Tile | 2,000 | SF | 1955 Building- Classrooms, including Rooms 110, 112, 113, 114, Office Vault Room | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 04FT3 | 12x12 White Floor Tile | 1,200 | SF | Main Office, West, South Halls, Room 101, 103, 115, 116 and Gym Office | Chrysotile | MISC | | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 05FT1 | 9x9 Dark Gray Floor Tile | 978 | SF | 1959 Building- Rooms 102 and 103 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 05FT2 | 12x12 Beige Floor Tile | 900 | SF | 1959 Building- Rooms 101 and 104 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06 | Wall Boards (NOT OBSERVED) | | | | | MISC | | | | | |
| 07 | Beige Multi-Colored Linoleum | 0 | SF | 1955 Building- Room 106 | No ACBM | MISC | | | SF | | |
| 08FT1 | 12"x12" Gray Floor Tile Mastic | 3,000 | SF | 1955 Building- Classrooms & Hallways, including Rooms 105, 107, 109, 111 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 08FT2 | 12x12 Beige Floor Tile Mastic | 2,000 | SF | 1955 Building- Classrooms, including Rooms 110, 112, 114 | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 08FT3 | 12x12 White Floor Tile Mastic | | | Main Office, Rooms 101 and 104, West and South Halls | No ACBM | MISC | | | | | |
| 09FT1 | 9x9 Dark Gray Floor Tile Mastic | | | 1959 Building- Rooms 102 and 103 | No ACBM | MISC | | | | | |
| 09FT2 | 12x12 Beige Floor Tile Mastic | | | 1959 Building- Rooms 101 and 104 | No ACBM | MISC | | | | | |
| 10 | Black Vinyl Baseboard-NOT OBSERVED | | | 1955 Building- Rooms 105, 107, 108, 109, 110, 112, 114 | No ACBM | MISC | | | | | |
| 11 | Black Vinyl Baseboard Mastic-NOT OBSERVED | | | 1955 Building, Rooms 105, 107, 108, 109, 110, 112, 114 | No ACBM | MISC | | | | | |
| 12 | Firebrick ABATED | | | Boiler Room | Abated | TSI | | | | | |
| 13 | Incinerator Door | | | Boiler Room | No ACBM | TSI | | | | | |
| 14 | Light Beige Linoleum | 2,020 | SF | Room 106, Kitchen | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 16 | Black Vinyl Baseboard | | | 1939 Bldg. Rooms 101, 102, 103, 104, 111 | No ACBM | MISC | | | | | |
| 17 | Black Vinyl Baseboard Mastic | 100 | LF | 1939 Building- Rooms 101, 102, 103, 104 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 | Light Beige Linoleum Adhesive NOT OBSERVED | | | Room 106, Kitchen | No ACBM | | | | | | |
| 19 | Gray Vinyl Baseboard Mastic | 210 | LF | 1959 Building- Room 101, 102, 103, 104, 111 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20 | Linoleum ABATED | | | 1959 Building- Rooms 101, 102, 103, 104 | Abated | MISC | | | | | |

Chicago Public Schools

School Hoyne School

Unit 23871

Building ID 4080

Address 8905 S Crandon

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--|-----------------|
| 22 | Boiler Gaskets ABATED | | | Boiler Room | Abated | TSI | | | | | |
| 23 | Plaster ABATED | | | Throughout School | Abated | SURFACE | | | | | |
| 24 | 1 x 1 White Ceiling Tile | 9,824 | SF | North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114 | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 25 | Beige and Tan Ceramic Tile Grout | 996 | SF | East Girls and Boys Washrooms, East and West Entrances | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 26 | Beige and Tan Ceramic Tile Adhesive | 996 | SF | East Girls and Boys Washrooms, East and West Entrances | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 27 | 12 x 12 Light Grey Floor Tile | 2,728 | SF | Multipurpose Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 27M | 12 x 12 Light Grey Floor Tile Mastic | 2,728 | SF | Multipurpose Room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28 | 12 x 12 Beige and White Checkerboard Floor Tile | 120 | SF | Main Office Restroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28M | 12 x 12 Beige and White Checkerboard Floor Tile Mastic | 120 | SF | Main Office Restroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29 | Carpet Adhesive | 748 | SF | Main Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 30 | Insulation in Vault Door | 1 | EA | Main Office | Assumed | TSI | No | 0 | EA | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31 | 2 x 2 White Lay-In Ceiling Tile | 4,484 | SF | Main Office, Rooms 101, 103, 115 and 116 | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 32 | 9 x 9 Beige Floor Tile | 936 | SF | Room 104 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32M | 9 x 9 Beige Floor Tile Mastic | 936 | SF | Room 104 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 33 | 2 x 4 Yellow Lay-In Ceiling Panels | 1,020 | SF | Kitchen 118 | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 34 | 2 x 4 White Lay-In Ceiling Tile | 216 | SF | Principal's Office | Assumed | MISC | Yes | 0 | SF | 7 Any remaining friable ACBM or friable suspect ACBM | Follow O&M Plan |
| 35 | 5" x 5" Brown Ceramic Floor Tile Grout | 96 | SF | NE Courtyard Entrance | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 36 | 5" x 5" Brown Ceramic Floor Tile Adhesive | 96 | SF | NE Courtyard Entrance | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 37 | Gray Vinyl Baseboard Panels | 210 | LF | 1959 Building- Rooms 101-104 and 111 | Assumed | MISC | No | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 38 | Black Fire Retardant | 1,500 | SF | Throughout 1959 Addition | Assumed | SURFACE | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 39 | Plaster Ceiling | 600 | SF | 1998 Addition- Boys and Girls Toilets and Janitor Closet | Assumed | SURFACE | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 40 | Ceramic Baseboard Grout | 1,200 | SF | Halls and Classrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 41 | 12" Gray Mottled Vinyl Floor Tile | 525 | SF | Room 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 42 | 12" Gray Mottled Vinyl Floor Tile Mastic | 525 | SF | Room 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 43 | 12" Tan Mottled Vinyl Floor Tile | 150 | SF | Room 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Hoyne School

Unit 23871

Building ID 4080

Address 8905 S Crandon

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|---|-------------------|----------------|--|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 44 | 12" Tan Mottled Vinyl Floor Tile Mastic | 150 | SF | Room 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 45 | 12" Orange Mottled Vinyl Floor Tile | 75 | SF | Room 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 46 | 12" Orange Vinyl Floor Tile Mastic | 75 | SF | Room 108 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 47 | Grey Wood Laminate Flooring | 1,200 | SF | Main Office Suite: Teachers' Room, Principal's Office, Storeroom, Public Space | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| NEW | Newly Installed Suspect ACM | | | Installed After Implementation of Management Plan and After Renovations | Assumed | MISC | | 0 | | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Hoyne School
Address 8905 S Crandon

Unit 23871
Chicago, IL, 60617

Building ID 4080
Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|---------------|
| Review Date | 6/3/2025 |
| Manager Planner Name | Daniel Juneau |
| 100-03613 | 5/15/2026 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 04FT1 | |
| 04FT2 | |
| 04FT3 | |
| 05FT1 | |
| 05FT2 | |
| 06 | |
| 07 | |
| 08FT1 | |
| 08FT2 | |
| 08FT3 | |
| 09FT1 | |
| 09FT2 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 22 | |
| 23 | |
| 24 | |
| 25 | |

Chicago Public Schools

School Hoyne School

Unit 23871

Building ID 4080

Address 8905 S Crandon

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 26 | |
| 27 | |
| 27M | |
| 28 | |
| 28M | |
| 29 | |
| 30 | |
| 31 | |
| 32 | |
| 32M | |
| 33 | |
| 34 | |
| 35 | |
| 36 | |
| 37 | |
| 38 | |
| 39 | |
| 40 | |
| 41 | |
| 42 | |
| 43 | |
| 44 | |
| 45 | |
| 46 | |
| 47 | |
| NEW | |

Chicago Public Schools

School Hoyne School

Unit 23871

Building ID 4080

Address 8905 S Crandon

Chicago, IL, 60617

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 04FT1 | | |
| MATERIAL DESCRIPTION: | 12x12 Gray Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, and 111 | | |
| MATERIAL QUANTITY: | 3000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | DAMAGE UNITS: SF | | |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **04FT1**

MATERIAL DESCRIPTION: **12x12 Gray Floor Tile**

MATERIAL LOCATION: **Classrooms & Hallways of 1955 Building, including Rooms 105, 107, 109, and 111**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 04FT2 | | |
| MATERIAL DESCRIPTION: | 12x12 Beige Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1955 Building- Classrooms, including Rooms 110, 112, 113, 114, Office Vault Room | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **04FT2**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**

MATERIAL LOCATION: **1955 Building- Classrooms, including Rooms 110, 112, 113, 114, Office Vault Room**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|------------------------|----------|--|
| HOMOGENEOUS AREA: | 04FT3 | | |
| MATERIAL DESCRIPTION: | 12x12 White Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Main Office, Wast, South Halls, Room 101, 103, 115, 116 and Gym Office | | |
| MATERIAL QUANTITY: | 1200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **04FT3**

MATERIAL DESCRIPTION: **12x12 White Floor Tile**

MATERIAL LOCATION: **Main Office, West, South Halls, Room 101, 103, 115, 116 and Gym Office**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 05FT1 | | |
| MATERIAL DESCRIPTION: | 9x9 Dark Gray Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1959 Building- Rooms 102 and 103 | | |
| MATERIAL QUANTITY: | 978 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **05FT1**

MATERIAL DESCRIPTION: **9x9 Dark Gray Floor Tile**

MATERIAL LOCATION: **1959 Building- Rooms 102 and 103**

MATERIAL QUANTITY: **978** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 05FT2 | | |
| MATERIAL DESCRIPTION: | 12x12 Beige Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1959 Building- Rooms 101 and 104 | | |
| MATERIAL QUANTITY: | 900 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **05FT2**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**

MATERIAL LOCATION: **1959 Building- Rooms 101 and 104**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Wall Boards (NOT OBSERVED)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed Multiple Years, including 2025**

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **Wall Boards (NOT OBSERVED)**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 07

MATERIAL DESCRIPTION: Beige Multi-Colored Linoleum

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1955 Building- Room 106

MATERIAL QUANTITY: 0 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Beige Multi-Colored Linoleum**

MATERIAL LOCATION: **1955 Building- Room 106**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 08FT1 | | |
| MATERIAL DESCRIPTION: | 12"x12" Gray Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1955 Building- Classrooms & Hallways, including Rooms 105, 107, 109, 111 | | |
| MATERIAL QUANTITY: | 3000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **08FT1**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **1955 Building- Classrooms & Hallways, including Rooms 105, 107, 109, 111**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 08FT2 | | |
| MATERIAL DESCRIPTION: | 12x12 Beige Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1955 Building- Classrooms, including Rooms 110, 112, 114 | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **08FT2**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**

MATERIAL LOCATION: **1955 Building- Classrooms, including Rooms 110, 112, 114**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **08FT3**

MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Rooms 101 and 104, West and South Halls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Room 104 has 9"x9" White w/Specs Floor Tile**

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **08FT3**

MATERIAL DESCRIPTION: **12x12 White Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Rooms 101 and 104, West and South Halls**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09FT1**

MATERIAL DESCRIPTION: **9x9 Dark Gray Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- Rooms 102 and 103**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **09FT1**

MATERIAL DESCRIPTION: **9x9 Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **1959 Building- Rooms 102 and 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **09FT2**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1959 Building- Rooms 101 and 104**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **09FT2**

MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**

MATERIAL LOCATION: **1959 Building- Rooms 101 and 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard-NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1955 Building- Rooms 105, 107, 108, 109, 110, 112, 114**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard-NOT OBSERVED**

MATERIAL LOCATION: **1955 Building- Rooms 105, 107, 108, 109, 110, 112, 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: Black Vinyl Baseboard Mastic-NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1955 Building, Rooms 105, 107, 108, 109, 110, 112, 114

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic-NOT OBSERVED**

MATERIAL LOCATION: **1955 Building, Rooms 105, 107, 108, 109, 110, 112, 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12
MATERIAL DESCRIPTION: Firebrick ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Firebrick ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 13
MATERIAL DESCRIPTION: Incinerator Door
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Incinerator Door**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 14 | | |
| MATERIAL DESCRIPTION: | Light Beige Linoleum | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 106, Kitchen | | |
| MATERIAL QUANTITY: | 2020 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Light Beige Linoleum**

MATERIAL LOCATION: **Room 106, Kitchen**

MATERIAL QUANTITY: **2020** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1939 Bldg. Rooms 101, 102, 103, 104, 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **1939 Bldg. Rooms 101, 102, 103, 104, 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 17 | | |
| MATERIAL DESCRIPTION: | Black Vinyl Baseboard Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1939 Building- Rooms 101, 102, 103, 104 | | |
| MATERIAL QUANTITY: | 100 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **1939 Building- Rooms 101, 102, 103, 104**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Light Beige Linoleum Adhesive NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 106, Kitchen**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Light Beige Linoleum Adhesive NOT OBSERVED**

MATERIAL LOCATION: **Room 106, Kitchen**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 19 | | |
| MATERIAL DESCRIPTION: | Gray Vinyl Baseboard Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1959 Building- Room 101, 102, 103, 104, 111 | | |
| MATERIAL QUANTITY: | 210 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard Mastic**

MATERIAL LOCATION: **1959 Building- Room 101, 102, 103, 104, 111**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 20
MATERIAL DESCRIPTION: Linoleum ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1959 Building- Rooms 101, 102, 103, 104

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Linoleum ABATED**

MATERIAL LOCATION: **1959 Building- Rooms 101, 102, 103, 104**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Boiler Gaskets ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Boiler Gaskets ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 23
MATERIAL DESCRIPTION: Plaster ABATED
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Plaster ABATED**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 24 | | |
| MATERIAL DESCRIPTION: | 1 x 1 White Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114 | | |
| MATERIAL QUANTITY: | 9824 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **1 x 1 White Ceiling Tile**

MATERIAL LOCATION: **North and West Corridors, Rooms 105, 106, 107, 108, 109, 110, 111, 112, 113, 114**

MATERIAL QUANTITY: **9824** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 25 | | |
| MATERIAL DESCRIPTION: | Beige and Tan Ceramic Tile Grout | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | East Girls and Boys Washrooms, East and West Entrances | | |
| MATERIAL QUANTITY: | 996 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Beige and Tan Ceramic Tile Grout**

MATERIAL LOCATION: **East Girls and Boys Washrooms, East and West Entrances**

MATERIAL QUANTITY: **996** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 26 | | |
| MATERIAL DESCRIPTION: | Beige and Tan Ceramic Tile Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | East Girls and Boys Washrooms, East and West Entrances | | |
| MATERIAL QUANTITY: | 996 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Beige and Tan Ceramic Tile Adhesive**

MATERIAL LOCATION: **East Girls and Boys Washrooms, East and West Entrances**

MATERIAL QUANTITY: **996** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 27 | | |
| MATERIAL DESCRIPTION: | 12 x 12 Light Grey Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Multipurpose Room | | |
| MATERIAL QUANTITY: | 2728 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12 x 12 Light Grey Floor Tile**

MATERIAL LOCATION: **Multipurpose Room**

MATERIAL QUANTITY: **2728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 27M | | |
| MATERIAL DESCRIPTION: | 12 x 12 Light Grey Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Multipurpose Room | | |
| MATERIAL QUANTITY: | 2728 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **27M**

MATERIAL DESCRIPTION: **12 x 12 Light Grey Floor Tile Mastic**

MATERIAL LOCATION: **Multipurpose Room**

MATERIAL QUANTITY: **2728** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 28 | | |
| MATERIAL DESCRIPTION: | 12 x 12 Beige and White Checkerboard Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Main Office Restroom | | |
| MATERIAL QUANTITY: | 120 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12 x 12 Beige and White Checkerboard Floor Tile**

MATERIAL LOCATION: **Main Office Restroom**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 28M | | |
| MATERIAL DESCRIPTION: | 12 x 12 Beige and White Checkerboard Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Main Office Restroom | | |
| MATERIAL QUANTITY: | 120 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **28M**

MATERIAL DESCRIPTION: **12 x 12 Beige and White Checkerboard Floor Tile Mastic**

MATERIAL LOCATION: **Main Office Restroom**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 29 | | |
| MATERIAL DESCRIPTION: | Carpet Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Main Office | | |
| MATERIAL QUANTITY: | 748 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Carpet Adhesive**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **748** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 30 | | |
| MATERIAL DESCRIPTION: | Insulation in Vault Door | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Main Office | | |
| MATERIAL QUANTITY: | 1 | MATERIAL UNITS: | EA |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | EA |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Insulation in Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 31 | | |
| MATERIAL DESCRIPTION: | 2 x 2 White Lay-In Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Main Office, Rooms 101, 103, 115 and 116 | | |
| MATERIAL QUANTITY: | 4484 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **2 x 2 White Lay-In Ceiling Tile**

MATERIAL LOCATION: **Main Office, Rooms 101, 103, 115 and 116**

MATERIAL QUANTITY: **4484** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 32 | | |
| MATERIAL DESCRIPTION: | 9 x 9 Beige Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 104 | | |
| MATERIAL QUANTITY: | 936 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **9 x 9 Beige Floor Tile**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 32M | | |
| MATERIAL DESCRIPTION: | 9 x 9 Beige Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 104 | | |
| MATERIAL QUANTITY: | 936 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **32M**

MATERIAL DESCRIPTION: **9 x 9 Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **936** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 33 | | |
| MATERIAL DESCRIPTION: | 2 x 4 Yellow Lay-In Ceiling Panels | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|-------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Kitchen 118 | | |
| MATERIAL QUANTITY: | 1020 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **2 x 4 Yellow Lay-In Ceiling Panels**

MATERIAL LOCATION: **Kitchen 118**

MATERIAL QUANTITY: **1020** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|-----|
| HOMOGENEOUS AREA: | 34 | | |
| MATERIAL DESCRIPTION: | 2 x 4 White Lay-In Ceiling Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 7 Any remaining friable ACBM or friable suspect ACBM | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

| | | | |
|------------------------|--------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Principal's Office | | |
| MATERIAL QUANTITY: | 216 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **2 x 4 White Lay-In Ceiling Tile**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **216** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--|----------|----|
| HOMOGENEOUS AREA: | 35 | | |
| MATERIAL DESCRIPTION: | 5" x 5" Brown Ceramic Floor Tile Grout | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | NE Courtyard Entrance | | |
| MATERIAL QUANTITY: | 96 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **5" x 5" Brown Ceramic Floor Tile Grout**

MATERIAL LOCATION: **NE Courtyard Entrance**

MATERIAL QUANTITY: **96** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 36 | | |
| MATERIAL DESCRIPTION: | 5" x 5" Brown Ceramic Floor Tile Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | NE Courtyard Entrance | | |
| MATERIAL QUANTITY: | 96 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **5" x 5" Brown Ceramic Floor Tile Adhesive**

MATERIAL LOCATION: **NE Courtyard Entrance**

MATERIAL QUANTITY: **96** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 37 | | |
| MATERIAL DESCRIPTION: | Gray Vinyl Baseboard Panels | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1959 Building- Rooms 101-104 and 111 | | |
| MATERIAL QUANTITY: | 210 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUILDING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Gray Vinyl Baseboard Panels**

MATERIAL LOCATION: **1959 Building- Rooms 101-104 and 111**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 38 | | |
| MATERIAL DESCRIPTION: | Black Fire Retardant | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Throughout 1959 Addition | | |
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Black Fire Retardant**

MATERIAL LOCATION: **Throughout 1959 Addition**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 39 | | |
| MATERIAL DESCRIPTION: | Plaster Ceiling | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1998 Addition- Boys and Girls Toilets and Janitor Closet | | |
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Plaster Ceiling**

MATERIAL LOCATION: **1998 Addition- Boys and Girls Toilets and Janitor Closet**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 40 | | |
| MATERIAL DESCRIPTION: | Ceramic Baseboard Grout | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Halls and Classrooms | | |
| MATERIAL QUANTITY: | 1200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Ceramic Baseboard Grout**

MATERIAL LOCATION: **Halls and Classrooms**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 41 | | |
| MATERIAL DESCRIPTION: | 12" Gray Mottled Vinyl Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 108 | | |
| MATERIAL QUANTITY: | 525 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" Gray Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|-----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|-----------|
| HOMOGENEOUS AREA: | 42 | | |
| MATERIAL DESCRIPTION: | 12" Gray Mottled Vinyl Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 108 | | |
| MATERIAL QUANTITY: | 525 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" Gray Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **525** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 43 | | |
| MATERIAL DESCRIPTION: | 12" Tan Mottled Vinyl Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 108 | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" Tan Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|---|----------|----|
| HOMOGENEOUS AREA: | 44 | | |
| MATERIAL DESCRIPTION: | 12" Tan Mottled Vinyl Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 108 | | |
| MATERIAL QUANTITY: | 150 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" Tan Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 45 | | |
| MATERIAL DESCRIPTION: | 12" Orange Mottled Vinyl Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 108 | | |
| MATERIAL QUANTITY: | 75 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12" Orange Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 46 | | |
| MATERIAL DESCRIPTION: | 12" Orange Vinyl Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 108 | | |
| MATERIAL QUANTITY: | 75 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" Orange Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 47 | | |
| MATERIAL DESCRIPTION: | Grey Wood Laminate Flooring | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Main Office Suite: Teachers' Room, Principal's Office, Storeroom, Public Space | | |
| MATERIAL QUANTITY: | 1200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/13/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Grey Wood Laminate Flooring**

MATERIAL LOCATION: **Main Office Suite: Teachers' Room, Principal's Office, Storeroom, Public Space**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|----------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | Imani Robinson | | |
| SCHOOL NAME: | Hoyne School | INSPECTION DATE: | 5/13/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|--|
| HOMOGENEOUS AREA: | NEW | | |
| MATERIAL DESCRIPTION: | Newly Installed Suspect ACM | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/13/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|----------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 23871 | BUIDLING ID: | 4080 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Daniel Juneau | | |
| SCHOOL NAME: | Hoyne School | REVIEW DATE: | 6/3/2025 | | |
| ADDRESS: | 8905 S Crandon | IDPH LICENSE NO: | 100-19716 | | |

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/03/2025**

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

CERTIFICATE OF ACHIEVEMENT

ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that IMANI ROBINSON has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the examination on 03/19/2025 with a minimum score of 70% or better. Training was in accordance with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools: Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



37 S Ashland Ave, Chicago, IL 60607 • www.public-health-safety.com

Course Dates:
03/19/2025

Expires:
03/19/2026



Certificate Number:
2503BIR07

Director of Training
Nicholas J. Penefit
Doctor of Public Health

FORM # A-010B

A handwritten signature in black ink, appearing to read "Nicholas J. Penefit".

Phone: 312-491-0081





TEM ENVIRONMENTAL, INC.

ENVIRONMENTAL SCIENTISTS | INDUSTRIAL HYGIENISTS



**ASBESTOS
PROFESSIONAL
LICENSE**

ID NUMBER
100 - 03613

ISSUED
3/1/2022

EXPIRES
05/15/2023

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS

INSPECTOR

TC EXPIRES

11/19/2022

MANAGEMENT PLANNER

11/19/2022

PROJECT MANAGER

11/1/2022

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois

Department of Public Health

This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: BIR2111192805

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/19/2021

Exam Date: 11/19/2021

Expiration Date: 11/19/2022

Certificate Number: MPR2111192816

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

4/3/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 03613

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| Front of License | | Back of License | |
|---|--------------------------------------|--|--|
|  | ASBESTOS PROFESSIONAL LICENSE | ENDORSEMENTS | TC EXPIRES |
| ID NUMBER 100 - 03613 | ISSUED 4/3/2024 | EXPIRES 05/15/2025 | INSPECTOR 11/3/2024 |
| DANIEL J JUNEAU 1408 OAKWOOD AVENUE DES PLAINES, IL 60016 Environmental Health | |  | MANAGEMENT PLANNER 11/3/2024 PROJECT MANAGER 11/7/2024 AIR SAMPLING PROFESSIONAL |
| Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

5/8/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 03613

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE | | | ENDORSEMENTS | TC EXPIRES |
|---|---------------------------|------------------------------|---|-------------------------|
| ID NUMBER 100 - 03613 | ISSUED 5/8/2025 | EXPIRES 05/15/2026 | INSPECTOR | 11/1/2025 |
| DANIEL J JUNEAU 1408 OAKWOOD AVENUE DES PLAINES, IL 60016 Environmental Health | | | MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL | 11/1/2025 11/13/2025 |
| | | | Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/12/2022

Exam Date: 12/12/2022

Expiration Date: 12/12/2023

Certificate Number: MPR2212123967

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/11/2022

Exam Date: 11/11/2022

Expiration Date: 11/11/2023

Certificate Number: BIR2211113645



Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2024

Exam Date: 11/1/2024

Expiration Date: 11/1/2025

Certificate Number: BIR2411013089

Course Credit Hours: BIR 4 Hours

A handwritten signature in blue ink that appears to read "Kristina Miczek".

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2024

Exam Date: 11/1/2024

Expiration Date: 11/1/2025

Certificate Number: MPR2411013107

Course Credit Hours: MPR 4 Hours

A handwritten signature in blue ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|------|--|
| MATERIAL | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | Loc | Localized |
| | Dist | Distributed |