

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2276
SCHOOL NAME: Hughes School, Charles Evans
ADDRESS OF SCHOOL: 4247 W. 15th St.
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/15/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/25/2025 ENROLLMENT 214
IDPH INSPECTOR LICENSE NUMBER: 100-19554
IDPH LICENSED INSPECTOR NAME (Please Print): Carol Ashman
IDPH MP LICENSE NUMBER: 100-18488
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/20/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Hughes School, Charles Evans

4247 W. 15th St.
Chicago, IL, 60623

Unit: 23901
Building ID: 4110

IDPH ID Number: 14-016-2990-2276

REPORT DATE:
Friday, June 20, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/20/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 23901 Region: 03 IDPH ID: 14-016-2990-2276

School: Hughes School, Charles Evans Building ID: 4110

Address: 4247 W. 15th St.

Chicago, IL, 60623

Building Contact: Zuffa, Steve Contact Phone: 7737103986

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/25/2025

Review Date: 06/20/2025

Inspector: Carol Ashman


Inspector IDPH License: 100-19554

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Mike Serio
100-18488

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 20, 2025

RE: Hughes School, Charles Evans, Unit 23901
4247 W. 15th St.
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Hughes School, Charles Evans , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Hughes School, Charles Evans, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Hughes School, Charles Evans
Address: 4247 W. 15th St.
IDPH ID: 14-016-2990-2276
Contact: Zufafa, Steve

Unit: 23901
Chicago, IL, 60623
Building ID: 4110
Phone: 7737103986

Region: 03

2. Description of Facility

Original Construction: 1960
Total Square Footage: 49043
Current Occupancy: 214

Additional Construction:
No of Floors: 2

3. LEA Designated Person

Contact: Richard J.Schleyer
Address: 42 West Madison Street
Chicago, IL 60602

Phone: (773) 251-7074

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900

Fax: (312) 782-5145

5. Inspector

Inspector Name: Carol Ashman

Inspector IDPH license # 100-19554
Reinspection Date: 5/25/2025

Signature:
Date: 5/25/2025

6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488

Signature:
Date: 06/20/2025

7. Review Date: 06/20/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:

Richard J. Schleyer

Date: 6/20/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Hughes School, Charles Evans. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4110:

06.2	9" x 9" Blue Vinyl Floor Tile Mastic
17	12" x 12" Yellow Floor Tile w/ Cream Specks
18	12" x 12" Yellow Floor Tile w/ Cream Specks Mastic
2.2	9" x 9" Blue Floor Tile
35	9" x 9" Green w/ White & Black Floor Tile
51	12" x 12" Yellow Cream Floor Tile
52	12" x 12" Yellow Cream Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 4110:

60	12" x 12" Sky Blue Floor Tile
61	12" x 12" Sky Blue Floor Tile Mastic
62	12" x 12" Lt. Gray Mottle Floor Tile
63	12" x 12" Lt. Gray Mottle Floor Tile Mastic
64	12" x 12" White w/ Dark Gray Streaks Floor Tile
65	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic
66	2" x 2" Light Beige Ceramic Tile and Grout
67	4" x 4" Rust Colored Ceramic Tile and Grout

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	12" x 12" Beige Floor Tile
03	1' x 1' Ceiling Tile
04	Plaster
06	9" x 9" Gray Vinyl Floor Tile Mastic
06.2	9" x 9" Blue Vinyl Floor Tile Mastic
07	4" Vinyl Mop Board
08	4" Vinyl Mop Board Mastic
09	Fire Doors
16	Drywall
17	12" x 12" Yellow Floor Tile w/ Cream Specks
19	4" Cream Vinyl Baseboard
20	4" Cream Vinyl Baseboard Adhesive
23	1' x 1' Ceiling Tile Adhesive
24	12" x 12" Light Blue w/ Blue Specks Floor Tile
26	12" x 12" Light Blue w/ Gray & White Specks Floor Tile
28	12" x 12" Brown Speckled Floor Tile
30	12" x 12" Cream w/ Gray & White Specks Floor Tile
33	1" x 1" White Pinhole Ceiling Tile
34	1" x 1" White Ceiling Tile
35	9" x 9" Green w/ White & Black Floor Tile
36	9" x 9" Green w/ White & Black Floor Tile Mastic
37	12" x 12" Gray Mix Floor Tile
38	12" x 12" Gray Mix Floor Tile Mastic
39	Sink Undercoat
40	2' x 4' Ceiling Panels
41	Chalk Board/Poster Board Adhesive
42	Drywall Ceilings
43	Drywall Joint Compound
44	Drywall Joint Tape
45	1' x 1' White Pinholed Ceiling Tiles
46	Black & White Terrazzo
47	Brown and White Ceramic Tile and Grout
48	Brown & White Ceramic Tile Mastic
49	12" x 12" Red Floor Tile
50	12" x 12" Red Floor Tile Mastic
51	12" x 12" Yellow Cream Floor Tile
52	12" x 12" Yellow Cream Floor Tile Mastic
53	12" x 12" Off-White Floor Tile
54	12" x 12" Off-White Floor Tile Mastic
58	12" x 12" Light Yellow Floor Tile

59	12" x 12" Light Yellow Floor Tile Mastic
60	12" x 12" Sky Blue Floor Tile
61	12" x 12" Sky Blue Floor Tile Mastic
62	12" x 12" Lt. Gray Mottle Floor Tile
63	12" x 12" Lt. Gray Mottle Floor Tile Mastic
64	12" x 12" White w/ Dark Gray Streaks Floor Tile
65	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic
66	2" x 2" Light Beige Ceramic Tile and Grout
67	4" x 4" Rust Colored Ceramic Tile and Grout
I	Duct Expander

The following areas were deemed to be inaccessible:

08	4" Vinyl Mop Board Mastic
20	4" Cream Vinyl Baseboard Adhesive
47	Brown and White Ceramic Tile and Grout
48	Brown & White Ceramic Tile Mastic
50	12" x 12" Red Floor Tile Mastic
54	12" x 12" Off-White Floor Tile Mastic
59	12" x 12" Light Yellow Floor Tile Mastic
61	12" x 12" Sky Blue Floor Tile Mastic
63	12" x 12" Lt. Gray Mottle Floor Tile Mastic
65	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Carol Ashman, IDPH License # 100-19554. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Hughes School, Charles Evans Building 4110 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12" x 12" Beige Floor Tile	800	SF	Lunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
02.1	9" x 9" Gray Vinyl Floor Tile	400	SF	2nd Floor Hall	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
02.2	9" x 9" Blue Floor Tile Mastic	4,320	SF	Throughout 2nd Floor Corridor, Patch in Rooms 100, 106	CHR	MISC	N	LOC	20	SF	No	ACBM with potential for significant damage	5	LOW
03	1' x 1' Ceiling Tile	30,000	SF	1st Floor Corridor, 2nd Floor West Half of Building, Rooms 110-116, 104-108, 201-209	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
04	Plaster	2,500	SF	Bathroom Ceiling & Stairway, Kitchen	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
05	12" x 12" Beige Floor Tile Mastic	800	SF	Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
06	9" x 9" Gray Vinyl Floor Tile Mastic	400	SF	2nd Floor Hall	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
06.2	9" x 9" Blue Vinyl Floor Tile Mastic			DUPLICATE HA	ASSUMED	MISC					Yes			
07	4" Vinyl Mop Board	324	LF	Gym	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
08	4" Vinyl Mop Board Mastic	324	LF	Gym	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
09	Fire Doors	21	SF	Throughout Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
10	Incinerator Door			ABATED	ABATED	MISC								
11	Incinerator Fire Brick			ABATED	ABATED	MISC								
12	Exterior Glazed Brown Brick - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
13	Exterior Glazed Brown Brick Mortar - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
14	Exterior Window Glaze - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
15	Exterior Window/ Door Caulk - Non-AHERA			Exterior of Building	CHR	MISC								
16	Drywall	10,000	SF	Above the 1'X 1' Ceiling Tile Throughout the Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	12" x 12" Yellow Floor Tile w/ Cream Specks			Auditorium Stage Area	ASSUMED	MISC					Yes			
18	12" x 12" Yellow Floor Tile w/ Cream Specks Mastic			Auditorium Stage Area	CHR	MISC					Yes			
19	4" Cream Vinyl Baseboard	800	LF	Auditorium Stage	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Area								potential for damage		
2.2	9" x 9" Blue Floor Tile	4,320	SF	Throughout 2nd Floor Corridor, Patch in Rooms 100, 106	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
20	4" Cream Vinyl Baseboard Adhesive	800	LF	Auditorium Stage Area	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
21	9" x 9" Cream w/ Gray Streaks Floor Tile			ABATED	ABATED	MISC								
22	9" x 9" Cream w/ Gray Streaks Floor Tile Mastic			ABATED	ABATED	MISC								
23	1' x 1' Ceiling Tile Adhesive	24,000	SF	1st Floor Corridor, 112, 114, 117, Gym, Office	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
24	12" x 12" Light Blue w/ Blue Specks Floor Tile	1,800	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
25	12" x 12" Light Blue w/ Blue Specks Floor Tile Mastic			2nd Floor Corridor	NO_ACBM	MISC								
26	12" x 12" Light Blue w/ Gray & White Specks Floor Tile	225	SF	2nd Floor Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
27	12" x 12" Light Blue w/ Gray & White Specks Floor Tile Mastic	225	SF	2nd Floor Corridor	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
28	12" x 12" Brown Speckled Floor Tile	44	SF	Meeting Room, Rooms 214 & 217	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
29	12" x 12" Brown Speckled Floor Tile Mastic	44	SF	Meeting Room, Rooms 214 & 217	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
30	12" x 12" Cream w/ Gray & White Specks Floor Tile	1,500	SF	Main Office, Room 106	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
31	12" x 12" Cream w/ Gray & White Specks Floor Tile Mastic			Main Office, Room 106	NO_ACBM	MISC								
32	Interior Door Caulk	1,530	LF	Throughout Building On Interior Side of Door Frames	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
33	1" x 1" White Pinhole Ceiling Tile			Now Ha 03	ASSUMED	MISC					No			
34	1" x 1" White Ceiling Tile			Now Ha 03	ASSUMED	MISC					No			
35	9" x 9" Green w/ White & Black Floor Tile	6,000	SF	Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206, 106, Replacement Tile in 100	ASSUMED	MISC	N	DIST	20	SF	Yes	ACBM with potential for significant damage	5	LOW
36	9" x 9" Green w/ White & Black Floor Tile Mastic	195	SF	Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				106, Replacement Tile in 100										
37	12" x 12" Gray Mix Floor Tile	45	SF	Rooms 217, 216, 212, 215, 210, 202, 208 and 203	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
38	12" x 12" Gray Mix Floor Tile Mastic	45	SF	Rooms 217, 216, 212, 215, 210, 202, 208 and 203	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
39	Sink Undercoat	14	SF	State Pre-K, 104, 106, 108, 110, 112, 215, 217	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
40	2' x 4' Ceiling Panels	9,000	SF	2nd Floor Hall, Rooms 210 - 217, Gym Stage Area, South Stairwell	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
41	Chalk Board/Poster Board Adhesive	2,522	SF	All Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
42	Drywall Ceilings	216	SF	East, West and North Vestibules	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
43	Drywall Joint Compound	40	SF	East, West and North Vestibules	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
44	Drywall Joint Tape	40	LF	East, West and North Vestibules	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
45	1' x 1' White Pinholed Ceiling Tiles	400	SF	Rooms 101 and 103	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
46	Black & White Terrazzo	3,000	SF	1st Floor and Stairwells	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
47	Brown and White Ceramic Tile and Grout	1,296	SF	1st, 2nd Floor Boys and Girls Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
48	Brown & White Ceramic Tile Mastic	1,296	SF	1st & 2nd Floor Boys and Girls Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
49	12" x 12" Red Floor Tile	520	SF	Auditorium Stage	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
50	12" x 12" Red Floor Tile Mastic	520	SF	Auditorium Stage	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
51	12" x 12" Yellow Cream Floor Tile			Gym Multi Purpose Room	ASSUMED	MISC					Yes			
52	12" x 12" Yellow Cream Floor Tile Mastic			Gym Multi Purpose Room	ASSUMED	MISC					Yes			
53	12" x 12" Off-White Floor Tile	1,800	SF	2nd Floor East Corridor, 212-217	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
54	12" x 12" Off-White Floor Tile Mastic	1,800	SF	2nd Floor East	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>5/25/2025</u>
Inspector Name	<u>Carol Ashman</u>
100-19554	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
01	
02.1	
02.2	Damage in 2nd floor corridor by drinking fountains
03	
04	
05	
06	
06.2	
07	
08	
09	
10	
11	
12	
13	
14	
15	
16	
17	Material not observed - 2025
18	Material not observed - 2025
19	
2.2	
20	
21	

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	Material not observed - 2025
34	Material not observed - 2025
35	Damage in 116, 110, 108, 210, 217, 106, 108 112 and Main Office
36	Not observed in 102 and 103
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
51	Material not observed - 2025
52	Material not observed - 2025
53	
54	
56	
57	
58	
59	
60	Damage in Room 103
61	
62	Damage in Room 103
63	
64	Damage in Room 103
65	
66	
67	
B	
H	
I	Material not observed - 2025
J	Material in inaccessible area(s) - 2025
L	
M	
N	

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Table II
Management Planner's Review

Chicago Public Schools

School Hughes School, Charles Evans

Unit 23901

Building ID 4110

Address 4247 W. 15th St.

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12" x 12" Beige Floor Tile	800	SF	Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
02.1	9" x 9" Gray Vinyl Floor Tile	400	SF	2nd Floor Hall	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
02.2	9" x 9" Blue Floor Tile Mastic	4,320	SF	Throughout 2nd Floor Corridor, Patch in Rooms 100, 106	Chrysotile	MISC	No	20	SF	5 ACBM with potential for significant damage	Remove
03	1' x 1' Ceiling Tile	30,000	SF	1st Floor Corridor, 2nd Floor West Half of Building, Rooms 110-116, 104-108, 201-209	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
04	Plaster	2,500	SF	Bathroom Ceiling & Stairway, Kitchen	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
05	12" x 12" Beige Floor Tile Mastic	800	SF	Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
06	9" x 9" Gray Vinyl Floor Tile Mastic	400	SF	2nd Floor Hall	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
06.2	9" x 9" Blue Vinyl Floor Tile Mastic			DUPLICATE HA	Assumed	MISC					Follow O&M Plan
07	4" Vinyl Mop Board	324	LF	Gym	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
08	4" Vinyl Mop Board Mastic	324	LF	Gym	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
09	Fire Doors	21	SF	Throughout Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Incinerator Door			ABATED	Abated	MISC					
11	Incinerator Fire Brick			ABATED	Abated	MISC					
12	Exterior Glazed Brown Brick - Non-AHERA			Exterior of Building	No ACBM	MISC					
13	Exterior Glazed Brown Brick Mortar - Non-AHERA			Exterior of Building	No ACBM	MISC					
14	Exterior Window Glaze - Non-AHERA			Exterior of Building	No ACBM	MISC					
15	Exterior Window/ Door Caulk - Non-AHERA			Exterior of Building	Chrysotile	MISC					
16	Drywall	10,000	SF	Above the 1' X 1' Ceiling Tile Throughout the Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12" x 12" Yellow Floor Tile w/ Cream Specks			Auditorium Stage Area	Assumed	MISC					
18	12" x 12" Yellow Floor Tile w/ Cream Specks Mastic			Auditorium Stage Area	Chrysotile	MISC					
19	4" Cream Vinyl Baseboard	800	LF	Auditorium Stage Area	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
2.2	9" x 9" Blue Floor Tile	4,320	SF	Throughout 2nd Floor Corridor, Patch in Rooms 100, 106	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	4" Cream Vinyl Baseboard Adhesive	800	LF	Auditorium Stage Area	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
21	9" x 9" Cream w/ Gray Streaks Floor Tile			ABATED	Abated	MISC					
22	9" x 9" Cream w/ Gray Streaks Floor Tile Mastic			ABATED	Abated	MISC					
23	1' x 1' Ceiling Tile Adhesive	24,000	SF	1st Floor Corridor, 112, 114, 117, Gym, Office	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
24	12" x 12" Light Blue w/ Blue Specks Floor Tile	1,800	SF	2nd Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Hughes School, Charles Evans

Unit 23901

Building ID 4110

Address 4247 W. 15th St.

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
25	12" x 12" Light Blue w/ Blue Specks Floor Tile Mastic			2nd Floor Corridor	No ACBM	MISC					
26	12" x 12" Light Blue w/ Gray & White Specks Floor Tile	225	SF	2nd Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" x 12" Light Blue w/ Gray & White Specks Floor Tile Mastic	225	SF	2nd Floor Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" Brown Speckled Floor Tile	44	SF	Meeting Room, Rooms 214 & 217	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Brown Speckled Floor Tile Mastic	44	SF	Meeting Room, Rooms 214 & 217	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" Cream w/ Gray & White Specks Floor Tile	1,500	SF	Main Office, Room 106	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12" x 12" Cream w/ Gray & White Specks Floor Tile Mastic			Main Office, Room 106	No ACBM	MISC					
32	Interior Door Caulk	1,530	LF	Throughout Building On Interior Side of Door Frames	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
33	1" x 1" White Pinhole Ceiling Tile			Now Ha 03	Assumed	MISC					
34	1" x 1" White Ceiling Tile			Now Ha 03	Assumed	MISC					
35	9" x 9" Green w/ White & Black Floor Tile	6,000	SF	Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206, 106, Replacement Tile in 100	Assumed	MISC	No	20	SF	5 ACBM with potential for significant damage	Remove
36	9" x 9" Green w/ White & Black Floor Tile Mastic	195	SF	Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206, 106, Replacement Tile in 100	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12" x 12" Gray Mix Floor Tile	45	SF	Rooms 217, 216, 212, 215, 210, 202, 208 and 203	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Gray Mix Floor Tile Mastic	45	SF	Rooms 217, 216, 212, 215, 210, 202, 208 and 203	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Sink Undercoat	14	SF	State Pre-K, 104, 106, 108, 110, 112, 215, 217	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	2' x 4' Ceiling Panels	9,000	SF	2nd Floor Hall, Rooms 210 - 217, Gym Stage Area, South Stairwell	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
41	Chalk Board/Poster Board Adhesive	2,522	SF	All Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Drywall Ceilings	216	SF	East, West and North Vestibules	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Drywall Joint Compound	40	SF	East, West and North Vestibules	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
44	Drywall Joint Tape	40	LF	East, West and North Vestibules	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
45	1' x 1' White Pinholed Ceiling Tiles	400	SF	Rooms 101 and 103	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Hughes School, Charles Evans

Unit 23901

Building ID 4110

Address 4247 W. 15th St.

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
46	Black & White Terrazzo	3,000	SF	1st Floor and Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Brown and White Ceramic Tile and Grout	1,296	SF	1st, 2nd Floor Boys and Girls Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Brown & White Ceramic Tile Mastic	1,296	SF	1st & 2nd Floor Boys and Girls Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" Red Floor Tile	520	SF	Auditorium Stage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" Red Floor Tile Mastic	520	SF	Auditorium Stage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Yellow Cream Floor Tile			Gym Multi Purpose Room	Assumed	MISC					
52	12" x 12" Yellow Cream Floor Tile Mastic			Gym Multi Purpose Room	Assumed	MISC					
53	12" x 12" Off-White Floor Tile	1,800	SF	2nd Floor East Corridor, 212-217	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Off-White Floor Tile Mastic	1,800	SF	2nd Floor East Corridor, 212-217	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" Light Gray w/ White Specks Floor Tile			ABATED	Abated	MISC					
57	12" x 12" Light Gray w/ White Specks Floor Tile Mastic			ABATED	Abated	MISC					
58	12" x 12" Light Yellow Floor Tile	10	SF	Room 203	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12" x 12" Light Yellow Floor Tile Mastic	10	SF	Room 203	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12" x 12" Sky Blue Floor Tile	800	SF	Room 101,102, 103	Assumed	MISC	No	2	SF	5 ACBM with potential for significant damage	Remove
61	12" x 12" Sky Blue Floor Tile Mastic	800	SF	Room 101, 102, 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Lt. Gray Mottle Floor Tile	800	SF	Room 101, 102, 103	Assumed	MISC	No	2	SF	5 ACBM with potential for significant damage	Remove
63	12" x 12" Lt. Gray Mottle Floor Tile Mastic	800	SF	Room 101, 102, 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" White w/ Dark Gray Streaks Floor Tile	800	SF	Room 101, 102, 103	Assumed	MISC	No	5	SF	5 ACBM with potential for significant damage	Remove
65	12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic	800	SF	Room 101, 102, 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
66	2" x 2" Light Beige Ceramic Tile and Grout	35	SF	Room 101 and 103 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
67	4" x 4" Rust Colored Ceramic Tile and Grout	600	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Fittings on Fiberglass Pipe Insulation			ABATED	Abated	TSI					
H	Breeching Insulation			ABATED	Abated	TSI					
I	Duct Expander			1st Floor Above Stage	Assumed	TSI					Follow O&M Plan
J	Duct Wrap			Kitchen and Stage and Above Ceiling in the Gym	Chrysotile	TSI					
L	Air Handler Duct Wrap			ABATED	Abated	TSI					

Chicago Public Schools

School Hughes School, Charles Evans **Unit** 23901 **Building ID** 4110
Address 4247 W. 15th St. **City** Chicago, IL, 60623 **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
M	Aircell Pipe Insulation			ABATED	Abated	TSI					
N	Cementitious Pipe Joint Ins. on Aircell Ins. Pipe			ABATED	Abated	MISC					

Review Date	6/20/2025
Manager Planner Name	Mike Serio

HA Number	Management Comments
01	

Chicago Public Schools

School Hughes School, Charles Evans

Address 4247 W. 15th St.

Unit 23901

Chicago, IL, 60623

Building ID 4110

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
02.1	
02.2	Remove or repair to intact.
03	
04	
05	
06	
06.2	
07	
08	
09	
10	
11	
12	Non-AHERA
13	Non-AHERA
14	Non-AHERA
15	Non-AHERA
16	
17	
18	
19	
2.2	
20	
21	
22	
23	
24	

Chicago Public Schools

School Hughes School, Charles Evans

Address 4247 W. 15th St.

Unit 23901

Chicago, IL, 60623

Building ID 4110

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	Sample to determine ACM content, remove or repair to intact.
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	

Chicago Public Schools

School Hughes School, Charles Evans

Address 4247 W. 15th St.

Unit 23901

Chicago, IL, 60623

Building ID 4110

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
51	
52	
53	
54	
56	
57	
58	
59	
60	Sample to determine ACM content, remove or repair to intact.
61	
62	Sample to determine ACM content, remove or repair to intact.
63	
64	Sample to determine ACM content, remove or repair to intact.
65	
66	
67	
B	
H	
I	
J	If identified, continue O&M.
L	
M	
N	

Chicago Public Schools

School	Hughes School, Charles Evans	Unit	23901	Building ID	4110
Address	4247 W. 15th St.		Chicago, IL, 60623	Region	03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02.1		
MATERIAL DESCRIPTION:	9" x 9" Gray Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Hall		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **02.1**

MATERIAL DESCRIPTION: **9" x 9" Gray Vinyl Floor Tile**

MATERIAL LOCATION: **2nd Floor Hall**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02.2		
MATERIAL DESCRIPTION:	9" x 9" Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	5 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Encapsulate		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 5. ACBM with potential for significant damage

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 2nd Floor Corridor, Patch in Rooms 100, 106		
MATERIAL QUANTITY:	4320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 2nd floor corridor by drinking fountains		

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **02.2**

MATERIAL DESCRIPTION: **9" x 9" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Throughout 2nd Floor Corridor, Patch in Rooms 100, 106**

MATERIAL QUANTITY: **4320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Encapsulate

Comments:

Remove or repair to intact.

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, 2nd Floor West Half of Building, Rooms 110-116, 104-108, 201-209		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **1st Floor Corridor, 2nd Floor West Half of Building, Rooms 110-116, 104-108, 201-209**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	04		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathroom Ceiling & Stairway, Kitchen		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **04**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **Bathroom Ceiling & Stairway, Kitchen**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	9" x 9" Gray Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Hall		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **9" x 9" Gray Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Hall**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06.2	
MATERIAL DESCRIPTION:	9" x 9" Blue Vinyl Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: DUPLICATE HA

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **06.2**

MATERIAL DESCRIPTION: **9" x 9" Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **DUPLICATE HA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	4" Vinyl Mop Board		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	324	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **4" Vinyl Mop Board**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **324** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	4" Vinyl Mop Board Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	324	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **4" Vinyl Mop Board Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **324** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	21	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Fire Doors**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **21** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Incinerator Door**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Incinerator Door**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11
MATERIAL DESCRIPTION: Incinerator Fire Brick
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Incinerator Fire Brick**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans		INSPECTION DATE:	5/25/2025	
ADDRESS:	4247 W. 15th St.		IDPH LICENSE NO:	100-19554	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Exterior Glazed Brown Brick - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Exterior Glazed Brown Brick - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Exterior Glazed Brown Brick Mortar - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Exterior Glazed Brown Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Exterior Window Glaze - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Exterior Window Glaze - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15	
MATERIAL DESCRIPTION:	Exterior Window/ Door Caulk - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Exterior Window/ Door Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Above the 1' X 1' Ceiling Tile Throughout the Building		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Above the 1' X 1' Ceiling Tile Throughout the Building**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17	
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile w/ Cream Specks	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Stage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/ Cream Specks**

MATERIAL LOCATION: **Auditorium Stage Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18	
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile w/ Cream Specks Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium Stage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile w/ Cream Specks Mastic**

MATERIAL LOCATION: **Auditorium Stage Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	4" Cream Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Stage Area		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **4" Cream Vinyl Baseboard**

MATERIAL LOCATION: **Auditorium Stage Area**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2.2		
MATERIAL DESCRIPTION:	9" x 9" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Encapsulate		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 2nd Floor Corridor, Patch in Rooms 100, 106		
MATERIAL QUANTITY:	4320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **2.2**

MATERIAL DESCRIPTION: **9" x 9" Blue Floor Tile**

MATERIAL LOCATION: **Throughout 2nd Floor Corridor, Patch in Rooms 100, 106**

MATERIAL QUANTITY: **4320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Encapsulate

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	4" Cream Vinyl Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Stage Area		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **4" Cream Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Auditorium Stage Area**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9" x 9" Cream w/ Gray Streaks Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9" x 9" Cream w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22

MATERIAL DESCRIPTION: 9" x 9" Cream w/ Gray Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **9" x 9" Cream w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor, 112, 114, 117, Gym, Office		
MATERIAL QUANTITY:	24000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile Adhesive**

MATERIAL LOCATION: **1st Floor Corridor, 112, 114, 117, Gym, Office**

MATERIAL QUANTITY: **24000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Blue Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Blue Specks Floor Tile**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25	
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Blue Specks Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Blue Specks Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Gray & White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor		
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Gray & White Specks Floor Tile**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/ Gray & White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor		
MATERIAL QUANTITY:	225	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/ Gray & White Specks Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Corridor**

MATERIAL QUANTITY: **225** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12" x 12" Brown Speckled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Meeting Room, Rooms 214 & 217		
MATERIAL QUANTITY:	44	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **Meeting Room, Rooms 214 & 217**

MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12" x 12" Brown Speckled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Meeting Room, Rooms 214 & 217		
MATERIAL QUANTITY:	44	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Meeting Room, Rooms 214 & 217**

MATERIAL QUANTITY: **44** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12" x 12" Cream w/ Gray & White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Room 106		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ Gray & White Specks Floor Tile**

MATERIAL LOCATION: **Main Office, Room 106**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ Gray & White Specks Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office, Room 106**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Cream w/ Gray & White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Room 106**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	Interior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building On Interior Side of Door Frames		
MATERIAL QUANTITY:	1530	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **Throughout Building On Interior Side of Door Frames**

MATERIAL QUANTITY: **1530** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 33

MATERIAL DESCRIPTION: 1" x 1" White Pinhole Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Now Ha 03

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **1" x 1" White Pinhole Ceiling Tile**

MATERIAL LOCATION: **Now Ha 03**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34

MATERIAL DESCRIPTION: 1" x 1" White Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Now Ha 03

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **1" x 1" White Ceiling Tile**

MATERIAL LOCATION: **Now Ha 03**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	9" x 9" Green w/ White & Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206, 106, Replacement Tile in 100		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 116, 110, 108, 210, 217, 106, 108 112 and Main Office		

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White & Black Floor Tile**

MATERIAL LOCATION: **Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206, 106, Replacement Tile in
100**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	9" x 9" Green w/ White & Black Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206, 106, Replacement Tile in 100		
MATERIAL QUANTITY:	195	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in 102 and 103		

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **9" x 9" Green w/ White & Black Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 116, 114, 112, 201, 202, 204, 212, 217, 213, 210, 207, 208, 205, 206, 106, Replacement Tile in
100**

MATERIAL QUANTITY: **195** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12" x 12" Gray Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 217, 216, 212, 215, 210, 202, 208 and 203		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile**

MATERIAL LOCATION: **Rooms 217, 216, 212, 215, 210, 202, 208 and 203**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12" x 12" Gray Mix Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 217, 216, 212, 215, 210, 202, 208 and 203		
MATERIAL QUANTITY:	45	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Gray Mix Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 217, 216, 212, 215, 210, 202, 208 and 203**

MATERIAL QUANTITY: **45** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Sink Undercoat		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	State Pre-K, 104, 106, 108, 110, 112, 215, 217		
MATERIAL QUANTITY:	14	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Sink Undercoat**

MATERIAL LOCATION: **State Pre-K, 104, 106, 108, 110, 112, 215, 217**

MATERIAL QUANTITY: **14** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Hall, Rooms 210 - 217, Gym Stage Area, South Stairwell		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Panels**

MATERIAL LOCATION: **2nd Floor Hall, Rooms 210 - 217, Gym Stage Area, South Stairwell**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Chalk Board/Poster Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Classrooms		
MATERIAL QUANTITY:	2522	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**

MATERIAL LOCATION: **All Classrooms**

MATERIAL QUANTITY: **2522** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Drywall Ceilings		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East, West and North Vestibules		
MATERIAL QUANTITY:	216	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Drywall Ceilings**

MATERIAL LOCATION: **East, West and North Vestibules**

MATERIAL QUANTITY: **216** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East, West and North Vestibules		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **East, West and North Vestibules**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Drywall Joint Tape		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	East, West and North Vestibules		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Drywall Joint Tape**

MATERIAL LOCATION: **East, West and North Vestibules**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	1' x 1' White Pinholed Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101 and 103		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **1' x 1' White Pinholed Ceiling Tiles**

MATERIAL LOCATION: **Rooms 101 and 103**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Black & White Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor and Stairwells		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Black & White Terrazzo**

MATERIAL LOCATION: **1st Floor and Stairwells**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	Brown and White Ceramic Tile and Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd Floor Boys and Girls Bathrooms		
MATERIAL QUANTITY:	1296	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **Brown and White Ceramic Tile and Grout**

MATERIAL LOCATION: **1st, 2nd Floor Boys and Girls Bathrooms**

MATERIAL QUANTITY: **1296** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Brown & White Ceramic Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st & 2nd Floor Boys and Girls Bathrooms		
MATERIAL QUANTITY:	1296	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Brown & White Ceramic Tile Mastic**

MATERIAL LOCATION: **1st & 2nd Floor Boys and Girls Bathrooms**

MATERIAL QUANTITY: **1296** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Stage		
MATERIAL QUANTITY:	520	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Auditorium Stage**

MATERIAL QUANTITY: **520** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium Stage		
MATERIAL QUANTITY:	520	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium Stage**

MATERIAL QUANTITY: **520** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51	
MATERIAL DESCRIPTION:	12" x 12" Yellow Cream Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Gym Multi Purpose Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" Yellow Cream Floor Tile**

MATERIAL LOCATION: **Gym Multi Purpose Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52	
MATERIAL DESCRIPTION:	12" x 12" Yellow Cream Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym Multi Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Yellow Cream Floor Tile Mastic**

MATERIAL LOCATION: **Gym Multi Purpose Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor East Corridor, 212-217		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**

MATERIAL LOCATION: **2nd Floor East Corridor, 212-217**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	12" x 12" Off-White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor East Corridor, 212-217		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor East Corridor, 212-217**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Specks Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans		INSPECTION DATE:	5/25/2025	
ADDRESS:	4247 W. 15th St.		IDPH LICENSE NO:	100-19554	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Specks Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Light Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 203		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Light Yellow Floor Tile**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12" x 12" Light Yellow Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 203		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" Light Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Room 203**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Fittings on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: Breeching Insulation

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Breeching Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: I

MATERIAL DESCRIPTION: Duct Expander

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Above Stage

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Duct Expander**

MATERIAL LOCATION: **1st Floor Above Stage**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Duct Wrap**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Kitchen and Stage and Above Ceiling in the Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Duct Wrap**

MATERIAL LOCATION: **Kitchen and Stage and Above Ceiling in the Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: L

MATERIAL DESCRIPTION: Air Handler Duct Wrap

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Air Handler Duct Wrap**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: N

MATERIAL DESCRIPTION: Cementitious Pipe Joint Ins. on Aircell Ins. Pipe

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUILDING ID:	4110
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Hughes School, Charles Evans	REVIEW DATE:	6/20/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Cementitious Pipe Joint Ins. on Aircell Ins. Pipe**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/20/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BULDING ID: **4110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Hughes School, Charles Evans** INSPECTION DATE: **5/25/2025**
ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **60**
MATERIAL DESCRIPTION: **12" x 12" Sky Blue Floor Tile**
MATERIAL LOCATION: **Room 101,102, 103**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**
COMMENTS:
Damage in Room 103

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **12" x 12" Sky Blue Floor Tile**

MATERIAL LOCATION: **Room 101,102, 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BULDING ID: **4110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Hughes School, Charles Evans** INSPECTION DATE: **5/25/2025**
ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **61**
MATERIAL DESCRIPTION: **12" x 12" Sky Blue Floor Tile Mastic**
MATERIAL LOCATION: **Room 101, 102, 103**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Sky Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 101, 102, 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Hughes School, Charles Evans** INSPECTION DATE: **5/25/2025**
ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **67**
MATERIAL DESCRIPTION: **4" x 4" Rust Colored Ceramic Tile and Grout**
MATERIAL LOCATION: **Kitchen**
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **4" x 4" Rust Colored Ceramic Tile and Grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Hughes School, Charles Evans** INSPECTION DATE: **5/25/2025**
ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **62**
MATERIAL DESCRIPTION: **12" x 12" Lt. Gray Mottle Floor Tile**
MATERIAL LOCATION: **Room 101, 102, 103**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **Damaged**
AHERA DAMAGE CATEGORY: **5 ACBM with potential for significant damage**
ACCESSIBILITY: **Within Reach** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**
COMMENTS:
Damage in Room 103

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Lt. Gray Mottle Floor Tile**

MATERIAL LOCATION: **Room 101, 102, 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	12" x 12" White w/ Dark Gray Streaks Floor Tile		
MATERIAL LOCATION:	Room 101, 102, 103		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	Damaged
AHERA DAMAGE CATEGORY:	5 ACBM with potential for significant damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	5	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:	Damage in Room 103		

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 101, 102, 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BULDING ID: **4110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Hughes School, Charles Evans** INSPECTION DATE: **5/25/2025**
ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **65**
MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic**
MATERIAL LOCATION: **Room 101, 102, 103**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **12" x 12" White w/ Dark Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 101, 102, 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Carol Ashman**
SCHOOL NAME: **Hughes School, Charles Evans** INSPECTION DATE: **5/25/2025**
ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **63**
MATERIAL DESCRIPTION: **12" x 12" Lt. Gray Mottle Floor Tile Mastic**
MATERIAL LOCATION: **Room 101, 102, 103**
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **MODERATE** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Date: **05/25/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Lt. Gray Mottle Floor Tile Mastic**

MATERIAL LOCATION: **Room 101, 102, 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/20/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	23901	BUIDLING ID:	4110
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Carol Ashman		
SCHOOL NAME:	Hughes School, Charles Evans	INSPECTION DATE:	5/25/2025		
ADDRESS:	4247 W. 15th St.	IDPH LICENSE NO:	100-19554		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	2" x 2" Light Beige Ceramic Tile and Grout		
MATERIAL LOCATION:	Room 101 and 103 Bathroom		
MATERIAL QUANTITY:	35	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/25/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **23901** BUIDLING ID: **4110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Hughes School, Charles Evans** REVIEW DATE: **6/20/2025**

ADDRESS: **4247 W. 15th St.** IDPH LICENSE NO: **100-19554**

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **2" x 2" Light Beige Ceramic Tile and Grout**

MATERIAL LOCATION: **Room 101 and 103 Bathroom**

MATERIAL QUANTITY: **35** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 06/20/2025

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Michael Serio

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed