

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2783
SCHOOL NAME: Cardenas School
ADDRESS OF SCHOOL: 2345 S. Millard
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 12/12/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/8/2025 ENROLLMENT 694
IDPH INSPECTOR LICENSE NUMBER: 100-03175
IDPH LICENSED INSPECTOR NAME (Please Print): Marcos Iwankiw
IDPH MP LICENSE NUMBER: 100-18488
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/4/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Cardenas School

2345 S. Millard
Chicago, IL, 60623

Unit: 24051
Building ID: 4320

IDPH ID Number: 14-016-2990-2783

REPORT DATE:
Wednesday, June 04, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/04/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24051 Region: 03 IDPH ID: 14-016-2990-2783

School: Cardenas School Building ID: 4320

Address: 2345 S. Millard

Chicago, IL, 60623

Building Contact: Flamm, Scott Contact Phone: 7083593941

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/8/2025

Review Date: 06/04/2025

Inspector: Marcos Iwankiw


Inspector IDPH License: 100-03175

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Mike Serio
100-18488

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 04, 2025

RE: Cardenas School, Unit 24051
2345 S. Millard
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Cardenas School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Cardenas School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Cardenas School Unit: 24051 Region: 03
Address: 2345 S. Millard Chicago, IL, 60623
IDPH ID: 14-016-2990-2783 Building ID: 4320
Contact: Flamm, Scott Phone: 7083593941

2. Description of Facility

Original Construction: 1972 Additional Construction:
Total Square Footage: 45270 No of Floors: 3
Current Occupancy: 694

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Marcos Iwankiw

Inspector IDPH license # 100-03175
Reinspection Date: 5/8/2025

Signature: 
Date: 5/8/2025

6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488

Signature: 
Date: 06/04/2025

7. Review Date: 06/04/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: 

Date: 6/4/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Cardenas School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4320:

14	12" x 12" White w/ Tan Streaks Floor Tile Mastic
16	12" x 12" Gray w/ Black Streaks Floor Tile Mastic
37	Wood Flooring
38	1' x 1' Ceiling Tile

B. The following new homogenous areas have been identified for Building 4320:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

012	Brown Carpet Mastic
013	12" x 12" White w/ Blue Streaks Floor Tile
014	12" x 12" White w/ Blue Streaks Floor Tile Adhesive
015	12" x 12" White w/ Gray Floor Tile
016	12" x 12" White w/ Gray Floor Tile Mastic
017	12" x 12" White w/ Light Brown Floor Tile
018	12" x 12" White w/ Light Brown Floor Tile Mastic
1	Plaster Walls
10	Window Caulk
11	12" x 12" White Floor Tile w/ Black Streaks
12	12" x 12" White Floor Tile w/ Black Streaks Mastic
13	12" x 12" White w/ Tan Streaks Floor Tile
14	12" x 12" White w/ Tan Streaks Floor Tile Mastic
15	12" x 12" Gray w/ Black Streaks Floor Tile
16	12" x 12" Gray w/ Black Streaks Floor Tile Mastic
17	12" x 12" Beige Mottled Floor Tile
18	12" x 12" Beige Mottled Floor Tile Mastic
19	12" x 12" White w/ Gray Streaks Floor Tile
2	Black Sink Undercoating
20	12" x 12" White w/ Gray Streaks Floor Tile Mastic
21	12" x 12" Tan w/ Black Streaks Floor Tile
22	12" x 12" Tan w/ Black Streaks Floor Tile Mastic
23	12" x 12" White w/ Tan Streaks Floor Tile
24	12" x 12" White w/ Tan Streaks Floor Tile Mastic
25	4" Black Vinyl Baseboard
26	4" Black Vinyl Baseboard Mastic
27	Brown Carpet Mastic
28	Chalkboard Adhesive
29	Stage Curtain
3	Expansion Joint Caulk
30	2' x 4' Smooth Ceiling Tile
31	2' x 4' Fissured Ceiling Tile
32	2' x 4' Pinhole Ceiling Tile
33	Partition Wall
34	Yellow Terrazzo
35	Lab Countertops
36	Reddish Window Caulk
37	Wood Flooring
38	1' x 1' Ceiling Tile
4	12" x 12" Beige Mottled Floor Tile
5	12" x 12" Beige Mottled Floor Tile Mastic

6	4" Brown Baseboard
7	4" Brown Baseboard Mastic
8	Light Brown Carpet Mastic
9	Vault Door Insulation
B	Mud Elbows on Drain Pipes

The following areas were deemed to be inaccessible:

005	12" x 12" Off White w/ Gray Floor Tile Mastic
014	12" x 12" White w/ Blue Streaks Floor Tile Adhesive
016	12" x 12" White w/ Gray Floor Tile Mastic
018	12" x 12" White w/ Light Brown Floor Tile Mastic
14	12" x 12" White w/ Tan Streaks Floor Tile Mastic
30	2' x 4' Smooth Ceiling Tile
31	2' x 4' Fissured Ceiling Tile
32	2' x 4' Pinhole Ceiling Tile
9	Vault Door Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Marcos Iwankiw, IDPH License # 100-03175. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Cardenas School Building 4320 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Cardenas School **Unit** 24051 **Building ID** 4320
Address 2345 S. Millard **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
002	2'x4' Patterned Ceiling Tiles			Throughout School	NO_ACBM	MISC								
003	2'x4' Plain Ceiling Tiles			Kitchen	NO_ACBM	MISC								
004	12" x 12" Off White w/ Gray Streak Floor Tile	16,320	SF	1st, 2nd and 3rd Floor Corridors, See Comments For Additional Locations	CHR	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
005	12" x 12" Off White w/ Gray Floor Tile Mastic	16,320	SF	1st, 2nd & 3rd Floor Corridors, See Comments For Additional Locations	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
006	Drywall			Throughout School	NO_ACBM	MISC								
007	Drywall Tape			Throughout School	NO_ACBM	MISC								
008	Baseboards			Throughout School	NO_ACBM	MISC								
009	Baseboard Mastic			Throughout School	NO_ACBM	MISC								
010	Interior Window Caulk			Throughout School	NO_ACBM	MISC								
011	Interior Door Caulk	144	LF	North, South, East, West, and Gym Exterior Doors	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
012	Brown Carpet Mastic	20,000	SF	Gym Off, Principal's Off, Rooms 100, 102,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
013	12" x 12" White w/ Blue Streaks Floor Tile	1,400	SF	2nd Floor Computer Room (Mdf Room) and Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
014	12" x 12" White w/ Blue Streaks Floor Tile Adhesive	1,400	SF	2nd Floor Computer Room (Mdf Room), Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
015	12" x 12" White w/ Gray Floor Tile	20,000	SF	Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge & Library	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
016	12" x 12" White w/ Gray Floor Tile Mastic	20,000	SF	Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge &	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Cardenas School **Unit** 24051 **Building ID** 4320
Address 2345 S. Millard **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Library										
017	12" x 12" White w/ Light Brown Floor Tile	7,780	SF	Rooms 105, 306 & Café	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
018	12" x 12" White w/ Light Brown Floor Tile Mastic	7,780	SF	Rooms 105, 306 & Café	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
1	Plaster Walls	2,500	SF	Throughout	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
10	Window Caulk	10	SF	Main Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
11	12" x 12" White Floor Tile w/ Black Streaks	150	SF	Teachers' Lounge	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
12	12" x 12" White Floor Tile w/ Black Streaks Mastic	150	SF	Teachers' Lounge	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
13	12" x 12" White w/ Tan Streaks Floor Tile	500	SF	Cafeteria, Room 212	ASSUMED	MISC	N	LOC	10	SF	No	ACBM with potential for significant damage	5	LOW
14	12" x 12" White w/ Tan Streaks Floor Tile Mastic	500	SF	Cafeteria, Room 212	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
15	12" x 12" Gray w/ Black Streaks Floor Tile	100	SF	Gym Storage	ASSUMED	MISC	N	LOC	10	SF	No	ACBM with potential for significant damage	5	LOW
16	12" x 12" Gray w/ Black Streaks Floor Tile Mastic	100	SF	Gym Storage	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
17	12" x 12" Beige Mottled Floor Tile	50	SF	Gym Storage	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
18	12" x 12" Beige Mottled Floor Tile Mastic	50	SF	Gym Storage	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
19	12" x 12" White w/ Gray Streaks Floor Tile	500	SF	Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
2	Black Sink Undercoating	2	SF	Room 103, 102	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
20	12" x 12" White w/ Gray Streaks Floor Tile Mastic	500	SF	Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
21	12" x 12" Tan w/ Black Streaks Floor Tile	1,500	SF	Hallways, Rooms	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Cardenas School **Unit** 24051 **Building ID** 4320
Address 2345 S. Millard **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				211 Closet, 312, 309 Closet, 307a, 303 Closet								potential for damage		
22	12" x 12" Tan w/ Black Streaks Floor Tile Mastic	1,500	SF	Hallways, Rooms 211 Closet, 312, 309 Closet, 307a, 303 Closet	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
23	12" x 12" White w/ Tan Streaks Floor Tile	200	SF	Room 306	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
24	12" x 12" White w/ Tan Streaks Floor Tile Mastic	200	SF	Room 306	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
25	4" Black Vinyl Baseboard	2,500	SF	Throughout	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
26	4" Black Vinyl Baseboard Mastic	2,500	SF	Throughout	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
27	Brown Carpet Mastic	100	SF	Gym Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
28	Chalkboard Adhesive	10	SF	Room 201, 308	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
29	Stage Curtain	250	SF	Gym	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
3	Expansion Joint Caulk	10	LF	Room 103	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
30	2' x 4' Smooth Ceiling Tile	308	SF	Room 202	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
31	2' x 4' Fissured Ceiling Tile	500	SF	Throughout	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
32	2' x 4' Pinhole Ceiling Tile	100	SF	Library	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
33	Partition Wall	500	SF	Room 105, 205, 208, 210, 211, 308	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
34	Yellow Terrazo	250	SF	North Stairs	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	Lab Countertops	20	SF	Room 310	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
36	Reddish Window Caulk	5	SF	Room 303	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
37	Wood Flooring	1,000	SF	Gym, 301, 302, 304, 306, 307, 309, 312, 310, 203, 209, 206, 207, 205, 204, 202,	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW

Chicago Public Schools

School Cardenas School **Unit** 24051 **Building ID** 4320
Address 2345 S. Millard **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				201, 102, 103, 105, 107, 109										
38	1' x 1' Ceiling Tile	6	SF	Room 402	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
4	12" x 12" Beige Mottled Floor Tile	250	SF	Room 105	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
5	12" x 12" Beige Mottled Floor Tile Mastic	250	SF	Room 105	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
6	4" Brown Baseboard	100	SF	Room 105	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
7	4" Brown Baseboard Mastic	100	SF	Room 105	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
8	Light Brown Carpet Mastic	100	SF	Principal's Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
9	Vault Door Insulation	12	SF	Main Office	ASSUMED	TSI	N	NONE			No	ACBM with the potential for damage		LOW
A	Cement Elbows on TSI			Throughout School	NO_ACBM	TSI								
B	Mud Elbows on Drain Pipes	5	LF	Gym	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Cardenas School Unit 24051 Building ID 4320
Address 2345 S. Millard Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>5/8/2025</u>
Inspector Name	<u>Marcos Iwankiw</u>
100-03175	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
002	
003	
004	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
1	
10	
11	
12	
13	Damage in cafeteria
14	
15	Damage in gym storage

Chicago Public Schools

School Cardenas School **Unit** 24051 **Building ID** 4320
Address 2345 S. Millard **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
4	
5	
6	
7	

Chicago Public Schools

School Cardenas School **Unit** 24051 **Building ID** 4320
Address 2345 S. Millard **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
8	
9	
A	
B	

Table II
Management Planner's Review

Chicago Public Schools

School Cardenas School

Unit 24051

Building ID 4320

Address 2345 S. Millard

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
002	2'x4' Patterned Ceiling Tiles			Throughout School	No ACBM	MISC					
003	2'x4' Plain Ceiling Tiles			Kitchen	No ACBM	MISC					
004	12" x 12" Off White w/ Gray Streak Floor Tile	16,320	SF	1st, 2nd and 3rd Floor Corridors, See Comments For Additional Locations	Chrysotile	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
005	12" x 12" Off White w/ Gray Floor Tile Mastic	16,320	SF	1st, 2nd & 3rd Floor Corridors, See Comments For Additional Locations	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
006	Drywall			Throughout School	No ACBM	MISC					
007	Drywall Tape			Throughout School	No ACBM	MISC					
008	Baseboards			Throughout School	No ACBM	MISC					
009	Baseboard Mastic			Throughout School	No ACBM	MISC					
010	Interior Window Caulk			Throughout School	No ACBM	MISC					
011	Interior Door Caulk	144	LF	North, South, East, West, and Gym Exterior Doors	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
012	Brown Carpet Mastic	20,000	SF	Gym Off, Principal's Off, Rooms 100, 102,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
013	12" x 12" White w/ Blue Streaks Floor Tile	1,400	SF	2nd Floor Computer Room (Mdf Room) and Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
014	12" x 12" White w/ Blue Streaks Floor Tile Adhesive	1,400	SF	2nd Floor Computer Room (Mdf Room), Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
015	12" x 12" White w/ Gray Floor Tile	20,000	SF	Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge & Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
016	12" x 12" White w/ Gray Floor Tile Mastic	20,000	SF	Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge & Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
017	12" x 12" White w/ Light Brown Floor Tile	7,780	SF	Rooms 105, 306 & Café	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
018	12" x 12" White w/ Light Brown Floor Tile Mastic	7,780	SF	Rooms 105, 306 & Café	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
1	Plaster Walls	2,500	SF	Throughout	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Window Caulk	10	SF	Main Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12" x 12" White Floor Tile w/ Black Streaks	150	SF	Teachers' Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12" x 12" White Floor Tile w/ Black Streaks Mastic	150	SF	Teachers' Lounge	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12" x 12" White w/ Tan Streaks Floor Tile	500	SF	Cafeteria, Room 212	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
14	12" x 12" White w/ Tan Streaks Floor Tile Mastic	500	SF	Cafeteria, Room 212	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Cardenas School

Unit 24051

Building ID 4320

Address 2345 S. Millard

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
15	12" x 12" Gray w/ Black Streaks Floor Tile	100	SF	Gym Storage	Assumed	MISC	No	10	SF	5 ACBM with potential for significant damage	Remove
16	12" x 12" Gray w/ Black Streaks Floor Tile Mastic	100	SF	Gym Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12" x 12" Beige Mottled Floor Tile	50	SF	Gym Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12" x 12" Beige Mottled Floor Tile Mastic	50	SF	Gym Storage	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12" x 12" White w/ Gray Streaks Floor Tile	500	SF	Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2	Black Sink Undercoating	2	SF	Room 103, 102	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12" x 12" White w/ Gray Streaks Floor Tile Mastic	500	SF	Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12" x 12" Tan w/ Black Streaks Floor Tile	1,500	SF	Hallways, Rooms 211 Closet, 312, 309 Closet, 307a, 303 Closet	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Tan w/ Black Streaks Floor Tile Mastic	1,500	SF	Hallways, Rooms 211 Closet, 312, 309 Closet, 307a, 303 Closet	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12" x 12" White w/ Tan Streaks Floor Tile	200	SF	Room 306	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12" x 12" White w/ Tan Streaks Floor Tile Mastic	200	SF	Room 306	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
25	4" Black Vinyl Baseboard	2,500	SF	Throughout	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	4" Black Vinyl Baseboard Mastic	2,500	SF	Throughout	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Brown Carpet Mastic	100	SF	Gym Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Chalkboard Adhesive	10	SF	Room 201, 308	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	Stage Curtain	250	SF	Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3	Expansion Joint Caulk	10	LF	Room 103	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
30	2' x 4' Smooth Ceiling Tile	308	SF	Room 202	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
31	2' x 4' Fissured Ceiling Tile	500	SF	Throughout	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
32	2' x 4' Pinhole Ceiling Tile	100	SF	Library	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
33	Partition Wall	500	SF	Room 105, 205, 208, 210, 211, 308	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Yellow Terrazo	250	SF	North Stairs	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Lab Countertops	20	SF	Room 310	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Reddish Window Caulk	5	SF	Room 303	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Cardenas School

Unit 24051

Building ID 4320

Address 2345 S. Millard

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
37	Wood Flooring	1,000	SF	Gym, 301, 302, 304, 306, 307, 309, 312, 310, 203, 209, 206, 207, 205, 204, 202, 201, 102, 103, 105, 107, 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	1' x 1' Ceiling Tile	6	SF	Room 402	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
4	12" x 12" Beige Mottled Floor Tile	250	SF	Room 105	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	12" x 12" Beige Mottled Floor Tile Mastic	250	SF	Room 105	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	4" Brown Baseboard	100	SF	Room 105	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	4" Brown Baseboard Mastic	100	SF	Room 105	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8	Light Brown Carpet Mastic	100	SF	Principal's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9	Vault Door Insulation	12	SF	Main Office	Assumed	TSI	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Cement Elbows on TSI			Throughout School	No ACBM	TSI					
B	Mud Elbows on Drain Pipes	5	LF	Gym	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Cardenas School

Unit 24051

Building ID 4320

Address 2345 S. Millard

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	6/4/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
002	Non-AHERA
003	Non-AHERA
004	
005	
006	Non-AHERA
007	Non-AHERA
008	Non-AHERA
009	Non-AHERA
010	Non-AHERA
011	
012	
013	Sample to determine ACM content prior to disturbance.
014	
015	
016	
017	
018	
1	
10	
11	
12	
13	Sample to determine ACM content, remove or repair to intact.

Chicago Public Schools

School Cardenas School

Unit 24051

Building ID 4320

Address 2345 S. Millard

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
14	
15	Sample to determine ACM content, remove or repair to intact.
16	
17	
18	
19	
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	

Chicago Public Schools

School Cardenas School

Unit 24051

Building ID 4320

Address 2345 S. Millard

Chicago, IL, 60623

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
4	
5	
6	
7	
8	
9	
A	Non-AHERA
B	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **2'x4' Patterned Ceiling Tiles**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **2'x4' Patterned Ceiling Tiles**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 003

MATERIAL DESCRIPTION: 2'x4' Plain Ceiling Tiles

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Kitchen

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **003**

MATERIAL DESCRIPTION: **2'x4' Plain Ceiling Tiles**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	004		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Gray Streak Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridors, See Comments For Additional Locations		
MATERIAL QUANTITY:	16320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **004**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Gray Streak Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridors, See Comments For Additional Locations**

MATERIAL QUANTITY: **16320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	005		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd & 3rd Floor Corridors, See Comments For Additional Locations		
MATERIAL QUANTITY:	16320	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **005**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Gray Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd & 3rd Floor Corridors, See Comments For Additional Locations**

MATERIAL QUANTITY: **16320** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 006
MATERIAL DESCRIPTION: Drywall
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **006**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 007

MATERIAL DESCRIPTION: Drywall Tape

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **007**

MATERIAL DESCRIPTION: **Drywall Tape**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 008

MATERIAL DESCRIPTION: Baseboards

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **008**

MATERIAL DESCRIPTION: **Baseboards**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 009

MATERIAL DESCRIPTION: Baseboard Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **009**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 010

MATERIAL DESCRIPTION: Interior Window Caulk

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	011		
MATERIAL DESCRIPTION:	Interior Door Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North, South, East, West, and Gym Exterior Doors		
MATERIAL QUANTITY:	144	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **Interior Door Caulk**

MATERIAL LOCATION: **North, South, East, West, and Gym Exterior Doors**

MATERIAL QUANTITY: **144** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	012		
MATERIAL DESCRIPTION:	Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Off, Principal's Off, Rooms 100, 102,		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **012**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Gym Off, Principal's Off, Rooms 100, 102,**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	013		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Computer Room (Mdf Room) and Office		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **013**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile**

MATERIAL LOCATION: **2nd Floor Computer Room (Mdf Room) and Office**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	014		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue Streaks Floor Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Computer Room (Mdf Room), Office		
MATERIAL QUANTITY:	1400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **014**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue Streaks Floor Tile Adhesive**

MATERIAL LOCATION: **2nd Floor Computer Room (Mdf Room), Office**

MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	015		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge & Library**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **015**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Floor Tile**

MATERIAL LOCATION: **Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge & Library**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	016		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge & Library**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 102, 104, 201, 202, 203, 205, 207, 208, 210, 211, 301, 302, 303, 304, 305, 307, 308, 309, 310, Office, Teachers' Lounge & Library**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	017		
MATERIAL DESCRIPTION:	12" x 12" White w/ Light Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105, 306 & Café		
MATERIAL QUANTITY:	7780	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **017**

MATERIAL DESCRIPTION: **12" x 12" White w/ Light Brown Floor Tile**

MATERIAL LOCATION: **Rooms 105, 306 & Café**

MATERIAL QUANTITY: **7780** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	018		
MATERIAL DESCRIPTION:	12" x 12" White w/ Light Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 105, 306 & Café		
MATERIAL QUANTITY:	7780	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **018**

MATERIAL DESCRIPTION: **12" x 12" White w/ Light Brown Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 105, 306 & Café**

MATERIAL QUANTITY: **7780** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	Plaster Walls		
HISTORICAL AHERA DAMAGE CATEGORY	6 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **2500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile w/ Black Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers' Lounge		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Black Streaks**

MATERIAL LOCATION: **Teachers' Lounge**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile w/ Black Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers' Lounge		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Black Streaks Mastic**

MATERIAL LOCATION: **Teachers' Lounge**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Room 212		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in cafeteria		

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streaks Floor Tile**

MATERIAL LOCATION: **Cafeteria, Room 212**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Cafeteria, Room 212		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	SF		
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Cafeteria, Room 212**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Storage		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in gym storage		

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Streaks Floor Tile**

MATERIAL LOCATION: **Gym Storage**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content, remove or repair to intact.

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Black Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Storage		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Gym Storage**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12" x 12" Beige Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Storage		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile**

MATERIAL LOCATION: **Gym Storage**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12" x 12" Beige Mottled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Storage		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Gym Storage**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2		
MATERIAL DESCRIPTION:	Black Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103, 102		
MATERIAL QUANTITY:	2	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **Black Sink Undercoating**

MATERIAL LOCATION: **Room 103, 102**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Rooms 201, 202, 203, 205, 208, 207, 210, 211, 309, 310, 307, 308, 305, 303, 304, 302, 300, 301, Patches in 1st Floor Classrooms**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Black Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, Rooms 211 Closet, 312, 309 Closet, 307a, 303 Closet		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black Streaks Floor Tile**

MATERIAL LOCATION: **Hallways, Rooms 211 Closet, 312, 309 Closet, 307a, 303 Closet**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12" x 12" Tan w/ Black Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Hallways, Rooms 211 Closet, 312, 309 Closet, 307a, 303 Closet		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Hallways, Rooms 211 Closet, 312, 309 Closet, 307a, 303 Closet**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 306		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streaks Floor Tile**

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12" x 12" White w/ Tan Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 306		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12" x 12" White w/ Tan Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 306**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Gym Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	Chalkboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201, 308		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Chalkboard Adhesive**

MATERIAL LOCATION: **Room 201, 308**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	Stage Curtain		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Stage Curtain**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3		
MATERIAL DESCRIPTION:	Expansion Joint Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Expansion Joint Caulk**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	2' x 4' Smooth Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**

MATERIAL LOCATION: **Room 202**

MATERIAL QUANTITY: **308** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	2' x 4' Fissured Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **2' x 4' Fissured Ceiling Tile**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	2' x 4' Pinhole Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **2' x 4' Pinhole Ceiling Tile**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Partition Wall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105, 205, 208, 210, 211, 308		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Partition Wall**

MATERIAL LOCATION: **Room 105, 205, 208, 210, 211, 308**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Yellow Terrazo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	North Stairs		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Yellow Terrazo**

MATERIAL LOCATION: **North Stairs**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	Lab Countertops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 310		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Lab Countertops**

MATERIAL LOCATION: **Room 310**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	Reddish Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 303		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Reddish Window Caulk**

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Wood Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Gym, 301, 302, 304, 306, 307, 309, 312, 310, 203, 209, 206, 207, 205, 204, 202, 201, 102, 103, 105, 107, 109**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Wood Flooring**

MATERIAL LOCATION: **Gym, 301, 302, 304, 306, 307, 309, 312, 310, 203, 209, 206, 207, 205, 204, 202, 201, 102, 103, 105, 107, 109**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 402		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **Room 402**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	12" x 12" Beige Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	12" x 12" Beige Mottled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **12" x 12" Beige Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6		
MATERIAL DESCRIPTION:	4" Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **4" Brown Baseboard**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7		
MATERIAL DESCRIPTION:	4" Brown Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **4" Brown Baseboard Mastic**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8		
MATERIAL DESCRIPTION:	Light Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Light Brown Carpet Mastic**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9		
MATERIAL DESCRIPTION:	Vault Door Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	12	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Vault Door Insulation**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 06/04/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: Cement Elbows on TSI

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout School

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUILDING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Cement Elbows on TSI**

MATERIAL LOCATION: **Throughout School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Marcos Iwankiw		
SCHOOL NAME:	Cardenas School	INSPECTION DATE:	5/8/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Mud Elbows on Drain Pipes		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24051	BUIDLING ID:	4320
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cardenas School	REVIEW DATE:	6/4/2025		
ADDRESS:	2345 S. Millard	IDPH LICENSE NO:	100-03175		

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Mud Elbows on Drain Pipes**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **06/04/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Marcos Iwankiw

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2410112747
Course Date: 10/11/2024
Exam Date: 10/11/2024
Expiration Date: 10/11/2025




Issue Date: 10/11/2024


Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

Marcos Iwankiw

Illinois Licensed Building Inspector, Air Sampling Professional, Asbestos Project Manager



ENDORSEMENTS

INSPECTOR

TC EXPIRES

10/11/2025

PROJECT MANAGER
AIR SAMPLING PROFESSIONAL

1/2/2026

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.





OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Michael Serio

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed