

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2819  
SCHOOL NAME: Mason School CPC  
ADDRESS OF SCHOOL: 4216 W. 19th Street  
CITY: Chicago, IL, 60623

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/27/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/17/2025 ENROLLMENT 235  
IDPH INSPECTOR LICENSE NUMBER: 100-20994  
IDPH LICENSED INSPECTOR NAME (Please Print): Cody Cummins  
IDPH MP LICENSE NUMBER: 100-18488  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

 5/16/2025  
Richard J. Schleyer  
Signature of Designated Person Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Mason School CPC**

4216 W. 19th Street  
Chicago, IL, 60623

Unit: 24381  
Building ID: 4651

IDPH ID Number: 14-016-2990-2819

**REPORT DATE:**  
Friday, May 16, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

05/16/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 24382      Region: 03      IDPH ID: 14-016-2990-2819

School: Mason School CPC      Building ID: 4651

Address: 4216 W. 19th Street

Chicago, IL, 60623

Building Contact:      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/17/2025

Review Date: 05/16/2025

Inspector: Cody Cummins

Inspector IDPH License: 100-20994

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Mike Serio  
100-18488

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: May 16, 2025

RE: Mason School CPC, Unit 24381  
4216 W. 19th Street  
Chicago, IL, 60623

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Mason School CPC , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Mason School CPC, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Mason School CPC      Unit: 24382      Region: 03  
Address: 4216 W. 19th Street      Chicago, IL, 60623  
IDPH ID: 14-016-2990-2819      Building ID: 4651  
Contact:      Phone:

### 2. Description of Facility

Original Construction:      Additional Construction:  
Total Square Footage:      No of Floors:  
Current Occupancy: 235

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Cody Cummins



Signature:  
Date: 4/17/2025

### 6. Management Planner

Management Planner Name: Mike Serio



Signature:  
Date: 05/16/2025

### 7. Review Date: 05/16/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/16/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Mason School CPC. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 4651:

13	9" x 9" Dark Green w/ White Specks Floor Tile
18	Multi-Brown Carpet Mastic
19	Plaster Walls
21	Textured Ceiling Plaster, 12" x 12" Ceiling Tile w/ Grooves
24	Blue Carpet Mastic
27	12" x 12" Off-White w/ Gold Streaks Floor Tile
3	9" x 9" Dark Brown w/ White Streaks Floor Tile
30	12" x 12" Taupe w/ White Specks Floor Tile Mastic
41	9" x 9" Multi-Beige Floor Tile

42 9" x 9" Multi-Beige Floor Tile Mastic

43 9" x 9" Light Brown w/ White & Brown Streaks Floor Tile

44 9" x 9" Light Brown w/ White & Brown Streaks Floor Tile Mastic

5 9" x 9" Mint Green w/ Dark Green Streaks Floor Tile

65 Brown & Purple Carpet Mastic

67 4" Black Vinyl Baseboard and Adhesive

68 4" Black Vinyl Baseboard and Adhesive

70 12" x 12" White w/ Blue/Gray Specks Floor Tile

71 12" x 12" White w/ Blue/Gray Specks Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 4651:

79	12" x 12" Blue/Green Mottled Floor Tile
80	12" x 12" Blue/Green Mottled Floor Tile Mastic
81	9" x 9" Red Floor Tile w/ White Streaks
82	9" x 9" Red Floor Tile w/ White Streaks Mastic
83	9" x 9" Gray w/ Black & Beige Streaks Floor Tile
84	9" x 9" Gray w/ Black & Beige Streaks Floor Tile Mastic
85	9 " x 9 " Beige w/ Black Streaks
86	9" x 9" Beige w/ Black Streaks Mastic
87	12" x 12" Blue w/ Blue & White Streaks Floor Tile
88	12" x 12" Blue w/ Blue & White Streaks Floor Tile Mastic
89	12" x 12" Light Blue Mottled Floor Tile
90	12" x 12" Light Blue Mottled Floor Tile Mastic
91	2' x 2' White Ceiling Tile w/ Pinholes
92	Blue/Green Carpet Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

13	9" x 9" Dark Green w/ White Specks Floor Tile
17	Green and Black Terrazzo Stairs 1963 Building
18	Multi-Brown Carpet Mastic
19	Plaster Walls
21	Textured Ceiling Plaster, 12" x 12" Ceiling Tile w/ Grooves
22	Interior Window Glaze
23	Finished Brick Mortar
24	Blue Carpet Mastic
25	Interior Window Caulk
26	Green Carpet Mastic
27	12" x 12" Off-White w/ Gold Streaks Floor Tile
28	12" x 12" Off-White w/ Gold Streaks Floor Tile Mastic
29	12" x 12" Taupe w/ White Specks Floor Tile
30	12" x 12" Taupe w/ White Specks Floor Tile Mastic
41	9" x 9" Multi-Beige Floor Tile
42	9" x 9" Multi-Beige Floor Tile Mastic
43	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile
45	9" x 9" Light Brown w/ Brown Splash Floor Tile
47	9" x 9" Tan w/ White & Black Streaks Floor Tile
49	9" x 9" Olive Green w/ White Streaks Floor Tile
51	9" x 9" Multi-Gray Floor Tile
53	2' x 4' Ceiling Tile w/ Small Fissures
54	Rose Carpet Mastic
55	Exterior Window Caulk - Non-AHERA
56	Exterior Door Caulk - Non-AHERA
57	Exterior Brick Mortar - Non-AHERA
58	Multi-Brown Ceramic Floor Tile Grout
59	Brown and Beige Ceramic Floor Tile Grout
60	Multi-Blue Ceramic Tile Grout
61	Roofing Material - Non-AHERA
62	Wine w/ Yellow Spots Carpet Mastic
63	Purple Carpet Mastic
64	Insulation Inside Of Vault Door
65	Brown & Purple Carpet Mastic
66	Brown Carpet Mastic
67	4" Black Vinyl Baseboard and Adhesive
68	4" Black Vinyl Baseboard and Adhesive
70	12" x 12" White w/ Blue/Gray Specks Floor Tile
71	12" x 12" White w/ Blue/Gray Specks Floor Tile

	Mastic
72	Black/Brown Terrazzo
73	Carpet Mastic
74	White/Blue Ceramic Grout
75	12" x 12" Tan/Beige Floor Tile
75M	12" x 12" Tan/Beige Floor Tile Mastic
76	12" x 12" Blue/White Floor Tile
76M	12" x 12" Blue/White Floor Tile Mastic
77	12" x 12" Brown Floor Tile
77M	12" x 12" Brown Floor Tile Mastic
78	12" x 12" White w/ Black Spec's Floor Tile
78M	12" x 12" White w/ Black Spec's Floor Tile Mastic
79	12" x 12" Blue/Green Mottled Floor Tile
80	12" x 12" Blue/Green Mottled Floor Tile Mastic
81	9" x 9" Red Floor Tile w/ White Streaks
82	9" x 9" Red Floor Tile w/ White Streaks Mastic
83	9" x 9" Gray w/ Black & Beige Streaks Floor Tile
84	9" x 9" Gray w/ Black & Beige Streaks Floor Tile Mastic
85	9 " x 9 " Beige w/ Black Streaks
86	9" x 9" Beige w/ Black Streaks Mastic
87	12" x 12" Blue w/ Blue & White Streaks Floor Tile
88	12" x 12" Blue w/ Blue & White Streaks Floor Tile Mastic
89	12" x 12" Light Blue Mottled Floor Tile
90	12" x 12" Light Blue Mottled Floor Tile Mastic
91	2' x 2' White Ceiling Tile w/ Pinholes
92	Blue/Green Carpet Mastic

The following areas were deemed to be inaccessible:

10	9" x 9" Tan w/ Light Brown Specks Floor Tile Mastic
12	9" x 9" Black w/ White Specks Floor Tile Mastic
14	9" x 9" Dark Green Floor Tile w/ White Specks Mastic
16	9" x 9" Lime Green w/ White Specks Floor Tile Mastic
18	Multi-Brown Carpet Mastic
2	9" x 9" Beige w/ Brown & White Streaks Floor Tile Mastic
23	Finished Brick Mortar
24	Blue Carpet Mastic
28	12" x 12" Off-White w/ Gold Streaks Floor Tile Mastic
30	12" x 12" Taupe w/ White Specks Floor Tile Mastic

32	9" x 9" Light Gray w/ White Streaks Floor Tile Mastic
34	12" x 3" Black Border Tile Mastic
36	9" x 9" Med. Gray w/ White Streaks Floor Tile Mastic
38	9" x 9" Brown w/ White Specks Floor Tile Mastic
4	9" x 9" Dark Brown w/ White Streaks Floor Tile Mastic
40	9" x 9" Light Gray w/ White & Brown Specks Floor Tile Mastic
42	9" x 9" Multi-Beige Floor Tile Mastic
44	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile Mastic
46	9" x 9" Light Brown w/ Brown Splash Floor Tile Mastic
48	9" x 9" Tan w/ White & Black Streaks Floor Tile Mastic
50	9" x 9" Olive Green w/ White Streaks Floor Tile Mastic
52	9" x 9" Multi-Gray Floor Tile Mastic
6	9" x 9" Mint Green w/ Dark Green Streaks Floor Tile Mastic
60	Multi-Blue Ceramic Tile Grout
64	Insulation Inside Of Vault Door
65	Brown & Purple Carpet Mastic
7	9" x 9" Choc w/ White & Orange Streaks Floor Tile
71	12" x 12" White w/ Blue/Gray Specks Floor Tile Mastic
73	Carpet Mastic
75M	12" x 12" Tan/Beige Floor Tile Mastic
76M	12" x 12" Blue/White Floor Tile Mastic
77M	12" x 12" Brown Floor Tile Mastic
78M	12" x 12" White w/ Black Spec's Floor Tile Mastic
8	9" x 9" Choc w/ White & Orange Streaks Floor Tile Mastic
80	12" x 12" Blue/Green Mottled Floor Tile Mastic
82	9" x 9" Red Floor Tile w/ White Streaks Mastic
84	9" x 9" Gray w/ Black & Beige Streaks Floor Tile Mastic
86	9" x 9" Beige w/ Black Streaks Mastic
88	12" x 12" Blue w/ Blue & White Streaks Floor Tile Mastic
90	12" x 12" Light Blue Mottled Floor Tile Mastic
92	Blue/Green Carpet Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Cody Cummins, IDPH License # 100-20994. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Mason School CPC Building 4651 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	9" x 9" Beige w/ Brown & White Streaks Floor Tile	15,000	SF	Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
10	9" x 9" Tan w/ Light Brown Specks Floor Tile Mastic	1,000	SF	1st, 2nd and 3rd Floor Corridor	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
11	9" x 9" Black w/ White Specks Floor Tile	200	SF	1st, 2nd and 3rd Floor Corridor	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
12	9" x 9" Black w/ White Specks Floor Tile Mastic	200	SF	1st, 2nd and 3rd Floor Corridor	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
13	9" x 9" Dark Green w/ White Specks Floor Tile	3,500	SF	1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
14	9" x 9" Dark Green Floor Tile w/ White Specks Mastic	3,500	SF	1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
15	9" x 9" Lime Green w/ White Specks Floor Tile	300	SF	1st, 2nd and 3rd Floor Corridor-1963 Building	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16	9" x 9" Lime Green w/ White Specks Floor Tile Mastic	300	SF	1st, 2nd and 3rd Floor Corridor-1963 Building	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	Green and Black Terrazzo Stairs 1963 Building	7,000	SF	First Through Third Floor Stairwells	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
18	Multi-Brown Carpet Mastic	800	SF	Assistant Principal's Second Floor Office	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
19	Plaster Walls	30,000	SF	Throughout Facility, 3rd Floor West Stairwell, Room 152, Assistant Principal Office, 2nd	ASSUMED	SURFACE	Y	LOC	105	SF	Yes	Significantly damaged friable surfacing ACBM	5	LOW

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
2	9" x 9" Beige w/ Brown & White Streaks Floor Tile Mastic	15,000	SF	Floor Facility Room, Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
20	Cinder Block Mortar	200	SF	2nd Floor Janitors Closet	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
21	Textured Ceiling Plaster, 12" x 12" Ceiling Tile w/ Grooves	45,000	SF	Throughout Corridors and Classrooms	ASSUMED	MISC	Y	NONE			Yes	Any remaining friable ACBM or friable suspect ACBM		MODERATE
22	Interior Window Glaze			Throughout Facility	ASSUMED	MISC					No			
23	Finished Brick Mortar	40,000	SF	Throughout Facility	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
24	Blue Carpet Mastic	1,080	SF	Room 247	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
25	Interior Window Caulk			Throughout Facility	ASSUMED	MISC					No			
26	Green Carpet Mastic			Main Office	ASSUMED	MISC					No			
27	12" x 12" Off-White w/ Gold Streaks Floor Tile	6,420	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
28	12" x 12" Off-White w/ Gold Streaks Floor Tile Mastic	6,420	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
29	12" x 12" Taupe w/ White Specks Floor Tile	1,000	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
3	9" x 9" Dark Brown w/ White Streaks Floor Tile	1,600	SF	2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
30	12" x 12" Taupe w/ White Specks Floor Tile Mastic	1,000	SF	1st Floor Corridor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
31	9" x 9" Light Gray w/ White Streaks Floor Tile	2,200	SF	Gym	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
32	9" x 9" Light Gray w/ White Streaks Floor Tile Mastic	2,200	SF	Gym	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
33	12" x 3" Black Border Tile	200	LF	Gym	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
34	12" x 3" Black Border Tile Mastic	200	LF	Gym	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	9" x 9" Med. Gray w/ White Streaks Floor Tile	30	SF	Gym	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
36	9" x 9" Med. Gray w/ White Streaks Floor Tile Mastic	30	SF	Gym	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
37	9" x 9" Brown w/ White Specks Floor Tile	3,100	SF	Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
38	9" x 9" Brown w/ White Specks Floor Tile Mastic	3,100	SF	Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
39	9" x 9" Light Gray w/ White & Brown Specks Floor Tile	3,100	SF	Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
4	9" x 9" Dark Brown w/ White Streaks Floor Tile Mastic	1,600	SF	2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
40	9" x 9" Light Gray w/ White & Brown Specks Floor Tile Mastic	3,100	SF	Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
41	9" x 9" Multi-Beige Floor Tile	200	SF	Lunchroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
42	9" x 9" Multi-Beige Floor Tile Mastic	200	SF	Lunchroom	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
43	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile	2,000	SF	Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
44	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile Mastic	2,000	SF	Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320	CHR	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
45	9" x 9" Light Brown w/ Brown Splash Floor Tile	200	SF	Lunchroom & Teachers' Lunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
46	9" x 9" Light Brown w/ Brown Splash Floor Tile Mastic	200	SF	Lunchroom & Teachers' Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
47	9" x 9" Tan w/ White & Black Streaks	2,000	SF	Lunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile			(1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317								potential for damage		
48	9" x 9" Tan w/ White & Black Streaks Floor Tile Mastic	2,000	SF	Lunchroom (1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
49	9" x 9" Olive Green w/ White Streaks Floor Tile	200	SF	Lunchroom & Teachers' Lunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
5	9" x 9" Mint Green w/ Dark Green Streaks Floor Tile	3,600	SF	2nd and 3rd Floor Corridor-1963 Building, 123 (office), 131, 225, 217, 325	CHR	MISC	N	LOC	12	SF	Yes	ACBM with the potential for damage	5	LOW
50	9" x 9" Olive Green w/ White Streaks Floor Tile Mastic	200	SF	Lunchroom & Teachers' Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
51	9" x 9" Multi-Gray Floor Tile	200	SF	Lunchroom & Teachers' Lunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
52	9" x 9" Multi-Gray Floor Tile Mastic	200	SF	Lunchroom & Teachers' Lunchroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
53	2' x 4' Ceiling Tile w/ Small Fissures	2,500	SF	Lunchroom & Teachers' Lunchroom	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
54	Rose Carpet Mastic			Room 149, Library	ASSUMED	MISC					No			
55	Exterior Window Caulk - Non-AHERA			Exterior of Building	ASSUMED	MISC								
56	Exterior Door Caulk - Non-AHERA			Exterior of Building	ASSUMED	MISC								
57	Exterior Brick Mortar - Non-AHERA			Exterior of Building	ASSUMED	MISC								
58	Multi-Brown Ceramic Floor Tile Grout	300	SF	2nd and 3rd Floor Girls Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
59	Brown and Beige Ceramic Floor Tile Grout	1,500	SF	1st, 2nd and 3rd Floor Boys Bathroom, 1st Floor Girls Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
6	9" x 9" Mint Green w/ Dark Green Streaks Floor Tile Mastic	3,600	SF	2nd and 3rd Floor Corridor-1963 Building, 123	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(office), 131, 225, 217, 325										
60	Multi-Blue Ceramic Tile Grout	200	SF	1st Floor Lobby Floor & On Pillars	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
61	Roofing Material - Non-AHERA			Roof	ASSUMED	MISC								
62	Wine w/ Yellow Spots Carpet Mastic			Main Office	ASSUMED	MISC					No			
63	Purple Carpet Mastic	400	SF	Main Office and 148	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
64	Insulation Inside Of Vault Door	32	SF	Main Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
65	Brown & Purple Carpet Mastic	500	SF	Room 149	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
66	Brown Carpet Mastic			Assistant Principal's Office	ASSUMED	MISC					No			
67	4" Black Vinyl Baseboard and Adhesive			Classrooms	ASSUMED	MISC					Yes			
68	4" Black Vinyl Baseboard and Adhesive			Classrooms	ASSUMED	MISC					Yes			
7	9" x 9" Choc w/ White & Orange Streaks Floor Tile	200	SF	3rd Floor Corridor, 119A	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
70	12" x 12" White w/ Blue/Gray Specks Floor Tile	1,500	SF	Rooms 148, 117, 121, Lunchroom (1963/South Building)	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
71	12" x 12" White w/ Blue/Gray Specks Floor Tile Mastic	1,500	SF	Rooms 148, 117, 121, Lunchroom (1963/South Building)	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
72	Black/Brown Terrazzo	5,500	SF	1st Floor Entry and Corridor	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
73	Carpet Mastic	6,500	SF	Rooms 102, 103, 104 105, 114, 206, 150, Office, Storage Room, and Room 247	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
74	White/Blue Ceramic Grout	400	SF	At Entrance WomensLunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
75	12" x 12" Tan/Beige Floor Tile	3,000	SF	Rooms 307, 309, 147 and Main Office, Lunchroom, Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
75M	12" x 12" Tan/Beige Floor Tile Mastic	3,000	SF	Rooms 307, 309, 147 and Main Office, Lunchroom,	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147										
76	12" x 12" Blue/White Floor Tile	1,000	SF	Rooms 116, 151, 119	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
76M	12" x 12" Blue/White Floor Tile Mastic	1,000	SF	Rooms 116, 151, 119	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
77	12" x 12" Brown Floor Tile	3,100	SF	Lunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
77M	12" x 12" Brown Floor Tile Mastic	3,100	SF	Lunchroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
78	12" x 12" White w/ Black Spec's Floor Tile	500	SF	Room 148	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
78M	12" x 12" White w/ Black Spec's Floor Tile Mastic	500	SF	Room 148	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
79	12" x 12" Blue/Green Mottled Floor Tile	500	SF	Room 119	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
8	9" x 9" Choc w/ White & Orange Streaks Floor Tile Mastic	200	SF	3rd Floor Corridor, 119A	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
80	12" x 12" Blue/Green Mottled Floor Tile Mastic	500	SF	Room 119	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
81	9" x 9" Red Floor Tile w/ White Streaks	1,000	SF	Room 127, 227, 222, 219, 218, 327, 322, 319, 318	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
82	9" x 9" Red Floor Tile w/ White Streaks Mastic	1,000	SF	Room 127, 227, 222, 219, 218, 327, 322, 319, 318	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
83	9" x 9" Gray w/ Black & Beige Streaks Floor Tile	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
84	9" x 9" Gray w/ Black & Beige Streaks Floor Tile Mastic	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
85	9" x 9" Beige w/ Black Streaks	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
86	9" x 9" Beige w/ Black Streaks Mastic	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
87	12" x 12" Blue w/ Blue & White Streaks	800	SF	Room 149	ASSUMED	MISC	N	NONE				ACBM with the		LOW

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile											potential for damage		
88	12" x 12" Blue w/ Blue & White Streaks Floor Tile Mastic	800	SF	Room 149	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
89	12" x 12" Light Blue Mottled Floor Tile	750	SF	Room 150	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
9	9" x 9" Tan w/ Light Brown Specks Floor Tile	1,000	SF	1st, 2nd and 3rd Floor Corridor	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
90	12" x 12" Light Blue Mottled Floor Tile Mastic	750	SF	Room 150	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
91	2' x 2' White Ceiling Tile w/ Pinholes	2,000	SF	1st Floor Corridor, 149, 150, 151	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
92	Blue/Green Carpet Mastic	850	SF	Room 151	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW

# Chicago Public Schools

School Mason School CPC Unit 24382 Building ID 4651  
Address 4216 W. 19th Street Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>4/17/2025</u>
Inspector Name <u>Cody Cummins</u>
<u>100-20994</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	Dm 3rd Floor West Stairwell, Room 152, Assistant Principal Office, 2nd Floor Facility Room, Room 357
2	
20	
21	
22	Material not observed - 2025
23	
24	
25	Material not observed - 2025
26	Material not observed - 2025
27	
28	
29	
3	

# Chicago Public Schools

School Mason School CPC Unit 24382 Building ID 4651  
Address 4216 W. 19th Street Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	Damage in 2nd Floor Corridor
50	
51	
52	
53	
54	Material not observed - 2025
55	
56	

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
57	
58	
59	
6	
60	
61	
62	Material not observed - 2025
63	
64	
65	
66	Material not observed - 2025
67	Material not observed - 2025
68	Material not observed - 2025
7	
70	
71	
72	
73	
74	
75	
75M	
76	
76M	
77	
77M	
78	
78M	
79	
8	

# Chicago Public Schools

**School** Mason School CPC **Unit** 24382 **Building ID** 4651  
**Address** 4216 W. 19th Street **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
9	
90	
91	
92	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	9" x 9" Beige w/ Brown & White Streaks Floor Tile	15,000	SF	Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9" x 9" Tan w/ Light Brown Specks Floor Tile Mastic	1,000	SF	1st, 2nd and 3rd Floor Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	9" x 9" Black w/ White Specks Floor Tile	200	SF	1st, 2nd and 3rd Floor Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	9" x 9" Black w/ White Specks Floor Tile Mastic	200	SF	1st, 2nd and 3rd Floor Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13	9" x 9" Dark Green w/ White Specks Floor Tile	3,500	SF	1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
14	9" x 9" Dark Green Floor Tile w/ White Specks Mastic	3,500	SF	1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15	9" x 9" Lime Green w/ White Specks Floor Tile	300	SF	1st, 2nd and 3rd Floor Corridor-1963 Building	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9" x 9" Lime Green w/ White Specks Floor Tile Mastic	300	SF	1st, 2nd and 3rd Floor Corridor-1963 Building	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Green and Black Terrazzo Stairs 1963 Building	7,000	SF	First Through Third Floor Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Multi-Brown Carpet Mastic	800	SF	Assistant Principal's Second Floor Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Plaster Walls	30,000	SF	Throughout Facility, 3rd Floor West Stairwell, Room 152, Assistant Principal Office, 2nd Floor Facility Room,	Assumed	SURFACE	Yes	105	SF	3 Significantly damaged friable surfacing ACBM	Repair
2	9" x 9" Beige w/ Brown & White Streaks Floor Tile Mastic	15,000	SF	Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Cinder Block Mortar	200	SF	2nd Floor Janitors Closet	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Textured Ceiling Plaster, 12" x 12" Ceiling Tile w/	45,000	SF	Throughout Corridors and Classrooms	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable	Follow O&M Plan

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Grooves									suspect ACBM	
22	Interior Window Glaze			Throughout Facility	Assumed	MISC					
23	Finished Brick Mortar	40,000	SF	Throughout Facility	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Blue Carpet Mastic	1,080	SF	Room 247	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Interior Window Caulk			Throughout Facility	Assumed	MISC					
26	Green Carpet Mastic			Main Office	Assumed	MISC					
27	12" x 12" Off-White w/ Gold Streaks Floor Tile	6,420	SF	1st Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" Off-White w/ Gold Streaks Floor Tile Mastic	6,420	SF	1st Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Taupe w/ White Specks Floor Tile	1,000	SF	1st Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3	9" x 9" Dark Brown w/ White Streaks Floor Tile	1,600	SF	2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" Taupe w/ White Specks Floor Tile Mastic	1,000	SF	1st Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
31	9" x 9" Light Gray w/ White Streaks Floor Tile	2,200	SF	Gym	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
32	9" x 9" Light Gray w/ White Streaks Floor Tile Mastic	2,200	SF	Gym	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 3" Black Border Tile	200	LF	Gym	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
34	12" x 3" Black Border Tile Mastic	200	LF	Gym	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
35	9" x 9" Med. Gray w/ White Streaks Floor Tile	30	SF	Gym	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	9" x 9" Med. Gray w/ White Streaks Floor Tile Mastic	30	SF	Gym	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9" x 9" Brown w/ White Specks Floor Tile	3,100	SF	Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	9" x 9" Brown w/ White Specks Floor Tile Mastic	3,100	SF	Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
39	9" x 9" Light Gray w/ White & Brown Specks Floor Tile	3,100	SF	Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	9" x 9" Dark Brown w/ White Streaks Floor Tile Mastic	1,600	SF	2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	9" x 9" Light Gray w/ White & Brown Specks Floor Tile Mastic	3,100	SF	Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
41	9" x 9" Multi-Beige Floor Tile	200	SF	Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
42	9" x 9" Multi-Beige Floor Tile Mastic	200	SF	Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
43	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile	2,000	SF	Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
44	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile Mastic	2,000	SF	Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
45	9" x 9" Light Brown w/ Brown Splash Floor Tile	200	SF	Lunchroom & Teachers' Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
46	9" x 9" Light Brown w/ Brown Splash Floor Tile Mastic	200	SF	Lunchroom & Teachers' Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9" x 9" Tan w/ White & Black Streaks Floor Tile	2,000	SF	Lunchroom (1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
48	9" x 9" Tan w/ White & Black Streaks Floor Tile Mastic	2,000	SF	Lunchroom (1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
49	9" x 9" Olive Green w/ White Streaks Floor Tile	200	SF	Lunchroom & Teachers' Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	9" x 9" Mint Green w/ Dark Green Streaks Floor Tile	3,600	SF	2nd and 3rd Floor Corridor-1963 Building, 123 (office), 131, 225, 217, 325	Chrysotile	MISC	No	12	SF	6 ACBM with the potential for damage	Remove
50	9" x 9" Olive Green w/ White Streaks Floor Tile Mastic	200	SF	Lunchroom & Teachers' Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
51	9" x 9" Multi-Gray Floor Tile	200	SF	Lunchroom & Teachers' Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
52	9" x 9" Multi-Gray Floor Tile Mastic	200	SF	Lunchroom & Teachers' Lunchroom	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
53	2' x 4' Ceiling Tile w/ Small Fissures	2,500	SF	Lunchroom & Teachers' Lunchroom	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
54	Rose Carpet Mastic			Room 149, Library	Assumed	MISC					
55	Exterior Window Caulk - Non-AHERA			Exterior of Building	Assumed	MISC					
56	Exterior Door Caulk - Non-AHERA			Exterior of Building	Assumed	MISC					
57	Exterior Brick Mortar - Non-AHERA			Exterior of Building	Assumed	MISC					
58	Multi-Brown Ceramic Floor Tile Grout	300	SF	2nd and 3rd Floor Girls Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Brown and Beige Ceramic Floor Tile Grout	1,500	SF	1st, 2nd and 3rd Floor Boys Bathroom, 1st Floor Girls Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	9" x 9" Mint Green w/ Dark Green Streaks Floor Tile Mastic	3,600	SF	2nd and 3rd Floor Corridor-1963 Building, 123 (office), 131, 225, 217, 325	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
60	Multi-Blue Ceramic Tile Grout	200	SF	1st Floor Lobby Floor & On Pillars	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Roofing Material - Non-AHERA			Roof	Assumed	MISC					
62	Wine w/ Yellow Spots Carpet Mastic			Main Office	Assumed	MISC					
63	Purple Carpet Mastic	400	SF	Main Office and 148	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Insulation Inside Of Vault Door	32	SF	Main Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
65	Brown & Purple Carpet Mastic	500	SF	Room 149	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Brown Carpet Mastic			Assistant Principal's Office	Assumed	MISC					
67	4" Black Vinyl Baseboard and Adhesive			Classrooms	Assumed	MISC					
68	4" Black Vinyl Baseboard and Adhesive			Classrooms	Assumed	MISC					
7	9" x 9" Choc w/ White & Orange Streaks Floor Tile	200	SF	3rd Floor Corridor, 119A	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12" x 12" White w/ Blue/Gray Specks Floor Tile	1,500	SF	Rooms 148, 117, 121, Lunchroom (1963/South Building)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12" x 12" White w/ Blue/Gray Specks Floor Tile Mastic	1,500	SF	Rooms 148, 117, 121, Lunchroom (1963/South Building)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
72	Black/Brown Terrazzo	5,500	SF	1st Floor Entry and Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Carpet Mastic	6,500	SF	Rooms 102, 103, 104 105, 114, 206, 150, Office, Storage Room, and Room 247	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
74	White/Blue Ceramic Grout	400	SF	At Entrance WomensLunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" x 12" Tan/Beige Floor Tile	3,000	SF	Rooms 307, 309, 147 and Main Office, Lunchroom, Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
75M	12" x 12" Tan/Beige Floor Tile Mastic	3,000	SF	Rooms 307, 309, 147 and Main Office, Lunchroom, Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12" x 12" Blue/White Floor Tile	1,000	SF	Rooms 116, 151, 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
76M	12" x 12" Blue/White Floor Tile Mastic	1,000	SF	Rooms 116, 151, 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12" x 12" Brown Floor Tile	3,100	SF	Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
77M	12" x 12" Brown Floor Tile Mastic	3,100	SF	Lunchroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" White w/ Black Spec's Floor Tile	500	SF	Room 148	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
78M	12" x 12" White w/ Black Spec's Floor Tile Mastic	500	SF	Room 148	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12" x 12" Blue/Green Mottled Floor Tile	500	SF	Room 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
8	9" x 9" Choc w/ White & Orange Streaks Floor Tile Mastic	200	SF	3rd Floor Corridor, 119A	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
80	12" x 12" Blue/Green Mottled Floor Tile Mastic	500	SF	Room 119	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
81	9" x 9" Red Floor Tile w/ White Streaks	1,000	SF	Room 127, 227, 222, 219, 218, 327, 322, 319, 318	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
82	9" x 9" Red Floor Tile w/ White Streaks Mastic	1,000	SF	Room 127, 227, 222, 219, 218, 327, 322, 319, 318	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
83	9" x 9" Gray w/ Black & Beige Streaks Floor Tile	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
84	9" x 9" Gray w/ Black & Beige Streaks Floor Tile Mastic	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
85	9" x 9" Beige w/ Black Streaks	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
86	9" x 9" Beige w/ Black Streaks Mastic	2,000	SF	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
87	12" x 12" Blue w/ Blue & White Streaks Floor Tile	800	SF	Room 149	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
88	12" x 12" Blue w/ Blue & White Streaks Floor Tile Mastic	800	SF	Room 149	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12" x 12" Light Blue Mottled Floor Tile	750	SF	Room 150	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9	9" x 9" Tan w/ Light Brown Specks Floor Tile	1,000	SF	1st, 2nd and 3rd Floor Corridor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Light Blue Mottled Floor Tile Mastic	750	SF	Room 150	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
91	2' x 2' White Ceiling Tile w/ Pinholes	2,000	SF	1st Floor Corridor, 149, 150, 151	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
92	Blue/Green Carpet Mastic	850	SF	Room 151	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

***Management Planner's Comments Summarized at the End of the Report***

Review Date	5/16/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	Sample to determine ACM content, remove or repair damaged surfacing material to intact.
2	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
3	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
4	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
5	Remove or repair to intact.
50	
51	
52	
53	

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
54	
55	Non-AHERA
56	Non-AHERA
57	Non-AHERA
58	
59	
6	
60	
61	Non-AHERA
62	
63	
64	
65	
66	
67	
68	
7	
70	
71	
72	
73	
74	
75	
75M	
76	
76M	
77	

# Chicago Public Schools

**School** Mason School CPC

**Unit** 24382

**Building ID** 4651

**Address** 4216 W. 19th Street

Chicago, IL, 60623

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
77M	
78	
78M	
79	
8	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
9	
90	
91	
92	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Brown & White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION: **Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUILDING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	9" x 9" Tan w/ Light Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Light Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	9" x 9" Black w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridor		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **9" x 9" Black w/ White Specks Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUILDING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	9" x 9" Black w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridor		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **9" x 9" Black w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>13</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Dark Green w/ White Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Remove</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:



Inspector's Signature:

Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **9" x 9" Dark Green w/ White Specks Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	9" x 9" Dark Green Floor Tile w/ White Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **9" x 9" Dark Green Floor Tile w/ White Specks Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor, Rooms 123 (Office), 131, 225, 217**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	9" x 9" Lime Green w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridor-1963 Building		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Lime Green w/ White Specks Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor-1963 Building**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	9" x 9" Lime Green w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridor-1963 Building		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **9" x 9" Lime Green w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor-1963 Building**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Green and Black Terrazzo Stairs 1963 Building		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	First Through Third Floor Stairwells		
MATERIAL QUANTITY:	7000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Green and Black Terrazzo Stairs 1963 Building**

MATERIAL LOCATION: **First Through Third Floor Stairwells**

MATERIAL QUANTITY: **7000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUILDING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	Multi-Brown Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assistant Principal's Second Floor Office		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Multi-Brown Carpet Mastic**

MATERIAL LOCATION: **Assistant Principal's Second Floor Office**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUILDING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Plaster Walls		
HISTORICAL AHERA DAMAGE CATEGORY	3 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 3. Significantly damaged friable surfacing ACBM

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility, 3rd Floor West Stairwell, Room 152, Assistant Principal Office, 2nd Floor Facility Room,		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Dm 3rd Floor West Stairwell, Room 152, Assistant Principal Office, 2nd Floor Facility Room, Room 357		

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Plaster Walls**

MATERIAL LOCATION: **Throughout Facility, 3rd Floor West Stairwell, Room 152, Assistant Principal Office, 2nd Floor Facility Room,**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **105** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content, remove or repair damaged surfacing material to intact.

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Brown & White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Brown & White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 347-357, 245-257, 152, 1st Floor Janitor's Closet, Teachers' Office, 149, Principal's Office, Teach Lounge, 345, 145, Main Office (Public Clerk/1963 Building), 152, 254, 257, 255, 253, 251, 252, 249, 250, 248, 245, 347, 345, 348, 350, 349, 352, 351, 353, 354, 355, 356, 357**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Cinder Block Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Janitors Closet		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **2nd Floor Janitors Closet**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Textured Ceiling Plaster, 12" x 12" Ceiling Tile w/ Grooves		
HISTORICAL AHERA DAMAGE CATEGORY	7		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Throughout Corridors and Classrooms</b>		
MATERIAL QUANTITY:	<b>45000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Textured Ceiling Plaster, 12" x 12" Ceiling Tile w/ Grooves**

MATERIAL LOCATION: **Throughout Corridors and Classrooms**

MATERIAL QUANTITY: **45000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 22  
MATERIAL DESCRIPTION: Interior Window Glaze  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Interior Window Glaze**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Finished Brick Mortar		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Facility		
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Finished Brick Mortar**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>24</b>		
MATERIAL DESCRIPTION:	<b>Blue Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 247</b>		
MATERIAL QUANTITY:	<b>1080</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Blue Carpet Mastic**

MATERIAL LOCATION: **Room 247**

MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Interior Window Caulk**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Green Carpet Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Gold Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor		
MATERIAL QUANTITY:	6420	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gold Streaks Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **6420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12" x 12" Off-White w/ Gold Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor		
MATERIAL QUANTITY:	6420	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Off-White w/ Gold Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **6420** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12" x 12" Taupe w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Taupe w/ White Specks Floor Tile**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	3		
MATERIAL DESCRIPTION:	9" x 9" Dark Brown w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/ White Streaks Floor Tile**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12" x 12" Taupe w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Taupe w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	9" x 9" Light Gray w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **9" x 9" Light Gray w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	9" x 9" Light Gray w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **9" x 9" Light Gray w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12" x 3" Black Border Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 3" Black Border Tile**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	12" x 3" Black Border Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **12" x 3" Black Border Tile Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	9" x 9" Med. Gray w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **9" x 9" Med. Gray w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	9" x 9" Med. Gray w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **9" x 9" Med. Gray w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	9" x 9" Brown w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ White Specks Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	9" x 9" Brown w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>39</b>		
MATERIAL DESCRIPTION:	<b>9" x 9" Light Gray w/ White &amp; Brown Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Lunchroom</b>		
MATERIAL QUANTITY:	<b>3100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **9" x 9" Light Gray w/ White & Brown Specks Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	4		
MATERIAL DESCRIPTION:	9" x 9" Dark Brown w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors - 1963 Building, Rooms 123 (Office), 223, 323, 320**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	9" x 9" Light Gray w/ White & Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **9" x 9" Light Gray w/ White & Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	9" x 9" Multi-Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **9" x 9" Multi-Beige Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	9" x 9" Multi-Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **9" x 9" Multi-Beige Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **9" x 9" Light Brown w/ White & Brown Streaks Floor Tile**

MATERIAL LOCATION: **Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/ White & Brown Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **9" x 9" Light Brown w/ White & Brown Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom (1963/South Building), Teachers' Lunchroom, 223, 323, 320**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/ Brown Splash Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Teachers' Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **9" x 9" Light Brown w/ Brown Splash Floor Tile**

MATERIAL LOCATION: **Lunchroom & Teachers' Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/ Brown Splash Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Teachers' Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **9" x 9" Light Brown w/ Brown Splash Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom & Teachers' Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	9" x 9" Tan w/ White & Black Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom (1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ White & Black Streaks Floor Tile**

MATERIAL LOCATION: **Lunchroom (1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	9" x 9" Tan w/ White & Black Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom (1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ White & Black Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom (1963/South Building), Teachers' Lunchroom, 125, 226, 224, 221, 220, 326, 324, 321, 317**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	9" x 9" Olive Green w/ White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Teachers' Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **9" x 9" Olive Green w/ White Streaks Floor Tile**

MATERIAL LOCATION: **Lunchroom & Teachers' Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	9" x 9" Mint Green w/ Dark Green Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Corridor-1963 Building, 123 (office), 131, 225, 217, 325		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 2nd Floor Corridor		

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **9" x 9" Mint Green w/ Dark Green Streaks Floor Tile**

MATERIAL LOCATION: **2nd and 3rd Floor Corridor-1963 Building, 123 (office), 131, 225, 217, 325**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **12** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	9" x 9" Olive Green w/ White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Teachers' Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **9" x 9" Olive Green w/ White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom & Teachers' Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	9" x 9" Multi-Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Teachers' Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **9" x 9" Multi-Gray Floor Tile**

MATERIAL LOCATION: **Lunchroom & Teachers' Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	9" x 9" Multi-Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Teachers' Lunchroom		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **9" x 9" Multi-Gray Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom & Teachers' Lunchroom**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	2' x 4' Ceiling Tile w/ Small Fissures		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Teachers' Lunchroom		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile w/ Small Fissures**

MATERIAL LOCATION: **Lunchroom & Teachers' Lunchroom**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 54  
MATERIAL DESCRIPTION: Rose Carpet Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: Follow O&M Plan  
ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 149, Library

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Rose Carpet Mastic**

MATERIAL LOCATION: **Room 149, Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55	
MATERIAL DESCRIPTION:	Exterior Window Caulk - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior of Building

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56	
MATERIAL DESCRIPTION:	Exterior Door Caulk - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57	
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>58</b>		
MATERIAL DESCRIPTION:	<b>Multi-Brown Ceramic Floor Tile Grout</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2nd and 3rd Floor Girls Bathroom</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Multi-Brown Ceramic Floor Tile Grout**

MATERIAL LOCATION: **2nd and 3rd Floor Girls Bathroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>59</b>		
MATERIAL DESCRIPTION:	<b>Brown and Beige Ceramic Floor Tile Grout</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st, 2nd and 3rd Floor Boys Bathroom, 1st Floor Girls Bathroom</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Brown and Beige Ceramic Floor Tile Grout**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Boys Bathroom, 1st Floor Girls Bathroom**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6		
MATERIAL DESCRIPTION:	9" x 9" Mint Green w/ Dark Green Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Corridor-1963 Building, 123 (office), 131, 225, 217, 325		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **9" x 9" Mint Green w/ Dark Green Streaks Floor Tile Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Corridor-1963 Building, 123 (office), 131, 225, 217, 325**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	Multi-Blue Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Lobby Floor & On Pillars		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Multi-Blue Ceramic Tile Grout**

MATERIAL LOCATION: **1st Floor Lobby Floor & On Pillars**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61	
MATERIAL DESCRIPTION:	Roofing Material - Non-AHERA	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Roof

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**

MATERIAL LOCATION: **Roof**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUILDING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Wine w/ Yellow Spots Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Wine w/ Yellow Spots Carpet Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>63</b>		
MATERIAL DESCRIPTION:	<b>Purple Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office and 148</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Purple Carpet Mastic**

MATERIAL LOCATION: **Main Office and 148**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	Insulation Inside Of Vault Door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	32	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Insulation Inside Of Vault Door**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **32** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Brown & Purple Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 149		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Brown & Purple Carpet Mastic**

MATERIAL LOCATION: **Room 149**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUILDING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Assistant Principal's Office**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Assistant Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67	
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard and Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard and Adhesive**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68	
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard and Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Classrooms

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard and Adhesive**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: **05/16/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7		
MATERIAL DESCRIPTION:	9" x 9" Choc w/ White & Orange Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor, 119A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **9" x 9" Choc w/ White & Orange Streaks Floor Tile**

MATERIAL LOCATION: **3rd Floor Corridor, 119A**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue/Gray Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 148, 117, 121, Lunchroom (1963/South Building)		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue/Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 148, 117, 121, Lunchroom (1963/South Building)**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	12" x 12" White w/ Blue/Gray Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 148, 117, 121, Lunchroom (1963/South Building)		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12" x 12" White w/ Blue/Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 148, 117, 121, Lunchroom (1963/South Building)**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	Black/Brown Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Entry and Corridor		
MATERIAL QUANTITY:	5500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Black/Brown Terrazzo**

MATERIAL LOCATION: **1st Floor Entry and Corridor**

MATERIAL QUANTITY: **5500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 102, 103, 104 105, 114, 206, 150, Office, Storage Room, and Room 247		
MATERIAL QUANTITY:	6500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Rooms 102, 103, 104 105, 114, 206, 150, Office, Storage Room, and Room 247**

MATERIAL QUANTITY: **6500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>74</b>		
MATERIAL DESCRIPTION:	<b>White/Blue Ceramic Grout</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>At Entrance WomensLunchroom</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **White/Blue Ceramic Grout**

MATERIAL LOCATION: **At Entrance WomensLunchroom**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75		
MATERIAL DESCRIPTION:	12" x 12" Tan/Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 307, 309, 147 and Main Office, Lunchroom, Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **12" x 12" Tan/Beige Floor Tile**

MATERIAL LOCATION: **Rooms 307, 309, 147 and Main Office, Lunchroom, Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	75M		
MATERIAL DESCRIPTION:	12" x 12" Tan/Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 307, 309, 147 and Main Office, Lunchroom, Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **75M**

MATERIAL DESCRIPTION: **12" x 12" Tan/Beige Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 307, 309, 147 and Main Office, Lunchroom, Library (118), 129, 226, 224, 221, 326, 324, 321, 317, 147**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>76</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blue/White Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 116, 151, 119</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **12" x 12" Blue/White Floor Tile**

MATERIAL LOCATION: **Rooms 116, 151, 119**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>76M</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blue/White Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 116, 151, 119</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **76M**

MATERIAL DESCRIPTION: **12" x 12" Blue/White Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 116, 151, 119**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	77M		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	3100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **77M**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **3100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78		
MATERIAL DESCRIPTION:	12" x 12" White w/ Black Spec's Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 148		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **04/17/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" White w/ Black Spec's Floor Tile**

MATERIAL LOCATION: **Room 148**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78M		
MATERIAL DESCRIPTION:	12" x 12" White w/ Black Spec's Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 148		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **78M**

MATERIAL DESCRIPTION: **12" x 12" White w/ Black Spec's Floor Tile Mastic**

MATERIAL LOCATION: **Room 148**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8		
MATERIAL DESCRIPTION:	9" x 9" Choc w/ White & Orange Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor, 119A		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUILDING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **9" x 9" Choc w/ White & Orange Streaks Floor Tile Mastic**

MATERIAL LOCATION: **3rd Floor Corridor, 119A**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9		
MATERIAL DESCRIPTION:	9" x 9" Tan w/ Light Brown Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd Floor Corridor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	REVIEW DATE:	<b>5/16/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Light Brown Specks Floor Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd Floor Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24382</b>	BUIDLING ID:	<b>4651</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Mason School CPC</b>	INSPECTION DATE:	<b>4/17/2025</b>		
ADDRESS:	<b>4216 W. 19th Street</b>	IDPH LICENSE NO:	<b>100-20994</b>		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	<b>81</b>			
MATERIAL DESCRIPTION:	<b>9" x 9" Red Floor Tile w/ White Streaks</b>			
MATERIAL LOCATION:	<b>Room 127, 227, 222, 219, 218, 327, 322, 319, 318</b>			
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>	
MATERIAL CATEGORY:	<b>MISC</b>	FRIABLE:	<b>No</b>	
ASBESTOS TYPE:	<b>Assumed</b>			
DISTURBANCE POTENTIAL:	<b>LOW</b>	CONDITION:	<b>No Damage</b>	
AHERA DAMAGE CATEGORY:	<b>6 ACBM with the potential for damage</b>			
ACCESSIBILITY:	<b>Within Reach</b>	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	<b>SF</b>	
COMMENTS:				

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Room 127, 227, 222, 219, 218, 327, 322, 319, 318**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	84		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ Black & Beige Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **9" x 9" Gray w/ Black & Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	86		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Black Streaks Mastic		
MATERIAL LOCATION:	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Black Streaks Mastic**

MATERIAL LOCATION: **Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	80		
MATERIAL DESCRIPTION:	12" x 12" Blue/Green Mottled Floor Tile Mastic		
MATERIAL LOCATION:	Room 119		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **12" x 12" Blue/Green Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 119**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	85		
MATERIAL DESCRIPTION:	9 " x 9 " Beige w/ Black Streaks		
MATERIAL LOCATION:	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **9 " x 9 " Beige w/ Black Streaks**

MATERIAL LOCATION: **Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	83		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ Black & Beige Streaks Floor Tile		
MATERIAL LOCATION:	Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BULDING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **9" x 9" Gray w/ Black & Beige Streaks Floor Tile**

MATERIAL LOCATION: **Rooms 128, 228, 227, 222, 219, 218, 328, 327, 322, 319, 318**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	Blue/Green Carpet Mastic		
MATERIAL LOCATION:	Room 151		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Blue/Green Carpet Mastic**

MATERIAL LOCATION: **Room 151**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Mottled Floor Tile Mastic		
MATERIAL LOCATION:	Room 150		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Room 150**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	12" x 12" Blue w/ Blue & White Streaks Floor Tile		
MATERIAL LOCATION:	Room 149		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Blue & White Streaks Floor Tile**

MATERIAL LOCATION: **Room 149**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	79		
MATERIAL DESCRIPTION:	12" x 12" Blue/Green Mottled Floor Tile		
MATERIAL LOCATION:	Room 119		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **12" x 12" Blue/Green Mottled Floor Tile**

MATERIAL LOCATION: **Room 119**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	82		
MATERIAL DESCRIPTION:	9" x 9" Red Floor Tile w/ White Streaks Mastic		
MATERIAL LOCATION:	Room 127, 227, 222, 219, 218, 327, 322, 319, 318		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile w/ White Streaks Mastic**

MATERIAL LOCATION: **Room 127, 227, 222, 219, 218, 327, 322, 319, 318**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	2' x 2' White Ceiling Tile w/ Pinholes		
MATERIAL LOCATION:	1st Floor Corridor, 149, 150, 151		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile w/ Pinholes**

MATERIAL LOCATION: **1st Floor Corridor, 149, 150, 151**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Mottled Floor Tile		
MATERIAL LOCATION:	Room 150		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Mottled Floor Tile**

MATERIAL LOCATION: **Room 150**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24382	BUIDLING ID:	4651
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Mason School CPC	INSPECTION DATE:	4/17/2025		
ADDRESS:	4216 W. 19th Street	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	12" x 12" Blue w/ Blue & White Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Room 149		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 04/17/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24382** BUIDLING ID: **4651**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Mason School CPC** REVIEW DATE: **5/16/2025**

ADDRESS: **4216 W. 19th Street** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **12" x 12" Blue w/ Blue & White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 149**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 05/16/2025

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



2200 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

## Environmental and Occupational Safety & Health Training

*Does hereby certify*

**Cody Cummins**

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least  
70% for accreditation under AHERA (Title II)*

## **Asbestos Management Planner Initial**



*Class Date:* 10/28-29/2024  
*Examination Date:* 10/29/2024  
*STC Certificate Number:* STC-20241029-000103AMPI  
*Certification Expiration:* 10/29/2025

David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

*This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources*

# Cody Cummins

## Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



## ENDORSEMENTS

TC EXPIRES

## INSPECTOR

3/8/2025

## AIR SAMPLING PROFESSIONAL

## ENDORSEMENTS

TC EXPIRES

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

## MANAGEMENT PLANNER

10/29/2025

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Cody Cummins

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2502280827  
Course Date: 2/28/2025  
Exam Date: 2/28/2025  
Expiration Date: 2/28/2026



  
Tyler Nicholson, Authorized Signer

Issue Date: 2/28/2025

Course Credit Hours: BIR WI 4 Hours



OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

---

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Serio**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed