

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2337  
SCHOOL NAME: Mayer School  
ADDRESS OF SCHOOL: 2250 N. Clifton Avenue  
CITY: Chicago, IL, 60614

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 6/9/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 6/3/2025 ENROLLMENT 775  
IDPH INSPECTOR LICENSE NUMBER: 100-06327  
IDPH LICENSED INSPECTOR NAME (Please Print): Roberto Rivera  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

 7/1/2025  
*Richard J. Schleyer*  
Signature of Designated Person Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Mayer School**

2250 N. Clifton Avenue  
Chicago, IL, 60614

Unit: 24401  
Building ID: 4680

IDPH ID Number: 14-016-2990-2337

**REPORT DATE:**  
Tuesday, July 01, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Specialty Consulting, Inc.**

2942 W. Van Buren Street  
Chicago, IL, 60612  
Phone (312) 319-7575  
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

07/01/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 24401      Region: 02      IDPH ID: 14-016-2990-2337

School: Mayer School      Building ID: 4680

Address: 2250 N. Clifton Avenue

Chicago, IL, 60614

Building Contact: Serowski, Daniel      Contact Phone: 7733961617

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/3/2025

Review Date: 07/01/2025

Inspector: Roberto Rivera

Inspector IDPH License: 100-06327

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: July 01, 2025

RE: Mayer School, Unit 24401  
2250 N. Clifton Avenue  
Chicago, IL, 60614

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Mayer School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Mayer School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

## 1. School Information

School: Mayer School Unit: 24401 Region: 02  
Address: 2250 N. Clifton Avenue Chicago, IL, 60614  
IDPH ID: 14-016-2990-2337 Building ID: 4680  
Contact: Serowski, Daniel Phone: 7733961617

## 2. Description of Facility

Original Construction: 1959 Additional Construction:  
Total Square Footage: 73514 No of Floors: 2  
Current Occupancy: 775

### 3. LEA Designated Person

#### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575 Fax: (312) 319-7580

## 5. Inspector

Inspector Name: Roberto Rivera

Inspector IDPH license # 100-06327  
Reinspection Date: 6/3/2025

Signature:  
Date: 6/3/2025

## 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature: 

7. Review Date: 07/01/2025

## 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Signature:

Date: 7/1/2025

Name: Richard J. Schleyer

## **II. EXECUTIVE SUMMARY**

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Mayer School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 4680:

B. The following new homogenous areas have been identified for Building 4680:

55	12" x12" Light Beige w/White Specks VFT (Replacement Tile)
55A	12" x 12" Light Beige w/ White Specks VFT MASTIC (replacement tile)
56	12" x 12" Sand VFT
56A	12" x 12" Sand VFT MASTIC
57	Terrazzo Flooring
58	12" x 12" Dark Gray Speckled VFT (Replacement Tile)
58A	12" x 12" Dark Gray Speckled VFT MASTIC (Replacement Tile)
59	12" x 12" Brown Speckled VFT (Replacement Tile)
59A	12" x 12" Brown Speckled VFT MASTIC (Replacement Tile)

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

22	12" x 12" Off White w/ Brown Streaks VFT
27	12" x 12" Gray w/ Dark Streaks VFT
28	12" x 12" Gray w/ Dark Streaks VFT Mastic
29	12" x 12" Beige w/ Brown Streaks VFT
39	12" x 12" Light Pink w/ Specks VFT
40	12" x 12" Light Pink w/ Specks VFT Mastic
41	12" x 12" Light Beige w/ Tan Specks VFT
42	12" x 12" Light Beige w/ Tan Specks VFT
46	12" x 12" Gray w/White Specks VFT
46 A	12" x 12" Gray w/White Specks VFT Mastic
47	12" x 12" Cream with Specs VFT
47A	12" x 12" Cream with Specs VFT Mastic
48	Grey Carpet with Specs - Mastic
49	12" x 12" Light Brown with Brown Specs VFT
49A	12" x 12" Light Brown with Brown Specs VFT Mastic
50	12" x 12" Light Grey with Specs Floor Tile
50A	12" x 12" Light Gray with Specs VFT Mastic
51	12" x 12" Black w/White Streaks VFT
52	12" x 12" Black w/White Streaks Mastic
53	Black Sink Undercoating
54	1' X 1' Swirl Ceiling Tile
55	12" x12" Light Beige w/White Specks VFT (Replacement Tile)
55A	12" x 12" Light Beige w/ White Specks VFT MASTIC (replacement tile)
56	12" x 12" Sand VFT
56A	12" x 12" Sand VFT MASTIC
57	Terrazzo Flooring
58	12" x 12" Dark Gray Speckled VFT (Replacement Tile)
58A	12" x 12" Dark Gray Speckled VFT MASTIC (Replacement Tile)
59	12" x 12" Brown Speckled VFT (Replacement Tile)
59A	12" x 12" Brown Speckled VFT MASTIC (Replacement Tile)

The following areas were deemed to be inaccessible:

59	12" x 12" Brown Speckled VFT (Replacement Tile)
----	---

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Roberto Rivera, IDPH License # 100-06327. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Mayer School Building 4680 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	MJP E/F/V on Cardboard Pipe Insulation	40	EA	Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
02	MJP E/F/V on Aircell Pipe Insulation	70	EA	Boiler Room & Passage, Crawl Spaces, Helps Lockerroom	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
05	Cardboard Pipe Insulation	200	LF	Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room, 227	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
06	MJP E/F/V on Fiberglass Pipe Insulation	40	EA	Boiler Room, Crawlspace	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
07	Aircell Pipe Insulation	2,491	LF	Boiler Room & Passage, Helps Lockerroom	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
12	Plaster Ceiling			1st Floor South Girls Toilet, Room 202, 210	NO_ACBM									
15	Spray Applied Acoustical Ceiling	15,000	SF	Rooms 215, 1st & 2nd Floor Corridors (Above Drywall), 1st Fl. Teacher's Dining, Room 101 and 105	CHR	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
20	Fire Door	40	SF	2nd Floor Fan Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	9" x 9" Gray w/ White Streaks VFT	24,900	SF	Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Principal's Office, Vault Room, MDF Room, Kitchen Manager's Office & Locker Room, 1st Fl. Storage Across From GYM										
22	12" x 12" Off White w/ Brown Streaks VFT	9,000	SF	2nd Floor Corridor, Room 216	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	9" x 9" Gray w/ White Streaks VFT Mastic	24,900	SF	Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass. Principal's Office, Vault Room, MDF Room, Kitchen Manager's Office & Locker Room, 1st Fl. Storage Across From GYM	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12" x 12" Off White w/ Brown Streaks VFT Mastic	9,000	SF	2nd Floor Corridor, Room 216	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12" x 12" Gray w/ Dark Streaks VFT	1,100	SF	Rooms 101, 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
28	12" x 12" Gray w/ Dark Streaks VFT Mastic	1,100	SF	Rooms 101, 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12" x 12" Beige w/ Brown Streaks VFT	1,500	SF	Lunchroom, Rm 102, 1st Fl. Teacher's Dining	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
30	12" x 12" Beige w/ Brown Streaks VFT Mastic	1,100	SF	Lunchroom, Rm 102, 1st Fl. Teacher's Dining	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	9" x 9" Red VFT	100	SF	Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
32	9" x 9" Red VFT Mastic	100	SF	Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	9" x 9" Brown w/ Black Streaks VFT	250	SF	Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
34	Drywall Compound			Throughout	NO ACBM									
38	9" x 9" Brown w/ Black Streaks VFT Mastic	250	SF	Engineer's Office	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12" x 12" Light Pink w/ Specks VFT Mastic	1,800	SF	Rooms 112, 113, 125	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
40	12" x 12" Light Pink w/ Specks VFT Mastic	1,800	SF	Rooms 112, 113, 125	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12" x 12" Light Beige w/ Tan Specks VFT	1,700	SF	Rooms 114, 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
42	12" x 12" Light Beige w/ Tan Specks VFT	1,700	SF	Rooms 114, 107	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Gray Linoleum - REMOVED			2nd Floor Library, Library Conference Room, Library Work Room	ABATED	MISC								
44	Gray Linoleum Mastic - REMOVED			2nd Floor Library, Library Conference Room, Library Work Room	ABATED	MISC								
45	Carpet Mastic - REMOVED			Rooms 117, 119, 121, 123	ABATED	MISC								
46	12" x 12" Gray w/White Specks VFT	3,600	SF	Rooms 117, 119, 121, 123, 1st floor Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
46 A	12" x 12" Gray w/White Specks VFT Mastic	3,600	SF	Rooms 117, 119, 121, 123, 1st floor Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	12" x 12" Cream with Specs VFT	200	SF	2nd Floor Corridor by Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
47A	12" x 12" Cream with Specs VFT Mastic	200	SF	2nd Floor Corridor by Elevator	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Grey Carpet with Specs - Mastic	1,200	SF	2nd Floor Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12" x 12" Light Brown with Brown Specs VFT	1,100	SF	Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
49A	12" x 12" Light Brown with Brown Specs VFT Mastic	1,100	SF	Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12" x 12" Light Grey with Specs Floor Tile	10,000	SF	1st Floor Corridors, Main Office & Principal's Office, JC by Room 125	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
50A	12" x 12" Light Gray with Specs VFT Mastic	10,000	SF	1st Floor Corridors, Main Office & Principal's Office,	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
51	12" x 12" Black w/White Streaks VFT	20	SF	JC by Room 125 2nd Floor Mens & Womens Toilet/Classroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12" x 12" Black w/White Streaks Mastic	20	SF	2nd Floor Mens & Womens Toilet/Classroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	Black Sink Undercoating	42	SF	Rooms 101, 102, 104, 105, 106, 202	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	1' X 1' Swirl Ceiling Tile	1,200	SF	Lunchroom	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
55	12" x12" Light Beige w/White Specks VFT (Replacement Tile)	1,600	SF	Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
55A	12" x 12" Light Beige w/ White Specks VFT MASTIC (replacement tile)	1,600	SF	Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12" x 12" Sand VFT	850	SF	Room 207, Principal's Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56A	12" x 12" Sand VFT MASTIC	850	SF	Room 207, Principal's Office Toilet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Terrazzo Flooring	3,800	SF	All Stairwells, 1st Floor Lobby by GYM	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58	12" x 12" Dark Gray Speckled VFT (Replacement Tile)	280	PERCENT	Rooms: 125, 123, 121, 119, 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58A	12" x 12" Dark Gray Speckled VFT MASTIC (Replacement Tile)	280	SF	Rooms: 125, 123, 121, 119, 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	12" x 12" Brown Speckled VFT (Replacement Tile)	240	SF	Rooms: 125, 114, 113, 112	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>6/3/2025</u>
Inspector Name	<u>Roberto Rivera</u>
<b>100-06327</b>	<b>5/15/2026</b>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
01	
02	
05	
06	
07	9 LF from Basement Boiler Room
12	
15	
20	
21	
22	
24	
25	
27	
28	
29	
30	
31	
32	
33	
34	
38	
39	
40	
41	

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
42	
43	
44	
45	
46	
46 A	
47	
47A	
48	
49	
49A	
50	
50A	
51	
52	
53	
54	
55	Replacement Tile
55A	Replacement Tile
56	
56A	
57	
58	Replacement Tile
58A	Replacement Tile
59	Replacement Tile
59A	Replacement Tile
A	
D	
E	

# Chicago Public Schools

**School** Mayer School **Unit** 24401 **Building ID** 4680  
**Address** 2250 N. Clifton Avenue **Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
F	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Mayer School

**Unit** 24401

**Building ID** 4680

**Address** 2250 N. Clifton Avenue

Chicago, IL, 60614

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	MJP E/F/V on Cardboard Pipe Insulation	40	EA	Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
02	MJP E/F/V on Aircell Pipe Insulation	70	EA	Boiler Room & Passage, Crawl Spaces, Helps Lockerroom	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
05	Cardboard Pipe Insulation	200	LF	Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room, 227	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
06	MJP E/F/V on Fiberglass Pipe Insulation	40	EA	Boiler Room, Crawlspaces	Chrysotile	TSI	Yes	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
07	Aircell Pipe Insulation	2,491	LF	Boiler Room & Passage, Helps Lockerroom	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
12	Plaster Ceiling			1st Floor South Girls Toilet, Room 202, 210	No ACBM						
15	Spray Applied Acoustical Ceiling	15,000	SF	Rooms 215, 1st & 2nd Floor Corridors (Above Drywall), 1st Fl. Teacher's Dining, Room 101 and 105	Chrysotile	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Fire Door	40	SF	2nd Floor Fan Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9" x 9" Gray w/ White Streaks VFT	24,900	SF	Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass. Principal's Office, Vault Room, MDF Room, Kitchen Manager's Office & Locker Room, 1st Fl. Storage Across From GYM	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" Off White w/ Brown Streaks VFT	9,000	SF	2nd Floor Corridor, Room 216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	9" x 9" Gray w/ White Streaks VFT Mastic	24,900	SF	Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass. Principal's Office, Vault Room, MDF Room, Kitchen	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Mayer School

**Unit** 24401

**Building ID** 4680

**Address** 2250 N. Clifton Avenue

Chicago, IL, 60614

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Manager's Office & Locker Room, 1st Fl. Storage Across From GYM							
25	12" x 12" Off White w/ Brown Streaks VFT Mastic	9,000	SF	2nd Floor Corridor, Room 216	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12" x 12" Gray w/ Dark Streaks VFT	1,100	SF	Rooms 101, 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12" x 12" Gray w/ Dark Streaks VFT Mastic	1,100	SF	Rooms 101, 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Beige w/ Brown Streaks VFT	1,500	SF	Lunchroom, Rm 102, 1st Fl. Teacher's Dining	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12" x 12" Beige w/ Brown Streaks VFT Mastic	1,100	SF	Lunchroom, Rm 102, 1st Fl. Teacher's Dining	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	9" x 9" Red VFT	100	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	9" x 9" Red VFT Mastic	100	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	9" x 9" Brown w/ Black Streaks VFT	250	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Drywall Compound			Throughout	No ACBM						
38	9" x 9" Brown w/ Black Streaks VFT Mastic	250	SF	Engineer's Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12" x 12" Light Pink w/ Specks VFT	1,800	SF	Rooms 112, 113, 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12" x 12" Light Pink w/ Specks VFT Mastic	1,800	SF	Rooms 112, 113, 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12" x 12" Light Beige w/ Tan Specks VFT	1,700	SF	Rooms 114, 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Light Beige w/ Tan Specks VFT	1,700	SF	Rooms 114, 107	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Gray Linoleum - REMOVED			2nd Floor Library, Library Conference Room, Library Work Room	Abated	MISC					
44	Gray Linoleum Mastic - REMOVED			2nd Floor Library, Library Conference Room, Library Work Room	Abated	MISC					
45	Carpet Mastic - REMOVED			Rooms 117, 119, 121, 123	Abated	MISC					
46	12" x 12" Gray w/White Specks VFT	3,600	SF	Rooms 117, 119, 121, 123, 1st floor Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46 A	12" x 12" Gray w/White Specks VFT Mastic	3,600	SF	Rooms 117, 119, 121, 123, 1st floor Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	12" x 12" Cream with Specs VFT	200	SF	2nd Floor Corridor by Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47A	12" x 12" Cream with Specs VFT Mastic	200	SF	2nd Floor Corridor by Elevator	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Grey Carpet with Specs - Mastic	1,200	SF	2nd Floor Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12" x 12" Light Brown with Brown Specs VFT	1,100	SF	Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49A	12" x 12" Light Brown with Brown Specs VFT Mastic	1,100	SF	Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12" x 12" Light Grey with Specs Floor Tile	10,000	SF	1st Floor Corridors, Main Office & Principal's Office, JC by Room 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Mayer School

**Unit** 24401

**Building ID** 4680

**Address** 2250 N. Clifton Avenue

Chicago, IL, 60614

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
50A	12" x 12" Light Gray with Specs VFT Mastic	10,000	SF	1st Floor Corridors, Main Office & Principal's Office, JC by Room 125	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Black w/White Streaks VFT	20	SF	2nd Floor Mens & Womens Toilet/Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Black w/White Streaks Mastic	20	SF	2nd Floor Mens & Womens Toilet/Classroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Black Sink Undercoating	42	SF	Rooms 101, 102, 104, 105, 106, 202	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	1' X 1' Swirl Ceiling Tile	1,200	SF	Lunchroom	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x12" Light Beige w/White Specks VFT (Replacement Tile)	1,600	SF	Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55A	12" x 12" Light Beige w/ White Specks VFT MASTIC (replacement tile)	1,600	SF	Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" Sand VFT	850	SF	Room 207, Principal's Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56A	12" x 12" Sand VFT MASTIC	850	SF	Room 207, Principal's Office Toilet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Terrazzo Flooring	3,800	SF	All Stairwells, 1st Floor Lobby by GYM	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Dark Gray Speckled VFT (Replacement Tile)	280	PERCENT	Rooms: 125, 123, 121, 119, 117	Assumed	MISC	No	0	PERCENT	6 ACBM with the potential for damage	Follow O&M Plan
58A	12" x 12" Dark Gray Speckled VFT MASTIC (Replacement Tile)	280	SF	Rooms: 125, 123, 121, 119, 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12" x 12" Brown Speckled VFT (Replacement Tile)	240	SF	Rooms: 125, 114, 113, 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59A	12" x 12" Brown Speckled VFT MASTIC (Replacement Tile)	240	SF	Rooms: 125, 114, 113, 112	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler Lagging	1,820	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	Boiler Gasket	10	LF	Boiler Room	Chrysotile	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	Carpet Mastic - Duplica HA se HA# 48			Room 215		MISC					
F						MISC					

# Chicago Public Schools

**School** Mayer School

**Unit** 24401

**Building ID** 4680

**Address** 2250 N. Clifton Avenue

Chicago, IL, 60614

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

*Management Planner's Comments Summarized at the End of the Report*

Review Date	7/1/2025
Manager Planner Name	Arturo Saenz
100-04019	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
05	
06	
07	
12	
15	
20	
21	

# Chicago Public Schools

**School** Mayer School

**Unit** 24401

**Building ID** 4680

**Address** 2250 N. Clifton Avenue

Chicago, IL, 60614

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
22	
24	
25	
27	
28	
29	
30	
31	
32	
33	
34	
38	
39	
40	
41	
42	
43	
44	
45	
46	
46 A	
47	
47A	
48	
49	
49A	
50	

# Chicago Public Schools

**School** Mayer School

**Unit** 24401

**Building ID** 4680

**Address** 2250 N. Clifton Avenue

Chicago, IL, 60614

**Region** 02

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
50A	
51	
52	
53	
54	
55	
55A	
56	
56A	
57	
58	
58A	
59	
59A	
A	
D	
E	
F	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUILDING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	EA
DAMAGE QUANTITY:		DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room & Passage, Crawl Spaces, Helps Lockeroom		
MATERIAL QUANTITY:	70	MATERIAL UNITS:	EA
DAMAGE QUANTITY:		DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Boiler Room & Passage, Crawl Spaces, Helps Lockerroom**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room, 227**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Boiler Room & Passage, All Pipe Chases, Rms 225/102/106(Under Sinks), Crawl Spaces, Helps Locker room, 227**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	06		
MATERIAL DESCRIPTION:	MJP E/F/V on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room, Crawlspaces		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	EA
DAMAGE QUANTITY:		DAMAGE UNITS:	EA
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Boiler Room, Crawlspaces**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room & Passage, Helps Lockerroom		
MATERIAL QUANTITY:	2491	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	9 LF from Basement Boiler Room		

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **07**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Boiler Room & Passage, Helps Lockerroom**

MATERIAL QUANTITY: **2491** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12  
MATERIAL DESCRIPTION: Plaster Ceiling  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor South Girls Toilet, Room 202, 210

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Plaster Ceiling**

MATERIAL LOCATION: **1st Floor South Girls Toilet, Room 202, 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Spray Applied Acoustical Ceiling		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 215, 1st & 2nd Floor Corridors (Above Drywall), 1st Fl. Teacher's Dining, Room 101 and 105**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Spray Applied Acoustical Ceiling**

MATERIAL LOCATION: **Rooms 215, 1st & 2nd Floor Corridors (Above Drywall), 1st Fl. Teacher's Dining, Room 101 and 105**

MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Fire Door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Fan Room		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Fire Door**

MATERIAL LOCATION: **2nd Floor Fan Room**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL: MODERATE

MATERIAL LOCATION: Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass. Principal's Office, Vault Room, MDF Room, Kitchen Manager's Office & Locker Room, 1st Fl. Storage Across From GYM

MATERIAL QUANTITY: 24900 MATERIAL UNITS: SF

DAMAGE QUANTITY: DAMAGE UNITS: SF

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9" x 9" Gray w/ White Streaks VFT**

MATERIAL LOCATION: **Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass. Principal's Office, Vault Room, MDF Room, Kitchen Manager's Office & Locker Room, 1st Fl. Storage Across From GYM**

MATERIAL QUANTITY: **24900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor, Room 216		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Brown Streaks VFT**

MATERIAL LOCATION: **2nd Floor Corridor, Room 216**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass. Principal's Office, Vault Room, MDF Room, Kitchen Manager's Office & Locker Room, 1st Fl. Storage Across From GYM**

MATERIAL QUANTITY: **24900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **9" x 9" Gray w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 102, 104, 106, 108, 109, 110, 111, 115, 201, 202, 203, 204, 205, 206, 208, 209, 210, 211, 213, 214, 216, 217, 219, 221, 225, 226, 229, All Janitor's Closet, 2nd Floor Men's and Women's Washrooms, Ass. Principal's Office, Vault Room, MDF Room, Kitchen Manager's Office & Locker Room, 1st Fl. Storage Across From GYM**

MATERIAL QUANTITY: **24900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor, Room 216		
MATERIAL QUANTITY:	9000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Brown Streaks VFT Mastic**

MATERIAL LOCATION: **2nd Floor Corridor, Room 216**

MATERIAL QUANTITY: **9000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Dark Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Rooms 101, 105**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Streaks VFT**

MATERIAL LOCATION: **Rooms 101, 105**

MATERIAL QUANTITY: **1100**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12" x 12" Gray w/ Dark Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101, 105		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Dark Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 101, 105**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Lunchroom, Rm 102, 1st Fl. Teacher's Dining		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks VFT**

MATERIAL LOCATION: **Lunchroom, Rm 102, 1st Fl. Teacher's Dining**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Rm 102, 1st Fl. Teacher's Dining		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Lunchroom, Rm 102, 1st Fl. Teacher's Dining**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	9" x 9" Red VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **9" x 9" Red VFT**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	9" x 9" Red VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **9" x 9" Red VFT Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	9" x 9" Brown w/ Black Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ Black Streaks VFT**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 34  
MATERIAL DESCRIPTION: Drywall Compound  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	9" x 9" Brown w/ Black Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **9" x 9" Brown w/ Black Streaks VFT Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12" x 12" Light Pink w/ Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Rooms 112, 113, 125</b>		
MATERIAL QUANTITY:	<b>1800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Light Pink w/ Specks VFT**

MATERIAL LOCATION: **Rooms 112, 113, 125**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12" x 12" Light Pink w/ Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 112, 113, 125		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12" x 12" Light Pink w/ Specks VFT Mastic**

MATERIAL LOCATION: **Rooms 112, 113, 125**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ Tan Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Rooms 114, 107</b>		
MATERIAL QUANTITY:	<b>1700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Tan Specks VFT**

MATERIAL LOCATION: **Rooms 114, 107**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ Tan Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 114, 107		
MATERIAL QUANTITY:	1700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Tan Specks VFT**

MATERIAL LOCATION: **Rooms 114, 107**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Gray Linoleum - REMOVED		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Library, Library Conference Room, Library Work Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Gray Linoleum - REMOVED**

MATERIAL LOCATION: **2nd Floor Library, Library Conference Room, Library Work Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44	
MATERIAL DESCRIPTION:	Gray Linoleum Mastic - REMOVED	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Library, Library Conference Room, Library Work Room

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Gray Linoleum Mastic - REMOVED**

MATERIAL LOCATION: **2nd Floor Library, Library Conference Room, Library Work Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45	
MATERIAL DESCRIPTION:	Carpet Mastic - REMOVED	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Rooms 117, 119, 121, 123

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **Carpet Mastic - REMOVED**

MATERIAL LOCATION: **Rooms 117, 119, 121, 123**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" x 12" Gray w/White Specks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 117, 119, 121, 123, 1st floor Library		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" Gray w/White Specks VFT**

MATERIAL LOCATION: **Rooms 117, 119, 121, 123, 1st floor Library**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46 A		
MATERIAL DESCRIPTION:	12" x 12" Gray w/White Specks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 117, 119, 121, 123, 1st floor Library		
MATERIAL QUANTITY:	3600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **46 A**

MATERIAL DESCRIPTION: **12" x 12" Gray w/White Specks VFT Mastic**

MATERIAL LOCATION: **Rooms 117, 119, 121, 123, 1st floor Library**

MATERIAL QUANTITY: **3600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12" x 12" Cream with Specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>2nd Floor Corridor by Elevator</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Arturo Saenz		
SCHOOL NAME:	Mayer School	REVIEW DATE:	7/1/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12" x 12" Cream with Specs VFT**

MATERIAL LOCATION: **2nd Floor Corridor by Elevator**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47A		
MATERIAL DESCRIPTION:	12" x 12" Cream with Specs VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Corridor by Elevator		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **47A**

MATERIAL DESCRIPTION: **12" x 12" Cream with Specs VFT Mastic**

MATERIAL LOCATION: **2nd Floor Corridor by Elevator**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	Grey Carpet with Specs - Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Library		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **Grey Carpet with Specs - Mastic**

MATERIAL LOCATION: **2nd Floor Library**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12" x 12" Light Brown with Brown Specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Room 223</b>		
MATERIAL QUANTITY:	<b>1100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12" x 12" Light Brown with Brown Specs VFT**

MATERIAL LOCATION: **Room 223**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown with Brown Specs VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 223		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **49A**

MATERIAL DESCRIPTION: **12" x 12" Light Brown with Brown Specs VFT Mastic**

MATERIAL LOCATION: **Room 223**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12" x 12" Light Grey with Specs Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	1st Floor Corridors, Main Office & Principal's Office, JC by Room 125		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **06/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" Light Grey with Specs Floor Tile**

MATERIAL LOCATION: **1st Floor Corridors, Mian Office & Principal's Office, JC by Room 125**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50A		
MATERIAL DESCRIPTION:	12" x 12" Light Gray with Specs VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Corridors, Mian Office & Principal's Office, JC by Room 125		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **50A**

MATERIAL DESCRIPTION: **12" x 12" Light Gray with Specs VFT Mastic**

MATERIAL LOCATION: **1st Floor Corridors, Mian Office & Principal's Office, JC by Room 125**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12" x 12" Black w/White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Mens & Womens Toilet/Classroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" Black w/White Streaks VFT**

MATERIAL LOCATION: **2nd Floor Mens & Womens Toilet/Classroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12" x 12" Black w/White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Mens & Womens Toilet/Classroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUIDLING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Black w/White Streaks Mastic**

MATERIAL LOCATION: **2nd Floor Mens & Womens Toilet/Classroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	Black Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101, 102, 104, 105, 106, 202		
MATERIAL QUANTITY:	42	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Black Sink Undercoating**

MATERIAL LOCATION: **Rooms 101, 102, 104, 105, 106, 202**

MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	1' X 1' Swirl Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **1' X 1' Swirl Ceiling Tile**

MATERIAL LOCATION: **Lunchroom**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Boiler Lagging		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	1820	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Laggings**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **1820** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Boiler Gasket		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUILDING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E
MATERIAL DESCRIPTION:	Carpet Mastic - Duplica HA se HA# 48
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	
HISTORICAL RESPONSE ACTION:	Follow O&M Plan
ASBESTOS TYPE:	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 215

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Carpet Mastic - Duplica HA se HA# 48**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: F

MATERIAL DESCRIPTION:

HISTORICAL AHERA DAMAGE CATEGORY ACBM with the potential for damage

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Remove

ASBESTOS TYPE: FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24401</b>	BUILDING ID:	<b>4680</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Mayer School</b>	REVIEW DATE:	<b>7/1/2025</b>		
ADDRESS:	<b>2250 N. Clifton Avenue</b>	IDPH LICENSE NO:	<b>100-06327</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	55A			
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ White Specks VFT MASTIC (replacement tile)			
MATERIAL LOCATION:	Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102			
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
		DAMAGE REASON:		
COMMENTS:	Replacement Tile			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **55A**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ White Specks VFT MASTIC (replacement tile)**

MATERIAL LOCATION: **Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Speckled VFT (Replacement Tile)		
MATERIAL LOCATION:	Rooms: 125, 123, 121, 119, 117		
MATERIAL QUANTITY:	280	MATERIAL UNITS:	PERCENT
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	PERCENT
COMMENTS:	Replacement Tile		

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Speckled VFT (Replacement Tile)**

MATERIAL LOCATION: **Rooms: 125, 123, 121, 119, 117**

MATERIAL QUANTITY: **280** MATERIAL UNITS: **PERCENT**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **PERCENT**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	12" x 12" Brown Speckled VFT (Replacement Tile)		
MATERIAL LOCATION:	Rooms: 125, 114, 113, 112		
MATERIAL QUANTITY:	240	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:	Replacement Tile		

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled VFT (Replacement Tile)**

MATERIAL LOCATION: **Rooms: 125, 114, 113, 112**

MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 07/01/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	59A				
MATERIAL DESCRIPTION:	12" x 12" Brown Speckled VFT MASTIC (Replacement Tile)				
MATERIAL LOCATION:	Rooms: 125, 114, 113, 112				
MATERIAL QUANTITY:	240	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:	Replacement Tile				

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **59A**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled VFT MASTIC (Replacement Tile)**

MATERIAL LOCATION: **Rooms: 125, 114, 113, 112**

MATERIAL QUANTITY: **240** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	55			
MATERIAL DESCRIPTION:	12" x12" Light Beige w/White Specks VFT (Replacement Tile)			
MATERIAL LOCATION:	Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102			
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	MODERATE		CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
		DAMAGE REASON:		
COMMENTS:	Replacement Tile			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12" x12" Light Beige w/White Specks VFT (Replacement Tile)**

MATERIAL LOCATION: **Rooms: 226, 225, 223, 221, 219, 217, 216, 214, 213, 212, 211, 210, 209, 208, 206, 205, 204, 203, 202, 201, 2nd Fl. Corridor by Room 216, 116, 110, 108, 106, 104, 102**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	12" x 12" Sand VFT		
MATERIAL LOCATION:	Room 207, Principal's Office Toilet		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" Sand VFT**

MATERIAL LOCATION: **Room 207, Principal's Office Toilet**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	56A				
MATERIAL DESCRIPTION:	12" x 12" Sand VFT MASTIC				
MATERIAL LOCATION:	Room 207, Principal's Office Toilet				
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **56A**

MATERIAL DESCRIPTION: **12" x 12" Sand VFT MASTIC**

MATERIAL LOCATION: **Room 207, Principal's Office Toilet**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	58A			
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Speckled VFT MASTIC (Replacement Tile)			
MATERIAL LOCATION:	Rooms: 125, 123, 121, 119, 117			
MATERIAL QUANTITY:	280	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:		
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
COMMENTS:	Replacement Tile			

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BULDING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **58A**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Speckled VFT MASTIC (Replacement Tile)**

MATERIAL LOCATION: **Rooms: 125, 123, 121, 119, 117**

MATERIAL QUANTITY: **280** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/01/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24401	BUIDLING ID:	4680
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Roberto Rivera		
SCHOOL NAME:	Mayer School	INSPECTION DATE:	6/3/2025		
ADDRESS:	2250 N. Clifton Avenue	IDPH LICENSE NO:	100-06327		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	Terrazzo Flooring		
MATERIAL LOCATION:	All Stairwells, 1st Floor Lobby by GYM		
MATERIAL QUANTITY:	3800	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 06/03/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24401** BUIDLING ID: **4680**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Mayer School** REVIEW DATE: **7/1/2025**

ADDRESS: **2250 N. Clifton Avenue** IDPH LICENSE NO: **100-06327**

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Terrazzo Flooring**

MATERIAL LOCATION: **All Stairwells, 1st Floor Lobby by GYM**

MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **07/01/2025**

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

## APPENDIX B

---

### Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois

**ROBERTO RIVERA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

2/28/2022



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
**100 - 06327**

ISSUED  
**2/28/2022**

EXPIRES  
**05/15/2023**

**ROBERTO RIVERA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **06327**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 06327</b>	ISSUED <b>2/28/2022</b>	EXPIRES <b>05/15/2023</b>	SUPERVISOR/WORKER INSPECTOR	1/13/2023 5/17/2022
<b>ROBERTO RIVERA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/13/2023
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**

*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois

**ROBERTO RIVERA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/30/202

ID NUMBER

**100 - 06327**

ISSUED  
**4/30/2025**

EXPIRES  
**05/15/2026**

**ROBERTO RIVERA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **06327**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

	<b>ASBESTOS PROFESSIONAL LICENSE</b>		
ID NUMBER <b>100 - 06327</b>	ISSUED <b>4/30/2025</b>	EXPIRES <b>05/15/2026</b>	
<b>ROBERTO RIVERA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612			
Environmental Health			
		<b>ENDORSEMENTS</b> SUPERVISOR/WORKER INSPECTOR	<b>TC EXPIRES</b> 1/11/2026 3/7/2026
		PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/11/2026
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
**100 - 06327**

ISSUED  
**4/5/2024**

EXPIRES  
**05/15/2025**

ROBERTO RIVERA  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



**ROBERTO RIVERA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/5/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **06327**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 06327</b>	ISSUED <b>4/5/2024</b>	EXPIRES <b>05/15/2025</b>	SUPERVISOR/WORKER INSPECTOR	1/13/2025 3/18/2025
<b>ROBERTO RIVERA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			PROJECT MANAGER AIR SAMPLING PROFESSIONAL	1/13/2025
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>				

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Roberto Rivera**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: BIR2503070923

Course Credit Hours: BIR 4 Hrs.

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Roberto Rivera**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 4/18/2022

Exam Date: 4/18/2022

Expiration Date: 4/18/2023

Certificate Number: BIR2204181081

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Roberto Rivera

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/18/2024

Exam Date: 3/18/2024

Expiration Date: 3/18/2025

Certificate Number: BIR2403181278

Course Credit Hours: BIR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

*Kathy DeSalvo*  
Kathy DeSalvo, Director



## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

*Kathy DeSalvo*  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

7/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 04019</b>	ISSUED <b>7/8/2024</b>	EXPIRES <b>05/15/2025</b>	INSPECTOR	5/6/2025
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	5/6/2025
			AIR SAMPLING PROFESSIONAL <b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 5/6/2024

Exam Date: 5/6/2024

Expiration Date: 5/6/2025


Certificate Number: MPR2405061823

Course Credit Hours: MPR 8 Hours

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois



ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/1/2022
MANAGEMENT PLANNER	11/1/2022
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Ill

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/30/2026

ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 04019

ISSUED  
4/30/2025

EXPIRES  
05/15/2026

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/6/2025
MANAGEMENT PLANNER	4/2/2026
AIR SAMPLING PROFESSIONAL	
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*

**Reliable  
Environmental  
Solutions, Inc.  R E S**

*This is to certify that* **Arturo Saenz**

*has on 4/2/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: April 2, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: April 2, 2025

Expiration Date: April 2, 2026

Certificate Number: MPR/0560



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed