

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2375
SCHOOL NAME: Nobel School
ADDRESS OF SCHOOL: 4127 W. Hirsch Street
CITY: Chicago, IL, 60651

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/29/2022


If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/16/2025 ENROLLMENT 543
IDPH INSPECTOR LICENSE NUMBER: 100-11093
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila
IDPH MP LICENSE NUMBER: 100-04019
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

 6/11/2025
Signature of Designated Person Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____
School has been closed. Date closed: _____
School building has been demolished. Date: _____
School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Nobel School

4127 W. Hirsch Street
Chicago, IL, 60651

Unit: 24691
Building ID: 5110

IDPH ID Number: 14-016-2990-2375

REPORT DATE:
Wednesday, June 11, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Specialty Consulting, Inc.

2942 W. Van Buren Street
Chicago, IL, 60612
Phone (312) 319-7575
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/11/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 24691 Region: 02 IDPH ID: 14-016-2990-2375

School: Nobel School Building ID: 5110

Address: 4127 W. Hirsch Street

Chicago, IL, 60651

Building Contact: Ramirez, Luis Contact Phone: 2198412763

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/16/2025

Review Date: 06/11/2025

Inspector: David Avila Inspector IDPH License: 100-11093
Management Planner: Arturo Saenz Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,
Specialty Consulting, Inc.



Arturo Saenz
100-04019

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 11, 2025

RE: Nobel School, Unit 24691
4127 W. Hirsch Street
Chicago, IL, 60651

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Nobel School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Nobel School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Nobel School Unit: 24691 Region: 02
Address: 4127 W. Hirsch Street Chicago, IL, 60651
IDPH ID: 14-016-2990-2375 Building ID: 5110
Contact: Ramirez, Luis Phone: 2198412763

2. Description of Facility

Original Construction: 1910 Additional Construction:
Total Square Footage: 75800 No of Floors: 4
Current Occupancy: 543

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.
Contact: Jigar Shah
Address 2942 W. Van Buren Street
Phone: (312) 319-7575 Fax: (312) 319-7580

5. Inspector

Inspector Name: David Avila

Inspector IDPH license # 100-11093
Reinspection Date: 5/16/2025

Signature:
Date: 5/16/2025



6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

Signature:
Date: 06/11/2025




7. Review Date: 06/11/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/11/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Nobel School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 5110:

B. The following new homogenous areas have been identified for Building 5110:

32

Drywall System

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

| | |
|-----|----------------------------------------------------------|
| 03 | 12"x12" Tan, Brown & White Floor Tile |
| 06 | 12"x12" Tan, Brown & White Floor Tile Mastic |
| 09 | 9"x9" Beige Floor Tile Mastic |
| 10 | 12"x12" Tan Floor Tile |
| 11 | 12"x12" Tan Floor Tile Mastic |
| 12 | Red & Brown Linoleum (under the plywood) |
| 13 | Red & Brown Linoleum Mastic (under the plywood) |
| 17 | Hardwood floors |
| 18 | Hardwood floors |
| 19 | 12"x12" Gray Floor Tile |
| 21 | 12"x12" White Floor Tile |
| 24 | 12"x12" Blue Floor Tile |
| 25 | 12"x12" Blue Floor Tile Mastic |
| 26 | Ceramic Tile Grout |
| 27 | Ceramic Tile Adhesive |
| 28 | 12"x12" White Floor Tile |
| 29 | 12"x12" White Floor Tile Mastic |
| 30 | Terrazzo |
| 31 | 12" x 12" Blue with gray and white streaks VFT |
| 31A | 12" x 12" Blue with gray and white streaks VFT Mastic |
| 32 | Drywall System |

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Nobel School Building 5110 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Nobel School **Unit** 24691 **Building ID** 5110
Address 4127 W. Hirsch Street **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|-------------------------------------------------|-------------------|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| 03 | 12"x12" Tan, Brown & White Floor Tile | 2,200 | SF | Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 06 | 12"x12" Tan, Brown & White Floor Tile Mastic | 2,200 | SF | Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 08 | 9"x9" Beige Floor Tile | 250 | SF | Engineer's Office | CHR | MISC | N | LOC | 10 | | No | ACBM with the potential for damage | 3 | MODERATE |
| 09 | 9"x9" Beige Floor Tile Mastic | 250 | SF | Engineer's Office | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 10 | 12"x12" Tan Floor Tile | 2,000 | SF | Auditorium Balcony | ASSUMED | MISC | N | LOC | 8 | | No | ACBM with the potential for damage | 3 | MODERATE |
| 11 | 12"x12" Tan Floor Tile Mastic | 2,000 | SF | Auditorium Balcony | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 12 | Red & Brown Linoleum (under the plywood) | 300 | SF | Gymnasium Supply Closet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 13 | Red & Brown Linoleum Mastic (under the plywood) | 300 | SF | Gymnasium Supply Closet | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 14 | 9"x9" Beige & Brown Floor Tile - ABATED | | | 2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell | ABATED | MISC | | | 0 | | | | | |
| 15 | 9"x9" Beige & Brown Floor Tile Mastic - ABATED | | | 2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell | ABATED | MISC | | | | | | | | |
| 16 | Black Carpet Mastic - Abated | | | Room 004 | ABATED | MISC | | | | | | | | |
| 17 | Hardwood floors | 3,200 | SF | Rooms 201 & 210 (Not Observed), 305 & 309 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 18 | Hardwood floors | 1,500 | SF | Rooms 201, 210, 305 & 309 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 19 | 12"x12" Gray Floor Tile | 350 | SF | Room 001 (Kindergarten - Art | ASSUMED | MISC | N | LOC | 3 | | No | ACBM with the potential for damage | 3 | MODERATE |

Chicago Public Schools

School Nobel School **Unit** 24691 **Building ID** 5110
Address 4127 W. Hirsch Street **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|-------------------------------------------------------|-------------------|----------------|-----------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | Room) | | | | | | | | | | |
| 20 | 12"x12" Gray Floor Tile Mastic | 350 | SF | Room 001 (Kindergarten - Art Room) | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 21 | 12"x12" White Floor Tile | 350 | SF | Room 001 (Kindergarten - Art Room) | ASSUMED | MISC | N | LOC | 3 | | No | ACBM with the potential for damage | 3 | MODERATE |
| 22 | 12"x12" White Floor Tile Mastic | 350 | SF | Room 001 (Kindergarten - Art Room) | CHR | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 24 | 12"x12" Blue Floor Tile | 1,100 | SF | Rooms 003/004 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 25 | 12"x12" Blue Floor Tile Mastic | 1,100 | SF | Rooms 003/004 | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 26 | Ceramic Tile Grout | 600 | SF | Washrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 27 | Ceramic Tile Adhesive | 600 | SF | Washrooms | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 28 | 12"x12" White Floor Tile | 70 | SF | Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | MODERATE |
| 29 | 12"x12" White Floor Tile Mastic | 70 | SF | Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 30 | Terrazzo | 40 | SF | Room 001 Bathroom | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 31 | 12" x 12" Blue with gray and white streaks VFT | 210 | SF | Ground floor resource room | ASSUMED | MISC | N | NONE | | | No | ACBM with the potential for damage | | MODERATE |
| 31A | 12" x 12" Blue with gray and white streaks VFT Mastic | 210 | SF | Ground floor resource room | ASSUMED | MISC | N | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| 32 | Drywall System | 1,600 | SF | 3rd Floor Boys and Girls Toilet and 1st Floor Boys and Girls Toilet | ASSUMED | MISC | N | NONE | 0 | | | ACBM with the potential for damage | | MODERATE |
| D | MJP E/F/V on Fiberglass Pipe Insulation | 116 | FITTING | 1st, 2nd , 3rd Fl Boys & Girls Toilets, Eng. & 1st Fl Teach Toilet, Rm | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Nobel School **Unit** 24691 **Building ID** 5110
Address 4127 W. Hirsch Street **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category | Damage Category | Damage Reason | Disturbance Potential |
|-------|----------------------------------------|-------------------|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|------------------------------------|---------------|-----------------------|
| | | | | 003, N & S Bsmt Playrooms | | | | | | | | | | |
| E | Cardboard Pipe Insulation | 1,163 | LF | N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| F | Aircell Pipe Insulation | 55 | LF | Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room, 004 | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| G | MJP E/F/V on Aircell Pipe Insulation | 10 | FITTING | Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |
| H | MJP E/F/V on Cardboard Pipe Insulation | 108 | FITTING | N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room | CHR | TSI | Y | NONE | 0 | | No | ACBM with the potential for damage | | LOW |

Chicago Public Schools

School Nobel School Unit 24691 Building ID 5110
Address 4127 W. Hirsch Street Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| |
|---------------------------------------------------|
| Reinspection Date <u>5/16/2025</u> |
| Inspector Name <u>David Avila</u> |
| <u>100-11093</u> <u>5/15/2026</u> |
| Inspector's IDPH License Number / Expiration Date |

Inspector's Comments

| HA Number: | Inspector Comments: |
|------------|---------------------|
| 03 | |
| 06 | |
| 08 | |
| 09 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |
| 22 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | |
| 30 | |

Chicago Public Schools

School Nobel School **Unit** 24691 **Building ID** 5110
Address 4127 W. Hirsch Street **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Inspector's Comments are Summarized at the End of the Report

| HA Number: | Inspector Comments: |
|------------|------------------------------------------|
| 31 | |
| 31A | |
| 32 | |
| D | |
| E | 140 LF of friable ACM from all bathrooms |
| F | |
| G | |
| H | |

Table II
Management Planner's Review

Chicago Public Schools

School Nobel School

Unit 24691

Building ID 5110

Address 4127 W. Hirsch Street

Chicago, IL, 60651

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|-------------------------------------------------|-------------------|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 03 | 12"x12" Tan, Brown & White Floor Tile | 2,200 | SF | Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 06 | 12"x12" Tan, Brown & White Floor Tile Mastic | 2,200 | SF | Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 08 | 9"x9" Beige Floor Tile | 250 | SF | Engineer's Office | Chrysotile | MISC | No | 10 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 09 | 9"x9" Beige Floor Tile Mastic | 250 | SF | Engineer's Office | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 10 | 12"x12" Tan Floor Tile | 2,000 | SF | Auditorium Balcony | Assumed | MISC | No | 8 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 11 | 12"x12" Tan Floor Tile Mastic | 2,000 | SF | Auditorium Balcony | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 12 | Red & Brown Linoleum (under the plywood) | 300 | SF | Gymnasium Supply Closet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 13 | Red & Brown Linoleum Mastic (under the plywood) | 300 | SF | Gymnasium Supply Closet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 14 | 9"x9" Beige & Brown Floor Tile - ABATED | | | 2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell | Abated | MISC | | 0 | | | |
| 15 | 9"x9" Beige & Brown Floor Tile Mastic - ABATED | | | 2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell | Abated | MISC | | | | | |
| 16 | Black Carpet Mastic - Abated | | | Room 004 | Abated | MISC | | | | | |
| 17 | Hardwood floors | 3,200 | SF | Rooms 201 & 210 (Not Observed), 305 & 309 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 18 | Hardwood floors | 1,500 | SF | Rooms 201, 210, 305 & 309 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 19 | 12"x12" Gray Floor Tile | 350 | SF | Room 001 (Kindergarten - Art Room) | Assumed | MISC | No | 3 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 20 | 12"x12" Gray Floor Tile Mastic | 350 | SF | Room 001 (Kindergarten - Art Room) | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 21 | 12"x12" White Floor Tile | 350 | SF | Room 001 (Kindergarten - Art Room) | Assumed | MISC | No | 3 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 22 | 12"x12" White Floor Tile Mastic | 350 | SF | Room 001 (Kindergarten - Art Room) | Chrysotile | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 24 | 12"x12" Blue Floor Tile | 1,100 | SF | Rooms 003/004 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 25 | 12"x12" Blue Floor Tile Mastic | 1,100 | SF | Rooms 003/004 | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 26 | Ceramic Tile Grout | 600 | SF | Washrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 27 | Ceramic Tile Adhesive | 600 | SF | Washrooms | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 28 | 12"x12" White Floor Tile | 70 | SF | Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 29 | 12"x12" White Floor Tile Mastic | 70 | SF | Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Nobel School

Unit 24691

Building ID 5110

Address 4127 W. Hirsch Street

Chicago, IL, 60651

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Num | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Quantity | Damage Units | Damage Category | Response |
|--------|-------------------------------------------------------|-------------------|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-----------------|--------------|--------------------------------------|-----------------|
| 30 | Terrazzo | 40 | SF | Room 001 Bathroom | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31 | 12" x 12" Blue with gray and white streaks VFT | 210 | SF | Ground floor resource room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 31A | 12" x 12" Blue with gray and white streaks VFT Mastic | 210 | SF | Ground floor resource room | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| 32 | Drywall System | 1,600 | SF | 3rd Floor Boys and Girls Toilet and 1st Floor Boys and Girls Toilet | Assumed | MISC | No | 0 | SF | 6 ACBM with the potential for damage | Follow O&M Plan |
| D | MJP E/F/V on Fiberglass Pipe Insulation | 116 | FITTING | 1st, 2nd , 3rd Fl Boys & Girls Toilets, Eng. & 1st Fl Teach Toilet, Rm 003, N & S Bsmt Playrooms | Chrysotile | TSI | Yes | 0 | FITTING | 6 ACBM with the potential for damage | Follow O&M Plan |
| E | Cardboard Pipe Insulation | 1,163 | LF | N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| F | Aircell Pipe Insulation | 55 | LF | Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room, 004 | Chrysotile | TSI | Yes | 0 | LF | 6 ACBM with the potential for damage | Follow O&M Plan |
| G | MJP E/F/V on Aircell Pipe Insulation | 10 | FITTING | Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room | Chrysotile | TSI | Yes | 0 | FITTING | 6 ACBM with the potential for damage | Follow O&M Plan |
| H | MJP E/F/V on Cardboard Pipe Insulation | 108 | FITTING | N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room | Chrysotile | TSI | Yes | 0 | FITTING | 6 ACBM with the potential for damage | Follow O&M Plan |

Chicago Public Schools

School Nobel School

Unit 24691

Building ID 5110

Address 4127 W. Hirsch Street

Chicago, IL, 60651

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| | |
|------------------------------------|--------------|
| Review Date | 6/11/2025 |
| Manager Planner Name | Arturo Saenz |
| 100-04019 | 5/15/2026 |
| Manager IDPH License No/Expiration | |

| HA Number | Management Comments |
|-----------|---------------------|
| 03 | |
| 06 | |
| 08 | |
| 09 | |
| 10 | |
| 11 | |
| 12 | |
| 13 | |
| 14 | |
| 15 | |
| 16 | |
| 17 | |
| 18 | |
| 19 | |
| 20 | |
| 21 | |

Chicago Public Schools

School Nobel School

Unit 24691

Building ID 5110

Address 4127 W. Hirsch Street

Chicago, IL, 60651

Region 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

Management Planner's Comments Summarized at the End of the Report

| HA Number | Management Comments |
|-----------|---------------------|
| 22 | |
| 24 | |
| 25 | |
| 26 | |
| 27 | |
| 28 | |
| 29 | |
| 30 | |
| 31 | |
| 31A | |
| 32 | |
| D | |
| E | |
| F | |
| G | |
| H | |

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|-------------------------------|------------------|--------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUILDING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------------------|----------|-----------|
| HOMOGENEOUS AREA: | 03 | | |
| MATERIAL DESCRIPTION: | 12"x12" Tan, Brown & White Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------------------------------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet | | |
| MATERIAL QUANTITY: | 2200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **12"x12" Tan, Brown & White Floor Tile**

MATERIAL LOCATION: **Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|----------------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 06 | | |
| MATERIAL DESCRIPTION: | 12"x12" Tan, Brown & White Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------------------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet | | |
| MATERIAL QUANTITY: | 2200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **06**

MATERIAL DESCRIPTION: **12"x12" Tan, Brown & White Floor Tile Mastic**

MATERIAL LOCATION: **Kitchen Office, Rm 305 and 309, between 2nd and 3rd teacher's toilet**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 08 | | |
| MATERIAL DESCRIPTION: | 9"x9" Beige Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Remove | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|-------------------|-----------------|----|
| DAMAGE REASON: | Deterioration | | |
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Engineer's Office | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **10** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 09 | | |
| MATERIAL DESCRIPTION: | 9"x9" Beige Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Engineer's Office | | |
| MATERIAL QUANTITY: | 250 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **9"x9" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Engineer's Office**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 10 | | |
| MATERIAL DESCRIPTION: | 12"x12" Tan Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|--------------------|-----------------|----|
| DAMAGE REASON: | Deterioration | | |
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Auditorium Balcony | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**

MATERIAL LOCATION: **Auditorium Balcony**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 11 | | |
| MATERIAL DESCRIPTION: | 12"x12" Tan Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Auditorium Balcony | | |
| MATERIAL QUANTITY: | 2000 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium Balcony**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|------------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 12 | | |
| MATERIAL DESCRIPTION: | Red & Brown Linoleum (under the plywood) | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Gymnasium Supply Closet | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Red & Brown Linoleum (under the plywood)**

MATERIAL LOCATION: **Gymnasium Supply Closet**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|-------------------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 13 | | |
| MATERIAL DESCRIPTION: | Red & Brown Linoleum Mastic (under the plywood) | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Gymnasium Supply Closet | | |
| MATERIAL QUANTITY: | 300 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|------------------------|---------------------|--------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: 13

MATERIAL DESCRIPTION: Red & Brown Linoleum Mastic (under the plywood)

MATERIAL LOCATION: Gymnasium Supply Closet

MATERIAL QUANTITY: 300 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: 06/11/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUILDING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: 9"x9" Beige & Brown Floor Tile - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: 14

MATERIAL DESCRIPTION: 9"x9" Beige & Brown Floor Tile - ABATED

MATERIAL LOCATION: **2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY: 0

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 06/11/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUILDING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 15

MATERIAL DESCRIPTION: 9"x9" Beige & Brown Floor Tile Mastic - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

 Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9"x9" Beige & Brown Floor Tile Mastic - ABATED**

MATERIAL LOCATION: **2nd Floor Teacher's Toilet, 3rd Floor Men's Toilet, North & South Stairwells, Teacher's toilet between basement and first floor on south stairwell**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Black Carpet Mastic - Abated**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 004**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Black Carpet Mastic - Abated**

MATERIAL LOCATION: **Room 004**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 17 | | |
| MATERIAL DESCRIPTION: | Hardwood floors | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rooms 201 & 210 (Not Observed), 305 & 309 | | |
| MATERIAL QUANTITY: | 3200 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Hardwood floors**

MATERIAL LOCATION: **Rooms 201 & 210 (Not Observed), 305 & 309**

MATERIAL QUANTITY: **3200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 18 | | |
| MATERIAL DESCRIPTION: | Hardwood floors | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 201, 210, 305 & 309 | | |
| MATERIAL QUANTITY: | 1500 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Hardwood floors**

MATERIAL LOCATION: **Rooms 201, 210, 305 & 309**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 19 | | |
| MATERIAL DESCRIPTION: | 12"x12" Gray Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|------------------------------------|-----------------|----|
| DAMAGE REASON: | Deterioration | | |
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 001 (Kindergarten - Art Room) | | |
| MATERIAL QUANTITY: | 350 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile**

MATERIAL LOCATION: **Room 001 (Kindergarten - Art Room)**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 20 | | |
| MATERIAL DESCRIPTION: | 12"x12" Gray Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 001 (Kindergarten - Art Room) | | |
| MATERIAL QUANTITY: | 350 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12"x12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 001 (Kindergarten - Art Room)**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 21 | | |
| MATERIAL DESCRIPTION: | 12"x12" White Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

| | | | |
|------------------------|------------------------------------|-----------------|----|
| DAMAGE REASON: | Deterioration | | |
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 001 (Kindergarten - Art Room) | | |
| MATERIAL QUANTITY: | 350 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile**

MATERIAL LOCATION: **Room 001 (Kindergarten - Art Room)**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **3** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 22 | | |
| MATERIAL DESCRIPTION: | 12"x12" White Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Room 001 (Kindergarten - Art Room) | | |
| MATERIAL QUANTITY: | 350 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**

MATERIAL LOCATION: **Room 001 (Kindergarten - Art Room)**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 24 | | |
| MATERIAL DESCRIPTION: | 12"x12" Blue Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Rooms 003/004 | | |
| MATERIAL QUANTITY: | 1100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile**

MATERIAL LOCATION: **Rooms 003/004**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 25 | | |
| MATERIAL DESCRIPTION: | 12"x12" Blue Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|---------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Rooms 003/004 | | |
| MATERIAL QUANTITY: | 1100 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 003/004**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 26 | | |
| MATERIAL DESCRIPTION: | Ceramic Tile Grout | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Washrooms | | |
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Washrooms**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 27 | | |
| MATERIAL DESCRIPTION: | Ceramic Tile Adhesive | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Washrooms | | |
| MATERIAL QUANTITY: | 600 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Ceramic Tile Adhesive**

MATERIAL LOCATION: **Washrooms**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 28 | | |
| MATERIAL DESCRIPTION: | 12"x12" White Floor Tile | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------------------------------------------------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell | | |
| MATERIAL QUANTITY: | 70 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile**

MATERIAL LOCATION: **Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 29 | | |
| MATERIAL DESCRIPTION: | 12"x12" White Floor Tile Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------------------------------------------------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell | | |
| MATERIAL QUANTITY: | 70 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" White Floor Tile Mastic**

MATERIAL LOCATION: **Second Floor Teacher's Lounge, Teacher's toilet between basement and first floor on south stairwell**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 30 | | |
| MATERIAL DESCRIPTION: | Terrazzo | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Room 001 Bathroom | | |
| MATERIAL QUANTITY: | 40 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Room 001 Bathroom**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|------------------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 31 | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue with gray and white streaks VFT | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-----------------------------------|-----------------|-----------|
| DISTURBANCE POTENTIAL: | MODERATE | | |
| MATERIAL LOCATION: | Ground floor resource room | | |
| MATERIAL QUANTITY: | 210 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Blue with gray and white streaks VFT**

MATERIAL LOCATION: **Ground floor resource room**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|-------------------------------------------------------|----------|----|
| HOMOGENEOUS AREA: | 31A | | |
| MATERIAL DESCRIPTION: | 12" x 12" Blue with gray and white streaks VFT Mastic | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Assumed | FRIABLE: | No |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|----------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Ground floor resource room | | |
| MATERIAL QUANTITY: | 210 | MATERIAL UNITS: | SF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | SF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **31A**

MATERIAL DESCRIPTION: **12" x 12" Blue with gray and white streaks VFT Mastic**

MATERIAL LOCATION: **Ground floor resource room**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|-----------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | D | | |
| MATERIAL DESCRIPTION: | MJP E/F/V on Fiberglass Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|--------------------------------------------------------------------------------------------------|-----------------|---------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | 1st, 2nd , 3rd Fl Boys & Girls Toilets, Eng. & 1st Fl Teach Toilet, Rm 003, N & S Bsmt Playrooms | | |
| MATERIAL QUANTITY: | 116 | MATERIAL UNITS: | FITTING |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | FITTING |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **1st, 2nd , 3rd Fl Boys & Girls Toilets, Eng. & 1st Fl Teach Toilet, Rm 003, N & S Bsmt Playrooms**

MATERIAL QUANTITY: **116** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | E | | |
| MATERIAL DESCRIPTION: | Cardboard Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room**

MATERIAL QUANTITY: **1163** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS: **140 LF of friable ACM from all bathrooms**

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room**

MATERIAL QUANTITY: **1163** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | F | | |
| MATERIAL DESCRIPTION: | Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|------------------------------------------------------------------|-----------------|----|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room, 004 | | |
| MATERIAL QUANTITY: | 55 | MATERIAL UNITS: | LF |
| DAMAGE QUANTITY: | | DAMAGE UNITS: | LF |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room, 004**

MATERIAL QUANTITY: **55** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|--------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | G | | |
| MATERIAL DESCRIPTION: | MJP E/F/V on Aircell Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

| | | | |
|------------------------|-------------------------------------------------------------|-----------------|---------|
| DISTURBANCE POTENTIAL: | LOW | | |
| MATERIAL LOCATION: | Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room | | |
| MATERIAL QUANTITY: | 10 | MATERIAL UNITS: | FITTING |
| DAMAGE QUANTITY: | DAMAGE UNITS: FITTING | | |
| COMMENTS: | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|------------------------|---------------------|--------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Boiler Room South Corridor, 2nd Fl Boys Toilet, Boiler Room**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM PREVIOUS INSPECTION

| | | | |
|----------------------------------|----------------------------------------|----------|-----|
| HOMOGENEOUS AREA: | H | | |
| MATERIAL DESCRIPTION: | MJP E/F/V on Cardboard Pipe Insulation | | |
| HISTORICAL AHERA DAMAGE CATEGORY | 6 ACBM with the potential for damage | | |
| HISTORICAL DAMAGE REASON: | | | |
| HISTORICAL RESPONSE ACTION: | Follow O&M Plan | | |
| ASBESTOS TYPE: | Chrysotile | FRIABLE: | Yes |

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room**

MATERIAL QUANTITY: **108** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: MATERIAL UNITS: **FITTING**

COMMENTS:

Inspector's Signature:



Date: **05/16/2025**

Chicago Public Schools

Specialty Consulting, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

| | | | | | |
|--------------|-------------------------------|---------------------|---------------------|--------------|-------------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | MANAGEMENT PLANNER: | Arturo Saenz | | |
| SCHOOL NAME: | Nobel School | REVIEW DATE: | 6/11/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **N & S Playrooms, Boiler Room S Corridor, 1st Fl Teachers Toilet, Janitors Closet Next Teach Toilet, Boiler Room, Room 001 Bathroom, Room 005 Storage Room**

MATERIAL QUANTITY: **108** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/11/2025**

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

| | | | | | |
|--------------|------------------------|------------------|-------------|--------------|------|
| LEA NAME: | Chicago Public Schools | UNIT NUMBER: | 24691 | BUIDLING ID: | 5110 |
| CITY/STATE: | Chicago, Illinois | AHERA INSPECTOR: | David Avila | | |
| SCHOOL NAME: | Nobel School | INSPECTION DATE: | 5/16/2025 | | |
| ADDRESS: | 4127 W. Hirsch Street | IDPH LICENSE NO: | 100-11093 | | |

INFORMATION FROM CURRENT INSPECTION

| | | | | |
|------------------------|---------------------------------------------------------------------|-----------------|------------|--|
| HOMOGENEOUS AREA: | 32 | | | |
| MATERIAL DESCRIPTION: | Drywall System | | | |
| MATERIAL LOCATION: | 3rd Floor Boys and Girls Toilet and 1st Floor Boys and Girls Toilet | | | |
| MATERIAL QUANTITY: | 1600 | MATERIAL UNITS: | SF | |
| MATERIAL CATEGORY: | MISC | FRIABLE: | No | |
| ASBESTOS TYPE: | Assumed | | | |
| DISTURBANCE POTENTIAL: | MODERATE | | CONDITION: | |
| AHERA DAMAGE CATEGORY: | 6 ACBM with the potential for damage | | | |
| ACCESSIBILITY: | Within Reach | DAMAGE REASON: | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | |
| DAMAGE QUANTITY: | 0 | DAMAGE REASON: | | |
| COMMENTS: | | | | |

Inspector's Signature:



Date: 05/16/2025

Chicago Public Schools

Specialty Consulting, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24691** BUIDLING ID: **5110**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Nobel School** REVIEW DATE: **6/11/2025**

ADDRESS: **4127 W. Hirsch Street** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **Drywall System**

MATERIAL LOCATION: **3rd Floor Boys and Girls Toilet and 1st Floor Boys and Girls Toilet**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:


Management Planner's Signature:  Date: **06/11/2025**

APPENDIX B

Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527
(630) 655-3900 | www.otssafety.com

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092141

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/10/2021

Exam Date: 9/10/2021

Expiration Date: 9/10/2022

Certificate Number: BIR2109101942


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, IL

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/2025



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

|  ASBESTOS PROFESSIONAL LICENSE | | ENDORSEMENTS | TC EXPIRES |
|-----------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|
| ID NUMBER 100 - 11093 | ISSUED 4/30/2025 | EXPIRES 05/15/2026 | INSPECTOR 9/13/2025 |
| DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health |  | PROJECT MANAGER AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | 9/14/2025 |
| PROTECTING HEALTH, IMPROVING LIVES <i>Nationally Accredited by PHAB</i> | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2409132631
Course Date: 9/13/2024
Exam Date: 9/13/2024
Expiration Date: 9/13/2025



Issue Date: 9/13/2024

Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours



525-535 West Jefferson Street • Springfield, Illinois

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

2/28/2022



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 11093

ISSUED
2/28/2022 EXPIRES
05/15/2023

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11093**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| | | | | | |
|----------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|---------------------|-------------------|
| | | ASBESTOS PROFESSIONAL LICENSE | | ENDORSEMENTS | TC EXPIRES |
| ID NUMBER 100 - 11093 | ISSUED 2/28/2022 | EXPIRES 05/15/2023 | | INSPECTOR | 9/10/2022 |
| DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 | | PROJECT MANAGER AIR SAMPLING PROFESSIONAL <i>Alteration of this license shall result in legal action. This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</i> | | | |
| Environmental Health | | | | | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 11093

ISSUED
4/8/2024

EXPIRES
05/15/2025

DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health



DAVID AVILA
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE | | | ENDORSEMENTS | TC EXPIRES |
|---------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|
| ID NUMBER 100 - 11093 | ISSUED 4/8/2024 | EXPIRES 05/15/2025 | INSPECTOR | 9/15/2024 |
| DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health |  | | | PROJECT MANAGER AIR SAMPLING PROFESSIONAL |
| | | | Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

Kathy DeSalvo
Kathy DeSalvo, Director



Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that
Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

Kathy DeSalvo
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

7/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

| ASBESTOS PROFESSIONAL LICENSE | | | ENDORSEMENTS | TC EXPIRES |
|----------------------------------------------------------------------------------|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|
| ID NUMBER 100 - 04019 | ISSUED 7/8/2024 | EXPIRES 05/15/2025 | INSPECTOR | 5/6/2025 |
| ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health |  |  | MANAGEMENT PLANNER | 5/6/2025 |
| | | | AIR SAMPLING PROFESSIONAL Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Arturo Saenz

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 5/6/2024

Exam Date: 5/6/2024

Expiration Date: 5/6/2025

Certificate Number: MPR2405061823


Course Credit Hours: MPR 8 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois



ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612


2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

| ENDORSEMENTS | TC EXPIRES |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|
| INSPECTOR | 11/1/2022 |
| MANAGEMENT PLANNER | 11/1/2022 |
| AIR SAMPLING PROFESSIONAL | |
| Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate. | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Ill

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

4/30/2026

ASBESTOS
PROFESSIONAL
LICENSE

ID NUMBER
100 - 04019

ISSUED
4/30/2025

EXPIRES
05/15/2026

ARTURO SAENZ
2942 W VAN BUREN ST
CHICAGO, IL 60612

Environmental Health




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

| ENDORSEMENTS | TC EXPIRES |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|
| INSPECTOR | 5/6/2025 |
| MANAGEMENT PLANNER | 4/2/2026 |
| AIR SAMPLING PROFESSIONAL | |
| <p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p> | |

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB

**Reliable
Environmental
Solutions, Inc. R E S**

This is to certify that **Arturo Saenz**

*has on 4/2/25, in Springfield, Illinois,
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

Asbestos Management Planner Refresher Training

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)
and passed the associated examination with a score of 70% or higher*

Course Date: April 2, 2025

COURSE LENGTH: 4 HOURS

Examination Date: April 2, 2025

Expiration Date: April 2, 2026

Certificate Number: MPR/0560



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois 217.787.9800 www.ReliableEnv.com

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

| | CODE | KEY |
|--------------------------|------|----------------------------------------|
| MATERIAL | ACBM | Asbestos Containing Building Materials |
| MATERIAL CATEGORY | MISC | Miscellaneous |
| | SURF | Surfacing |
| | TSI | Thermal System Insulation |
| MATERIAL UNITS | LF | Linear Feet |
| | SF | Square Feet |
| | CF | Cubic Feet |
| DAMAGE TYPE | Loc | Localized |
| | Dist | Distributed |