

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2383  
SCHOOL NAME: Onahan School  
ADDRESS OF SCHOOL: 6634 W Raven Street  
CITY: Chicago, IL, 60631

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 11/3/2022

If the address on this form is different than the address of the building, submit a written explanation.

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 1/30/2025 ENROLLMENT 626  
IDPH INSPECTOR LICENSE NUMBER: 100-11093  
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila  
IDPH MP LICENSE NUMBER: 100-07342  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jigar Shah

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 3/3/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Onahan School**

6634 W Raven Street  
Chicago, IL, 60631

Unit: 24761  
Building ID: 5190

IDPH ID Number: 14-016-2990-2383

**REPORT DATE:**  
Monday, March 03, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Specialty Consulting, Inc.**

2942 W. Van Buren Street  
Chicago, IL, 60612  
Phone (312) 319-7575  
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

03/03/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 24761      Region: 01      IDPH ID: 14-016-2990-2383

School: Onahan School      Building ID: 5190

Address: 6634 W Raven Street

Chicago, IL, 60631

Building Contact: Hennessy, Michael      Contact Phone: 7737106276

Current Building Owners: Chicago Public Schools

Reinspection Date: 1/30/2025

Review Date: 03/03/2025

Inspector: David Avila

Inspector IDPH License: 100-11093

Management Planner: Jigar Shah

Management Planner IDPH License: 100-07342

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Jigar Shah  
100-07342

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 03, 2025

RE: Onahan School, Unit 24761  
6634 W Raven Street  
Chicago, IL, 60631

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Onahan School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Onahan School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Onahan School      Unit: 24761      Region: 01  
Address: 6634 W Raven Street      Chicago, IL, 60631  
IDPH ID: 14-016-2990-2383      Building ID: 5190  
Contact: Hennessy, Michael      Phone: 7737106276

### 2. Description of Facility

Original Construction: 1928      Additional Construction: 1995  
Total Square Footage: 61130      No of Floors: 3  
Current Occupancy: 626

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575      Fax: (312) 319-7580

### 5. Inspector

Inspector Name: David Avila

Inspector IDPH license # 100-11093  
Reinspection Date: 1/30/2025

  
Signature:  
Date: 1/30/2025

### 6. Management Planner

Management Planner Name: Jigar Shah

Management Planner IDPH license # 100-07342


  
Signature:  
Date: 03/03/2025

### 7. Review Date: 03/03/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 3/3/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Onahan School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5190:

22	Cardboard Pipe Insulation
39	Aircell Pipe Insulation
40	MJP E/F/V on Aircell Pipe Insulation
65	MJP E/F/V on Cardboard Pipe Insulation

B. The following new homogenous areas have been identified for Building 5190:

104                    12" x 12" Brown w/ Specks VFT

105                    12" x 12" Brown w/ Specks VFT Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	Spray-on Fire Proofing
101	12" x 12" Beige w/ Tan Streaks VFT
101A	12" x 12" Beige w/ Tan Streaks VFT Mastic
102	12" X 12" Off-white streaked VFT
102A	12" X 12" Off-white streaked VFT Mastic
103	2' x 2' Light blue w/ blue streaks VFT
103A	2' x 2' Light Blue w/ Blue Streaks VFT Mastic
104	12" x 12" Brown w/ Specks VFT
105	12" x 12" Brown w/ Specks VFT Mastic
48	12"x12" White w/Tan Streaks VFT
50	12"x12" Brown w/White & Black Streaks VFT
67	12"x12" Beige w/ White Specs VFT
68	12"x12" Beige w/ White Specs VFT Mastic
69	12"x12" Brown w/ Black Specs VFT
70	12"x12" Brown w/ Black Specs VFT Mastic
71	12"x12" Black VFT
72	12"x12" Black VFT Mastic
73	12"x12" Blue VFT
74	12"x12" Blue VFT Mastic
87	Carpet Mastic
88	Terrazzo Floor
89	12" x 12" Gray Streaked VFT
90	12" x 12" Gray VFT Mastic
91	12" x 12" Blue Streaked VFT
92	12" x 12" Blue Streaked VFT Mastic
93	12" x 12" Light Blue Streaked VFT
94	12" x 12" Light Blue Streaked VFT Mastic
95	12" x 12" White with Gray Streaks VFT
96	12" x 12" White with Gray Streaks VFT Mastic
97	4' x 4' White Ceiling Tile
99	Decorative Plaster

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The

Management Plan was updated by Jigar Shah, IDPH License # 100-07342. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 10/9/2024

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Onahan School Building 5190 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
10	Hard Coat Plaster			Throughout - 1927 Building	NO_ACBM									
100	Spray-on Fire Proofing	3,000	SF	Lunch room and Kitchen (above ceiling tiles) - 1995 Building	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
101	12" x 12" Beige w/ Tan Streaks VFT	400	SF	Room 210 - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
101A	12" x 12" Beige w/ Tan Streaks VFT Mastic	400	SF	Room 210 - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
102	12" X 12" Off-white streaked VFT	400	SF	Room 210 - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
102A	12" X 12" Off-white streaked VFT Mastic	400	SF	Room 210 - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	2' x 2' Light blue w/ blue streaks VFT	1,000	SF	Auditorium & Balcony (not Observed), Projection Room, Front of stage & aisles	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
103A	2' x 2' Light Blue w/ Blue Streaks VFT Mastic	1,000	SF	Auditorium & Balcony (not observed), Projection Room, Front of stage & aisles	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
104	12" x 12" Brown w/ Specks VFT	250	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
105	12" x 12" Brown w/ Specks VFT Mastic	250	SF	Room 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	Cardboard Pipe Insulation	660	LF	Basement air and tunnel, coal room, AHU #4	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
26	9"x9" Tan VFT - ABATED			Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED	ABATED	MISC								
28	Aircell Duct Insulation (Abated)			SW, NW, S, & NE Unexcavated Spaces - 1927 Building (Abated)	ABATED	TSI								
36	Tank Lagging	800	SF	Pump Room, Store Room South Of Boiler Room - 1927	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
39	Aircell Pipe Insulation	1,000	SF	Basement air tunnel, coal room and AHU#4	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
40	MJP E/F/V on Aircell Pipe Insulation	250	FITTING	Basement air tunnel, Coal Room, and AHU#4	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
44	12" x 12" Cream w/Brown Streaks VFT	2,200	SF	1st and 2nd Floor Corridors - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
46	9"x9" Tan VFT Mastic - ABATED			Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED	ABATED	MISC								
47	12"x12" Cream w/Brown Streaks VFT Mastic	2,200	SF	1st and 2nd Floor Corridors - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	12"x12" White w/Tan Streaks VFT	1,300	SF	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
49	12"x12" White w/Tan Streaks VFT Mastic	1,300	SF	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12"x12" Brown w/White & Black Streaks VFT	1,300	SF	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
51	12"x12" Brown w/White & Black Streaks VFT Mastic	1,300	SF	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	9"x9" Brown VFT - ABATED			Room 209 (Library) (Under Carpet) - 1927 Building - ABATED	ABATED	MISC								
53	9"x9" Brown VFT Mastic - ABATED			Room 209 (Library) (Under Carpet) - 1927 Building - ABATED	ABATED	MISC								
54	9"x9" Brown w/Brown & White Streaks VFT	500	SF	Room 108 (Teacher's Restroom) - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
55	9"x9" Brown w/Brown & White Streaks VFT Mastic	500	SF	Room 108 (Teacher's Restroom) - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	9"x9" Beige w/Brown & Cream Streaks VFT	4,470	SF	Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
57	9"x9" Beige w/Brown & Cream Streaks VFT Mastic	4,470	SF	Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	9"x9" Beige VFT - ABATED			Small Hallway NW of Room 102 - 1927 Building - ABATED	ABATED	MISC								
59	9"x9" Beige VFT Mastic - ABATED			Small Hallway NW of Room 102 - 1927 Building - ABATED	ABATED	MISC								
60	9"x9" Gray VFT - ABATED			Room 102 - 1927 Building (ABATED)	ABATED	MISC								
61	9"x9" Gray VFT Mastic - ABATED			Room 102 - 1927 Building (ABATED)	ABATED	MISC								
62	12"x12" White VFT	600	SF	Main Office & Main Office Store Room - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
63	12"x12" White VFT Mastic	600	SF	Main Office & Main Office Store Room - 1927 Building	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	MJP E/F/V on Cardboard Pipe Insulation	180	FITTING	Basement air tunnel, cool room, and AHU#4	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		MODERATE
66	MJP E/F/V on Fiberglass Pipe Insulation			Throughout - 1927 Building	NO_ACBM	TSI								
67	12"x12" Beige w/ White Specs VFT	1,600	SF	Lunch Room - 1995 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
68	12"x12" Beige w/ White Specs VFT Mastic	1,600	SF	Lunch Room - 1995 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	12"x12" Brown w/ Black Specs VFT	1,300	SF	Lunch Room - 1995 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
70	12"x12" Brown w/ Black Specs VFT	1,300	SF	Lunch Room - 1995	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC) Specialty Consulting, Inc.**

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Under Carpet - 1927 Building (Abated)										
87	Carpet Mastic	1,100	SF	Auditorium (Not Observed), 209, Main Office, Principals Office - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88	Terrazzo Floor	3,500	SF	Stairwells (Throughout Building 1st to 3rd floors), Auditorium (Stairs to Stage), Auditorium (Balcony Stairwell), 1st Floor vestibules - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
89	12" x 12" Gray Streaked VFT	60	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
90	12" x 12" Gray VFT Mastic	60	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
91	12" x 12" Blue Streaked VFT	120	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
92	12" x 12" Blue Streaked VFT Mastic	120	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	12" x 12" Light Blue Streaked VFT	150	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
94	12" x 12" Light Blue Streaked VFT Mastic	150	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
95	12" x 12" White with Gray Streaks VFT	460	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
96	12" x 12" White with Gray Streaks VFT	460	SF	1st, 2nd and 3rd	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic			floor hall to new addition building - 1927 Building								potential for damage		
97	4' x 4' White Ceiling Tile	500	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
98	Heat Barrier Paper	0		Room 101 - Inside radiator (bench) cover along exterior wall - 1927 Building	ABATED	TSI								
99	Decorative Plaster	1,500	SF	Auditorium - 1927 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Onahan School Unit 24761 Building ID 5190  
Address 6634 W Raven Street Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>1/30/2025</u>
Inspector Name	<u>David Avila</u>
<b>100-11093</b>	<b>5/15/2026</b>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
10	
100	
101	
101A	
102	
102A	
103	
103A	
104	
105	
22	Damage Repaired
26	
28	
36	
39	Damage Repaired
40	Damage Repaired
44	
46	
47	
48	
49	
50	
51	
52	

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
53	
54	
55	
56	30 SF abated from room 101
57	30 SF abated from room 101
58	
59	
60	
61	
62	
63	
65	Damage Repaired
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	

# Chicago Public Schools

**School** Onahan School **Unit** 24761 **Building ID** 5190  
**Address** 6634 W Raven Street **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	Abated 2024
99	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Onahan School

**Unit** 24761

**Building ID** 5190

**Address** 6634 W Raven Street

Chicago, IL, 60631

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
10	Hard Coat Plaster			Throughout - 1927 Building	No ACBM						
100	Spray-on Fire Proofing	3,000	SF	Lunch room and Kitchen (above ceiling tiles) - 1995 Building	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	12" x 12" Beige w/ Tan Streaks VFT	400	SF	Room 210 - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101A	12" x 12" Beige w/ Tan Streaks VFT Mastic	400	SF	Room 210 - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" X 12" Off-white streaked VFT	400	SF	Room 210 - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102A	12" X 12" Off-white streaked VFT Mastic	400	SF	Room 210 - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	2' x 2' Light blue w/ blue streaks VFT	1,000	SF	Auditorium & Balcony (not Observed), Projection Room, Front of stage & aisles	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103A	2' x 2' Light Blue w/ Blue Streaks VFT Mastic	1,000	SF	Auditorium & Balcony (not observed), Projection Room, Front of stage & aisles	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" Brown w/ Specks VFT	250	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
105	12" x 12" Brown w/ Specks VFT Mastic	250	SF	Room 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Cardboard Pipe Insulation	660	LF	Basement air and tunnel, coal room, AHU #4	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
26	9"x9" Tan VFT - ABATED			Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED	Abated	MISC					
28	Aircell Duct Insulation (Abated)			SW, NW, S, & NE Unexcavated Spaces - 1927 Building (Abated)	Abated	TSI					
36	Tank Lagging	800	SF	Pump Room, Store Room South Of Boiler Room - 1927 Building	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Aircell Pipe Insulation	1,000	SF	Basement air tunnel, coal room and AHU#4	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	MJP E/F/V on Aircell Pipe Insulation	250	FITTING	Basement air tunnel, Coal Room, and AHU#4	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
44	12" x 12" Cream w/Brown Streaks VFT	2,200	SF	1st and 2nd Floor Corridors - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	9"x9" Tan VFT Mastic - ABATED			Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED	Abated	MISC					
47	12"x12" Cream w/Brown Streaks VFT Mastic	2,200	SF	1st and 2nd Floor Corridors - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	12"x12" White w/Tan Streaks VFT	1,300	SF	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12"x12" White w/Tan Streaks VFT Mastic	1,300	SF	3rd Floor Corridor, Room 204,	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Onahan School

**Unit** 24761

**Building ID** 5190

**Address** 6634 W Raven Street

Chicago, IL, 60631

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
50	12"x12" Brown w/White & Black Streaks VFT	1,300	SF	Engineers Office - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12"x12" Brown w/White & Black Streaks VFT Mastic	1,300	SF	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	9"x9" Brown VFT - ABATED			Room 209 (Library) (Under Carpet) - 1927 Building - ABATED	Abated	MISC					
53	9"x9" Brown VFT Mastic - ABATED			Room 209 (Library) (Under Carpet) - 1927 Building - ABATED	Abated	MISC					
54	9"x9" Brown w/Brown & White Streaks VFT	500	SF	Room 108 (Teacher's Restroom) - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	9"x9" Brown w/Brown & White Streaks VFT Mastic	500	SF	Room 108 (Teacher's Restroom) - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	9"x9" Beige w/Brown & Cream Streaks VFT	4,470	SF	Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	9"x9" Beige w/Brown & Cream Streaks VFT Mastic	4,470	SF	Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	9"x9" Beige VFT - ABATED			Small Hallway NW of Room 102 - 1927 Building - ABATED	Abated	MISC					
59	9"x9" Beige VFT Mastic - ABATED			Small Hallway NW of Room 102 - 1927 Building - ABATED	Abated	MISC					
60	9"x9" Gray VFT - ABATED			Room 102 - 1927 Building (ABATED)	Abated	MISC					
61	9"x9" Gray VFT Mastic - ABATED			Room 102 - 1927 Building (ABATED)	Abated	MISC					
62	12"x12" White VFT	600	SF	Main Office & Main Office Store Room - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12"x12" White VFT Mastic	600	SF	Main Office & Main Office Store Room - 1927 Building	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	MJP E/F/V on Cardboard Pipe Insulation	180	FITTING	Basement air tunnel, coal room, and AHU#4	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
66	MJP E/F/V on Fiberglass Pipe Insulation			Throughout - 1927 Building	No ACBM	TSI					
67	12"x12" Beige w/ White Specs VFT	1,600	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12"x12" Beige w/ White Specs VFT Mastic	1,600	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12"x12" Brown w/ Black Specs VFT	1,300	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12"x12" Brown w/ Black Specs VFT Mastic	1,300	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12"x12" Black VFT	250	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12"x12" Black VFT Mastic	250	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Onahan School

**Unit** 24761

**Building ID** 5190

**Address** 6634 W Raven Street

Chicago, IL, 60631

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575      Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
73	12"x12" Blue VFT	25	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12"x12" Blue VFT Mastic	25	SF	Lunch Room - 1995 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	Black Rubber Flooring			Food Storage, Serving Area, Prep Area - 1995 Building	No ACBM						
76	Black Rubber Flooring Mastic			Food Storage, Serving Area, Prep Area - 1995 Building	No ACBM						
77	2'x2' White Ceiling Tile			Serving Area, Prep Room, Serving Area Toilet - 1995 Building	No ACBM						
78	2'x2' Dot White Ceiling Tile			Lunch Room, Lunch Room Office - 1995 Building	No ACBM						
79	Vinyl Baseboard			Lunch Room - 1995 Building	No ACBM						
80	Vinyl Baseboard Mastic			Lunch Room - 1995 Building	No ACBM						
81	12"x12" Black VFT (Abated)			Auditorium and Under Carpet - 1927 Building (Abated)	Abated	MISC					
82	12"x12" Black VFT Mastic (Abated)			Auditorium and Under Carpet - 1927 Building (Abated)	Abated	MISC					
83	12"x12" Red VFT (Abated)			Auditorium and Under Carpet - 1927 Building (Abated)	Abated	MISC					
84	12"x12" Red VFT Mastic (Abated)			Auditorium and Under Carpet - 1927 Building (Abated)	Abated	MISC					
85	6"x18" Black VFT (Abated)			Auditorium and Under Carpet - 1927 Building (Abated)	Abated	MISC					
86	6"x18" Black VFT Mastic (Abated)			Auditorium and Under Carpet - 1927 Building (Abated)	Abated	MISC					
87	Carpet Mastic	1,100	SF	Auditorium (Not Observed), 209, Main Office, Principals Office - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	Terrazzo Floor	3,500	SF	Stairwells (Throughout Building 1st to 3rd floors), Auditorium (Stairs to Stage), Auditorium (Balcony Stairwell), 1st Floor vestibules - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	12" x 12" Gray Streaked VFT	60	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
90	12" x 12" Gray VFT Mastic	60	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Blue Streaked VFT	120	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Onahan School

**Unit** 24761

**Building ID** 5190

**Address** 6634 W Raven Street

Chicago, IL, 60631

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575      Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
92	12" x 12" Blue Streaked VFT Mastic	120	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	12" x 12" Light Blue Streaked VFT	150	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Light Blue Streaked VFT Mastic	150	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	12" x 12" White with Gray Streaks VFT	460	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
96	12" x 12" White with Gray Streaks VFT Mastic	460	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	4' x 4' White Ceiling Tile	500	SF	1st, 2nd and 3rd floor hall to new addition building - 1927 Building	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	Heat Barrier Paper	0		Room 101 - Inside radiator (bench) cover along exterior wall - 1927 Building	Abated	TSI					
99	Decorative Plaster	1,500	SF	Auditorium - 1927 Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Onahan School

**Unit** 24761

**Building ID** 5190

**Address** 6634 W Raven Street

Chicago, IL, 60631

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

***Management Planner's Comments Summarized at the End of the Report***

Review Date	3/3/2025
Manager Planner Name	Jigar Shah
100-07342	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
10	
100	
101	
101A	
102	
102A	
103	
103A	
104	
105	
22	
26	
28	
36	
39	
40	
44	
46	
47	
48	
49	
50	

# Chicago Public Schools

**School** Onahan School

**Unit** 24761

**Building ID** 5190

**Address** 6634 W Raven Street

Chicago, IL, 60631

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	

# Chicago Public Schools

**School** Onahan School

**Unit** 24761

**Building ID** 5190

**Address** 6634 W Raven Street

Chicago, IL, 60631

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Specialty Consulting, Inc.

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>David Avila</b>		
SCHOOL NAME:	<b>Onahan School</b>	INSPECTION DATE:	<b>1/30/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1927 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1927 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	Spray-on Fire Proofing		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunch room and Kitchen (above ceiling tiles) - 1995 Building		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Spray-on Fire Proofing**

MATERIAL LOCATION: **Lunch room and Kitchen (above ceiling tiles) - 1995 Building**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 210 - 1927 Building		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Tan Streaks VFT**

MATERIAL LOCATION: **Room 210 - 1927 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101A		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210 - 1927 Building		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **101A**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ Tan Streaks VFT Mastic**

MATERIAL LOCATION: **Room 210 - 1927 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12" X 12" Off-white streaked VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 210 - 1927 Building		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" X 12" Off-white streaked VFT**

MATERIAL LOCATION: **Room 210 - 1927 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102A		
MATERIAL DESCRIPTION:	12" X 12" Off-white streaked VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210 - 1927 Building		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **102A**

MATERIAL DESCRIPTION: **12" X 12" Off-white streaked VFT Mastic**

MATERIAL LOCATION: **Room 210 - 1927 Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	2' x 2' Light blue w/ blue streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Auditorium &amp; Balcony (not Observed), Projection Room, Front of stage &amp; aisles</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **2' x 2' Light blue w/ blue streaks VFT**

MATERIAL LOCATION: **Auditorium & Balcony (not Observed), Projection Room, Front of stage & aisles**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103A		
MATERIAL DESCRIPTION:	2' x 2' Light Blue w/ Blue Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium & Balcony (not observed), Projection Room, Front of stage & aisles		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **103A**

MATERIAL DESCRIPTION: **2' x 2' Light Blue w/ Blue Streaks VFT Mastic**

MATERIAL LOCATION: **Auditorium & Balcony (not observed), Projection Room, Front of stage & aisles**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Air Erosion/Flow Delamination Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement air and tunnel, coal room, AHU #4**

MATERIAL QUANTITY: **660** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS: **Damage Repaired**

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement air and tunnel, coal room, AHU #4**

MATERIAL QUANTITY: **660** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 26  
MATERIAL DESCRIPTION: 9"x9" Tan VFT - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **9"x9" Tan VFT - ABATED**

MATERIAL LOCATION: **Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: Aircell Duct Insulation (Abated)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: SW, NW, S, & NE Unexcavated Spaces - 1927 Building (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Aircell Duct Insulation (Abated)**

MATERIAL LOCATION: **SW, NW, S, & NE Unexcavated Spaces - 1927 Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	Tank Lagging		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pump Room, Store Room South Of Boiler Room - 1927 Building		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Tank Lagging**

MATERIAL LOCATION: **Pump Room, Store Room South Of Boiler Room - 1927 Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Air Erosion/Flow Delamination Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement air tunnel, coal room and AHU#4**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY:  DAMAGE UNITS: **SF**

COMMENTS: **Damage Repaired**

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement air tunnel, coal room and AHU#4**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Air Erosion/Flow Delamination Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement air tunnel, Coal Room, and AHU#4**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS: **Damage Repaired**

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement air tunnel, Coal Room, and AHU#4**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUILDING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12" x 12" Cream w/Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>1st and 2nd Floor Corridors - 1927 Building</b>		
MATERIAL QUANTITY:	<b>2200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" x 12" Cream w/Brown Streaks VFT**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - 1927 Building**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 46

MATERIAL DESCRIPTION: 9"x9" Tan VFT Mastic - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic - ABATED**

MATERIAL LOCATION: **Room 202 (Teacher's Lunchroom) - 1927 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	12"x12" Cream w/Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Corridors - 1927 Building		
MATERIAL QUANTITY:	2200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **12"x12" Cream w/Brown Streaks VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors - 1927 Building**

MATERIAL QUANTITY: **2200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	12"x12" White w/Tan Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **12"x12" White w/Tan Streaks VFT**

MATERIAL LOCATION: **3rd Floor Corridor, Room 204, Engineers Office - 1927 Building**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12"x12" White w/Tan Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12"x12" White w/Tan Streaks VFT Mastic**

MATERIAL LOCATION: **3rd Floor Corridor, Room 204, Engineers Office - 1927 Building**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12"x12" Brown w/White & Black Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12"x12" Brown w/White & Black Streaks VFT**

MATERIAL LOCATION: **3rd Floor Corridor, Room 204, Engineers Office - 1927 Building**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12"x12" Brown w/White & Black Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	3rd Floor Corridor, Room 204, Engineers Office - 1927 Building		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12"x12" Brown w/White & Black Streaks VFT Mastic**

MATERIAL LOCATION: **3rd Floor Corridor, Room 204, Engineers Office - 1927 Building**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 52  
MATERIAL DESCRIPTION: 9"x9" Brown VFT - ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 209 (Library) (Under Carpet) - 1927 Building - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **9"x9" Brown VFT - ABATED**

MATERIAL LOCATION: **Room 209 (Library) (Under Carpet) - 1927 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 53

MATERIAL DESCRIPTION: 9"x9" Brown VFT Mastic - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 209 (Library) (Under Carpet) - 1927 Building - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic - ABATED**

MATERIAL LOCATION: **Room 209 (Library) (Under Carpet) - 1927 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	9"x9" Brown w/Brown & White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 108 (Teacher's Restroom) - 1927 Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **9"x9" Brown w/Brown & White Streaks VFT**

MATERIAL LOCATION: **Room 108 (Teacher's Restroom) - 1927 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	9"x9" Brown w/Brown & White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 108 (Teacher's Restroom) - 1927 Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **9"x9" Brown w/Brown & White Streaks VFT Mastic**

MATERIAL LOCATION: **Room 108 (Teacher's Restroom) - 1927 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	9"x9" Beige w/Brown & Cream Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building		
MATERIAL QUANTITY:	4470	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	30 SF abated from room 101		

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **9"x9" Beige w/Brown & Cream Streaks VFT**

MATERIAL LOCATION: **Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building**

MATERIAL QUANTITY: **4470** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	9"x9" Beige w/Brown & Cream Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building		
MATERIAL QUANTITY:	4470	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	30 SF abated from room 101		

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **9"x9" Beige w/Brown & Cream Streaks VFT Mastic**

MATERIAL LOCATION: **Room 101 (Kindergarten) and closet, 1st Floor Corridor - 1927 Building**

MATERIAL QUANTITY: **4470** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **9"x9" Beige VFT - ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Small Hallway NW of Room 102 - 1927 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **9"x9" Beige VFT - ABATED**

MATERIAL LOCATION: **Small Hallway NW of Room 102 - 1927 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 59  
MATERIAL DESCRIPTION: 9"x9" Beige VFT Mastic - ABATED  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Small Hallway NW of Room 102 - 1927 Building - ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **9"x9" Beige VFT Mastic - ABATED**

MATERIAL LOCATION: **Small Hallway NW of Room 102 - 1927 Building - ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9"x9" Gray VFT - ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 102 - 1927 Building (ABATED)**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9"x9" Gray VFT - ABATED**

MATERIAL LOCATION: **Room 102 - 1927 Building (ABATED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 61

MATERIAL DESCRIPTION: 9"x9" Gray VFT Mastic - ABATED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 102 - 1927 Building (ABATED)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9"x9" Gray VFT Mastic - ABATED**

MATERIAL LOCATION: **Room 102 - 1927 Building (ABATED)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	12"x12" White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Main Office & Main Office Store Room - 1927 Building		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12"x12" White VFT**

MATERIAL LOCATION: **Main Office & Main Office Store Room - 1927 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	12"x12" White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office & Main Office Store Room - 1927 Building		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**

MATERIAL LOCATION: **Main Office & Main Office Store Room - 1927 Building**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Air Erosion/Flow Delamination Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Basement air tunnel, coal room, and AHU#4**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS: **Damage Repaired**

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement air tunnel, coal room, and AHU#4**

MATERIAL QUANTITY: **180** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUILDING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout - 1927 Building**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **MJP E/F/V on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout - 1927 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12"x12" Beige w/ White Specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Lunch Room - 1995 Building		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12"x12" Beige w/ White Specs VFT**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12"x12" Beige w/ White Specs VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunch Room - 1995 Building		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12"x12" Beige w/ White Specs VFT Mastic**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Black Specs VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Lunch Room - 1995 Building		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Black Specs VFT**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Black Specs VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunch Room - 1995 Building		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Black Specs VFT Mastic**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	12"x12" Black VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Lunch Room - 1995 Building		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12"x12" Black VFT**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	72		
MATERIAL DESCRIPTION:	12"x12" Black VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunch Room - 1995 Building		
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	73		
MATERIAL DESCRIPTION:	12"x12" Blue VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Lunch Room - 1995 Building		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **12"x12" Blue VFT**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>David Avila</b>		
SCHOOL NAME:	<b>Onahan School</b>	INSPECTION DATE:	<b>1/30/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>74</b>		
MATERIAL DESCRIPTION:	<b>12"x12" Blue VFT Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Lunch Room - 1995 Building</b>		
MATERIAL QUANTITY:	<b>25</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **12"x12" Blue VFT Mastic**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 75  
MATERIAL DESCRIPTION: Black Rubber Flooring  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Food Storage, Serving Area, Prep Area - 1995 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **Black Rubber Flooring**

MATERIAL LOCATION: **Food Storage, Serving Area, Prep Area - 1995 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 76  
MATERIAL DESCRIPTION: Black Rubber Flooring Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Food Storage, Serving Area, Prep Area - 1995 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **76**

MATERIAL DESCRIPTION: **Black Rubber Flooring Mastic**

MATERIAL LOCATION: **Food Storage, Serving Area, Prep Area - 1995 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 77  
MATERIAL DESCRIPTION: 2'x2' White Ceiling Tile  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Serving Area, Prep Room, Serving Area Toilet - 1995 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **77**

MATERIAL DESCRIPTION: **2'x2' White Ceiling Tile**

MATERIAL LOCATION: **Serving Area, Prep Room, Serving Area Toilet - 1995 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 78  
MATERIAL DESCRIPTION: 2'x2' Dot White Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunch Room, Lunch Room Office - 1995 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **2'x2' Dot White Ceiling Tile**

MATERIAL LOCATION: **Lunch Room, Lunch Room Office - 1995 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 79  
MATERIAL DESCRIPTION: Vinyl Baseboard  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunch Room - 1995 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Vinyl Baseboard**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 80  
MATERIAL DESCRIPTION: Vinyl Baseboard Mastic  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Lunch Room - 1995 Building

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **80**

MATERIAL DESCRIPTION: **Vinyl Baseboard Mastic**

MATERIAL LOCATION: **Lunch Room - 1995 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 81  
MATERIAL DESCRIPTION: 12"x12" Black VFT (Abated)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium and Under Carpet - 1927 Building (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **81**

MATERIAL DESCRIPTION: **12"x12" Black VFT (Abated)**

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic (Abated)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **82**

MATERIAL DESCRIPTION: **12"x12" Black VFT Mastic (Abated)**

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>David Avila</b>		
SCHOOL NAME:	<b>Onahan School</b>	INSPECTION DATE:	<b>1/30/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12"x12" Red VFT (Abated)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: \_\_\_\_\_

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **83**

MATERIAL DESCRIPTION: **12"x12" Red VFT (Abated)**

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 84

MATERIAL DESCRIPTION: 12"x12" Red VFT Mastic (Abated)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium and Under Carpet - 1927 Building (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **84**

MATERIAL DESCRIPTION: **12"x12" Red VFT Mastic (Abated)**

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 85  
MATERIAL DESCRIPTION: 6"x18" Black VFT (Abated)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium and Under Carpet - 1927 Building (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **85**

MATERIAL DESCRIPTION: **6"x18" Black VFT (Abated)**

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 86  
MATERIAL DESCRIPTION: 6"x18" Black VFT Mastic (Abated)

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium and Under Carpet - 1927 Building (Abated)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **86**

MATERIAL DESCRIPTION: **6"x18" Black VFT Mastic (Abated)**

MATERIAL LOCATION: **Auditorium and Under Carpet - 1927 Building (Abated)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	87		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium (Not Observed), 209, Main Office, Principals Office - 1927 Building		
MATERIAL QUANTITY:	1100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **87**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Auditorium (Not Observed), 209, Main Office, Principals Office - 1927 Building**

MATERIAL QUANTITY: **1100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	88		
MATERIAL DESCRIPTION:	Terrazzo Floor		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Stairwells (Throughout Building 1st to 3rd floors), Auditorium (Stairs to Stage), Auditorium (Balcony Stairwell), 1st Floor vestibules - 1927 Building**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **88**

MATERIAL DESCRIPTION: **Terrazzo Floor**

MATERIAL LOCATION: **Stairwells (Throughout Building 1st to 3rd floors), Auditorium (Stairs to Stage), Auditorium (Balcony Stairwell), 1st Floor vestibules - 1927 Building**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	89		
MATERIAL DESCRIPTION:	12" x 12" Gray Streaked VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	<b>60</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **12" x 12" Gray Streaked VFT**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	90		
MATERIAL DESCRIPTION:	12" x 12" Gray VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **90**

MATERIAL DESCRIPTION: **12" x 12" Gray VFT Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91		
MATERIAL DESCRIPTION:	12" x 12" Blue Streaked VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **12" x 12" Blue Streaked VFT**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92		
MATERIAL DESCRIPTION:	12" x 12" Blue Streaked VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **12" x 12" Blue Streaked VFT Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Streaked VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Streaked VFT**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	12" x 12" Light Blue Streaked VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Streaked VFT Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	95		
MATERIAL DESCRIPTION:	12" x 12" White with Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	<b>460</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **01/30/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **12" x 12" White with Gray Streaks VFT**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	96		
MATERIAL DESCRIPTION:	12" x 12" White with Gray Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	460	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **96**

MATERIAL DESCRIPTION: **12" x 12" White with Gray Streaks VFT Mastic**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **460** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	97		
MATERIAL DESCRIPTION:	4' x 4' White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st, 2nd and 3rd floor hall to new addition building - 1927 Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **97**

MATERIAL DESCRIPTION: **4' x 4' White Ceiling Tile**

MATERIAL LOCATION: **1st, 2nd and 3rd floor hall to new addition building - 1927 Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUILDING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	98		
MATERIAL DESCRIPTION:	Heat Barrier Paper		
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Air Erosion/Flow Deterioration		
HISTORICAL RESPONSE ACTION:	Remove		
ASBESTOS TYPE:	Abated	FRIABLE:	

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 101 - Inside radiator (bench) cover along exterior wall - 1927 Building

MATERIAL QUANTITY: 0 MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated 2024

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUIDLING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **98**

MATERIAL DESCRIPTION: **Heat Barrier Paper**

MATERIAL LOCATION: **Room 101 - Inside radiator (bench) cover along exterior wall - 1927 Building**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Remove**

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	99		
MATERIAL DESCRIPTION:	Decorative Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium - 1927 Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24761</b>	BUILDING ID:	<b>5190</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jigar Shah</b>		
SCHOOL NAME:	<b>Onahan School</b>	REVIEW DATE:	<b>3/3/2025</b>		
ADDRESS:	<b>6634 W Raven Street</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **99**

MATERIAL DESCRIPTION: **Decorative Plaster**

MATERIAL LOCATION: **Auditorium - 1927 Building**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	104			
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Specks VFT			
MATERIAL LOCATION:	Room 108			
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	MODERATE			CONDITION:
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE REASON:		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF	

COMMENTS:

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24761** BUIDLING ID: **5190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Onahan School** REVIEW DATE: **3/3/2025**

ADDRESS: **6634 W Raven Street** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Specks VFT**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/03/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24761	BUIDLING ID:	5190
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Onahan School	INSPECTION DATE:	1/30/2025		
ADDRESS:	6634 W Raven Street	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	105				
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Specks VFT Mastic				
MATERIAL LOCATION:	Room 108				
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 01/30/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24761** BUIDLING ID: **5190**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jigar Shah**

SCHOOL NAME: **Onahan School** REVIEW DATE: **3/3/2025**

ADDRESS: **6634 W Raven Street** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Specks VFT Mastic**

MATERIAL LOCATION: **Room 108**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:



Date: **03/03/2025**


## APPENDIX B

---

### Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## David Avila

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092141

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**David Avila**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/10/2021

Exam Date: 9/10/2021

Expiration Date: 9/10/2022

Certificate Number: BIR2109101942


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, IL

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/30/2025



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

 ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 4/30/2025	EXPIRES 05/15/2026	INSPECTOR 9/13/2025
<b>DAVID AVILA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		PROJECT MANAGER AIR SAMPLING PROFESSIONAL <b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	9/14/2025
<b>PROTECTING HEALTH, IMPROVING LIVES</b> <i>Nationally Accredited by PHAB</i>			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**David Avila**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2409132631  
Course Date: 9/13/2024  
Exam Date: 9/13/2024  
Expiration Date: 9/13/2025



Issue Date: 9/13/2024

Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

A handwritten signature in blue ink, appearing to read 'Tyler Nicholson'.



525-535 West Jefferson Street • Springfield, Illinois

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

2/28/2022



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
**100 - 11093**

ISSUED  
**2/28/2022** EXPIRES  
**05/15/2023**

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11093**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER <b>100 - 11093</b>	ISSUED <b>2/28/2022</b>	EXPIRES <b>05/15/2023</b>		INSPECTOR	9/10/2022
<b>DAVID AVILA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612		PROJECT MANAGER AIR SAMPLING PROFESSIONAL <i>Alteration of this license shall result in legal action. This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</i>			
Environmental Health					

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 11093

ISSUED  
4/8/2024

EXPIRES  
05/15/2025

DAVID AVILA  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



DAVID AVILA  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 4/8/2024	EXPIRES 05/15/2025	INSPECTOR	9/15/2024
DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

6/9/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 07342</b>	ISSUED <b>6/9/2025</b>	EXPIRES <b>05/15/2026</b>	INSPECTOR PROJECT DESIGNER MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	3/7/2026 1/27/2026 3/7/2026 4/7/2026
JIGAR M SHAH 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	


If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES  
*Nationally Accredited by PHAB*

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2023



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/23/2023

Exam Date: 2/23/2023

Expiration Date: 2/23/2024

Certificate Number: MPR2302230560

*Kathy DeSalvo*

Kathy DeSalvo, Director



# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022


Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: MPR2203090714

A handwritten signature in black ink that reads "Kathy DeSalvo".

Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/9/2022

Exam Date: 3/9/2022

Expiration Date: 3/9/2023

Certificate Number: BIR2203090705

Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 07342

ISSUED  
4/1/2022

EXPIRES  
05/15/2023

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


4/1/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/9/2023
PROJECT DESIGNER	3/24/2023
MANAGEMENT PLANNER	3/9/2023
PROJECT MANAGER	3/2/2023
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

Nationally Accredited by PHAB



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 07342

ISSUED  
4/8/2024

EXPIRES  
05/15/2025

JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



JIGAR M SHAH  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 07342

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	3/8/2025
PROJECT DESIGNER	3/7/2025
MANAGEMENT PLANNER	3/8/2025
PROJECT MANAGER	3/25/2024
AIR SAMPLING PROFESSIONAL	
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH. IMPROVING LIVES  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/8/2024

Exam Date: 3/8/2024

Expiration Date: 3/8/2025

Certificate Number: MPR2403081126

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Jigar Shah**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 3/7/2025

Exam Date: 3/7/2025

Expiration Date: 3/7/2026

Certificate Number: MPR2503070948

Course Credit Hours: MPR 4 Hours

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed