

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2396  
SCHOOL NAME: Pasteur School  
ADDRESS OF SCHOOL: 5825 S. Kostner  
CITY: Chicago, IL, 60629

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **8/30/2022**

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** (Please type or print)

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 6/2/2025 ENROLLMENT 574  
IDPH INSPECTOR LICENSE NUMBER: 100-21040  
IDPH LICENSED INSPECTOR NAME (Please Print): Josh Herman  
IDPH MP LICENSE NUMBER: 100-00349  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): James Tuinenga

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

  
Signature of Designated Person Date 6/18/2025

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_  
School has been closed. Date closed: \_\_\_\_\_  
School building has been demolished. Date: \_\_\_\_\_  
School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Pasteur School**

5825 S. Kostner  
Chicago, IL, 60629

Unit: 24851  
Building ID: 5310

IDPH ID Number: 14-016-2990-2396

**REPORT DATE:**

Wednesday, June 18, 2025

**Prepared for:**

**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL**  
**REQUIRED BY FEDERAL LAW**

06/16/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 24851                      Region: 05                      IDPH ID: 14-016-2990-2396

School: Pasteur School                      Building ID: 5310

Address: 5825 S. Kostner

Chicago, IL, 60629

Building Contact:                      Contact Phone:

Current Building Owners: Chicago Public Schools

Reinspection Date: 6/2/2025

Review Date: 06/16/2025

Inspector: Josh Herman

Inspector IDPH License: 100-21040

Management Planner: James Tuinenga

Management Planner IDPH License: 100-00349

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.



James Tuinenga  
100-00349

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: June 18, 2025

RE: Pasteur School, Unit 24851  
5825 S. Kostner  
Chicago, IL, 60629

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Pasteur School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Pasteur School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Pasteur School  
Address: 5825 S. Kostner  
IDPH ID: 14-016-2990-2396  
Contact:

Unit: 24851  
Chicago, IL, 60629  
Building ID: 5310  
Phone:

Region: 05

### 2. Description of Facility

Original Construction:  
Total Square Footage:  
Current Occupancy: 574

Additional Construction:  
No of Floors:

### 3. LEA Designated Person

Contact: Richard J. Schleyer  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 251-7074

### 4. Managing Environmental Consultant


MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Josh Herman


Inspector IDPH license # 100-21040  
Reinspection Date: 6/2/2025

Signature:   
Date: 6/2/2025

### 6. Management Planner

Management Planner Name: James Tuinenga

Management Planner IDPH license # 100-00349

Signature:   
Date: 06/16/2025

### 7. Review Date: 06/16/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 6/18/2025

Name: Richard J. Schleyer

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pasteur School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5310:

003	Plaster
020A	9"x9" Orange Speckled Vinyl Floor Tile ABATED
021A	9"x9" Orange Vinyl Floor Tile Mastic ABATED
023D	12"x12" Beige Speckled Floor Tile ABATED
036	12"x12" Multicolor Floor Tile
036M	Mastic associated with 12"x12" Multicolor Floor Tile
037	2'x4' White Ceiling Tile
038	Grey Carpet Mastic
039	12"x12" Green, Light Blue & White Floor Tile

039M	Mastic associated w/12"x12" Green, Light Blue & White Floor Tile
041	2"x2" Blue Ceramic Tile Grout
042	Hexagonal Ceramic Tile Grout
043	Fire Brick
045	Stage Curtains
NEW	Newly Installed Suspect ACM



B. The following new homogenous areas have been identified for Building 5310:

039	12"x12" Green, Light Blue & White Floor Tile
039M	Mastic associated w/12"x12" Green, Light Blue & White Floor Tile
040	2"x2" Ceramic Tile Grout
041	2"x2" Blue Ceramic Tile Grout
042	Hexagonal Ceramic Tile Grout
043	Fire Brick
045	Stage Curtains

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

T	Mag Pipe Insulation
003	Plaster
004	Terrazzo
020D	12"x12" Beige w/Brown Floor Tile NOT OBSERVED
020E	12"x12" Beige w/Brown Floor Tile NOT OBSERVED
021D	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED
021E	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED
023A	12"x12" Off-White w/Tan Specks Floor Tile
023B	12"x12" White/Green & White Dark Green Specks Floor Tile
023C	12"x12" Blue Floor Tile NOT OBSERVED
024B	Linoleum NOT OBSERVED
024C	Linoleum NOT OBSERVED
025B	Linoleum Adhesive NOT OBSERVED
025C	Linoleum Adhesive NOT OBSERVED
028	12"x12" White Floor Tile
029	2'x4' Pinhole & Fissure Ceiling Tile
030	Insulation in Fire Doors
031	Insulation in Fire Doors
033	Rolled Flooring
034	Rolled Flooring Adhesive
035	12"x12" Beige Floor Tile
036	12"x12" Multicolor Floor Tile
036M	Mastic associated with 12"x12" Multicolor Floor Tile
037	2'x4' White Ceiling Tile
038	Grey Carpet Mastic
039	12"x12" Green, Light Blue & White Floor Tile
039M	Mastic associated w/12"x12" Green, Light Blue & White Floor Tile
040	2"x2" Ceramic Tile Grout
041	2"x2" Blue Ceramic Tile Grout
042	Hexagonal Ceramic Tile Grout
043	Fire Brick
045	Stage Curtains
B	12"x12" Blue Floor Tile (part of pattern)
C	12"x12" Light Blue Floor Tile (part of pattern)
D	12"x12" Pink Floor Tile (part of pattern)

E	12"x12" Gray Floor Tile (part of pattern)
F	2'x2' Ceiling Tile
G	Drywall
G-2	Drywall
G-2A	Drywall Compound
G-3	Drywall
G-3A	Drywall Joint Compound
G-4	Drywall
G-4A	Drywall Compound
G-5	Drywall
G-5A	Drywall Compound
H	Floor Tile Mastic
I	Gray Baseboard
I-2	Light Brown Baseboard
I-3	Light Brown Baseboard
J	Gray Baseboard Mastic
J-2	Light Brown Baseboard Adhesive
J-3	Light Brown Baseboard Adhesive
K	Drywall Joint Compound
L	12"x12" Cream w/Specks Vinyl Floor Tile NOT OBSERVED
L-2	12"x12" Beige Floor Tile NOT OBSERVED
M	12"x12" Cream w/Specks Vinyl Floor Tile Mastic NOT OBSERVED
M-1	12"x12" Beige Floor Tile Mastic NOT OBSERVED
M-2	12"x12" Beige Floor Tile Mastic NOT OBSERVED
N	Transite Cream Texture Wall NOT OBSERVED
NEW	Newly Installed Suspect ACM
O-1	4'x8' Textured Ceiling Panels NOT OBSERVED
P-1	White Baseboard
Q-1	White Baseboard Adhesive
R	Aircell Pipe Insulation
S	Cementitious Pipe Joint Insulation
V	Pipe Fittings
W	Chalkboards
X	Chalkboard Adhesive
Y	Chalkboard
Z	Chalkboard Adhesive

The following areas were deemed to be inaccessible:

021B	9"x9" Dark Bown Floor Tile Mastic
021C	9"x9" Tan Vinyl Floor Tile Mastic NOT OBSERVED
021D	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED

021E	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED
022A	12"x12" Off-White/Tan Streaks Vinyl Floor Tile Mastic
022B	12"x12" White/Green & Dark Green Specks Floor Tile Mastic
022C	12"x12" Blue Floor Tile Mastic NOT OBSERVED
022D	12"x12" Beige Floor Tile Mastic NOT OBSERVED
025B	Linoleum Adhesive NOT OBSERVED
025C	Linoleum Adhesive NOT OBSERVED
026	Gray Carpet Mastic NOT OBSERVED
027	Green Carpet Mastic NOT OBSERVED
030	Insulation in Fire Doors
031	Insulation in Fire Doors
034	Rolled Flooring Adhesive
H	Floor Tile Mastic
J	Gray Baseboard Mastic
J-2	Light Brown Baseboard Adhesive
J-3	Light Brown Baseboard Adhesive
M	12"x12" Cream w/Specks Vinyl Floor Tile Mastic NOT OBSERVED
M-1	12"x12" Beige Floor Tile Mastic NOT OBSERVED
M-2	12"x12" Beige Floor Tile Mastic NOT OBSERVED
Q-1	White Baseboard Adhesive
X	Chalkboard Adhesive
Z	Chalkboard Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Josh Herman, IDPH License # 100-21040. The Management Plan was updated by James Tuinenga, IDPH License # 100-00349. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Pasteur School Building 5310 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
A	12"x12" Cream Floor Tile ABATED			Throughout Annex	ABATED	MISC								
T	Mag Pipe Insulation	100	LF	Boiler Room and Tunnels	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
001	Acoustical Wall Plaster No ACBM			Auditorium	NO ACBM	SURFACE								
002	Plaster Walls and Ceilings - No ACBM			Throughout Facility	NO ACBM	SURFACE								
003	Plaster	400	SF	Engineer Office and Washrooms in Boiler House	ASSUMED	SURFACE	N	NONE	0		Yes	ACBM with the potential for damage		LOW
004	Terrazzo	1,900	SF	Throughout Corridors, Stairways, Janitor Closets, 114B, 208	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020A	9"x9" Orange Speckled Vinyl Floor Tile ABATED			Room 120	ABATED	MISC					Yes			
020B	9"x9" Dark Brown Floor Tile	100	SF	Engineer's Office & Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020C	9"x9" Tan Vinyl Floor Tile NOT OBSERVED	150	SF	Main Office, Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020D	12"x12" Beige w/Brown Floor Tile NOT OBSERVED	1,564	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
020E	12"x12" Beige w/Brown Floor Tile NOT OBSERVED	1,564	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021A	9"x9" Orange Vinyl Floor Tile Mastic ABATED			Room 120	ABATED	MISC					Yes			
021B	9"x9" Dark Bown Floor Tile Mastic	100	SF	Engineer's Office & Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021C	9"x9" Tan Vinyl Floor Tile Mastic NOT OBSERVED	150	SF	Main Office, Storage Room	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021D	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED	1,564	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021E	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED	1,564	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022A	12"x12" Off-White/Tan Streaks Vinyl Floor Tile Mastic	15,925	SF	1st & 2nd Floor Corridors, Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022B	12"x12" White/Green & Dark Green Specks Floor Tile Mastic	3,870	SF	Main Office, Lunchroom, Rooms 108, 215, 218	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022C	12"x12" Blue Floor Tile Mastic NOT OBSERVED	2,640	SF	Rooms 110, 211, 222 & 224	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022D	12"x12" Beige Floor Tile Mastic NOT	40	SF	Storage Room in	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	OBSERVED			Lunchroom								potential for damage		
023A	12"x12" Off-White w/Tan Specks Floor Tile	15,925	SF	1st & 2nd Floor Corridors; Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023B	12"x12" White/Green & White Dark Green Specks Floor Tile	3,170	SF	Main Office, Lunchroom, Rooms 108, 215, 218	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023C	12"x12" Blue Floor Tile NOT OBSERVED	2,640	SF	Rooms 110, 211, 222 & 224	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023D	12"x12" Beige Speckled Floor Tile ABATED			Storage Room in Lunchroom	ABATED	MISC					Yes			
024	Brown Linoleum ABATED			Auditorium Under Seating On 1st Floor	ABATED	MISC								
024B	Linoleum NOT OBSERVED	238	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
024C	Linoleum NOT OBSERVED	238	SF	503/504 Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025	Brown Linoleum Mastic ABATED			Auditorium, under Seating Area On 1st Floor	ABATED	MISC								
025B	Linoleum Adhesive NOT OBSERVED	238	SF	501/502 Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
025C	Linoleum Adhesive NOT OBSERVED	238	SF	503/504 Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
026	Gray Carpet Mastic NOT OBSERVED	1,626	SF	Main Office, Library & Room 214	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
027	Green Carpet Mastic NOT OBSERVED	730	SF	Room 114, Teachers' Lounge, 2nd Floor Men's Teacher Toilet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
028	12"x12" White Floor Tile	12,720	SF	Annex, 120, Main Office, Storage Room, Engineer's Office and Toilet, Lunchroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
029	2'x4' Pinhole & Fissure Ceiling Tile	82,000	SF	All Classrooms, Offices & Corridors	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
030	Insulation in Fire Doors	84	SF	501/502	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
031	Insulation in Fire Doors	84	SF	503/504	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable		LOW



# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												ACBM or friable suspect ACBM		
032	Aircell Pipe Insulation	40	LF	Room 108 Storage Access-South	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
033	Rolled Flooring	728	SF	Annex Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
034	Rolled Flooring Adhesive	728	SF	Annex Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
035	12"x12" Beige Floor Tile	600	SF	401/402 Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
036	12"x12" Multicolor Floor Tile	2,250	SF	Lunchroom & Rooms 116 - 120	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
036M	Mastic associated with 12"x12" Multicolor Floor Tile	2,250	SF	Lunchroom & Rooms 116 - 120	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
037	2'x4' White Ceiling Tile	4,000	SF	Lunchroom, Rooms 116, 118, 120, Kitchen (122) & Media Room (123)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
038	Grey Carpet Mastic	1,000	SF	Room 121A Office & Media Room (123)	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
039	12"x12" Green, Light Blue & White Floor Tile	6,000	SF	All Mobile Units	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
039M	Mastic associated w/12"x12" Green, Light Blue & White Floor Tile	6,000	SF	All Mobile Units	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
040	2"x2" Ceramic Tile Grout	1,000	SF	1st Floor Boys' & Girls' Washrooms, 2nd Floor Staff Washroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
041	2"x2" Blue Ceramic Tile Grout	400	SF	All Mobile Units	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
042	Hexagonal Ceramic Tile Grout	1,000	SF	2nd Floor Old Locker Rooms, Washrooms	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
043	Fire Brick	50	SF	Room 118 Lunchroom	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
045	Stage Curtains	900	SF	Auditorium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
B	12"x12" Blue Floor Tile (part of pattern)	10	SF	Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
C	12"x12" Light Blue Floor Tile (part of pattern)	10	SF	Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
D	12"x12" Pink Floor Tile (part of pattern)	10	SF	Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
E	12"x12" Gray Floor Tile (part of pattern)	10	SF	Annex	ASSUMED	MISC	N		0		No	ACBM with the potential for damage		LOW
F	2'x2' Ceiling Tile	13,500	SF	Throughout Annex	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Drywall	350	SF	On All Interior New Load Bearing Walls	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-2	Drywall	1,319	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-2A	Drywall Compound	1,319	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-3	Drywall	1,319	SF	403/404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-3A	Drywall Joint Compound	1,319	SF	403/404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-4	Drywall	1,319	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-4A	Drywall Compound	1,319	SF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-5	Drywall	1,319	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
G-5A	Drywall Compound	1,319	SF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
H	Floor Tile Mastic	13,500	SF	Throughout Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I	Gray Baseboard	1,600	SF	Throughout Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I-2	Light Brown Baseboard	306	LF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
I-3	Light Brown Baseboard	306	LF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J	Gray Baseboard Mastic	1,600	SF	Throughout Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J-2	Light Brown Baseboard Adhesive	306	LF	501/502	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
J-3	Light Brown Baseboard Adhesive	306	LF	503/504	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
K	Drywall Joint Compound	350	SF	Throughout Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L	12"x12" Cream w/Specks Vinyl Floor Tile NOT OBSERVED	1,200	SF	Throughout North & South Modulares	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
L-2	12"x12" Beige Floor Tile NOT OBSERVED	600	SF	403/404 Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
M	12"x12" Cream w/Specks Vinyl Floor Tile Mastic NOT OBSERVED	1,200	SF	Throughout North & South Modulares	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M-1	12"x12" Beige Floor Tile Mastic NOT OBSERVED	600	SF	401/402 Modular Unit	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
M-2	12"x12" Beige Floor Tile Mastic NOT OBSERVED	600	SF	403/404 Modular Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
N	Transite Cream Texture Wall NOT OBSERVED	960	SF	Throughout North Modulares	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN			Yes	ACBM with the potential for damage		
O-1	4'x8' Textured Ceiling Panels NOT OBSERVED	1,200	SF	Throughout North & South Modulares	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
P-1	White Baseboard	160	LF	Throughout North & South Modulares	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Q-1	White Baseboard Adhesive	160	LF	Throughout North & South Modulares	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
R	Aircell Pipe Insulation	1,660	LF	Boiler Room and Tunnels	ASSUMED	TSI	Y	LOC	5		No	Any remaining friable ACBM or friable suspect ACBM		LOW
S	Cementitious Pipe Joint Insulation	150	LF	Boiler Room and Tunnels	ASSUMED	TSI	Y	LOC	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
U	Boiler Tank Jacket	2,400	SF	Boiler Room	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
V	Pipe Fittings	100	LF	Pipe Chases in Bathrooms	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
W	Chalkboards	104	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
X	Chalkboard Adhesive	104	SF	401/402	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Y	Chalkboard	104	SF	403/404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
Z	Chalkboard Adhesive	104	SF	403/404	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Pasteur School Unit 24851 Building ID 5310

Address 5825 S. Kostner Region 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date **6/2/2025**

Inspector Name **Josh Herman**

**100-21040**

**5/15/2026**

Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
A	
T	
001	
002	
003	
004	
020A	
020B	
020C	Not Observed 2025
020D	Not Observed 2025
020E	Not Observed 2025
021A	
021B	
021C	Not Observed 2025
021D	Not Observed 2025
021E	Not Observed 2025
022A	Material Abated from Room 116 & 118
022B	
022C	Not Observed 2025
022D	Not Observed 2025
023A	Material Abated from Room 116 & 118
023B	
023C	Not Observed 2025. 20 SF found in 224 Closet
023D	

# Chicago Public Schools

**School** Pasteur School **Unit** 24851 **Building ID** 5310

**Address** 5825 S. Kostner **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
024	
024B	Not Observed 2025
024C	Not Observed 2025
025	
025B	Not Observed 2025
025C	Not Observed 2025
026	Not Observed 2025
027	Not Observed 2025
028	
029	
030	
031	
032	
033	
034	
035	
036	
036M	
037	
038	
039	
039M	
040	
041	
042	
043	
045	
B	
C	

# Chicago Public Schools

**School** Pasteur School **Unit** 24851 **Building ID** 5310

**Address** 5825 S. Kostner **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
D	
E	
F	
G	
G-2	
G-2A	
G-3	
G-3A	
G-4	
G-4A	
G-5	
G-5A	
H	
I	
I-2	
I-3	
J	
J-2	
J-3	
K	
L	Not Observed 2025
L-2	
M	Not Observed 2025
M-1	Not Observed 2025
M-2	Not Observed 2025
N	Not Observed 2025
NEW	
O-1	Not Observed 2025
P-1	

# Chicago Public Schools

**School** Pasteur School **Unit** 24851 **Building ID** 5310

**Address** 5825 S. Kostner **Region** 05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
Q-1	
R	5 LF of material damaged at south end of basement
S	2025- 10 LF of material damaged in North crawlspace
U	
V	
W	2025- Throughout Main
X	2025- Throughout Main
Y	
Z	

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

School    Pasteur School

Unit    24851

Building ID    5310

Address    5825 S. Kostner

Chicago, IL, 60629

Region    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)    TEM Environmental, Inc.

174 N. Brandon Drive

Phone:    630-790-0880

Fax:    630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
A	12"x12" Cream Floor Tile ABATED			Throughout Annex	Abated	MISC					
T	Mag Pipe Insulation	100	LF	Boiler Room and Tunnels	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
001	Acoustical Wall Plaster No ACBM			Auditorium	No ACBM	SURFACE					
002	Plaster Walls and Ceilings - No ACBM			Throughout Facility	No ACBM	SURFACE					
003	Plaster	400	SF	Engineer Office and Washrooms in Boiler House	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
004	Terrazzo	1,900	SF	Throughout Corridors, Stairways, Janitor Closets, 114B, 208	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020A	9"x9" Orange Speckled Vinyl Floor Tile ABATED			Room 120	Abated	MISC					
020B	9"x9" Dark Brown Floor Tile	100	SF	Engineer's Office & Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020C	9"x9" Tan Vinyl Floor Tile NOT OBSERVED	150	SF	Main Office, Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020D	12"x12" Beige w/Brown Floor Tile NOT OBSERVED	1,564	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
020E	12"x12" Beige w/Brown Floor Tile NOT OBSERVED	1,564	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021A	9"x9" Orange Vinyl Floor Tile Mastic ABATED			Room 120	Abated	MISC					
021B	9"x9" Dark Bown Floor Tile Mastic	100	SF	Engineer's Office & Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021C	9"x9" Tan Vinyl Floor Tile Mastic NOT OBSERVED	150	SF	Main Office, Storage Room	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021D	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED	1,564	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
021E	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED	1,564	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022A	12"x12" Off-White/Tan Streaks Vinyl Floor Tile Mastic	15,925	SF	1st & 2nd Floor Corridors, Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022B	12"x12" White/Green & Dark Green Specks Floor Tile Mastic	3,870	SF	Main Office, Lunchroom, Rooms 108, 215, 218	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022C	12"x12" Blue Floor Tile Mastic NOT OBSERVED	2,640	SF	Rooms 110, 211, 222 & 224	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
022D	12"x12" Beige Floor Tile Mastic NOT OBSERVED	40	SF	Storage Room in Lunchroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023A	12"x12" Off-White w/Tan Specks Floor Tile	15,925	SF	1st & 2nd Floor Corridors; Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023B	12"x12" White/Green & White Dark Green Specks Floor Tile	3,170	SF	Main Office, Lunchroom, Rooms 108, 215, 218	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
023C	12"x12" Blue Floor Tile NOT OBSERVED	2,640	SF	Rooms 110, 211, 222 & 224	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School    Pasteur School

Unit    24851

Building ID    5310

Address    5825 S. Kostner

Chicago, IL, 60629

Region    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)    TEM Environmental, Inc.

174 N. Brandon Drive

Phone:    630-790-0880

Fax:    630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
023D	12"x12" Beige Speckled Floor Tile ABATED			Storage Room in Lunchroom	Abated	MISC					
024	Brown Linoleum ABATED			Auditorium Under Seating On 1st Floor	Abated	MISC					
024B	Linoleum NOT OBSERVED	238	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
024C	Linoleum NOT OBSERVED	238	SF	503/504 Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025	Brown Linoleum Mastic ABATED			Auditorium, under Seating Area On 1st Floor	Abated	MISC					
025B	Linoleum Adhesive NOT OBSERVED	238	SF	501/502 Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
025C	Linoleum Adhesive NOT OBSERVED	238	SF	503/504 Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
026	Gray Carpet Mastic NOT OBSERVED	1,626	SF	Main Office, Library & Room 214	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
027	Green Carpet Mastic NOT OBSERVED	730	SF	Room 114, Teachers' Lounge, 2nd Floor Men's Teacher Toilet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
028	12"x12" White Floor Tile	12,720	SF	Annex, 120, Main Office, Storage Room, Engineer's Office and Toilet, Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
029	2'x4' Pinhole & Fissure Ceiling Tile	82,000	SF	All Classrooms, Offices & Corridors	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
030	Insulation in Fire Doors	84	SF	501/502	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
031	Insulation in Fire Doors	84	SF	503/504	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
032	Aircell Pipe Insulation	40	LF	Room 108 Storage Access-South	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
033	Rolled Flooring	728	SF	Annex Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
034	Rolled Flooring Adhesive	728	SF	Annex Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
035	12"x12" Beige Floor Tile	600	SF	401/402 Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
036	12"x12" Multicolor Floor Tile	2,250	SF	Lunchroom & Rooms 116 - 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
036M	Mastic associated with 12"x12" Multicolor Floor Tile	2,250	SF	Lunchroom & Rooms 116 - 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
037	2'x4' White Ceiling Tile	4,000	SF	Lunchroom, Rooms 116, 118, 120, Kitchen (122) & Media Room (123)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
038	Grey Carpet Mastic	1,000	SF	Room 121A Office & Media Room (123)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
039	12"x12" Green, Light Blue & White Floor Tile	6,000	SF	All Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
039M	Mastic associated w/12"x12" Green, Light Blue & White Floor Tile	6,000	SF	All Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
040	2"x2" Ceramic Tile Grout	1,000	SF	1st Floor Boys' & Girls' Washrooms, 2nd Floor Staff Washroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School    Pasteur School

Unit    24851

Building ID    5310

Address    5825 S. Kostner

Chicago, IL, 60629

Region    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)    TEM Environmental, Inc.

174 N. Brandon Drive

Phone:    630-790-0880

Fax:    630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
041	2"x2" Blue Ceramic Tile Grout	400	SF	All Mobile Units	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
042	Hexagonal Ceramic Tile Grout	1,000	SF	2nd Floor Old Locker Rooms, Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
043	Fire Brick	50	SF	Room 118 Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
045	Stage Curtains	900	SF	Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
B	12"x12" Blue Floor Tile (part of pattern)	10	SF	Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	12"x12" Light Blue Floor Tile (part of pattern)	10	SF	Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
D	12"x12" Pink Floor Tile (part of pattern)	10	SF	Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
E	12"x12" Gray Floor Tile (part of pattern)	10	SF	Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
F	2'x2' Ceiling Tile	13,500	SF	Throughout Annex	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Drywall	350	SF	On All Interior New Load Bearing Walls	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-2	Drywall	1,319	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-2A	Drywall Compound	1,319	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-3	Drywall	1,319	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-3A	Drywall Joint Compound	1,319	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-4	Drywall	1,319	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-4A	Drywall Compound	1,319	SF	501/502	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-5	Drywall	1,319	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
G-5A	Drywall Compound	1,319	SF	503/504	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Floor Tile Mastic	13,500	SF	Throughout Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I	Gray Baseboard	1,600	SF	Throughout Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
I-2	Light Brown Baseboard	306	LF	501/502	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I-3	Light Brown Baseboard	306	LF	503/504	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Gray Baseboard Mastic	1,600	SF	Throughout Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
J-2	Light Brown Baseboard Adhesive	306	LF	501/502	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J-3	Light Brown Baseboard Adhesive	306	LF	503/504	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Drywall Joint Compound	350	SF	Throughout Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L	12"x12" Cream w/Specks Vinyl Floor Tile NOT OBSERVED	1,200	SF	Throughout North & South Modulares	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
L-2	12"x12" Beige Floor Tile NOT OBSERVED	600	SF	403/404 Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	12"x12" Cream w/Specks Vinyl Floor Tile Mastic NOT OBSERVED	1,200	SF	Throughout North & South Modulares	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M-1	12"x12" Beige Floor Tile Mastic NOT OBSERVED	600	SF	401/402 Modular Unit	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M-2	12"x12" Beige Floor Tile Mastic NOT OBSERVED	600	SF	403/404 Modular Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

School    Pasteur School

Unit    24851

Building ID    5310

Address    5825 S. Kostner

Chicago, IL, 60629

Region    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

Managing Environmental Consultant (MEC)    TEM Environmental, Inc.

174 N. Brandon Drive

Phone:    630-790-0880

Fax:    630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
N	Transite Cream Texture Wall NOT OBSERVED	960	SF	Throughout North Modulares	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC				6 ACBM with the potential for damage	Follow O&M Plan
O-1	4'x8' Textured Ceiling Panels NOT OBSERVED	1,200	SF	Throughout North & South Modulares	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
P-1	White Baseboard	160	LF	Throughout North & South Modulares	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q-1	White Baseboard Adhesive	160	LF	Throughout North & South Modulares	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Aircell Pipe Insulation	1,660	LF	Boiler Room and Tunnels	Assumed	TSI	Yes	5	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
S	Cementitious Pipe Joint Insulation	150	LF	Boiler Room and Tunnels	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
U	Boiler Tank Jacket	2,400	SF	Boiler Room	Chrysotile	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
V	Pipe Fittings	100	LF	Pipe Chases in Bathrooms	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
W	Chalkboards	104	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
X	Chalkboard Adhesive	104	SF	401/402	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Y	Chalkboard	104	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
Z	Chalkboard Adhesive	104	SF	403/404	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School**    Pasteur School  
**Address**    5825 S. Kostner

**Unit**    24851  
Chicago, IL, 60629

**Building ID**    5310  
**Region**    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)**    TEM Environmental, Inc.

174 N. Brandon Drive

Phone:    630-790-0880

Fax:    630-790-0882

*Management Planner's Comments Summarized at the End of the Report*

Review Date	6/16/2025
Manager Planner Name	James Tuinenga
100-00349	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
A	
T	
001	
002	
003	
004	
020A	
020B	
020C	
020D	
020E	
021A	
021B	
021C	
021D	
021E	
022A	
022B	
022C	
022D	

# Chicago Public Schools

**School**    Pasteur School  
**Address**    5825 S. Kostner

**Unit**    24851  
Chicago, IL, 60629

**Building ID**    5310  
**Region**    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)**    TEM Environmental, Inc.  
  
174 N. Brandon Drive  
  
Phone:    630-790-0880

Fax:    630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
023A	
023B	
023C	
023D	
024	
024B	
024C	
025	
025B	
025C	
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
036M	
037	
038	
039	
039M	
040	

# Chicago Public Schools

**School**    Pasteur School  
**Address**    5825 S. Kostner

**Unit**    24851  
Chicago, IL, 60629

**Building ID**    5310  
**Region**    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)**    TEM Environmental, Inc.

174 N. Brandon Drive

Phone:    630-790-0880                      Fax:    630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
041	
042	
043	
045	
B	
C	
D	
E	
F	
G	
G-2	
G-2A	
G-3	
G-3A	
G-4	
G-4A	
G-5	
G-5A	
H	
I	
I-2	
I-3	
J	
J-2	
J-3	
K	
L	

# Chicago Public Schools

**School**    Pasteur School  
**Address**    5825 S. Kostner

**Unit**    24851  
Chicago, IL, 60629

**Building ID**    5310  
**Region**    05

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)**    TEM Environmental, Inc.

174 N. Brandon Drive

Phone:    630-790-0880                      Fax:    630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
L-2	
M	
M-1	
M-2	
N	
NEW	
O-1	
P-1	
Q-1	
R	
S	
U	
V	
W	
X	
Y	
Z	



# APPENDIX A

## Assessment Sheets, Drawings and Photos

---

# Chicago Public Schools

TEM Environmental, Inc.  
*2025 AHERA REINSPECTION*

# Chicago Public Schools

TEM Environmental, Inc.

## 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A	
MATERIAL DESCRIPTION:	12"x12" Cream Floor Tile ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Annex

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: A

MATERIAL DESCRIPTION: 12"x12" Cream Floor Tile ABATED

MATERIAL LOCATION: Throughout Annex

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	T		
MATERIAL DESCRIPTION:	Mag Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room and Tunnels		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	T				
MATERIAL DESCRIPTION:	Mag Pipe Insulation				
MATERIAL LOCATION:	Boiler Room and Tunnels				
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	001	
MATERIAL DESCRIPTION:	Acoustical Wall Plaster No ACBM	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 001

MATERIAL DESCRIPTION: Acoustical Wall Plaster No ACBM

MATERIAL LOCATION: Auditorium

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	002	
MATERIAL DESCRIPTION:	Plaster Walls and Ceilings - No ACBM	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	No ACBM	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 002

MATERIAL DESCRIPTION: Plaster Walls and Ceilings - No ACBM

MATERIAL LOCATION: Throughout Facility

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	003		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer Office and Washrooms in Boiler House		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	003		
MATERIAL DESCRIPTION:	Plaster		
MATERIAL LOCATION:	Engineer Office and Washrooms in Boiler House		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	004		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Corridors, Stairways, Janitor Closets, 114B, 208		
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	004				
MATERIAL DESCRIPTION:	Terrazzo				
MATERIAL LOCATION:	Throughout Corridors, Stairways, Janitor Closets, 114B, 208				
MATERIAL QUANTITY:	1900	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020A	
MATERIAL DESCRIPTION:	9"x9" Orange Speckled Vinyl Floor Tile ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 120

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 020A

MATERIAL DESCRIPTION: 9"x9" Orange Speckled Vinyl Floor Tile ABATED

MATERIAL LOCATION: Room 120

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020B		
MATERIAL DESCRIPTION:	9"x9" Dark Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office & Toilet		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 020B

MATERIAL DESCRIPTION: 9"x9" Dark Brown Floor Tile

MATERIAL LOCATION: Engineer's Office & Toilet

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020C		
MATERIAL DESCRIPTION:	9"x9" Tan Vinyl Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Storage Room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 020C

MATERIAL DESCRIPTION: 9"x9" Tan Vinyl Floor Tile NOT OBSERVED

MATERIAL LOCATION: Main Office, Storage Room

MATERIAL QUANTITY: 150 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020D		
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	1564	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 020D

MATERIAL DESCRIPTION: 12"x12" Beige w/Brown Floor Tile NOT OBSERVED

MATERIAL LOCATION: 501/502

MATERIAL QUANTITY: 1564

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020E		
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	1564	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 020E

MATERIAL DESCRIPTION: 12"x12" Beige w/Brown Floor Tile NOT OBSERVED

MATERIAL LOCATION: 503/504

MATERIAL QUANTITY: 1564

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021A	
MATERIAL DESCRIPTION:	9"x9" Orange Vinyl Floor Tile Mastic ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 120

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24851</b>	BUILDING ID:	<b>5310</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Pasteur School</b>	REVIEW DATE:	<b>6/16/2025</b>		
ADDRESS:	<b>5825 S. Kostner</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA: **021A**

MATERIAL DESCRIPTION: **9"x9" Orange Vinyl Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 120**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021B		
MATERIAL DESCRIPTION:	9"x9" Dark Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Engineer's Office & Toilet		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 021B

MATERIAL DESCRIPTION: 9"x9" Dark Brown Floor Tile Mastic

MATERIAL LOCATION: Engineer's Office & Toilet

MATERIAL QUANTITY: 100 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021C		
MATERIAL DESCRIPTION:	9"x9" Tan Vinyl Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Storage Room**

MATERIAL QUANTITY: **150**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 021C

MATERIAL DESCRIPTION: 9"x9" Tan Vinyl Floor Tile Mastic NOT OBSERVED

MATERIAL LOCATION: Main Office, Storage Room

MATERIAL QUANTITY: 150 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021D		
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	1564	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 021D

MATERIAL DESCRIPTION: 12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED

MATERIAL LOCATION: 501/502

MATERIAL QUANTITY: 1564

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021E		
MATERIAL DESCRIPTION:	12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	1564	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 021E

MATERIAL DESCRIPTION: 12"x12" Beige w/Brown Floor Tile Mastic NOT OBSERVED

MATERIAL LOCATION: 503/504

MATERIAL QUANTITY: 1564

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	022A		
MATERIAL DESCRIPTION:	12"x12" Off-White/Tan Streaks Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220**

MATERIAL QUANTITY: **15925**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Abated from Room 116 & 118**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 022A

MATERIAL DESCRIPTION: 12"x12" Off-White/Tan Streaks Vinyl Floor Tile Mastic

MATERIAL LOCATION: 1st & 2nd Floor Corridors, Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220

MATERIAL QUANTITY: 15925

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	022B		
MATERIAL DESCRIPTION:	12"x12" White/Green & Dark Green Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, Lunchroom, Rooms 108, 215, 218**

MATERIAL QUANTITY: **3870**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	022B				
MATERIAL DESCRIPTION:	12"x12" White/Green & Dark Green Specks Floor Tile Mastic				
MATERIAL LOCATION:	Main Office, Lunchroom, Rooms 108, 215, 218				
MATERIAL QUANTITY:	3870	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	022C		
MATERIAL DESCRIPTION:	12"x12" Blue Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 110, 211, 222 & 224**

MATERIAL QUANTITY: **2640**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 022C

MATERIAL DESCRIPTION: 12"x12" Blue Floor Tile Mastic NOT OBSERVED

MATERIAL LOCATION: Rooms 110, 211, 222 & 224

MATERIAL QUANTITY: 2640

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	022D		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic	NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Storage Room in Lunchroom**

MATERIAL QUANTITY: **40**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 022D

MATERIAL DESCRIPTION: 12"x12" Beige Floor Tile Mastic NOT OBSERVED

MATERIAL LOCATION: Storage Room in Lunchroom

MATERIAL QUANTITY: 40

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023A		
MATERIAL DESCRIPTION:	12"x12" Off-White w/Tan Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floor Corridors; Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220**

MATERIAL QUANTITY: **15925**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Material Abated from Room 116 & 118**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 023A

MATERIAL DESCRIPTION: 12"x12" Off-White w/Tan Specks Floor Tile

MATERIAL LOCATION: 1st & 2nd Floor Corridors; Rooms: 112, 114, 116, 117, 118, 210, 212, 213, 216, 217, 219, 220

MATERIAL QUANTITY: 15925

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023B		
MATERIAL DESCRIPTION:	12"x12" White/Green & White Dark Green Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Lunchroom, Rooms 108, 215, 218		
MATERIAL QUANTITY:	3170	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 023B

MATERIAL DESCRIPTION: 12"x12" White/Green & White Dark Green Specks Floor Tile

MATERIAL LOCATION: Main Office, Lunchroom, Rooms 108, 215, 218

MATERIAL QUANTITY: 3170 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023C		
MATERIAL DESCRIPTION:	12"x12" Blue Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 110, 211, 222 & 224**

MATERIAL QUANTITY: **2640**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025. 20 SF found in 224 Closet**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 023C

MATERIAL DESCRIPTION: 12"x12" Blue Floor Tile NOT OBSERVED

MATERIAL LOCATION: Rooms 110, 211, 222 & 224

MATERIAL QUANTITY: 2640

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023D	
MATERIAL DESCRIPTION:	12"x12" Beige Speckled Floor Tile ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Storage Room in Lunchroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 023D

MATERIAL DESCRIPTION: 12"x12" Beige Speckled Floor Tile ABATED

MATERIAL LOCATION: Storage Room in Lunchroom

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024	
MATERIAL DESCRIPTION:	Brown Linoleum ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium Under Seating On 1st Floor

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 024

MATERIAL DESCRIPTION: Brown Linoleum ABATED

MATERIAL LOCATION: Auditorium Under Seating On 1st Floor

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024B		
MATERIAL DESCRIPTION:	Linoleum NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	238	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 024B

MATERIAL DESCRIPTION: Linoleum NOT OBSERVED

MATERIAL LOCATION: 501/502

MATERIAL QUANTITY: 238

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024C		
MATERIAL DESCRIPTION:	Linoleum NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504 Washroom		
MATERIAL QUANTITY:	238	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 024C

MATERIAL DESCRIPTION: Linoleum NOT OBSERVED

MATERIAL LOCATION: 503/504 Washroom

MATERIAL QUANTITY: 238

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	025	
MATERIAL DESCRIPTION:	Brown Linoleum Mastic ABATED	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	Abated	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Auditorium, under Seating Area On 1st Floor

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24851</b>	BUILDING ID:	<b>5310</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>James Tuinenga</b>		
SCHOOL NAME:	<b>Pasteur School</b>	REVIEW DATE:	<b>6/16/2025</b>		
ADDRESS:	<b>5825 S. Kostner</b>	IDPH LICENSE NO:	<b>100-21040</b>		

---

HOMOGENEOUS AREA:	<b>025</b>	
MATERIAL DESCRIPTION:	<b>Brown Linoleum Mastic ABATED</b>	
MATERIAL LOCATION:	<b>Auditorium, under Seating Area On 1st Floor</b>	
MATERIAL QUANTITY:		MATERIAL UNITS:
DAMAGE QUANTITY:		DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	025B		
MATERIAL DESCRIPTION:	Linoleum Adhesive NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502 Washroom		
MATERIAL QUANTITY:	238	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 025B

MATERIAL DESCRIPTION: Linoleum Adhesive NOT OBSERVED

MATERIAL LOCATION: 501/502 Washroom

MATERIAL QUANTITY: 238 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	025C		
MATERIAL DESCRIPTION:	Linoleum Adhesive NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504 Washroom		
MATERIAL QUANTITY:	238	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 025C

MATERIAL DESCRIPTION: Linoleum Adhesive NOT OBSERVED

MATERIAL LOCATION: 503/504 Washroom

MATERIAL QUANTITY: 238 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	026		
MATERIAL DESCRIPTION:	Gray Carpet Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Library & Room 214		
MATERIAL QUANTITY:	1626	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	026		
MATERIAL DESCRIPTION:	Gray Carpet Mastic NOT OBSERVED		
MATERIAL LOCATION:	Main Office, Library & Room 214		
MATERIAL QUANTITY:	1626	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	027		
MATERIAL DESCRIPTION:	Green Carpet Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114, Teachers' Lounge, 2nd Floor Men's Teacher Toilet		
MATERIAL QUANTITY:	730	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	027				
MATERIAL DESCRIPTION:	Green Carpet Mastic NOT OBSERVED				
MATERIAL LOCATION:	Room 114, Teachers' Lounge, 2nd Floor Men's Teacher Toilet				
MATERIAL QUANTITY:	730	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	028		
MATERIAL DESCRIPTION:	12"x12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex, 120, Main Office, Storage Room, Engineer's Office and Toilet, Lunchroom		
MATERIAL QUANTITY:	12720	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	028				
MATERIAL DESCRIPTION:	12"x12" White Floor Tile				
MATERIAL LOCATION:	Annex, 120, Main Office, Storage Room, Engineer's Office and Toilet, Lunchroom				
MATERIAL QUANTITY:	12720	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	029		
MATERIAL DESCRIPTION:	2'x4' Pinhole & Fissure Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	All Classrooms, Offices & Corridors		
MATERIAL QUANTITY:	82000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	029				
MATERIAL DESCRIPTION:	2'x4' Pinhole & Fissure Ceiling Tile				
MATERIAL LOCATION:	All Classrooms, Offices & Corridors				
MATERIAL QUANTITY:	82000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	030		
MATERIAL DESCRIPTION:	Insulation in Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	84	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	030		
MATERIAL DESCRIPTION:	Insulation in Fire Doors		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	84	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	031		
MATERIAL DESCRIPTION:	Insulation in Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	84	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 031

MATERIAL DESCRIPTION: Insulation in Fire Doors

MATERIAL LOCATION: 503/504

MATERIAL QUANTITY: 84

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	032		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 108 Storage Access-South		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	032		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
MATERIAL LOCATION:	Room 108 Storage Access-South		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	033		
MATERIAL DESCRIPTION:	Rolled Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex Washroom		
MATERIAL QUANTITY:	728	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	033		
MATERIAL DESCRIPTION:	Rolled Flooring		
MATERIAL LOCATION:	Annex Washroom		
MATERIAL QUANTITY:	728	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	034		
MATERIAL DESCRIPTION:	Rolled Flooring Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Annex Washroom**

MATERIAL QUANTITY: **728**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	034		
MATERIAL DESCRIPTION:	Rolled Flooring Adhesive		
MATERIAL LOCATION:	Annex Washroom		
MATERIAL QUANTITY:	728	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	035		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	401/402 Modular Unit		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	035		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile		
MATERIAL LOCATION:	401/402 Modular Unit		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	036		
MATERIAL DESCRIPTION:	12"x12" Multicolor Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom & Rooms 116 - 120		
MATERIAL QUANTITY:	2250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	036				
MATERIAL DESCRIPTION:	12"x12" Multicolor Floor Tile				
MATERIAL LOCATION:	Lunchroom & Rooms 116 - 120				
MATERIAL QUANTITY:	2250	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	036M		
MATERIAL DESCRIPTION:	Mastic associated with 12"x12" Multicolor Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Lunchroom & Rooms 116 - 120**

MATERIAL QUANTITY: **2250**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: 036M

MATERIAL DESCRIPTION: Mastic associated with 12"x12" Multicolor Floor Tile

MATERIAL LOCATION: Lunchroom & Rooms 116 - 120

MATERIAL QUANTITY: 2250

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	037		
MATERIAL DESCRIPTION:	2'x4' White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Lunchroom, Rooms 116, 118, 120, Kitchen (122) & Media Room (123)		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	037				
MATERIAL DESCRIPTION:	2'x4' White Ceiling Tile				
MATERIAL LOCATION:	Lunchroom, Rooms 116, 118, 120, Kitchen (122) & Media Room (123)				
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	038		
MATERIAL DESCRIPTION:	Grey Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 121A Office & Media Room (123)		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	038				
MATERIAL DESCRIPTION:	Grey Carpet Mastic				
MATERIAL LOCATION:	Room 121A Office & Media Room (123)				
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	12"x12" Blue Floor Tile (part of pattern)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: B

MATERIAL DESCRIPTION: 12"x12" Blue Floor Tile (part of pattern)

MATERIAL LOCATION: Annex

MATERIAL QUANTITY: 10

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	12"x12" Light Blue Floor Tile (part of pattern)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: C

MATERIAL DESCRIPTION: 12"x12" Light Blue Floor Tile (part of pattern)

MATERIAL LOCATION: Annex

MATERIAL QUANTITY: 10

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	12"x12" Pink Floor Tile (part of pattern)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: D

MATERIAL DESCRIPTION: 12"x12" Pink Floor Tile (part of pattern)

MATERIAL LOCATION: Annex

MATERIAL QUANTITY: 10

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	12"x12" Gray Floor Tile (part of pattern)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Annex		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: E

MATERIAL DESCRIPTION: 12"x12" Gray Floor Tile (part of pattern)

MATERIAL LOCATION: Annex

MATERIAL QUANTITY: 10

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	2'x2' Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Annex		
MATERIAL QUANTITY:	13500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	F				
MATERIAL DESCRIPTION:	2'x2' Ceiling Tile				
MATERIAL LOCATION:	Throughout Annex				
MATERIAL QUANTITY:	13500	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	On All Interior New Load Bearing Walls		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **On All Interior New Load Bearing Walls**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-2		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	401/402		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	G-2		
MATERIAL DESCRIPTION:	Drywall		
MATERIAL LOCATION:	401/402		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-2A		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	401/402		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: **G-2A**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **401/402**

MATERIAL QUANTITY: **1319**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-3		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	403/404		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	G-3		
MATERIAL DESCRIPTION:	Drywall		
MATERIAL LOCATION:	403/404		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-3A		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	403/404		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: **G-3A**

MATERIAL DESCRIPTION: **Drywall Joint Compound**

MATERIAL LOCATION: **403/404**

MATERIAL QUANTITY: **1319**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-4		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	G-4		
MATERIAL DESCRIPTION:	Drywall		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-4A		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

---

HOMOGENEOUS AREA: **G-4A**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **501/502**  
MATERIAL QUANTITY: **1319** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-5		
MATERIAL DESCRIPTION:	Drywall		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	G-5		
MATERIAL DESCRIPTION:	Drywall		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G-5A		
MATERIAL DESCRIPTION:	Drywall Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	1319	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: **G-5A**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **503/504**

MATERIAL QUANTITY: **1319**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Annex		
MATERIAL QUANTITY:	13500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: H

MATERIAL DESCRIPTION: Floor Tile Mastic

MATERIAL LOCATION: Throughout Annex

MATERIAL QUANTITY: 13500

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I		
MATERIAL DESCRIPTION:	Gray Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Annex		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUIDLING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Gray Baseboard**  
MATERIAL LOCATION: **Throughout Annex**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I-2		
MATERIAL DESCRIPTION:	Light Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	306	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: I-2

MATERIAL DESCRIPTION: Light Brown Baseboard

MATERIAL LOCATION: 501/502

MATERIAL QUANTITY: 306

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	I-3		
MATERIAL DESCRIPTION:	Light Brown Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	306	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: I-3

MATERIAL DESCRIPTION: Light Brown Baseboard

MATERIAL LOCATION: 503/504

MATERIAL QUANTITY: 306 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Gray Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Annex		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: J

MATERIAL DESCRIPTION: Gray Baseboard Mastic

MATERIAL LOCATION: Throughout Annex

MATERIAL QUANTITY: 1600

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J-2		
MATERIAL DESCRIPTION:	Light Brown Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	501/502		
MATERIAL QUANTITY:	306	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: J-2

MATERIAL DESCRIPTION: Light Brown Baseboard Adhesive

MATERIAL LOCATION: 501/502

MATERIAL QUANTITY: 306 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J-3		
MATERIAL DESCRIPTION:	Light Brown Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	503/504		
MATERIAL QUANTITY:	306	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: J-3

MATERIAL DESCRIPTION: Light Brown Baseboard Adhesive

MATERIAL LOCATION: 503/504

MATERIAL QUANTITY: 306

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Drywall Joint Compound		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Annex		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	K				
MATERIAL DESCRIPTION:	Drywall Joint Compound				
MATERIAL LOCATION:	Throughout Annex				
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	12"x12" Cream w/Specks Vinyl Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout North & South Modulars		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	L				
MATERIAL DESCRIPTION:	12"x12" Cream w/Specks Vinyl Floor Tile NOT OBSERVED				
MATERIAL LOCATION:	Throughout North & South Modulares				
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L-2		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	403/404 Modular Building		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: L-2

MATERIAL DESCRIPTION: 12"x12" Beige Floor Tile NOT OBSERVED

MATERIAL LOCATION: 403/404 Modular Building

MATERIAL QUANTITY: 600 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	12"x12" Cream w/Specks Vinyl Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout North & South Modulars**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	M				
MATERIAL DESCRIPTION:	12"x12" Cream w/Specks Vinyl Floor Tile Mastic NOT OBSERVED				
MATERIAL LOCATION:	Throughout North & South Modulares				
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M-1		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **401/402 Modular Unit**

MATERIAL QUANTITY: **600**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	M-1				
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic NOT OBSERVED				
MATERIAL LOCATION:	401/402 Modular Unit				
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M-2		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic	NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	403/404 Modular Building		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	M-2				
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic NOT OBSERVED				
MATERIAL LOCATION:	403/404 Modular Building				
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Transite Cream Texture Wall	NOT OBSERVED	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM	with the potential for damage	
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout North Modulars**

MATERIAL QUANTITY: **960**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: N

MATERIAL DESCRIPTION: Transite Cream Texture Wall NOT OBSERVED

MATERIAL LOCATION: Throughout North Modulares

MATERIAL QUANTITY: 960 MATERIAL UNITS: SF

DAMAGE QUANTITY: 0 DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW	
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM	
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	NEW				
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM				
MATERIAL LOCATION:	Installed After Implementation of Management Plan and After Renovations				
MATERIAL QUANTITY:				MATERIAL UNITS:	
DAMAGE QUANTITY:				DAMAGE UNITS:	

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O-1		
MATERIAL DESCRIPTION:	4'x8' Textured Ceiling Panels NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout North & South Modulars**

MATERIAL QUANTITY: **1200**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY:

DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	O-1				
MATERIAL DESCRIPTION:	4'x8' Textured Ceiling Panels NOT OBSERVED				
MATERIAL LOCATION:	Throughout North & South Modulares				
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P-1		
MATERIAL DESCRIPTION:	White Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout North & South Modulars		
MATERIAL QUANTITY:	160	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: P-1

MATERIAL DESCRIPTION: White Baseboard

MATERIAL LOCATION: Throughout North & South Modulars

MATERIAL QUANTITY: 160 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Q-1		
MATERIAL DESCRIPTION:	White Baseboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout North & South Modulars**

MATERIAL QUANTITY: **160**

MATERIAL UNITS: **LF**

DAMAGE QUANTITY:

DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	Q-1				
MATERIAL DESCRIPTION:	White Baseboard Adhesive				
MATERIAL LOCATION:	Throughout North & South Modulars				
MATERIAL QUANTITY:	160	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	LF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room and Tunnels		
MATERIAL QUANTITY:	1660	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	5 LF of material damaged at south end of basement		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	R				
MATERIAL DESCRIPTION:	Aircell Pipe Insulation				
MATERIAL LOCATION:	Boiler Room and Tunnels				
MATERIAL QUANTITY:	1660	MATERIAL UNITS:	LF		
DAMAGE QUANTITY:	5	DAMAGE UNITS:	LF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	S		
MATERIAL DESCRIPTION:	Cementitious Pipe Joint Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room and Tunnels		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:	2025- 10 LF of material damaged in North crawlspace		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: S

MATERIAL DESCRIPTION: Cementitious Pipe Joint Insulation

MATERIAL LOCATION: Boiler Room and Tunnels

MATERIAL QUANTITY: 150 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	U		
MATERIAL DESCRIPTION:	Boiler Tank Jacket		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: U

MATERIAL DESCRIPTION: Boiler Tank Jacket

MATERIAL LOCATION: Boiler Room

MATERIAL QUANTITY: 2400

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	V		
MATERIAL DESCRIPTION:	Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases in Bathrooms		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: V

MATERIAL DESCRIPTION: Pipe Fittings

MATERIAL LOCATION: Pipe Chases in Bathrooms

MATERIAL QUANTITY: 100 MATERIAL UNITS: LF

DAMAGE QUANTITY: 0 DAMAGE UNITS: LF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	W		
MATERIAL DESCRIPTION:	Chalkboards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	401/402		
MATERIAL QUANTITY:	104	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Throughout Main		

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA:	W				
MATERIAL DESCRIPTION:	Chalkboards				
MATERIAL LOCATION:	401/402				
MATERIAL QUANTITY:	104	MATERIAL UNITS:	SF		
DAMAGE QUANTITY:	0	DAMAGE UNITS:	SF		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	X		
MATERIAL DESCRIPTION:	Chalkboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	401/402		
MATERIAL QUANTITY:	104	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	2025- Throughout Main		

Inspector's Signature:



Date: 06/02/2025

Date: 06/16/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Y		
MATERIAL DESCRIPTION:	Chalkboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	403/404		
MATERIAL QUANTITY:	104	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: Y

MATERIAL DESCRIPTION: Chalkboard

MATERIAL LOCATION: 403/404

MATERIAL QUANTITY: 104

MATERIAL UNITS: SF

DAMAGE QUANTITY: 0

DAMAGE UNITS: SF

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: 06/16/2025



# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Josh Herman		
SCHOOL NAME:	Pasteur School	INSPECTION DATE:	6/2/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Z		
MATERIAL DESCRIPTION:	Chalkboard Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	403/404		
MATERIAL QUANTITY:	104	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24851	BUILDING ID:	5310
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	James Tuinenga		
SCHOOL NAME:	Pasteur School	REVIEW DATE:	6/16/2025		
ADDRESS:	5825 S. Kostner	IDPH LICENSE NO:	100-21040		

---

HOMOGENEOUS AREA: **Z**

MATERIAL DESCRIPTION: **Chalkboard Adhesive**

MATERIAL LOCATION: **403/404**

MATERIAL QUANTITY: **104** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24851**      BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Pasteur School**      INSPECTION DATE: **6/2/2025**  
ADDRESS: **5825 S. Kostner**      IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **042**  
MATERIAL DESCRIPTION: **Hexagonal Ceramic Tile Grout**  
MATERIAL LOCATION: **2nd Floor Old Locker Rooms, Washrooms**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:  \_\_\_\_\_ Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **042**  
MATERIAL DESCRIPTION: **Hexagonal Ceramic Tile Grout**  
MATERIAL LOCATION: **2nd Floor Old Locker Rooms, Washrooms**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24851**      BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Pasteur School**      INSPECTION DATE: **6/2/2025**  
ADDRESS: **5825 S. Kostner**      IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **039**  
MATERIAL DESCRIPTION: **12"x12" Green, Light Blue & White Floor Tile**  
MATERIAL LOCATION: **All Mobile Units**  
MATERIAL QUANTITY: **6000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:  \_\_\_\_\_ Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **039**  
MATERIAL DESCRIPTION: **12"x12" Green, Light Blue & White Floor Tile**  
MATERIAL LOCATION: **All Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24851**      BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Pasteur School**      INSPECTION DATE: **6/2/2025**  
ADDRESS: **5825 S. Kostner**      IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **040**  
MATERIAL DESCRIPTION: **2"x2" Ceramic Tile Grout**  
MATERIAL LOCATION: **1st Floor Boys' & Girls' Washrooms, 2nd Floor Staff Washroom**  
MATERIAL QUANTITY: **1000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:  \_\_\_\_\_ Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **040**  
MATERIAL DESCRIPTION: **2"x2" Ceramic Tile Grout**  
MATERIAL LOCATION: **1st Floor Boys' & Girls' Washrooms, 2nd Floor Staff Washroom**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24851**      BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Pasteur School**      INSPECTION DATE: **6/2/2025**  
ADDRESS: **5825 S. Kostner**      IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **039M**  
MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Green, Light Blue & White Floor Tile**  
MATERIAL LOCATION: **All Mobile Units**  
MATERIAL QUANTITY: **6000**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:       Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **039M**  
MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Green, Light Blue & White Floor Tile**  
MATERIAL LOCATION: **All Mobile Units**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24851**      BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Pasteur School**      INSPECTION DATE: **6/2/2025**  
ADDRESS: **5825 S. Kostner**      IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **045**  
MATERIAL DESCRIPTION: **Stage Curtains**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **900**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:  \_\_\_\_\_ Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **045**  
MATERIAL DESCRIPTION: **Stage Curtains**  
MATERIAL LOCATION: **Auditorium**  
MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24851**      BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Pasteur School**      INSPECTION DATE: **6/2/2025**  
ADDRESS: **5825 S. Kostner**      IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **043**  
MATERIAL DESCRIPTION: **Fire Brick**  
MATERIAL LOCATION: **Room 118 Lunchroom**  
MATERIAL QUANTITY: **50**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:       Date: **06/02/2025**

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **043**  
MATERIAL DESCRIPTION: **Fire Brick**  
MATERIAL LOCATION: **Room 118 Lunchroom**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**

# Chicago Public Schools

TEM Environmental, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **24851**      BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Josh Herman**  
SCHOOL NAME: **Pasteur School**      INSPECTION DATE: **6/2/2025**  
ADDRESS: **5825 S. Kostner**      IDPH LICENSE NO: **100-21040**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **041**  
MATERIAL DESCRIPTION: **2"x2" Blue Ceramic Tile Grout**  
MATERIAL LOCATION: **All Mobile Units**  
MATERIAL QUANTITY: **400**      MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**      FRIABLE: **No**  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**      CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE QUANTITY: **0**      DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature:  \_\_\_\_\_ Date: 06/02/2025

# Chicago Public Schools

## TEM Environmental, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24851** BUILDING ID: **5310**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **James Tuinenga**  
SCHOOL NAME: **Pasteur School** REVIEW DATE: **6/16/2025**  
ADDRESS: **5825 S. Kostner** IDPH LICENSE NO: **100-21040**

HOMOGENEOUS AREA: **041**  
MATERIAL DESCRIPTION: **2"x2" Blue Ceramic Tile Grout**  
MATERIAL LOCATION: **All Mobile Units**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_



Date: **06/16/2025**



# APPENDIX B

## Inspector and Management Planner Licenses

---



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630

5/23/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 21040

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License



**ASBESTOS  
PROFESSIONAL  
LICENSE**

ID NUMBER  
100 - 21040

ISSUED  
5/23/2025

EXPIRES  
05/15/2026

**JOSH R HERMAN**  
5121 N MONITOR AVE  
CHICAGO, IL 60630  
Environmental Health



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

7/19/2025

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH. IMPROVING LIVES**  
*Nationally Accredited by PHAB*



Reliable  
Environmental  
Solutions, Inc. **RES**

*This is to certify that*

**James Tuinenga**

*has on 2/2/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

Certificate Number: BIR/1013

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)





Reliable  
Environmental  
Solutions, Inc. **RES**

*This is to certify that*

**James Tuinenga**

*has on 2/02/22, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 2, 2022

**COURSE LENGTH: 4 HOURS**

Examination Date: February 2, 2022

Expiration Date: February 2, 2023

Certificate Number: MPR/0458

*William S. Williams*

Training Program Manager, William S. Williams

4211 Westgate Drive, Springfield, Illinois ☐ 217.787.9800 ☐ 217.787.9801 FAX ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



ENDORSEMENTS	TC EXPIRES
INSPECTOR	1/31/2025
PROJECT DESIGNER	2/1/2025
MANAGEMENT PLANNER	1/31/2025
PROJECT MANAGER	1/30/2025
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b>	
This license issued under authority of the State of Illinois	
Department of Public Health	
This license is valid only when accompanied by a valid	
training course certificate.	



**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that*

**James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Building Inspector Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher.*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025


Expiration Date: February 5, 2026

Certificate Number: BIR/1227

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)



ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/5/2026
PROJECT DESIGNER	2/6/2025
MANAGEMENT PLANNER	2/5/2026
PROJECT MANAGER	2/4/2026
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b>	
This license issued under authority of the State of Illinois	
Department of Public Health	
This license is valid only when accompanied by a valid	
training course certificate.	



**Reliable**  
**Environmental**  
**Solutions, Inc.** **RES**

*This is to certify that* **James Tuinenga**

*has on 2/5/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*

Course Date: February 5, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: February 5, 2025

Expiration Date: February 5, 2026

Certificate Number: MPR/0546

*William S. Williams*

Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois ☐ 217.787.9800 ☐ [www.ReliableEnv.com](http://www.ReliableEnv.com)

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed