

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2404  
SCHOOL NAME: Pickard School  
ADDRESS OF SCHOOL: 2301 W. 21st Pl.  
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 9/22/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II (Please type or print)**

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 4/4/2025 ENROLLMENT 274  
IDPH INSPECTOR LICENSE NUMBER: 100-06435  
IDPH LICENSED INSPECTOR NAME (Please Print): Jose Escobedo  
IDPH MP LICENSE NUMBER: 100-20634  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 4/28/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Pickard School**

2301 W. 21st Pl.  
Chicago, IL, 60608

Unit: 24961  
Building ID: 5430

IDPH ID Number: 14-016-2990-2404

**REPORT DATE:**  
Monday, April 28, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500  
Chicago, IL, 60607  
Phone (312) 762-2900  
Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

04/28/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 24961      Region: 03      IDPH ID: 14-016-2990-2404

School: Pickard School      Building ID: 5430

Address: 2301 W. 21st Pl.

Chicago, IL, 60608

Building Contact: Haynes, Patrick      Contact Phone: 7737101059

Current Building Owners: Chicago Public Schools

Reinspection Date: 4/4/2025

Review Date: 04/28/2025

Inspector: Jose Escobedo

Inspector IDPH License: 100-06435

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Jackson Montgomery  
100-20634

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 28, 2025

RE: Pickard School, Unit 24961  
2301 W. 21st Pl.  
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Pickard School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Pickard School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

## 1. School Information

School: Pickard School Unit: 24961 Region: 03  
Address: 2301 W. 21st Pl. Chicago, IL, 60608  
IDPH ID: 14-016-2990-2404 Building ID: 5430  
Contact: Haynes, Patrick Phone: 7737101059

## 2. Description of Facility

Original Construction: 2001 Additional Construction: 1896  
Total Square Footage: 46690 No of Floors: 3  
Current Occupancy: 274

### 3. LEA Designated Person

#### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

## 5. Inspector

Inspector Name: Jose Escobedo

Inspector IDPH license # 100-06435  
Reinspection Date: 4/4/2025

## 6. Management Planner

Management Planner Name: Jackson Montgomery

Management Planner IDPH license # 100-20634

Signature: 

7. Review Date: 04/28/2025

## 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schleyer

Signature:

Date: 4/28/2025

Name: Richard J. Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Pickard School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5430:

103	12" x 12" Bright Blue Vinyl Floor Tile Mastic
105	Boiler Gasket
106	Sink Insulation
107	Water Pump Gaskets
109	12" x 12" New Brown Vinyl Floor Tile Mastic
10F	Blue 12" x 12" Floor Tile Mastic
10H	Off-White 12" x 12" Floor Tile Mastic
10I	Light Brown 12" x 12" Floor Tile Mastic
111	12" x 12" Blotted Red Vinyl Floor Tile Mastic

113	12" x 12" Blotted White Vinyl Floor Tile Mastic
118	Gray Carpet Adhesive
12	1' x 1' Acoustical Ceiling Tile Mastic
121	12" x 12" Blotted Blue Vinyl Floor Tile Mastic
124	12" x 12" Blotted Beige Vinyl Floor Tile Mastic
126	12" x 12" Blotted Green Vinyl Floor Tile Mastic
129	12" x 12" Bright White Vinyl Floor Tile
13	Red Brick - Non-AHERA
130	12" x 12" Bright White Vinyl Floor Tile Mastic
132	12" x 12" Bright Blue Vinyl Floor Tile Mastic
139	12" x 12" Green Gray and Tan Floor Tile Mastic
16	Hardcoat Plaster
20	Stage Curtains
22	Chalk Board Adhesive
23	Marker Board Adhesive
26	4" Gray Baseboard
27	4" Gray Baseboard Adhesive
29	12" x 12" Blue Floor Tile Mastic
2B	12" x 12" White Speckled Floor Tile
2G	12" x 12" Dark Tan Floor Tile
2H	12" x 12" Off-White Floor Tile
2I	12" x 12" Light Brown Floor Tile
30	Blue Carpet Adhesive
31	12" x 12" Beige Mix Floor Tile

32	12" x 12" Beige Mix Floor Tile Mastic
35	12" x 12" Beige Mix Floor Tile
36	12" x 12" Beige Mix Floor Tile Mastic
38	12" x 12" Green Mix Floor Tile Mastic
40	12" x 12" Red Mix Floor Tile Mastic
42	12" x 12" Light Blue Mix Floor Tile Mastic
44	12" x 12" Dark Blue Mix Floor Tile Mastic
46	1" Dark Blue Floor Tile Striping Mastic
48	1" Yellow Floor Tile Striping Mastic
55	4" Beige Vinyl Baseboard Adhesive
56	Material Inside Of Wall Mats
58	Marker Board Adhesive
59	Chalk Board Adhesive
60	Brown Mix Carpet Adhesive
62	12" x 12" Beige Floor Tile Mastic
64	12" x 12" Red Floor Tile Mastic
65	Brown Carpet Mastic
68	12" x 12" White w/ Cream Specks Floor Tile
70m	12" x 12" Tan w/ White Specks Floor Tile Mastic
71m	4" Black Baseboard Mastic
73	Terrazzo Sinks
74	1' x 1' White Ceiling Tile Adhesive
K	Packing Material

B. The following new homogenous areas have been identified for Building 5430:

- 141 Black Epoxy Flooring
- 142 1" x 1" Brown and White Ceramic Floor Tile
- 143 Gray CMU
- 144 Gray CMU Mortar
- 145 White Glazed CMU
- 146 White Glazed CMU Mortar
- 147 Green Glazed CMU
- 148 Green Glazed CMU Mortar
- 149 Red Glazed CMU
- 150 Red Glazed CMU Mortar
- 151 2" x 2" Light Blue Ceramic Floor Tile
- 152 2" x 2" Light Blue Ceramic Floor Tile Mortar
- 153 2" x 2" Cream Ceramic Wall Tile
- 154 2" x 2" Cream Ceramic Wall Tile Mortar
- 155 2" x 2" Dark Blue Ceramic Floor Tile
- 156 2" x 2" Dark Blue Ceramic Floor Tile Mortar
- 157 2" x 2" Cream Ceramic Floor Tile
- 158 2" x 2" Cream Ceramic Floor Tile Mortar
- 159 2" x 2" Yellow Ceramic Floor Tile
- 160 2" x 2" Yellow Ceramic Floor Tile Mortar
- 161 Thermal Insulation

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	9" x 9" Floor Tile (Enclosed By 12" x 12")
100	Door Caulk
101	Window Caulk
102	12" x 12" Bright Blue Vinyl Floor Tile
103	12" x 12" Bright Blue Vinyl Floor Tile Mastic
104	1' x 1' Ceiling Tile
105	Boiler Gasket
106	Sink Insulation
107	Water Pump Gaskets
108	12" x 12" New Brown Vinyl Floor Tile
109	12" x 12" New Brown Vinyl Floor Tile Mastic
10A	12" x 12" Tan Speckled Floor Tile Mastic
10B	12" x 12" White Speckled Floor Tile Mastic
10C	12" x 12" Brown Speckled Floor Tile Mastic
10D	12" x 12" Pink Speckled Floor Tile Mastic
10E	12" x 12" Beige Speckled Floor Tile Mastic
10F	Blue 12" x 12" Floor Tile Mastic
10G	Dark Tan 12" x 12" Floor Tile Mastic
10H	Off-White 12" x 12" Floor Tile Mastic
110	12" x 12" Blotted Red Vinyl Floor Tile
111	12" x 12" Blotted Red Vinyl Floor Tile Mastic
112	12" x 12" Blotted White Vinyl Floor Tile
113	12" x 12" Blotted White Vinyl Floor Tile Mastic
114	White Terrazzo
115	Red Terrazzo
116	Green Terrazzo
117	Blue Terrazzo
118	Gray Carpet Adhesive
119	Blue Epoxy Flooring
11C	Linoleum Mastic
12	1' x 1' Acoustical Ceiling Tile Mastic
120	12" x 12" Blotted Blue Vinyl Floor Tile
121	12" x 12" Blotted Blue Vinyl Floor Tile Mastic
122	2' x 4' Solid Ceiling Tile
123	12" x 12" Blotted Beige Vinyl Floor Tile
124	12" x 12" Blotted Beige Vinyl Floor Tile Mastic
125	12" x 12" Blotted Green Vinyl Floor Tile
126	12" x 12" Blotted Green Vinyl Floor Tile Mastic
127	Drywall
128	Joint Compound
129	12" x 12" Bright White Vinyl Floor Tile
130	12" x 12" Bright White Vinyl Floor Tile Mastic

131	12" x 12" Bright Blue Vinyl Floor Tile
132	12" x 12" Bright Blue Vinyl Floor Tile Mastic
133	2' x 4' Fiber Ceiling Tile
134	Spray on Fire Proofing
136	Brown Vinyl Plank Flooring
137	12" x 12" Gray w/ Black Specks Floor Tile
138	12" x 12" Tan w/ Gray Specks Floor Tile
139	12" x 12" Green Gray and Tan Floor Tile Mastic
140	Tongue and Groove Wood Flooring
141	Black Epoxy Flooring
142	1" x 1" Brown and White Ceramic Floor Tile
143	Gray CMU
144	Gray CMU Mortar
145	White Glazed CMU
146	White Glazed CMU Mortar
147	Green Glazed CMU
148	Green Glazed CMU Mortar
149	Red Glazed CMU
15	9" x 9" Floor Tile Mastic
150	Red Glazed CMU Mortar
151	2" x 2" Light Blue Ceramic Floor Tile
152	2" x 2" Light Blue Ceramic Floor Tile Mortar
153	2" x 2" Cream Ceramic Wall Tile
154	2" x 2" Cream Ceramic Wall Tile Mortar
155	2" x 2" Dark Blue Ceramic Floor Tile
156	2" x 2" Dark Blue Ceramic Floor Tile Mortar
157	2" x 2" Cream Ceramic Floor Tile
158	2" x 2" Cream Ceramic Floor Tile Mortar
159	2" x 2" Yellow Ceramic Floor Tile
16	Hardcoat Plaster
160	2" x 2" Yellow Ceramic Floor Tile Mortar
161	Thermal Insulation
17	Burlap Wall Covering
18	1' x 1' Acoustical Ceiling Tile
19	Rough Coat Plaster
20	Stage Curtains
21	Textured Paint
22	Chalk Board Adhesive
23	Marker Board Adhesive
24	Non-Skid Strips
25	2' x 4' Lay-in Ceiling Panels
26	4" Gray Baseboard
27	4" Gray Baseboard Adhesive
28	12" x 12" Blue Floor Tile
29	12" x 12" Blue Floor Tile Mastic
2A	12" x 12" Tan Speckled Floor Tile
2B	12" x 12" White Speckled Floor Tile
2C	12" x 12" Brown Speckled Floor Tile

2D	12" x 12" Beige Speckled Floor Tile
2E	12" x 12" Beige Speckled Floor Tile
2F	12" x 12" Blue Floor Tile
2G	12" x 12" Dark Tan Floor Tile
2H	12" x 12" Off-White Floor Tile
30	Blue Carpet Adhesive
31	12" x 12" Beige Mix Floor Tile
32	12" x 12" Beige Mix Floor Tile Mastic
33	Sink Undercoating
34	Masonite Wall Covering Adhesive
35	12" x 12" Beige Mix Floor Tile
36	12" x 12" Beige Mix Floor Tile Mastic
37	12" x 12" Green Mix Floor Tile
38	12" x 12" Green Mix Floor Tile Mastic
39	12" x 12" Red Mix Floor Tile
3C	Linoleum
40	12" x 12" Red Mix Floor Tile Mastic
41	12" x 12" Light Blue Mix Floor Tile
42	12" x 12" Light Blue Mix Floor Tile Mastic
43	12" x 12" Dark Blue Mix Floor Tile
44	12" x 12" Dark Blue Mix Floor Tile Mastic
45	1" Dark Blue Floor Tile Striping
46	1" Dark Blue Floor Tile Striping Mastic
47	1" Yellow Floor Tile Striping
48	1" Yellow Floor Tile Striping Mastic
49	2' x 4' Fissured Lay-in Ceiling Panels
50	Tectum Ceiling Panels
51	2' x 4' Smooth Lay-in Ceiling Panels
52	Drywall
53	Drywall Compound
54	4" Beige Vinyl Baseboard
55	4" Beige Vinyl Baseboard Adhesive
56	Material Inside Of Wall Mats
57	Spray on Fireproofing
58	Marker Board Adhesive
59	Chalk Board Adhesive
60	Brown Mix Carpet Adhesive
61	12" x 12" Beige Floor Tile
62	12" x 12" Beige Floor Tile Mastic
63	12" x 12" Red Floor Tile
64	12" x 12" Red Floor Tile Mastic
65	Brown Carpet Mastic
66	New Fire Doors
67	Old Fire Doors
68	12" x 12" White w/ Cream Specks Floor Tile
68m	12" x 12" White w/ Cream Specks Floor Tile Mastic
69	Light Blue Floor Tile Border
70	12" x 12" Tan Floor Tile w/ White Specks

70m	12" x 12" Tan w/ White Specks Floor Tile Mastic
71	4" Black Baseboard
71m	4" Black Baseboard Mastic
72	Ceramic Grout
73	Terrazzo Sinks
74	1' x 1' White Ceiling Tile Adhesive
75	2' x 2' Lay-in Ceiling Tile
8	Masonite Wall Covering
H	Mag - Block Joints

The following areas were deemed to be inaccessible:

10A	12" x 12" Tan Speckled Floor Tile Mastic
10B	12" x 12" White Speckled Floor Tile Mastic
10D	12" x 12" Pink Speckled Floor Tile Mastic
10E	12" x 12" Beige Speckled Floor Tile Mastic
25	2' x 4' Lay-in Ceiling Panels
34	Masonite Wall Covering Adhesive
66	New Fire Doors
67	Old Fire Doors
68m	12" x 12" White w/ Cream Specks Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jose Escobedo, IDPH License # 100-06435. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Pickard School Building 5430 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	9" x 9" Floor Tile (Enclosed By 12" x 12")			Room 103	ASSUMED	MISC					No			
100	Door Caulk	300	LF	Throughout	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
101	Window Caulk	300	LF	Throughout	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
102	12" x 12" Bright Blue Vinyl Floor Tile	800	SF	Rooms 112, 114, 404a, 004a	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
103	12" x 12" Bright Blue Vinyl Floor Tile Mastic			Rooms 112, 114, 404a, 004a	ASSUMED	MISC					Yes			
104	1' x 1' Ceiling Tile	800	SF	Rooms 112, 114, 404a, and 004a	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
105	Boiler Gasket			Boiler Room	ASSUMED	TSI					Yes			
106	Sink Insulation			Yoga	ASSUMED	TSI					Yes			
107	Water Pump Gaskets			Sprinkler Room	ASSUMED	MISC					Yes			
108	12" x 12" New Brown Vinyl Floor Tile	800	SF	Room 409 and Rr	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
109	12" x 12" New Brown Vinyl Floor Tile Mastic			Room 409 and Rr	ASSUMED	MISC					Yes			
10A	12" x 12" Tan Speckled Floor Tile Mastic	300	SF	Basement - Engineer's Office	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
10B	12" x 12" White Speckled Floor Tile Mastic	300	SF	Basement - Engineer's Office, 2nd Floor Teachers' Room	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
10C	12" x 12" Brown Speckled Floor Tile Mastic	1,500	SF	Basement - Kitchen	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
10D	12" x 12" Pink Speckled Floor Tile Mastic	3,750	SF	Basement - Assembly Hall and Room 009	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
10E	12" x 12" Beige Speckled Floor Tile Mastic	1,350	SF	Basement - Room 009, 103, 203, and 303	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
10F	Blue 12" x 12" Floor Tile Mastic			1st Floor Room 103	ASSUMED	MISC					Yes			
10G	Dark Tan 12" x 12" Floor Tile Mastic			1st Floor Principal's Bathroom	ASSUMED	MISC					No			
10H	Off-White 12" x 12" Floor Tile Mastic			1st Floor Principal's Office and Clerk Space	ASSUMED	MISC					Yes			
10I	Light Brown 12" x 12" Floor Tile Mastic			Mobile Unit # 4, 5 & 6	NO_ACBM	MISC					Yes			
10J	White 12" x 12" Floor Tile Mastic			Mobile Unit 002/003 Hallway	NO_ACBM	MISC					No			
110	12" x 12" Blotted Red Vinyl Floor Tile	500	SF	Room 103	ASSUMED	MISC	N				No	ACBM with the		LOW

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				(Kidagarden), 216, 214, 212, 210								potential for damage		
111	12" x 12" Blotted Red Vinyl Floor Tile Mastic			Room 103, 216, 214, 212, 210	ASSUMED	MISC					Yes			
112	12" x 12" Blotted White Vinyl Floor Tile	3,500	SF	Room 103, 214, 216, 212, 210	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
113	12" x 12" Blotted White Vinyl Floor Tile Mastic			Room 103, 216, 214, 212, 210	ASSUMED	MISC					Yes			
114	White Terrazzo	30,000	SF	Addition Corridor, Stairwells 2nd & 3rd Floor and Rr	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
115	Red Terrazzo	3,333	SF	Addition Corridor, Stairways 2nd & 3rd Floor and Rr	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
116	Green Terrazzo	3,333	SF	Addition Corridor, Stairways 2nd & 3rd Floor and Rr	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
117	Blue Terrazzo	2,000	SF	1st Floor Corridor	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
118	Gray Carpet Adhesive			Library and Teacher Lounge	ASSUMED	MISC					Yes			
119	Blue Epoxy Flooring	1,000	SF	Kitchen	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
11A	Brown Linoleum Mastic			Basement - Supply Room	NO_ACBM	MISC					No			
11B	Green Linoleum Mastic			Room 302 and Adjustment Office	NO_ACBM	MISC					No			
11C	Linoleum Mastic			3rd Floor Gym (New Gym Floor Enclosed Linoleum, 1995)	ASSUMED	MISC					No			
12	1' x 1' Acoustical Ceiling Tile Mastic			West End of 1st, 2nd, 3rd Floors	ASSUMED	MISC					Yes			
120	12" x 12" Blotted Blue Vinyl Floor Tile	3,000	SF	Servery and Multipurpose	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
121	12" x 12" Blotted Blue Vinyl Floor Tile Mastic			Servery and Multipurpose	ASSUMED	MISC					Yes			
122	2' x 4' Solid Ceiling Tile	1,000	SF	Kitchen	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
123	12" x 12" Blotted Beige Vinyl Floor Tile	5,600	SF	Room 310, 311, 312, 314, 316, 203, 313	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
124	12" x 12" Blotted Beige Vinyl Floor Tile Mastic			Room 310, 311, 312, 314, 316, 203, 313	ASSUMED	MISC					Yes			

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
125	12" x 12" Blotted Green Vinyl Floor Tile	1,000	SF	Room 310, 311, 312, 314, 316, 203, 313	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
126	12" x 12" Blotted Green Vinyl Floor Tile Mastic			Room 310, 311, 312, 314, 316, 203, 313	ASSUMED	MISC					Yes			
127	Drywall	200,000	SF	Addition Throughout	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
128	Joint Compound	20,000	SF	Addition Throughout	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
129	12" x 12" Bright White Vinyl Floor Tile			Room 303	ASSUMED	MISC					Yes			
13	Red Brick - Non-AHERA			Building Exterior - East Side, Building Exterior - West Side	NO_ACBM	SURFACE					Yes			
130	12" x 12" Bright White Vinyl Floor Tile Mastic			Room 303	ASSUMED	MISC					Yes			
131	12" x 12" Bright Blue Vinyl Floor Tile	200	SF	Room 303	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
132	12" x 12" Bright Blue Vinyl Floor Tile Mastic			Room 303	ASSUMED	MISC					Yes			
133	2' x 4' Fiber Ceiling Tile	4,000	SF	Gym and Stairwells	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
134	Spray on Fire Proofing	40,000	SF	Throughout	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
136	Brown Vinyl Plank Flooring	1,200	SF	Main Office 102	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
137	12" x 12" Gray w/ Black Specks Floor Tile	400	SF	Room 404	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
138	12" x 12" Tan w/ Gray Specks Floor Tile	400	SF	Room 404	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
139	12" x 12" Green Gray and Tan Floor Tile Mastic			Room 404	ASSUMED	MISC					Yes			
14	Gray Brick Mortar - Non-AHERA			Building Exterior - East Side, Building Exterior - West Side,	NO_ACBM	MISC					No			
140	Tongue and Groove Wood Flooring	1,000	SF	Rooms 300, 301, 308, 304, 305, 306, 307, 206, Close Across 206, 205, 204, 201, 202, 106, Storage Across 106, 105, 104, Auditorium, 401	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
141	Black Epoxy Flooring	50,000	SF	Throughout Old	ASSUMED	MISC	N	NONE				ACBM with the		LOW

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building								potential for damage		
142	1" x 1" Brown and White Ceramic Floor Tile	10,000	SF	Throughout Boys and Girls Toilet Rooms in Original Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
143	Gray CMU	50,000	LF	Throughout Corridors in New Addition Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
144	Gray CMU Mortar	50,000	LF	Throughout Corridors in New Additions Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
145	White Glazed CMU	1,000	LF	Throughout Boys and Girls Toilet Rooms in New Additions Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
146	White Glazed CMU Mortar	1,000	LF	Throughout Boys and Girls Toilet Rooms in New Additions Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
147	Green Glazed CMU	500	LF	3rd Floor Boys and Girls Toilet Rooms in New Additions Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
148	Green Glazed CMU Mortar	500	LF	3rd Floor Boys and Girls Toilet Rooms in New Additions Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
149	Red Glazed CMU	500	LF	2nd Floor Boys and Girls Toilet Rooms in New Additions Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
15	9" x 9" Floor Tile Mastic			Gym	ASSUMED	MISC					No			
150	Red Glazed CMU Mortar	500	LF	2nd Floor Boys and Girls Toilet Rooms in New Additions Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
151	2" x 2" Light Blue Ceramic Floor Tile	200	SF	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
152	2" x 2" Light Blue Ceramic Floor Tile Mortar	200	SF	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				of Old Building										
153	2" x 2" Cream Ceramic Wall Tile	500	LF	Room 114 and 112 Bathroom, Boys and Girls Bathroom 1st Floor of Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
154	2" x 2" Cream Ceramic Wall Tile Mortar	500	LF	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
155	2" x 2" Dark Blue Ceramic Floor Tile	500	SF	Boys Bathroom 1st Floor of Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
156	2" x 2" Dark Blue Ceramic Floor Tile Mortar	500	LF	Boys Bathroom 1st Floor of Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
157	2" x 2" Cream Ceramic Floor Tile	1,000	SF	Boys and Girls Bathroom 1st Floor of Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
158	2" x 2" Cream Ceramic Floor Tile Mortar	1,000	SF	Boys and Girls Bathroom 1st Floor of Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
159	2" x 2" Yellow Ceramic Floor Tile	400	SF	1st Floor Girls Bathroom in Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
16	Hardcoat Plaster	500,000	SF	Throughout Original Building	ASSUMED	SURFACE	Y	LOC	75	SF	Yes	Damaged friable surfacing ACBM	10	LOW
160	2" x 2" Yellow Ceramic Floor Tile Mortar	500	SF	1st Floor Girls Bathroom in Old Building	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
161	Thermal Insulation	3,000	LF	Boiler Room	ASSUMED	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
17	Burlap Wall Covering	3,000	SF	Teachers' Room and 3rd Floor Corridor	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
18	1' x 1' Acoustical Ceiling Tile	8,000	SF	West Portion of Original Building	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
19	Rough Coat Plaster	2,000	SF	Waroom Air Chamber in Original Building, Basement Hallway	ASSUMED	SURFACE	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
20	Stage Curtains	3,000	SF	Auditorium	ASSUMED	MISC	N				Yes	ACBM with the		MODERATE

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
21	Textured Paint	2,000	SF	Original Building: Ceilings, Pipe, Duct in Basement Corridor, Engineer's Office, 409a, Storage by Fan Room	ASSUMED	MISC	N	LOC	50	SF	No	ACBM with potential for significant damage	3	MODERATE
22	Chalk Board Adhesive			Original Building: Classrooms 101-106, 204-206, 300, 301, 304-306, 308 and 2nd Floor Teachers' Lounge	ASSUMED	MISC					Yes			
23	Marker Board Adhesive			Original Building: 409a and 103	ASSUMED	MISC					Yes			
24	Non-Skid Strips	300	LF	Original Building Stairs	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
25	2' x 4' Lay-in Ceiling Panels	1,600	LF	Original Building: Classroom 409a and Bathroom	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
26	4" Gray Baseboard			Original Building: Classroom 404	ASSUMED	MISC					Yes			
27	4" Gray Baseboard Adhesive			Original Building: Classroom 404	ASSUMED	MISC					Yes			
28	12" x 12" Blue Floor Tile	60	SF	Room 303 Border	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
29	12" x 12" Blue Floor Tile Mastic			Original Building: Classroom 409a and Bathroom	ASSUMED	MISC					Yes			
2A	12" x 12" Tan Speckled Floor Tile	150	SF	Basement - Engineer's Office Bathroom	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
2B	12" x 12" White Speckled Floor Tile	3,000	SF	Basement - Engineer's Office and 2nd Floor Teachers' Room, 202a and Library	ASSUMED	MISC	N				Yes	ACBM with the potential for damage		LOW
2C	12" x 12" Brown Speckled Floor Tile	1,500	SF	Basement - Kitchen	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
2D	12" x 12" Beige Speckled Floor Tile	1,300	SF	Basement - Assembly Hall and Room 009	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
2E	12" x 12" Beige Speckled Floor Tile	1,350	SF	Basement - Room	ASSUMED	MISC	N				No	ACBM with the		LOW

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				009, 103, 203, and 303								potential for damage		
2F	12" x 12" Blue Floor Tile	800	SF	1st Floor Room 103	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
2G	12" x 12" Dark Tan Floor Tile			1st Floor Principal's Bathroom (Wood)	ASSUMED	MISC					Yes			
2H	12" x 12" Off-White Floor Tile			1st Floor Principal's Office, Clerk's Space (Wood)	ASSUMED	MISC					Yes			
2I	12" x 12" Light Brown Floor Tile			Mobile Units 4, 5, 6	NO_ACBM	MISC					Yes			
2J	12" x 12" White Floor Tile			Mobile Unit 002/003 Hallway	NO_ACBM	MISC					No			
30	Blue Carpet Adhesive			Original Building: Office 102, Clerk's Office and Principal's Office	ASSUMED	MISC					Yes			
31	12" x 12" Beige Mix Floor Tile	900	SF	Original Building: Room 101, Library	ASSUMED	MISC	N				Yes	ACBM with the potential for damage		LOW
32	12" x 12" Beige Mix Floor Tile Mastic			Original Building: Room 101	ASSUMED	MISC					Yes			
33	Sink Undercoating	6	SF	Original Building: 2nd Floor Teachers' Lounge, 409-A	ASSUMED	SURFACE	N				No	ACBM with the potential for damage		LOW
34	Masonite Wall Covering Adhesive	600	SF	Basement	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
35	12" x 12" Beige Mix Floor Tile	8,000	SF	Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a	ASSUMED	MISC	N				Yes	ACBM with the potential for damage		LOW
36	12" x 12" Beige Mix Floor Tile Mastic			Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a	ASSUMED	MISC					Yes			
37	12" x 12" Green Mix Floor Tile	880	SF	2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and Library	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
38	12" x 12" Green Mix Floor Tile Mastic			2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and Library	ASSUMED	MISC					Yes			
39	12" x 12" Red Mix Floor Tile	440	SF	2002 Addition: Classrooms 210, 212, 214, and 216	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
3A	Brown Linoleum			Basement - Supply Room	NO_ACBM	MISC					No			
3B	Green Linoleum			Room 302 and Adjustment Office	NO_ACBM	MISC					No			
3C	Linoleum	2,700	SF	Gym	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
40	12" x 12" Red Mix Floor Tile Mastic			2002 Addition: Classrooms 210, 212, 214, and 216	ASSUMED	MISC					Yes			
41	12" x 12" Light Blue Mix Floor Tile	3,464	SF	2002 Addition: Classrooms 112, 114, 115, Kit., Servingarea&Allpur poseroom	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
42	12" x 12" Light Blue Mix Floor Tile Mastic			2002 Addition: Classrooms 112, 114, 115, Kit., Servingarea&Allpur poseroom	ASSUMED	MISC					Yes			
43	12" x 12" Dark Blue Mix Floor Tile	220	SF	2002 Addition: Classrooms 112 and 114	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
44	12" x 12" Dark Blue Mix Floor Tile Mastic			2002 Addition: Classrooms 112 and 114	ASSUMED	MISC					Yes			
45	1" Dark Blue Floor Tile Striping	13	SF	2002 Addition: All Purpose Room	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
46	1" Dark Blue Floor Tile Striping Mastic			2002 Addition: All Purpose Room	ASSUMED	MISC					Yes			
47	1" Yellow Floor Tile Striping	13	SF	2002 Addition: All Purpose Room	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
48	1" Yellow Floor Tile Striping Mastic			2002 Addition: All Purpose Room	ASSUMED	MISC					Yes			
49	2' x 4' Fissured Lay-in Ceiling Panels	28,000	SF	2002 Addition: All Corridors, Library and Classrooms	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
50	Tectum Ceiling Panels	1,200	SF	2002 Addition: All Purpose Room	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
51	2' x 4' Smooth Lay-in Ceiling Panels	2,600	SF	2002 Addition: Kitchen and Serving Area	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
52	Drywall	4,800	SF	2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
53	Drywall Compound	3,000	SF	2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
54	4" Beige Vinyl Baseboard	2,780	LF	Original Building: Classrooms 103, 302, 203 and 303 2002 Addition: All Classrooms, Serving Area, All Purposeroom&Library	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
55	4" Beige Vinyl Baseboard Adhesive			Original Building: Classrooms 103, 302, 203 and 303 2002 Addition: All Classrooms, Serving Area, All Purposeroom&Library	ASSUMED	MISC					Yes			
56	Material Inside Of Wall Mats			2002 Addition: All Purpose Room	ASSUMED	MISC					Yes			
57	Spray on Fireproofing	20,000	SF	Throughout 2002 Addition	ASSUMED	SURFACE	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
58	Marker Board Adhesive			2002 Addition: Classrooms 112, 114, 212, 216, 303, 310-314, and 316	ASSUMED	MISC					Yes			
59	Chalk Board Adhesive			2002 Addition: Classrooms 112, 114, 212, 214, 216,	ASSUMED	MISC					Yes			

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				303, 310-311, 313-314, and 316										
60	Brown Mix Carpet Adhesive			2002 Addition: Classroom 108, Library and 315	ASSUMED	MISC					Yes			
61	12" x 12" Beige Floor Tile	625	SF	Room 103 & Bathroom	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
62	12" x 12" Beige Floor Tile Mastic			Room 103 & Bathroom	ASSUMED	MISC					Yes			
63	12" x 12" Red Floor Tile	60	SF	Room 103 & Bathroom	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
64	12" x 12" Red Floor Tile Mastic			Room 103 & Bathroom	ASSUMED	MISC					Yes			
65	Brown Carpet Mastic			Library, Teachers' Lounge	ASSUMED	MISC					Yes			
66	New Fire Doors	800	SF	Throughout New Building	ASSUMED	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
67	Old Fire Doors	63	SF	Old Building 1, 2, 3 Floor Corridor Ends	ASSUMED	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
68	12" x 12" White w/ Cream Specks Floor Tile	768	SF	Original Building Room 302	ASSUMED	MISC	N				Yes	ACBM with the potential for damage		LOW
68m	12" x 12" White w/ Cream Specks Floor Tile Mastic	768	SF	Original Building Room 302	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
69	Light Blue Floor Tile Border	75	SF	Original Building Room 302	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
70	12" x 12" Tan Floor Tile w/ White Specks	800	SF	Original Building Room 409 and Toilet	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
70m	12" x 12" Tan w/ White Specks Floor Tile Mastic			Original Building Room 409 and Toilet	ASSUMED	MISC					Yes			
71	4" Black Baseboard	768	LF	Original Building 409 and Toilet	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
71m	4" Black Baseboard Mastic			Original Building Room 409	ASSUMED	MISC					Yes			
72	Ceramic Grout	1,080	SF	Original Building 1st, 2nd, and 3rd Floor Boys and Girls Toilets	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
73	Terrazzo Sinks			Original Building 1st, 2nd, 3rd Floors Boys and Girls	ASSUMED	MISC					Yes			

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bathrooms.										
74	1' x 1' White Ceiling Tile Adhesive			Original Building Rooms 201, 202, 202a, Office, Clerk Space, Principal Office, 1st- 3rd Corridors 301, 302, and 308	ASSUMED	MISC					Yes			
75	2' x 2' Lay-in Ceiling Tile	1,300	SF	Original Building 103, 205, and 303	ASSUMED	MISC	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
8	Masonite Wall Covering	600	SF	Basement	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
B	Cementitious Mud Joints			Fieldhouse	NO_ACBM	TSI								
C	Aircell Pipe Insulation	300	LF	Basement - Room 009, Sprinkler Pump Room, West Corridor, Assembly Hall Passage	CHR	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
D	Aircell Joints	40	LF	Basement - Room 009, Sprinkler Pump Room	CHR	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Cardboard Insulation Joints	60	LF	Basement - West Corridor	AMO	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
G	Mag - Block Pipe Insulation	30	LF	2nd Floor Above Principal's Bathroom	CHR	TSI					No			
H	Mag - Block Joints	2	LF	Basement - Corridor	ASSUMED	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
I	Joint Insul. Assoc. w/ Fiberglass Insulated Piping	100	LF	Basement and Bathrooms	CHR	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
J	Joint Insul. Assoc. w/ Cardboard Insulated Piping	140	SF	Basement and Bathrooms	CHR	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
K	Packing Material			MATERIAL REMOVED	NO_ACBM	MISC					Yes			

# Chicago Public Schools

School Pickard School Unit 24961 Building ID 5430  
Address 2301 W. 21st Pl. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>4/4/2025</u>
Inspector Name	<u>Jose Escobedo</u>
<b>100-06435</b>	<b>5/15/2026</b>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
1	Material not observed - 2025
100	
101	
102	
103	Material not observed - 2025
104	
105	Material not observed - 2025
106	Material not observed - 2025
107	Material not observed - 2025
108	
109	Material not observed - 2025
10A	
10B	
10C	
10D	
10E	
10F	Material not observed - 2025
10G	Material not observed - 2025
10H	Material not observed - 2025
10I	
10J	
110	
111	Material not observed - 2025
112	

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
113	Material not observed - 2025
114	
115	
116	
117	
118	Material not observed - 2025
119	
11A	
11B	
11C	Material not observed - 2025
12	Material not observed - 2025
120	
121	Material not observed - 2025
122	
123	
124	Material not observed - 2025
125	
126	Material not observed - 2025
127	
128	
129	Material not observed - 2025
13	
130	Material not observed - 2025
131	
132	Material not observed - 2025
133	
134	
136	
137	

# Chicago Public Schools

School Pickard School Unit 24961 Building ID 5430  
Address 2301 W. 21st Pl. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
138	
139	Material not observed - 2025
14	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
15	Material not observed - 2025
150	
151	
152	
153	
154	
155	
156	
157	
158	
159	
16	Damage in: 3rd Floor corridor near room 303
160	
161	
17	
18	

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
19	
20	
21	Damage near room 104
22	Material not observed - 2025
23	Material not observed - 2025
24	
25	
26	Material not observed - 2025
27	Material not observed - 2025
28	
29	Material not observed - 2025
2A	
2B	Damage fixed
2C	
2D	
2E	
2F	
2G	Material not observed - 2025
2H	Material not observed - 2025
2I	
2J	
30	Material not observed - 2025
31	Damaged fixed
32	Material not observed - 2025
33	
34	
35	Damage fixed
36	Material not observed - 2025
37	

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
38	Material not observed - 2025
39	
3A	
3B	
3C	
40	Material not observed - 2025
41	
42	Material not observed - 2025
43	
44	Material not observed - 2025
45	
46	Material not observed - 2025
47	
48	Material not observed - 2025
49	
50	
51	
52	
53	
54	
55	Material not observed - 2025
56	Material not observed - 2025
57	
58	Material not observed - 2025
59	Material not observed - 2025
60	Material not observed - 2025
61	
62	Material not observed - 2025
63	

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
64	Material not observed - 2025
65	Material not observed - 2025
66	
67	
68	Damage fixed
68m	
69	
70	
70m	Material not observed - 2025
71	
71m	Material not observed - 2025
72	
73	Material not observed - 2025
74	Material not observed - 2025
75	
8	
B	
C	
D	
F	
G	Material in inaccessible area(s) - 2025
H	
I	
J	
K	

# Chicago Public Schools

**School** Pickard School **Unit** 24961 **Building ID** 5430  
**Address** 2301 W. 21st Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500  
Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	9" x 9" Floor Tile (Enclosed By 12" x 12")			Room 103	Assumed	MISC					
100	Door Caulk	300	LF	Throughout	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
101	Window Caulk	300	LF	Throughout	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
102	12" x 12" Bright Blue Vinyl Floor Tile	800	SF	Rooms 112, 114, 404a, 004a	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
103	12" x 12" Bright Blue Vinyl Floor Tile Mastic			Rooms 112, 114, 404a, 004a	Assumed	MISC					
104	1' x 1' Ceiling Tile	800	SF	Rooms 112, 114, 404a, and 004a	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
105	Boiler Gasket			Boiler Room	Assumed	TSI					
106	Sink Insulation			Yoga	Assumed	TSI					
107	Water Pump Gaskets			Sprinkler Room	Assumed	MISC					
108	12" x 12" New Brown Vinyl Floor Tile	800	SF	Room 409 and Rr	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
109	12" x 12" New Brown Vinyl Floor Tile Mastic			Room 409 and Rr	Assumed	MISC					
10A	12" x 12" Tan Speckled Floor Tile Mastic	300	SF	Basement - Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10B	12" x 12" White Speckled Floor Tile Mastic	300	SF	Basement - Engineer's Office, 2nd Floor Teachers' Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10C	12" x 12" Brown Speckled Floor Tile Mastic	1,500	SF	Basement - Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10D	12" x 12" Pink Speckled Floor Tile Mastic	3,750	SF	Basement - Assembly Hall and Room 009	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10E	12" x 12" Beige Speckled Floor Tile Mastic	1,350	SF	Basement - Room 009, 103, 203, and 303	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10F	Blue 12" x 12" Floor Tile Mastic			1st Floor Room 103	Assumed	MISC					
10G	Dark Tan 12" x 12" Floor Tile Mastic			1st Floor Principal's Bathroom	Assumed	MISC					
10H	Off-White 12" x 12" Floor Tile Mastic			1st Floor Principal's Office and Clerk Space	Assumed	MISC					
10I	Light Brown 12" x 12" Floor Tile Mastic			Mobile Unit # 4, 5 & 6	No ACBM	MISC					
10J	White 12" x 12" Floor Tile Mastic			Mobile Unit 002/003 Hallway	No ACBM	MISC					
110	12" x 12" Blotted Red Vinyl Floor Tile	500	SF	Room 103 (Kidagarden), 216, 214, 212, 210	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
111	12" x 12" Blotted Red Vinyl Floor Tile Mastic			Room 103, 216, 214, 212, 210	Assumed	MISC					
112	12" x 12" Blotted White Vinyl Floor Tile	3,500	SF	Room 103, 214, 216, 212, 210	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
113	12" x 12" Blotted White Vinyl Floor Tile Mastic			Room 103, 216, 214, 212, 210	Assumed	MISC					
114	White Terrazzo	30,000	SF	Addition Corridor, Stairwells 2nd & 3rd Floor and Rr	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Red Terrazzo	3,333	SF	Addition Corridor, Stairways 2nd & 3rd Floor and Rr	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
116	Green Terrazzo	3,333	SF	Addition Corridor, Stairways 2nd & 3rd Floor and Rr	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
117	Blue Terrazzo	2,000	SF	1st Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
118	Gray Carpet Adhesive			Library and Teacher Lounge	Assumed	MISC					
119	Blue Epoxy Flooring	1,000	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11A	Brown Linoleum Mastic			Basement - Supply Room	No ACBM	MISC					
11B	Green Linoleum Mastic			Room 302 and Adjustment Office	No ACBM	MISC					
11C	Linoleum Mastic			3rd Floor Gym (New Gym Floor Enclosed Linoleum, 1995)	Assumed	MISC					
12	1' x 1' Acoustical Ceiling Tile Mastic			West End of 1st, 2nd, 3rd Floor s	Assumed	MISC					
120	12" x 12" Blotted Blue Vinyl Floor Tile	3,000	SF	Servery and Multipurpose	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
121	12" x 12" Blotted Blue Vinyl Floor Tile Mastic			Servery and Multipurpose	Assumed	MISC					
122	2' x 4' Solid Ceiling Tile	1,000	SF	Kitchen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
123	12" x 12" Blotted Beige Vinyl Floor Tile	5,600	SF	Room 310, 311, 312, 314, 316, 203, 313	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
124	12" x 12" Blotted Beige Vinyl Floor Tile Mastic			Room 310, 311, 312, 314, 316, 203, 313	Assumed	MISC					
125	12" x 12" Blotted Green Vinyl Floor Tile	1,000	SF	Room 310, 311, 312, 314, 316, 203, 313	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12" x 12" Blotted Green Vinyl Floor Tile Mastic			Room 310, 311, 312, 314, 316, 203, 313	Assumed	MISC					
127	Drywall	200,000	SF	Addition Throughout	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
128	Joint Compound	20,000	SF	Addition Throughout	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
129	12" x 12" Bright White Vinyl Floor Tile			Room 303	Assumed	MISC					
13	Red Brick - Non-AHERA			Building Exterior - East Side, Building Exterior - West Side	No ACBM	SURFACE					
130	12" x 12" Bright White Vinyl Floor Tile Mastic			Room 303	Assumed	MISC					
131	12" x 12" Bright Blue Vinyl Floor Tile	200	SF	Room 303	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12" x 12" Bright Blue Vinyl Floor Tile Mastic			Room 303	Assumed	MISC					
133	2' x 4' Fiber Ceiling Tile	4,000	SF	Gym and Stairwells	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
134	Spray on Fire Proofing	40,000	SF	Throughout	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
136	Brown Vinyl Plank Flooring	1,200	SF	Main Office 102	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
137	12" x 12" Gray w/ Black Specks Floor Tile	400	SF	Room 404	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
138	12" x 12" Tan w/ Gray Specks Floor Tile	400	SF	Room 404	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
139	12" x 12" Green Gray and Tan Floor Tile Mastic			Room 404	Assumed	MISC					
14	Gray Brick Mortar - Non-AHERA			Building Exterior - East Side, Building Exterior - West Side,	No ACBM	MISC					
140	Tongue and Groove Wood Flooring	1,000	SF	Rooms 300, 301, 308, 304, 305, 306, 307, 206, Closet Across 206, 205, 204, 201, 202, 106, Storage Across 106, 105, 104, Auditorium, 401	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
141	Black Epoxy Flooring	50,000	SF	Throughout Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
142	1" x 1" Brown and White Ceramic Floor Tile	10,000	SF	Throughout Boys and Girls Toilet Rooms in Original Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
143	Gray CMU	50,000	LF	Throughout Corridors in New Addition Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
144	Gray CMU Mortar	50,000	LF	Throughout Corridors in New Additions Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
145	White Glazed CMU	1,000	LF	Throughout Boys and Girls Toilet Rooms in New Additions Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
146	White Glazed CMU Mortar	1,000	LF	Throughout Boys and Girls Toilet Rooms in New Additions Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
147	Green Glazed CMU	500	LF	3rd Floor Boys and Girls Toilet Rooms in New Additions Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
148	Green Glazed CMU Mortar	500	LF	3rd Floor Boys and Girls Toilet Rooms in New Additions Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
149	Red Glazed CMU	500	LF	2nd Floor Boys and Girls Toilet Rooms in New Additions Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
15	9" x 9" Floor Tile Mastic			Gym	Assumed	MISC					
150	Red Glazed CMU Mortar	500	LF	2nd Floor Boys and Girls Toilet Rooms in New Additions Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
151	2" x 2" Light Blue Ceramic Floor Tile	200	SF	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
152	2" x 2" Light Blue Ceramic Floor Tile Mortar	200	SF	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
153	2" x 2" Cream Ceramic Wall Tile	500	LF	Room 114 and 112 Bathroom, Boys	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				and Girls Bathroom 1st Floor of Old Building							
154	2" x 2" Cream Ceramic Wall Tile Mortar	500	LF	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
155	2" x 2" Dark Blue Ceramic Floor Tile	500	SF	Boys Bathroom 1st Floor of Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
156	2" x 2" Dark Blue Ceramic Floor Tile Mortar	500	LF	Boys Bathroom 1st Floor of Old Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
157	2" x 2" Cream Ceramic Floor Tile	1,000	SF	Boys and Girls Bathroom 1st Floor of Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
158	2" x 2" Cream Ceramic Floor Tile Mortar	1,000	SF	Boys and Girls Bathroom 1st Floor of Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
159	2" x 2" Yellow Ceramic Floor Tile	400	SF	1st Floor Girls Bathroom in Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Hardcoat Plaster	500,000	SF	Throughout Original Building	Assumed	SURFACE	Yes	75	SF	2 Damaged friable surfacing ACBM	Repair
160	2" x 2" Yellow Ceramic Floor Tile Mortar	500	SF	1st Floor Girls Bathroom in Old Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
161	Thermal Insulation	3,000	LF	Boiler Room	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
17	Burlap Wall Covering	3,000	SF	Teachers' Room and 3rd Floor Corridor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	1' x 1' Acoustical Ceiling Tile	8,000	SF	West Portion of Original Building	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
19	Rough Coat Plaster	2,000	SF	Waroom Air Chamber in Original Building, Basement Hallway	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
20	Stage Curtains	3,000	SF	Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Textured Paint	2,000	SF	Original Building: Ceilings, Pipe, Duct in Basement Corridor, Engineer's Office, 409a, Storage by Fan Room	Assumed	MISC	No	50	SF	5 ACBM with potential for significant damage	Repair
22	Chalk Board Adhesive			Original Building: Classrooms 101-106, 204-206, 300, 301, 304-306, 308 and 2nd Floor Teachers' Lounge	Assumed	MISC					
23	Marker Board Adhesive			Original Building: 409a and 103	Assumed	MISC					
24	Non-Skid Strips	300	LF	Original Building Stairs	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
25	2' x 4' Lay-in Ceiling Panels	1,600	LF	Original Building: Classroom 409a and Bathroom	Assumed	MISC	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
26	4" Gray Baseboard			Original Building: Classroom 404	Assumed	MISC					
27	4" Gray Baseboard Adhesive			Original Building: Classroom 404	Assumed	MISC					

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
28	12" x 12" Blue Floor Tile	60	SF	Room 303 Border	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12" x 12" Blue Floor Tile Mastic			Original Building: Classroom 409a and Bathroom	Assumed	MISC					
2A	12" x 12" Tan Speckled Floor Tile	150	SF	Basement - Engineer's Office Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2B	12" x 12" White Speckled Floor Tile	3,000	SF	Basement - Engineer's Office and 2nd Floor Teachers' Room, 202a and Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2C	12" x 12" Brown Speckled Floor Tile	1,500	SF	Basement - Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2D	12" x 12" Beige Speckled Floor Tile	1,300	SF	Basement - Assembly Hall and Room 009	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2E	12" x 12" Beige Speckled Floor Tile	1,350	SF	Basement - Room 009, 103, 203, and 303	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2F	12" x 12" Blue Floor Tile	800	SF	1st Floor Room 103	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2G	12" x 12" Dark Tan Floor Tile			1st Floor Principal's Bathroom (Wood)	Assumed	MISC					
2H	12" x 12" Off-White Floor Tile			1st Floor Principal's Office, Clerk's Space (Wood)	Assumed	MISC					
2I	12" x 12" Light Brown Floor Tile			Mobile Units 4, 5, 6	No ACBM	MISC					
2J	12" x 12" White Floor Tile			Mobile Unit 002/003 Hallway	No ACBM	MISC					
30	Blue Carpet Adhesive			Original Building: Office 102, Clerk's Office and Principal's Office	Assumed	MISC					
31	12" x 12" Beige Mix Floor Tile	900	SF	Original Building: Room 101, Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12" x 12" Beige Mix Floor Tile Mastic			Original Building: Room 101	Assumed	MISC					
33	Sink Undercoating	6	SF	Original Building: 2nd Floor Teachers' Lounge , 409-A	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Masonite Wall Covering Adhesive	600	SF	Basement	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	12" x 12" Beige Mix Floor Tile	8,000	SF	Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Beige Mix Floor Tile Mastic			Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a	Assumed	MISC					
37	12" x 12" Green Mix Floor Tile	880	SF	2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Green Mix Floor Tile Mastic			2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and	Assumed	MISC					

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Library							
39	12" x 12" Red Mix Floor Tile	440	SF	2002 Addition: Classrooms 210, 212, 214, and 216	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
3A	Brown Linoleum			Basement - Supply Room	No ACBM	MISC					
3B	Green Linoleum			Room 302 and Adjustment Office	No ACBM	MISC					
3C	Linoleum	2,700	SF	Gym	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12" x 12" Red Mix Floor Tile Mastic			2002 Addition: Classrooms 210, 212, 214, and 216	Assumed	MISC					
41	12" x 12" Light Blue Mix Floor Tile	3,464	SF	2002 Addition: Classrooms 112, 114, 115, Kit., Servingarea&Allpurposeroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12" x 12" Light Blue Mix Floor Tile Mastic			2002 Addition: Classrooms 112, 114, 115, Kit., Servingarea&Allpurposeroom	Assumed	MISC					
43	12" x 12" Dark Blue Mix Floor Tile	220	SF	2002 Addition: Classrooms 112 and 114	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" x 12" Dark Blue Mix Floor Tile Mastic			2002 Addition: Classrooms 112 and 114	Assumed	MISC					
45	1" Dark Blue Floor Tile Striping	13	SF	2002 Addition: All Purpose Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
46	1" Dark Blue Floor Tile Striping Mastic			2002 Addition: All Purpose Room	Assumed	MISC					
47	1" Yellow Floor Tile Striping	13	SF	2002 Addition: All Purpose Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
48	1" Yellow Floor Tile Striping Mastic			2002 Addition: All Purpose Room	Assumed	MISC					
49	2' x 4' Fissured Lay-in Ceiling Panels	28,000	SF	2002 Addition: All Corridors, Library and Classrooms	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
50	Tectum Ceiling Panels	1,200	SF	2002 Addition: All Purpose Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
51	2' x 4' Smooth Lay-in Ceiling Panels	2,600	SF	2002 Addition: Kitchen and Serving Area	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
52	Drywall	4,800	SF	2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
53	Drywall Compound	3,000	SF	2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
54	4" Beige Vinyl Baseboard	2,780	LF	Original Building: Classrooms 103, 302, 203 and 303 2002 Addition: All Classrooms, Serving Area, All Purposeroom&Library	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
55	4" Beige Vinyl Baseboard Adhesive			Original Building: Classrooms 103, 302,	Assumed	MISC					

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				203 and 303 2002 Addition: All Classrooms, Serving Area, All Purpose Room&Library							
56	Material Inside Of Wall Mats			2002 Addition: All Purpose Room	Assumed	MISC					
57	Spray on Fireproofing	20,000	SF	Throughout 2002 Addition	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
58	Marker Board Adhesive			2002 Addition: Classrooms 112, 114, 212, 216, 303, 310-314, and 316	Assumed	MISC					
59	Chalk Board Adhesive			2002 Addition: Classrooms 112, 114, 212, 214, 216, 303, 310-311, 313-314, and 316	Assumed	MISC					
60	Brown Mix Carpet Adhesive			2002 Addition: Classroom 108, Library and 315	Assumed	MISC					
61	12" x 12" Beige Floor Tile	625	SF	Room 103 & Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12" x 12" Beige Floor Tile Mastic			Room 103 & Bathroom	Assumed	MISC					
63	12" x 12" Red Floor Tile	60	SF	Room 103 & Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12" x 12" Red Floor Tile Mastic			Room 103 & Bathroom	Assumed	MISC					
65	Brown Carpet Mastic			Library, Teachers' Lounge	Assumed	MISC					
66	New Fire Doors	800	SF	Throughout New Building	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
67	Old Fire Doors	63	SF	Old Building 1, 2, 3 Floor Corridor Ends	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
68	12" x 12" White w/ Cream Specks Floor Tile	768	SF	Original Building Room 302	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
68m	12" x 12" White w/ Cream Specks Floor Tile Mastic	768	SF	Original Building Room 302	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Light Blue Floor Tile Border	75	SF	Original Building Room 302	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12" x 12" Tan Floor Tile w/ White Specks	800	SF	Original Building Room 409 and Toilet	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
70m	12" x 12" Tan w/ White Specks Floor Tile Mastic			Original Building Room 409 and Toilet	Assumed	MISC					
71	4" Black Baseboard	768	LF	Original Building 409 and Toilet	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
71m	4" Black Baseboard Mastic			Original Building Room 409	Assumed	MISC					
72	Ceramic Grout	1,080	SF	Original Building 1st, 2nd, and 3rd Floor Boys and Girls Toilets	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
73	Terrazzo Sinks			Original Building 1st, 2nd, 3rd Floor s Boys and Girls Bathrooms.	Assumed	MISC					
74	1' x 1' White Ceiling Tile Adhesive			Original Building Rooms 201, 202, 202a, Office, Clerk Space, Principal Office, 1st- 3rd Corridors 301, 302, and	Assumed	MISC					

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				308							
75	2' x 2' Lay-in Ceiling Tile	1,300	SF	Original Building 103, 205, and 303	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
8	Masonite Wall Covering	600	SF	Basement	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
B	Cementitious Mud Joints			Fieldhouse	No ACBM	TSI					
C	Aircell Pipe Insulation	300	LF	Basement - Room 009, Sprinkler Pump Room, West Corridor, Assembly Hall Passage	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Aircell Joints	40	LF	Basement - Room 009, Sprinkler Pump Room	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Cardboard Insulation Joints	60	LF	Basement - West Corridor	Amosite	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Mag - Block Pipe Insulation	30	LF	2nd Floor Above Principal's Bathroom	Chrysotile	TSI			LF		Follow O&M Plan
H	Mag - Block Joints	2	LF	Basement - Corridor	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
I	Joint Insul. Assoc. w/ Fiberglass Insulated Piping	100	LF	Basement and Bathrooms	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
J	Joint Insul. Assoc. w/ Cardboard Insulated Piping	140	SF	Basement and Bathrooms	Chrysotile	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Packing Material			MATERIAL REMOVED	No ACBM	MISC					

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/28/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
10A	
10B	
10C	
10D	
10E	
10F	
10G	

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
10H	
10I	
10J	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
11A	
11B	
11C	
12	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
13	
130	
131	
132	
133	
134	
136	
137	
138	
139	
14	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
15	
150	
151	
152	
153	
154	

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
155	
156	
157	
158	
159	
16	Sample to determine ACM content, remove or repair damaged surfacing material to intact.
160	
161	
17	
18	
19	
20	
21	Remove or repair to intact.
22	
23	
24	
25	
26	
27	
28	
29	
2A	
2B	
2C	
2D	
2E	
2F	

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
2G	
2H	
2I	
2J	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
3A	
3B	
3C	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
68m	
69	
70	
70m	
71	
71m	
72	
73	

# Chicago Public Schools

**School** Pickard School

**Unit** 24961

**Building ID** 5430

**Address** 2301 W. 21st Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
74	
75	
8	
B	
C	
D	
F	
G	If identified, continue O&M.
H	
I	
J	
K	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile (Enclosed By 12" x 12")**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile (Enclosed By 12" x 12")**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>100</b>		
MATERIAL DESCRIPTION:	<b>Door Caulk</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Door Caulk**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>101</b>		
MATERIAL DESCRIPTION:	<b>Window Caulk</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>102</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Bright Blue Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112, 114, 404a, 004a</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" Bright Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Rooms 112, 114, 404a, 004a**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>103</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Bright Blue Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 112, 114, 404a, 004a**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" Bright Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 112, 114, 404a, 004a**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>104</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Rooms 112, 114, 404a, and 004a</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tile**

MATERIAL LOCATION: **Rooms 112, 114, 404a, and 004a**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>105</b>		
MATERIAL DESCRIPTION:	<b>Boiler Gasket</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **Boiler Gasket**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>		IDPH LICENSE NO:	<b>100-06435</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **106**  
MATERIAL DESCRIPTION: **Sink Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Yoga**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **Sink Insulation**

MATERIAL LOCATION: **Yoga**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>107</b>		
MATERIAL DESCRIPTION:	<b>Water Pump Gaskets</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Sprinkler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **Water Pump Gaskets**

MATERIAL LOCATION: **Sprinkler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	12" x 12" New Brown Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 409 and Rr		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **12" x 12" New Brown Vinyl Floor Tile**

MATERIAL LOCATION: **Room 409 and Rr**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>109</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" New Brown Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 409 and Rr**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **12" x 12" New Brown Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 409 and Rr**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>10A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan Speckled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Engineer's Office</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10A**

MATERIAL DESCRIPTION: **12" x 12" Tan Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Basement - Engineer's Office**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>10B</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White Speckled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Engineer's Office, 2nd Floor Teachers' Room</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10B**

MATERIAL DESCRIPTION: **12" x 12" White Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Basement - Engineer's Office, 2nd Floor Teachers' Room**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>10C</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Brown Speckled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Kitchen</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10C**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Basement - Kitchen**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>10D</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Pink Speckled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Assembly Hall and Room 009</b>		
MATERIAL QUANTITY:	<b>3750</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10D**

MATERIAL DESCRIPTION: **12" x 12" Pink Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Basement - Assembly Hall and Room 009**

MATERIAL QUANTITY: **3750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>10E</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Speckled Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Room 009, 103, 203, and 303</b>		
MATERIAL QUANTITY:	<b>1350</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10E**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Floor Tile Mastic**

MATERIAL LOCATION: **Basement - Room 009, 103, 203, and 303**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10F**  
MATERIAL DESCRIPTION: **Blue 12" x 12" Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Room 103**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10F**

MATERIAL DESCRIPTION: **Blue 12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Room 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10G**

MATERIAL DESCRIPTION: **Dark Tan 12" x 12" Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Principal's Bathroom**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10G**

MATERIAL DESCRIPTION: **Dark Tan 12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Principal's Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>10H</b>		
MATERIAL DESCRIPTION:	<b>Off-White 12" x 12" Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Principal's Office and Clerk Space**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10H**

MATERIAL DESCRIPTION: **Off-White 12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Principal's Office and Clerk Space**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10I**

MATERIAL DESCRIPTION: **Light Brown 12" x 12" Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mobile Unit # 4, 5 & 6**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10I**

MATERIAL DESCRIPTION: **Light Brown 12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **Mobile Unit # 4, 5 & 6**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10J**

MATERIAL DESCRIPTION: **White 12" x 12" Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mobile Unit 002/003 Hallway**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **10J**

MATERIAL DESCRIPTION: **White 12" x 12" Floor Tile Mastic**

MATERIAL LOCATION: **Mobile Unit 002/003 Hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>		IDPH LICENSE NO:	<b>100-06435</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>110</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Red Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 103 (Kidagarden), 216, 214, 212, 210</b>		
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **12" x 12" Blotted Red Vinyl Floor Tile**

MATERIAL LOCATION: **Room 103 (Kidagarden), 216, 214, 212, 210**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>111</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Red Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103, 216, 214, 212, 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **12" x 12" Blotted Red Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 103, 216, 214, 212, 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	112		
MATERIAL DESCRIPTION:	12" x 12" Blotted White Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103, 214, 216, 212, 210		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **12" x 12" Blotted White Vinyl Floor Tile**

MATERIAL LOCATION: **Room 103, 214, 216, 212, 210**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>113</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted White Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103, 216, 214, 212, 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **12" x 12" Blotted White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 103, 216, 214, 212, 210**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>114</b>		
MATERIAL DESCRIPTION:	<b>White Terrazzo</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Addition Corridor, Stairwells 2nd &amp; 3rd Floor and Rr</b>		
MATERIAL QUANTITY:	<b>30000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **White Terrazzo**

MATERIAL LOCATION: **Addition Corridor, Stairwells 2nd & 3rd Floor and Rr**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>115</b>		
MATERIAL DESCRIPTION:	<b>Red Terrazzo</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Addition Corridor, Stairways 2nd &amp; 3rd Floor and Rr</b>		
MATERIAL QUANTITY:	<b>3333</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **Red Terrazzo**

MATERIAL LOCATION: **Addition Corridor, Stairways 2nd & 3rd Floor and Rr**

MATERIAL QUANTITY: **3333** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>116</b>		
MATERIAL DESCRIPTION:	<b>Green Terrazzo</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Addition Corridor, Stairways 2nd &amp; 3rd Floor and Rr</b>		
MATERIAL QUANTITY:	<b>3333</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **Green Terrazzo**

MATERIAL LOCATION: **Addition Corridor, Stairways 2nd & 3rd Floor and Rr**

MATERIAL QUANTITY: **3333** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>117</b>		
MATERIAL DESCRIPTION:	<b>Blue Terrazzo</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Corridor</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **Blue Terrazzo**

MATERIAL LOCATION: **1st Floor Corridor**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>118</b>		
MATERIAL DESCRIPTION:	<b>Gray Carpet Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library and Teacher Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **Gray Carpet Adhesive**

MATERIAL LOCATION: **Library and Teacher Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>119</b>		
MATERIAL DESCRIPTION:	<b>Blue Epoxy Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Kitchen</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **Blue Epoxy Flooring**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>11A</b>		
MATERIAL DESCRIPTION:	<b>Brown Linoleum Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>No ACBM</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement - Supply Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **11A**

MATERIAL DESCRIPTION: **Brown Linoleum Mastic**

MATERIAL LOCATION: **Basement - Supply Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>11B</b>		
MATERIAL DESCRIPTION:	<b>Green Linoleum Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	<b>No ACBM</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302 and Adjustment Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **11B**

MATERIAL DESCRIPTION: **Green Linoleum Mastic**

MATERIAL LOCATION: **Room 302 and Adjustment Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>11C</b>		
MATERIAL DESCRIPTION:	<b>Linoleum Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **3rd Floor Gym (New Gym Floor Enclosed Linoleum, 1995)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **11C**

MATERIAL DESCRIPTION: **Linoleum Mastic**

MATERIAL LOCATION: **3rd Floor Gym (New Gym Floor Enclosed Linoleum, 1995)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>12</b>	
MATERIAL DESCRIPTION:	<b>1' x 1' Acoustical Ceiling Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **West End of 1st, 2nd, 3rd Floor s**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile Mastic**

MATERIAL LOCATION: **West End of 1st, 2nd, 3rd Floor s**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>120</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Blue Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Servery and Multipurpose</b>		
MATERIAL QUANTITY:	<b>3000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **12" x 12" Blotted Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Servery and Multipurpose**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>121</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Blue Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Servery and Multipurpose**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **12" x 12" Blotted Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Servery and Multipurpose**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>122</b>		
MATERIAL DESCRIPTION:	<b>2' x 4' Solid Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **2' x 4' Solid Ceiling Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>123</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Beige Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 310, 311, 312, 314, 316, 203, 313</b>		
MATERIAL QUANTITY:	<b>5600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **12" x 12" Blotted Beige Vinyl Floor Tile**

MATERIAL LOCATION: **Room 310, 311, 312, 314, 316, 203, 313**

MATERIAL QUANTITY: **5600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>124</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Beige Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 310, 311, 312, 314, 316, 203, 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **12" x 12" Blotted Beige Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 310, 311, 312, 314, 316, 203, 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>125</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Green Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 310, 311, 312, 314, 316, 203, 313</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **12" x 12" Blotted Green Vinyl Floor Tile**

MATERIAL LOCATION: **Room 310, 311, 312, 314, 316, 203, 313**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>		IDPH LICENSE NO:	<b>100-06435</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>126</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Blotted Green Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 310, 311, 312, 314, 316, 203, 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **12" x 12" Blotted Green Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 310, 311, 312, 314, 316, 203, 313**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>127</b>		
MATERIAL DESCRIPTION:	<b>Drywall</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Addition Throughout</b>		
MATERIAL QUANTITY:	<b>200000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **127**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **Addition Throughout**

MATERIAL QUANTITY: **200000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>128</b>		
MATERIAL DESCRIPTION:	<b>Joint Compound</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Addition Throughout</b>		
MATERIAL QUANTITY:	<b>20000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **128**

MATERIAL DESCRIPTION: **Joint Compound**

MATERIAL LOCATION: **Addition Throughout**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>		IDPH LICENSE NO:	<b>100-06435</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>129</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Bright White Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **129**

MATERIAL DESCRIPTION: **12" x 12" Bright White Vinyl Floor Tile**

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>13</b>	
MATERIAL DESCRIPTION:	<b>Red Brick - Non-AHERA</b>	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:		
ASBESTOS TYPE:	<b>No ACBM</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior - East Side, Building Exterior - West Side**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Red Brick - Non-AHERA**

MATERIAL LOCATION: **Building Exterior - East Side, Building Exterior - West Side**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>130</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Bright White Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **130**

MATERIAL DESCRIPTION: **12" x 12" Bright White Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>131</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Bright Blue Vinyl Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 303</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **131**

MATERIAL DESCRIPTION: **12" x 12" Bright Blue Vinyl Floor Tile**

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>132</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Bright Blue Vinyl Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **132**

MATERIAL DESCRIPTION: **12" x 12" Bright Blue Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Room 303**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	133		
MATERIAL DESCRIPTION:	2' x 4' Fiber Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym and Stairwells		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **133**

MATERIAL DESCRIPTION: **2' x 4' Fiber Ceiling Tile**

MATERIAL LOCATION: **Gym and Stairwells**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>134</b>		
MATERIAL DESCRIPTION:	<b>Spray on Fire Proofing</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout</b>		
MATERIAL QUANTITY:	<b>40000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **134**

MATERIAL DESCRIPTION: **Spray on Fire Proofing**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>136</b>		
MATERIAL DESCRIPTION:	<b>Brown Vinyl Plank Flooring</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Main Office 102</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **136**

MATERIAL DESCRIPTION: **Brown Vinyl Plank Flooring**

MATERIAL LOCATION: **Main Office 102**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>137</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Gray w/ Black Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 404</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **137**

MATERIAL DESCRIPTION: **12" x 12" Gray w/ Black Specks Floor Tile**

MATERIAL LOCATION: **Room 404**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>138</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan w/ Gray Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 404</b>		
MATERIAL QUANTITY:	<b>400</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **138**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Gray Specks Floor Tile**

MATERIAL LOCATION: **Room 404**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>139</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Green Gray and Tan Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 404**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **12" x 12" Green Gray and Tan Floor Tile Mastic**

MATERIAL LOCATION: **Room 404**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Gray Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Building Exterior - East Side, Building Exterior - West Side,**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Gray Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Building Exterior - East Side, Building Exterior - West Side,**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	140		
MATERIAL DESCRIPTION:	Tongue and Groove Wood Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 300, 301, 308, 304, 305, 306, 307, 206, Closet Across 206, 205, 204, 201, 202, 106, Storage Across 106, 105, 104, Auditorium, 401**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **140**

MATERIAL DESCRIPTION: **Tongue and Groove Wood Flooring**

MATERIAL LOCATION: **Rooms 300, 301, 308, 304, 305, 306, 307, 206, Closet Across 206, 205, 204, 201, 202, 106, Storage Across 106, 105, 104, Auditorium, 401**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>		IDPH LICENSE NO:	<b>100-06435</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile Mastic**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	2 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **2. Damaged friable surfacing ACBM**

DAMAGE REASON:	Water		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Original Building		
MATERIAL QUANTITY:	500000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in: 3rd Floor corridor near room 303		

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Hardcoat Plaster**

MATERIAL LOCATION: **Throughout Original Building**

MATERIAL QUANTITY: **500000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content, remove or repair damaged surfacing material to intact.

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>17</b>		
MATERIAL DESCRIPTION:	<b>Burlap Wall Covering</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Teachers' Room and 3rd Floor Corridor</b>		
MATERIAL QUANTITY:	<b>3000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Burlap Wall Covering**

MATERIAL LOCATION: **Teachers' Room and 3rd Floor Corridor**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>18</b>		
MATERIAL DESCRIPTION:	<b>1' x 1' Acoustical Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Damaged or significantly damaged friable misc. ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>West Portion of Original Building</b>		
MATERIAL QUANTITY:	<b>8000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **1' x 1' Acoustical Ceiling Tile**

MATERIAL LOCATION: **West Portion of Original Building**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Rough Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 7. Any remaining friable ACBM or friable suspect ACBM

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Waroom Air Chamber in Original Building, Basement Hallway		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Rough Coat Plaster**

MATERIAL LOCATION: **Waroom Air Chamber in Original Building, Basement Hallway**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>20</b>		
MATERIAL DESCRIPTION:	<b>Stage Curtains</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage See Comments</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Auditorium</b>		
MATERIAL QUANTITY:	<b>3000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Stage Curtains**

MATERIAL LOCATION: **Auditorium**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>21</b>		
MATERIAL DESCRIPTION:	<b>Textured Paint</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>5 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	<b>Deterioration</b>		
DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Original Building: Ceilings, Pipe, Duct in Basement Corridor, Engineer's Office, 409a, Storage by Fan Room</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damage near room 104</b>		

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Textured Paint**

MATERIAL LOCATION: **Original Building: Ceilings, Pipe, Duct in Basement Corridor, Engineer's Office, 409a, Storage by Fan Room**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>22</b>	
MATERIAL DESCRIPTION:	<b>Chalk Board Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Classrooms 101-106, 204-206, 300, 301, 304-306, 308 and 2nd Floor Teachers' Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Chalk Board Adhesive**

MATERIAL LOCATION: **Original Building: Classrooms 101-106, 204-206, 300, 301, 304-306, 308 and 2nd Floor Teachers' Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>23</b>	
MATERIAL DESCRIPTION:	<b>Marker Board Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: 409a and 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Marker Board Adhesive**

MATERIAL LOCATION: **Original Building: 409a and 103**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>24</b>		
MATERIAL DESCRIPTION:	<b>Non-Skid Strips</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building Stairs</b>		
MATERIAL QUANTITY:	<b>300</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Non-Skid Strips**

MATERIAL LOCATION: **Original Building Stairs**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>25</b>		
MATERIAL DESCRIPTION:	<b>2' x 4' Lay-in Ceiling Panels</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building: Classroom 409a and Bathroom</b>		
MATERIAL QUANTITY:	<b>1600</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **2' x 4' Lay-in Ceiling Panels**

MATERIAL LOCATION: **Original Building: Classroom 409a and Bathroom**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>26</b>	
MATERIAL DESCRIPTION:	<b>4" Gray Baseboard</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Classroom 404**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **4" Gray Baseboard**

MATERIAL LOCATION: **Original Building: Classroom 404**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>27</b>	
MATERIAL DESCRIPTION:	<b>4" Gray Baseboard Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Classroom 404**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **4" Gray Baseboard Adhesive**

MATERIAL LOCATION: **Original Building: Classroom 404**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 303 Border		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **Room 303 Border**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Classroom 409a and Bathroom**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile Mastic**

MATERIAL LOCATION: **Original Building: Classroom 409a and Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2A</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Engineer's Office Bathroom</b>		
MATERIAL QUANTITY:	<b>150</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2A**

MATERIAL DESCRIPTION: **12" x 12" Tan Speckled Floor Tile**

MATERIAL LOCATION: **Basement - Engineer's Office Bathroom**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2B</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Engineer's Office and 2nd Floor Teachers' Room, 202a and Library</b>		
MATERIAL QUANTITY:	<b>3000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Damage fixed</b>		

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2B**

MATERIAL DESCRIPTION: **12" x 12" White Speckled Floor Tile**

MATERIAL LOCATION: **Basement - Engineer's Office and 2nd Floor Teachers' Room, 202a and Library**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2C</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Brown Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Kitchen</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2C**

MATERIAL DESCRIPTION: **12" x 12" Brown Speckled Floor Tile**

MATERIAL LOCATION: **Basement - Kitchen**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2D</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Assembly Hall and Room 009</b>		
MATERIAL QUANTITY:	<b>1300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2D**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Floor Tile**

MATERIAL LOCATION: **Basement - Assembly Hall and Room 009**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>2E</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Speckled Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Room 009, 103, 203, and 303</b>		
MATERIAL QUANTITY:	<b>1350</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2E**

MATERIAL DESCRIPTION: **12" x 12" Beige Speckled Floor Tile**

MATERIAL LOCATION: **Basement - Room 009, 103, 203, and 303**

MATERIAL QUANTITY: **1350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2F		
MATERIAL DESCRIPTION:	12" x 12" Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Room 103		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2F**

MATERIAL DESCRIPTION: **12" x 12" Blue Floor Tile**

MATERIAL LOCATION: **1st Floor Room 103**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2G**

MATERIAL DESCRIPTION: **12" x 12" Dark Tan Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Principal's Bathroom (Wood)**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2G**

MATERIAL DESCRIPTION: **12" x 12" Dark Tan Floor Tile**

MATERIAL LOCATION: **1st Floor Principal's Bathroom (Wood)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 2H

MATERIAL DESCRIPTION: 12" x 12" Off-White Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st Floor Principal's Office, Clerk's Space (Wood)

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2H**

MATERIAL DESCRIPTION: **12" x 12" Off-White Floor Tile**

MATERIAL LOCATION: **1st Floor Principal's Office, Clerk's Space (Wood)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2I**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mobile Units 4, 5, 6**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" Light Brown Floor Tile**

MATERIAL LOCATION: **Mobile Units 4, 5, 6**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>		IDPH LICENSE NO:	<b>100-06435</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **2J**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Mobile Unit 002/003 Hallway**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **2J**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **Mobile Unit 002/003 Hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Office 102, Clerk's Office and Principal's Office**

MATERIAL QUANTITY:  MATERIAL UNITS:

DAMAGE QUANTITY:  DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Original Building: Office 102, Clerk's Office and Principal's Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>31</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Mix Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Deterioration</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building: Room 101, Library</b>		
MATERIAL QUANTITY:	<b>900</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	DAMAGE UNITS: <b>SF</b>		
COMMENTS:	<b>Damaged fixed</b>		

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **Original Building: Room 101, Library**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>32</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Mix Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building: Room 101**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **Original Building: Room 101**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>33</b>		
MATERIAL DESCRIPTION:	<b>Sink Undercoating</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building: 2nd Floor Teachers' Lounge , 409-A</b>		
MATERIAL QUANTITY:	<b>6</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Sink Undercoating**

MATERIAL LOCATION: **Original Building: 2nd Floor Teachers' Lounge , 409-A**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>34</b>		
MATERIAL DESCRIPTION:	<b>Masonite Wall Covering Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Masonite Wall Covering Adhesive**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12" x 12" Beige Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a		
MATERIAL QUANTITY:	8000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage fixed		

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUILDING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile**

MATERIAL LOCATION: **Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a**

MATERIAL QUANTITY: **8000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36	
MATERIAL DESCRIPTION:	12" x 12" Beige Mix Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" Beige Mix Floor Tile Mastic**

MATERIAL LOCATION: **Original Building: Classroom 302 2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316 & Library, 409a**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>37</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Green Mix Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and Library</b>		
MATERIAL QUANTITY:	<b>880</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12" x 12" Green Mix Floor Tile**

MATERIAL LOCATION: **2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and Library**

MATERIAL QUANTITY: **880** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>38</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Green Mix Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Green Mix Floor Tile Mastic**

MATERIAL LOCATION: **2002 Addition: Classrooms 210, 212, 214, 216, 303, 310-314, 316, and Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>39</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Red Mix Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2002 Addition: Classrooms 210, 212, 214, and 216</b>		
MATERIAL QUANTITY:	<b>440</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12" x 12" Red Mix Floor Tile**

MATERIAL LOCATION: **2002 Addition: Classrooms 210, 212, 214, and 216**

MATERIAL QUANTITY: **440** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3A**

MATERIAL DESCRIPTION: **Brown Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Basement - Supply Room**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **3A**

MATERIAL DESCRIPTION: **Brown Linoleum**

MATERIAL LOCATION: **Basement - Supply Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3B**

MATERIAL DESCRIPTION: **Green Linoleum**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 302 and Adjustment Office**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **3B**

MATERIAL DESCRIPTION: **Green Linoleum**

MATERIAL LOCATION: **Room 302 and Adjustment Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>3C</b>		
MATERIAL DESCRIPTION:	<b>Linoleum</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Gym</b>		
MATERIAL QUANTITY:	<b>2700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **3C**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **Gym**

MATERIAL QUANTITY: **2700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>40</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Red Mix Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: Classrooms 210, 212, 214, and 216**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12" x 12" Red Mix Floor Tile Mastic**

MATERIAL LOCATION: **2002 Addition: Classrooms 210, 212, 214, and 216**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>41</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Light Blue Mix Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2002 Addition:Classrooms 112, 114, 115, Kit., Serving area&amp;All purpose room</b>		
MATERIAL QUANTITY:	<b>3464</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Mix Floor Tile**

MATERIAL LOCATION: **2002 Addition:Classrooms 112, 114, 115, Kit., Serving area & All purpose room**

MATERIAL QUANTITY: **3464** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>42</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Light Blue Mix Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition:Classrooms 112, 114, 115, Kit., Serving area&All purpose room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Light Blue Mix Floor Tile Mastic**

MATERIAL LOCATION: **2002 Addition:Classrooms 112, 114, 115, Kit., Serving area & All purpose room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12" x 12" Dark Blue Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2002 Addition: Classrooms 112 and 114		
MATERIAL QUANTITY:	220	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue Mix Floor Tile**

MATERIAL LOCATION: **2002 Addition: Classrooms 112 and 114**

MATERIAL QUANTITY: **220** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>44</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Dark Blue Mix Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: Classrooms 112 and 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" x 12" Dark Blue Mix Floor Tile Mastic**

MATERIAL LOCATION: **2002 Addition: Classrooms 112 and 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>45</b>		
MATERIAL DESCRIPTION:	<b>1" Dark Blue Floor Tile Striping</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2002 Addition: All Purpose Room</b>		
MATERIAL QUANTITY:	<b>13</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **1" Dark Blue Floor Tile Striping**

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: **13** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>46</b>	
MATERIAL DESCRIPTION:	<b>1" Dark Blue Floor Tile Striping Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **1" Dark Blue Floor Tile Striping Mastic**

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>47</b>		
MATERIAL DESCRIPTION:	<b>1" Yellow Floor Tile Striping</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2002 Addition: All Purpose Room</b>		
MATERIAL QUANTITY:	<b>13</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **1" Yellow Floor Tile Striping**

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: **13** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>48</b>	
MATERIAL DESCRIPTION:	<b>1" Yellow Floor Tile Striping Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **1" Yellow Floor Tile Striping Mastic**

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>49</b>		
MATERIAL DESCRIPTION:	<b>2' x 4' Fissured Lay-in Ceiling Panels</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Damaged or significantly damaged friable misc. ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2002 Addition: All Corridors, Library and Classrooms</b>		
MATERIAL QUANTITY:	<b>28000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **2' x 4' Fissured Lay-in Ceiling Panels**

MATERIAL LOCATION: **2002 Addition: All Corridors, Library and Classrooms**

MATERIAL QUANTITY: **28000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>50</b>		
MATERIAL DESCRIPTION:	<b>Tectum Ceiling Panels</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>2002 Addition: All Purpose Room</b>		
MATERIAL QUANTITY:	<b>1200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Tectum Ceiling Panels**

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	2' x 4' Smooth Lay-in Ceiling Panels		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2002 Addition: Kitchen and Serving Area		
MATERIAL QUANTITY:	2600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **2' x 4' Smooth Lay-in Ceiling Panels**

MATERIAL LOCATION: **2002 Addition: Kitchen and Serving Area**

MATERIAL QUANTITY: **2600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>52</b>		
MATERIAL DESCRIPTION:	<b>Drywall</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a**

MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **Drywall**

MATERIAL LOCATION: **2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a**

MATERIAL QUANTITY: **4800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>53</b>		
MATERIAL DESCRIPTION:	<b>Drywall Compound</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **Drywall Compound**

MATERIAL LOCATION: **2002 Addition: Student and Faculty Bathrooms Ceilings, Original Building Rooms 103, 203, 303, 404a, and 007a**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>54</b>		
MATERIAL DESCRIPTION:	<b>4" Beige Vinyl Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Original Building: Classrooms 103, 302, 203 and 303 2002 Addition: All Classrooms, Serving Area, All Purpose room&Library**

MATERIAL QUANTITY: **2780** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard**

MATERIAL LOCATION: **Original Building: Classrooms 103, 302, 203 and 303 2002 Addition: All Classrooms, Serving Area, All Purposeroom&Library**

MATERIAL QUANTITY: **2780** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55	
MATERIAL DESCRIPTION:	4" Beige Vinyl Baseboard Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Original Building: Classrooms 103, 302, 203 and 303 2002 Addition: All Classrooms, Serving Area, All Purposeroom&Library

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **4" Beige Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **Original Building: Classrooms 103, 302, 203 and 303 2002 Addition: All Classrooms, Serving Area, All Purposeroom&Library**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>56</b>	
MATERIAL DESCRIPTION:	<b>Material Inside Of Wall Mats</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **Material Inside Of Wall Mats**

MATERIAL LOCATION: **2002 Addition: All Purpose Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>57</b>		
MATERIAL DESCRIPTION:	<b>Spray on Fireproofing</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout 2002 Addition</b>		
MATERIAL QUANTITY:	<b>20000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **Spray on Fireproofing**

MATERIAL LOCATION: **Throughout 2002 Addition**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>58</b>	
MATERIAL DESCRIPTION:	<b>Marker Board Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: Classrooms 112, 114, 212, 216, 303, 310-314, and 316**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **Marker Board Adhesive**

MATERIAL LOCATION: **2002 Addition: Classrooms 112, 114, 212, 216, 303, 310-314, and 316**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>59</b>	
MATERIAL DESCRIPTION:	<b>Chalk Board Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: Classrooms 112, 114, 212, 214, 216, 303, 310-311, 313-314, and 316**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Chalk Board Adhesive**

MATERIAL LOCATION: **2002 Addition: Classrooms 112, 114, 212, 214, 216, 303, 310-311, 313-314, and 316**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>60</b>	
MATERIAL DESCRIPTION:	<b>Brown Mix Carpet Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2002 Addition: Classroom 108, Library and 315**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Brown Mix Carpet Adhesive**

MATERIAL LOCATION: **2002 Addition: Classroom 108, Library and 315**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>61</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 103 &amp; Bathroom</b>		
MATERIAL QUANTITY:	<b>625</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Room 103 & Bathroom**

MATERIAL QUANTITY: **625** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>62</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103 & Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 103 & Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>63</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Red Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 103 &amp; Bathroom</b>		
MATERIAL QUANTITY:	<b>60</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **Room 103 & Bathroom**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>64</b>	
MATERIAL DESCRIPTION:	<b>12" x 12" Red Floor Tile Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 103 & Bathroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **Room 103 & Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>65</b>	
MATERIAL DESCRIPTION:	<b>Brown Carpet Mastic</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Library, Teachers' Lounge**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Brown Carpet Mastic**

MATERIAL LOCATION: **Library, Teachers' Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>66</b>		
MATERIAL DESCRIPTION:	<b>New Fire Doors</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout New Building</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **New Fire Doors**

MATERIAL LOCATION: **Throughout New Building**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>67</b>		
MATERIAL DESCRIPTION:	<b>Old Fire Doors</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Old Building 1, 2, 3 Floor Corridor Ends</b>		
MATERIAL QUANTITY:	<b>63</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **Old Fire Doors**

MATERIAL LOCATION: **Old Building 1, 2, 3 Floor Corridor Ends**

MATERIAL QUANTITY: **63** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---


In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>68</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" White w/ Cream Specks Floor Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:	<b>Physical Damage</b>		
HISTORICAL RESPONSE ACTION:	<b>Repair</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building Room 302</b>		
MATERIAL QUANTITY:	<b>768</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:	DAMAGE UNITS: <b>SF</b>		
COMMENTS:	<b>Damage fixed</b>		

Inspector's Signature: \_\_\_\_\_ Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" White w/ Cream Specks Floor Tile**

MATERIAL LOCATION: **Original Building Room 302**

MATERIAL QUANTITY: **768** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68m		
MATERIAL DESCRIPTION:	12" x 12" White w/ Cream Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Original Building Room 302		
MATERIAL QUANTITY:	768	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **68m**

MATERIAL DESCRIPTION: **12" x 12" White w/ Cream Specks Floor Tile Mastic**

MATERIAL LOCATION: **Original Building Room 302**

MATERIAL QUANTITY: **768** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>69</b>		
MATERIAL DESCRIPTION:	<b>Light Blue Floor Tile Border</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building Room 302</b>		
MATERIAL QUANTITY:	<b>75</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **Light Blue Floor Tile Border**

MATERIAL LOCATION: **Original Building Room 302**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>70</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan Floor Tile w/ White Specks</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building Room 409 and Toilet</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile w/ White Specks**

MATERIAL LOCATION: **Original Building Room 409 and Toilet**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>70m</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Tan w/ White Specks Floor Tile Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building Room 409 and Toilet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **70m**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Original Building Room 409 and Toilet**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>71</b>		
MATERIAL DESCRIPTION:	<b>4" Black Baseboard</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building 409 and Toilet</b>		
MATERIAL QUANTITY:	<b>768</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **4" Black Baseboard**

MATERIAL LOCATION: **Original Building 409 and Toilet**

MATERIAL QUANTITY: **768** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>71m</b>		
MATERIAL DESCRIPTION:	<b>4" Black Baseboard Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building Room 409**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **71m**

MATERIAL DESCRIPTION: **4" Black Baseboard Mastic**

MATERIAL LOCATION: **Original Building Room 409**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>72</b>		
MATERIAL DESCRIPTION:	<b>Ceramic Grout</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building 1st, 2nd, and 3rd Floor Boys and Girls Toilets</b>		
MATERIAL QUANTITY:	<b>1080</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **72**

MATERIAL DESCRIPTION: **Ceramic Grout**

MATERIAL LOCATION: **Original Building 1st, 2nd, and 3rd Floor Boys and Girls Toilets**

MATERIAL QUANTITY: **1080** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>73</b>	
MATERIAL DESCRIPTION:	<b>Terrazzo Sinks</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building 1st, 2nd, 3rd Floor s Boys and Girls Bathrooms.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **73**

MATERIAL DESCRIPTION: **Terrazzo Sinks**

MATERIAL LOCATION: **Original Building 1st, 2nd, 3rd Floor s Boys and Girls Bathrooms.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>74</b>	
MATERIAL DESCRIPTION:	<b>1' x 1' White Ceiling Tile Adhesive</b>	
HISTORICAL AHERA DAMAGE CATEGORY	<b>ACBM with the potential for damage</b>	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>	
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Original Building Rooms 201, 202, 202a, Office, Clerk Space, Principal Office, 1st- 3rd Corridors 301, 302, and 308**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **74**

MATERIAL DESCRIPTION: **1' x 1' White Ceiling Tile Adhesive**

MATERIAL LOCATION: **Original Building Rooms 201, 202, 202a, Office, Clerk Space, Principal Office, 1st- 3rd Corridors 301, 302, and 308**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>75</b>		
MATERIAL DESCRIPTION:	<b>2' x 2' Lay-in Ceiling Tile</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Original Building 103, 205, and 303</b>		
MATERIAL QUANTITY:	<b>1300</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **75**

MATERIAL DESCRIPTION: **2' x 2' Lay-in Ceiling Tile**

MATERIAL LOCATION: **Original Building 103, 205, and 303**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>8</b>		
MATERIAL DESCRIPTION:	<b>Masonite Wall Covering</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement</b>		
MATERIAL QUANTITY:	<b>600</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Masonite Wall Covering**

MATERIAL LOCATION: **Basement**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cementitious Mud Joints**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Fieldhouse**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cementitious Mud Joints**

MATERIAL LOCATION: **Fieldhouse**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>C</b>		
MATERIAL DESCRIPTION:	<b>Aircell Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement - Room 009, Sprinkler Pump Room, West Corridor, Assembly Hall Passage**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement - Room 009, Sprinkler Pump Room, West Corridor, Assembly Hall Passage**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>D</b>		
MATERIAL DESCRIPTION:	<b>Aircell Joints</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - Room 009, Sprinkler Pump Room</b>		
MATERIAL QUANTITY:	<b>40</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Aircell Joints**

MATERIAL LOCATION: **Basement - Room 009, Sprinkler Pump Room**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>F</b>		
MATERIAL DESCRIPTION:	<b>Cardboard Insulation Joints</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Amosite</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement - West Corridor</b>		
MATERIAL QUANTITY:	<b>60</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Cardboard Insulation Joints**

MATERIAL LOCATION: **Basement - West Corridor**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>G</b>		
MATERIAL DESCRIPTION:	<b>Mag - Block Pipe Insulation</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd Floor Above Principal's Bathroom**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS: **Material in inaccessible area(s) - 2025**

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Mag - Block Pipe Insulation**

MATERIAL LOCATION: **2nd Floor Above Principal's Bathroom**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>H</b>		
MATERIAL DESCRIPTION:	<b>Mag - Block Joints</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Basement - Corridor**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Mag - Block Joints**

MATERIAL LOCATION: **Basement - Corridor**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>I</b>		
MATERIAL DESCRIPTION:	<b>Joint Insul. Assoc. w/ Fiberglass Insulated Piping</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement and Bathrooms</b>		
MATERIAL QUANTITY:	<b>100</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Joint Insul. Assoc. w/ Fiberglass Insulated Piping**

MATERIAL LOCATION: **Basement and Bathrooms**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>J</b>		
MATERIAL DESCRIPTION:	<b>Joint Insul. Assoc. w/ Cardboard Insulated Piping</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>7 Any remaining friable ACBM or friable suspect ACBM</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Chrysotile</b>	FRIABLE:	<b>Yes</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement and Bathrooms</b>		
MATERIAL QUANTITY:	<b>140</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **04/04/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Joint Insul. Assoc. w/ Cardboard Insulated Piping**

MATERIAL LOCATION: **Basement and Bathrooms**

MATERIAL QUANTITY: **140** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Jose Escobedo</b>		
SCHOOL NAME:	<b>Pickard School</b>	INSPECTION DATE:	<b>4/4/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>		IDPH LICENSE NO:	<b>100-06435</b>	

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Packing Material**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 04/04/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Packing Material**

MATERIAL LOCATION: **MATERIAL REMOVED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	158		
MATERIAL DESCRIPTION:	2" x 2" Cream Ceramic Floor Tile Mortar		
MATERIAL LOCATION:	Boys and Girls Bathroom 1st Floor of Old Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

HOMOGENEOUS AREA: **158**

MATERIAL DESCRIPTION: **2" x 2" Cream Ceramic Floor Tile Mortar**

MATERIAL LOCATION: **Boys and Girls Bathroom 1st Floor of Old Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	160		
MATERIAL DESCRIPTION:	2" x 2" Yellow Ceramic Floor Tile Mortar		
MATERIAL LOCATION:	1st Floor Girls Bathroom in Old Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

HOMOGENEOUS AREA: **160**

MATERIAL DESCRIPTION: **2" x 2" Yellow Ceramic Floor Tile Mortar**

MATERIAL LOCATION: **1st Floor Girls Bathroom in Old Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	154		
MATERIAL DESCRIPTION:	2" x 2" Cream Ceramic Wall Tile Mortar		
MATERIAL LOCATION:	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		
HOMOGENEOUS AREA:		<b>154</b>			
MATERIAL DESCRIPTION:		<b>2" x 2" Cream Ceramic Wall Tile Mortar</b>			
MATERIAL LOCATION:		<b>Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building</b>			
MATERIAL QUANTITY:	<b>500</b>	MATERIAL UNITS:	<b>LF</b>		
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	159		
MATERIAL DESCRIPTION:	2" x 2" Yellow Ceramic Floor Tile		
MATERIAL LOCATION:	1st Floor Girls Bathroom in Old Building		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

HOMOGENEOUS AREA: **159**

MATERIAL DESCRIPTION: **2" x 2" Yellow Ceramic Floor Tile**

MATERIAL LOCATION: **1st Floor Girls Bathroom in Old Building**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	145			
MATERIAL DESCRIPTION:	White Glazed CMU			
MATERIAL LOCATION:	Throughout Boys and Girls Toilet Rooms in New Additions Building			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **145**

MATERIAL DESCRIPTION: **White Glazed CMU**

MATERIAL LOCATION: **Throughout Boys and Girls Toilet Rooms in New Additions Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	156		
MATERIAL DESCRIPTION:	2" x 2" Dark Blue Ceramic Floor Tile Mortar		
MATERIAL LOCATION:	Boys Bathroom 1st Floor of Old Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BULDING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **156**

MATERIAL DESCRIPTION: **2" x 2" Dark Blue Ceramic Floor Tile Mortar**

MATERIAL LOCATION: **Boys Bathroom 1st Floor of Old Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	141			
MATERIAL DESCRIPTION:	Black Epoxy Flooring			
MATERIAL LOCATION:	Throughout Old Building			
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **141**

MATERIAL DESCRIPTION: **Black Epoxy Flooring**

MATERIAL LOCATION: **Throughout Old Building**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	148			
MATERIAL DESCRIPTION:	Green Glazed CMU Mortar			
MATERIAL LOCATION:	3rd Floor Boys and Girls Toilet Rooms in New Additions Building			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **148**

MATERIAL DESCRIPTION: **Green Glazed CMU Mortar**

MATERIAL LOCATION: **3rd Floor Boys and Girls Toilet Rooms in New Additions Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	152		
MATERIAL DESCRIPTION:	2" x 2" Light Blue Ceramic Floor Tile Mortar		
MATERIAL LOCATION:	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		
HOMOGENEOUS AREA:		<b>152</b>			
MATERIAL DESCRIPTION:		<b>2" x 2" Light Blue Ceramic Floor Tile Mortar</b>			
MATERIAL LOCATION:		<b>Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building</b>			
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	146			
MATERIAL DESCRIPTION:	White Glazed CMU Mortar			
MATERIAL LOCATION:	Throughout Boys and Girls Toilet Rooms in New Additions Building			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **146**

MATERIAL DESCRIPTION: **White Glazed CMU Mortar**

MATERIAL LOCATION: **Throughout Boys and Girls Toilet Rooms in New Additions Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	157		
MATERIAL DESCRIPTION:	2" x 2" Cream Ceramic Floor Tile		
MATERIAL LOCATION:	Boys and Girls Bathroom 1st Floor of Old Building		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUILDING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

HOMOGENEOUS AREA: **157**

MATERIAL DESCRIPTION: **2" x 2" Cream Ceramic Floor Tile**

MATERIAL LOCATION: **Boys and Girls Bathroom 1st Floor of Old Building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	161		
MATERIAL DESCRIPTION:	Thermal Insulation		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	TSI	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **161**

MATERIAL DESCRIPTION: **Thermal Insulation**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	149			
MATERIAL DESCRIPTION:	Red Glazed CMU			
MATERIAL LOCATION:	2nd Floor Boys and Girls Toilet Rooms in New Additions Building			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **149**

MATERIAL DESCRIPTION: **Red Glazed CMU**

MATERIAL LOCATION: **2nd Floor Boys and Girls Toilet Rooms in New Additions Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	155		
MATERIAL DESCRIPTION:	2" x 2" Dark Blue Ceramic Floor Tile		
MATERIAL LOCATION:	Boys Bathroom 1st Floor of Old Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		

HOMOGENEOUS AREA: **155**

MATERIAL DESCRIPTION: **2" x 2" Dark Blue Ceramic Floor Tile**

MATERIAL LOCATION: **Boys Bathroom 1st Floor of Old Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	143			
MATERIAL DESCRIPTION:	Gray CMU			
MATERIAL LOCATION:	Throughout Corridors in New Addition Building			
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **143**

MATERIAL DESCRIPTION: **Gray CMU**

MATERIAL LOCATION: **Throughout Corridors in New Addition Building**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	150		
MATERIAL DESCRIPTION:	Red Glazed CMU Mortar		
MATERIAL LOCATION:	2nd Floor Boys and Girls Toilet Rooms in New Additions Building		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **150**

MATERIAL DESCRIPTION: **Red Glazed CMU Mortar**

MATERIAL LOCATION: **2nd Floor Boys and Girls Toilet Rooms in New Additions Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	153			
MATERIAL DESCRIPTION:	2" x 2" Cream Ceramic Wall Tile			
MATERIAL LOCATION:	Room 114 and 112 Bathroom, Boys and Girls Bathroom 1st Floor of Old Building			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **153**

MATERIAL DESCRIPTION: **2" x 2" Cream Ceramic Wall Tile**

MATERIAL LOCATION: **Room 114 and 112 Bathroom, Boys and Girls Bathroom 1st Floor of Old Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	142			
MATERIAL DESCRIPTION:	1" x 1" Brown and White Ceramic Floor Tile			
MATERIAL LOCATION:	Throughout Boys and Girls Toilet Rooms in Original Building			
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **142**

MATERIAL DESCRIPTION: **1" x 1" Brown and White Ceramic Floor Tile**

MATERIAL LOCATION: **Throughout Boys and Girls Toilet Rooms in Original Building**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

---

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	144			
MATERIAL DESCRIPTION:	Gray CMU Mortar			
MATERIAL LOCATION:	Throughout Corridors in New Additions Building			
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **144**

MATERIAL DESCRIPTION: **Gray CMU Mortar**

MATERIAL LOCATION: **Throughout Corridors in New Additions Building**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	147			
MATERIAL DESCRIPTION:	Green Glazed CMU			
MATERIAL LOCATION:	3rd Floor Boys and Girls Toilet Rooms in New Additions Building			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24961** BUIDLING ID: **5430**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Pickard School** REVIEW DATE: **4/28/2025**

ADDRESS: **2301 W. 21st Pl.** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **147**

MATERIAL DESCRIPTION: **Green Glazed CMU**

MATERIAL LOCATION: **3rd Floor Boys and Girls Toilet Rooms in New Additions Building**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24961	BUIDLING ID:	5430
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Pickard School	INSPECTION DATE:	4/4/2025		
ADDRESS:	2301 W. 21st Pl.	IDPH LICENSE NO:	100-06435		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	151		
MATERIAL DESCRIPTION:	2" x 2" Light Blue Ceramic Floor Tile		
MATERIAL LOCATION:	Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 04/04/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24961</b>	BUIDLING ID:	<b>5430</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Jackson Montgomery</b>		
SCHOOL NAME:	<b>Pickard School</b>	REVIEW DATE:	<b>4/28/2025</b>		
ADDRESS:	<b>2301 W. 21st Pl.</b>	IDPH LICENSE NO:	<b>100-06435</b>		
HOMOGENEOUS AREA:		<b>151</b>			
MATERIAL DESCRIPTION:		<b>2" x 2" Light Blue Ceramic Floor Tile</b>			
MATERIAL LOCATION:		<b>Room 114, 112 and 404 Bathrooms, Boys and Girls Bathroom 1st Floor of Old Building</b>			
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>		
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>		

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **04/28/2025**

## APPENDIX B

---

### Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**Jose Escobedo**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2409132637  
Course Date: 9/13/2024  
Exam Date: 9/13/2024  
Expiration Date: 9/13/2025



Issue Date: 9/13/2024


  
Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

# Jose Escobedo

---

Air Sampling Professional, Illinois Licensed Building Inspector, Asbestos Project Manager



ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	1/11/2026
INSPECTOR	9/13/2025



PROJECT MANAGER	1/11/2026
AIR SAMPLING PROFESSIONAL	

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

---

# Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



**ENDORSEMENTS**

INSPECTOR

**TC EXPIRES**

2/22/2025

**ENDORSEMENTS**

**TC EXPIRES**

10/29/2025

**AIR SAMPLING PROFESSIONAL**

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.



2200 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

### Environmental and Occupational Safety & Health Training

*Does hereby certify*

**Jackson Montgomery**

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least  
70% for accreditation under AHERA (Title II)*

### **Asbestos Management Planner Initial**

*Class Date:* 10/28-29/2024

*Examination Date:* 10/29/2024

*STC Certificate Number:* STC-20241029-000101AMPI

*Certification Expiration:* 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

*This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources*

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed