

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2406  
SCHOOL NAME: Plamondon School  
ADDRESS OF SCHOOL: 2642 W. 15th Pl.  
CITY: Chicago, IL, 60608

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 11/30/2022

If the address on this form is different than the address of the building, submit a written explanation.

**SECTION II** *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 3/27/2025 ENROLLMENT 88  
IDPH INSPECTOR LICENSE NUMBER: 100-20994  
IDPH LICENSED INSPECTOR NAME (Please Print): Cody Cummins  
IDPH MP LICENSE NUMBER: 100-18488  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 4/14/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Plamondon School**

2642 W. 15th Pl.  
Chicago, IL, 60608

Unit: 24981  
Building ID: 5450

IDPH ID Number: 14-016-2990-2406

**REPORT DATE:**  
Monday, April 14, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Carnow, Conibear and Associates**

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

04/14/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 24981      Region: 03      IDPH ID: 14-016-2990-2406

School: Plamondon School      Building ID: 5450

Address: 2642 W. 15th Pl.

Chicago, IL, 60608

Building Contact: Lumpkin, Robert      Contact Phone: 7736731971

Current Building Owners: Chicago Public Schools

Reinspection Date: 3/27/2025

Review Date: 04/14/2025

Inspector: Cody Cummins

Inspector IDPH License: 100-20994

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,  
Carnow, Conibear and Associates



Mike Serio  
100-18488

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: April 14, 2025

RE: Plamondon School, Unit 24981  
2642 W. 15th Pl.  
Chicago, IL, 60608

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Plamondon School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Plamondon School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Plamondon School      Unit: 24981      Region: 03  
Address: 2642 W. 15th Pl.      Chicago, IL, 60608  
IDPH ID: 14-016-2990-2406      Building ID: 5450  
Contact: Lumpkin, Robert      Phone: 7736731971

### 2. Description of Facility

Original Construction: 1903      Additional Construction:  
Total Square Footage: 38751      No of Floors: 3  
Current Occupancy: 88

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates  
Contact: Doug McCormick  
Address 600 West Van Buren St., Ste 500  
Phone: (312) 762-2900      Fax: (312) 782-5145

### 5. Inspector

Inspector Name: Cody Cummins

Inspector IDPH license # 100-20994  
Reinspection Date: 3/27/2025



Signature:  
Date: 3/27/2025

### 6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488




Signature:  
Date: 04/14/2025

### 7. Review Date: 04/14/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 4/14/2025

Name: Richard J.Schleyer

## II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Plamondon School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 5450:

12	12" x 12" Tan w/ Brown & White Streaks Floor Tile Mastic
13	Terrazzo
24	Incinerator Fire Brick
26	Transite Behind Fire Alarm
28	Underlayment & 12" x 12" Floor Tile - Mastic
29	12" x 12" Floor Tile
3	Cinder Block
30	12" x 12" Beige Floor Tile
31	12" x 12" Beige Floor Tile Mastic

32	12" x 12" Beige Floor Tile w/ White Streaks
33	12" x 12" Beige Floor Tile w/ White Streaks Mastic
43	Incinerator Seals and Gaskets
6	Interior Brick Mortar
E	Fiberglass Pipe Insulation
EXM	Exterior Brick Mortar - Non-AHERA

B. The following new homogenous areas have been identified for Building 5450:

101	Tongue & Groove Wood Flooring
102	2' x 4' Smooth Ceiling Tile
103	12" x 12" Blue Gray Mottled Vinyl Floor Tile
104	12" x 12" Blue Gray Mottled Vinyl Floor Tile Mastic
105	2' x 2' Pinholed Ceiling Tile
106	4" Black Vinyl Baseboard
107	4" Black Vinyl Baseboard Adhesive

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

1	Plaster
100	Door Caulk
101	Tongue & Groove Wood Flooring
102	2' x 4' Smooth Ceiling Tile
103	12" x 12" Blue Gray Mottled Vinyl Floor Tile
104	12" x 12" Blue Gray Mottled Vinyl Floor Tile Mastic
105	2' x 2' Pinholed Ceiling Tile
106	4" Black Vinyl Baseboard
107	4" Black Vinyl Baseboard Adhesive
11	12" x 12" Tan w/ Brown & White Streaks Floor Tile
13	Terrazzo
15	Ceramic Tile Grout
16	1' x 1' Tan, Gray, White Specks Ceramic Tile Grout
17	Ceramic Wall Tile, Base Board Adhesive
18	12" x 12" White Floor Tile w/ Gray Streaks
2	1' x 1' Ceiling Tiles
20	Multi- Brown Asphalight Tile Grout
21	Wall Tile Adhesive
22	Boiler Insulation
23	Blue/Gray Carpet Mastic
24	Incinerator Fire Brick
25	Yellow & Brown Carpet Mastic, Library in Basement
26	Transite Behind Fire Alarm
27	Insulation Inside Fire Doors
29	12" x 12" Floor Tile
30	12" x 12" Beige Floor Tile
31	12" x 12" Beige Floor Tile Mastic
32	12" x 12" Beige Floor Tile w/ White Streaks
33	12" x 12" Beige Floor Tile w/ White Streaks Mastic
34	Red and Gold Terrazo
35	Red and Gold Terrazo Adhesive
36	Metal Pan Ceiling Paper Backing
37	6" Black Vinyl Baseboard
38	6" Black Vinyl Baseboard Adhesive
39	Dark Brown w/ Light Brown Carpet Mastic
40	Black Chalk Boards
41	Wall Sizing Paper
42	Incinerator Flue Lining
43	Incinerator Seals and Gaskets
44	Fire Escape Fire Doors

45	12" x 12" Yellow Floor Tile
45m	1' x 1' Tan, Gray, White Specks, Ceramic Tile Grout
46	12" x 12" Yellow Floor Tile Mastic
5	Interior Brick
EXF	Exterior Roof Flashing - Non-AHERA
EXR	Roofing - Non-AHERA
F	Hard Joint Compound on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

102	2' x 4' Smooth Ceiling Tile
104	12" x 12" Blue Gray Mottled Vinyl Floor Tile Mastic
105	2' x 2' Pinholed Ceiling Tile
107	4" Black Vinyl Baseboard Adhesive
19	12" x 12" White Floor Tile w/ Gray Streaks Mastic
23	Blue/Gray Carpet Mastic
24	Incinerator Fire Brick
27	Insulation Inside Fire Doors
33	12" x 12" Beige Floor Tile w/ White Streaks Mastic
35	Red and Gold Terrazo Adhesive
38	6" Black Vinyl Baseboard Adhesive
39	Dark Brown w/ Light Brown Carpet Mastic
43	Incinerator Seals and Gaskets
44	Fire Escape Fire Doors
46	12" x 12" Yellow Floor Tile Mastic
A	Cardboard Pipe Insulation
B	Cardboard Pipe Insulation Joints

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Cody Cummins, IDPH License # 100-20994. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Plamondon School Building 5450 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Plamondon School **Unit** 24981 **Building ID** 5450  
**Address** 2642 W. 15th Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
1	Plaster	120,000	SF	3rd Floor Hallway, 304, 3rd Floor Gymnasium, 302, 301, 2nd Floor Hallway, 202, 201, 203, 205, 204, First Floor Hallway, 101, 102, 104, 105, Basement Hallway	ASSUMED	SURFACE	N	NONE			No	ACBM with the potential for damage		LOW
10	Small Tank Insulation (At Top Of Tank)				NO_ACBM	TSI					No			
100	Door Caulk	2,000	LF	Throughout	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
101	Tongue & Groove Wood Flooring	10,000	SF	3rd Floor Hallway, 3rd Floor Gym 303, 301, 302, 304, 201, 202, 203, 204, 205, 101, 102, 104, 105,	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
102	2' x 4' Smooth Ceiling Tile	1,000	SF	Rooms 203, 205	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
103	12" x 12" Blue Gray Mottled Vinyl Floor Tile	300	SF	Main Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
104	12" x 12" Blue Gray Mottled Vinyl Floor Tile Mastic	300	SF	Main Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
105	2' x 2' Pinholed Ceiling Tile	5,000	SF	023 Office, 023a Office, Hallway to Boiler Room	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
106	4" Black Vinyl Baseboard	100	LF	023 Office, Hallway to Boiler Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
107	4" Black Vinyl Baseboard Adhesive	100	LF	023 Office, Hallway to Boiler Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
11	12" x 12" Tan w/ Brown & White Streaks Floor Tile				ASSUMED	MISC					No			
12	12" x 12" Tan w/ Brown & White Streaks Floor Tile Mastic				NO_ACBM	MISC					Yes			
13	Terrazzo	1,000	SF	Basement, Hallways, & Stairs- Except 3rd Floor	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
15	Ceramic Tile Grout	40	SF	Teachers' Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16	1' x 1' Tan, Gray, White Specks Ceramic Tile Grout	750	SF	2nd Floor Girls & Boys Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	Ceramic Wall Tile, Base Board Adhesive	750	SF	2nd Floor Girls & Boys Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Plamondon School **Unit** 24981 **Building ID** 5450  
**Address** 2642 W. 15th Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
18	12" x 12" White Floor Tile w/ Gray Streaks	1,920	SF	Rooms 102, 104, & Kindergarten, Basement Counselors Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
19	12" x 12" White Floor Tile w/ Gray Streaks Mastic	1,920	SF	Rooms 102, 104, & Kindergarten, Basement Counselors Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office	CHR	MISC	N				No	ACBM with the potential for damage		LOW
2	1' x 1' Ceiling Tiles	10,000	SF	304, 3rd Floor Hallway, 302, 301, 202, 201, 204, 102, 101, 105, 104	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
20	Multi- Brown Asphalight Tile Grout	36	SF	Room 104 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
21	Wall Tile Adhesive	75	SF	Room 104 Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
22	Boiler Insulation				ASSUMED	TSI					No			
23	Blue/Gray Carpet Mastic	250	SF	Office 023A	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
24	Incinerator Fire Brick	3	SF	Boiler Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
25	Yellow & Brown Carpet Mastic, Library in Basement	864	SF	Social Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
26	Transite Behind Fire Alarm	1	SF	Room 301	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
27	Insulation Inside Fire Doors	126	SF	Entrances & Exits Doors, Boiler Room and Coal Room Doors	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
28	Underlayment & 12" x 12" Floor Tile - Mastic			ABATED	ABATED	MISC					Yes			
29	12" x 12" Floor Tile			Mens Bathroom	ASSUMED	MISC					Yes			
3	Cinder Block			Throughout Basement	NO_ACBM	MISC					Yes			
30	12" x 12" Beige Floor Tile			Main office	ASSUMED	MISC					Yes			
31	12" x 12" Beige Floor Tile Mastic			Main office	ASSUMED	MISC					Yes			

# Chicago Public Schools

**School** Plamondon School **Unit** 24981 **Building ID** 5450  
**Address** 2642 W. 15th Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
32	12" x 12" Beige Floor Tile w/ White Streaks	1,000	SF	Basement Classrooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
33	12" x 12" Beige Floor Tile w/ White Streaks Mastic	1,000	SF	Basement Classrooms	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
34	Red and Gold Terrazzo	20	SF	1st Floor Teachers' Bathroom, Main Office Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
35	Red and Gold Terrazzo Adhesive	20	SF	1st Floor Teachers' Bathroom, Main Office Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
36	Metal Pan Ceiling Paper Backing	18,529	SF	101, 102, 104, 105, 201, 202, 204, 205, 2nd & 3rd Fl. Corr., 3rd Fl. E. Stair Vestibule	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
37	6" Black Vinyl Baseboard	20	LF	1st Floor Mens Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
38	6" Black Vinyl Baseboard Adhesive	20	LF	1st Floor Mens Bathroom	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
39	Dark Brown w/ Light Brown Carpet Mastic	350	SF	Basement Library	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
4	Cinder Block Mortar			Throughout Basement	NO_ACBM	MISC					No			
40	Black Chalk Boards	2,904	SF	105, 101, 102, 201, 202, 204, 301, 302, 304	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
41	Wall Sizing Paper	30	SF	Room 301 Behind Ladder Womens Attic	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
42	Incinerator Flue Lining	150	SF	Boiler Room	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
43	Incinerator Seals and Gaskets	15	LF	Boiler Room	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
44	Fire Escape Fire Doors	84	SF	2nd and 3rd Floor Corridors At Fire Escape Entrances	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
45	12" x 12" Yellow Floor Tile	15	SF	1st Floor Mens Wash Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
45m	1' x 1' Tan, Gray, White Specks, Ceramic Tile Grout	1,300	SF	Girls & Boys Basement Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
46	12" x 12" Yellow Floor Tile Mastic	15	SF	1st Floor Mens Wash Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Plamondon School **Unit** 24981 **Building ID** 5450  
**Address** 2642 W. 15th Pl. **Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
5	Interior Brick	30,000	SF	Throughout Basement	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
6	Interior Brick Mortar			Throughout Basement	NO_ACBM	MISC					Yes			
7	Window Caulk			Throughout Facility	NO_ACBM	MISC					No			
8	Insulation Wrap For Water Heater			Boiler Room	NO_ACBM	TSI					No			
9	Small Tank Insulation (Sides)			Boiler Room	NO_ACBM	TSI					No			
A	Cardboard Pipe Insulation	1,000	LF	Basement & Throughout 1st, 2nd & 3rd Floors	CHR	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
B	Cardboard Pipe Insulation Joints	50	LF	Basement & Throughout 1st, 2nd & 3rd Floors	CHR	TSI	Y				No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Fiberglass Pipe Insulation	1,500	LF	Throughout Facility	NOT_TESTED	TSI	Y				Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
EDG	Exterior Door Grout - Non-AHERA			Exterior	NO_ACBM	MISC					No			
EWG	Exterior Window Caulk - Non-AHERA			Exterior	NO_ACBM	MISC					No			
EXB	Exterior Brick - Non-AHERA			Exterior	NO_ACBM	MISC					No			
EXF	Exterior Roof Flashing - Non-AHERA			Exterior	ASSUMED	MISC					No			
EXM	Exterior Brick Mortar - Non-AHERA			Exterior	NO_ACBM	MISC					Yes			
EXR	Roofing - Non-AHERA			Exterior	ASSUMED	MISC					No			
F	Hard Joint Compound on Fiberglass Pipe Insulation	20	LF	Coal Room Next Womens Boiler Room	ASSUMED	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW

# Chicago Public Schools

School Plamondon School Unit 24981 Building ID 5450  
Address 2642 W. 15th Pl. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <u>3/27/2025</u>
Inspector Name <u>Cody Cummins</u>
<u>100-20994</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
1	
10	
100	
101	
102	
103	
104	
105	
106	
107	
11	Material not observed - 2025
12	
13	
15	
16	
17	
18	
19	
2	
20	
21	
22	Material not observed - 2025
23	
24	

# Chicago Public Schools

School Plamondon School Unit 24981 Building ID 5450  
Address 2642 W. 15th Pl. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
25	
26	
27	
28	
29	Material not observed - 2025
3	
30	Material not observed - 2025
31	Material not observed - 2025
32	
33	
34	
35	
36	
37	
38	
39	Not found in office
4	
40	Not found in 205
41	
42	
43	
44	
45	
45m	
46	
5	
6	
7	
8	

# Chicago Public Schools

School Plamondon School Unit 24981 Building ID 5450  
Address 2642 W. 15th Pl. Region 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
9	
A	
B	
E	Fiberglass not suspect
EDG	
EWG	
EXB	
EXF	
EXM	
EXR	
F	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Plamondon School

**Unit** 24981

**Building ID** 5450

**Address** 2642 W. 15th Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
1	Plaster	120,000	SF	3rd Floor Hallway, 304, 3rd Floor Gymnasium, 302, 301, 2nd Floor Hallway, 202, 201, 203, 205, 204, First Floor Hallway, 101, 102, 104, 105, Basement Hallway	Assumed	SURFACE	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	Small Tank Insulation (At Top Of Tank)				No ACBM	TSI					
100	Door Caulk	2,000	LF	Throughout	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
101	Tongue & Groove Wood Flooring	10,000	SF	3rd Floor Hallway, 3rd Floor Gym 303, 301, 302, 304, 201, 202, 203, 204, 205, 101, 102, 104, 105,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
102	2' x 4' Smooth Ceiling Tile	1,000	SF	Rooms 203, 205	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
103	12" x 12" Blue Gray Mottled Vinyl Floor Tile	300	SF	Main Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
104	12" x 12" Blue Gray Mottled Vinyl Floor Tile Mastic	300	SF	Main Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	2' x 2' Pinholed Ceiling Tile	5,000	SF	023 Office, 023a Office, Hallway to Boiler Room	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
106	4" Black Vinyl Baseboard	100	LF	023 Office, Hallway to Boiler Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
107	4" Black Vinyl Baseboard Adhesive	100	LF	023 Office, Hallway to Boiler Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
11	12" x 12" Tan w/ Brown & White Streaks Floor Tile				Assumed	MISC					
12	12" x 12" Tan w/ Brown & White Streaks Floor Tile Mastic				No ACBM	MISC					
13	Terrazzo	1,000	SF	Basement, Hallways, & Stairs-Except 3rd Floor	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Ceramic Tile Grout	40	SF	Teachers' Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	1' x 1' Tan, Gray, White Specks Ceramic Tile Grout	750	SF	2nd Floor Girls & Boys Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	Ceramic Wall Tile, Base Board Adhesive	750	SF	2nd Floor Girls & Boys Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12" x 12" White Floor Tile w/ Gray Streaks	1,920	SF	Rooms 102, 104, & Kindergarten, Basement Counselors Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	12" x 12" White Floor Tile w/ Gray Streaks Mastic	1,920	SF	Rooms 102, 104, & Kindergarten, Basement Counselors Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2	1' x 1' Ceiling Tiles	10,000	SF	304, 3rd Floor Hallway, 302, 301, 202, 201, 204, 102, 101, 105, 104	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Plamondon School

**Unit** 24981

**Building ID** 5450

**Address** 2642 W. 15th Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
20	Multi- Brown Asphalight Tile Grout	36	SF	Room 104 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Wall Tile Adhesive	75	SF	Room 104 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Boiler Insulation				Assumed	TSI					
23	Blue/Gray Carpet Mastic	250	SF	Office 023A	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
24	Incinerator Fire Brick	3	SF	Boiler Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Yellow & Brown Carpet Mastic, Library in Basement	864	SF	Social Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
26	Transite Behind Fire Alarm	1	SF	Room 301	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
27	Insulation Inside Fire Doors	126	SF	Entrances & Exits Doors, Boiler Room and Coal Room Doors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
28	Underlayment & 12" x 12" Floor Tile - Mastic			ABATED	Abated	MISC					
29	12" x 12" Floor Tile			Mens Bathroom	Assumed	MISC					
3	Cinder Block			Throughout Basement	No ACBM	MISC					
30	12" x 12" Beige Floor Tile			Main office	Assumed	MISC					
31	12" x 12" Beige Floor Tile Mastic			Main office	Assumed	MISC					
32	12" x 12" Beige Floor Tile w/ White Streaks	1,000	SF	Basement Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	12" x 12" Beige Floor Tile w/ White Streaks Mastic	1,000	SF	Basement Classrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Red and Gold Terrazzo	20	SF	1st Floor Teachers' Bathroom, Main Office Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Red and Gold Terrazzo Adhesive	20	SF	1st Floor Teachers' Bathroom, Main Office Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Metal Pan Ceiling Paper Backing	18,529	SF	101, 102, 104, 105, 201, 202, 204, 205, 2nd & 3rd Fl. Corr., 3rd Fl. E. Stair Vestibule	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37	6" Black Vinyl Baseboard	20	LF	1st Floor Mens Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
38	6" Black Vinyl Baseboard Adhesive	20	LF	1st Floor Mens Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
39	Dark Brown w/ Light Brown Carpet Mastic	350	SF	Basement Library	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
4	Cinder Block Mortar			Throughout Basement	No ACBM	MISC					
40	Black Chalk Boards	2,904	SF	105, 101, 102, 201, 202, 204, 301, 302, 304	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
41	Wall Sizing Paper	30	SF	Room 301 Behind Ladder Womens Attic	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
42	Incinerator Flue Lining	150	SF	Boiler Room	Assumed	TSI	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
43	Incinerator Seals and Gaskets	15	LF	Boiler Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
44	Fire Escape Fire Doors	84	SF	2nd and 3rd Floor Corridors At Fire	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Plamondon School

**Unit** 24981

**Building ID** 5450

**Address** 2642 W. 15th Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Escape Entrances							
45	12" x 12" Yellow Floor Tile	15	SF	1st Floor Mens Wash Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
45m	1' x 1' Tan, Gray, White Specks, Ceramic Tile Grout	1,300	SF	Girls & Boys Basement Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" Yellow Floor Tile Mastic	15	SF	1st Floor Mens Wash Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
5	Interior Brick	30,000	SF	Throughout Basement	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	Interior Brick Mortar			Throughout Basement	No ACBM	MISC					
7	Window Caulk			Throughout Facility	No ACBM	MISC					
8	Insulation Wrap For Water Heater			Boiler Room	No ACBM	TSI					
9	Small Tank Insulation (Sides)			Boiler Room	No ACBM	TSI					
A	Cardboard Pipe Insulation	1,000	LF	Basement & Throughout 1st, 2nd & 3rd Floors	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Cardboard Pipe Insulation Joints	50	LF	Basement & Throughout 1st, 2nd & 3rd Floors	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Fiberglass Pipe Insulation	1,500	LF	Throughout Facility	Not Tested	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
EDG	Exterior Door Grout - Non-AHERA			Exterior	No ACBM	MISC					
EWG	Exterior Window Caulk - Non-AHERA			Exterior	No ACBM	MISC					
EXB	Exterior Brick - Non-AHERA			Exterior	No ACBM	MISC					
EXF	Exterior Roof Flashing - Non-AHERA			Exterior	Assumed	MISC					
EXM	Exterior Brick Mortar - Non-AHERA			Exterior	No ACBM	MISC					
EXR	Roofing - Non-AHERA			Exterior	Assumed	MISC					
F	Hard Joint Compound on Fiberglass Pipe Insulation	20	LF	Coal Room Next Womens Boiler Room	Assumed	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Plamondon School

**Unit** 24981

**Building ID** 5450

**Address** 2642 W. 15th Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900      Fax: (312) 782-5145

*Management Planner's Comments Summarized at the End of the Report*

Review Date	4/14/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
1	Sample to determine ACM content prior to disturbance.
10	
100	Sample to determine ACM content prior to disturbance.
101	Sample to determine ACM content prior to disturbance.
102	Sample to determine ACM content prior to disturbance.
103	Sample to determine ACM content prior to disturbance.
104	Sample to determine ACM content prior to disturbance.
105	Sample to determine ACM content prior to disturbance.
106	Sample to determine ACM content prior to disturbance.
107	Sample to determine ACM content prior to disturbance.
11	If identified, continue O&M.
12	
13	Sample to determine ACM content prior to disturbance.
15	Sample to determine ACM content prior to disturbance.
16	Sample to determine ACM content prior to disturbance.
17	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Plamondon School

**Unit** 24981

**Building ID** 5450

**Address** 2642 W. 15th Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
18	Sample to determine ACM content prior to disturbance.
19	
2	Sample to determine ACM content prior to disturbance.
20	Sample to determine ACM content prior to disturbance.
21	Sample to determine ACM content prior to disturbance.
22	If identified, continue O&M.
23	Sample to determine ACM content prior to disturbance.
24	Sample to determine ACM content prior to disturbance.
25	Sample to determine ACM content prior to disturbance.
26	Sample to determine ACM content prior to disturbance.
27	Sample to determine ACM content prior to disturbance.
28	
29	If identified, continue O&M.
3	
30	If identified, continue O&M.
31	If identified, continue O&M.
32	Sample to determine ACM content prior to disturbance.
33	Sample to determine ACM content prior to disturbance.
34	Sample to determine ACM content prior to disturbance.
35	Sample to determine ACM content prior to disturbance.
36	Sample to determine ACM content prior to disturbance.
37	Sample to determine ACM content prior to disturbance.
38	Sample to determine ACM content prior to disturbance.
39	Sample to determine ACM content prior to disturbance.
4	
40	Sample to determine ACM content prior to disturbance.
41	Sample to determine ACM content prior to disturbance.

# Chicago Public Schools

**School** Plamondon School

**Unit** 24981

**Building ID** 5450

**Address** 2642 W. 15th Pl.

Chicago, IL, 60608

**Region** 03

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
42	Sample to determine ACM content prior to disturbance.
43	Sample to determine ACM content prior to disturbance.
44	Sample to determine ACM content prior to disturbance.
45	Sample to determine ACM content prior to disturbance.
45m	Sample to determine ACM content prior to disturbance.
46	Sample to determine ACM content prior to disturbance.
5	Sample to determine ACM content prior to disturbance.
6	
7	
8	
9	
A	
B	
E	
EDG	
EWG	
EXB	
EXF	Non-AHERA
EXM	
EXR	Non-AHERA
F	Sample to determine ACM content prior to disturbance.

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

# **Chicago Public Schools**

**Carnow, Conibear and Associates**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA RE/INSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>3rd Floor Hallway, 304, 3rd Floor Gymnasium, 302, 301, 2nd Floor Hallway, 202, 201, 203, 205, 204, First Floor Hallway, 101, 102, 104, 105, Basement Hallway</b>		
MATERIAL QUANTITY:	<b>120000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **3rd Floor Hallway, 304, 3rd Floor Gymnasium, 302, 301, 2nd Floor Hallway, 202, 201, 203, 205, 204, First Floor Hallway, 101, 102, 104, 105, Basement Hallway**

MATERIAL QUANTITY: **120000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Small Tank Insulation (At Top Of Tank)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **Small Tank Insulation (At Top Of Tank)**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>100</b>		
MATERIAL DESCRIPTION:	<b>Door Caulk</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Throughout</b>		
MATERIAL QUANTITY:	<b>2000</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **Door Caulk**

MATERIAL LOCATION: **Throughout**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 11

MATERIAL DESCRIPTION: 12" x 12" Tan w/ Brown & White Streaks Floor Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Brown & White Streaks Floor Tile**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 12

MATERIAL DESCRIPTION: 12" x 12" Tan w/ Brown & White Streaks Floor Tile Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" Tan w/ Brown & White Streaks Floor Tile Mastic**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement, Hallways, & Stairs-Except 3rd Floor		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **Basement, Hallways, & Stairs-Except 3rd Floor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>15</b>		
MATERIAL DESCRIPTION:	<b>Ceramic Tile Grout</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Teachers' Bathroom</b>		
MATERIAL QUANTITY:	<b>40</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Ceramic Tile Grout**

MATERIAL LOCATION: **Teachers' Bathroom**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	1' x 1' Tan, Gray, White Specks Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Girls & Boys Bathrooms		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **1' x 1' Tan, Gray, White Specks Ceramic Tile Grout**

MATERIAL LOCATION: **2nd Floor Girls & Boys Bathrooms**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Ceramic Wall Tile, Base Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Girls & Boys Bathrooms		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Ceramic Wall Tile, Base Board Adhesive**

MATERIAL LOCATION: **2nd Floor Girls & Boys Bathrooms**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile w/ Gray Streaks		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 104, & Kindergarten, Basement Counslers Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office**

MATERIAL QUANTITY: **1920** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks**

MATERIAL LOCATION: **Rooms 102, 104, & Kindergarten, Basement Counlers Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office**

MATERIAL QUANTITY: **1920** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

#### Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile w/ Gray Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 102, 104, & Kindergarten, Basement Counslers Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office**

MATERIAL QUANTITY: **1920** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile w/ Gray Streaks Mastic**

MATERIAL LOCATION: **Rooms 102, 104, & Kindergarten, Basement Counlers Office, Room 002 Teachers' Assistant Room, Rooms. 001 Basement, 023 Basement Office**

MATERIAL QUANTITY: **1920** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUILDING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	304, 3rd Floor Hallway, 302, 301, 202, 201, 204, 102, 101, 105, 104		
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles**

MATERIAL LOCATION: **304, 3rd Floor Hallway, 302, 301, 202, 201, 204, 102, 101, 105, 104**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>20</b>		
MATERIAL DESCRIPTION:	<b>Multi- Brown Asphalight Tile Grout</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 104 Bathroom</b>		
MATERIAL QUANTITY:	<b>36</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Multi- Brown Asphaltite Tile Grout**

MATERIAL LOCATION: **Room 104 Bathroom**

MATERIAL QUANTITY: **36** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>21</b>		
MATERIAL DESCRIPTION:	<b>Wall Tile Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Room 104 Bathroom</b>		
MATERIAL QUANTITY:	<b>75</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Wall Tile Adhesive**

MATERIAL LOCATION: **Room 104 Bathroom**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **Boiler Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Boiler Insulation**

MATERIAL LOCATION:

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>23</b>		
MATERIAL DESCRIPTION:	<b>Blue/Gray Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Office 023A</b>		
MATERIAL QUANTITY:	<b>250</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Blue/Gray Carpet Mastic**

MATERIAL LOCATION: **Office 023A**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	Incinerator Fire Brick		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	3	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Incinerator Fire Brick**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **3** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>25</b>		
MATERIAL DESCRIPTION:	<b>Yellow &amp; Brown Carpet Mastic, Library in Basement</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Social Room</b>		
MATERIAL QUANTITY:	<b>864</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Yellow & Brown Carpet Mastic, Library in Basement**

MATERIAL LOCATION: **Social Room**

MATERIAL QUANTITY: **864** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	Transite Behind Fire Alarm		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301		
MATERIAL QUANTITY:	1	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **Transite Behind Fire Alarm**

MATERIAL LOCATION: **Room 301**

MATERIAL QUANTITY: **1** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	Insulation Inside Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Entrances & Exits Doors, Boiler Room and Coal Room Doors		
MATERIAL QUANTITY:	126	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Insulation Inside Fire Doors**

MATERIAL LOCATION: **Entrances & Exits Doors, Boiler Room and Coal Room Doors**

MATERIAL QUANTITY: **126** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUILDING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 28

MATERIAL DESCRIPTION: Underlayment & 12" x 12" Floor Tile - Mastic

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Underlayment & 12" x 12" Floor Tile - Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29	
MATERIAL DESCRIPTION:	12" x 12" Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Mens Bathroom

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12" x 12" Floor Tile**

MATERIAL LOCATION: **Mens Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Cinder Block**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **3**

MATERIAL DESCRIPTION: **Cinder Block**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30	
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile**

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31	
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main office

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

If identified, continue O&M.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>32</b>		
MATERIAL DESCRIPTION:	<b>12" x 12" Beige Floor Tile w/ White Streaks</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement Classrooms</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Streaks**

MATERIAL LOCATION: **Basement Classrooms**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUILDING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12" x 12" Beige Floor Tile w/ White Streaks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Classrooms		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12" x 12" Beige Floor Tile w/ White Streaks Mastic**

MATERIAL LOCATION: **Basement Classrooms**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>34</b>		
MATERIAL DESCRIPTION:	<b>Red and Gold Terrazo</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Teachers' Bathroom, Main Office Bathroom</b>		
MATERIAL QUANTITY:	<b>20</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Red and Gold Terrazzo**

MATERIAL LOCATION: **1st Floor Teachers' Bathroom, Main Office Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	Red and Gold Terrazo Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Teachers' Bathroom, Main Office Bathroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Red and Gold Terrazzo Adhesive**

MATERIAL LOCATION: **1st Floor Teachers' Bathroom, Main Office Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>36</b>		
MATERIAL DESCRIPTION:	<b>Metal Pan Ceiling Paper Backing</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>101, 102, 104, 105, 201, 202, 204, 205, 2nd &amp; 3rd Fl. Corr., 3rd Fl. E. Stair Vestibule</b>		
MATERIAL QUANTITY:	<b>18529</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **Metal Pan Ceiling Paper Backing**

MATERIAL LOCATION: **101, 102, 104, 105, 201, 202, 204, 205, 2nd & 3rd Fl. Corr., 3rd Fl. E. Stair Vestibule**

MATERIAL QUANTITY: **18529** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	6" Black Vinyl Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Mens Bathroom		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard**

MATERIAL LOCATION: **1st Floor Mens Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>38</b>		
MATERIAL DESCRIPTION:	<b>6" Black Vinyl Baseboard Adhesive</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>1st Floor Mens Bathroom</b>		
MATERIAL QUANTITY:	<b>20</b>	MATERIAL UNITS:	<b>LF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>LF</b>
COMMENTS:			

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **6" Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **1st Floor Mens Bathroom**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>39</b>		
MATERIAL DESCRIPTION:	<b>Dark Brown w/ Light Brown Carpet Mastic</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>LOW</b>		
MATERIAL LOCATION:	<b>Basement Library</b>		
MATERIAL QUANTITY:	<b>350</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not found in office</b>		

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Dark Brown w/ Light Brown Carpet Mastic**

MATERIAL LOCATION: **Basement Library**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **4**

MATERIAL DESCRIPTION: **Cinder Block Mortar**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	Black Chalk Boards		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	105, 101, 102, 201, 202, 204, 301, 302, 304		
MATERIAL QUANTITY:	2904	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not found in 205		

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **Black Chalk Boards**

MATERIAL LOCATION: **105, 101, 102, 201, 202, 204, 301, 302, 304**

MATERIAL QUANTITY: **2904** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	Wall Sizing Paper		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 301 Behind Ladder Womens Attic		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **Wall Sizing Paper**

MATERIAL LOCATION: **Room 301 Behind Ladder Womens Attic**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	Incinerator Flue Lining		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **Incinerator Flue Lining**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUILDING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	Incinerator Seals and Gaskets		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **Incinerator Seals and Gaskets**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	Fire Escape Fire Doors		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd and 3rd Floor Corridors At Fire Escape Entrances		
MATERIAL QUANTITY:	84	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **Fire Escape Fire Doors**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors At Fire Escape Entrances**

MATERIAL QUANTITY: **84** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.


The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Mens Wash Room		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **1st Floor Mens Wash Room**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45m		
MATERIAL DESCRIPTION:	1' x 1' Tan, Gray, White Specks, Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girls & Boys Basement Bathrooms		
MATERIAL QUANTITY:	1300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **45m**

MATERIAL DESCRIPTION: **1' x 1' Tan, Gray, White Specks, Ceramic Tile Grout**

MATERIAL LOCATION: **Girls & Boys Basement Bathrooms**

MATERIAL QUANTITY: **1300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st Floor Mens Wash Room		
MATERIAL QUANTITY:	15	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **1st Floor Mens Wash Room**

MATERIAL QUANTITY: **15** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	Interior Brick		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Basement		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **Throughout Basement**

MATERIAL QUANTITY: MATERIAL UNITS:


DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Window Caulk**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **Window Caulk**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Insulation Wrap For Water Heater**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **Insulation Wrap For Water Heater**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Small Tank Insulation (Sides)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **Small Tank Insulation (Sides)**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement & Throughout 1st, 2nd & 3rd Floors		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement & Throughout 1st, 2nd & 3rd Floors**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUILDING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation Joints		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement & Throughout 1st, 2nd & 3rd Floors		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation Joints**

MATERIAL LOCATION: **Basement & Throughout 1st, 2nd & 3rd Floors**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**


---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUILDING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Not Tested	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS: **Fiberglass not suspect**

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Facility**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EDG**

MATERIAL DESCRIPTION: **Exterior Door Grout - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **EDG**

MATERIAL DESCRIPTION: **Exterior Door Grout - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EWG**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: \_\_\_\_\_

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: \_\_\_\_\_ MATERIAL UNITS: \_\_\_\_\_

DAMAGE QUANTITY: \_\_\_\_\_ DAMAGE UNITS: \_\_\_\_\_

COMMENTS:

Inspector's Signature: 

Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **EWG**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EXB**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **EXB**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	EXF		
MATERIAL DESCRIPTION:	Exterior Roof Flashing - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **EXF**

MATERIAL DESCRIPTION: **Exterior Roof Flashing - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>Cody Cummins</b>		
SCHOOL NAME:	<b>Plamondon School</b>	INSPECTION DATE:	<b>3/27/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **EXM**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **03/27/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **EXM**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: EXR

MATERIAL DESCRIPTION: Roofing - Non-AHERA

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: Follow O&M Plan

ASBESTOS TYPE: Assumed FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUIDLING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **EXR**

MATERIAL DESCRIPTION: **Roofing - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Hard Joint Compound on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Coal Room Next Womens Boiler Room		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>24981</b>	BUILDING ID:	<b>5450</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Mike Serio</b>		
SCHOOL NAME:	<b>Plamondon School</b>	REVIEW DATE:	<b>4/14/2025</b>		
ADDRESS:	<b>2642 W. 15th Pl.</b>	IDPH LICENSE NO:	<b>100-20994</b>		

---

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Hard Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Coal Room Next Womens Boiler Room**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **04/14/2025**

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	101			
MATERIAL DESCRIPTION:	Tongue & Groove Wood Flooring			
MATERIAL LOCATION:	3rd Floor Hallway, 3rd Floor Gym 303, 301, 302, 304, 201, 202, 203, 204, 205, 101, 102, 104, 105,			
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24981** BUIDLING ID: **5450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Plamondon School** REVIEW DATE: **4/14/2025**

ADDRESS: **2642 W. 15th Pl.** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **Tongue & Groove Wood Flooring**

MATERIAL LOCATION: **3rd Floor Hallway, 3rd Floor Gym 303, 301, 302, 304, 201, 202, 203, 204, 205, 101, 102, 104, 105,**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard		
MATERIAL LOCATION:	023 Office, Hallway to Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24981** BUIDLING ID: **5450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Plamondon School** REVIEW DATE: **4/14/2025**

ADDRESS: **2642 W. 15th Pl.** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard**

MATERIAL LOCATION: **023 Office, Hallway to Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	2' x 2' Pinholed Ceiling Tile		
MATERIAL LOCATION:	023 Office, 023a Office, Hallway to Boiler Room		
MATERIAL QUANTITY:	5000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24981** BUIDLING ID: **5450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Plamondon School** REVIEW DATE: **4/14/2025**

ADDRESS: **2642 W. 15th Pl.** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **2' x 2' Pinholed Ceiling Tile**

MATERIAL LOCATION: **023 Office, 023a Office, Hallway to Boiler Room**

MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	104			
MATERIAL DESCRIPTION:	12" x 12" Blue Gray Mottled Vinyl Floor Tile Mastic			
MATERIAL LOCATION:	Main Office			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24981** BUIDLING ID: **5450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Plamondon School** REVIEW DATE: **4/14/2025**

ADDRESS: **2642 W. 15th Pl.** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **12" x 12" Blue Gray Mottled Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	103			
MATERIAL DESCRIPTION:	12" x 12" Blue Gray Mottled Vinyl Floor Tile			
MATERIAL LOCATION:	Main Office			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24981** BUIDLING ID: **5450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Plamondon School** REVIEW DATE: **4/14/2025**

ADDRESS: **2642 W. 15th Pl.** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **12" x 12" Blue Gray Mottled Vinyl Floor Tile**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	2' x 4' Smooth Ceiling Tile		
MATERIAL LOCATION:	Rooms 203, 205		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

## Carnow, Conibear and Associates 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24981** BUIDLING ID: **5450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Plamondon School** REVIEW DATE: **4/14/2025**

ADDRESS: **2642 W. 15th Pl.** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **2' x 4' Smooth Ceiling Tile**

MATERIAL LOCATION: **Rooms 203, 205**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

# Chicago Public Schools

Carnow, Conibear and Associates

**2025 AHERA REINSPECTION**

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	24981	BUIDLING ID:	5450
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Cody Cummins		
SCHOOL NAME:	Plamondon School	INSPECTION DATE:	3/27/2025		
ADDRESS:	2642 W. 15th Pl.	IDPH LICENSE NO:	100-20994		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	107		
MATERIAL DESCRIPTION:	4" Black Vinyl Baseboard Adhesive		
MATERIAL LOCATION:	023 Office, Hallway to Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
		DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 03/27/2025

# Chicago Public Schools

Carnow, Conibear and Associates  
**2025 AHERA REINSPECTION**

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **24981** BUIDLING ID: **5450**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Plamondon School** REVIEW DATE: **4/14/2025**

ADDRESS: **2642 W. 15th Pl.** IDPH LICENSE NO: **100-20994**

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **4" Black Vinyl Baseboard Adhesive**

MATERIAL LOCATION: **023 Office, Hallway to Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:  Date: 04/14/2025

## APPENDIX B

---

### Inspector and Management Planner Licenses



2200 Vandalia Street, Collinsville, IL 62234 \* Phone: 618-855-8764

## Environmental and Occupational Safety & Health Training

*Does hereby certify*

**Cody Cummins**

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least  
70% for accreditation under AHERA (Title II)*

## **Asbestos Management Planner Initial**



*Class Date:* 10/28-29/2024  
*Examination Date:* 10/29/2024  
*STC Certificate Number:* STC-20241029-000103AMPI  
*Certification Expiration:* 10/29/2025

David M. Mendoza – President/Training Director  
Certified Environmental Specialist  
OSHA Authorized Instructor

*This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources*

# Cody Cummins

## Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



## ENDORSEMENTS

TC EXPIRES

## INSPECTOR

3/8/2025

## AIR SAMPLING PROFESSIONAL

## ENDORSEMENTS

TC EXPIRES

**Alteration of this license shall result in legal action.**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

**Alteration of this license shall result in legal  
This license issued under authority of the State of  
Department of Public Health  
This license is valid only when accompanied by a  
training course certificate.**



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2025

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

## Cody Cummins

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2502280827  
Course Date: 2/28/2025  
Exam Date: 2/28/2025  
Expiration Date: 2/28/2026



  
Tyler Nicholson, Authorized Signer

Issue Date: 2/28/2025

Course Credit Hours: BIR WI 4 Hours



OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

---

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Michael Serio**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

---

Kristina Miczek, Training Manager

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed