

ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2461  
SCHOOL NAME: Solomon School  
ADDRESS OF SCHOOL: 6206 N Hamlin Avenue  
CITY: Chicago, IL, 60645

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 5/13/2022

**If the address on this form is different than the address of the building, submit a written explanation.**

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 2/20/2025 ENROLLMENT 304  
IDPH INSPECTOR LICENSE NUMBER: 100-11093  
IDPH LICENSED INSPECTOR NAME (Please Print): David Avila  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

*Richard J. Schleyer* 3/19/2025

Signature of Designated Person

Date

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Solomon School**

6206 N Hamlin Avenue  
Chicago, IL, 60645

Unit: 25431  
Building ID: 5980

IDPH ID Number: 14-016-2990-2461

**REPORT DATE:**  
Wednesday, March 19, 2025

**Prepared for:**  
**Chicago Public Schools**  
**42 W. Madison Street**  
**Chicago, IL 60602**

**Prepared by:**  
**Specialty Consulting, Inc.**

2942 W. Van Buren Street  
Chicago, IL, 60612  
Phone (312) 319-7575  
Fax (312) 319-7580

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

03/19/2025

Mr. Eric Culbertson  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Specialty Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299      Unit: 25431      Region: 01      IDPH ID: 14-016-2990-2461

School: Solomon School      Building ID: 5980

Address: 6206 N Hamlin Avenue

Chicago, IL, 60645

Building Contact: Erickson, Charles      Contact Phone: 3125049409

Current Building Owners: Chicago Public Schools

Reinspection Date: 2/20/2025

Review Date: 03/19/2025

Inspector: David Avila

Inspector IDPH License: 100-11093

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at (312) 319-7575

Sincerely,  
Specialty Consulting, Inc.



Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: March 19, 2025

RE: Solomon School, Unit 25431  
6206 N Hamlin Avenue  
Chicago, IL, 60645

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Solomon School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Solomon School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J. Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074.

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Solomon School      Unit: 25431      Region: 01  
Address: 6206 N Hamlin Avenue      Chicago, IL, 60645  
IDPH ID: 14-016-2990-2461      Building ID: 5980  
Contact: Erickson, Charles      Phone: 3125049409

### 2. Description of Facility

Original Construction: 1953      Additional Construction: 1956  
Total Square Footage: 18083      No of Floors: 1  
Current Occupancy: 304

### 3. LEA Designated Person

Contact: Richard J.Schleyer      Phone: (773) 251-7074  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: Specialty Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren Street  
Phone: (312) 319-7575      Fax: (312) 319-7580

### 5. Inspector

Inspector Name: David Avila

Inspector IDPH license # 100-11093  
Reinspection Date: 2/20/2025

  
Signature:  
Date: 2/20/2025

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019

  
Signature:  
Date: 03/19/2025

### 7. Review Date: 03/19/2025

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 3/19/2025

Name: Richard J.Schleyer

## **II. EXECUTIVE SUMMARY**

Specialty Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Solomon School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 5980:

B. The following new homogenous areas have been identified for Building 5980:

- 60                    Replacement 12"X12" White w/ Black Specs VFT
- 61                    Replacement 12"X12" White w/ Black Specs Mastic
- 62                    Replacement 12"X12" White w/ Black Specs VFT
- 63                    Replacement 12"X12" White w/ Black Spells Mastic
- 64                    Replacement 12"X12" Gray w/ Specs VFT
- 65                    Replacement 12"X12" Gray Specs w/ Mastic

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

25	Linoleum
25A	Linoleum Mastic
26	12"x12" Tan VFT - NOT OBSERVED
27	12"x12" White VFT
29	12"x12" Brown w/ Beige VFT
31	12"x12" White VFT
32	12"x12" Beige w/ Brown & White Streaks VFT (Over HA 28)
36	12"x12" Brown VFT
37	12"x12" Brown VFT
39	12"x12" White w/ Gray Streaks VFT
39A	12"x12" White w/ Grey Streaks VFT Mastic
40	12"x12" White w/ Beige Streaks VFT
40A	12"x12" White w/ Beige Streaks VFT
41	12"x12" Grey w/ Blue Streaks VFT
41A	12"x12" Grey w/ Blue Streaks VFT Mastic
42	12"x12" Tan VFT
42A	12"x12" Tan VFT Mastic
43	12"x12" White w/ Grey Streaks VFT
43A	12"x12" White w/ Grey Streaks VFT Mastic
44	12" x 12" Light Brown w/white & Dark Streaks VFT
44 A	12" x 12" Light Brown w/white & Dark Streaks VFT Mastic
45	12" x 12" White w/Grey VFT
45 A	12" x 12" White w/Grey VFT Mastic
46	12" x 12" White w/Blue Red & Brn Streaks VFT
46 A	12" x 12" White w/Blue Red & Brn Strks VFT Mastic
47	1' x 1' Ceiling Tiles with Grooves
48	1'x1' Ceiling tile
48A	1'x1' Ceiling tile (MASTIC)
49	12"x12" White w/ gray streaks VFT
49A	12"x12" White w/ gray streaks VFT MASTIC
50	Carpet MASTIC
51	Fire door
52	12"x12" White w/ beige streaks VFT
52A	12"x12" White w/beige streaks VFT MASTIC
53	12"x12" Brown w/ beige streaks VFT
53A	12"x12" Brown w/ beige streaks VFT MASTIC
54	Black Sink Undercoating
54A	White Sink Undercoating

54B	Gray Sink Undercoating
54C	Gray Sink Undercoating
55	12" x 12" Dark blue w/black streaks VFT
55A	12" x 12" Dark blue w/black streaks VFT Mastic
56	12" x 12" Light Blue w/blue streaks VFT
56A	12" x 12" Light Blue w/blue streaks VFT Mastic
57	12" x 12" White w/gray streaks VFT
57A	12" x 12" White w/gray streaks VFT Mastic
58	12" x 12" Tan w/brown & white streaks VFT
58A	12" x 12" Tan w/brown & white streaks VFT Mastic
59	Drywall System: Wallboard, compound, tape
60	Replacement 12"X12" White w/ Black Specs VFT
61	Replacement 12"X12" White w/ Black Specs Mastic
62	Replacement 12"X12" White w/ Black Specs VFT
63	Replacement 12"X12" White w/ Black Spells Mastic
64	Replacement 12"X12" Gray w/ Specs VFT
65	Replacement 12"X12" Gray Specs w/ Mastic
L	Hard Coat Plaster
M	Hard Coat Plaster

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by David Avila, IDPH License # 100-11093. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Solomon School Building 5980 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	12"x12" Blue and Gray VFT	90	SF	Teachers Toilet, Room 107 Closet, 108 Bathroom - 1953 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
02	12"x12" Brown w/ Brown Streaks VFT	300	SF	Rooms 111 (Under New VFT) and 113 - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
08	12"x12" Grey VFT	2,250	SF	Room 115 (Under New VFT), 117, 119 (Under New VFT) - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
10	12"x12" Yellow and White VFT	750	SF	Room 112 (Under New VFT) - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
16	12"x12" Blue and Grey VFT Mastic	60	SF	Teachers Toilet, Room 107 Closet - 1953 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12"x12" Brown w/ Brown Streaks VFT Mastic	1,500	SF	Rooms 111 (Under New VFT) , 113 - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	12"x12" Grey VFT Mastic	2,250	SF	Room 115 (Under New VFT), 117, 119 & Library (Under New VFT) - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
22	12"x12" Yellow and White VFT Mastic	750	SF	Room 112 (Under New VFT) - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	Linoleum	1,800	SF	Rooms 101, 103, 107, 106 countertops - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
25A	Linoleum Mastic	1,825	SF	Rooms 101, 103, 107, 106 Countertops - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12"x12" Tan VFT - NOT OBSERVED	0	SF	Room 103 - 1953 - NOT OBSERVED	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
26A	12"x12" Tan VFT Mastic - NOT OBSERVED	850	SF	Room 103, 107 - 1953 - NOT OBSERVED	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12"x12" White VFT	1,650	SF	Room 108, & 103 - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
27A	12"x12" White VFT Mastic	1,650	SF	Room 108, & 103 - 1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	9"x9" Brown VFT (Under HA 32)	50	SF	Gym Vestibule - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
28A	9"x9" Brown VFT Mastic (Under HA 32)	50	SF	Gym Vestibule - 1956	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## **ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS**

## Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

## ***Inspector's Comments are Summarized at the End of the Report***

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
38A	Linoleum Mastic - Abated			Library - 1956 - Abated	ABATED	MISC								
39	12"x12" White w/ Gray Streaks VFT	2,800	SF	Rooms 100, 101, 102, 104, Teachers Restroom - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
39A	12"x12" White w/ Grey Streaks VFT Mastic	2,800	SF	Rooms 100, 101, 102, 104, Teachers Restroom - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	12"x12" White w/ Beige Streaks VFT	2,500	SF	Room 107, & Corridor - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
40A	12"x12" White w/ Beige Streaks VFT	2,500	SF	Room 107, & Corridor - Observed 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12"x12" Grey w/ Blue Streaks VFT	2,100	SF	Rooms 118, 120, 122 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
41A	12"x12" Grey w/ Blue Streaks VFT Mastic	2,100	SF	Rooms 118, 120, 122 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12"x12" Tan VFT	350	SF	Room 110 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
42A	12"x12" Tan VFT Mastic	350	SF	Room 110 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12"x12" White w/ Grey Streaks VFT	4,000	SF	Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43A	12"x12" White w/ Grey Streaks VFT Mastic	4,000	SF	Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12" x 12" Light Brown w/white & Dark Streaks VFT	1,000	SF	Room 105 + 105A - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44 A	12" x 12" Light Brown w/white & Dark Streaks VFT Mastic	1,000	SF	Room 105 + 105A - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12" x 12" White w/Grey VFT	2,000	SF	Room 106 - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
45 A	12" x 12" White w/Grey VFT Mastic	2,000	SF	Room 106 - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12" x 12" White w/Blue Red & Brn Streaks VFT	800	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
46 A	12" x 12" White w/Blue Red & Brn Strks	800	SF	Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	VFT Mastic											potential for damage		
47	1' x 1' Ceiling Tiles with Grooves	25,000	SF	Throughout - 1956 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
48	1'x1' Ceiling tile	7,500	SF	Throughout 1953 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
48A	1'x1' Ceiling tile (MASTIC)	7,500	SF	Throughout - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	12"x12" White w/ gray streaks VFT	700	SF	Main office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
49A	12"x12" White w/ gray streaks VFT MASTIC	700	SF	Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Carpet MASTIC	200	SF	Principal's office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	Fire door	6	EA		ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
52	12"x12" White w/ beige streaks VFT	4,000	SF	Rooms 103, 110, 107, 121, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
52A	12"x12" White w/beige streaks VFT MASTIC	4,000	SF	Rooms 103, 110, 107, 121, 108	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"x12" Brown w/ beige streaks VFT	1,000	SF	Rooms 107, 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
53A	12"x12" Brown w/ beige streaks VFT MASTIC	1,000	SF	Rooms 107, 121	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	Black Sink Undercoating	100	SF	Rooms 110, 112, 113, 114, 115, 116, 117, 118, 119, 120 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54A	White Sink Undercoating	20	SF	Room 103, 104 - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54B	Gray Sink Undercoating	20	SF	Room 106, 108 - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54C	Gray Sink Undercoating	10	SF	Room 111 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	12" x 12" Dark blue w/black streaks VFT	900	SF	Rooms 103A, 103B, 103C - 1953 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
55A	12" x 12" Dark blue w/black streaks VFT Mastic	900	SF	Rooms 103A, 103B, 103C - 1953 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	12" x 12" Light Blue w/blue streaks VFT	900	SF	Rooms 103A, 103B, 103C - 1953 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
56A	12" x 12" Light Blue w/blue streaks VFT Mastic	900	SF	Rooms 103A, 103B, 103C - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building										
57	12" x 12" White w/gray streaks VFT	900	SF	Rooms 103A, 103B, 103C - 1953 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
57A	12" x 12" White w/gray streaks VFT Mastic	900	SF	Rooms 103A, 103B, 103C - 1953 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12" x 12" Tan w/brown & white streaks VFT	200	SF	Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
58A	12" x 12" Tan w/brown & white streaks VFT Mastic	200	SF	Room 105	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
59	Drywall System: Wallboard, compound, tape	1,500	SF	Rooms 103A, 103B, 103C - 1953 Building	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
60	Replacement 12"X12" White w/ Black Specs VFT	400	SF	Rooms 101, 102, 104 - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
61	Replacement 12"X12" White w/ Black Specs Mastic	400	SF	Rooms 101, 102, 104 - 1953	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	Replacement 12"X12" White w/ Black Specs VFT	40	SF	Room 116 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
63	Replacement 12"X12" White w/ Black Specs Mastic	40	SF	Room 116 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Replacement 12"X12" Gray w/ Specs VFT	12	SF	Room 118 - 1956	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		MODERATE
65	Replacement 12"X12" Gray Specs w/ Mastic	12	SF	118 - 1956	ASSUMED	MISC	N	NONE	0			ACBM with the potential for damage		LOW
A	Aircell Pipe Insulation	600	LF	Pipe Chases - 1953	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
B	Mag Block Pipe Insulation - Abated			Boiler Room - 1953 - Abated	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
C	Cardboard Pipe Insulation	200	LF	Pipe Chases - 1953	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
D	MJP on Aircell Pipe Insulation	30	FITTING	Pipe Chases - 1953	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	MJP on Cardboard Pipe Insulation	25	FITTING	Pipe Chases - 1953	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
G	Boiler Insulation (Abated 2002)			Boiler Room - 1953	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
H	Transite Panels	1,000	SF	Rooms 101, 102, 103, 104, 105, 106, 107, 108 - 1953	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
K	MJP on Fiberglass Pipe Insulation	120	FITTING	Crawlspace - 1953	CHR	TSI	Y	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
L	Hard Coat Plaster	30,000	SF	Throughout - 1953	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
M	Hard Coat Plaster	20,000	SF	Throughout - 1956	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		MODERATE
N	Aircell Pipe Insulation	1,000	LF	Mens Toliet, Womens Toliet, Mens Toliet Chase, Girls Toliet Chase, Boys Toliet, Cust. Locker Room - 1956 building	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	MJP on Aircell Pipe Insulation	100	FITTING	Mens Toilet, Womens Toilet, Mens Toilet Chase, Girls Toilet Chase, Boys Toilet, Cust. Locker Room 1956	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
P	Cardboard Pipe Insulation	30	LF	Girls Toliet Chase, Cust. Locker - 1956	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Q	MJP on Cardboard Pipe Insulation	30	FITTING	Girls Toliet Chase, Cust. Locker Room - 1956	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
R	MJP on Fiberglass Pipe Insulation (Abated 2002)			Crawlspase - 1956	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		

# Chicago Public Schools

School Solomon School Unit 25431 Building ID 5980  
Address 6206 N Hamlin Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date	<u>2/20/2025</u>
Inspector Name	<u>David Avila</u>
<b>100-11093</b>	<b>5/15/2026</b>
Inspector's IDPH License Number / Expiration Date	

#### Inspector's Comments

HA Number:	Inspector Comments:
01	NOT OBSERVED
02	Not Observed possibly under newer VFT
08	Not Observed possibly under newer VFT
10	Not Observed possibly under newer VFT
16	Same as HA 01?
17	Same as HA 02?
20	Same as HA 08
22	Same as HA 10
25	
25A	
26	
26A	
27	Abated in 103
27A	Abated in 103
28	
28A	
29	
29A	
30	
30A	
31	
31A	
32	
32A	

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
33	Abated in 2023
33A	Abated in 2023
35	Not Observed
35A	Not Observed
36	Not Observed
36A	Not Observed
37	Not Observed
37A	
38	
38A	
39	
39A	
40	
40A	
41	
41A	
42	
42A	
43	
43A	
44	
44 A	
45	
45 A	
46	
46 A	
47	
48	
48A	

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

HA Number:	Inspector Comments:
49	
49A	
50	
51	
52	
52A	
53	
53A	
54	
54A	
54B	
54C	
55	
55A	
56	
56A	
57	
57A	
58	
58A	
59	
60	
61	
62	
63	
64	
65	
A	
B	

# Chicago Public Schools

**School** Solomon School **Unit** 25431 **Building ID** 5980  
**Address** 6206 N Hamlin Avenue **Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
C	
D	
E	
G	
H	
K	
L	
M	
N	
O	
P	
Q	
R	

**Table II**  
**Management Planner's Review**

---

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	12"x12" Blue and Gray VFT	90	SF	Teachers Toilet, Room 107 Closet, 108 Bathroom - 1953 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02	12"x12" Brown w/ Brown Streaks VFT	300	SF	Rooms 111 (Under New VFT) and 113 - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	12"x12" Grey VFT	2,250	SF	Room 115 (Under New VFT), 117, 119 (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	12"x12" Yellow and White VFT	750	SF	Room 112 (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12"x12" Blue and Grey VFT Mastic	60	SF	Teachers Toilet, Room 107 Closet - 1953 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12"x12" Brown w/ Brown Streaks VFT Mastic	1,500	SF	Rooms 111 (Under New VFT) , 113 - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	12"x12" Grey VFT Mastic	2,250	SF	Room 115 (Under New VFT), 117, 119 & Library (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12"x12" Yellow and White VFT Mastic	750	SF	Room 112 (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	Linoleum	1,800	SF	Rooms 101, 103, 107, 106 countertops - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25A	Linoleum Mastic	1,825	SF	Rooms 101, 103, 107, 106 Countertops - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12"x12" Tan VFT - NOT OBSERVED	0	SF	Room 103 - 1953 - NOT OBSERVED	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26A	12"x12" Tan VFT Mastic - NOT OBSERVED	850	SF	Room 103, 107 - 1953 - NOT OBSERVED	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" White VFT	1,650	SF	Room 108, & 103 - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27A	12"x12" White VFT Mastic	1,650	SF	Room 108, & 103 - 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	9"x9" Brown VFT (Under HA 32)	50	SF	Gym Vestibule - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28A	9"x9" Brown VFT Mastic (Under HA 32)	50	SF	Gym Vestibule - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" Brown w/ Beige VFT	50	SF	Gym Vestibule - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29A	12"x12" Brown w/ Beige VFT Mastic	50	SF	Gym Vestibule - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12"x12" Tan w/ White Streaks VFT	800	SF	Library (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30A	12"x12" Tan w/ White Streaks VFT Mastic	800	SF	Library (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" White VFT	3,500	SF	Corridor, Eng. Office and Cust. Lockerroom - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31A	12"x12" White VFT Mastic	3,500	SF	Corridor, Eng. Office and Cust. Lockerroom - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Beige w/ Brown & White Streaks VFT (Over HA 28)	50	SF	Gym Vestibule - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32A	12"x12" Beige w/ Brown & White Streaks VFT	50	SF	Gym Vestibule - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
	Mastic (Over HA 28)										
33	12"x12" Beige w/ Red Streaks VFT (under carpet) - Abated			Main Office and Restroom (Under Carpet) - 1956 - Abated	Abated	MISC					
33A	12"x12" Beige w/ Red Streaks VFT Mastic UNDER CARPET - Abated			Main Office and Restroom - 1956 - Abated	Abated	MISC					
35	12"x12" Grey w/ Black, White, & Orange Streaks VFT	1,500	SF	Room 114, 116 (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
35A	12"x12" Grey w/ Blk, Wht & Orange Stks VFT Mastic	1,500	SF	Room 114, 116 (Under New VFT) - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12"x12" Brown VFT	2,500	SF	1st Floor Corridor, Room 108 Toilet - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36A	12"x12" Brown VFT Mastic	2,500	SF	Corridor, Room 108 Toilet - 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	12"x12" Brown VFT	1,500	SF	Corridor - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37A	12"x12" Brown VFT Mastic	3,500	SF	Corridor, Rooms 110, 121, Eng. Office & Cust. Locker Room - 1956	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	Linoleum - Abated			Library - 1956 - Abated	Abated	MISC					
38A	Linoleum Mastic - Abated			Library - 1956 - Abated	Abated	MISC					
39	12"x12" White w/ Gray Streaks VFT	2,800	SF	Rooms 100, 101, 102, 104, Teachers Restroom - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39A	12"x12" White w/ Grey Streaks VFT Mastic	2,800	SF	Rooms 100, 101, 102, 104, Teachers Restroom - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12"x12" White w/ Beige Streaks VFT	2,500	SF	Room 107, & Corridor - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40A	12"x12" White w/ Beige Streaks VFT	2,500	SF	Room 107, & Corridor - Observed 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12"x12" Grey w/ Blue Streaks VFT	2,100	SF	Rooms 118, 120, 122 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41A	12"x12" Grey w/ Blue Streaks VFT Mastic	2,100	SF	Rooms 118, 120, 122 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12"x12" Tan VFT	350	SF	Room 110 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42A	12"x12" Tan VFT Mastic	350	SF	Room 110 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12"x12" White w/ Grey Streaks VFT	4,000	SF	Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43A	12"x12" White w/ Grey Streaks VFT Mastic	4,000	SF	Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12" x 12" Light Brown w/white & Dark Streaks VFT	1,000	SF	Room 105 + 105A - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44 A	12" x 12" Light Brown w/white & Dark Streaks VFT Mastic	1,000	SF	Room 105 + 105A - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
45	12" x 12" White w/Grey VFT	2,000	SF	Room 106 - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45 A	12" x 12" White w/Grey VFT Mastic	2,000	SF	Room 106 - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12" x 12" White w/Blue Red & Brn Streaks VFT	800	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46 A	12" x 12" White w/Blue Red & Brn Strks VFT Mastic	800	SF	Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	1' x 1' Ceiling Tiles with Grooves	25,000	SF	Throughout - 1956 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	1'x1' Ceiling tile	7,500	SF	Throughout 1953 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48A	1'x1' Ceiling tile (MASTIC)	7,500	SF	Throughout - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	12"x12" White w/ gray streaks VFT	700	SF	Main office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49A	12"x12" White w/ gray streaks VFT MASTIC	700	SF	Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Carpet MASTIC	200	SF	Principal's office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	Fire door	6	EA		Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" White w/ beige streaks VFT	4,000	SF	Rooms 103, 110, 107, 121, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52A	12"x12" White w/beige streaks VFT MASTIC	4,000	SF	Rooms 103, 110, 107, 121, 108	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" Brown w/ beige streaks VFT	1,000	SF	Rooms 107, 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53A	12"x12" Brown w/ beige streaks VFT MASTIC	1,000	SF	Rooms 107, 121	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	Black Sink Undercoating	100	SF	Rooms 110, 112, 113, 114, 115, 116, 117, 118, 119, 120 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54A	White Sink Undercoating	20	SF	Room 103, 104 - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54B	Gray Sink Undercoating	20	SF	Room 106, 108 - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54C	Gray Sink Undercoating	10	SF	Room 111 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Dark blue w/black streaks VFT	900	SF	Rooms 103A, 103B, 103C - 1953 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
55A	12" x 12" Dark blue w/black streaks VFT Mastic	900	SF	Rooms 103A, 103B, 103C - 1953 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" Light Blue w/blue streaks VFT	900	SF	Rooms 103A, 103B, 103C - 1953 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
56A	12" x 12" Light Blue w/blue streaks VFT Mastic	900	SF	Rooms 103A, 103B, 103C - 1953 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" White w/gray streaks VFT	900	SF	Rooms 103A, 103B, 103C - 1953 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57A	12" x 12" White w/gray streaks VFT Mastic	900	SF	Rooms 103A, 103B, 103C - 1953 Building	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58	12" x 12" Tan w/brown & white streaks VFT	200	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
58A	12" x 12" Tan w/brown & white streaks VFT Mastic	200	SF	Room 105	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	Drywall System: Wallboard, compound, tape	1,500	SF	Rooms 103A, 103B, 103C - 1953	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575 Fax: (312) 319-7580

### Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Building							
60	Replacement 12"X12" White w/ Black Specs VFT	400	SF	Rooms 101, 102, 104 - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	Replacement 12"X12" White w/ Black Specs Mastic	400	SF	Rooms 101, 102, 104 - 1953	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	Replacement 12"X12" White w/ Black Specs VFT	40	SF	Room 116 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	Replacement 12"X12" White w/ Black Spells Mastic	40	SF	Room 116 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	Replacement 12"X12" Gray w/ Specs VFT	12	SF	Room 118 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Replacement 12"X12" Gray Specs w/ Mastic	12	SF	118 - 1956	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Aircell Pipe Insulation	600	LF	Pipe Chases - 1953	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
B	Mag Block Pipe Insulation - Abated			Boiler Room - 1953 - Abated	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	
C	Cardboard Pipe Insulation	200	LF	Pipe Chases - 1953	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP on Aircell Pipe Insulation	30	FITTING	Pipe Chases - 1953	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
E	MJP on Cardboard Pipe Insulation	25	FITTING	Pipe Chases - 1953	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
G	Boiler Insulation (Abated 2002)			Boiler Room - 1953	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	
H	Transite Panels	1,000	SF	Rooms 101, 102, 103, 104, 105, 106, 107, 108 - 1953	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
K	MJP on Fiberglass Pipe Insulation	120	FITTING	Crawlspace - 1953	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
L	Hard Coat Plaster	30,000	SF	Throughout - 1953	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Hard Coat Plaster	20,000	SF	Throughout - 1956	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
N	Aircell Pipe Insulation	1,000	LF	Mens Toliet, Womens Toliet, Mens Toliet Chase, Girls Toliet Chase, Boys Toliet, Cust. Locker Room - 1956 building	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
O	MJP on Aircell Pipe Insulation	100	FITTING	Mens Toilet, Womens Toilet, Mens Toilet Chase, Girls Toilet Chase, Boys Toilet, Cust Locker Room 1956	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
P	Cardboard Pipe Insulation	30	LF	Girls Toliet Chase, Cust. Locker - 1956	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q	MJP on Cardboard Pipe Insulation	30	FITTING	Girls Toliet Chase, Cust. Locker Room - 1956	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
R	MJP on Fiberglass Pipe Insulation (Abated 2002)			Crawlspace - 1956	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

*Management Planner's Comments Summarized at the End of the Report*

Review Date	3/19/2025
Manager Planner Name	Arturo Saenz
100-04019	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
08	
10	
16	
17	
20	
22	
25	

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
25A	
26	
26A	
27	
27A	
28	
28A	
29	
29A	
30	
30A	
31	
31A	
32	
32A	
33	
33A	
35	
35A	
36	
36A	
37	
37A	
38	
38A	
39	
39A	

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
40	
40A	
41	
41A	
42	
42A	
43	
43A	
44	
44 A	
45	
45 A	
46	
46 A	
47	
48	
48A	
49	
49A	
50	
51	
52	
52A	
53	
53A	
54	
54A	

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
54B	
54C	
55	
55A	
56	
56A	
57	
57A	
58	
58A	
59	
60	
61	
62	
63	
64	
65	
A	
B	
C	
D	
E	
G	
H	
K	
L	
M	

# Chicago Public Schools

**School** Solomon School

**Unit** 25431

**Building ID** 5980

**Address** 6206 N Hamlin Avenue

Chicago, IL, 60645

**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** Specialty Consulting, Inc.

2942 W. Van Buren Street

Phone: (312) 319-7575

Fax: (312) 319-7580

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
N	
O	
P	
Q	
R	

## APPENDIX A

---

### Assessment Sheets, Drawings and Photos

**Chicago Public Schools**

**Specialty Consulting, Inc.**

***2025 AHERA REINSPECTION***

# Chicago Public Schools

Specialty Consulting, Inc.

2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUILDING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	01		
MATERIAL DESCRIPTION:	12"x12" Blue and Gray VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Teachers Toilet, Room 107 Closet, 108 Bathroom - 1953 Bldg.		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>NOT OBSERVED</b>		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **01**

MATERIAL DESCRIPTION: **12"x12" Blue and Gray VFT**

MATERIAL LOCATION: **Teachers Toilet, Room 107 Closet, 108 Bathroom - 1953 Bldg.**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Brown Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 111 (Under New VFT) and 113 - 1956		
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed possibly under newer VFT		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **02**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Brown Streaks VFT**

MATERIAL LOCATION: **Rooms 111 (Under New VFT) and 113 - 1956**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	12"x12" Grey VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 115 (Under New VFT), 117, 119 (Under New VFT) - 1956		
MATERIAL QUANTITY:	2250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	<b>Not Observed possibly under newer VFT</b>		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **12"x12" Grey VFT**

MATERIAL LOCATION: **Room 115 (Under New VFT), 117, 119 (Under New VFT) - 1956**

MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUILDING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	12"x12" Yellow and White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 112 (Under New VFT) - 1956		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed possibly under newer VFT		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **12"x12" Yellow and White VFT**

MATERIAL LOCATION: **Room 112 (Under New VFT) - 1956**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	12"x12" Blue and Grey VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Teachers Toilet, Room 107 Closet - 1953 Bldg.		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Same as HA 01?		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **12"x12" Blue and Grey VFT Mastic**

MATERIAL LOCATION: **Teachers Toilet, Room 107 Closet - 1953 Bldg.**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Brown Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 111 (Under New VFT) , 113 - 1956		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Same as HA 02?		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Brown Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 111 (Under New VFT) , 113 - 1956**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	12"x12" Grey VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 115 (Under New VFT), 117, 119 & Library (Under New VFT) - 1956		
MATERIAL QUANTITY:	2250	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Same as HA 08		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **12"x12" Grey VFT Mastic**

MATERIAL LOCATION: **Room 115 (Under New VFT), 117, 119 & Library (Under New VFT) - 1956**

MATERIAL QUANTITY: **2250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	22		
MATERIAL DESCRIPTION:	12"x12" Yellow and White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 112 (Under New VFT) - 1956		
MATERIAL QUANTITY:	750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Same as HA 10		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12"x12" Yellow and White VFT Mastic**

MATERIAL LOCATION: **Room 112 (Under New VFT) - 1956**

MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 101, 103, 107, 106 countertops - 1953		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Linoleum**

MATERIAL LOCATION: **Rooms 101, 103, 107, 106 countertops - 1953**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25A		
MATERIAL DESCRIPTION:	Linoleum Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101, 103, 107, 106 Countertops - 1953		
MATERIAL QUANTITY:	1825	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **25A**

MATERIAL DESCRIPTION: **Linoleum Mastic**

MATERIAL LOCATION: **Rooms 101, 103, 107, 106 Countertops - 1953**

MATERIAL QUANTITY: **1825** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUILDING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	12"x12" Tan VFT - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 103 - 1953 - NOT OBSERVED		
MATERIAL QUANTITY:	0	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **12"x12" Tan VFT - NOT OBSERVED**

MATERIAL LOCATION: **Room 103 - 1953 - NOT OBSERVED**

MATERIAL QUANTITY: **0** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26A		
MATERIAL DESCRIPTION:	12"x12" Tan VFT Mastic - NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103, 107 - 1953 - NOT OBSERVED		
MATERIAL QUANTITY:	850	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **26A**

MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic - NOT OBSERVED**

MATERIAL LOCATION: **Room 103, 107 - 1953 - NOT OBSERVED**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12"x12" White VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 108, & 103 - 1953		
MATERIAL QUANTITY:	1650	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	Abated in 103		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" White VFT**

MATERIAL LOCATION: **Room 108, & 103 - 1953**

MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27A		
MATERIAL DESCRIPTION:	12"x12" White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 108, & 103 - 1953		
MATERIAL QUANTITY:	1650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Abated in 103		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **27A**

MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**

MATERIAL LOCATION: **Room 108, & 103 - 1953**

MATERIAL QUANTITY: **1650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	9"x9" Brown VFT (Under HA 32)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Gym Vestibule - 1956</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **9"x9" Brown VFT (Under HA 32)**

MATERIAL LOCATION: **Gym Vestibule - 1956**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28A		
MATERIAL DESCRIPTION:	9"x9" Brown VFT Mastic (Under HA 32)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Vestibule - 1956		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **28A**

MATERIAL DESCRIPTION: **9"x9" Brown VFT Mastic (Under HA 32)**

MATERIAL LOCATION: **Gym Vestibule - 1956**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Beige VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Gym Vestibule - 1956</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Beige VFT**

MATERIAL LOCATION: **Gym Vestibule - 1956**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29A		
MATERIAL DESCRIPTION:	12"x12" Brown w/ Beige VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Vestibule - 1956		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **29A**

MATERIAL DESCRIPTION: **12"x12" Brown w/ Beige VFT Mastic**

MATERIAL LOCATION: **Gym Vestibule - 1956**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12"x12" Tan w/ White Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Library (Under New VFT) - 1956		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT**

MATERIAL LOCATION: **Library (Under New VFT) - 1956**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30A		
MATERIAL DESCRIPTION:	12"x12" Tan w/ White Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library (Under New VFT) - 1956		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **30A**

MATERIAL DESCRIPTION: **12"x12" Tan w/ White Streaks VFT Mastic**

MATERIAL LOCATION: **Library (Under New VFT) - 1956**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	AHERA INSPECTOR:	<b>David Avila</b>		
SCHOOL NAME:	<b>Solomon School</b>	INSPECTION DATE:	<b>2/20/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	<b>31</b>		
MATERIAL DESCRIPTION:	<b>12"x12" White VFT</b>		
HISTORICAL AHERA DAMAGE CATEGORY	<b>6 ACBM with the potential for damage</b>		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	<b>Follow O&amp;M Plan</b>		
ASBESTOS TYPE:	<b>Assumed</b>	FRIABLE:	<b>No</b>

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Corridor, Eng. Office and Cust. Lockerroom - 1956</b>		
MATERIAL QUANTITY:	<b>3500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12"x12" White VFT**

MATERIAL LOCATION: **Corridor, Eng. Office and Cust. Lockerroom - 1956**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31A		
MATERIAL DESCRIPTION:	12"x12" White VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor, Eng. Office and Cust. Lockerroom - 1956		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **31A**

MATERIAL DESCRIPTION: **12"x12" White VFT Mastic**

MATERIAL LOCATION: **Corridor, Eng. Office and Cust. Lockerroom - 1956**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Streaks VFT (Over HA 28)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Gym Vestibule - 1956</b>		
MATERIAL QUANTITY:	<b>50</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Streaks VFT (Over HA 28)**

MATERIAL LOCATION: **Gym Vestibule - 1956**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUILDING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32A		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Brown & White Streaks VFT Mastic (Over HA 28)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gym Vestibule - 1956		
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **32A**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Brown & White Streaks VFT Mastic (Over HA 28)**

MATERIAL LOCATION: **Gym Vestibule - 1956**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Red Streaks VFT (under carpet) - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office and Restroom (Under Carpet) - 1956 - Abated

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated in 2023

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Red Streaks VFT (under carpet) - Abated**

MATERIAL LOCATION: **Main Office and Restroom (Under Carpet) - 1956 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33A		
MATERIAL DESCRIPTION:	12"x12" Beige w/ Red Streaks VFT Mastic UNDER CARPET - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Main Office and Restroom - 1956 - Abated

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Abated in 2023

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **33A**

MATERIAL DESCRIPTION: **12"x12" Beige w/ Red Streaks VFT Mastic UNDER CARPET - Abated**

MATERIAL LOCATION: **Main Office and Restroom - 1956 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	12"x12" Grey w/ Black, White, & Orange Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 114, 116 (Under New VFT) - 1956		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed</b>		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **12"x12" Grey w/ Black, White, & Orange Streaks VFT**

MATERIAL LOCATION: **Room 114, 116 (Under New VFT) - 1956**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35A		
MATERIAL DESCRIPTION:	12"x12" Grey w/ Blk, Wht & Orange Stks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114, 116 (Under New VFT) - 1956		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **35A**

MATERIAL DESCRIPTION: **12"x12" Grey w/ Blk, Wht & Orange Stks VFT Mastic**

MATERIAL LOCATION: **Room 114, 116 (Under New VFT) - 1956**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12"x12" Brown VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	1st Floor Corridor, Room 108 Toilet - 1953		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12"x12" Brown VFT**

MATERIAL LOCATION: **1st Floor Corridor, Room 108 Toilet - 1953**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36A		
MATERIAL DESCRIPTION:	12"x12" Brown VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor, Room 108 Toilet - 1953		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed		

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **36A**

MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic**

MATERIAL LOCATION: **Corridor, Room 108 Toilet - 1953**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	12"x12" Brown VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Corridor - 1956</b>		
MATERIAL QUANTITY:	<b>1500</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:	<b>Not Observed</b>		

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **12"x12" Brown VFT**

MATERIAL LOCATION: **Corridor - 1956**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37A		
MATERIAL DESCRIPTION:	12"x12" Brown VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Corridor, Rooms 110, 121, Eng. Office & Cust. Locker Room - 1956		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **37A**

MATERIAL DESCRIPTION: **12"x12" Brown VFT Mastic**

MATERIAL LOCATION: **Corridor, Rooms 110, 121, Eng. Office & Cust. Locker Room - 1956**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUILDING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	Linoleum - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library - 1956 - Abated

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **Linoleum - Abated**

MATERIAL LOCATION: **Library - 1956 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUILDING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38A		
MATERIAL DESCRIPTION:	Linoleum Mastic - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Library - 1956 - Abated

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **38A**

MATERIAL DESCRIPTION: **Linoleum Mastic - Abated**

MATERIAL LOCATION: **Library - 1956 - Abated**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	12"x12" White w/ Gray Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 100, 101, 102, 104, Teachers Restroom - 1953		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **12"x12" White w/ Gray Streaks VFT**

MATERIAL LOCATION: **Rooms 100, 101, 102, 104, Teachers Restroom - 1953**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39A		
MATERIAL DESCRIPTION:	12"x12" White w/ Grey Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 100, 101, 102, 104, Teachers Restroom - 1953		
MATERIAL QUANTITY:	2800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **39A**

MATERIAL DESCRIPTION: **12"x12" White w/ Grey Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 100, 101, 102, 104, Teachers Restroom - 1953**

MATERIAL QUANTITY: **2800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUILDING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	12"x12" White w/ Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 107, & Corridor - 1953		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT**

MATERIAL LOCATION: **Room 107, & Corridor - 1953**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40A		
MATERIAL DESCRIPTION:	12"x12" White w/ Beige Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 107, & Corridor - Observed 1953		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **40A**

MATERIAL DESCRIPTION: **12"x12" White w/ Beige Streaks VFT**

MATERIAL LOCATION: **Room 107, & Corridor - Observed 1953**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	12"x12" Grey w/ Blue Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Rooms 118, 120, 122 - 1956</b>		
MATERIAL QUANTITY:	<b>2100</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **12"x12" Grey w/ Blue Streaks VFT**

MATERIAL LOCATION: **Rooms 118, 120, 122 - 1956**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41A		
MATERIAL DESCRIPTION:	12"x12" Grey w/ Blue Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 118, 120, 122 - 1956		
MATERIAL QUANTITY:	2100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **41A**

MATERIAL DESCRIPTION: **12"x12" Grey w/ Blue Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 118, 120, 122 - 1956**

MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42		
MATERIAL DESCRIPTION:	12"x12" Tan VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Room 110 - 1956		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12"x12" Tan VFT**

MATERIAL LOCATION: **Room 110 - 1956**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	42A		
MATERIAL DESCRIPTION:	12"x12" Tan VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 110 - 1956		
MATERIAL QUANTITY:	350	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **42A**

MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**

MATERIAL LOCATION: **Room 110 - 1956**

MATERIAL QUANTITY: **350** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12"x12" White w/ Grey Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12"x12" White w/ Grey Streaks VFT**

MATERIAL LOCATION: **Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43A		
MATERIAL DESCRIPTION:	12"x12" White w/ Grey Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **43A**

MATERIAL DESCRIPTION: **12"x12" White w/ Grey Streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 111, 112, 113, 114, 115, 116, 117, 119, Principal Office (over ha's 2, 10, 35, 8, 33) & Main Office - 1956**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

#### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/white & Dark Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105 + 105A - 1953		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/white & Dark Streaks VFT**

MATERIAL LOCATION: **Room 105 + 105A - 1953**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44 A		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/white & Dark Streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105 + 105A - 1953		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **44 A**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/white & Dark Streaks VFT Mastic**

MATERIAL LOCATION: **Room 105 + 105A - 1953**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	12" x 12" White w/Grey VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Room 106 - 1953		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **12" x 12" White w/Grey VFT**

MATERIAL LOCATION: **Room 106 - 1953**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45 A		
MATERIAL DESCRIPTION:	12" x 12" White w/Grey VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106 - 1953		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **45 A**

MATERIAL DESCRIPTION: **12" x 12" White w/Grey VFT Mastic**

MATERIAL LOCATION: **Room 106 - 1953**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	12" x 12" White w/Blue Red & Brn Streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Library</b>		
MATERIAL QUANTITY:	<b>800</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Red & Brn Streaks VFT**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46 A		
MATERIAL DESCRIPTION:	12" x 12" White w/Blue Red & Brn Strks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Library		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **46 A**

MATERIAL DESCRIPTION: **12" x 12" White w/Blue Red & Brn Strks VFT Mastic**

MATERIAL LOCATION: **Library**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	1' x 1' Ceiling Tiles with Grooves		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1956 Bldg.		
MATERIAL QUANTITY:	25000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **1' x 1' Ceiling Tiles with Grooves**

MATERIAL LOCATION: **Throughout - 1956 Bldg.**

MATERIAL QUANTITY: **25000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	1'x1' Ceiling tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout 1953 Bldg.		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **1'x1' Ceiling tile**

MATERIAL LOCATION: **Throughout 1953 Bldg.**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48A		
MATERIAL DESCRIPTION:	1'x1' Ceiling tile (MASTIC)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout - 1953		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **48A**

MATERIAL DESCRIPTION: **1'x1' Ceiling tile (MASTIC)**

MATERIAL LOCATION: **Throughout - 1953**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12"x12" White w/ gray streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Main office</b>		
MATERIAL QUANTITY:	<b>700</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12"x12" White w/ gray streaks VFT**

MATERIAL LOCATION: **Main office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49A		
MATERIAL DESCRIPTION:	12"x12" White w/ gray streaks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **49A**

MATERIAL DESCRIPTION: **12"x12" White w/ gray streaks VFT MASTIC**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	Carpet MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's office		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **Carpet MASTIC**

MATERIAL LOCATION: **Principal's office**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	Fire door		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION:

MATERIAL QUANTITY: **6** MATERIAL UNITS: **EA**

DAMAGE QUANTITY: DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **Fire door**

MATERIAL LOCATION:

MATERIAL QUANTITY:	<b>6</b>	MATERIAL UNITS:	<b>EA</b>
--------------------	----------	-----------------	-----------

DAMAGE QUANTITY:	<b>0</b>	DAMAGE UNITS:	<b>EA</b>
------------------	----------	---------------	-----------

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12"x12" White w/ beige streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 103, 110, 107, 121, 108		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12"x12" White w/ beige streaks VFT**

MATERIAL LOCATION: **Rooms 103, 110, 107, 121, 108**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52A		
MATERIAL DESCRIPTION:	12"x12" White w/beige streaks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103, 110, 107, 121, 108		
MATERIAL QUANTITY:	4000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **52A**

MATERIAL DESCRIPTION: **12"x12" White w/beige streaks VFT MASTIC**

MATERIAL LOCATION: **Rooms 103, 110, 107, 121, 108**

MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53		
MATERIAL DESCRIPTION:	12"x12" Brown w/ beige streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Rooms 107, 121</b>		
MATERIAL QUANTITY:	<b>1000</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **12"x12" Brown w/ beige streaks VFT**

MATERIAL LOCATION: **Rooms 107, 121**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	53A		
MATERIAL DESCRIPTION:	12"x12" Brown w/ beige streaks VFT MASTIC		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 107, 121		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **53A**

MATERIAL DESCRIPTION: **12"x12" Brown w/ beige streaks VFT MASTIC**

MATERIAL LOCATION: **Rooms 107, 121**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	Black Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 110, 112, 113, 114, 115, 116, 117, 118, 119, 120 - 1956		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **Black Sink Undercoating**

MATERIAL LOCATION: **Rooms 110, 112, 113, 114, 115, 116, 117, 118, 119, 120 - 1956**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54A		
MATERIAL DESCRIPTION:	White Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103, 104 - 1953		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **54A**

MATERIAL DESCRIPTION: **White Sink Undercoating**

MATERIAL LOCATION: **Room 103, 104 - 1953**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54B		
MATERIAL DESCRIPTION:	Gray Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 106, 108 - 1953		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **54B**

MATERIAL DESCRIPTION: **Gray Sink Undercoating**

MATERIAL LOCATION: **Room 106, 108 - 1953**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54C		
MATERIAL DESCRIPTION:	Gray Sink Undercoating		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111 - 1956		
MATERIAL QUANTITY:	10	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **54C**

MATERIAL DESCRIPTION: **Gray Sink Undercoating**

MATERIAL LOCATION: **Room 111 - 1956**

MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12" x 12" Dark blue w/black streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 103A, 103B, 103C - 1953 Building		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12" x 12" Dark blue w/black streaks VFT**

MATERIAL LOCATION: **Rooms 103A, 103B, 103C - 1953 Building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55A		
MATERIAL DESCRIPTION:	12" x 12" Dark blue w/black streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103A, 103B, 103C - 1953 Building		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **55A**

MATERIAL DESCRIPTION: **12" x 12" Dark blue w/black streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 103A, 103B, 103C - 1953 Building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/blue streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 103A, 103B, 103C - 1953 Building		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/blue streaks VFT**

MATERIAL LOCATION: **Rooms 103A, 103B, 103C - 1953 Building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56A		
MATERIAL DESCRIPTION:	12" x 12" Light Blue w/blue streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103A, 103B, 103C - 1953 Building		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **56A**

MATERIAL DESCRIPTION: **12" x 12" Light Blue w/blue streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 103A, 103B, 103C - 1953 Building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	12" x 12" White w/gray streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Rooms 103A, 103B, 103C - 1953 Building		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" White w/gray streaks VFT**

MATERIAL LOCATION: **Rooms 103A, 103B, 103C - 1953 Building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57A		
MATERIAL DESCRIPTION:	12" x 12" White w/gray streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 103A, 103B, 103C - 1953 Building		
MATERIAL QUANTITY:	900	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **57A**

MATERIAL DESCRIPTION: **12" x 12" White w/gray streaks VFT Mastic**

MATERIAL LOCATION: **Rooms 103A, 103B, 103C - 1953 Building**

MATERIAL QUANTITY: **900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	12" x 12" Tan w/brown & white streaks VFT		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	<b>Room 105</b>		
MATERIAL QUANTITY:	<b>200</b>	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **12" x 12" Tan w/brown & white streaks VFT**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58A		
MATERIAL DESCRIPTION:	12" x 12" Tan w/brown & white streaks VFT Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 105		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **58A**

MATERIAL DESCRIPTION: **12" x 12" Tan w/brown & white streaks VFT Mastic**

MATERIAL LOCATION: **Room 105**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	Drywall System: Wallboard, compound, tape		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	<b>MODERATE</b>		
MATERIAL LOCATION:	Rooms 103A, 103B, 103C - 1953 Building		
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	<b>SF</b>
DAMAGE QUANTITY:		DAMAGE UNITS:	<b>SF</b>
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **Drywall System: Wallboard, compound, tape**

MATERIAL LOCATION: **Rooms 103A, 103B, 103C - 1953 Building**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases - 1953		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases - 1953**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	B		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation - Abated		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room - 1953 - Abated

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

## Specialty Consulting, Inc. 2025 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation - Abated**

MATERIAL LOCATION: **Boiler Room - 1953 - Abated**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases - 1953		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases - 1953**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	MJP on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases - 1953		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases - 1953**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	MJP on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Pipe Chases - 1953		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Pipe Chases - 1953**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	G		
MATERIAL DESCRIPTION:	Boiler Insulation (Abated 2002)		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Boiler Room - 1953

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Boiler Insulation (Abated 2002)**

MATERIAL LOCATION: **Boiler Room - 1953**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	H		
MATERIAL DESCRIPTION:	Transite Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101, 102, 103, 104, 105, 106, 107, 108 - 1953		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Transite Panels**

MATERIAL LOCATION: **Rooms 101, 102, 103, 104, 105, 106, 107, 108 - 1953**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Crawlspace - 1953		
MATERIAL QUANTITY:	120	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Crawlspace - 1953**

MATERIAL QUANTITY: **120** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout - 1953		
MATERIAL QUANTITY:	30000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1953**

MATERIAL QUANTITY: **30000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Hard Coat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Throughout - 1956		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Hard Coat Plaster**

MATERIAL LOCATION: **Throughout - 1956**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage Vandalism		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Mens Toliet, Womens Toliet, Mens Toliet Chase, Girls Toliet Chase, Boys Toliet, Cust. Locker Room - 1956 building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Mens Toliet, Womens Toliet, Mens Toliet Chase, Girls Toliet Chase, Boys Toliet, Cust. Locker Room - 1956 building**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	MJP on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage Vandalism		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Mens Toilet, Womens Toilet, Mens Toilet Chase, Girls Toilet Chase, Boys Toilet, Cust Locker Room 1956**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: MATERIAL UNITS: **FITTING**

COMMENTS:

Inspector's Signature:



Date: **02/20/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**

MATERIAL LOCATION: **Mens Toilet, Womens Toilet, Mens Toilet Chase, Girls Toilet Chase, Boys Toilet, Cust Locker Room 1956**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girls Toliet Chase, Cust. Locker - 1956		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUILDING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Girls Toliet Chase, Cust. Locker - 1956**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Q		
MATERIAL DESCRIPTION:	MJP on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Girls Toliet Chase, Cust. Locker Room - 1956		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	FITTING
DAMAGE QUANTITY:		DAMAGE UNITS:	FITTING
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Girls Toliet Chase, Cust. Locker Room - 1956**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

### **Follow O&M Plan**

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	MJP on Fiberglass Pipe Insulation (Abated 2002)		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Crawlspace - 1956

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME:	<b>Chicago Public Schools</b>	UNIT NUMBER:	<b>25431</b>	BUIDLING ID:	<b>5980</b>
CITY/STATE:	<b>Chicago, Illinois</b>	MANAGEMENT PLANNER:	<b>Arturo Saenz</b>		
SCHOOL NAME:	<b>Solomon School</b>	REVIEW DATE:	<b>3/19/2025</b>		
ADDRESS:	<b>6206 N Hamlin Avenue</b>	IDPH LICENSE NO:	<b>100-11093</b>		

---

HOMOGENEOUS AREA: **R**

MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation (Abated 2002)**

MATERIAL LOCATION: **Crawlspace - 1956**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	Replacement 12"X12" Gray Specs w/ Mastic		
MATERIAL LOCATION:	118 - 1956		
MATERIAL QUANTITY:	12	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25431** BUIDLING ID: **5980**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Solomon School** REVIEW DATE: **3/19/2025**

ADDRESS: **6206 N Hamlin Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **Replacement 12"X12" Gray Specs w/ Mastic**

MATERIAL LOCATION: **118 - 1956**

MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	61				
MATERIAL DESCRIPTION:	Replacement 12"X12" White w/ Black Specs Mastic				
MATERIAL LOCATION:	Rooms 101, 102, 104 - 1953				
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25431** BUIDLING ID: **5980**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Solomon School** REVIEW DATE: **3/19/2025**

ADDRESS: **6206 N Hamlin Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **Replacement 12"X12" White w/ Black Specs Mastic**

MATERIAL LOCATION: **Rooms 101, 102, 104 - 1953**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	63				
MATERIAL DESCRIPTION:	Replacement 12"X12" White w/ Black Spells Mastic				
MATERIAL LOCATION:	Room 116 - 1956				
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25431** BUIDLING ID: **5980**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Solomon School** REVIEW DATE: **3/19/2025**

ADDRESS: **6206 N Hamlin Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **Replacement 12"X12" White w/ Black Spells Mastic**

MATERIAL LOCATION: **Room 116 - 1956**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	64				
MATERIAL DESCRIPTION:	Replacement 12"X12" Gray w/ Specs VFT				
MATERIAL LOCATION:	Room 118 - 1956				
MATERIAL QUANTITY:	12	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25431** BUIDLING ID: **5980**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Solomon School** REVIEW DATE: **3/19/2025**

ADDRESS: **6206 N Hamlin Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **Replacement 12"X12" Gray w/ Specs VFT**

MATERIAL LOCATION: **Room 118 - 1956**

MATERIAL QUANTITY: **12** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	60				
MATERIAL DESCRIPTION:	Replacement 12"X12" White w/ Black Specs VFT				
MATERIAL LOCATION:	Rooms 101, 102, 104 - 1953				
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25431** BUIDLING ID: **5980**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Solomon School** REVIEW DATE: **3/19/2025**

ADDRESS: **6206 N Hamlin Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **Replacement 12"X12" White w/ Black Specs VFT**

MATERIAL LOCATION: **Rooms 101, 102, 104 - 1953**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **03/19/2025**

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25431	BUIDLING ID:	5980
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	David Avila		
SCHOOL NAME:	Solomon School	INSPECTION DATE:	2/20/2025		
ADDRESS:	6206 N Hamlin Avenue	IDPH LICENSE NO:	100-11093		

## INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	62				
MATERIAL DESCRIPTION:	Replacement 12"X12" White w/ Black Specs VFT				
MATERIAL LOCATION:	Room 116 - 1956				
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	MODERATE	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 02/20/2025

# Chicago Public Schools

Specialty Consulting, Inc.  
2025 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25431** BUIDLING ID: **5980**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**

SCHOOL NAME: **Solomon School** REVIEW DATE: **3/19/2025**

ADDRESS: **6206 N Hamlin Avenue** IDPH LICENSE NO: **100-11093**

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **Replacement 12"X12" White w/ Black Specs VFT**

MATERIAL LOCATION: **Room 116 - 1956**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: **03/19/2025**


## APPENDIX B

---

### Inspector and Management Planner Licenses

7233 S. Adams Street | Willowbrook, IL 60527  
(630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2022



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**David Avila**


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 9/9/2022

Exam Date: 9/9/2022

Expiration Date: 9/9/2023

Certificate Number: BIR2209092141



Kathy DeSalvo, Director



OCCUPATIONAL TRAINING & SUPPLY, INC.

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**David Avila**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 9/10/2021

Exam Date: 9/10/2021

Expiration Date: 9/10/2022

Certificate Number: BIR2109101942


Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, IL

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/30/2025



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE		ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 4/30/2025	INSPECTOR	9/13/2025
DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health	EXPIRES 05/15/2026	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/14/2025
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**David Avila**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street  
Kenosha, WI 53142

Certificate Number: BIRWI2409132631  
Course Date: 9/13/2024  
Exam Date: 9/13/2024  
Expiration Date: 9/13/2025



Issue Date: 9/13/2024

Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours



525-535 West Jefferson Street • Springfield, Illinois

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

2/28/2022



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
**100 - 11093**

ISSUED  
**2/28/2022** EXPIRES  
**05/15/2023**

**DAVID AVILA**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



ASBESTOS PROFESSIONAL LICENSE ID NUMBER: **11093**

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER <b>100 - 11093</b>	ISSUED <b>2/28/2022</b>	EXPIRES <b>05/15/2023</b>		INSPECTOR	9/10/2022
<b>DAVID AVILA</b> 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health		PROJECT MANAGER AIR SAMPLING PROFESSIONAL <i>Alteration of this license shall result in legal action.</i> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Illinois



ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 11093

ISSUED  
4/8/2024

EXPIRES  
05/15/2025

DAVID AVILA  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health



DAVID AVILA  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11093

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 11093	ISSUED 4/8/2024	EXPIRES 05/15/2025	INSPECTOR	9/15/2024
DAVID AVILA 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health				PROJECT MANAGER AIR SAMPLING PROFESSIONAL
			<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*



## Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: BIR2111012562

*Kathy DeSalvo*  
Kathy DeSalvo, Director



## Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that  
**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/1/2021

Exam Date: 11/1/2021

Expiration Date: 11/1/2022

Certificate Number: MPR2111012583

*Kathy DeSalvo*  
Kathy DeSalvo, Director



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

7/8/2024

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

ASBESTOS PROFESSIONAL LICENSE			ENDORSEMENTS	TC EXPIRES
ID NUMBER <b>100 - 04019</b>	ISSUED <b>7/8/2024</b>	EXPIRES <b>05/15/2025</b>	INSPECTOR	5/6/2025
ARTURO SAENZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health			MANAGEMENT PLANNER	5/6/2025
			AIR SAMPLING PROFESSIONAL <b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*



OCCUPATIONAL TRAINING & SUPPLY, INC.  
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | [www.otssafety.com](http://www.otssafety.com)

2024

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 5/6/2024

Exam Date: 5/6/2024

Expiration Date: 5/6/2025

Certificate Number: MPR2405061823


Course Credit Hours: MPR 8 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois



ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612


2/28/2022

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/1/2022
MANAGEMENT PLANNER	11/1/2022
AIR SAMPLING PROFESSIONAL	
<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*



525-535 West Jefferson Street • Springfield, Ill

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/30/2026

ASBESTOS  
PROFESSIONAL  
LICENSE

ID NUMBER  
100 - 04019

ISSUED  
4/30/2025

EXPIRES  
05/15/2026

ARTURO SAENZ  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

Environmental Health




ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 04019

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License



Back of License

ENDORSEMENTS	TC EXPIRES
INSPECTOR	5/6/2025
MANAGEMENT PLANNER	4/2/2026
AIR SAMPLING PROFESSIONAL	
<p><b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

PROTECTING HEALTH, IMPROVING LIVES

*Nationally Accredited by PHAB*

**Reliable  
Environmental  
Solutions, Inc.  R E S**

*This is to certify that* **Arturo Saenz**

*has on 4/2/25, in Springfield, Illinois,  
completed the requirements for asbestos accreditation under Section 206 of TSCA Title II*

**Asbestos Management Planner Refresher Training**

*as accredited by the State of Illinois and approved by the U.S.E.P.A. under 40 CFR 763 (AHERA)  
and passed the associated examination with a score of 70% or higher*


Course Date: April 2, 2025

**COURSE LENGTH: 4 HOURS**

Examination Date: April 2, 2025

Expiration Date: April 2, 2026

Certificate Number: MPR/0560



Training Program Manager, William S. Williams

2760 W. Jefferson Street, Springfield, Illinois  217.787.9800  [www.ReliableEnv.com](http://www.ReliableEnv.com)

## APPENDIX C

---

### **Laboratory Accreditations**

## APPENDIX D

---

### Laboratory Results

## APPENDIX E

---

### Chain of Custody Forms

## Three-Year Reinspection Key to Terms

	CODE	KEY
<b>MATERIAL</b>	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>	Loc	Localized
	Dist	Distributed