

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2476
SCHOOL NAME: Sutherland School
ADDRESS OF SCHOOL: 10015 S Leavitt
CITY: Chicago, IL, 60643

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 8/18/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II (Please type or print)

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/12/2025 ENROLLMENT 682
IDPH INSPECTOR LICENSE NUMBER: 100-21052
IDPH LICENSED INSPECTOR NAME (Please Print): Jonathan Marquez
IDPH MP LICENSE NUMBER: 100-09766
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Szeredy

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 5/26/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Sutherland School

10015 S Leavitt
Chicago, IL, 60643

Unit: 25561
Building ID: 6120

IDPH ID Number: 14-016-2990-2476

REPORT DATE:
Monday, May 26, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
TEM Environmental, Inc.

174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone 630-790-0880
Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

05/23/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25561 Region: 06 IDPH ID: 14-016-2990-2476

School: Sutherland School Building ID: 6120

Address: 10015 S Leavitt

Chicago, IL, 60643

Building Contact: Madera, Jonathan Contact Phone: 3125095201

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/12/2025

Review Date: 05/23/2025

Inspector: Jonathan Marquez

Inspector IDPH License: 100-21052

Management Planner: Steven Szeredy

Management Planner IDPH License: 100-09766

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.



Steven Szeredy
100-09766

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: May 26, 2025

RE: Sutherland School, Unit 25561
10015 S Leavitt
Chicago, IL, 60643

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Sutherland School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Sutherland School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Sutherland School Unit: 25561 Region: 06
Address: 10015 S Leavitt Chicago, IL, 60643
IDPH ID: 14-016-2990-2476 Building ID: 6120
Contact: Madera, Jonathan Phone: 3125095201

2. Description of Facility

Original Construction: 1926 Additional Construction:
Total Square Footage: 69781 No of Floors: 2
Current Occupancy: 682

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Phone: 630-790-0880 Fax: 630-790-0882

5. Inspector

Inspector Name: Jonathan Marquez

Inspector IDPH license # 100-21052
Reinspection Date: 5/12/2025



Signature:
Date: 5/12/2025

6. Management Planner

Management Planner Name: Steven Szeregy

Management Planner IDPH license # 100-09766




Signature:
Date: 05/23/2025

7. Review Date: 05/23/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 5/26/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Sutherland School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6120:

02A	12"x12" Orange Floor Tile ABATED 2023
05	Tectum Panels
07A	12"x12" Orange Tan Floor Tile Mastic ABATED
31	12"x12" Blue Grey Mottled Floor Tile
31A	12"x12" Blue Grey Mottled Floor Tile Mastic
32	12"x12" Grey w/Dark Specks Floor Tile
32M	Mastic associated w/12"x12" Grey w/Dark Specks Floor Tile
33	Stage Curtain
NEW	Newly Installed Suspect ACM

R

Duct Insulation

B. The following new homogenous areas have been identified for Building 6120:

32	12"x12" Grey w/Dark Specks Floor Tile
32M	Mastic associated w/12"x12" Grey w/Dark Specks Floor Tile
33	Stage Curtain

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

05	Tectum Panels
09	Blown-in Insulation
12	Blue Carpet Mastic NOT OBSERVED
13	12x 12 Blue w/Specs Floor Tile
13A	12x 12 Blue w/Specs Floor Tile Mastic
14	Tan with Black Specks Terrazzo Flooring
15	Tan Ceramic Tile Grout
16	Tan Ceramic Tile Adhesive
17	White Ceramic Tile Grout
18	White Ceramic Tile Adhesive
20	Light Brown Carpet Adhesive
21	Hardcoat Plaster
23	Green Carpet Adhesive
24	12"x12" Green Vinyl Floor Tile
24M	12"x12" Green Vinyl Floor Tile Mastic
25	12"x12" White w/Green Specks Floor Tile
25M	12"x12" White w/Green Specks Floor Tile Mastic
26	2'x4' White Ceiling Tile
27	12"x12" Cream w/Tan Specks Floor Tile NOT OBSERVED
28	12"x12" Cream w/Tan Specks Mastic NOT OBSERVED
29	12"x12" Gray w/Dark Gray Specks Floor Tile
30	12"X12" Gray w/Dark Gray Specks Mastic
31	12"x12" Blue Grey Mottled Floor Tile
31A	12"x12" Blue Grey Mottled Floor Tile Mastic
32	12"x12" Grey w/Dark Specks Floor Tile
32M	Mastic associated w/12"x12" Grey w/Dark Specks Floor Tile
33	Stage Curtain
NEW	Newly Installed Suspect ACM
R	Duct Insulation

The following areas were deemed to be inaccessible:

09	Blown-in Insulation
16	Tan Ceramic Tile Adhesive
18	White Ceramic Tile Adhesive
20	Light Brown Carpet Adhesive
23	Green Carpet Adhesive

24M	12"x12" Green Vinyl Floor Tile Mastic
25M	12"x12" White w/Green Specks Floor Tile Mastic
28	12"x12" Cream w/Tan Specks Mastic NOT OBSERVED

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jonathan Marquez, IDPH License # 100-21052. The Management Plan was updated by Steven Szeredy, IDPH License # 100-09766. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates: 7/25/2023

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Sutherland School Building 6120 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Sutherland School **Unit** 25561 **Building ID** 6120
Address 10015 S Leavitt **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01A	9"x9" Brown Floor Tile NOT OBSERVED			1st & 2nd Floor Corridors		MISC								
01B	9"x9" Tan Floor Tile NOT OBSERVED			1st & 2nd Floor Corridors		MISC								
02A	12"x12" Orange Floor Tile ABATED 2023			Room 212	ABATED	MISC					Yes			
02B	12"x12" Taupe Floor Tile	1,644	SF	Main Office, Rooms 103 and 110	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02C	12"x12" Beige Streaked Floor Tile	111	SF	Room 103	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02D	12"x12" Brown Floor Tile	275	SF	Room 103	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02E	12"x12" Tan Floor Tile	275	SF	Room 103	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
02F	12"x12" Beige Floor Tile	90	SF	Main Office and Room 110	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
03	Orange Linoleum NOT OBSERVED	600	SF	Rooms 104, 105, 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
05	Tectum Panels	3,000	SF	Gymnasium	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
06A	9"x9" Brown Floor Tile Mastic NOT OBSERVED			1st & 2nd Floor Corridors		MISC								
06B	9"x9" Tan Floor Tile Mastic NOT OBSERVED			1st & 2nd Floor Corridors		MISC								
07A	12"x12" Orange Tan Floor Tile Mastic ABATED			Room 212	ABATED	MISC					Yes			
07B	12"x12" Taupe Floor Tile Mastic	1,644	SF	Main Office, Room 103, and 110	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07C	12"x12" Beige Streaked Floor Tile Mastic	111	SF	Room 103	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07D	12"x12" Brown Floor Tile Mastic	275	SF	Room 103	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07E	12"x12" Tan Floor Tile Mastic	275	SF	Room 103	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
07F	12"x12" Beige Floor Tile Mastic	90	SF	Main Office and Room 110	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
08	Orange Linoleum Mastic NOT OBSERVED	600	SF	Rooms 104, 105, and 106	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
09	Blown-in Insulation	32,500	SF	Attic Above Entire School	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
11	Window Glazing			Windows on East Side of School		MISC								
12	Blue Carpet Mastic NOT OBSERVED	650	SF	Room 104	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
13	12x 12 Blue w/Specs Floor Tile	8,600	SF	1st and 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Sutherland School **Unit** 25561 **Building ID** 6120
Address 10015 S Leavitt **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Sutherland School Unit 25561 Building ID 6120
 Address 10015 S Leavitt Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
23	Green Carpet Adhesive	531	SF	Assembly Hall, Men's Toilet Entrance, Assembly Hall Offices, Vestibule	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24	12"x12" Green Vinyl Floor Tile	2,340	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
24M	12"x12" Green Vinyl Floor Tile Mastic	2,340	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25	12"x12" White w/Green Specks Floor Tile	2,340	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
25M	12"x12" White w/Green Specks Floor Tile Mastic	2,340	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	2'x4' White Ceiling Tile	3,500	SF	Gymnasium	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
27	12"x12" Cream w/Tan Specks Floor Tile NOT OBSERVED	500	SF	Room 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12"x12" Cream w/Tan Specks Mastic NOT OBSERVED	500	SF	Room 114	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12"x12" Gray w/Dark Gray Specks Floor Tile	500	SF	Rooms 104 & 104B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12'X12' Gray w/Dark Gray Specks Mastic	500	SF	Rooms 104 & 104B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
31	12"x12" Blue Grey Mottled Floor Tile		SF	1st & 2nd Floor Elevator Lobby	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
31A	12"x12" Blue Grey Mottled Floor Tile Mastic		SF	1st & 2nd Floor Elevator Lobby	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
32	12"x12" Grey w/Dark Specks Floor Tile	1,200	SF	Room 212	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
32M	Mastic associated w/12"x12" Grey w/Dark Specks Floor Tile	1,200	SF	Room 212	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
33	Stage Curtain	1,200	SF	Assembly Hall	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
C	Aircell Pipe Insulation	3,750	LF	Basement Crawlspaces, Air Tunnels	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
D	MJP E/F/V on Aircell Pipe Insulation	237	LF	Basement Crawlspaces, Air Tunnels	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
E	Cardboard Pipe Insulation	2,885	LF	Basement Crawlspaces, Air Tunnels	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
F	MJP E/F/V on Cardboard Pipe Insulation	125	LF	Basement Crawlspaces, Air	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Sutherland School **Unit** 25561 **Building ID** 6120
Address 10015 S Leavitt **Region** 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Tunnels, Boiler Room										
G	Mag Block Tank Insulation ABATED			Boiler Room	ABATED	TSI								
H	Mag Block Pipe Joint Insulation ABATED			Boiler Room	ABATED	TSI								
K	Aircell Duct Insulation	3,000	LF	Crawlspaces	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
L	ACM Pipe Wrap ABATED			Boiler Room	ABATED	TSI								
M	Boiler Gasket ABATED	0		Boiler Room	ABATED	TSI								
N	Mag Block Pipe Insulation	400	LF	Basement Crawlspaces, Air Tunnels	AMO	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	ASSUMED	MISC		UNKNO WN	0		Yes	ACBM with the potential for damage		
O	Incinerator Insulation ABATED	0		Boiler Room		TSI								
P	Boiler Insulation ABATED	0		Boiler Room	ABATED	TSI								
Q	Boiler Brick ABATED	0		Boiler Room	ABATED	TSI								
R	Duct Insulation		LF	Basement Crawlspace	ASSUMED	TSI	N	NONE	0		Yes	ACBM with potential for significant damage		MODERATE

Chicago Public Schools

School Sutherland School Unit 25561 Building ID 6120
Address 10015 S Leavitt Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date	<u>5/12/2025</u>
Inspector Name	<u>Jonathan Marquez</u>
100-21052	5/15/2026
Inspector's IDPH License Number / Expiration Date	

Inspector's Comments

HA Number:	Inspector Comments:
01A	Not Observed 2025
01B	Not Observed 2025
02A	Abated July 2023
02B	
02C	
02D	
02E	
02F	
03	Not Observed 2025
05	
06A	Not Observed 2025
06B	
07A	Abated July 2023
07B	
07C	
07D	
07E	
07F	
08	Not Observed 2025
09	
11	Not Observed 2025
12	Not Observed 2025
13	
13A	

Chicago Public Schools

School Sutherland School Unit 25561 Building ID 6120
Address 10015 S Leavitt Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
14	
15	
16	
17	
18	
19	Not Observed 2025
20	
21	
22	Not Observed 2025
23	
24	
24M	
25	
25M	
26	
27	Not Observed 2025. Might be under Wood Floor
28	Not Observed 2025. Might be under Wood Floor
29	
30	
31	
31A	
32	
32M	
33	
C	
D	
E	
F	
G	

Chicago Public Schools

School Sutherland School Unit 25561 Building ID 6120
Address 10015 S Leavitt Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
H	
K	
L	
M	
N	
NEW	
O	
P	
Q	
R	

Table II
Management Planner's Review

Chicago Public Schools

School Sutherland School

Unit 25561

Building ID 6120

Address 10015 S Leavitt

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01A	9"x9" Brown Floor Tile NOT OBSERVED			1st & 2nd Floor Corridors		MISC					
01B	9"x9" Tan Floor Tile NOT OBSERVED			1st & 2nd Floor Corridors		MISC					
02A	12"x12" Orange Floor Tile ABATED 2023			Room 212	Abated	MISC					
02B	12"x12" Taupe Floor Tile	1,644	SF	Main Office, Rooms 103 and 110	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02C	12"x12" Beige Streaked Floor Tile	111	SF	Room 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02D	12"x12" Brown Floor Tile	275	SF	Room 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02E	12"x12" Tan Floor Tile	275	SF	Room 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
02F	12"x12" Beige Floor Tile	90	SF	Main Office and Room 110	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
03	Orange Linoleum NOT OBSERVED	600	SF	Rooms 104, 105, 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
05	Tectum Panels	3,000	SF	Gymnasium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
06A	9"x9" Brown Floor Tile Mastic NOT OBSERVED			1st & 2nd Floor Corridors		MISC					
06B	9"x9" Tan Floor Tile Mastic NOT OBSERVED			1st & 2nd Floor Corridors		MISC					
07A	12"x12" Orange Tan Floor Tile Mastic ABATED			Room 212	Abated	MISC					
07B	12"x12" Taupe Floor Tile Mastic	1,644	SF	Main Office, Room 103, and 110	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07C	12"x12" Beige Streaked Floor Tile Mastic	111	SF	Room 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07D	12"x12" Brown Floor Tile Mastic	275	SF	Room 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07E	12"x12" Tan Floor Tile Mastic	275	SF	Room 103	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
07F	12"x12" Beige Floor Tile Mastic	90	SF	Main Office and Room 110	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
08	Orange Linoleum Mastic NOT OBSERVED	600	SF	Rooms 104, 105, and 106	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
09	Blown-in Insulation	32,500	SF	Attic Above Entire School	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	Window Glazing			Windows on East Side of School		MISC					Follow O&M Plan
12	Blue Carpet Mastic NOT OBSERVED	650	SF	Room 104	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13	12x 12 Blue w/Speccks Floor Tile	8,600	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
13A	12x 12 Blue w/Speccks Floor Tile Mastic	8,600	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Tan with Black Specks Terrazzo Flooring	11,680	SF	1st Floor - North Center and South Corridors / 2nd Floor - North Center and South Corridors, NW, NE, SW and SE Stairwells, and Teachers Lunchroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
15	Tan Ceramic Tile Grout	1,200	SF	1st and 2nd Floor North Boys' and Girls' Restrooms	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	Tan Ceramic Tile Adhesive	1,200	SF	1st and 2nd Floor North Boys' and Girls' Restrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	White Ceramic Tile Grout	4,940	SF	1st and 2nd Floor South Boys' and Girls' Restrooms, 1st Floor Women's	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sutherland School

Unit 25561

Building ID 6120

Address 10015 S Leavitt

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Toilet, 2nd Floor Teachers Toilet, Gym and Boys' Locker Room, Gym Office, IDF Room & Room 120							
18	White Ceramic Tile Adhesive	4,940	SF	1st and 2nd Floor South Boys' and Girls' Restrooms, 1st Floor Women's Toilet, 2nd Floor Teachers Toilet, Gym and Boys' Locker Room, Gym Office, IDF Room & Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Maroon Carpet Adhesive	150	SF	Office Storage Room		MISC			SF		Follow O&M Plan
20	Light Brown Carpet Adhesive	192	SF	Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Hardcoat Plaster	40,000	SF	Throughout Building	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
22	Gray Carpet Adhesive			Teacher's Lounge		MISC					Follow O&M Plan
23	Green Carpet Adhesive	531	SF	Assembly Hall, Men's Toilet Entrance, Assembly Hall Offices, Vestibule	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12"x12" Green Vinyl Floor Tile	2,340	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24M	12"x12" Green Vinyl Floor Tile Mastic	2,340	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25	12"x12" White w/Green Specks Floor Tile	2,340	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
25M	12"x12" White w/Green Specks Floor Tile Mastic	2,340	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	2'x4' White Ceiling Tile	3,500	SF	Gymnasium	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12"x12" Cream w/Tan Specks Floor Tile NOT OBSERVED	500	SF	Room 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12"x12" Cream w/Tan Specks Mastic NOT OBSERVED	500	SF	Room 114	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12"x12" Gray w/Dark Gray Specks Floor Tile	500	SF	Rooms 104 & 104B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
30	12'X12" Gray w/Dark Gray Specks Mastic	500	SF	Rooms 104 & 104B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31	12"x12" Blue Grey Mottled Floor Tile		SF	1st & 2nd Floor Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
31A	12"x12" Blue Grey Mottled Floor Tile Mastic		SF	1st & 2nd Floor Elevator Lobby	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32	12"x12" Grey w/Dark Specks Floor Tile	1,200	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
32M	Mastic associated w/12"x12" Grey w/Dark Specks Floor Tile	1,200	SF	Room 212	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Stage Curtain	1,200	SF	Assembly Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
C	Aircell Pipe Insulation	3,750	LF	Basement Crawlspace, Air Tunnels	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
D	MJP E/F/V on Aircell Pipe Insulation	237	LF	Basement Crawlspace, Air Tunnels	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
E	Cardboard Pipe Insulation	2,885	LF	Basement Crawlspace, Air Tunnels	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
F	MJP E/F/V on Cardboard Pipe Insulation	125	LF	Basement Crawlspace, Air Tunnels, Boiler Room	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Sutherland School

Unit 25561

Building ID 6120

Address 10015 S Leavitt

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
G	Mag Block Tank Insulation ABATED			Boiler Room	Abated	TSI					
H	Mag Block Pipe Joint Insulation ABATED			Boiler Room	Abated	TSI					
K	Aircell Duct Insulation	3,000	LF	Crawlspaces	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
L	ACM Pipe Wrap ABATED			Boiler Room	Abated	TSI					
M	Boiler Gasket ABATED	0		Boiler Room	Abated	TSI					
N	Mag Block Pipe Insulation	400	LF	Basement Crawlspaces, Air Tunnels	Amosite	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
NEW	Newly Installed Suspect ACM			Installed After Implementation of Management Plan and After Renovations	Assumed	MISC		0		6 ACBM with the potential for damage	Follow O&M Plan
O	Incinerator Insulation ABATED	0		Boiler Room		TSI					
P	Boiler Insulation ABATED	0		Boiler Room	Abated	TSI					
Q	Boiler Brick ABATED	0		Boiler Room	Abated	TSI					
R	Duct Insulation		LF	Basement Crawlspac	Assumed	TSI	No	0	LF	5 ACBM with potential for significant damage	Follow O&M Plan

Chicago Public Schools

School Sutherland School

Unit 25561

Building ID 6120

Address 10015 S Leavitt

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	5/23/2025
Manager Planner Name	Steven Szeregy
100-09766	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
01A	2025 - Not Observed
01B	2025 - Not Observed
02A	
02B	
02C	
02D	
02E	
02F	
03	2025 - Not Observed
05	
06A	2025 - Not Observed
06B	2025 - Not Observed
07A	
07B	
07C	
07D	
07E	
07F	
08	2025 - Not Observed
09	
11	
12	2025 - Not Observed

Chicago Public Schools

School Sutherland School

Unit 25561

Building ID 6120

Address 10015 S Leavitt

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
13	
13A	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
24M	
25	
25M	
26	
27	2025 - Not Observed
28	2025 - Not Observed
29	
30	
31	
31A	
32	
32M	
33	
C	

Chicago Public Schools

School Sutherland School

Unit 25561

Building ID 6120

Address 10015 S Leavitt

Chicago, IL, 60643

Region 06

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive

Phone: 630-790-0880

Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
D	
E	
F	
G	
H	
K	
L	
M	
N	
NEW	
O	
P	
Q	
R	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Chicago Public Schools

TEM Environmental, Inc.

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 01A

MATERIAL DESCRIPTION: 9"x9" Brown Floor Tile NOT OBSERVED

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1st & 2nd Floor Corridors

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Not Observed 2025

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **01A**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **01B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **01B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02A	
MATERIAL DESCRIPTION:	12"x12" Orange Floor Tile ABATED 2023	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with potential for significant damage	
HISTORICAL DAMAGE REASON:	Deterioration	
HISTORICAL RESPONSE ACTION:	Repair	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 212

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: Abated July 2023

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **02A**

MATERIAL DESCRIPTION: **12"x12" Orange Floor Tile ABATED 2023**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02B		
MATERIAL DESCRIPTION:	12"x12" Taupe Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Rooms 103 and 110		
MATERIAL QUANTITY:	1644	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **02B**

MATERIAL DESCRIPTION: **12"x12" Taupe Floor Tile**

MATERIAL LOCATION: **Main Office, Rooms 103 and 110**

MATERIAL QUANTITY: **1644** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02C		
MATERIAL DESCRIPTION:	12"x12" Beige Streaked Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	111	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **02C**

MATERIAL DESCRIPTION: **12"x12" Beige Streaked Floor Tile**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **111** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02D		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	275	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **02D**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02E		
MATERIAL DESCRIPTION:	12"x12" Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	275	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **02E**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	02F		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office and Room 110		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **02F**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile**

MATERIAL LOCATION: **Main Office and Room 110**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	03		
MATERIAL DESCRIPTION:	Orange Linoleum NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104, 105, 106		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **03**

MATERIAL DESCRIPTION: **Orange Linoleum NOT OBSERVED**

MATERIAL LOCATION: **Rooms 104, 105, 106**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	05		
MATERIAL DESCRIPTION:	Tectum Panels		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **05**

MATERIAL DESCRIPTION: **Tectum Panels**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **06A**

MATERIAL DESCRIPTION: **9"x9" Brown Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **06B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic NOT OBSERVED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **06B**

MATERIAL DESCRIPTION: **9"x9" Tan Floor Tile Mastic NOT OBSERVED**

MATERIAL LOCATION: **1st & 2nd Floor Corridors**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07A	
MATERIAL DESCRIPTION:	12"x12" Orange Tan Floor Tile Mastic ABATED	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Room 212

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Abated July 2023

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **07A**

MATERIAL DESCRIPTION: **12"x12" Orange Tan Floor Tile Mastic ABATED**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07B		
MATERIAL DESCRIPTION:	12"x12" Taupe Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Room 103, and 110		
MATERIAL QUANTITY:	1644	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **07B**

MATERIAL DESCRIPTION: **12"x12" Taupe Floor Tile Mastic**

MATERIAL LOCATION: **Main Office, Room 103, and 110**

MATERIAL QUANTITY: **1644** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07C		
MATERIAL DESCRIPTION:	12"x12" Beige Streaked Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	111	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **07C**

MATERIAL DESCRIPTION: **12"x12" Beige Streaked Floor Tile Mastic**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **111** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07D		
MATERIAL DESCRIPTION:	12"x12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	275	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **07D**

MATERIAL DESCRIPTION: **12"x12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07E		
MATERIAL DESCRIPTION:	12"x12" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 103		
MATERIAL QUANTITY:	275	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **07E**

MATERIAL DESCRIPTION: **12"x12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Room 103**

MATERIAL QUANTITY: **275** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	07F		
MATERIAL DESCRIPTION:	12"x12" Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office and Room 110		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **07F**

MATERIAL DESCRIPTION: **12"x12" Beige Floor Tile Mastic**

MATERIAL LOCATION: **Main Office and Room 110**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	08		
MATERIAL DESCRIPTION:	Orange Linoleum Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104, 105, and 106		
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **08**

MATERIAL DESCRIPTION: **Orange Linoleum Mastic NOT OBSERVED**

MATERIAL LOCATION: **Rooms 104, 105, and 106**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	09		
MATERIAL DESCRIPTION:	Blown-in Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Attic Above Entire School		
MATERIAL QUANTITY:	32500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **09**

MATERIAL DESCRIPTION: **Blown-in Insulation**

MATERIAL LOCATION: **Attic Above Entire School**

MATERIAL QUANTITY: **32500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Window Glazing**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Windows on East Side of School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **Window Glazing**

MATERIAL LOCATION: **Windows on East Side of School**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	Blue Carpet Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 104		
MATERIAL QUANTITY:	650	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025		

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **Blue Carpet Mastic NOT OBSERVED**

MATERIAL LOCATION: **Room 104**

MATERIAL QUANTITY: **650** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13		
MATERIAL DESCRIPTION:	12x 12 Blue w/Speccks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Corridors		
MATERIAL QUANTITY:	8600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **12x 12 Blue w/Specs Floor Tile**

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: **8600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	13A		
MATERIAL DESCRIPTION:	12x 12 Blue w/Speccks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor Corridors		
MATERIAL QUANTITY:	8600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **13A**

MATERIAL DESCRIPTION: **12x 12 Blue w/Specs Floor Tile Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors**

MATERIAL QUANTITY: **8600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	14		
MATERIAL DESCRIPTION:	Tan with Black Specks Terrazzo Flooring		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st Floor - North Center and South Corridors / 2nd Floor - North Center and South Corridors, NW, NE, SW and SE Stairwells, and Teachers Lunchroom**

MATERIAL QUANTITY: **11680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Tan with Black Specks Terrazzo Flooring**

MATERIAL LOCATION: **1st Floor - North Center and South Corridors / 2nd Floor - North Center and South Corridors, NW, NE, SW and SE Stairwells, and Teachers Lunchroom**

MATERIAL QUANTITY: **11680** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	15		
MATERIAL DESCRIPTION:	Tan Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor North Boys' and Girls' Restrooms		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Tan Ceramic Tile Grout**

MATERIAL LOCATION: **1st and 2nd Floor North Boys' and Girls' Restrooms**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	16		
MATERIAL DESCRIPTION:	Tan Ceramic Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1st and 2nd Floor North Boys' and Girls' Restrooms		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Tan Ceramic Tile Adhesive**

MATERIAL LOCATION: **1st and 2nd Floor North Boys' and Girls' Restrooms**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	White Ceramic Tile Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor South Boys' and Girls' Restrooms, 1st Floor Women's Toilet, 2nd Floor Teachers Toilet, Gym and Boys' Locker Room, Gym Office, IDF Room & Room 120**

MATERIAL QUANTITY: **4940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **White Ceramic Tile Grout**

MATERIAL LOCATION: **1st and 2nd Floor South Boys' and Girls' Restrooms, 1st Floor Women's Toilet, 2nd Floor Teachers Toilet, Gym and Boys' Locker Room, Gym Office, IDF Room & Room 120**

MATERIAL QUANTITY: **4940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	18		
MATERIAL DESCRIPTION:	White Ceramic Tile Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st and 2nd Floor South Boys' and Girls' Restrooms, 1st Floor Women's Toilet, 2nd Floor Teachers Toilet, Gym and Boys' Locker Room, Gym Office, IDF Room & Room 120**

MATERIAL QUANTITY: **4940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**

MATERIAL LOCATION: **1st and 2nd Floor South Boys' and Girls' Restrooms, 1st Floor Women's Toilet, 2nd Floor Teachers Toilet, Gym and Boys' Locker Room, Gym Office, IDF Room & Room 120**

MATERIAL QUANTITY: **4940** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Maroon Carpet Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Office Storage Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Maroon Carpet Adhesive**

MATERIAL LOCATION: **Office Storage Room**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Light Brown Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Principal's Office		
MATERIAL QUANTITY:	192	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Light Brown Carpet Adhesive**

MATERIAL LOCATION: **Principal's Office**

MATERIAL QUANTITY: **192** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	21		
MATERIAL DESCRIPTION:	Hardcoat Plaster		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building		
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **Hardcoat Plaster**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Gray Carpet Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2025**

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **Gray Carpet Adhesive**

MATERIAL LOCATION: **Teacher's Lounge**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	23		
MATERIAL DESCRIPTION:	Green Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall, Men's Toilet Entrance, Assembly Hall Offices, Vestibule		
MATERIAL QUANTITY:	531	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Green Carpet Adhesive**

MATERIAL LOCATION: **Assembly Hall, Men's Toilet Entrance, Assembly Hall Offices, Vestibule**

MATERIAL QUANTITY: **531** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24		
MATERIAL DESCRIPTION:	12"x12" Green Vinyl Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2340	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12"x12" Green Vinyl Floor Tile**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	24M		
MATERIAL DESCRIPTION:	12"x12" Green Vinyl Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2340	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **24M**

MATERIAL DESCRIPTION: **12"x12" Green Vinyl Floor Tile Mastic**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25		
MATERIAL DESCRIPTION:	12"x12" White w/Green Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2340	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **12"x12" White w/Green Specks Floor Tile**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	25M		
MATERIAL DESCRIPTION:	12"x12" White w/Green Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	2340	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **25M**

MATERIAL DESCRIPTION: **12"x12" White w/Green Specks Floor Tile Mastic**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	2'x4' White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium		
MATERIAL QUANTITY:	3500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **2'x4' White Ceiling Tile**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	27		
MATERIAL DESCRIPTION:	12"x12" Cream w/Tan Specks Floor Tile NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. Might be under Wood Floor		

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Floor Tile NOT OBSERVED**

MATERIAL LOCATION: **Room 114**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	28		
MATERIAL DESCRIPTION:	12"x12" Cream w/Tan Specks Mastic NOT OBSERVED		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not Observed 2025. Might be under Wood Floor		

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **12"x12" Cream w/Tan Specks Mastic NOT OBSERVED**

MATERIAL LOCATION: **Room 114**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

2025 - Not Observed

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	29		
MATERIAL DESCRIPTION:	12"x12" Gray w/Dark Gray Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104 & 104B		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **12"x12" Gray w/Dark Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 104 & 104B**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	12"X12" Gray w/Dark Gray Specks Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 104 & 104B		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **12"X12" Gray w/Dark Gray Specks Mastic**

MATERIAL LOCATION: **Rooms 104 & 104B**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12"x12" Blue Grey Mottled Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floor Elevator Lobby**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeredy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: 31

MATERIAL DESCRIPTION: 12"x12" Blue Grey Mottled Floor Tile

MATERIAL LOCATION: 1st & 2nd Floor Elevator Lobby

MATERIAL QUANTITY: _____ **MATERIAL UNITS:** _____ **SF** _____

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:

St R. n

Date: 05/23/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31A		
MATERIAL DESCRIPTION:	12"x12" Blue Grey Mottled Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1st & 2nd Floor Elevator Lobby**

MATERIAL QUANTITY: MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeredy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: 31A

MATERIAL DESCRIPTION: 12"x12" Blue Grey Mottled Floor Tile Mastic

MATERIAL LOCATION: 1st & 2nd Floor Elevator Lobby

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____ SF _____

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:

st r. n

Date: 05/23/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Basement Crawlspaces, Air Tunnels		
MATERIAL QUANTITY:	3750	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement Crawlspaces, Air Tunnels**

MATERIAL QUANTITY: **3750** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	MJP E/F/V on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Crawlspaces, Air Tunnels		
MATERIAL QUANTITY:	237	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **MJP E/F/V on Aircell Pipe Insulation**

MATERIAL LOCATION: **Basement Crawlspaces, Air Tunnels**

MATERIAL QUANTITY: **237** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Crawlspaces, Air Tunnels		
MATERIAL QUANTITY:	2885	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement Crawlspaces, Air Tunnels**

MATERIAL QUANTITY: **2885** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	MJP E/F/V on Cardboard Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Crawlspaces, Air Tunnels, Boiler Room		
MATERIAL QUANTITY:	125	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **MJP E/F/V on Cardboard Pipe Insulation**

MATERIAL LOCATION: **Basement Crawlspaces, Air Tunnels, Boiler Room**

MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Mag Block Tank Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **G**

MATERIAL DESCRIPTION: **Mag Block Tank Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Mag Block Pipe Joint Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Mag Block Pipe Joint Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Aircell Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Crawlspaces		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Aircell Duct Insulation**

MATERIAL LOCATION: **Crawlspaces**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **ACM Pipe Wrap ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **ACM Pipe Wrap ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Boiler Gasket ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Boiler Gasket ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	Mag Block Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Amosite	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: Basement Crawlspaces, Air Tunnels

MATERIAL QUANTITY: 400 MATERIAL UNITS: LF

DAMAGE QUANTITY: DAMAGE UNITS: LF

COMMENTS:

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **Mag Block Pipe Insulation**

MATERIAL LOCATION: **Basement Crawlspaces, Air Tunnels**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	NEW		
MATERIAL DESCRIPTION:	Newly Installed Suspect ACM		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **NEW**

MATERIAL DESCRIPTION: **Newly Installed Suspect ACM**

MATERIAL LOCATION: **Installed After Implementation of Management Plan and After Renovations**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: **0** DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Incinerator Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **FRIABLE**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:


MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Incinerator Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Boiler Insulation ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **Boiler Insulation ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0**

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt		IDPH LICENSE NO:	100-21052	

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Boiler Brick ABATED**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUILDING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeregy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **Boiler Brick ABATED**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **0** MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **05/23/2025**

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	R		
MATERIAL DESCRIPTION:	Duct Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE
MATERIAL LOCATION:	Basement Crawlspace
MATERIAL QUANTITY:	MATERIAL UNITS: LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF
COMMENTS:	

Inspector's Signature:



Date: **05/12/2025**

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Steven Szeredy		
SCHOOL NAME:	Sutherland School	REVIEW DATE:	5/23/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

HOMOGENEOUS AREA: R

MATERIAL DESCRIPTION: Duct Insulation

MATERIAL LOCATION: **Basement Crawlspace**

MATERIAL QUANTITY:

MATERIAL UNITS: LF

DAMAGE QUANTITY: 0

DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:

st r. n

Date: 05/23/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12"x12" Grey w/Dark Specks Floor Tile		
MATERIAL LOCATION:	Room 212		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25561** BUIDLING ID: **6120**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szereedy**

SCHOOL NAME: **Sutherland School** REVIEW DATE: **5/23/2025**

ADDRESS: **10015 S Leavitt** IDPH LICENSE NO: **100-21052**

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12"x12" Grey w/Dark Specks Floor Tile**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. ~ Date: 05/23/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	32M				
MATERIAL DESCRIPTION:	Mastic associated w/12"x12" Grey w/Dark Specks Floor Tile				
MATERIAL LOCATION:	Room 212				
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF		
MATERIAL CATEGORY:	MISC	FRIABLE:	No		
ASBESTOS TYPE:	Assumed				
DISTURBANCE POTENTIAL:	LOW	CONDITION:			
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage				
ACCESSIBILITY:	Within Reach	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
DAMAGE QUANTITY:	0	DAMAGE REASON:			
COMMENTS:					

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25561** BUIDLING ID: **6120**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szereedy**

SCHOOL NAME: **Sutherland School** REVIEW DATE: **5/23/2025**

ADDRESS: **10015 S Leavitt** IDPH LICENSE NO: **100-21052**

HOMOGENEOUS AREA: **32M**

MATERIAL DESCRIPTION: **Mastic associated w/12"x12" Grey w/Dark Specks Floor Tile**

MATERIAL LOCATION: **Room 212**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. ~ Date: 05/23/2025

Chicago Public Schools

TEM Environmental, Inc.
2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25561	BUIDLING ID:	6120
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jonathan Marquez		
SCHOOL NAME:	Sutherland School	INSPECTION DATE:	5/12/2025		
ADDRESS:	10015 S Leavitt	IDPH LICENSE NO:	100-21052		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	33		
MATERIAL DESCRIPTION:	Stage Curtain		
MATERIAL LOCATION:	Assembly Hall		
MATERIAL QUANTITY:	1200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:	0	DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF

COMMENTS:

Inspector's Signature:



Date: 05/12/2025

Chicago Public Schools

TEM Environmental, Inc. 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25561** BUIDLING ID: **6120**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Steven Szereedy**

SCHOOL NAME: **Sutherland School** REVIEW DATE: **5/23/2025**

ADDRESS: **10015 S Leavitt** IDPH LICENSE NO: **100-21052**

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Stage Curtain**

MATERIAL LOCATION: **Assembly Hall**

MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: St. R. ~ Date: 05/23/2025

APPENDIX B

Inspector and Management Planner Licenses



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

JONATHAN MARQUEZ
3S564 ELIZABETH AVE
WARRENVILLE, IL 60555

2/10/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 21052

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

Front of License		Back of License	
	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 21052	ISSUED 2/10/2025	EXPIRES 05/15/2026	INSPECTOR 8/21/2025
JONATHAN MARQUEZ 3S564 ELIZABETH AVE WARRENVILLE, IL 60555 Environmental Health		PROJECT MANAGER 9/13/2025	
<p>Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.</p>			

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Initial

Occupational Training & Supply, Inc. certifies that

Jonathan Marquez

has successfully completed the Asbestos Building Inspector Initial course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 8/19/2024 - 8/21/2024

Exam Date: 8/21/2024

Expiration Date: 8/21/2025

Certificate Number: ABI2408212398

Course Credit Hours: ABI 24 Hours

Kristina Miczek, Training Manager



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • www.dph.illinois.gov

STEVEN R SZEREDY
16W451 HILLSIDE LN
WILLOWBROOK, IL 60527

3/27/2025

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 09766

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License		Back of License	
	ASBESTOS PROFESSIONAL LICENSE	ENDORSEMENTS	TC EXPIRES
ID NUMBER 100 - 09766	ISSUED 3/27/2025	EXPIRES 05/15/2026	INSPECTOR 7/12/2025
STEVEN R SZEREDY 16W451 HILLSIDE LN WILLOWBROOK, IL 60527 Environmental Health		MANAGEMENT PLANNER PROJECT MANAGER AIR SAMPLING PROFESSIONAL	2/20/2026 7/13/2025
Alteration of this license shall result in legal action This license issued under authority of the State of Illinois Department of Public Health		This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: dph.illinois.gov/topics-services/environmental-health-protection/asbestos
EMAIL Address: dph.asbestos@illinois.gov

PROTECTING HEALTH, IMPROVING LIVES
Nationally Accredited by PHAB



OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2025

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Steven Szeregy

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 2/20/2025

Exam Date: 2/20/2025

Expiration Date: 2/20/2026

Certificate Number: MPR2502200748

Course Credit Hours: MPR 4 Hours

Kristina Miczek

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed