

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2487
SCHOOL NAME: Tilton School
ADDRESS OF SCHOOL: 223 N. Keeler
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 10/6/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 5/26/2025 ENROLLMENT 243
IDPH INSPECTOR LICENSE NUMBER: 100-06435
IDPH LICENSED INSPECTOR NAME (Please Print): Jose Escobedo
IDPH MP LICENSE NUMBER: 100-20634
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Jackson Montgomery

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 6/9/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Tilton School

223 N. Keeler
Chicago, IL, 60624

Unit: 25621
Building ID: 6210

IDPH ID Number: 14-016-2990-2487

REPORT DATE:
Monday, June 09, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

06/09/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 25621 Region: 03 IDPH ID: 14-016-2990-2487

School: Tilton School Building ID: 6210

Address: 223 N. Keeler

Chicago, IL, 60624

Building Contact: Petruslis, Scott Contact Phone: 7739153517

Current Building Owners: Chicago Public Schools

Reinspection Date: 5/26/2025

Review Date: 06/09/2025

Inspector: Jose Escobedo

Inspector IDPH License: 100-06435

Management Planner: Jackson Montgomery

Management Planner IDPH License: 100-20634

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Jackson Montgomery
100-20634

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 09, 2025

RE: Tilton School, Unit 25621
223 N. Keeler
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Tilton School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Tilton School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Tilton School Unit: 25621 Region: 03
Address: 223 N. Keeler Chicago, IL, 60624
IDPH ID: 14-016-2990-2487 Building ID: 6210
Contact: Petruslis, Scott Phone: 7739153517

2. Description of Facility

Original Construction: 1971 Additional Construction: 1909
Total Square Footage: 27218 No of Floors: 3
Current Occupancy: 243

3. LEA Designated Person

Contact: Richard J.Schleyer Phone: (773) 251-7074
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Jose Escobedo

Inspector IDPH license # 100-06435 Signature:
Reinspection Date: 5/26/2025 Date: 5/26/2025

6. Management Planner

Management Planner Name: Jackson Montgomery


Management Planner IDPH license # 100-20634


Signature:
Date: 06/09/2025

7. Review Date: 06/09/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.


Signature: Date: 6/9/2025

Name: Richard J.Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Tilton School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6210:

008	12" x 12" Light Brown w/ Gray Streaks Floor Tile
010	9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile
019	Black Border Tile
021	12" x 12" Light Beige w/ Light Brown Streaks Floor Tile
041	12" x 12" Light Off-White w/ Cream Mix Floor Tile
042	12" x 12" Light Off-White w/ Cream Mix Floor Tile Mastic
049	9" x 9" Light Brown w/ Beige Streaks Floor Tile
072	Incinerator Interior Materials

078	12" x 12" Red Floor Tile
079	12" x 12" Red Floor Tile Mastic
080	Blue Carpet Adhesive
082	Chalk Board/Poster Board Adhesive
084	12" x 12" Off-White/Beige Floor Tile
085	12" x 12" Off-White/Beige Floor Tile Mastic
086	12" x 12" Off-White & Beige Floor Tile
088	9" x 9" Red/Gray Floor Tile
089	9" x 9" Red/Gray Floor Tile Mastic
100	12" x 12" White Floor Tile
101	9" x 9" Black Floor Tile
102	12" x 12" Off-White Beige Floor Tile
103	Woven Insulation on Tank Piping
78	12" x 12" Red Floor Tile
91	Gray Vinyl Sheeting
92	Gray Vinyl Sheeting Adhesive
M	Carpet Mastic
Q	12" x 12" Gray Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 6210:

104	2" x 2" Green Floor Tile
105	2" x 2" Green Floor Tile Mastic
106	2" x 2" Light Gray Floor Tile
107	2" x 2" Light Gray Floor Tile Mastic
108	2" x 2" Dark Gray Floor Tile
109	2" x 2" Dark Gray Floor Tile Mastic
110	Beige w/ Brown Spots Terrazzo
111	CMU Glazed Tile
112	CMU Glazed Tile Mortar
113	1" x 1" Multicolored Floor Tile
114	1" x 1" Multicolored Floor Tile Grout
115	Light Green Terrazzo
116	Green Terrazzo w/ Multicolored Specks
117	Gray Terrazzo w/ Multicolored Specks
118	Light Yellow Multicolored Terrazzo
119	2" x 2" Light Gray Floor Tile
120	2" x 2" Light Gray Floor Tile Grout
121	2' x 2' Dark Gray Wall Tile
122	2' x 2' Dark Gray Wall Tile Grout
123	2' x 2' Yellow Wall Tile
124	2' x 2' Yellow Wall Tile Grout
125	12" x 12" Brown w/ Beige Streaks Floor Tile
126	12" x 12" Brown w/ Beige Streaks Floor Tile Mastic

- 127 5" x 5" Orange Floor Tile
- 128 5" x 5" Orange Floor Tile Grout
- 129 12" x 12" Off White w/ Gray Streaks Floor Tile
- 130 12" x 12" Off White w/ Gray Streaks Floor Tile
Mastic
- 131 12" x 12" Yellow Floor Tile
- 132 12" x 12" Yellow Floor Tile Mastic
- 133 12" x 12" Dark Gray Floor Tile
- 134 12" x 12" Dark Gray Floor Tile Mastic
- 135 12" x 3" Cream Glazed Brick Tile
- 136 12" x 3" Cream Glazed Brick Tile Mortar
- 137 3" x 3" Gray Glazed Brick Tile
- 138 3" x 3" Gray Glazed Brick Tile Mortar
- 139 Wood Flooring

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

008	12" x 12" Light Brown w/ Gray Streaks Floor Tile
021	12" x 12" Light Beige w/ Light Brown Streaks Floor Tile
041	12" x 12" Light Off-White w/ Cream Mix Floor Tile
069	Roofing Material - Non-AHERA
070	Roofing Material - Non-AHERA
071	Boiler Interior Materials
072	Incinerator Interior Materials
074	Purple Carpet Adhesive
075	Floor Tile
076	Floor Tile Mastic
077	Vault Door Core
078	12" x 12" Red Floor Tile
079	12" x 12" Red Floor Tile Mastic
080	Blue Carpet Adhesive
081	Lab Table Tops
082	Chalk Board/Poster Board Adhesive
084	12" x 12" Off-White/Beige Floor Tile
085	12" x 12" Off-White/Beige Floor Tile Mastic
086	12" x 12" Off-White & Beige Floor Tile
087	12" x 12" Off-White & Beige Floor Tile Mastic
089	9" x 9" Red/Gray Floor Tile Mastic
090	Carpet Adhesive
100	12" x 12" White Floor Tile
101	9" x 9" Black Floor Tile
102	12" x 12" Off-White Beige Floor Tile
103	Woven Insulation on Tank Piping
104	2" x 2" Green Floor Tile
105	2" x 2" Green Floor Tile Mastic
106	2" x 2" Light Gray Floor Tile
107	2" x 2" Light Gray Floor Tile Mastic
108	2" x 2" Dark Gray Floor Tile
109	2" x 2" Dark Gray Floor Tile Mastic
110	Beige w/ Brown Spots Terrazzo
111	CMU Glazed Tile
112	CMU Glazed Tile Mortar
113	1" x 1" Multicolored Floor Tile
114	1" x 1" Multicolored Floor Tile Grout
115	Light Green Terrazzo
116	Green Terrazzo w/ Multicolored Specks
117	Gray Terrazzo w/ Multicolored Specks
118	Light Yellow Multicolored Terrazzo

119	2" x 2" Light Gray Floor Tile
120	2" x 2" Light Gray Floor Tile Grout
121	2' x 2' Dark Gray Wall Tile
122	2' x 2' Dark Gray Wall Tile Grout
123	2' x 2' Yellow Wall Tile
124	2' x 2' Yellow Wall Tile Grout
125	12" x 12" Brown w/ Beige Streaks Floor Tile
126	12" x 12" Brown w/ Beige Streaks Floor Tile Mastic
127	5" x 5" Orange Floor Tile
128	5" x 5" Orange Floor Tile Grout
129	12" x 12" Off White w/ Gray Streaks Floor Tile
130	12" x 12" Off White w/ Gray Streaks Floor Tile Mastic
131	12" x 12" Yellow Floor Tile
132	12" x 12" Yellow Floor Tile Mastic
133	12" x 12" Dark Gray Floor Tile
134	12" x 12" Dark Gray Floor Tile Mastic
135	12" x 3" Cream Glazed Brick Tile
136	12" x 3" Cream Glazed Brick Tile Mortar
137	3" x 3" Gray Glazed Brick Tile
138	3" x 3" Gray Glazed Brick Tile Mortar
139	Wood Flooring
91	Gray Vinyl Sheeting
92	Gray Vinyl Sheeting Adhesive
93	2' x 2' Smooth White Ceiling Tile
94	Purple Carpet Adhesive
L	Beige Terrazzo
M	Carpet Mastic
N	9" x 9" White Floor Tile
O	9" x 9" White Floor Tile Mastic
P	12" x 12" Gray Floor Tile
Q	12" x 12" Gray Floor Tile Mastic

The following areas were deemed to be inaccessible:

006	9" x 9" Brick Red w/ Beige Streaks Floor Tile Mastic
011	9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile Mastic
020	Black Border Tile Mastic
022	12" x 12" Light Beige w/ Light Brown Streaks Floor Tile Mastic
023	9" x 9" Leaf Green w/ Beige Streaks Floor Tile
024	9" x 9" Leaf Green w/ Beige Streaks Floor Tile Mastic
026	9" x 9" Cherry Red w/ Beige Streaks Floor Tile

	Mastic
046	9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile Mastic
050	9" x 9" Light Brown w/ Beige Streaks Floor Tile Mastic
059	Black Ceiling Pipe Filler
077	Vault Door Core
087	12" x 12" Off-White & Beige Floor Tile Mastic
94	Purple Carpet Adhesive
O	9" x 9" White Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jose Escobedo, IDPH License # 100-06435. The Management Plan was updated by Jackson Montgomery, IDPH License # 100-20634. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Tilton School Building 6210 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
028	9" x 9" Black w/ Beige Streaks Floor Tile Mastic			ABATED	ABATED	MISC								
029	Exterior Window Caulk			ABATED	ABATED	MISC								
030	Exterior Door Caulk			1908 Building - Exterior	NO_ACBM	MISC								
031	Exterior Brick - Non-AHERA			1908 Building - Exterior	NO_ACBM	MISC								
032	Exterior Brick Mortar - Non-AHERA			1908 Building - Exterior	NO_ACBM	MISC								
033	Exterior (Window Side) Wall Caulk - Non-AHERA			1908 Building - Exterior	NO_ACBM	MISC								
034	Exterior Window Caulk -Non-AHERA			ABATED	ABATED	MISC								
035	Exterior Door Caulk -Non-AHERA			ABATED	ABATED	MISC								
036	Exterior Window Glazing Non-AHERA			1966 Addition - Exterior	NO_ACBM	MISC								
037	Exterior Brick - Non-AHERA			1966 Addition - Exterior	NO_ACBM	MISC								
038	Exterior Brick Mortar - Non-AHERA			1966 Addition - Exterior	NO_ACBM	MISC								
039	9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile			ABATED	ABATED	MISC								
040	9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile Mastic			ABATED	ABATED	MISC								
041	12" x 12" Light Off-White w/ Cream Mix Floor Tile			1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office	ASSUMED	MISC					Yes			
042	12" x 12" Light Off-White w/ Cream Mix Floor Tile Mastic			1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office	CHR	MISC					Yes			
043	Blue Vinyl Baseboard			1966 Addition - Kitchen Serving Area	NO_ACBM	MISC								
044	Blue Vinyl Baseboard Mastic			1966 Addition - Kitchen Serving Area	NO_ACBM	MISC								
045	9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile	1,750	SF	1966 Addition - 1st, 2nd and 3rd Floor Hallways	CHR	MISC	N	LOC	8	SF	No	ACBM with potential for significant damage	5	LOW

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
046	9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile Mastic	1,800	SF	1966 Addition - 1st, 2nd and 3rd Floor Hallways	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
047	Cream Rubber Floor Adhesive			1908 Building - 1st Floor Hallway (West Corridor)	NO_ACBM	MISC								
048	Partition Bridging Floor Compound			1966 Addition - 2nd Floor Hallway (Between Original Building and Addition)	NO_ACBM	MISC								
049	9" x 9" Light Brown w/ Beige Streaks Floor Tile	42	SF	1966 Addition - Room 209	CHR	MISC	N	LOC	5	SF	Yes	ACBM with potential for significant damage	10	LOW
050	9" x 9" Light Brown w/ Beige Streaks Floor Tile Mastic	42	SF	1966 Addition - Room 209	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
051	Countertop Masonite Material			1966 Addition - Lunchroom	NO_ACBM	MISC								
052	Countertop Masonite Backing Insulation			1966 Addition - Lunchroom	NO_ACBM	MISC								
053	Black Vinyl Baseboard			1966 Addition - Main Office Areas	NO_ACBM	MISC								
054	Black Vinyl Baseboard Mastic			1966 Addition - Main Office Areas	NO_ACBM	MISC								
055	Sheet Rock			1966 Addition - Lunchroom	NO_ACBM	MISC								
056	Joint Compound on Sheet Rock			1966 Addition - Lunchroom	NO_ACBM	MISC								
057	Smooth Plaster			1966 Addition - Throughout	NO_ACBM	SURFACE								
058	Rough Ornamental Ceiling Plaster (Acoustical)			1966 Addition - Main Office Areas, Rooms 110, 112, and 114	NO_ACBM	SURFACE								
059	Black Ceiling Pipe Filler	5	LF	1908 Building - 2nd Floor Girls Bathroom	CHR	MISC	N	NONE			No	ACBM with the potential for damage		LOW
060	Pipe Coating Material			ABATED	ABATED	TSI								
061	Stack Fire Brick Material			1908 Building - Boiler Room	NO_ACBM	MISC								
062	Incinerator Brick			1908 Building - Boiler Room	NO_ACBM	MISC								
063	Sink Bottom Caulk Material	12	LF	1966 Addition - Rooms 112, and 212	CHR	SURFACE	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
064	Interior Window Glazing Compound			ABATED	ABATED	MISC								
065	Caulk Between Ceramic and Metal Windows			ABATED	ABATED	MISC								
066	Black Flooring			1908 Building - 1st Floor Teachers' Lounge Next Womens 104 (Museum), Entrance 15	NO_ACBM	MISC								
067	Pink Mix Flooring Material			1908 Building - 1st Floor Teachers' Lounge (Museum)	NO_ACBM	MISC								
068	Stairway Floor Material (Stair Tread)			1908 Building - 3rd Floor by Library	NO_ACBM	MISC								
069	Roofing Material - Non-AHERA			1908 Building Exterior	ASSUMED	MISC								
070	Roofing Material - Non-AHERA			1966 Addition Exterior	ASSUMED	MISC								
071	Boiler Interior Materials	100	SF	1908 Building - Boiler Room	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
072	Incinerator Interior Materials			1908 Building - Boiler Room	ASSUMED	MISC					Yes			
074	Purple Carpet Adhesive			Room 104 (Now Supply Room)	ASSUMED	MISC					No			
075	Floor Tile			Beneath Tiles in First Floor Foyer	ASSUMED	MISC					No			
076	Floor Tile Mastic			Beneath Tiles in First Floor Foyer	ASSUMED	MISC					No			
077	Vault Door Core	25	SF	Office 1966 Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
078	12" x 12" Red Floor Tile			2nd and 3rd Floor Corridors 1908 Building	ASSUMED	MISC					Yes			
079	12" x 12" Red Floor Tile Mastic			2nd and 3rd Floor Corridors 1908 Building	ASSUMED	MISC					Yes			
080	Blue Carpet Adhesive			Room 206 and Library	ASSUMED	MISC					Yes			
081	Lab Table Tops	150	SF	Room 102	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
082	Chalk Board/Poster Board Adhesive			Classrooms	ASSUMED	MISC					Yes			
084	12" x 12" Off-White/Beige Floor Tile			Room 203 Closet and Bathroom	ASSUMED	MISC					Yes			
085	12" x 12" Off-White/Beige Floor Tile			Room 203 Closet	ASSUMED	MISC					Yes			

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Mastic			and Bathroom										
086	12" x 12" Off-White & Beige Floor Tile	935	SF	Auditorium, 1908 Hallway, Room 100	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
087	12" x 12" Off-White & Beige Floor Tile Mastic	935	SF	Auditorium, 1908 Hallway, Room 100	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
088	9" x 9" Red/Gray Floor Tile			101a (Assistant Principal's Office)	ANT	MISC					Yes			
089	9" x 9" Red/Gray Floor Tile Mastic			101a (Assistant Principal's Office)	ASSUMED	MISC					Yes			
090	Carpet Adhesive			Room 206 (Library)	ASSUMED	MISC					No			
100	12" x 12" White Floor Tile			4th Floor Teacher Bathroom	ASSUMED	MISC					Yes			
101	9" x 9" Black Floor Tile			Room 118	ASSUMED	MISC					Yes			
102	12" x 12" Off-White Beige Floor Tile	100	SF	Room 102	ASSUMED	MISC	N	NONE			Yes	ACBM with the potential for damage		LOW
103	Woven Insulation on Tank Piping			Boiler Room	ASSUMED	TSI					Yes			
104	2" x 2" Green Floor Tile	40	SF	Assistant Principal's Office, Counselor's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
105	2" x 2" Green Floor Tile Mastic	40	SF	Assistant Principal's Office, Counselor's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
106	2" x 2" Light Gray Floor Tile	60	SF	Assistant Principal's Office, Counselor's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
107	2" x 2" Light Gray Floor Tile Mastic	60	SF	Assistant Principal's Office, Counselor's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
108	2" x 2" Dark Gray Floor Tile	40	SF	Assistant Principal's Office, Counselor's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
109	2" x 2" Dark Gray Floor Tile Mastic	40	SF	Assistant Principal's Office, Counselor's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
110	Beige w/ Brown Spots Terrazzo	2,000	SF	1996 Building - Throughout Stairwells	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
111	CMU Glazed Tile	40,000	LF	1996 Building - Throughout Stairwells	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
112	CMU Glazed Tile Mortar	40,000	LF	1996 Building - Throughout Stairwells	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
113	1" x 1" Multicolored Floor Tile	1,000	SF	Boys and Girls	ASSUMED	MISC	N	NONE				ACBM with the		LOW

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway								potential for damage		
114	1" x 1" Multicolored Floor Tile Grout	1,000	SF	Boys and Girls Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
115	Light Green Terrazzo	10,000	SF	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
116	Green Terrazzo w/ Multicolored Specks	1,000	SF	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
117	Gray Terrazzo w/ Multicolored Specks	500	SF	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
118	Light Yellow Multicolored Terrazzo	100	SF	Elevator Vestibules 225a, 325a, 407a, 1908 Building Girls and Boys Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
119	2" x 2" Light Gray Floor Tile	500	SF	1908 Building Teachers Bathrooms, Room 103 Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
120	2" x 2" Light Gray Floor Tile Grout	500	SF	1908 Building Teachers Bathroom, Room 103 Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
121	2' x 2' Dark Gray Wall Tile	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
122	2' x 2' Dark Gray Wall Tile Grout	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
123	2' x 2' Yellow Wall Tile	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
124	2' x 2' Yellow Wall Tile Grout	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
125	12" x 12" Brown w/ Beige Streaks Floor	40	SF	Room 307	ASSUMED	MISC	N	NONE				ACBM with the		LOW

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Tile											potential for damage		
126	12" x 12" Brown w/ Beige Streaks Floor Tile Mastic	40	SF	Room 307	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
127	5" x 5" Orange Floor Tile	500	SF	Kitchen	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
128	5" x 5" Orange Floor Tile Grout	500	SF	Kitchen	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
129	12" x 12" Off White w/ Gray Streaks Floor Tile	200	SF	Room 112	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
130	12" x 12" Off White w/ Gray Streaks Floor Tile Mastic	200	SF	Room 112	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
131	12" x 12" Yellow Floor Tile	60	SF	Room 112	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
132	12" x 12" Yellow Floor Tile Mastic	60	SF	Room 112	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
133	12" x 12" Dark Gray Floor Tile	60	SF	Room 112	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
134	12" x 12" Dark Gray Floor Tile Mastic	60	SF	Room 112	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
135	12" x 3" Cream Glazed Brick Tile	3,000	LF	Auditorium, 1908 Building Lobby	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
136	12" x 3" Cream Glazed Brick Tile Mortar	2,000	LF	Auditorium, 1908 Building Lobby	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
137	3" x 3" Gray Glazed Brick Tile	500	LF	Auditorium, 1908 Building Lobby	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
138	3" x 3" Gray Glazed Brick Tile Mortar	500	LF	Auditorium, 1908 Building Lobby	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
139	Wood Flooring	50,000	SF	1908 Building - Throughout Classrooms On All Floors	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
78	12" x 12" Red Floor Tile			DUPLICATE HA							Yes			
91	Gray Vinyl Sheeting			Elevator (1966)	ASSUMED	MISC					Yes			
92	Gray Vinyl Sheeting Adhesive			Elevator (1966)	ASSUMED	MISC					Yes			
93	2' x 2' Smooth White Ceiling Tile	1,750	SF	1966 Building West Main Foyer & Stairway	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
94	Purple Carpet Adhesive	500	SF	1966 Building Room 114	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
A	Tank Insulation			ABATED	ABATED	TSI								
C	Joint Compound on Fiberglass Pipe Insulation	75	LF	1908 Building - Boiler Room, Pipe Chases, and Throughout Facility	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
D	Paperwrap Pipe Insulation	210	LF	1908 Building - Boiler Room, Tunnel, and Possibly in Inaccessible Areas Throughout Facility	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
E	Joint Compound on Paperwrap Pipe Insulation	21	LF	1908 Building - Boiler Room, Tunnel, and Throughout Facility	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
F	Aircell Pipe Insulation	150	LF	1908 Building - Boiler Room, Tank Room, and Throughout Facility	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
H	Mag-Block Pipe Insulation			1908 Building - Throughout Facility	CHR	TSI					No			
I	Joint Compound on Mag-Block Pipe Insulation			1908 Building - Throughout Facility	CHR	TSI					No			
J	Joint Compound on Aircell Pipe Insulation	19	LF	1908 Building - Boiler Room	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
K	Joint Compound on Fiberglass Pipe Insulation	100	LF	1966 Addition - Throughout Facility, Crawl Space	CHR	TSI	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
L	Beige Terrazzo	3,000	SF	Bathrooms	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
M	Carpet Mastic			Room 307, Museum	ASSUMED	MISC					Yes			
N	9" x 9" White Floor Tile	500	SF	Room 118	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
O	9" x 9" White Floor Tile Mastic	500	SF	Room 118	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
P	12" x 12" Gray Floor Tile	700	SF	Room 114	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
Q	12" x 12" Gray Floor Tile Mastic			Room 114	ASSUMED	MISC					Yes			

Chicago Public Schools

School Tilton School Unit 25621 Building ID 6210
Address 223 N. Keeler Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>5/26/2025</u>
Inspector Name <u>Jose Escobedo</u>
<u>100-06435</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	Both Closets Damaged By Entrance Door 1, Pictures taken separately
001A	Damaged Ceiling In Room 204, picture taken separately
002	
005	
006	
007	
008	Material not observed - 2025
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	Material not observed - 2025
022	
023	
024	
025	

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	Material not observed - 2025
042	Material not observed - 2025
043	
044	
045	Damage in 3rd Floor Hallway in front of Girls Bathroom
046	
047	
048	
049	Damage In Janitors closet 324
050	
051	
052	
053	
054	

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
055	
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	
070	
071	
072	Material not observed - 2025
074	Material not observed - 2025
075	Material not observed - 2025
076	Material not observed - 2025
077	
078	Material not observed - 2025
079	Material not observed - 2025
080	Material not observed - 2025
081	
082	Material not observed - 2025
084	Material not observed - 2025
085	Material not observed - 2025

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
086	
087	
088	Material not observed - 2025
089	Material not observed - 2025
090	Material not observed - 2025
100	Material not observed - 2025
101	Material not observed - 2025
102	
103	Material not observed - 2025
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
78	
91	Material not observed - 2025
92	Material not observed - 2025
93	
94	
A	
C	
D	
E	
F	
H	Material not observed - 2025
I	Material not observed - 2025
J	

Chicago Public Schools

School Tilton School **Unit** 25621 **Building ID** 6210
Address 223 N. Keeler **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
K	
L	
M	Material not observed - 2025
N	
O	
P	
Q	Material not observed - 2025

Table II
Management Planner's Review

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	Plaster			1908 Building - Throughout	No ACBM	SURFACE					
001A	Smooth Plaster			1908 Building - Throughout	No ACBM	SURFACE					
002	Rough Plaster			1966 Addition - Throughout	No ACBM	SURFACE					
005	9" x 9" Brick Red w/ Beige Streaks Floor Tile	10,200	SF	1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways, Room 118	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
006	9" x 9" Brick Red w/ Beige Streaks Floor Tile Mastic	10,200	SF	1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways, Room 118	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
007	12" x 12" Light Brown w/ Gray Streaks Floor Tile Mastic			1908 Building - Throughout (See Comments For Locations)	No ACBM	MISC					
008	12" x 12" Light Brown w/ Gray Streaks Floor Tile			1908 Building - Throughout	Assumed	MISC					
009	2' x 2' Rough Ceiling Tile			1908 Building - 1st Floor Hallway	No ACBM	MISC					
010	9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile	16,900	SF	2nd Floor Hallway, 3rd Floor Hallway, Main Office, and Classrooms: 110, 110a, 112, 114, 208-212, 214, 308-312, and 314	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
011	9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile Mastic	16,900	SF	2nd Floor Hallway, 3rd Floor Hallway, Main Office, and Classrooms: 110, 110a, 112, 114, 208-212, 214, 308-312, and 314	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
012	Sheet Rock Board Material			1908 Building - Throughout	No ACBM	MISC					
013	Joint Compound on Sheetrock Board Material			1908 Building - Throughout	No ACBM	MISC					
014	Black Flooring Beneath 9" x 9" Red Floor Tile			1908 Building - Throughout (See Comments For Locations)	No ACBM	MISC					
015	Interior Brick			1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Bathrooms, 1st Floor Storage Room By Room 105	No ACBM	MISC					
016	Interior Brick Mortar			1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Bathrooms, 1st Floor Storage Room By Room 105	No ACBM	MISC					
017	Black Vinyl Baseboard			1908 Building - Throughout, Foyers	No ACBM	MISC					
018	Black Vinyl Baseboard Mastic			1908 Building - Throughout, Foyers	No ACBM	MISC					
019	Black Border Tile	500	SF	1908 Building - Lobby, and 3rd Floor Hallways	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
020	Black Border Tile Mastic	500	SF	1908 Building - Lobby, and 3rd Floor	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Hallways							
021	12" x 12" Light Beige w/ Light Brown Streaks Floor Tile			1908 Building - Rooms 100, 101a, 104, 105, 203, 205, Library, 1st Floor Foyers	Assumed	MISC					
022	12" x 12" Light Beige w/ Light Brown Streaks Floor Tile Mastic	6,000	SF	1908 Building - Rooms 100, 100a, 104, 105, 203, 205, Library, 1st Floor Foyers	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
023	9" x 9" Leaf Green w/ Beige Streaks Floor Tile	6	SF	1908 Building - Room 205, 312	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
024	9" x 9" Leaf Green w/ Beige Streaks Floor Tile Mastic	6	SF	1908 Building - Room 205, 312	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
025	9" x 9" Cherry Red w/ Beige Streaks Floor Tile	90	SF	1908 Building - Engineer's Office, Room 210	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
026	9" x 9" Cherry Red w/ Beige Streaks Floor Tile Mastic	90	SF	1908 Building - Engineer's Office, Room 210	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
027	9" x 9" Black w/ Beige Streaks Floor Tile			ABATED	Abated	MISC					
028	9" x 9" Black w/ Beige Streaks Floor Tile Mastic			ABATED	Abated	MISC					
029	Exterior Window Caulk			ABATED	Abated	MISC					
030	Exterior Door Caulk			1908 Building - Exterior	No ACBM	MISC					
031	Exterior Brick - Non-AHERA			1908 Building - Exterior	No ACBM	MISC					
032	Exterior Brick Mortar - Non-AHERA			1908 Building - Exterior	No ACBM	MISC					
033	Exterior (Window Side) Wall Caulk - Non-AHERA			1908 Building - Exterior	No ACBM	MISC					
034	Exterior Window Caulk -Non-AHERA			ABATED	Abated	MISC					
035	Exterior Door Caulk - Non-AHERA			ABATED	Abated	MISC					
036	Exterior Window Glazing Non-AHERA			1966 Addition - Exterior	No ACBM	MISC					
037	Exterior Brick - Non-AHERA			1966 Addition - Exterior	No ACBM	MISC					
038	Exterior Brick Mortar - Non-AHERA			1966 Addition - Exterior	No ACBM	MISC					
039	9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile			ABATED	Abated	MISC					
040	9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile Mastic			ABATED	Abated	MISC					
041	12" x 12" Light Off-White w/ Cream Mix Floor Tile			1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office	Assumed	MISC					
042	12" x 12" Light Off-White w/ Cream Mix Floor Tile Mastic			1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office	Chrysotile	MISC					
043	Blue Vinyl Baseboard			1966 Addition - Kitchen Serving Area	No ACBM	MISC					
044	Blue Vinyl Baseboard Mastic			1966 Addition - Kitchen Serving Area	No ACBM	MISC					

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
045	9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile	1,750	SF	1966 Addition - 1st, 2nd and 3rd Floor Hallways	Chrysotile	MISC	No	8	SF	5 ACBM with potential for significant damage	Repair
046	9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile Mastic	1,800	SF	1966 Addition - 1st, 2nd and 3rd Floor Hallways	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
047	Cream Rubber Floor Adhesive			1908 Building - 1st Floor Hallway (West Corridor)	No ACBM	MISC					
048	Partition Bridging Floor Compound			1966 Addition - 2nd Floor Hallway (Between Original Building and Addition)	No ACBM	MISC					
049	9" x 9" Light Brown w/ Beige Streaks Floor Tile	42	SF	1966 Addition - Room 209	Chrysotile	MISC	No	5	SF	5 ACBM with potential for significant damage	Remove
050	9" x 9" Light Brown w/ Beige Streaks Floor Tile Mastic	42	SF	1966 Addition - Room 209	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
051	Countertop Masonite Material			1966 Addition - Lunchroom	No ACBM	MISC					
052	Countertop Masonite Backing Insulation			1966 Addition - Lunchroom	No ACBM	MISC					
053	Black Vinyl Baseboard			1966 Addition - Main Office Areas	No ACBM	MISC					
054	Black Vinyl Baseboard Mastic			1966 Addition - Main Office Areas	No ACBM	MISC					
055	Sheet Rock			1966 Addition - Lunchroom	No ACBM	MISC					
056	Joint Compound on Sheet Rock			1966 Addition - Lunchroom	No ACBM	MISC					
057	Smooth Plaster			1966 Addition - Throughout	No ACBM	SURFACE					
058	Rough Ornamental Ceiling Plaster (Acoustical)			1966 Addition - Main Office Areas, Rooms 110, 112, and 114	No ACBM	SURFACE					
059	Black Ceiling Pipe Filler	5	LF	1908 Building - 2nd Floor Girls Bathroom	Chrysotile	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
060	Pipe Coating Material			ABATED	Abated	TSI					
061	Stack Fire Brick Material			1908 Building - Boiler Room	No ACBM	MISC					
062	Incinerator Brick			1908 Building - Boiler Room	No ACBM	MISC					
063	Sink Bottom Caulk Material	12	LF	1966 Addition - Rooms 112, and 212	Chrysotile	SURFACE	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
064	Interior Window Glazing Compound			ABATED	Abated	MISC					
065	Caulk Between Ceramic and Metal Windows			ABATED	Abated	MISC					
066	Black Flooring			1908 Building - 1st Floor Teachers' Lounge Next Womens 104 (Museum), Entrance 15	No ACBM	MISC					
067	Pink Mix Flooring Material			1908 Building - 1st Floor Teachers' Lounge (Museum)	No ACBM	MISC					

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
068	Stairway Floor Material (Stair Tread)			1908 Building - 3rd Floor by Library	No ACBM	MISC					
069	Roofing Material - Non-AHERA			1908 Building Exterior	Assumed	MISC					
070	Roofing Material - Non-AHERA			1966 Addition Exterior	Assumed	MISC					
071	Boiler Interior Materials	100	SF	1908 Building - Boiler Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
072	Incinerator Interior Materials			1908 Building - Boiler Room	Assumed	MISC					
074	Purple Carpet Adhesive			Room 104 (Now Supply Room)	Assumed	MISC					
075	Floor Tile			Beneath Tiles in First Floor Foyer	Assumed	MISC					
076	Floor Tile Mastic			Beneath Tiles in First Floor Foyer	Assumed	MISC					
077	Vault Door Core	25	SF	Office 1966 Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
078	12" x 12" Red Floor Tile			2nd and 3rd Floor Corridors 1908 Building	Assumed	MISC					
079	12" x 12" Red Floor Tile Mastic			2nd and 3rd Floor Corridors 1908 Building	Assumed	MISC					
080	Blue Carpet Adhesive			Room 206 and Library	Assumed	MISC					
081	Lab Table Tops	150	SF	Room 102	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
082	Chalk Board/Poster Board Adhesive			Classrooms	Assumed	MISC					
084	12" x 12" Off-White/Beige Floor Tile			Room 203 Closet and Bathroom	Assumed	MISC					
085	12" x 12" Off-White/Beige Floor Tile Mastic			Room 203 Closet and Bathroom	Assumed	MISC					
086	12" x 12" Off-White & Beige Floor Tile	935	SF	Auditorium, 1908 Hallway, Room 100	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
087	12" x 12" Off-White & Beige Floor Tile Mastic	935	SF	Auditorium, 1908 Hallway, Room 100	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
088	9" x 9" Red/Gray Floor Tile			101a (Assistant Principal's Office)	Anthophyllite	MISC					
089	9" x 9" Red/Gray Floor Tile Mastic			101a (Assistant Principal's Office)	Assumed	MISC					
090	Carpet Adhesive			Room 206 (Library)	Assumed	MISC					
100	12" x 12" White Floor Tile			4th Floor Teacher Bathroom	Assumed	MISC					
101	9" x 9" Black Floor Tile			Room 118	Assumed	MISC					
102	12" x 12" Off-White Beige Floor Tile	100	SF	Room 102	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Woven Insulation on Tank Piping			Boiler Room	Assumed	TSI					
104	2" x 2" Green Floor Tile	40	SF	Assistant Principal's Office, Counselor's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
105	2" x 2" Green Floor Tile Mastic	40	SF	Assistant Principal's Office, Counselor's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
106	2" x 2" Light Gray Floor Tile	60	SF	Assistant Principal's Office, Counselor's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
107	2" x 2" Light Gray Floor Tile Mastic	60	SF	Assistant Principal's Office, Counselor's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Office							
108	2" x 2" Dark Gray Floor Tile	40	SF	Assistant Principal's Office, Counselor's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
109	2" x 2" Dark Gray Floor Tile Mastic	40	SF	Assistant Principal's Office, Counselor's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
110	Beige w/ Brown Spots Terrazzo	2,000	SF	1996 Building - Throughout Stairwells	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
111	CMU Glazed Tile	40,000	LF	1996 Building - Throughout Stairwells	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
112	CMU Glazed Tile Mortar	40,000	LF	1996 Building - Throughout Stairwells	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
113	1" x 1" Multicolored Floor Tile	1,000	SF	Boys and Girls Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
114	1" x 1" Multicolored Floor Tile Grout	1,000	SF	Boys and Girls Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
115	Light Green Terrazzo	10,000	SF	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
116	Green Terrazzo w/ Multicolored Specks	1,000	SF	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
117	Gray Terrazzo w/ Multicolored Specks	500	SF	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
118	Light Yellow Multicolored Terrazzo	100	SF	Elevator Vestibules 225a, 325a, 407a, 1908 Building Girls and Boys Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
119	2" x 2" Light Gray Floor Tile	500	SF	1908 Building Teachers Bathrooms, Room 103 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
120	2" x 2" Light Gray Floor Tile Grout	500	SF	1908 Building Teachers Bathroom, Room 103 Bathroom	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
121	2' x 2' Dark Gray Wall Tile	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
122	2' x 2' Dark Gray Wall Tile Grout	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
123	2' x 2' Yellow Wall Tile	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
124	2' x 2' Yellow Wall Tile Grout	300	LF	1908 Building Teachers Bathroom, Room 103 Bathroom	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
125	12" x 12" Brown w/ Beige Streaks Floor Tile	40	SF	Room 307	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
126	12" x 12" Brown w/ Beige Streaks Floor Tile Mastic	40	SF	Room 307	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
127	5" x 5" Orange Floor Tile	500	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
128	5" x 5" Orange Floor Tile Grout	500	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
129	12" x 12" Off White w/ Gray Streaks Floor Tile	200	SF	Room 112	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
130	12" x 12" Off White w/ Gray Streaks Floor Tile Mastic	200	SF	Room 112	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
131	12" x 12" Yellow Floor Tile	60	SF	Room 112	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
132	12" x 12" Yellow Floor Tile Mastic	60	SF	Room 112	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
133	12" x 12" Dark Gray Floor Tile	60	SF	Room 112	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
134	12" x 12" Dark Gray Floor Tile Mastic	60	SF	Room 112	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
135	12" x 3" Cream Glazed Brick Tile	3,000	LF	Auditorium, 1908 Building Lobby	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
136	12" x 3" Cream Glazed Brick Tile Mortar	2,000	LF	Auditorium, 1908 Building Lobby	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
137	3" x 3" Gray Glazed Brick Tile	500	LF	Auditorium, 1908 Building Lobby	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
138	3" x 3" Gray Glazed Brick Tile Mortar	500	LF	Auditorium, 1908 Building Lobby	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
139	Wood Flooring	50,000	SF	1908 Building - Throughout Classrooms On All Floors	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Red Floor Tile			DUPLICATE HA							Follow O&M Plan
91	Gray Vinyl Sheeting			Elevator (1966)	Assumed	MISC					
92	Gray Vinyl Sheeting Adhesive			Elevator (1966)	Assumed	MISC					
93	2' x 2' Smooth White Ceiling Tile	1,750	SF	1966 Building West Main Foyer & Stairway	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
94	Purple Carpet Adhesive	500	SF	1966 Building Room 114	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Tank Insulation			ABATED	Abated	TSI					
C	Joint Compound on Fiberglass Pipe Insulation	75	LF	1908 Building - Boiler Room, Pipe Chases, and Throughout Facility	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Paperwrap Pipe Insulation	210	LF	1908 Building - Boiler Room, Tunnel, and Possibly in Inaccessible Areas Throughout Facility	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
E	Joint Compound on Paperwrap Pipe Insulation	21	LF	1908 Building - Boiler Room, Tunnel, and Throughout Facility	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
F	Aircell Pipe Insulation	150	LF	1908 Building - Boiler Room, Tank Room, and Throughout Facility	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
H	Mag-Block Pipe Insulation			1908 Building - Throughout Facility	Chrysotile	TSI					
I	Joint Compound on Mag-Block Pipe Insulation			1908 Building - Throughout Facility	Chrysotile	TSI					
J	Joint Compound on Aircell Pipe Insulation	19	LF	1908 Building - Boiler Room	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
K	Joint Compound on Fiberglass Pipe Insulation	100	LF	1966 Addition - Throughout Facility, Crawl Space	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
L	Beige Terrazzo	3,000	SF	Bathrooms	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
M	Carpet Mastic			Room 307, Museum	Assumed	MISC					
N	9" x 9" White Floor Tile	500	SF	Room 118	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
O	9" x 9" White Floor Tile Mastic	500	SF	Room 118	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
P	12" x 12" Gray Floor Tile	700	SF	Room 114	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
Q	12" x 12" Gray Floor Tile Mastic			Room 114	Assumed	MISC					

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Review Date	6/9/2025
Manager Planner Name	Jackson Montgomery
100-20634	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	Repair non-ACBM material.
001A	Repair non-ACBM material.
002	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	
025	
026	
027	
028	

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
029	
030	
031	Non-AHERA
032	Non-AHERA
033	Non-AHERA
034	Non-AHERA
035	Non-AHERA
036	Non-AHERA
037	Non-AHERA
038	Non-AHERA
039	
040	
041	
042	
043	
044	
045	Remove or repair to intact.
046	
047	
048	
049	Remove or repair to intact.
050	
051	
052	
053	
054	
055	

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
056	
057	
058	
059	
060	
061	
062	
063	
064	
065	
066	
067	
068	
069	Non-AHERA
070	Non-AHERA
071	
072	
074	
075	
076	
077	
078	
079	
080	
081	
082	
084	

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
085	
086	
087	
088	
089	
090	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
78	
91	
92	
93	
94	
A	
C	
D	

Chicago Public Schools

School Tilton School

Unit 25621

Building ID 6210

Address 223 N. Keeler

Chicago, IL, 60624

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
E	
F	
H	
I	
J	
K	
L	
M	
N	
O	
P	
Q	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **001**
MATERIAL DESCRIPTION: **Plaster**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Both Closets Damaged By Entrance Door 1, Pictures taken separately**

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **001**

MATERIAL DESCRIPTION: **Plaster**

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Repair non-ACBM material.

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	001A		
MATERIAL DESCRIPTION:	Smooth Plaster		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Damaged Ceiling In Room 204, picture taken separately**

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **001A**

MATERIAL DESCRIPTION: **Smooth Plaster**

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Repair non-ACBM material.

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **Rough Plaster**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **002**

MATERIAL DESCRIPTION: **Rough Plaster**

MATERIAL LOCATION: **1966 Addition - Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	005		
MATERIAL DESCRIPTION:	9" x 9" Brick Red w/ Beige Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways, Room 118		
MATERIAL QUANTITY:	10200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **005**

MATERIAL DESCRIPTION: **9" x 9" Brick Red w/ Beige Streaks Floor Tile**

MATERIAL LOCATION: **1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways, Room 118**

MATERIAL QUANTITY: **10200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	006		
MATERIAL DESCRIPTION:	9" x 9" Brick Red w/ Beige Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways, Room 118		
MATERIAL QUANTITY:	10200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **006**

MATERIAL DESCRIPTION: **9" x 9" Brick Red w/ Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways, Room 118**

MATERIAL QUANTITY: **10200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	007		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Gray Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout (See Comments For Locations)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **007**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1908 Building - Throughout (See Comments For Locations)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	008		
MATERIAL DESCRIPTION:	12" x 12" Light Brown w/ Gray Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **008**

MATERIAL DESCRIPTION: **12" x 12" Light Brown w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 009
MATERIAL DESCRIPTION: 2' x 2' Rough Ceiling Tile

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1908 Building - 1st Floor Hallway

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **009**

MATERIAL DESCRIPTION: **2' x 2' Rough Ceiling Tile**

MATERIAL LOCATION: **1908 Building - 1st Floor Hallway**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	010		
MATERIAL DESCRIPTION:	9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Hallway, 3rd Floor Hallway, Main Office, and Classrooms: 110, 110a, 112, 114, 208-212, 214, 308-312, and 314**

MATERIAL QUANTITY: **16900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **010**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile**

MATERIAL LOCATION: **2nd Floor Hallway, 3rd Floor Hallway, Main Office, and Classrooms: 110, 110a, 112, 114, 208-212, 214, 308-312, and 314**

MATERIAL QUANTITY: **16900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	011		
MATERIAL DESCRIPTION:	9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **2nd Floor Hallway, 3rd Floor Hallway, Main Office, and Classrooms: 110, 110a, 112, 114, 208-212, 214, 308-312, and 314**

MATERIAL QUANTITY: **16900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **011**

MATERIAL DESCRIPTION: **9" x 9" Tan w/ Beige & Chocolate Streaks Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Hallway, 3rd Floor Hallway, Main Office, and Classrooms: 110, 110a, 112, 114, 208-212, 214, 308-312, and 314**

MATERIAL QUANTITY: **16900** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **012**

MATERIAL DESCRIPTION: **Sheet Rock Board Material**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **012**

MATERIAL DESCRIPTION: **Sheet Rock Board Material**

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	013		
MATERIAL DESCRIPTION:	Joint Compound on Sheetrock Board Material		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **013**

MATERIAL DESCRIPTION: **Joint Compound on Sheetrock Board Material**

MATERIAL LOCATION: **1908 Building - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	014		
MATERIAL DESCRIPTION:	Black Flooring Beneath 9" x 9" Red Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout (See Comments For Locations)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **014**

MATERIAL DESCRIPTION: **Black Flooring Beneath 9" x 9" Red Floor Tile**

MATERIAL LOCATION: **1908 Building - Throughout (See Comments For Locations)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **015**

MATERIAL DESCRIPTION: **Interior Brick**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Bathrooms, 1st Floor Storage Room By Room 105**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **015**

MATERIAL DESCRIPTION: **Interior Brick**

MATERIAL LOCATION: **1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Bathrooms, 1st Floor Storage Room By Room 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Bathrooms, 1st Floor Storage Room By Room 105**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **Interior Brick Mortar**

MATERIAL LOCATION: **1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Bathrooms, 1st Floor Storage Room By Room 105**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **017**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout, Foyers**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **017**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **1908 Building - Throughout, Foyers**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **018**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout, Foyers**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **018**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **1908 Building - Throughout, Foyers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	019		
MATERIAL DESCRIPTION:	Black Border Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Lobby, and 3rd Floor Hallways		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:	DAMAGE UNITS: SF		
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **019**

MATERIAL DESCRIPTION: **Black Border Tile**

MATERIAL LOCATION: **1908 Building - Lobby, and 3rd Floor Hallways**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	020		
MATERIAL DESCRIPTION:	Black Border Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Lobby, and 3rd Floor Hallways		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **020**

MATERIAL DESCRIPTION: **Black Border Tile Mastic**

MATERIAL LOCATION: **1908 Building - Lobby, and 3rd Floor Hallways**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	021		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ Light Brown Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Rooms 100, 101a, 104, 105, 203, 205, Library, 1st Floor Foyers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **021**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Light Brown Streaks Floor Tile**

MATERIAL LOCATION: **1908 Building - Rooms 100, 101a, 104, 105, 203, 205, Library, 1st Floor Foyers**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	022		
MATERIAL DESCRIPTION:	12" x 12" Light Beige w/ Light Brown Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Rooms 100, 100a, 104, 105, 203, 205, Library, 1st Floor Foyers		
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **022**

MATERIAL DESCRIPTION: **12" x 12" Light Beige w/ Light Brown Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1908 Building - Rooms 100, 100a, 104, 105, 203, 205, Library, 1st Floor Foyers**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	023		
MATERIAL DESCRIPTION:	9" x 9" Leaf Green w/ Beige Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Room 205, 312		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **023**

MATERIAL DESCRIPTION: **9" x 9" Leaf Green w/ Beige Streaks Floor Tile**

MATERIAL LOCATION: **1908 Building - Room 205, 312**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	024		
MATERIAL DESCRIPTION:	9" x 9" Leaf Green w/ Beige Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Room 205, 312		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **024**

MATERIAL DESCRIPTION: **9" x 9" Leaf Green w/ Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1908 Building - Room 205, 312**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	025		
MATERIAL DESCRIPTION:	9" x 9" Cherry Red w/ Beige Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Engineer's Office, Room 210		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **025**

MATERIAL DESCRIPTION: **9" x 9" Cherry Red w/ Beige Streaks Floor Tile**

MATERIAL LOCATION: **1908 Building - Engineer's Office, Room 210**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	026		
MATERIAL DESCRIPTION:	9" x 9" Cherry Red w/ Beige Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Engineer's Office, Room 210		
MATERIAL QUANTITY:	90	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **026**

MATERIAL DESCRIPTION: **9" x 9" Cherry Red w/ Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1908 Building - Engineer's Office, Room 210**

MATERIAL QUANTITY: **90** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	027		
MATERIAL DESCRIPTION:	9" x 9" Black w/ Beige Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **027**

MATERIAL DESCRIPTION: **9" x 9" Black w/ Beige Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	028		
MATERIAL DESCRIPTION:	9" x 9" Black w/ Beige Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **028**

MATERIAL DESCRIPTION: **9" x 9" Black w/ Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	029		
MATERIAL DESCRIPTION:	Exterior Window Caulk		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **029**

MATERIAL DESCRIPTION: **Exterior Window Caulk**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 030

MATERIAL DESCRIPTION: Exterior Door Caulk

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: No ACBM FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1908 Building - Exterior

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **030**

MATERIAL DESCRIPTION: **Exterior Door Caulk**

MATERIAL LOCATION: **1908 Building - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Exterior**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **031**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **1908 Building - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	032		
MATERIAL DESCRIPTION:	Exterior Brick Mortar - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **032**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **1908 Building - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	033		
MATERIAL DESCRIPTION:	Exterior (Window Side) Wall Caulk - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **033**

MATERIAL DESCRIPTION: **Exterior (Window Side) Wall Caulk - Non-AHERA**

MATERIAL LOCATION: **1908 Building - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: 034

MATERIAL DESCRIPTION: Exterior Window Caulk -Non-AHERA

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: Abated FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: ABATED

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **034**

MATERIAL DESCRIPTION: **Exterior Window Caulk -Non-AHERA**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	035		
MATERIAL DESCRIPTION:	Exterior Door Caulk - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **035**

MATERIAL DESCRIPTION: **Exterior Door Caulk - Non-AHERA**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	036		
MATERIAL DESCRIPTION:	Exterior Window Glazing Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **036**

MATERIAL DESCRIPTION: **Exterior Window Glazing Non-AHERA**

MATERIAL LOCATION: **1966 Addition - Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **037**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Exterior**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **037**

MATERIAL DESCRIPTION: **Exterior Brick - Non-AHERA**

MATERIAL LOCATION: **1966 Addition - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **038**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Exterior**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **038**

MATERIAL DESCRIPTION: **Exterior Brick Mortar - Non-AHERA**

MATERIAL LOCATION: **1966 Addition - Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	039		
MATERIAL DESCRIPTION:	9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **039**

MATERIAL DESCRIPTION: **9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	040		
MATERIAL DESCRIPTION:	9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **040**

MATERIAL DESCRIPTION: **9" x 9" Beige & Brown w/ Chocolate Streaks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	041		
MATERIAL DESCRIPTION:	12" x 12" Light Off-White w/ Cream Mix Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **041**

MATERIAL DESCRIPTION: **12" x 12" Light Off-White w/ Cream Mix Floor Tile**

MATERIAL LOCATION: **1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	042	
MATERIAL DESCRIPTION:	12" x 12" Light Off-White w/ Cream Mix Floor Tile Mastic	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Chrysotile	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: 1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: Material not observed - 2025

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **042**

MATERIAL DESCRIPTION: **12" x 12" Light Off-White w/ Cream Mix Floor Tile Mastic**

MATERIAL LOCATION: **1966 Addition - Lunchroom, Main Office Bathroom/Vault, Kitchen Serving Area, Kitchen Office**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **043**

MATERIAL DESCRIPTION: **Blue Vinyl Baseboard**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Kitchen Serving Area**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **043**

MATERIAL DESCRIPTION: **Blue Vinyl Baseboard**

MATERIAL LOCATION: **1966 Addition - Kitchen Serving Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	044		
MATERIAL DESCRIPTION:	Blue Vinyl Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Kitchen Serving Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **044**

MATERIAL DESCRIPTION: **Blue Vinyl Baseboard Mastic**

MATERIAL LOCATION: **1966 Addition - Kitchen Serving Area**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	045		
MATERIAL DESCRIPTION:	9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1966 Addition - 1st, 2nd and 3rd Floor Hallways		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in 3rd Floor Hallway in front of Girls Bathroom		

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **045**

MATERIAL DESCRIPTION: **9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile**

MATERIAL LOCATION: **1966 Addition - 1st, 2nd and 3rd Floor Hallways**

MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **8** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	046		
MATERIAL DESCRIPTION:	9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1966 Addition - 1st, 2nd and 3rd Floor Hallways		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **046**

MATERIAL DESCRIPTION: **9" x 9" Chocolate Mix w/ Off-White Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1966 Addition - 1st, 2nd and 3rd Floor Hallways**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	047		
MATERIAL DESCRIPTION:	Cream Rubber Floor Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - 1st Floor Hallway (West Corridor)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **047**

MATERIAL DESCRIPTION: **Cream Rubber Floor Adhesive**

MATERIAL LOCATION: **1908 Building - 1st Floor Hallway (West Corridor)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **048**

MATERIAL DESCRIPTION: **Partition Bridging Floor Compound**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - 2nd Floor Hallway (Between Original Building and Addition)**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **048**

MATERIAL DESCRIPTION: **Partition Bridging Floor Compound**

MATERIAL LOCATION: **1966 Addition - 2nd Floor Hallway (Between Original Building and Addition)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	049		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/ Beige Streaks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Water		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1966 Addition - Room 209		
MATERIAL QUANTITY:	42	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:	Damage In Janitors closet 324		

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **049**

MATERIAL DESCRIPTION: **9" x 9" Light Brown w/ Beige Streaks Floor Tile**

MATERIAL LOCATION: **1966 Addition - Room 209**

MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **5** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	050		
MATERIAL DESCRIPTION:	9" x 9" Light Brown w/ Beige Streaks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1966 Addition - Room 209		
MATERIAL QUANTITY:	42	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **050**

MATERIAL DESCRIPTION: **9" x 9" Light Brown w/ Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **1966 Addition - Room 209**

MATERIAL QUANTITY: **42** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Countertop Masonite Material**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **051**

MATERIAL DESCRIPTION: **Countertop Masonite Material**

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	052		
MATERIAL DESCRIPTION:	Countertop Masonite Backing Insulation		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **052**

MATERIAL DESCRIPTION: **Countertop Masonite Backing Insulation**

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **053**
MATERIAL DESCRIPTION: **Black Vinyl Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Main Office Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **053**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard**

MATERIAL LOCATION: **1966 Addition - Main Office Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **054**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Main Office Areas**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **054**

MATERIAL DESCRIPTION: **Black Vinyl Baseboard Mastic**

MATERIAL LOCATION: **1966 Addition - Main Office Areas**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **055**

MATERIAL DESCRIPTION: **Sheet Rock**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **055**

MATERIAL DESCRIPTION: **Sheet Rock**

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	056		
MATERIAL DESCRIPTION:	Joint Compound on Sheet Rock		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **056**

MATERIAL DESCRIPTION: **Joint Compound on Sheet Rock**

MATERIAL LOCATION: **1966 Addition - Lunchroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	057		
MATERIAL DESCRIPTION:	Smooth Plaster		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Throughout**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **057**

MATERIAL DESCRIPTION: **Smooth Plaster**

MATERIAL LOCATION: **1966 Addition - Throughout**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	058		
MATERIAL DESCRIPTION:	Rough Ornamental Ceiling Plaster (Acoustical)		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	No ACBM	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition - Main Office Areas, Rooms 110, 112, and 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **058**

MATERIAL DESCRIPTION: **Rough Ornamental Ceiling Plaster (Acoustical)**

MATERIAL LOCATION: **1966 Addition - Main Office Areas, Rooms 110, 112, and 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	059		
MATERIAL DESCRIPTION:	Black Ceiling Pipe Filler		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - 2nd Floor Girls Bathroom		
MATERIAL QUANTITY:	5	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **059**

MATERIAL DESCRIPTION: **Black Ceiling Pipe Filler**

MATERIAL LOCATION: **1908 Building - 2nd Floor Girls Bathroom**

MATERIAL QUANTITY: **5** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **060**
MATERIAL DESCRIPTION: **Pipe Coating Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **060**

MATERIAL DESCRIPTION: **Pipe Coating Material**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **061**
MATERIAL DESCRIPTION: **Stack Fire Brick Material**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **061**

MATERIAL DESCRIPTION: **Stack Fire Brick Material**

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **062**
MATERIAL DESCRIPTION: **Incinerator Brick**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **062**

MATERIAL DESCRIPTION: **Incinerator Brick**

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	063		
MATERIAL DESCRIPTION:	Sink Bottom Caulk Material		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1966 Addition - Rooms 112, and 212		
MATERIAL QUANTITY:	12	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **063**

MATERIAL DESCRIPTION: **Sink Bottom Caulk Material**

MATERIAL LOCATION: **1966 Addition - Rooms 112, and 212**

MATERIAL QUANTITY: **12** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	064		
MATERIAL DESCRIPTION:	Interior Window Glazing Compound		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **064**

MATERIAL DESCRIPTION: **Interior Window Glazing Compound**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **065**

MATERIAL DESCRIPTION: **Caulk Between Ceramic and Metal Windows**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **065**

MATERIAL DESCRIPTION: **Caulk Between Ceramic and Metal Windows**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **066**

MATERIAL DESCRIPTION: **Black Flooring**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - 1st Floor Teachers' Lounge Next Womens 104 (Museum), Entrance 15**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **066**

MATERIAL DESCRIPTION: **Black Flooring**

MATERIAL LOCATION: **1908 Building - 1st Floor Teachers' Lounge Next Womens 104 (Museum), Entrance 15**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **067**

MATERIAL DESCRIPTION: **Pink Mix Flooring Material**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - 1st Floor Teachers' Lounge (Museum)**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **067**

MATERIAL DESCRIPTION: **Pink Mix Flooring Material**

MATERIAL LOCATION: **1908 Building - 1st Floor Teachers' Lounge (Museum)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **068**

MATERIAL DESCRIPTION: **Stairway Floor Material (Stair Tread)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - 3rd Floor by Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **068**

MATERIAL DESCRIPTION: **Stairway Floor Material (Stair Tread)**

MATERIAL LOCATION: **1908 Building - 3rd Floor by Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	069		
MATERIAL DESCRIPTION:	Roofing Material - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **069**

MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**

MATERIAL LOCATION: **1908 Building Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	070		
MATERIAL DESCRIPTION:	Roofing Material - Non-AHERA		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1966 Addition Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **070**

MATERIAL DESCRIPTION: **Roofing Material - Non-AHERA**

MATERIAL LOCATION: **1966 Addition Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	071		
MATERIAL DESCRIPTION:	Boiler Interior Materials		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Boiler Room		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **071**

MATERIAL DESCRIPTION: **Boiler Interior Materials**

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	072		
MATERIAL DESCRIPTION:	Incinerator Interior Materials		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **072**

MATERIAL DESCRIPTION: **Incinerator Interior Materials**

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **074**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 104 (Now Supply Room)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **074**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive**

MATERIAL LOCATION: **Room 104 (Now Supply Room)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **075**

MATERIAL DESCRIPTION: **Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Beneath Tiles in First Floor Foyer**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **075**

MATERIAL DESCRIPTION: **Floor Tile**

MATERIAL LOCATION: **Beneath Tiles in First Floor Foyer**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **076**

MATERIAL DESCRIPTION: **Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Beneath Tiles in First Floor Foyer**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **076**

MATERIAL DESCRIPTION: **Floor Tile Mastic**

MATERIAL LOCATION: **Beneath Tiles in First Floor Foyer**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	077		
MATERIAL DESCRIPTION:	Vault Door Core		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Office 1966 Building		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **077**

MATERIAL DESCRIPTION: **Vault Door Core**

MATERIAL LOCATION: **Office 1966 Building**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	078		
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Corridors 1908 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **078**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors 1908 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	079		
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **2nd and 3rd Floor Corridors 1908 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **079**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **2nd and 3rd Floor Corridors 1908 Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	080		
MATERIAL DESCRIPTION:	Blue Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 206 and Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **080**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **Room 206 and Library**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	081		
MATERIAL DESCRIPTION:	Lab Table Tops		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **081**

MATERIAL DESCRIPTION: **Lab Table Tops**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	082		
MATERIAL DESCRIPTION:	Chalk Board/Poster Board Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **082**

MATERIAL DESCRIPTION: **Chalk Board/Poster Board Adhesive**

MATERIAL LOCATION: **Classrooms**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	084		
MATERIAL DESCRIPTION:	12" x 12" Off-White/Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203 Closet and Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **084**

MATERIAL DESCRIPTION: **12" x 12" Off-White/Beige Floor Tile**

MATERIAL LOCATION: **Room 203 Closet and Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	085		
MATERIAL DESCRIPTION:	12" x 12" Off-White/Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 203 Closet and Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **085**

MATERIAL DESCRIPTION: **12" x 12" Off-White/Beige Floor Tile Mastic**

MATERIAL LOCATION: **Room 203 Closet and Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	086		
MATERIAL DESCRIPTION:	12" x 12" Off-White & Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, 1908 Hallway, Room 100		
MATERIAL QUANTITY:	935	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **086**

MATERIAL DESCRIPTION: **12" x 12" Off-White & Beige Floor Tile**

MATERIAL LOCATION: **Auditorium, 1908 Hallway, Room 100**

MATERIAL QUANTITY: **935** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	087		
MATERIAL DESCRIPTION:	12" x 12" Off-White & Beige Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Auditorium, 1908 Hallway, Room 100		
MATERIAL QUANTITY:	935	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **087**

MATERIAL DESCRIPTION: **12" x 12" Off-White & Beige Floor Tile Mastic**

MATERIAL LOCATION: **Auditorium, 1908 Hallway, Room 100**

MATERIAL QUANTITY: **935** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	088		
MATERIAL DESCRIPTION:	9" x 9" Red/Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Anthophyllite	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **101a (Assistant Principal's Office)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **088**

MATERIAL DESCRIPTION: **9" x 9" Red/Gray Floor Tile**

MATERIAL LOCATION: **101a (Assistant Principal's Office)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	089		
MATERIAL DESCRIPTION:	9" x 9" Red/Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **101a (Assistant Principal's Office)**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **089**

MATERIAL DESCRIPTION: **9" x 9" Red/Gray Floor Tile Mastic**

MATERIAL LOCATION: **101a (Assistant Principal's Office)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **090**
MATERIAL DESCRIPTION: **Carpet Adhesive**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 206 (Library)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **090**

MATERIAL DESCRIPTION: **Carpet Adhesive**

MATERIAL LOCATION: **Room 206 (Library)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	100		
MATERIAL DESCRIPTION:	12" x 12" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **4th Floor Teacher Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **100**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **4th Floor Teacher Bathroom**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	101		
MATERIAL DESCRIPTION:	9" x 9" Black Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 118**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **101**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

MATERIAL LOCATION: **Room 118**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	102		
MATERIAL DESCRIPTION:	12" x 12" Off-White Beige Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 102		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **102**

MATERIAL DESCRIPTION: **12" x 12" Off-White Beige Floor Tile**

MATERIAL LOCATION: **Room 102**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	103		
MATERIAL DESCRIPTION:	Woven Insulation on Tank Piping		
HISTORICAL AHERA DAMAGE CATEGORY	Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Woven Insulation on Tank Piping**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	78
MATERIAL DESCRIPTION:	12" x 12" Red Floor Tile
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage
HISTORICAL DAMAGE REASON:	Physical Damage
HISTORICAL RESPONSE ACTION:	Remove
ASBESTOS TYPE:	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **DUPLICATE HA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **78**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **DUPLICATE HA**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Remove

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	91	
MATERIAL DESCRIPTION:	Gray Vinyl Sheeting	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Elevator (1966)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **91**

MATERIAL DESCRIPTION: **Gray Vinyl Sheeting**

MATERIAL LOCATION: **Elevator (1966)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	92	
MATERIAL DESCRIPTION:	Gray Vinyl Sheeting Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage	
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Assumed	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Elevator (1966)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **92**

MATERIAL DESCRIPTION: **Gray Vinyl Sheeting Adhesive**

MATERIAL LOCATION: **Elevator (1966)**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	93		
MATERIAL DESCRIPTION:	2' x 2' Smooth White Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1966 Building West Main Foyer & Stairway		
MATERIAL QUANTITY:	1750	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **93**

MATERIAL DESCRIPTION: **2' x 2' Smooth White Ceiling Tile**

MATERIAL LOCATION: **1966 Building West Main Foyer & Stairway**

MATERIAL QUANTITY: **1750** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	94		
MATERIAL DESCRIPTION:	Purple Carpet Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1966 Building Room 114		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **Purple Carpet Adhesive**

MATERIAL LOCATION: **1966 Building Room 114**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Tank Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Tank Insulation**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	C		
MATERIAL DESCRIPTION:	Joint Compound on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Boiler Room, Pipe Chases, and Throughout Facility		
MATERIAL QUANTITY:	75	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **1908 Building - Boiler Room, Pipe Chases, and Throughout Facility**

MATERIAL QUANTITY: **75** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	D		
MATERIAL DESCRIPTION:	Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1908 Building - Boiler Room, Tunnel, and Possibly in Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Paperwrap Pipe Insulation**

MATERIAL LOCATION: **1908 Building - Boiler Room, Tunnel, and Possibly in Inaccessible Areas Throughout Facility**

MATERIAL QUANTITY: **210** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	E		
MATERIAL DESCRIPTION:	Joint Compound on Paperwrap Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1908 Building - Boiler Room, Tunnel, and Throughout Facility**

MATERIAL QUANTITY: **21** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Joint Compound on Paperwrap Pipe Insulation**

MATERIAL LOCATION: **1908 Building - Boiler Room, Tunnel, and Throughout Facility**

MATERIAL QUANTITY: **21** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	F		
MATERIAL DESCRIPTION:	Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Boiler Room, Tank Room, and Throughout Facility		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	LF
DAMAGE QUANTITY:	DAMAGE UNITS: LF		
COMMENTS:			

Inspector's Signature: _____ Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **F**

MATERIAL DESCRIPTION: **Aircell Pipe Insulation**

MATERIAL LOCATION: **1908 Building - Boiler Room, Tank Room, and Throughout Facility**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Mag-Block Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Mag-Block Pipe Insulation**

MATERIAL LOCATION: **1908 Building - Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Joint Compound on Mag-Block Pipe Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1908 Building - Throughout Facility**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **I**

MATERIAL DESCRIPTION: **Joint Compound on Mag-Block Pipe Insulation**

MATERIAL LOCATION: **1908 Building - Throughout Facility**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	J		
MATERIAL DESCRIPTION:	Joint Compound on Aircell Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	1908 Building - Boiler Room		
MATERIAL QUANTITY:	19	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **J**

MATERIAL DESCRIPTION: **Joint Compound on Aircell Pipe Insulation**

MATERIAL LOCATION: **1908 Building - Boiler Room**

MATERIAL QUANTITY: **19** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	K		
MATERIAL DESCRIPTION:	Joint Compound on Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable thermal system insulating ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1966 Addition - Throughout Facility, Crawl Space**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **K**

MATERIAL DESCRIPTION: **Joint Compound on Fiberglass Pipe Insulation**

MATERIAL LOCATION: **1966 Addition - Throughout Facility, Crawl Space**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	L		
MATERIAL DESCRIPTION:	Beige Terrazzo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathrooms		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **L**

MATERIAL DESCRIPTION: **Beige Terrazzo**

MATERIAL LOCATION: **Bathrooms**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	M		
MATERIAL DESCRIPTION:	Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 307, Museum**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **M**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 307, Museum**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	N		
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 118		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **N**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile**

MATERIAL LOCATION: **Room 118**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	O		
MATERIAL DESCRIPTION:	9" x 9" White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 118		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **O**

MATERIAL DESCRIPTION: **9" x 9" White Floor Tile Mastic**

MATERIAL LOCATION: **Room 118**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	P		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 114		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **P**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Room 114**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	Q		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 114**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Material not observed - 2025**

Inspector's Signature: _____ Date: **05/26/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUILDING ID:	6210
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Jackson Montgomery		
SCHOOL NAME:	Tilton School	REVIEW DATE:	6/9/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **Q**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 114**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	129			
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Gray Streaks Floor Tile			
MATERIAL LOCATION:	Room 112			
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **129**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Gray Streaks Floor Tile**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	133			
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Floor Tile			
MATERIAL LOCATION:	Room 112			
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **133**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	111			
MATERIAL DESCRIPTION:	CMU Glazed Tile			
MATERIAL LOCATION:	1996 Building - Throughout Stairwells			
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **111**

MATERIAL DESCRIPTION: **CMU Glazed Tile**

MATERIAL LOCATION: **1996 Building - Throughout Stairwells**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	121			
MATERIAL DESCRIPTION:	2' x 2' Dark Gray Wall Tile			
MATERIAL LOCATION:	1908 Building Teachers Bathroom, Room 103 Bathroom			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **121**

MATERIAL DESCRIPTION: **2' x 2' Dark Gray Wall Tile**

MATERIAL LOCATION: **1908 Building Teachers Bathroom, Room 103 Bathroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	122			
MATERIAL DESCRIPTION:	2' x 2' Dark Gray Wall Tile Grout			
MATERIAL LOCATION:	1908 Building Teachers Bathroom, Room 103 Bathroom			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **122**

MATERIAL DESCRIPTION: **2' x 2' Dark Gray Wall Tile Grout**

MATERIAL LOCATION: **1908 Building Teachers Bathroom, Room 103 Bathroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	128		
MATERIAL DESCRIPTION:	5" x 5" Orange Floor Tile Grout		
MATERIAL LOCATION:	Kitchen		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **128**

MATERIAL DESCRIPTION: **5" x 5" Orange Floor Tile Grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	132			
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile Mastic			
MATERIAL LOCATION:	Room 112			
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **132**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile Mastic**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	134			
MATERIAL DESCRIPTION:	12" x 12" Dark Gray Floor Tile Mastic			
MATERIAL LOCATION:	Room 112			
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **134**

MATERIAL DESCRIPTION: **12" x 12" Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	139		
MATERIAL DESCRIPTION:	Wood Flooring		
MATERIAL LOCATION:	1908 Building - Throughout Classrooms On All Floors		
MATERIAL QUANTITY:	50000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **139**

MATERIAL DESCRIPTION: **Wood Flooring**

MATERIAL LOCATION: **1908 Building - Throughout Classrooms On All Floors**

MATERIAL QUANTITY: **50000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	123			
MATERIAL DESCRIPTION:	2' x 2' Yellow Wall Tile			
MATERIAL LOCATION:	1908 Building Teachers Bathroom, Room 103 Bathroom			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **123**

MATERIAL DESCRIPTION: **2' x 2' Yellow Wall Tile**

MATERIAL LOCATION: **1908 Building Teachers Bathroom, Room 103 Bathroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	104			
MATERIAL DESCRIPTION:	2" x 2" Green Floor Tile			
MATERIAL LOCATION:	Assistant Principal's Office, Counselor's Office			
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **104**

MATERIAL DESCRIPTION: **2" x 2" Green Floor Tile**

MATERIAL LOCATION: **Assistant Principal's Office, Counselor's Office**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	107			
MATERIAL DESCRIPTION:	2" x 2" Light Gray Floor Tile Mastic			
MATERIAL LOCATION:	Assistant Principal's Office, Counselor's Office			
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **107**

MATERIAL DESCRIPTION: **2" x 2" Light Gray Floor Tile Mastic**

MATERIAL LOCATION: **Assistant Principal's Office, Counselor's Office**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	114		
MATERIAL DESCRIPTION:	1" x 1" Multicolored Floor Tile Grout		
MATERIAL LOCATION:	Boys and Girls Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **114**

MATERIAL DESCRIPTION: **1" x 1" Multicolored Floor Tile Grout**

MATERIAL LOCATION: **Boys and Girls Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	115			
MATERIAL DESCRIPTION:	Light Green Terrazzo			
MATERIAL LOCATION:	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance			
MATERIAL QUANTITY:	10000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **115**

MATERIAL DESCRIPTION: **Light Green Terrazzo**

MATERIAL LOCATION: **Corridors Near Stairs and Stairwell 1966 Building, Main Entrance**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	118			
MATERIAL DESCRIPTION:	Light Yellow Multicolored Terrazzo			
MATERIAL LOCATION:	Elevator Vestibules 225a, 325a, 407a, 1908 Building Girls and Boys Bathroom			
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **118**

MATERIAL DESCRIPTION: **Light Yellow Multicolored Terrazzo**

MATERIAL LOCATION: **Elevator Vestibules 225a, 325a, 407a, 1908 Building Girls and Boys Bathroom**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	124			
MATERIAL DESCRIPTION:	2' x 2' Yellow Wall Tile Grout			
MATERIAL LOCATION:	1908 Building Teachers Bathroom, Room 103 Bathroom			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **124**

MATERIAL DESCRIPTION: **2' x 2' Yellow Wall Tile Grout**

MATERIAL LOCATION: **1908 Building Teachers Bathroom, Room 103 Bathroom**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	126			
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Beige Streaks Floor Tile Mastic			
MATERIAL LOCATION:	Room 307			
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **126**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Beige Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	105		
MATERIAL DESCRIPTION:	2" x 2" Green Floor Tile Mastic		
MATERIAL LOCATION:	Assistant Principal's Office, Counselor's Office		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **105**

MATERIAL DESCRIPTION: **2" x 2" Green Floor Tile Mastic**

MATERIAL LOCATION: **Assistant Principal's Office, Counselor's Office**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	130		
MATERIAL DESCRIPTION:	12" x 12" Off White w/ Gray Streaks Floor Tile Mastic		
MATERIAL LOCATION:	Room 112		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **130**

MATERIAL DESCRIPTION: **12" x 12" Off White w/ Gray Streaks Floor Tile Mastic**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	131			
MATERIAL DESCRIPTION:	12" x 12" Yellow Floor Tile			
MATERIAL LOCATION:	Room 112			
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **131**

MATERIAL DESCRIPTION: **12" x 12" Yellow Floor Tile**

MATERIAL LOCATION: **Room 112**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	112			
MATERIAL DESCRIPTION:	CMU Glazed Tile Mortar			
MATERIAL LOCATION:	1996 Building - Throughout Stairwells			
MATERIAL QUANTITY:	40000	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **112**

MATERIAL DESCRIPTION: **CMU Glazed Tile Mortar**

MATERIAL LOCATION: **1996 Building - Throughout Stairwells**

MATERIAL QUANTITY: **40000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	113			
MATERIAL DESCRIPTION:	1" x 1" Multicolored Floor Tile			
MATERIAL LOCATION:	Boys and Girls Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **113**

MATERIAL DESCRIPTION: **1" x 1" Multicolored Floor Tile**

MATERIAL LOCATION: **Boys and Girls Bathrooms Throughout 1966 Building, Doors 2, 3 Entryway**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	119			
MATERIAL DESCRIPTION:	2" x 2" Light Gray Floor Tile			
MATERIAL LOCATION:	1908 Building Teachers Bathrooms, Room 103 Bathroom			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **119**

MATERIAL DESCRIPTION: **2" x 2" Light Gray Floor Tile**

MATERIAL LOCATION: **1908 Building Teachers Bathrooms, Room 103 Bathroom**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	125			
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Beige Streaks Floor Tile			
MATERIAL LOCATION:	Room 307			
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **125**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Beige Streaks Floor Tile**

MATERIAL LOCATION: **Room 307**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	137			
MATERIAL DESCRIPTION:	3" x 3" Gray Glazed Brick Tile			
MATERIAL LOCATION:	Auditorium, 1908 Building Lobby			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	LF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **137**

MATERIAL DESCRIPTION: **3" x 3" Gray Glazed Brick Tile**

MATERIAL LOCATION: **Auditorium, 1908 Building Lobby**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	116			
MATERIAL DESCRIPTION:	Green Terrazzo w/ Multicolored Specks			
MATERIAL LOCATION:	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **116**

MATERIAL DESCRIPTION: **Green Terrazzo w/ Multicolored Specks**

MATERIAL LOCATION: **Corridors Near Stairs and Stairwell 1966 Building, Main Entrance**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	120		
MATERIAL DESCRIPTION:	2" x 2" Light Gray Floor Tile Grout		
MATERIAL LOCATION:	1908 Building Teachers Bathroom, Room 103 Bathroom		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **120**

MATERIAL DESCRIPTION: **2" x 2" Light Gray Floor Tile Grout**

MATERIAL LOCATION: **1908 Building Teachers Bathroom, Room 103 Bathroom**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	138		
MATERIAL DESCRIPTION:	3" x 3" Gray Glazed Brick Tile Mortar		
MATERIAL LOCATION:	Auditorium, 1908 Building Lobby		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **138**

MATERIAL DESCRIPTION: **3" x 3" Gray Glazed Brick Tile Mortar**

MATERIAL LOCATION: **Auditorium, 1908 Building Lobby**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	136		
MATERIAL DESCRIPTION:	12" x 3" Cream Glazed Brick Tile Mortar		
MATERIAL LOCATION:	Auditorium, 1908 Building Lobby		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **136**

MATERIAL DESCRIPTION: **12" x 3" Cream Glazed Brick Tile Mortar**

MATERIAL LOCATION: **Auditorium, 1908 Building Lobby**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	109			
MATERIAL DESCRIPTION:	2" x 2" Dark Gray Floor Tile Mastic			
MATERIAL LOCATION:	Assistant Principal's Office, Counselor's Office			
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **109**

MATERIAL DESCRIPTION: **2" x 2" Dark Gray Floor Tile Mastic**

MATERIAL LOCATION: **Assistant Principal's Office, Counselor's Office**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	110			
MATERIAL DESCRIPTION:	Beige w/ Brown Spots Terrazzo			
MATERIAL LOCATION:	1996 Building - Throughout Stairwells			
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **110**

MATERIAL DESCRIPTION: **Beige w/ Brown Spots Terrazzo**

MATERIAL LOCATION: **1996 Building - Throughout Stairwells**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	117			
MATERIAL DESCRIPTION:	Gray Terrazzo w/ Multicolored Specks			
MATERIAL LOCATION:	Corridors Near Stairs and Stairwell 1966 Building, Main Entrance			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **117**

MATERIAL DESCRIPTION: **Gray Terrazzo w/ Multicolored Specks**

MATERIAL LOCATION: **Corridors Near Stairs and Stairwell 1966 Building, Main Entrance**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	135		
MATERIAL DESCRIPTION:	12" x 3" Cream Glazed Brick Tile		
MATERIAL LOCATION:	Auditorium, 1908 Building Lobby		
MATERIAL QUANTITY:	3000	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **135**

MATERIAL DESCRIPTION: **12" x 3" Cream Glazed Brick Tile**

MATERIAL LOCATION: **Auditorium, 1908 Building Lobby**

MATERIAL QUANTITY: **3000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	106		
MATERIAL DESCRIPTION:	2" x 2" Light Gray Floor Tile		
MATERIAL LOCATION:	Assistant Principal's Office, Counselor's Office		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **106**

MATERIAL DESCRIPTION: **2" x 2" Light Gray Floor Tile**

MATERIAL LOCATION: **Assistant Principal's Office, Counselor's Office**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	108		
MATERIAL DESCRIPTION:	2" x 2" Dark Gray Floor Tile		
MATERIAL LOCATION:	Assistant Principal's Office, Counselor's Office		
MATERIAL QUANTITY:	40	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **108**

MATERIAL DESCRIPTION: **2" x 2" Dark Gray Floor Tile**

MATERIAL LOCATION: **Assistant Principal's Office, Counselor's Office**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: *06/09/2025*

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	25621	BUIDLING ID:	6210
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Tilton School	INSPECTION DATE:	5/26/2025		
ADDRESS:	223 N. Keeler	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	127			
MATERIAL DESCRIPTION:	5" x 5" Orange Floor Tile			
MATERIAL LOCATION:	Kitchen			
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 05/26/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25621** BUIDLING ID: **6210**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Jackson Montgomery**

SCHOOL NAME: **Tilton School** REVIEW DATE: **6/9/2025**

ADDRESS: **223 N. Keeler** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **127**

MATERIAL DESCRIPTION: **5" x 5" Orange Floor Tile**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: *Jackson Montgomery* Date: **06/09/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jose Escobedo


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2409132637
Course Date: 9/13/2024
Exam Date: 9/13/2024
Expiration Date: 9/13/2025




Issue Date: 9/13/2024


Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

Jose Escobedo

Air Sampling Professional, Illinois Licensed Building Inspector, Asbestos Project Manager





ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	1/11/2026
INSPECTOR	9/13/2025

PROJECT MANAGER	1/11/2026
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Jackson Montgomery

Illinois Licensed Building Inspector, Air Sampling Professional, Management Planner



ENDORSEMENTS

INSPECTOR

TC EXPIRES

2/22/2025

ENDORSEMENTS

TC EXPIRES

10/29/2025

AIR SAMPLING PROFESSIONAL

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



2200 Vandalia Street, Collinsville, IL 62234 * Phone: 618-855-8764

Environmental and Occupational Safety & Health Training

Does hereby certify

Jackson Montgomery

600 W. Van Buren St., Suite 500, Chicago, IL 60607



*Has successfully completed and passed the course examination with at least
70% for accreditation under AHERA (Title II)*

Asbestos Management Planner Initial

Class Date: 10/28-29/2024

Examination Date: 10/29/2024

STC Certificate Number: STC-20241029-000101AMPI

Certification Expiration: 10/29/2025

A handwritten signature in black ink that reads 'David M. Mendoza'.

David M. Mendoza – President/Training Director

Certified Environmental Specialist

OSHA Authorized Instructor

This training course is accredited by the Illinois Department of Public Health and the Missouri Department of Natural Resources

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed