

ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-2127
SCHOOL NAME: Cather School
ADDRESS OF SCHOOL: 2908 W. Washington
CITY: Chicago, IL, 60612

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED 12/1/2022

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 7/29/2025 ENROLLMENT 324
IDPH INSPECTOR LICENSE NUMBER: 100-06435
IDPH LICENSED INSPECTOR NAME (Please Print): Jose Escobedo
IDPH MP LICENSE NUMBER: 100-18488
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Mike Serio

DESIGNATED PERSON (Please Print): Richard J.Schleyer PHONE: (773) 251-7074

Richard J. Schleyer 8/8/2025

Signature of Designated Person

Date

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE-YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Cather School

2908 W. Washington
Chicago, IL, 60612

Unit: 26021
Building ID: 6730

IDPH ID Number: 14-016-2990-2127

REPORT DATE:
Friday, August 08, 2025

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Chicago, IL, 60607

Phone (312) 762-2900

Fax (312) 782-5145

**DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW**

08/08/2025

Mr. Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr. Culbertson:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3, 4 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 26021 Region: 03 IDPH ID: 14-016-2990-2127

School: Cather School Building ID: 6730

Address: 2908 W. Washington

Chicago, IL, 60612

Building Contact: Suggs, Marshaun Contact Phone: 3126089218

Current Building Owners: Chicago Public Schools

Reinspection Date: 7/29/2025

Review Date: 08/08/2025

Inspector: Jose Escobedo

Inspector IDPH License: 100-06435

Management Planner: Mike Serio

Management Planner IDPH License: 100-18488

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Mike Serio
100-18488

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: August 08, 2025

RE: Cather School, Unit 26021
2908 W. Washington
Chicago, IL, 60612

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at Cather School , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at Cather School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Richard J.Schleyer, the designated Local Education Authority's Designated Person at (773) 251-7074 .

Table of Contents

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Cather School Unit: 26021 Region: 03
Address: 2908 W. Washington Chicago, IL, 60612
IDPH ID: 14-016-2990-2127 Building ID: 6730
Contact: Suggs, Marshaun Phone: 3126089218

2. Description of Facility

Original Construction: 1962 Additional Construction:
Total Square Footage: 52579 No of Floors: 2
Current Occupancy: 324

3. LEA Designated Person

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Doug McCormick
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

5. Inspector

Inspector Name: Jose Escobedo

Inspector IDPH license # 100-06435
Reinspection Date: 7/29/2025

Signature: _____
Date: 7/29/2025

6. Management Planner

Management Planner Name: Mike Serio

Management Planner IDPH license # 100-18488

7. Review Date: 08/08/2025

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature: Richard J. Schlegel

Signature:

Date: 8/8/2025

Name: Richard J. Schleyer

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Cather School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

- A. The following HAs have changed assessment categories for Building 6730:

B. The following new homogenous areas have been identified for Building 6730:

203	12" x 12" White w/ Gray Specks Floor Tile
204	12" x 12" White w/ Gray Specks Floor Tile Mastic
205	12" x 12" Black Mottled Floor Tile
206	12" x 12" Black Mottled Floor Tile Mastic
207	12" x 12" Blue Mottled Floor Tile
208	12" x 12" Blue Mottled Floor Tile Mastic
209	12" x 12" Red Ceramic Floor Tile w/ Grout
210	CMU and Mortar
211	1' x 1' White Pinholes and Gouges Ceiling Tile
212	1' x 1' White Pinhole w/ Holes Ceiling Tile
213	1' x 1' White Pinholes and Deep Fissures Ceiling Tile
214	1' x 1' White Pinholes and Light Fissures Ceiling Tile
215	Masonite Ceiling Paneling
216	Wire Insulation
217	Light Reflector Insulation

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

11	12" x 12" Tan Floor Tile
12	12" x 12" Tan Floor Tile Mastic
17	Interior Of Boilers
18	Roof Material - Non-AHERA
19	Vault Door (Insulation)
2	12" x 12" Brown Floor Tile
20	Vibration Collar (Cloth)
201	Light Gray w/ White & Black Specks Linoleum
202	Light Gray w/ White & Black Specks Linoleum Adhesive
203	12" x 12" White w/ Gray Specks Floor Tile
204	12" x 12" White w/ Gray Specks Floor Tile Mastic
205	12" x 12" Black Mottled Floor Tile
206	12" x 12" Black Mottled Floor Tile Mastic
207	12" x 12" Blue Mottled Floor Tile
208	12" x 12" Blue Mottled Floor Tile Mastic
209	12" x 12" Red Ceramic Floor Tile w/ Grout
210	CMU and Mortar
211	1' x 1' White Pinholes and Gouges Ceiling Tile
212	1' x 1' White Pinhole w/ Holes Ceiling Tile
213	1' x 1' White Pinholes and Deep Fissures Ceiling Tile
214	1' x 1' White Pinholes and Light Fissures Ceiling Tile
215	Masonite Ceiling Paneling
216	Wire Insulation
217	Light Reflector Insulation
30	Acoustical Spray-on Fireproofing
31	12" x 12" Brown w/ Speckles Floor Tile
32	12" x 12" Brown w/ Speckles Floor Tile Mastic
34	Terrazzo
35	Red Carpet Mastic
36	12" x 12" Gray Floor Tile
36M	12" x 12" Gray Floor Tile Mastic
37	Tan Baseboard
37M	Tan Baseboard Mastic
38	12" x 12" Aqua & White Floor Tile
38M	12" x 12" Aqua & White Floor Tile Mastic
39	Ceramic Tile & Grout
39M	Ceramic Tile Mastic
40	6" x 6" White Floor Tile
40 M	6" x 6" White Floor Tile Mastic

41	2' x 2' White Pinholes and Gouges Ceiling Tiles
43	12" x 12" Green and Blue Floor Tile
43M	12" x 12" Green and Blue Floor Tile Mastic
45	1' x 1' White Textured Ceiling Tile
46	Tongue and Groove Wooden Floor
49	12" x 12" Beige w/ White Specks Floor Tile
50	12" x 12" Beige w/ White Specks Floor Tile Mastic
51	12" x 12" Light Gray w/ White Specks Floor Tile
52	12" x 12" Light Gray w/ White Specks Floor Tile Mastic
54	12" x 12" Purple w/ Light Purple Specks Floor Tile
55	12" x 12" Purple w/ Light Purple Specks Floor Tile Mastic
56	12" x 12" White w/ Gray Specks Floor Tile
57	12" x 12" White w/ Gray Specks Floor Tile Mastic
58	9" x 9" Gray w/ Black Specks Floor Tile
59	9" x 9" Gray w/ Black Specks Floor Tile Mastic
64	9" x 9" Dark Brown & Beige Specks Floor Tile
65	9" x 9" Dark Brown w/ Beige Specks Floor Tile Mastic
66	12" x 12" Dark Grays Floor Tile
67	12" x 12" Dark Grays Floor Tile Mastic
68	12" x 12" Light Gray Floor Tile
69	12" x 12" Light Gray Floor Tile Mastic

The following areas were deemed to be inaccessible:

016	White Fiberglass Pipe Insulation
10	9" x 9" Gray Floor Tile Mastic
12	12" x 12" Tan Floor Tile Mastic
17	Interior Of Boilers
19	Vault Door (Insulation)
202	Light Gray w/ White & Black Specks Linoleum Adhesive
204	12" x 12" White w/ Gray Specks Floor Tile Mastic
206	12" x 12" Black Mottled Floor Tile Mastic
208	12" x 12" Blue Mottled Floor Tile Mastic
216	Wire Insulation
217	Light Reflector Insulation
32	12" x 12" Brown w/ Speckles Floor Tile Mastic
35	Red Carpet Mastic
36M	12" x 12" Gray Floor Tile Mastic
37M	Tan Baseboard Mastic
38M	12" x 12" Aqua & White Floor Tile Mastic
39	Ceramic Tile & Grout
39M	Ceramic Tile Mastic

40 M	6" x 6" White Floor Tile Mastic
43M	12" x 12" Green and Blue Floor Tile Mastic
50	12" x 12" Beige w/ White Specks Floor Tile Mastic
52	12" x 12" Light Gray w/ White Specks Floor Tile Mastic
55	12" x 12" Purple w/ Light Purple Specks Floor Tile Mastic
57	12" x 12" White w/ Gray Specks Floor Tile Mastic
65	9" x 9" Dark Brown w/ Beige Specks Floor Tile Mastic
67	12" x 12" Dark Grays Floor Tile Mastic
69	12" x 12" Light Gray Floor Tile Mastic
7	9" x 9" Brown/Gray Floor Tile Mastic
8	12" x 12" Brown Floor Tile Mastic

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Jose Escobedo, IDPH License # 100-06435. The Management Plan was updated by Mike Serio, IDPH License # 100-18488. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Cather School Building 6730 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I
Inspector's Reinspection Findings

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
016	White Fiberglass Pipe Insulation	10,000	LF	Throughout Building as Replacement Insulation - Not a Suspect Material	NOT_TESTED	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
1	9" x 9" Brown/Gray Floor Tile	700	SF	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
10	9" x 9" Gray Floor Tile Mastic	150	SF	A210 Wellness Room, MDF Room (A210)	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
11	12" x 12" Tan Floor Tile	400	SF	Room 111 & Engineer's Office	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		HIGH
12	12" x 12" Tan Floor Tile Mastic	400	SF	Room 111 & Engineer's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
13	Baseboard			Throughout Building	NO_ACBM	MISC								
14	Baseboard Mastic			Throughout Building	NO_ACBM	MISC								
15	Curtain Wall Insulation			Rooms 105, 106, 207, 217, 218	NO_ACBM	TSI								
16	Window Glaze (Interior)			Throughout Building	NO_ACBM	MISC								
17	Interior Of Boilers	800	SF	Boiler Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
18	Roof Material - Non-AHERA			Exterior	ASSUMED	MISC								
19	Vault Door (Insulation)	30	SF	Main Office	ASSUMED	TSI	N	NONE				ACBM with the potential for damage		LOW
2	12" x 12" Brown Floor Tile	1,800	SF	Room 116	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
20	Vibration Collar (Cloth)	60	LF	Mechanical Areas and Boiler Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
201	Light Gray w/ White & Black Specks Linoleum	2,000	SF	Room 201	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
202	Light Gray w/ White & Black Specks Linoleum Adhesive	2,000	SF	Room 201	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
203	12" x 12" White w/ Gray Specks Floor Tile	300	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218,	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				219, 220, Unisex Bathroom Vestibule										
204	12" x 12" White w/ Gray Specks Floor Tile Mastic	600	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220, Unisex Bathroom Vestibule	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
205	12" x 12" Black Mottled Floor Tile	2,500	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
206	12" x 12" Black Mottled Floor Tile Mastic	6,000	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
207	12" x 12" Blue Mottled Floor Tile	2,500	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		HIGH
208	12" x 12" Blue Mottled Floor Tile Mastic	2,500	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
209	12" x 12" Red Ceramic Floor Tile w/ Grout	800	SF	Kitchen	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
21	12" x 12" White Floor Tile			ABATED	ABATED	MISC								
210	CMU and Mortar	20,000	SF	Through Out Classroom and Hallway Walls	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
211	1' x 1' White Pinholes and Gouges Ceiling Tile	1,000	SF	Throughout 2nd Floor Corridor	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
212	1' x 1' White Pinhole w/ Holes Ceiling Tile	400	SF	East and South 2nd Floor Corridors (Patching)	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
213	1' x 1' White Pinholes and Deep Fissures Ceiling Tile	250	SF	South and West 2nd Floor Corridors	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
214	1' x 1' White Pinholes and Light Fissures Ceiling Tile	1,500	SF	2nd Floor East Corridor	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
215	Masonite Ceiling Paneling	50	SF	2nd Floor Boys Bathroom Next to 218, 2nd Floor Girls Bathroom Next to 219	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
216	Wire Insulation	6	LF	2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
217	Light Reflector Insulation	2	SF	2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
22	12" x 12" White Floor Tile Mastic			ABATED	ABATED	MISC								
23	Gray Baseboard			Room 111	NO_ACBM	MISC								
24	Gray Baseboard Mastic			Room 111	NO_ACBM	MISC								
25	Plaster Ceiling			Room 111	NO_ACBM	SURFACE								
26	1' x 1' White Ceiling Tile (Pinhole)	1,000	SF	Throughout Classrooms On Soffits, Closets	AMO	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
27	Carpet Mastic			Room 111	NO_ACBM	MISC								
28	Interior Window Caulk			Throughout Interior of Building	NO_ACBM	MISC								
29	Exterior Window Caulk - Non-AHERA			Exterior of Building	NO_ACBM	MISC								
30	Acoustical Spray-on Fireproofing	62,000	SF	Throughout Building Above Ceilings in Classrooms and Hallways	ASSUMED	SURFACE	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW
31	12" x 12" Brown w/ Speckles Floor Tile	2,400	SF	Basement Entrance, Lunchroom, Rooms 109, 111, 116	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
32	12" x 12" Brown w/ Speckles Floor Tile Mastic	2,400	SF	Basement Entrance, Lunchroom, Rooms 109, 111, 116	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
33	Blue Carpet Adhesive			ABATED	ABATED	MISC								
34	Terrazo	1,600	SF	Stairs in Gym, Stairwell &	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Auditorium										
35	Red Carpet Mastic	500	SF	Main Office, Principal Office, and Room 238, 1st Floor Conference Room	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
36	12" x 12" Gray Floor Tile	17,000	SF	Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
36M	12" x 12" Gray Floor Tile Mastic	17,000	SF	Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
37	Tan Baseboard	100	SF	Room 111, 109	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
37M	Tan Baseboard Mastic	100	SF	Room 111, 109	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
38	12" x 12" Aqua & White Floor Tile	150	SF	Room 111	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
38M	12" x 12" Aqua & White Floor Tile Mastic	150	SF	Room 111	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
39	Ceramic Tile & Grout	500	SF	Bathrooms Walls	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
39M	Ceramic Tile Mastic	500	SF	Bathroom Walls	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
40	6" x 6" White Floor Tile	200	SF	Bathrooms in Room 111	ASSUMED	MISC	Y	NONE			Any remaining friable ACBM or friable suspect ACBM			HIGH
40 M	6" x 6" White Floor Tile Mastic	200	SF	Bathrooms in Room 111	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
41	2' x 2' White Pinholes and Gouges Ceiling Tiles	1,700	SF	Main Office, 105, 118, 1st Floor Corridor, Kitchen, Faculty Lounge, 103A	ASSUMED	MISC	Y	NONE			Any remaining friable ACBM or friable suspect ACBM			LOW
42	12" x 12" Red Floor Tile			ABATED	ABATED	MISC								
42M	12" x 12" Red Floor Tile Mastic			ABATED	ABATED	MISC								
43	12" x 12" Green and Blue Floor Tile	150	SF	Room 111	ASSUMED	MISC	N	NONE			ACBM with the potential for damage			LOW
43M	12" x 12" Green and Blue Floor Tile Mastic	150	SF	Room 111	ASSUMED	MISC	N	NONE			ACBM with the			LOW

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
44	9" x 9" Floor Tile			ABATED	ABATED	MISC						potential for damage		
45	1' x 1' White Textured Ceiling Tile	25	SF	Southwest Corner of 2nd Floor Corridor	ASSUMED	MISC	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		MODERATE
46	Tongue and Groove Wooden Floor	7,500	SF	Gymnasium	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
47	9" x 9" Black w/ White Specks Floor Tile			ABATED	ABATED	MISC								
48	9" x 9" Black w/ White Specks Floor Tile Mastic			ABATED	ABATED	MISC								
49	12" x 12" Beige w/ White Specks Floor Tile	4	SF	Rooms 209 (Patches)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
5	Transite Ceiling Panel			ABATED	ABATED	MISC								
50	12" x 12" Beige w/ White Specks Floor Tile Mastic	4	SF	Rooms 209 (Patches)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
51	12" x 12" Light Gray w/ White Specks Floor Tile	20	SF	Rooms 101 (Patches)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
52	12" x 12" Light Gray w/ White Specks Floor Tile Mastic	20	SF	Rooms 101 (Patches)	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
54	12" x 12" Purple w/ Light Purple Specks Floor Tile	2,000	SF	Room 215	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
55	12" x 12" Purple w/ Light Purple Specks Floor Tile Mastic	2,000	SF	Room 215	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
56	12" x 12" White w/ Gray Specks Floor Tile	2,000	SF	Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
57	12" x 12" White w/ Gray Specks Floor Tile Mastic	2,000	SF	Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
58	9" x 9" Gray w/ Black Specks Floor Tile	575	SF	Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105 Storage Room	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW
59	9" x 9" Gray w/ Black Specks Floor Tile Mastic	575	SF	Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105	ASSUMED	MISC	N	NONE				ACBM with the potential for damage		LOW

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	Floor Tile													
71	12" x 12" Rose Gold w/ Brown Specks Floor Tile Mastic			ABATED	ABATED	MISC								
8	12" x 12" Brown Floor Tile Mastic	2,400	SF	Room 116	CHR	MISC	N	NONE				ACBM with the potential for damage		LOW
9	9" x 9" Gray Floor Tile	150	SF	A210 Wellness Room, MDF Room (A210)	CHR	MISC	N	LOC	2	SF		ACBM with potential for significant damage	5	LOW
A	Fiberglass Pipe Fittings	125	LF	Concealed within Pipe Chases	CHR	TSI	Y	NONE				Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School Cather School Unit 26021 Building ID 6730
Address 2908 W. Washington Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date <u>7/29/2025</u>
Inspector Name <u>Jose Escobedo</u>
<u>100-06435</u> <u>5/15/2026</u>
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
016	
1	
10	
11	Not observed in room 112
12	
13	
14	
15	
16	
17	Boiler were replaced with Fulton electric boilers
18	
19	
2	Not observed in room 115, 117
20	
201	
202	
203	
204	
205	
206	
207	
208	
209	
21	

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
210	
211	
212	
213	
214	
215	
216	
217	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	Not observed in room 115, 117
32	
33	
34	
35	
36	
36M	
37	
37M	
38	
38M	
39	

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
39M	
40	
40 M	
41	
42	
42M	
43	
43M	
44	
45	
46	
47	
48	
49	Not observed in room 216 and 213, 114
5	
50	Not observed in room 216 and 213, 114
51	Not observed in room 114
52	Not observed in room 114
54	
55	
56	Not observed in room 113
57	Not observed in room 113
58	
59	
6	
60	
61	
62	
63	

Chicago Public Schools

School Cather School **Unit** 26021 **Building ID** 6730
Address 2908 W. Washington **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
64	
65	
66	
67	
68	
69	
7	
70	
71	
8	Not observed in room 115, 117
9	Damage in MDF Room (A210)
A	

Table II
Management Planner's Review

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
016	White Fiberglass Pipe Insulation	10,000	LF	Throughout Building as Replacement Insulation - Not a Suspect Material	Not Tested	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
1	9" x 9" Brown/Gray Floor Tile	700	SF	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9" x 9" Gray Floor Tile Mastic	150	SF	A210 Wellness Room, MDF Room (A210)	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12" x 12" Tan Floor Tile	400	SF	Room 111 & Engineer's Office	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
12	12" x 12" Tan Floor Tile Mastic	400	SF	Room 111 & Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13	Baseboard			Throughout Building	No ACBM	MISC					
14	Baseboard Mastic			Throughout Building	No ACBM	MISC					
15	Curtain Wall Insulation			Rooms 105, 106, 207, 217, 218	No ACBM	TSI					
16	Window Glaze (Interior)			Throughout Building	No ACBM	MISC					
17	Interior Of Boilers	800	SF	Boiler Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Roof Material - Non-AHERA			Exterior	Assumed	MISC					
19	Vault Door (Insulation)	30	SF	Main Office	Assumed	TSI	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
2	12" x 12" Brown Floor Tile	1,800	SF	Room 116	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
20	Vibration Collar (Cloth)	60	LF	Mechanical Areas and Boiler Room	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
201	Light Gray w/ White & Black Specks Linoleum	2,000	SF	Room 201	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
202	Light Gray w/ White & Black Specks Linoleum Adhesive	2,000	SF	Room 201	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
203	12" x 12" White w/ Gray Specks Floor Tile	300	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220, Unisex Bathroom Vestibule	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
204	12" x 12" White w/ Gray Specks Floor Tile Mastic	600	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220, Unisex Bathroom Vestibule	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
205	12" x 12" Black Mottled Floor Tile	2,500	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
206	12" x 12" Black Mottled Floor Tile Mastic	6,000	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
207	12" x 12" Blue Mottled Floor Tile	2,500	SF	Rooms 101, 107, 108, 110, 112, 113,	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220							
208	12" x 12" Blue Mottled Floor Tile Mastic	2,500	SF	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
209	12" x 12" Red Ceramic Floor Tile w/ Grout	800	SF	Kitchen	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
21	12" x 12" White Floor Tile			ABATED	Abated	MISC					
210	CMU and Mortar	20,000	SF	Through Out Classroom and Hallway Walls	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
211	1' x 1' White Pinholes and Gouges Ceiling Tile	1,000	SF	Throughout 2nd Floor Corridor	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
212	1' x 1' White Pinhole w/ Holes Ceiling Tile	400	SF	East and South 2nd Floor Corridors (Patching)	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
213	1' x 1' White Pinholes and Deep Fissures Ceiling Tile	250	SF	South and West 2nd Floor Corridors	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
214	1' x 1' White Pinholes and Light Fissures Ceiling Tile	1,500	SF	2nd Floor East Corridor	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
215	Masonite Ceiling Paneling	50	SF	2nd Floor Boys Bathroom Next to 218, 2nd Floor Girls Bathroom Next to 219	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
216	Wire Insulation	6	LF	2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
217	Light Reflector Insulation	2	SF	2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
22	12" x 12" White Floor Tile Mastic			ABATED	Abated	MISC					
23	Gray Baseboard			Room 111	No ACBM	MISC					
24	Gray Baseboard Mastic			Room 111	No ACBM	MISC					
25	Plaster Ceiling			Room 111	No ACBM	SURFACE					
26	1' x 1' White Ceiling Tile (Pinhole)	1,000	SF	Throughout Classrooms On Soffits, Closets	Amosite	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
27	Carpet Mastic			Room 111	No ACBM	MISC					
28	Interior Window Caulk			Throughout Interior of Building	No ACBM	MISC					
29	Exterior Window Caulk - Non-AHERA			Exterior of Building	No ACBM	MISC					
30	Acoustical Spray-on Fireproofing	62,000	SF	Throughout Building Above Ceilings in Classrooms and Hallways	Assumed	SURFACE	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
31	12" x 12" Brown w/ Speckles Floor Tile	2,400	SF	Basement Entrance, Lunchroom, Rooms 109, 111, 116	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
32	12" x 12" Brown w/ Speckles Floor Tile Mastic	2,400	SF	Basement Entrance, Lunchroom, Rooms 109, 111, 116	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Blue Carpet Adhesive			ABATED	Abated	MISC					
34	Terrazzo	1,600	SF	Stairs in Gym, Stairwell & Auditorium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
35	Red Carpet Mastic	500	SF	Main Office, Principal Office, and Room 238, 1st Floor Conference Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36	12" x 12" Gray Floor Tile	17,000	SF	Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
36M	12" x 12" Gray Floor Tile Mastic	17,000	SF	Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37	Tan Baseboard	100	SF	Room 111, 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
37M	Tan Baseboard Mastic	100	SF	Room 111, 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38	12" x 12" Aqua & White Floor Tile	150	SF	Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
38M	12" x 12" Aqua & White Floor Tile Mastic	150	SF	Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
39	Ceramic Tile & Grout	500	SF	Bathrooms Walls	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
39M	Ceramic Tile Mastic	500	SF	Bathroom Walls	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
40	6" x 6" White Floor Tile	200	SF	Bathrooms in Room 111	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
40 M	6" x 6" White Floor Tile Mastic	200	SF	Bathrooms in Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
41	2' x 2' White Pinholes and Gouges Ceiling Tiles	1,700	SF	Main Office, 105, 118, 1st Floor Corridor, Kitchen, Faculty Lounge, 103A	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
42	12" x 12" Red Floor Tile			ABATED	Abated	MISC					
42M	12" x 12" Red Floor Tile Mastic			ABATED	Abated	MISC					
43	12" x 12" Green and Blue Floor Tile	150	SF	Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
43M	12" x 12" Green and Blue Floor Tile Mastic	150	SF	Room 111	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
44	9" x 9" Floor Tile			ABATED	Abated	MISC					
45	1' x 1' White Textured Ceiling Tile	25	SF	Southwest Corner of 2nd Floor Corridor	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
46	Tongue and Groove Wooden Floor	7,500	SF	Gymnasium	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9" x 9" Black w/ White Specks Floor Tile			ABATED	Abated	MISC					
48	9" x 9" Black w/ White Specks Floor Tile Mastic			ABATED	Abated	MISC					
49	12" x 12" Beige w/ White Specks Floor Tile	4	SF	Rooms 209 (Patches)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
5	Transite Ceiling Panel			ABATED	Abated	MISC					
50	12" x 12" Beige w/ White Specks Floor Tile Mastic	4	SF	Rooms 209 (Patches)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12" x 12" Light Gray w/ White Specks Floor Tile	20	SF	Rooms 101 (Patches)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12" x 12" Light Gray w/ White Specks Floor Tile Mastic	20	SF	Rooms 101 (Patches)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
54	12" x 12" Purple w/ Light Purple Specks Floor Tile	2,000	SF	Room 215	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
55	12" x 12" Purple w/ Light Purple Specks Floor Tile Mastic	2,000	SF	Room 215	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
56	12" x 12" White w/ Gray Specks Floor Tile	2,000	SF	Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
57	12" x 12" White w/ Gray Specks Floor Tile Mastic	2,000	SF	Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
58	9" x 9" Gray w/ Black Specks Floor Tile	575	SF	Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105 Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
59	9" x 9" Gray w/ Black Specks Floor Tile Mastic	575	SF	Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105 Storage Room	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
6	1' x 1' Random Dot Ceiling Tile	100	SF	Bathroom Next to Engineer's Office, Boys Bathroom Across From Faculty Lunch & Lounge, A210 Corridor, 2nd Floor Boys Bathroom Next to 218, 2nd Floor Girls Bathroom Next to 219	Chrysotile	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
60	9" x 9" Rose Gold w/ Brown Specks Floor Tile			ABATED	Abated	MISC					
61	9" x 9" Rose Gold w/ Brown Specks Floor Tile Mastic			ABATED	Abated	MISC					
62	9" x 9" Beige w/ Brown & White Specks Floor Tile			ABATED	Abated	MISC					
63	9" x 9" Beige w/ Brown & White Specks Floor Tile Mastic			ABATED	Abated	MISC					
64	9" x 9" Dark Brown & Beige Specks Floor Tile	1,000	SF	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
65	9" x 9" Dark Brown w/ Beige Specks Floor Tile Mastic	1,000	SF	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
66	12" x 12" Dark Grays Floor Tile	2,500	SF	Room 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
67	12" x 12" Dark Grays Floor Tile Mastic	2,500	SF	Room 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" Light Gray Floor Tile	2,500	SF	Rooms 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
69	12" x 12" Light Gray Floor Tile Mastic	2,500	SF	Rooms 109	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
7	9" x 9" Brown/Gray Floor Tile Mastic	700	SF	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
70	12" x 12" Rose Gold w/ Brown Specks Floor Tile			ABATED	Abated	MISC					
71	12" x 12" Rose Gold w/ Brown Specks Floor Tile Mastic			ABATED	Abated	MISC					
8	12" x 12" Brown Floor Tile Mastic	2,400	SF	Room 116	Chrysotile	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
9	9" x 9" Gray Floor Tile	150	SF	A210 Wellness Room, MDF Room (A210)	Chrysotile	MISC	No	2	SF	5 ACBM with potential for significant damage	Remove
A	Fiberglass Pipe Fittings	125	LF	Concealed within Pipe Chases	Chrysotile	TSI	Yes		LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	8/8/2025
Manager Planner Name	Mike Serio
100-18488	5/15/2026
Manager IDPH License No/Expiration	

HA Number	Management Comments
016	
1	
10	
11	
12	
13	
14	
15	
16	
17	
18	Non-AHERA
19	
2	
20	
201	
202	
203	
204	
205	
206	
207	
208	
209	
21	

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
210	
211	
212	
213	
214	
215	
216	
217	
22	
23	
24	
25	
26	
27	
28	
29	Non-AHERA
30	
31	
32	
33	
34	
35	
36	
36M	
37	
37M	
38	

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
38M	
39	
39M	
40	
40 M	
41	
42	
42M	
43	
43M	
44	Sample to determine ACM content prior to disturbance.
45	
46	
47	
48	
49	
5	
50	
51	
52	
54	
55	
56	
57	
58	
59	
6	

Chicago Public Schools

School Cather School

Unit 26021

Building ID 6730

Address 2908 W. Washington

Chicago, IL, 60612

Region 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
7	
70	
71	
8	
9	Remove or repair to intact.
A	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	016		
MATERIAL DESCRIPTION:	White Fiberglass Pipe Insulation		
HISTORICAL AHERA DAMAGE CATEGORY	7		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Not Tested	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Building as Replacement Insulation - Not a Suspect Material**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **016**

MATERIAL DESCRIPTION: **White Fiberglass Pipe Insulation**

MATERIAL LOCATION: **Throughout Building as Replacement Insulation - Not a Suspect Material**

MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	1		
MATERIAL DESCRIPTION:	9" x 9" Brown/Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **1**

MATERIAL DESCRIPTION: **9" x 9" Brown/Gray Floor Tile**

MATERIAL LOCATION: **2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	10		
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A210 Wellness Room, MDF Room (A210)		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **10**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile Mastic**

MATERIAL LOCATION: **A210 Wellness Room, MDF Room (A210)**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	11		
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Room 111 & Engineer's Office		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 112		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **11**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile**

MATERIAL LOCATION: **Room 111 & Engineer's Office**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	12		
MATERIAL DESCRIPTION:	12" x 12" Tan Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111 & Engineer's Office		
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **12**

MATERIAL DESCRIPTION: **12" x 12" Tan Floor Tile Mastic**

MATERIAL LOCATION: **Room 111 & Engineer's Office**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**
MATERIAL DESCRIPTION: **Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **13**

MATERIAL DESCRIPTION: **Baseboard**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **14**

MATERIAL DESCRIPTION: **Baseboard Mastic**

MATERIAL LOCATION: **Throughout Building**


MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Curtain Wall Insulation**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 105, 106, 207, 217, 218**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **15**

MATERIAL DESCRIPTION: **Curtain Wall Insulation**

MATERIAL LOCATION: **Rooms 105, 106, 207, 217, 218**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Window Glaze (Interior)**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **16**

MATERIAL DESCRIPTION: **Window Glaze (Interior)**

MATERIAL LOCATION: **Throughout Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	17		
MATERIAL DESCRIPTION:	Interior Of Boilers		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Boiler Room		
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Boiler were replaced with Fulton electric boilers		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **17**

MATERIAL DESCRIPTION: **Interior Of Boilers**

MATERIAL LOCATION: **Boiler Room**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Roof Material - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Assumed** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **Roof Material - Non-AHERA**

MATERIAL LOCATION: **Exterior**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	19		
MATERIAL DESCRIPTION:	Vault Door (Insulation)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office		
MATERIAL QUANTITY:	30	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **19**

MATERIAL DESCRIPTION: **Vault Door (Insulation)**

MATERIAL LOCATION: **Main Office**

MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	2		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 116		
MATERIAL QUANTITY:	1800	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 115, 117		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **2**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile**

MATERIAL LOCATION: **Room 116**

MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	20		
MATERIAL DESCRIPTION:	Vibration Collar (Cloth)		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Mechanical Areas and Boiler Room		
MATERIAL QUANTITY:	60	MATERIAL UNITS:	LF
DAMAGE QUANTITY:		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **20**

MATERIAL DESCRIPTION: **Vibration Collar (Cloth)**

MATERIAL LOCATION: **Mechanical Areas and Boiler Room**

MATERIAL QUANTITY: **60** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: DAMAGE UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	201		
MATERIAL DESCRIPTION:	Light Gray w/ White & Black Specks Linoleum		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **201**

MATERIAL DESCRIPTION: **Light Gray w/ White & Black Specks Linoleum**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	202		
MATERIAL DESCRIPTION:	Light Gray w/ White & Black Specks Linoleum Adhesive		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 201		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **202**

MATERIAL DESCRIPTION: **Light Gray w/ White & Black Specks Linoleum Adhesive**

MATERIAL LOCATION: **Room 201**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**
MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Abated** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **22**

MATERIAL DESCRIPTION: **12" x 12" White Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**
MATERIAL DESCRIPTION: **Gray Baseboard**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **23**

MATERIAL DESCRIPTION: **Gray Baseboard**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **Gray Baseboard Mastic**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**
MATERIAL DESCRIPTION: **Plaster Ceiling**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION:
ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **25**

MATERIAL DESCRIPTION: **Plaster Ceiling**

MATERIAL LOCATION: **Room 111**


MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	26		
MATERIAL DESCRIPTION:	1' x 1' White Ceiling Tile (Pinhole)		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Encapsulate		
ASBESTOS TYPE:	Amosite	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Classrooms On Soffits, Closets**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **26**

MATERIAL DESCRIPTION: **1' x 1' White Ceiling Tile (Pinhole)**

MATERIAL LOCATION: **Throughout Classrooms On Soffits, Closets**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Encapsulate

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Carpet Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **27**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Interior Window Caulk**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Throughout Interior of Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **28**

MATERIAL DESCRIPTION: **Interior Window Caulk**

MATERIAL LOCATION: **Throughout Interior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Non-AHERA**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **No ACBM** FRIABLE: _____

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: _____ MATERIAL UNITS: _____

DAMAGE QUANTITY: _____ DAMAGE UNITS: _____

COMMENTS:

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **29**

MATERIAL DESCRIPTION: **Exterior Window Caulk - Non-AHERA**

MATERIAL LOCATION: **Exterior of Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Non-AHERA

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	30		
MATERIAL DESCRIPTION:	Acoustical Spray-on Fireproofing		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Throughout Building Above Ceilings in Classrooms and Hallways		
MATERIAL QUANTITY:	62000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **30**

MATERIAL DESCRIPTION: **Acoustical Spray-on Fireproofing**

MATERIAL LOCATION: **Throughout Building Above Ceilings in Classrooms and Hallways**

MATERIAL QUANTITY: **62000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	31		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Speckles Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Entrance, Lunchroom, Rooms 109, 111, 116		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 115, 117		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **31**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Speckles Floor Tile**

MATERIAL LOCATION: **Basement Entrance, Lunchroom, Rooms 109, 111, 116**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	32		
MATERIAL DESCRIPTION:	12" x 12" Brown w/ Speckles Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Basement Entrance, Lunchroom, Rooms 109, 111, 116		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **32**

MATERIAL DESCRIPTION: **12" x 12" Brown w/ Speckles Floor Tile Mastic**

MATERIAL LOCATION: **Basement Entrance, Lunchroom, Rooms 109, 111, 116**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	33	
MATERIAL DESCRIPTION:	Blue Carpet Adhesive	
HISTORICAL AHERA DAMAGE CATEGORY		
HISTORICAL DAMAGE REASON:		
HISTORICAL RESPONSE ACTION:	Follow O&M Plan	
ASBESTOS TYPE:	Abated	FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **33**

MATERIAL DESCRIPTION: **Blue Carpet Adhesive**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	34		
MATERIAL DESCRIPTION:	Terrazo		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Stairs in Gym, Stairwell & Auditorium		
MATERIAL QUANTITY:	1600	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **34**

MATERIAL DESCRIPTION: **Terrazo**

MATERIAL LOCATION: **Stairs in Gym, Stairwell & Auditorium**

MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	35		
MATERIAL DESCRIPTION:	Red Carpet Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Main Office, Principal Office, and Room 238, 1st Floor Conference Room		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **35**

MATERIAL DESCRIPTION: **Red Carpet Mastic**

MATERIAL LOCATION: **Main Office, Principal Office, and Room 238, 1st Floor Conference Room**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208**

MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **36**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile**

MATERIAL LOCATION: **Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208**

MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	36M		
MATERIAL DESCRIPTION:	12" x 12" Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208**

MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **36M**

MATERIAL DESCRIPTION: **12" x 12" Gray Floor Tile Mastic**

MATERIAL LOCATION: **Top of Stage in Gym, Throughout 1, 2, Floor Hallways, Rooms 118, 203, 212, 109, Office, 208**

MATERIAL QUANTITY: **17000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37		
MATERIAL DESCRIPTION:	Tan Baseboard		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111, 109		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **37**

MATERIAL DESCRIPTION: **Tan Baseboard**

MATERIAL LOCATION: **Room 111, 109**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	37M		
MATERIAL DESCRIPTION:	Tan Baseboard Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111, 109		
MATERIAL QUANTITY:	100	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **37M**

MATERIAL DESCRIPTION: **Tan Baseboard Mastic**

MATERIAL LOCATION: **Room 111, 109**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38		
MATERIAL DESCRIPTION:	12" x 12" Aqua & White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **38**

MATERIAL DESCRIPTION: **12" x 12" Aqua & White Floor Tile**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	38M		
MATERIAL DESCRIPTION:	12" x 12" Aqua & White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **38M**

MATERIAL DESCRIPTION: **12" x 12" Aqua & White Floor Tile Mastic**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39		
MATERIAL DESCRIPTION:	Ceramic Tile & Grout		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathrooms Walls		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **39**

MATERIAL DESCRIPTION: **Ceramic Tile & Grout**

MATERIAL LOCATION: **Bathrooms Walls**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	39M		
MATERIAL DESCRIPTION:	Ceramic Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathroom Walls		
MATERIAL QUANTITY:	500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **39M**

MATERIAL DESCRIPTION: **Ceramic Tile Mastic**

MATERIAL LOCATION: **Bathroom Walls**

MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40		
MATERIAL DESCRIPTION:	6" x 6" White Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	HIGH		
MATERIAL LOCATION:	Bathrooms in Room 111		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **40**

MATERIAL DESCRIPTION: **6" x 6" White Floor Tile**

MATERIAL LOCATION: **Bathrooms in Room 111**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	40 M		
MATERIAL DESCRIPTION:	6" x 6" White Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Bathrooms in Room 111		
MATERIAL QUANTITY:	200	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **40 M**

MATERIAL DESCRIPTION: **6" x 6" White Floor Tile Mastic**

MATERIAL LOCATION: **Bathrooms in Room 111**

MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	41		
MATERIAL DESCRIPTION:	2' x 2' White Pinholes and Gouges Ceiling Tiles		
HISTORICAL AHERA DAMAGE CATEGORY	7 Any remaining friable ACBM or friable suspect ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Main Office, 105, 118, 1st Floor Corridor, Kitchen, Faculty Lounge, 103A**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **41**

MATERIAL DESCRIPTION: **2' x 2' White Pinholes and Gouges Ceiling Tiles**

MATERIAL LOCATION: **Main Office, 105, 118, 1st Floor Corridor, Kitchen, Faculty Lounge, 103A**

MATERIAL QUANTITY: **1700** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**
MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**
HISTORICAL AHERA DAMAGE CATEGORY
HISTORICAL DAMAGE REASON:
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**
ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **42**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42M**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION: **Follow O&M Plan**

ASBESTOS TYPE: **Abated** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **42M**

MATERIAL DESCRIPTION: **12" x 12" Red Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43		
MATERIAL DESCRIPTION:	12" x 12" Green and Blue Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **43**

MATERIAL DESCRIPTION: **12" x 12" Green and Blue Floor Tile**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	43M		
MATERIAL DESCRIPTION:	12" x 12" Green and Blue Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 111		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **43M**

MATERIAL DESCRIPTION: **12" x 12" Green and Blue Floor Tile Mastic**

MATERIAL LOCATION: **Room 111**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	44		
MATERIAL DESCRIPTION:	9" x 9" Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Physical Damage		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **44**

MATERIAL DESCRIPTION: **9" x 9" Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Sample to determine ACM content prior to disturbance.

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	45		
MATERIAL DESCRIPTION:	1' x 1' White Textured Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 ACBM with potential for significant damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	MODERATE		
MATERIAL LOCATION:	Southwest Corner of 2nd Floor Corridor		
MATERIAL QUANTITY:	25	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **45**

MATERIAL DESCRIPTION: **1' x 1' White Textured Ceiling Tile**

MATERIAL LOCATION: **Southwest Corner of 2nd Floor Corridor**

MATERIAL QUANTITY: **25** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	46		
MATERIAL DESCRIPTION:	Tongue and Groove Wooden Floor		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Gymnasium		
MATERIAL QUANTITY:	7500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **46**

MATERIAL DESCRIPTION: **Tongue and Groove Wooden Floor**

MATERIAL LOCATION: **Gymnasium**

MATERIAL QUANTITY: **7500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	47		
MATERIAL DESCRIPTION:	9" x 9" Black w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **47**

MATERIAL DESCRIPTION: **9" x 9" Black w/ White Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	48		
MATERIAL DESCRIPTION:	9" x 9" Black w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **48**

MATERIAL DESCRIPTION: **9" x 9" Black w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	49		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 209 (Patches)		
MATERIAL QUANTITY:	4	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 216 and 213, 114		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **49**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 209 (Patches)**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	5		
MATERIAL DESCRIPTION:	Transite Ceiling Panel		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **5**

MATERIAL DESCRIPTION: **Transite Ceiling Panel**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	50		
MATERIAL DESCRIPTION:	12" x 12" Beige w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 209 (Patches)		
MATERIAL QUANTITY:	4	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 216 and 213, 114		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **50**

MATERIAL DESCRIPTION: **12" x 12" Beige w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 209 (Patches)**

MATERIAL QUANTITY: **4** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	51		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101 (Patches)		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 114		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Specks Floor Tile**

MATERIAL LOCATION: **Rooms 101 (Patches)**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	52		
MATERIAL DESCRIPTION:	12" x 12" Light Gray w/ White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 101 (Patches)		
MATERIAL QUANTITY:	20	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 114		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **12" x 12" Light Gray w/ White Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 101 (Patches)**

MATERIAL QUANTITY: **20** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	54		
MATERIAL DESCRIPTION:	12" x 12" Purple w/ Light Purple Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 215		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **12" x 12" Purple w/ Light Purple Specks Floor Tile**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	55		
MATERIAL DESCRIPTION:	12" x 12" Purple w/ Light Purple Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 215		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12" x 12" Purple w/ Light Purple Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 215**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	56		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room		
MATERIAL QUANTITY:	2000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 113		

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	57		
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS: **Not observed in room 113**

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 214, 210, 106, 107, 114 (Patches), 102, 103, 103a, 104, Counselors Office, 105 Storage Room**

MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	58		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ Black Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:	Deterioration		
HISTORICAL RESPONSE ACTION:	Repair		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be 6. ACBM with the potential for damage

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105 Storage Room		
MATERIAL QUANTITY:	575	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **9" x 9" Gray w/ Black Specks Floor Tile**

MATERIAL LOCATION: **Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105 Storage Room**

MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Repair

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	59		
MATERIAL DESCRIPTION:	9" x 9" Gray w/ Black Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105 Storage Room		
MATERIAL QUANTITY:	575	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature: _____ Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **9" x 9" Gray w/ Black Specks Floor Tile Mastic**

MATERIAL LOCATION: **Room 210 Wellness Room and MDF, Vault Room, Office Supply Room, 105 Storage Room**

MATERIAL QUANTITY: **575** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	6		
MATERIAL DESCRIPTION:	1' x 1' Random Dot Ceiling Tile		
HISTORICAL AHERA DAMAGE CATEGORY	7 Damaged or significantly damaged friable misc. ACBM		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Bathroom Next to Engineer's Office, Boys Bathroom Across From Faculty Lunch & Lounge, A210 Corridor, 2nd Floor Boys Bathroom Next to 218, 2nd Floor Girls Bathroom Next to 219**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

COMMENTS:

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **6**

MATERIAL DESCRIPTION: **1' x 1' Random Dot Ceiling Tile**

MATERIAL LOCATION: **Bathroom Next to Engineer's Office, Boys Bathroom Across From Faculty Lunch & Lounge, A210 Corridor, 2nd Floor Boys Bathroom Next to 218, 2nd Floor Girls Bathroom Next to 219**

MATERIAL QUANTITY: **100** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	60		
MATERIAL DESCRIPTION:	9" x 9" Rose Gold w/ Brown Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **60**

MATERIAL DESCRIPTION: **9" x 9" Rose Gold w/ Brown Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	61		
MATERIAL DESCRIPTION:	9" x 9" Rose Gold w/ Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **61**

MATERIAL DESCRIPTION: **9" x 9" Rose Gold w/ Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	62		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Brown & White Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **62**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Brown & White Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	63		
MATERIAL DESCRIPTION:	9" x 9" Beige w/ Brown & White Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **63**

MATERIAL DESCRIPTION: **9" x 9" Beige w/ Brown & White Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	64		
MATERIAL DESCRIPTION:	9" x 9" Dark Brown & Beige Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **64**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown & Beige Specks Floor Tile**

MATERIAL LOCATION: **2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	65		
MATERIAL DESCRIPTION:	9" x 9" Dark Brown w/ Beige Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)		
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **65**

MATERIAL DESCRIPTION: **9" x 9" Dark Brown w/ Beige Specks Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	66		
MATERIAL DESCRIPTION:	12" x 12" Dark Grays Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 109		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **66**

MATERIAL DESCRIPTION: **12" x 12" Dark Grays Floor Tile**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	67		
MATERIAL DESCRIPTION:	12" x 12" Dark Grays Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 109		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **67**

MATERIAL DESCRIPTION: **12" x 12" Dark Grays Floor Tile Mastic**

MATERIAL LOCATION: **Room 109**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	68		
MATERIAL DESCRIPTION:	12" x 12" Light Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **68**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile**

MATERIAL LOCATION: **Rooms 109**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	69		
MATERIAL DESCRIPTION:	12" x 12" Light Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Assumed	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Rooms 109		
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **69**

MATERIAL DESCRIPTION: **12" x 12" Light Gray Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 109**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	7		
MATERIAL DESCRIPTION:	9" x 9" Brown/Gray Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)		
MATERIAL QUANTITY:	700	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **7**

MATERIAL DESCRIPTION: **9" x 9" Brown/Gray Floor Tile Mastic**

MATERIAL LOCATION: **2nd Floor Janitors Closet, A210 Corridor, Faculty Lounge, Stage (Gym)**

MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**


DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	70		
MATERIAL DESCRIPTION:	12" x 12" Rose Gold w/ Brown Specks Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **70**

MATERIAL DESCRIPTION: **12" x 12" Rose Gold w/ Brown Specks Floor Tile**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	71		
MATERIAL DESCRIPTION:	12" x 12" Rose Gold w/ Brown Specks Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Abated	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **71**

MATERIAL DESCRIPTION: **12" x 12" Rose Gold w/ Brown Specks Floor Tile Mastic**

MATERIAL LOCATION: **ABATED**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	8		
MATERIAL DESCRIPTION:	12" x 12" Brown Floor Tile Mastic		
HISTORICAL AHERA DAMAGE CATEGORY	6 ACBM with the potential for damage		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Room 116		
MATERIAL QUANTITY:	2400	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Not observed in room 115, 117		

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **8**

MATERIAL DESCRIPTION: **12" x 12" Brown Floor Tile Mastic**

MATERIAL LOCATION: **Room 116**

MATERIAL QUANTITY: **2400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	9		
MATERIAL DESCRIPTION:	9" x 9" Gray Floor Tile		
HISTORICAL AHERA DAMAGE CATEGORY	5		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	No

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:	Physical Damage		
DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	A210 Wellness Room, MDF Room (A210)		
MATERIAL QUANTITY:	150	MATERIAL UNITS:	SF
DAMAGE QUANTITY:		DAMAGE UNITS:	SF
COMMENTS:	Damage in MDF Room (A210)		

Inspector's Signature: _____ Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **9**

MATERIAL DESCRIPTION: **9" x 9" Gray Floor Tile**

MATERIAL LOCATION: **A210 Wellness Room, MDF Room (A210)**

MATERIAL QUANTITY: **150** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **2** DAMAGE UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Remove or repair to intact.

Management Planner's Signature:



Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	A		
MATERIAL DESCRIPTION:	Fiberglass Pipe Fittings		
HISTORICAL AHERA DAMAGE CATEGORY	7		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	Follow O&M Plan		
ASBESTOS TYPE:	Chrysotile	FRIABLE:	Yes

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	LOW		
MATERIAL LOCATION:	Concealed within Pipe Chases		
MATERIAL QUANTITY:	125	MATERIAL UNITS:	LF
DAMAGE QUANTITY:			
COMMENTS:			

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUILDING ID:	6730
CITY/STATE:	Chicago, Illinois	MANAGEMENT PLANNER:	Mike Serio		
SCHOOL NAME:	Cather School	REVIEW DATE:	8/8/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Fiberglass Pipe Fittings**

MATERIAL LOCATION: **Concealed within Pipe Chases**

MATERIAL QUANTITY: **125** MATERIAL UNITS: **LF**


DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature:  Date: **08/08/2025**

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	204			
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Specks Floor Tile Mastic			
MATERIAL LOCATION:	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220, Unisex Bathroom Vestibule			
MATERIAL QUANTITY:	600	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **204**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220, Unisex Bathroom Vestibule**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	216		
MATERIAL DESCRIPTION:	Wire Insulation		
MATERIAL LOCATION:	2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office		
MATERIAL QUANTITY:	6	MATERIAL UNITS:	LF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	LF
COMMENTS:			

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **216**

MATERIAL DESCRIPTION: **Wire Insulation**

MATERIAL LOCATION: **2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office**

MATERIAL QUANTITY: **6** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: MATERIAL UNITS: **LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	207			
MATERIAL DESCRIPTION:	12" x 12" Blue Mottled Floor Tile			
MATERIAL LOCATION:	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220			
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **207**

MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile**

MATERIAL LOCATION: **Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	211			
MATERIAL DESCRIPTION:	1' x 1' White Pinholes and Gouges Ceiling Tile			
MATERIAL LOCATION:	Throughout 2nd Floor Corridor			
MATERIAL QUANTITY:	1000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **211**

MATERIAL DESCRIPTION: **1' x 1' White Pinholes and Gouges Ceiling Tile**

MATERIAL LOCATION: **Throughout 2nd Floor Corridor**

MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	209			
MATERIAL DESCRIPTION:	12" x 12" Red Ceramic Floor Tile w/ Grout			
MATERIAL LOCATION:	Kitchen			
MATERIAL QUANTITY:	800	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **209**

MATERIAL DESCRIPTION: **12" x 12" Red Ceramic Floor Tile w/ Grout**

MATERIAL LOCATION: **Kitchen**

MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	213			
MATERIAL DESCRIPTION:	1' x 1' White Pinholes and Deep Fissures Ceiling Tile			
MATERIAL LOCATION:	South and West 2nd Floor Corridors			
MATERIAL QUANTITY:	250	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates 2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **213**

MATERIAL DESCRIPTION: **1' x 1' White Pinholes and Deep Fissures Ceiling Tile**

MATERIAL LOCATION: **South and West 2nd Floor Corridors**

MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	215			
MATERIAL DESCRIPTION:	Masonite Ceiling Paneling			
MATERIAL LOCATION:	2nd Floor Boys Bathroom Next to 218, 2nd Floor Girls Bathroom Next to 219			
MATERIAL QUANTITY:	50	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **215**

MATERIAL DESCRIPTION: **Masonite Ceiling Paneling**

MATERIAL LOCATION: **2nd Floor Boys Bathroom Next to 218, 2nd Floor Girls Bathroom Next to 219**

MATERIAL QUANTITY: **50** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	203			
MATERIAL DESCRIPTION:	12" x 12" White w/ Gray Specks Floor Tile			
MATERIAL LOCATION:	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220, Unisex Bathroom Vestibule			
MATERIAL QUANTITY:	300	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **203**

MATERIAL DESCRIPTION: **12" x 12" White w/ Gray Specks Floor Tile**

MATERIAL LOCATION: **Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220, Unisex Bathroom Vestibule**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	210		
MATERIAL DESCRIPTION:	CMU and Mortar		
MATERIAL LOCATION:	Through Out Classroom and Hallway Walls		
MATERIAL QUANTITY:	20000	MATERIAL UNITS:	SF
MATERIAL CATEGORY:	MISC	FRIABLE:	No
ASBESTOS TYPE:	Assumed		
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage		
ACCESSIBILITY:	Within Reach	DAMAGE REASON:	
DAMAGE QUANTITY:		DAMAGE REASON:	
		DAMAGE REASON:	
		DAMAGE UNITS:	SF
COMMENTS:			

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **210**

MATERIAL DESCRIPTION: **CMU and Mortar**

MATERIAL LOCATION: **Through Out Classroom and Hallway Walls**

MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	206			
MATERIAL DESCRIPTION:	12" x 12" Black Mottled Floor Tile Mastic			
MATERIAL LOCATION:	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220			
MATERIAL QUANTITY:	6000	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **206**

MATERIAL DESCRIPTION: **12" x 12" Black Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220**

MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	217			
MATERIAL DESCRIPTION:	Light Reflector Insulation			
MATERIAL LOCATION:	2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office			
MATERIAL QUANTITY:	2	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Not Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **217**

MATERIAL DESCRIPTION: **Light Reflector Insulation**

MATERIAL LOCATION: **2nd Floor Boys Bathroom Next to 218, Bathroom Next to Engineer's Office**

MATERIAL QUANTITY: **2** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Jose Escobedo**
SCHOOL NAME: **Cather School** INSPECTION DATE: **7/29/2025**
ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **208**
MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile Mastic**
MATERIAL LOCATION: **Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220**
MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**
MATERIAL CATEGORY: **MISC** FRIABLE: **No**
ASBESTOS TYPE: **Assumed**
DISTURBANCE POTENTIAL: **LOW** CONDITION: **No Damage**
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**
ACCESSIBILITY: **Not Reachable** DAMAGE REASON:
DAMAGE REASON:
DAMAGE REASON:
DAMAGE QUANTITY: DAMAGE UNITS: **SF**
COMMENTS:

Inspector's Signature:

Date: **07/29/2025**

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **208**

MATERIAL DESCRIPTION: **12" x 12" Blue Mottled Floor Tile Mastic**

MATERIAL LOCATION: **Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	205			
MATERIAL DESCRIPTION:	12" x 12" Black Mottled Floor Tile			
MATERIAL LOCATION:	Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220			
MATERIAL QUANTITY:	2500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	No	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	HIGH	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	6 ACBM with the potential for damage			
ACCESSIBILITY:	Within Reach	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **205**

MATERIAL DESCRIPTION: **12" x 12" Black Mottled Floor Tile**

MATERIAL LOCATION: **Rooms 101, 107, 108, 110, 112, 113, 114, 115, 211, 212, 204, 205, 206, 207, 213, 216, 217, 218, 219, 220**

MATERIAL QUANTITY: **2500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	212			
MATERIAL DESCRIPTION:	1' x 1' White Pinhole w/ Holes Ceiling Tile			
MATERIAL LOCATION:	East and South 2nd Floor Corridors (Patching)			
MATERIAL QUANTITY:	400	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **212**

MATERIAL DESCRIPTION: **1' x 1' White Pinhole w/ Holes Ceiling Tile**

MATERIAL LOCATION: **East and South 2nd Floor Corridors (Patching)**

MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

Inspector Assessment Form (New Homogeneous Area)

LEA NAME:	Chicago Public Schools	UNIT NUMBER:	26021	BUIDLING ID:	6730
CITY/STATE:	Chicago, Illinois	AHERA INSPECTOR:	Jose Escobedo		
SCHOOL NAME:	Cather School	INSPECTION DATE:	7/29/2025		
ADDRESS:	2908 W. Washington	IDPH LICENSE NO:	100-06435		

INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA:	214			
MATERIAL DESCRIPTION:	1' x 1' White Pinholes and Light Fissures Ceiling Tile			
MATERIAL LOCATION:	2nd Floor East Corridor			
MATERIAL QUANTITY:	1500	MATERIAL UNITS:	SF	
MATERIAL CATEGORY:	MISC	FRIABLE:	Yes	
ASBESTOS TYPE:	Assumed			
DISTURBANCE POTENTIAL:	LOW	CONDITION:	No Damage	
AHERA DAMAGE CATEGORY:	7 Any remaining friable ACBM or friable suspect ACBM			
ACCESSIBILITY:	Barely Reachable	DAMAGE REASON:		
DAMAGE QUANTITY:		DAMAGE REASON:		
		DAMAGE REASON:		
		DAMAGE UNITS:	SF	
COMMENTS:				

Inspector's Signature:

Date: 07/29/2025

Chicago Public Schools

Carnow, Conibear and Associates
2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **26021** BUIDLING ID: **6730**

CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Mike Serio**

SCHOOL NAME: **Cather School** REVIEW DATE: **8/8/2025**

ADDRESS: **2908 W. Washington** IDPH LICENSE NO: **100-06435**

HOMOGENEOUS AREA: **214**

MATERIAL DESCRIPTION: **1' x 1' White Pinholes and Light Fissures Ceiling Tile**

MATERIAL LOCATION: **2nd Floor East Corridor**

MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: MATERIAL UNITS: **SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature:  Date: 08/08/2025

Chicago Public Schools

Carnow, Conibear and Associates

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses



OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

2024

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Jose Escobedo


has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. This course is accredited by the State of Wisconsin, Department of Health Services under ch. DHS 159, Wis. Admin. Code, The Illinois Department of Public Health and The Indiana Department of Environmental Management, under 326 IAC 18. Training was in accordance with requirements listed under EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Location: 12304 75th Street
Kenosha, WI 53142

Certificate Number: BIRWI2409132637
Course Date: 9/13/2024
Exam Date: 9/13/2024
Expiration Date: 9/13/2025




Issue Date: 9/13/2024


Tyler Nicholson, Authorized Signer

Course Credit Hours: BIR WI 4 Hours

Jose Escobedo

Air Sampling Professional, Illinois Licensed Building Inspector, Asbestos Project Manager



ENDORSEMENTS	TC EXPIRES
SUPERVISOR/WORKER	1/11/2026
INSPECTOR	9/13/2025

PROJECT MANAGER	1/11/2026
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.



OCCUPATIONAL TRAINING & SUPPLY, INC. **2024**
7233 S. Adams Street | Willowbrook, IL 60527 (630) 655-3900 | www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Michael Serio

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency Response Act (AHERA) and TSCA Title II.

Course Date: 11/18/2024

Exam Date: 11/18/2024

Expiration Date: 11/18/2025

Certificate Number: MPR2411183328

Course Credit Hours: MPR 4 Hours

A handwritten signature in black ink that reads "Kristina Miczek".

Kristina Miczek, Training Manager

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE	Loc	Localized
	Dist	Distributed